

## PUBLIC UTILITIES COMMISSION

505 VAN NESS AVENUE  
SAN FRANCISCO, CA 94102-3298



May 3, 2024

EA2024-1180

Ms. Cindy Sauers  
Electric Utility Director  
Ukiah Electric Department  
300 Seminary Avenue  
Ukiah, CA 95482

**SUBJECT:** Electric Distribution Facilities Audit of City of Ukiah

Ms. Sauers:

On behalf of the Electric Safety and Reliability Branch (ESRB) of the California Public Utilities Commission (CPUC), Dmitriy Lysak and Monica Hoskins of ESRB staff conducted an electric distribution audit of City of Ukiah from February 20 through February 23, 2024. During the audit, ESRB staff conducted field inspections of Ukiah's distribution facilities and equipment and reviewed pertinent documents and records.

As a result of the audit, ESRB staff identified violations of General Order (GO) 95, GO 128, and GO 165. A copy of the audit findings itemizing the violations and observations is enclosed. Please provide a response no later than May 31, 2024, via electronic copy of all corrective actions and preventive measures taken by City of Ukiah to correct the identified violations and prevent the recurrence of such violations. Please note that ESRB will be posting the audit report and your response to our audit on the CPUC website. If there is any information in your response that you would like us to consider as confidential, we request that in addition to your confidential response, you provide us with a public version (a redacted version of your confidential response) to be posted on our website.

If you have any questions concerning this audit, please contact Monica Hoskins at (415) 652-1847 or [monica.hoskins@cpuc.ca.gov](mailto:monica.hoskins@cpuc.ca.gov).

Sincerely,

A handwritten signature in blue ink, appearing to read 'Rickey Tse'.

Rickey Tse, P.E.  
Program and Project Supervisor  
Electric Safety and Reliability Branch  
Safety and Enforcement Division

California Public Utilities Commission

Enclosure: CPUC Electric Distribution Audit Report for City of Ukiah

Cc: Lee Palmer, Director, Safety and Enforcement Division (SED), CPUC  
Nika Kjensli, Program Manager, ESRB, SED, CPUC  
Fadi Daye, Program and Project Supervisor, ESRB, SED, CPUC  
Nathan Sarina, Senior Utilities Engineer (Supervisor), ESRB, SED, CPUC  
Yi (Rocky) Yang, Senior Utilities Engineer (Supervisor), ESRB, SED, CPUC  
Monica Hoskins, Utilities Engineer, ESRB, SED, CPUC

**CITY OF UKIAH**  
**ELECTRIC DISTRIBUTION AUDIT FINDINGS**  
**FEBRUARY 20 – 23, 2024**

**I. Records Review**

During the audit, Electric Safety and Reliability Branch (ESRB) staff reviewed the following records:

- City of Ukiah Overhead/Underground Preventative Maintenance Program
- Overhead and underground facilities statistics.
- Completed work orders with notifications, canceled work orders with notifications, and open work orders with notifications from December 2018 to December 2023.
- Patrol and detailed inspection records from December 2018 to December 2023.
- Reliability metrics and sustained outages from December 2018 to December 2023.
- City of Ukiah system map.
- New Construction projects (both overhead and underground) from December 2022 to December 2023.
- Pole loading and safety factor calculations completed from December 2022 to December 2023.
- Inspector list from December 2018 to December 2023 and inspector qualifications.
- Equipment test records from December 2018 to December 2023.
- Intrusive inspection records from January 2018 to December 2023.

## II. Records Violations

ESRB observed the following violations during the record review portion of the audit:

### 1. GO 95, Rule 18-A, Resolution of Potential Violations of General Order 95 and Safety Hazards states in part:

*“(2) Where a communications company’s or an electric utility’s (Company A’s) actions result in potential violations of GO 95 for another entity (Company B), that entity’s (Company B’s) remedial action will be to transmit a single documented notice of identified potential violations to the communications company or electric utility (Company A) within a reasonable amount of time not to exceed 180 days after the entity discovers the potential violations of GO 95. If the potential violation constitutes a Safety Hazard, such notice shall be transmitted within ten (10) business days after the entity discovers the Safety Hazard.*

*(3) If a company, while performing inspections of its facilities, discovers a Safety Hazard(s) on or near a communications facility or electric facility involving another company, the inspecting company shall notify the other entity of such Safety Hazard(s) no later than ten (10) business days after the discovery.*

*(4) To the extent a company that has a notification requirement under (2) or (3) above cannot determine the facility owner/operator, it shall contact the pole owner(s) within ten (10) business days if the subject of the notification is a Safety Hazard, or otherwise within a reasonable amount of time not to exceed 180 days after discovery. The notified pole owner(s) shall be responsible for promptly (normally not to exceed five business days) notifying the company owning/operating the facility if the subject of the notification is a Safety Hazard, or otherwise within a reasonable amount of time not to exceed 180 days, after being notified of the potential violation of GO 95.*

*(5) A company receiving a notification under (2), (3), or (4) above shall take appropriate corrective action consistent with the provisions of this rule. For at least ten (10) years, the documentation of the notice shall be maintained by both the notifying and receiving parties and documentation of the correction shall be maintained by the receiving party.”*

City of Ukiah has not maintained a record of notifications sent to third parties. City of Ukiah shall start documenting any incoming or outgoing third party notifications.

### 2. GO 95, Rule 18-B, Maintenance Programs, (1)(a) states in part:

*“Each company (including electric utilities and communications companies) shall establish and implement an auditable maintenance program for its facilities and lines for the purpose of ensuring that they are in good condition so as to conform to these rules. Each company must describe in its auditable maintenance program the required qualifications for the company representatives who perform inspections and/or who schedule corrective actions. Companies that are subject to GO 165 may*

*maintain procedures for conducting inspections and maintenance activities in compliance with this rule and with GO 165.*

*The maximum time periods for corrective actions associated with potential violation of GO 95 or a Safety Hazard are based on the following priority levels:*

- (i) Level 1 -- An immediate risk of high potential impact to safety or reliability:*
  - *Take corrective action immediately, either by fully repairing or by temporarily repairing and reclassifying to a lower priority.*
- (ii) Level 2 -- Any other risk of at least moderate potential impact to safety or reliability:*
  - *Take corrective action within specified time period (either by fully repair or by temporarily repairing and reclassifying to Level 3 priority). Time period for corrective action to be determined at the time of identification by a qualified company representative, but not to exceed: (1) six months for potential violations that create a fire risk located in Tier 3 of the High Fire-Threat District; (2) 12 months for potential violations that create a fire risk located in Tier 2 of the High Fire-Threat District; (3) 12 months for potential violations that compromise worker safety; and (4) 36 months for all other Level 2 potential violations.*
- (iii) Level 3 -- Any risk of low potential impact to safety or reliability:*
  - *Take corrective action within 60 months subject to the exception specified below.”*

**GO 95, Rule 31.1, Design, Construction and Maintenance** states in part:

*“Electrical supply and communication systems shall be designed, constructed, and maintained for their intended use, regard being given to the conditions under which they are to be operated, to enable the furnishing of safe, proper, and adequate service.*

*For all particulars not specified in these rules, design, construction, and maintenance should be done in accordance with accepted good practice for the given local conditions known at the time by those responsible for the design, construction, or maintenance of communication or supply lines and equipment.”*

**GO 128, Rule 17.1, Design, Construction and Maintenance** states in part:

*“Electrical supply and communication systems shall be designed, constructed, and maintained for their intended use, regard being given to the conditions under which they are to be operated, to enable the furnishing of safe, proper, and adequate service.*

*For all particulars not specified in these rules, design, construction, and maintenance should be done in accordance with accepted good practice for the given local conditions known at the time by those responsible for the design, construction, or maintenance of [the] communication or supply lines and equipment.”*

ESRB staff reviewed work orders completed within the City of Ukiah for the past 60 months (December 2018 – December 2023). City of Ukiah’s Preventative Maintenance program defines the priority codes and associated time frames for the response/repair action as follows:

*Priority 1 Immediate Hazard – Priority 1 Conditions are those that may affect the integrity of the system or present a hazard to workers or the general public. All Priority #1 Tags will be responded to immediately, and appropriate action taken until the hazardous condition is remedied.*

*Priority 2 Non-emergency repair condition – Priority 2 Conditions are those that require maintenance that can be scheduled to maintain the integrity of the system. Priority #2 Tags will be prioritized by urgency and will be scheduled to have appropriate repairs made to correct the condition within 6 months, where practicable.*

*Priority 3 & 4 Non-emergency repair condition – Conditions are those that do not present a situation that could jeopardize the safety of the system, workmen and the general public. Either Priority #3 or #4 tags will be issued by the inspector with the time interval recommended. In the judgment of the inspector, work will be scheduled to be completed either in 1 year for Priority # 3 tags or 3 years for priority #4 tags.*

While the City of Ukiah notes the above repair timeframes in its Preventative Maintenance program and inspection forms, the priorities and timeframes are not utilized when generating work orders for repairs. A sampling of 21 Work Orders showed a variety of repair priorities including: Priority Replacement, Medium, High (within 1-4 weeks) and High Priority. The rest of the work orders did not list priority levels or due dates.

While the scale of work orders for the City of Ukiah is not very large, they should utilize the priorities noted in their Preventative Maintenance program as required by GO 95 to ensure repair timelines are consistent and required repair timeframes are kept.

As of March 5, 2024, there are 2 open work orders from 2021, 3 open work orders from 2022 and 15 open work orders from 2023.

**3. GO 165, Rule III B, Standard for Inspection states:**

*“Each utility subject to this General Order shall conduct inspections of its distribution facilities, as necessary, to ensure reliable, high-quality, and safe operation, but in no case may the period between inspections (measured in years) exceed the time specified in Table 1.”*

ESRB staff reviewed overhead and underground patrol and detailed inspection records from December 2018 to December 2023. The City of Ukiah’s latest underground detailed inspections occurred in 2020 and exceeds the maximum 3-year interval in Table 1 of GO 165.

### III. Field Inspection

During the field inspection, ESRB inspected the following facilities in Table 1:

**Table 1: Field Inspection Locations**

| Location # | Structure ID | Structure Type        | City  |
|------------|--------------|-----------------------|-------|
| 1          | 05VLYVW12    | Pole                  | Ukiah |
| 2          | 05VLYVW11    | Pole                  | Ukiah |
| 3          | 05VLYVW10    | Pole                  | Ukiah |
| 4          | 06MAPLE04    | Pole                  | Ukiah |
| 5          | 06MAPLE02    | Pole                  | Ukiah |
| 6          | 06MAPLE01    | Pole                  | Ukiah |
| 7          | 05MAPLE18    | Pole                  | Ukiah |
| 8          | 05HAZEL02    | Pole                  | Ukiah |
| 9          | 06BUSHN03    | Pole                  | Ukiah |
| 10         | 06BUSHN06    | Pole                  | Ukiah |
| 11         | 06BUSHN08    | Pole                  | Ukiah |
| 12         | 06BUSHN09    | Pole                  | Ukiah |
| 13         | 06BUSHN07    | Pole                  | Ukiah |
| 14         | 06BUSHN04    | Pole                  | Ukiah |
| 15         | 02ELMST02    | Pole                  | Ukiah |
| 16         | 02ELMST07    | Pole                  | Ukiah |
| 17         | 02ELMST08    | Pole                  | Ukiah |
| 18         | 02EMPIRE08   | Pole                  | Ukiah |
| 19         | 02STATN06    | Pole                  | Ukiah |
| 20         | 02STATN07    | Pole                  | Ukiah |
| 21         | 02STATN08    | Pole                  | Ukiah |
| 22         | 04STATN01    | Pole                  | Ukiah |
| 23         | 04ELMST02    | Pole                  | Ukiah |
| 24         | 04ELMST03    | Pole                  | Ukiah |
| 25         | 04ELMST04    | Pole                  | Ukiah |
| 26         | 09BRNSN07    | Pole                  | Ukiah |
| 27         | 00STANDW02   | Pole                  | Ukiah |
| 28         | 09STNDW01    | Pole                  | Ukiah |
| 29         | 08STNDW37    | Pole                  | Ukiah |
| 30         | 09BRNSN06    | Pole                  | Ukiah |
| 31         | 09BRNSN05    | Pole                  | Ukiah |
| 32         | 2148         | Pad Mount Transformer | Ukiah |
| 33         | 1889         | Pad Mount Transformer | Ukiah |
| 34         | 117          | Junction Box          | Ukiah |
| 35         | 1698         | Pad Mount Transformer | Ukiah |
| 36         | 08LVOAK03    | Pole                  | Ukiah |
| 37         | 08LVOAK02    | Pole                  | Ukiah |

|    |            |                       |       |
|----|------------|-----------------------|-------|
| 38 | 2304       | Pad Mount Transformer | Ukiah |
| 39 | 11PERKE01  | Pole                  | Ukiah |
| 40 | 11PERKE02  | Pole                  | Ukiah |
| 41 | 11PERKE04  | Pole                  | Ukiah |
| 42 | 2171       | Pad Mount Transformer | Ukiah |
| 43 | 12ESTLK01  | Pole                  | Ukiah |
| 44 | 12CLYSW03  | Pole                  | Ukiah |
| 45 | 12CLYSW02  | Pole                  | Ukiah |
| 46 | 12ESTLK05  | Pole                  | Ukiah |
| 47 | 12ESTLK07  | Pole                  | Ukiah |
| 48 | 13MILLW27  | Pole                  | Ukiah |
| 49 | 13SCHLS08  | Pole                  | Ukiah |
| 50 | 13SCHLS07  | Pole                  | Ukiah |
| 51 | 13SCHLS05  | Pole                  | Ukiah |
| 52 | 13SCHLS04  | Pole                  | Ukiah |
| 53 | 13SCHLS03  | Pole                  | Ukiah |
| 54 | 1697       | Pad Mount Transformer | Ukiah |
| 55 | 1077       | Pad Mount Transformer | Ukiah |
| 56 | 2344       | Pad Mount Transformer | Ukiah |
| 57 | 2347       | Pad Mount Transformer | Ukiah |
| 58 | 14MILLE01  | Pole                  | Ukiah |
| 59 | 2165       | Pad Mount Transformer | Ukiah |
| 60 | 14MILLE03  | Pole                  | Ukiah |
| 61 | 14MILLE11  | Pole                  | Ukiah |
| 62 | 14MILLE11  | Pole                  | Ukiah |
| 63 | 2372       | Pad Mount Transformer | Ukiah |
| 64 | 178        | Pad Mount Transformer | Ukiah |
| 65 | 2280       | Pad Mount Transformer | Ukiah |
| 66 | 16LUCE08   | Pole                  | Ukiah |
| 67 | 16LUCE07   | Pole                  | Ukiah |
| 68 | 16LUCE06   | Pole                  | Ukiah |
| 69 | 16LUCE05   | Pole                  | Ukiah |
| 70 | 16LUCE03   | Pole                  | Ukiah |
| 71 | 17BTTYST04 | Pole                  | Ukiah |
| 72 | 17DEBRA01  | Pole                  | Ukiah |
| 73 | 17BTTYST03 | Pole                  | Ukiah |
| 74 | 17BTTYST02 | Pole                  | Ukiah |
| 75 | 17BTTYST01 | Pole                  | Ukiah |
| 76 | 19LORRA03  | Pole                  | Ukiah |
| 77 | 19LORRA04  | Pole                  | Ukiah |
| 78 | 19LORRA05  | Pole                  | Ukiah |
| 79 | 19LORRA01  | Pole                  | Ukiah |
| 80 | 19LORRA01  | Pole                  | Ukiah |
| 81 | 17LORRA14  | Pole                  | Ukiah |
| 82 | 2007       | Pad Mount Transformer | Ukiah |

|    |           |                       |       |
|----|-----------|-----------------------|-------|
| 83 | 8         | Underground Pedestal  | Ukiah |
| 84 | 7         | Underground Pedestal  | Ukiah |
| 85 | 1994      | Pad Mount Transformer | Ukiah |
| 86 | 21LAURL02 | Pole                  | Ukiah |
| 87 | 669       | Pad Mount Transformer | Ukiah |
| 88 | 21LAURL01 | Pole                  | Ukiah |
| 89 | 21BECNL01 | Pole                  | Ukiah |
| 90 | 21BECNL02 | Pole                  | Ukiah |
| 91 | 21YOKYD09 | Pole                  | Ukiah |
| 92 | 21STATS01 | Pole                  | Ukiah |
| 93 | 21STATS02 | Pole                  | Ukiah |
| 94 | 21STATS03 | Pole                  | Ukiah |
| 95 | 23STATS11 | Pole                  | Ukiah |

#### IV. Field Inspection Violations

ESRB identified the following violations during the field inspection:

##### 1. GO 95, Rule 31.1, Design, Construction and Maintenance states in part:

*“Electrical supply and communication systems shall be designed, constructed, and maintained for their intended use, regard being given to the conditions under which they are to be operated, to enable the furnishing of safe, proper, and adequate service.”*

ESRB’s findings are listed in Table 2:

**Table 2: GO 95, Rule 31.1 Findings**

| Location # | Findings  |
|------------|---|
| 3          | Ground molding detached from pole, slack guy wire         |
| 6          | Woodpecker holes at top of pole                           |
| 23         | Tie wire on splice on center phase                        |
| 30         | Woodpecker holes at top of pole                           |
| 31         | Woodpecker damage, pole top splitting, crossarms decaying |
| 36         | Woodpecker holes at top of pole                           |
| 44         | Pole top splitting, woodpecker damage                     |
| 45         | Woodpecker damage, pole top splitting                     |

| Location # | Findings   |
|------------|--|
| 46         | Pole top splitting, woodpecker damage                    |
| 74         | Pole top deterioration, loose hardware on top insulator  |
| 75         | Pole top splitting, deterioration at down guy attachment |
| 80         | Woodpecker holes at top of pole                          |

**2. GO 95, Rule 91.3C, Stepping** states in part:

*“Where installed, the lowest step shall not be less than 8 feet from the ground line, or any easily climbable foreign structure from which one could reach or step.”*

ESRB’s findings are listed in Table 3:

**Table 3: GO 95, Rule 91.3C Findings**

| Location # | Findings          |
|------------|-------------------|
| 7          | Pole step too low |
| 44         | Pole step too low |
| 49         | Pole step too low |

**3. GO 95, Rule 51.6, Marking and Guarding, High Voltage Marking** states:

*"A. High Voltage Marking*

*Poles which support line conductors of more than 750 volts shall be marked with high voltage signs. This marking shall consist of a single sign showing the words "HIGH VOLTAGE," or pair of signs showing the words "HIGH" and "VOLTAGE," not more than six (6) inches in height with letters not less than 3 inches in height. Such signs shall be of weather and corrosion-resisting material, solid or with letters cut out therefrom and clearly legible."*

ESRB’s findings are listed in Table 4:

**Table 4: GO 95, Rule 51.6 Findings**

| <b>Location #</b> | <b>Findings</b>           |
|-------------------|---------------------------|
| 8                 | High Voltage sign loose   |
| 9                 | Missing High Voltage sign |
| 44                | Missing High Voltage sign |
| 46                | High Voltage sign damaged |
| 47                | High Voltage sign damaged |
| 49                | Missing High Voltage sign |
| 50                | Missing High Voltage sign |
| 51                | Missing High Voltage sign |
| 61                | Missing High Voltage sign |
| 62                | High Voltage sign damaged |
| 73                | High Voltage sign damaged |
| 75                | Missing High Voltage sign |
| 78                | Missing High Voltage sign |
| 92                | High Voltage sign damaged |

**4. GO 95, Rule 84.6.B, Ground Wires** states:

*“Ground wires, other than lightning protection wires not attached to equipment or ground wires on grounded structures, shall be covered by metal pipe or suitable covering of wood or metal, or of plastic conduit material as specified in Rule 22.8–A, for a distance above ground sufficient to protect against mechanical injury, but in no case shall such distance be less than 7 feet. Such covering may be omitted providing the ground wire in this 7-foot section has a mechanical strength at least equal to the strength of No. 6 AWG medium–hard–drawn copper.*

*Portions of ground wires which are on the surface of wood poles and within 6 feet vertically of unprotected supply conductors supported on the same pole, shall be covered with a suitable protective covering (see Rule 22.8).”*

ESRB’s findings are listed in Table 5:

**Table 5: GO 95, Rule 84.6.B Findings**

| Location # | Findings                                  |
|------------|---|
| 7          | Exposed ground wire                       |
| 22         | Exposed ground wire                       |
| 37         | Exposed ground wire                       |
| 47         | Exposed ground wire                       |
| 49         | Exposed ground wire                       |
| 50         | Exposed ground wire                       |
| 52         | Exposed ground wire                       |
| 58         | Exposed ground wire, old ground abandoned |
| 70         | Exposed ground wire                       |
| 72         | Exposed ground wire                       |

**5. GO 95, Rule 35, Vegetation Management** states in part:

*“Where overhead conductors traverse trees and vegetation, safety and reliability of service demand that certain vegetation management activities be performed in order to establish necessary and reasonable clearances, the minimum clearances set forth in Table 1, Cases 13 and 14, measured between line conductors and vegetation under normal conditions shall be maintained. (Also see Appendix E for tree trimming guidelines.) These requirements apply to all overhead electrical supply and communication facilities that are covered by this General Order, including facilities on lands owned and maintained by California state and local agencies.”*

ESRB’s findings are listed in Table 6:

**Table 6: GO 95, Rule 35 Findings**

| Location # | Findings                                 |
|------------|--|
| 3          | Vegetation on guy wire above insulator   |
| 4          | Vegetation on guy wire above insulator   |
| 5          | Tree strain on span                      |
| 13         | Tree in contact with base of pole        |
| 26         | Vegetation near guy wire above insulator |

| Location # | Findings                               |
|------------|--|
| 37         | Vegetation on guy wire above insulator |
| 39         | Vegetation on guy wire above insulator |
| 47         | Overgrown vegetation                   |
| 66         | Overgrown vegetation                   |
| 76         | Strain on service drop                 |
| 90         | Vegetation on guy wire above insulator |

**6. GO 95, Rule 86.9, Guy Marker (Guy Guard) states:**

*“A substantial marker of suitable material, including but not limited to metal or plastic, not less than 8 feet in length, shall be securely attached to all anchor guys. Where more than one guy is attached to an anchor rod, only the outermost guy is required to have a marker.”*

ESRB’s findings are listed in Table 7:

**Table 7: GO 95, Rule 86.9 Findings**

| Location # | Findings                            |
|------------|-------------------------------------|
| 27         | Guy guard missing visibility strips |
| 49         | Guy marker damaged                  |
| 78         | Guy guard missing visibility strips |

**7. GO 95, Rule 49.1C, Setting of Poles states in part:**

*“The depths of pole setting given in Table 6 are applicable to poles set in firm soil or in solid rock.*

*Where poles were set in firm soil, but the soil has since been excavated or subjected to erosion, the minimum embedment shall be no less than 90% of the values specified in Table 6.*

*Where, under the loading conditions in Rule 43 and the requirements of Rule 44, the resultant bearing surface is not sufficient to prevent overturning or excessive*

*movement of the pole at the ground line, and/or the soil is not firm, deeper settings or other special methods shall be used.”*

ESRB found that the set depth of the pole at location 71 does not meet the minimum pole setting depth in Table 6 of Rule 49.1C. Table 6 requires 7 feet of set depth for 55 foot poles and ESRB estimates 6.5 feet of set depth based on the pole stamp height.

**8. GO 128, Rule 35.1, Identification of Cables** states:

*“Cables operating at a voltage in excess of 750 volts shall be permanently and clearly identified by tags or other suitable means to indicate their operating voltage and the circuit with which they are normally associated at each manhole or other commonly accessible location of the underground system.”*

ESRB’s findings are listed in Table 8:

**Table 8: GO 128, Rule 35.1 Findings**

| <b>Location #</b> | <b>Findings</b>                        |
|-------------------|--|
| 33                | Missing voltage tags on primary cables |
| 34                | Missing voltage tags on primary cables |
| 35                | Missing voltage tags on primary cables |
| 38                | Missing voltage tags on primary cables |
| 42                | Missing voltage tags on primary cables |
| 54                | Missing voltage tags on primary cables |
| 55                | Missing voltage tags on primary cables |
| 60                | Missing voltage tags on primary cables |
| 63                | Missing voltage tags on primary cables |
| 64                | Missing voltage tags on primary cables |
| 65                | Missing voltage tags on primary cables |
| 82                | Missing voltage tags on primary cables |
| 83                | Missing voltage tags on primary cables |
| 84                | Missing voltage tags on primary cables |
| 85                | Missing voltage tags on primary cables |

**V. Observations**

**1. GO 95, Rule 18-A, Resolution of Potential Violations of General Order 95 and Safety Hazards** states in part:

- (2) *“Where a communications company’s or an electric utility’s (Company A’s) actions result in potential violations of GO 95 for another entity (Company B), that entity’s (Company B’s) remedial action will be to transmit a single documented notice of identified potential violations to the communications company or electric utility (Company A) within a reasonable amount of time not to exceed 180 days after the entity discovers the potential violations of GO 95. If the potential violation constitutes a Safety Hazard, such notice shall be transmitted within ten (10) business days after the entity discovers the Safety Hazard.*
- (3) *If a company, while performing inspections of its facilities, discovers a Safety Hazard(s) on or near a communications facility or electric facility involving another company, the inspecting company shall notify the other entity of such Safety Hazard(s) no later than ten (10) business days after the discovery.*
- (4) *To the extent a company that has a notification requirement under (2) or (3) above cannot determine the facility owner/operator, it shall contact the pole owner(s) within ten (10) business days if the subject of the notification is a Safety Hazard, or otherwise within a reasonable amount of time not to exceed 180 days after discovery. The notified pole owner(s) shall be responsible for promptly (normally not to exceed five business days) notifying the company owning/operating the facility if the subject of the notification is a Safety Hazard, or otherwise within a reasonable amount of time not to exceed 180 days, after being notified of the potential violation of GO95.”*

Table 9 includes all non-Ukiah (third-party) findings that ESRB observed during the audit:

**Table 9: Observations**

| <b>Location #</b> | <b>Observations</b>   |
|-------------------|---|
| 23                | Pole not fully removed by third party                         |
| 37                | Exposed ground wire   |
| 47                | Exposed ground wire   |
| 49                | Loose down guy, communications cable in contact with down guy |
| 73                | Exposed ground wire   |
| 80                | Exposed ground wire   |