

## PUBLIC UTILITIES COMMISSION

505 VAN NESS AVENUE  
SAN FRANCISCO, CA 94102-3298



June 7, 2026

CA2026-1347

Judy Geise  
Regulatory Manager  
Frontier Communications  
1919 McKinney Avenue  
Dallas, TX 75201

Subject: Audit of Frontier's Yucca Valley District

Ms. Geise:

On behalf of the Electric Safety and Reliability Branch of the California Public Utilities Commission (CPUC), James Miller of my staff conducted a communications infrastructure provider audit of Frontier's Yucca Valley District from April 6-10, 2026. The audit included a review of Frontier's records and field inspections of Frontier's facilities.

During the audit, my staff identified violations of one or more General Orders (GOs). A copy of the audit findings itemizing the violations is enclosed. Please advise me no later than July 8, 2026, by electronic or hard copy, of all corrective measures taken by Frontier to remedy and prevent such violations. Please note that ESRB will be posting the audit report and your response to our audit on the CPUC website. If there is any information in your response that you would like us to consider as confidential, we request that in addition to your confidential response, you also provide us with a public or redacted version of your response that can be posted publicly on our website.

If you have any questions concerning this audit, you can contact James Miller at (213) 660-8898 or [James.Miller@cpuc.ca.gov](mailto:James.Miller@cpuc.ca.gov).

Sincerely,

A handwritten signature in black ink that reads "Majed Ibrahim".

Majed Ibrahim, P.E.  
Program and Project Supervisor  
Electric Safety and Reliability Branch  
Safety and Enforcement Division  
California Public Utilities Commission

Enclosures: Audit Findings

Cc: Leslie Palmer, Deputy Executive Director for Safety Enforcement, Safety Policy and Water, CPUC  
Eric Wu, Program Manager, ESRB, SED, CPUC  
Saimon Islam, Senior Utilities Engineer (Supervisor), ESRB, SED, CPUC  
James Miller, Utilities Engineer, ESRB, SED, CPUC

## AUDIT FINDINGS

### I. Records Review

My staff reviewed the following records during the audit:

- Inspection records
- Work order and notification records
- Third party notifications
- Pole loading calculation records
- Inspection and maintenance procedures

### II. Records Review – Violations List

My staff observed the following violations during the records review portion of the audit:

**GO 95, Rule 18-B1, Maintenance Programs**, states in part:

*Companies shall undertake corrective actions within the time periods stated for each of the priority levels set forth below. Scheduling of corrective actions within the time periods below may be based on additional factors, including the following factors, as appropriate ...*

**GO 95, Rule 31.1, Design, Construction and Maintenance**, states in part:

*For all particulars not specified in these rules, design, construction, and maintenance should be done in accordance with accepted good practice for the given local conditions known at the time by those responsible for the design, construction, or maintenance of communication or supply lines and equipment.*

Frontier's records indicated that during the twelve months prior to the audit, Frontier completed 23 work orders past Frontier's due date for corrective action. Additionally, as of the audit, Frontier had 33 open work orders that were past Frontier's scheduled due date for corrective action.

**GO 95, Rule 80.1-A4, Record Keeping**, states:

*Each company shall maintain records for at least ten (10) years that provide the following information for each facility subject to this rule: The location of the facility, the date of each inspection of the facility, the results of each inspection, the personnel who performed each inspection, the date and description of each corrective action, and the personnel who performed each correction action. Commission staff shall be permitted to inspect records consistent with Public Utilities Code Section 314 (a).*

Frontier's work order records showed that work order No. T-00326676 had been completed on November 10, 2025 for a pole located at 34.1389193 °N, 116.4154287 °W. The work order record indicated that it had been generated because of a clearance or separation issue. My staff went to this location and found that Pole No. 1555856E matched Frontier's coordinates for this work order but also

observed that Frontier’s facilities were still in contact with a third-party communications conductor at this pole.

### III. Field Inspections

My staff inspected the following structures during the field inspection portion of the audit:

No.	Facility ID No.	Facility Type	City	Coordinates
1	40392S	Utility Pole	29 Palms	34.12087 °N , 116.03461 °W
2	243232S	Utility Pole	29 Palms	34.12082 °N , 116.03526 °W
3	1779332E	Utility Pole	29 Palms	34.12083 °N , 116.03578 °W
4	8519CWT	Utility Pole	29 Palms	34.12075 °N , 116.03579 °W
5	2233011E	Utility Pole	29 Palms	34.12083 °N , 116.03620 °W
6	22815CWT	Utility Pole	29 Palms	34.12047 °N , 116.03578 °W
7	40350	Utility Pole	29 Palms	34.12023 °N , 116.03577 °W
8	22816CWT	Utility Pole	29 Palms	34.11987 °N , 116.03574 °W
9	40351	Utility Pole	29 Palms	34.11952 °N , 116.03575 °W
10	40409S	Utility Pole	29 Palms	34.11918 °N , 116.03574 °W
11	40352	Utility Pole	29 Palms	34.11891 °N , 116.03574 °W
12	22817CWT	Utility Pole	29 Palms	34.11864 °N , 116.03574 °W
13	40393S	Utility Pole	29 Palms	34.12086 °N , 116.03407 °W
14	4938649E	Utility Pole	29 Palms	34.12086 °N , 116.03284 °W
15	5000380E	Utility Pole	29 Palms	34.12086 °N , 116.03284 °W
16	41936	Utility Pole	29 Palms	34.14427 °N , 116.08510 °W
17	4999957E	Utility Pole	29 Palms	34.14426 °N , 116.08573 °W
18	4035342E	Utility Pole	29 Palms	34.14428 °N , 116.08467 °W
19	32567CWT	Utility Pole	29 Palms	34.14519 °N , 116.08510 °W
20	4712293E	Utility Pole	29 Palms	34.14519 °N , 116.08542 °W
21	No ID Tag	Handhole	29 Palms	34.14519 °N , 116.08542 °W
22	4036700E	Utility Pole	29 Palms	34.14518 °N , 116.08606 °W
23	20834CWT	Utility Pole	29 Palms	34.14516 °N , 116.08662 °W
24	43321	Utility Pole	29 Palms	34.14521 °N , 116.08458 °W
25	47950CWT	Utility Pole	29 Palms	34.14608 °N , 116.08491 °W
26	43325	Utility Pole	29 Palms	34.14606 °N , 116.08541 °W
27	4851013E	Utility Pole	29 Palms	34.14607 °N , 116.08590 °W
28	No ID Tag	Pull Box	Joshua Tree	34.13920 °N , 116.21216 °W
29	4850514E	Utility Pole	Joshua Tree	34.14049 °N , 116.31308 °W
30	41383	Utility Pole	Joshua Tree	34.14089 °N , 116.31309 °W
31	4961531E	Utility Pole	Joshua Tree	34.14116 °N , 116.31308 °W
32	4036394E	Utility Pole	Joshua Tree	34.14155 °N , 116.31309 °W
33	41385	Utility Pole	Joshua Tree	34.14157 °N , 116.31264 °W
34	27354CWT	Utility Pole	Joshua Tree	34.14156 °N , 116.31214 °W

35	2231203E	Utility Pole	Joshua Tree	34.14156 °N , 116.31165 °W
36	41387S	Utility Pole	Joshua Tree	34.14157 °N , 116.31118 °W
37	GT119334	Utility Pole	Joshua Tree	34.14150 °N , 116.31093 °W
38	No ID Tag	Utility Pole	Joshua Tree	34.14202 °N , 116.31092 °W
39	No ID Tag	Utility Pole	Joshua Tree	34.14229 °N , 116.31092 °W
40	41388	Utility Pole	Joshua Tree	34.14138 °N , 116.31321 °W
41	30189CWT	Utility Pole	Joshua Tree	34.14103 °N , 116.31361 °W
42	41891S	Utility Pole	Joshua Tree	34.14069 °N , 116.31404 °W
43	1607038	Utility Pole	Joshua Tree	34.14059 °N , 116.31392 °W
44	2292429E	Utility Pole	Joshua Tree	34.16866 °N , 116.31292 °W
45	2292430E	Utility Pole	Joshua Tree	34.16924 °N , 116.31293 °W
46	2292431E	Utility Pole	Joshua Tree	34.16980 °N , 116.31293 °W
47	No ID Tag	Utility Pole	Joshua Tree	34.17039 °N , 116.31293 °W
48	2292433E	Utility Pole	Joshua Tree	34.17095 °N , 116.31292 °W
49	T-2793	Pedestal	Joshua Tree	34.16894 °N , 116.31292 °W
50	1607120E	Utility Pole	Joshua Tree	34.16792 °N , 116.31292 °W
51	No ID Tag	Handhole	Joshua Tree	34.14851 °N , 116.30742 °W
52	No ID Tag	Handhole	Joshua Tree	34.14849 °N , 116.30815 °W
53	No ID Tag	Handhole	Joshua Tree	34.14833 °N , 116.30805 °W
54	No ID Tag	Handhole	Joshua Tree	34.14834 °N , 116.30708 °W
55	No ID Tag	Handhole	Joshua Tree	34.14850 °N , 116.30703 °W
56	No ID Tag	Handhole	Joshua Tree	34.14836 °N , 116.30659 °W
57	No ID Tag	Handhole	Joshua Tree	34.14850 °N , 116.30627 °W
58	No ID Tag	Handhole	Joshua Tree	34.14836 °N , 116.30574 °W
59	No ID Tag	Handhole	Joshua Tree	34.14854 °N , 116.30552 °W
60	No ID Tag	Handhole	Joshua Tree	34.14837 °N , 116.30504 °W
61	No ID Tag	Handhole	Joshua Tree	34.14852 °N , 116.30476 °W
62	No ID Tag	Handhole	Joshua Tree	34.14852 °N , 116.30476 °W
63	No ID Tag	Handhole	Joshua Tree	34.14852 °N , 116.30382 °W
64	342129	Utility Pole	Joshua Tree	34.11889 °N , 116.34428 °W
65	341826	Utility Pole	Joshua Tree	34.11990 °N , 116.34424 °W
66	No ID Tag	Pedestal	Joshua Tree	34.11989 °N , 116.34427 °W
67	No ID Tag	Utility Pole	Joshua Tree	34.11993 °N , 116.34412 °W
68	GT112771	Stub Pole w/Repeater	Joshua Tree	34.11991 °N , 116.34395 °W
69	No ID Tag	Utility Pole	Joshua Tree	34.12036 °N , 116.34410 °W
70	4967129E	Utility Pole	Pioneertown	34.15341 °N , 116.49383 °W
71	4967128E	Utility Pole	Pioneertown	34.15309 °N , 116.49375 °W
72	4667877E	Utility Pole	Pioneertown	34.15205 °N , 116.49389 °W
73	4037551E	Utility Pole	Pioneertown	34.15108 °N , 116.49379 °W
74	4742671E	Utility Pole	Pioneertown	34.15386 °N , 116.49384 °W
75	4036565E	Utility Pole	Pioneertown	34.15476 °N , 116.49383 °W

76	No ID Tag	Utility Pole	Pioneertown	34.15531 °N , 116.49384 °W
77	4967131E	Utility Pole	Pioneertown	34.15597 °N , 116.49345 °W
78	1742841E	Utility Pole	Rimrock	34.20414 °N , 116.49378 °W
79	No ID Tag	Pedestal	Rimrock	34.20414 °N , 116.49378 °W
80	1742483E	Utility Pole	Rimrock	34.20511 °N , 116.49507 °W
81	1742484E	Utility Pole	Rimrock	34.20511 °N , 116.49507 °W
82	1742485E	Utility Pole	Rimrock	34.20616 °N , 116.49507 °W
83	1742486E	Utility Pole	Rimrock	34.20616 °N , 116.49507 °W
84	1742488E	Utility Pole	Rimrock	34.20616 °N , 116.49507 °W
85	1741334E	Utility Pole	Rimrock	34.20616 °N , 116.49507 °W
86	GT11663	Utility Pole	Rimrock	34.20616 °N , 116.49746 °W
87	No ID Tag	Utility Pole	Yucca Valley	34.18587 °N , 116.39483 °W
88	2107730E	Utility Pole	Yucca Valley	34.18602 °N , 116.39475 °W
89	2107731E	Utility Pole	Yucca Valley	34.18657 °N , 116.39450 °W
90	2107732E	Utility Pole	Yucca Valley	34.18708 °N , 116.39426 °W
91	2107737E	Utility Pole	Yucca Valley	34.18637 °N , 116.39388 °W
92	2107738E	Utility Pole	Yucca Valley	34.18630 °N , 116.39373 °W
93	2107484E	Utility Pole	Yucca Valley	34.10852 °N , 116.44362 °W
94	T-3046	Pedestal	Yucca Valley	34.10835 °N , 116.44359 °W
95	4967487E	Utility Pole	Yucca Valley	34.10795 °N , 116.44359 °W
96	4967488E	Utility Pole	Yucca Valley	34.10752 °N , 116.44361 °W
97	No ID Tag	Pedestal	Yucca Valley	34.10752 °N , 116.44361 °W
98	2311838E	Utility Pole	Yucca Valley	34.10660 °N , 116.44361 °W
99	P-3049	Pedestal	Yucca Valley	34.10661 °N , 116.44359 °W
100	4573628E	Utility Pole	Yucca Valley	34.10579 °N , 116.44357 °W
101	T-3702	Pedestal	Yucca Valley	34.10577 °N , 116.44366 °W
102	4766357E	Utility Pole	Yucca Valley	34.10577 °N , 116.44310 °W
103	4812586E	Utility Pole	Yucca Valley	34.10577 °N , 116.44260 °W
104	T-1456	Pedestal	Yucca Valley	34.10578 °N , 116.44259 °W
105	No ID Tag	Handhole	Yucca Valley	34.10851 °N , 116.43989 °W
106	T1757718	Handhole	Yucca Valley	34.10880 °N , 116.43978 °W
107	T1757721	Handhole	Yucca Valley	34.10943 °N , 116.43942 °W
108	No ID Tag	Handhole	Yucca Valley	34.10944 °N , 116.43878 °W
109	T1757722	Handhole	Yucca Valley	34.10943 °N , 116.43811 °W
110	No ID Tag	Handhole	Yucca Valley	34.10944 °N , 116.43746 °W
111	T1757724	Handhole	Yucca Valley	34.10946 °N , 116.43681 °W
112	No ID Tag	Handhole	Yucca Valley	34.10946 °N , 116.43681 °W
113	40412	Utility Pole	29 Palms	34.16095 °N , 116.03214 °W
114	40667	Utility Pole	29 Palms	34.15541 °N , 116.05328 °W
115	40034	Utility Pole	29 Palms	34.13278 °N , 116.08309 °W
116	1802397E	Utility Pole	29 Palms	34.18103 °N , 116.42266 °W

117	1555856E	Utility Pole	29 Palms	34.13932 °N , 116.41772 °W
118	4967417E	Utility Pole	29 Palms	34.13891 °N , 116.41542 °W
119	6495	Utility Pole	29 Palms	34.10655 °N , 116.41440 °W
120	4537845E	Utility Pole	Yucca Valley	34.11182 °N , 116.47552 °W
121	4328391E	Utility Pole	Yucca Valley	34.11451 °N , 116.46796 °W
122	4328393E	Utility Pole	Yucca Valley	34.11458 °N , 116.46676 °W

#### IV. Field Inspection – Violations List

**GO 95, Rule 31.1, Design, Construction and Maintenance**, states in part:

*Electrical supply and communication systems shall be designed, constructed, and maintained for their intended use, regard being given to the conditions under which they are to be operated, to enable the furnishing of safe, proper, and adequate service.*

My staff observed broken lashing wire near Pole No. 4999957E and Pole No. 4850514E.

My staff observed that two aerial terminals were missing their covers near Pole No. 4036565E.

**GO 95, Rule 31.6, Abandoned Lines**, states:

*Lines or portions of lines permanently abandoned shall be removed by their owners so that such lines shall not become a public nuisance or a hazard to life or property. For the purposes of this rule, lines that are permanently abandoned shall be defined as those lines that are determined by their owner to have no foreseeable future use.*

My staff found that the following Frontier facilities had been abandoned without having been removed:

- Two cut and dangling service drops attached to Pole No. 1779332E
- A service drop, cut and in contact with the ground, attached to Pole No. 2231203E
- A service drop, cut and in contact with the ground, attached to Pole No. 41891S
- A service drop attached to Pole No. 6495
- Multiple service drops midspan just east of Pole No. 4999957E

**GO 95, Rule 92.4-D1 – Exposed Cables and Messengers** states in part:

*The exposed communications conductors and messengers shall be grounded: At all deadend poles and at intervals not greater than every one-quarter of a mile (1320 feet).*

My staff observed that Frontier communications conductors and messengers were not grounded at the following dead-end poles:

- 1607038E
- 2292433E
- 4967131E
- 1742841E
- 1742486E
- 2311838E
- GT119334

**GO 95, Rule 38 - Minimum Clearances of Wires from Other Wires, Table 2, Column C, Case 8,** requires the minimum vertical clearance of “Communication Conductors (Including Open Wire, Cables and Service Drops),” and “Communication Conductors and Supply Drops” supported on the same pole to be 12 inches.

My staff observed that Frontier communications conductors were in contact with third-party communications conductors on or near each of the following poles:

- 40392S
- 243232S
- 22815CWT
- 40351
- 5000380E
- 4999957E
- 32567CWT
- 4712293E
- 4036700E
- 20834CWT
- 43321
- 47950CWT
- 4851013E
- 4961531E
- 4036394E
- 41385
- 27354CWT
- 2231203E
- 41387S
- GT119334
- 30189CWT
- 2292429E
- 2292430E
- 2292431E
- The tagless pole north of 2292431E
- 2292433E
- 1607120E
- 341826
- 2107730E
- 2107731E
- 2107732E
- 2107738E
- 4967487E
- 4967488E
- 4573628E
- 6495
- 1555856E

**GO 128, Rule 17.1, Design, Construction and Maintenance,** states in part:

*For all particulars not specified in these rules, design, construction, and maintenance should be done in accordance with accepted good practice for the given local conditions known at the time by those responsible for the design, construction, or maintenance of [the] communication or supply lines and equipment.*

My staff observed that Pedestal No. T2793 was damaged and appeared to have been knocked over.

My staff also observed that Pedestal No. T1456 was partially buried in the soil.

**GO 128, Rule 42.7, Covers,** states in part:

*Manholes and handholes, while not being worked in shall be securely closed by covers of sufficient strength to sustain such loads as may reasonably be imposed upon them, and arrangement shall be such that a tool or appliance shall be required for their opening and cover removal.*

My staff found that none of the handholes inspected required a tool or appliance for the removal of their covers; all twenty-two could be opened by hand.

**GO 95, Rule 38, Minimum Clearances of Wires from Other Wires, Table 2, Column C, Case 19** requires the minimum radial clearance between guys and span wires passing communications conductors supported on the same pole to be three inches.

My staff observed that Frontier conductors were in contact with third-party down guy wires on or near the following poles:

- 4967129E
- 4967131E
- 2311838E

**GO 95, Rule 91.3, Stepping, Section B., Location of Steps**, states in part:

*The lowest step shall be not less than 8 feet from the ground line, or any easily climbable foreign structure from which one could reach or step. Above this point steps shall be placed, with spacing between steps on the same side of the pole not exceeding 36 inches, at least to that conductor level above which only circuits operated and maintained by one party remain. Steps or fixtures for temporary steps shall be installed as part of a pole restoration process. Steps shall be so placed that runs or risers do not interfere with the free use of the steps.*

My staff observed that the lowest pole step on each of the following poles was located at a height of less than 8 feet:

- 41383
- 40034

**GO 95, Rule 84.4-A3, Clearances Above Ground [in areas] Accessible to Pedestrians Only**, states:

*Communication conductors of not more than 160 volts which transmit not more than 50 watts and communication cables having grounded metal sheaths may have a clearance above ground accessible to pedestrians only less than as specified in Table 1, Case 5, Column B, (10 feet) but not less than 8 feet*

My staff observed six instances of Frontier conductors in areas accessible to pedestrians only with less than eight feet of ground clearance:

- A Frontier hardline conductor at a height of 6.5 feet near Pole No. 2233011E.
- A Frontier service drop at a height of 5 feet near Pole No. 4667877E.
- A Frontier service drop in contact with the ground near Pole No. 4037551E.
- A Frontier service drop at a height of 6 feet near Pole No. 1741334E.
- A Frontier service drop in contact with the ground near Pole No. 40667.
- A Frontier service drop at a height of 5 feet near Pole No. 6495.

**87.7 Covering or Guarding D. Risers (1) Covered from Ground Level to 8 Feet above the Ground:**

*Risers shall be protected from the ground level to a level not less than 8 feet above the ground by:*

*(a) Securely or effectively grounded iron or steel pipe (or other covering at least of equal strength). When metallic sheathed cable rising from underground non-metallic conduit is protected by metallic pipe or moulding, such pipe or moulding shall be effectively grounded as specified in Rule 21.4-A, or*

*(b) Non-metallic conduit or rigid U-shaped moulding. Such conduit or moulding shall be of material as specified in Rule 22.8.*

My staff observed that a hardline riser supported on Pole No. 4938649E was not securely attached to the surface of the pole and lacked a protective conduit or covering.

My staff also observed that a fiber optic riser supported on Pole No. 342129 was not securely attached to the surface of the pole and lacked a protective conduit or covering.

My staff found that multiple service drops on Pole No. 2107732E were not secured to the pole or protected by a conduit or molding.