

CPUC SUBSTATION AUDIT FINDINGS
PG&E Vaca Dixon Headquarters
December 4 – 8, 2023

I. Records Review

During the substation audit, Electric Safety and Reliability Branch (ESRB) reviewed the following standards, procedures, and records for PG&E's Vaca Dixon Headquarters (HQ):

- List of all PG&E substations in the Vaca Dixon HQ
- Map showing all PG&E substation locations in the Vaca Dixon HQ
- PG&E Substation Maintenance and Construction (SM&C) Manual, Utility Standard: TD-3322M, Revision 11, with forms 1, 2, 5, 6, and 7
- PG&E Substation Equipment Maintenance Requirements, Utility Standard: TD-3322S, Revision 9, with attachments 2 through 12
- PG&E Substation Supplemental Inspection Program, Utility Standard: TD-3328S, Revision 2
- PG&E Substation Asset Performance Management (APM) Process, Utility Procedure: TD-3320P-36, Revision 0
- PG&E Substation SAP Work Management System (WMS) Process, Utility Procedure: TD-3320P-12, Revision 7
- PG&E SM&C Manual – Infrared Inspections, Utility Standard: TD-3322M, Revision 11
- PG&E SM&C Manual – Insulating Oil, Utility Standard: TD-3322M, Revision 8
- PG&E Accumulated Critical Current (ACC) Process, Utility Standard: TD-3320P-12, Revision 0
- PG&E SM&C Manual – Substation Batteries, Utility Standard: TD-3322M, Revision 13
- PG&E Substation Fire Protection Systems and Equipment – Inspection, Test and Maintenance: TD-3320P-07, Revision 3
- Explanation of PG&E inspector training policies
- List of the previous five years' substation inspections
- List of all open/pending, completed, cancelled, and late work orders, or what PG&E refers to as Line Corrective (LC) Notifications, in the previous five years
- Equipment lists for ESRB selected substations
- Single-line diagrams of ESRB selected substations
- Last two visual inspection checklists for ESRB selected substations
- List of transformer banks that operated beyond nameplate capacity for the last five years for ESRB selected substations.
- Infrared Testing records for ESRB selected substations in the last 24 months
- Most recent oil sample test results for ESRB selected substations
- Most recent electric test results for ESRB selected substations
- Training records for all substation and maintenance personnel in the past five years
- Other relevant substation inspections for the past five years for ESRB selected substations
- PG&E internal audit findings for Vaca Dixon HQ for the past five years

II. Records Violations

ESRB observed the following violations during the records review portion of the audit:

1. General Order (GO) 174, Rule 12, General states in part:

“Design, construction and maintenance should be performed in accordance with accepted good practices for the given local conditions known at the time by those responsible.”

PG&E Substation Equipment Maintenance Requirements, Utility Standard: TD-3322S¹, establishes PG&E’s required end dates and out-of-compliance dates as follows:

Table 1: Due Dates Per Priority Code

Priority Code	Required End Date	Out-of-Compliance Date
A	Within 30 days	Close notifications (after removing the hazard [make safe] with either permanent or temporary repairs within 30 days. Create a new lower priority notification immediately for any remaining work that will exceed 30 days.
B	Within 90 days	The out-of-compliance date is the 1 st day of the 2 nd month following the month in which the repair date occurs.
E	Within 365 days	The out-of-compliance date is the 1 st day of the year following the year in which the required end date occurs.
F	Greater than 365 days	There is no out-of-compliance date. This work will be completed when it is operationally efficient to perform the work.

Based on Table 1 above, ESRB noted four LC notifications that were closed after their out-of-compliance (OOC) date. Therefore, PG&E did not perform maintenance in accordance with accepted good practices described in Utility Standard TD-3322S. See Table 2 below for the past-due LC notifications.

Table 2: Overdue LC Notifications

Notification Number	Priority	Notification Date	Completion Date	Out-of-Compliance Date	Days Late
118278788	E	12/11/2019	2/18/2021	1/1/2021	48
117665050	B	7/11/2019	12/10/2019	12/1/2019	9
115132742	E	11/1/2018	1/10/2020	1/1/2020	9
117966267	A	9/6/2019	10/7/2019	10/6/2019	1

PG&E Response:

We are committed to responding to all priority A notifications immediately, to prevent and mitigate any found safety and reliability issues and risks. Additionally, our intent is to have all priority A notifications closed out within our system of record, SAP within 30 days.

¹ PG&E Utility Standard TD-3322S, August 3, 2023, Revision 9.

We agree that our closure notification reflected 10/7/2019, however we disagree it was past due the compliance due date. Due to a clerical error, the actual start date was 10/6/2019 (not 9/6/2019) and corrective work was completed on 10/7/2019.

We agree that we completed priority B notification 117665050 9 days past the OOC date. This notification was inadvertently created as an E priority originally. Once the error was found, all work was scheduled and completed as soon as possible. This error type was found to be a systematic issue in 2020, upon discovery, we created CAP 120564870, which lead to the automation of infrared hot-spot notifications in AssetWise Performance Management (APM).

We would like to note that as requested by ESRB, we provided 5 years' worth of data, in which, 614 priority A and B notifications were created. Although the 2 notifications above (1 priority A and 1 priority B) were completed past the OOC date in 2019, this data strongly indicates that we are actively striving to and successfully completing priority A and B notifications timely.

Additionally, we agree that the 2 priority E notifications listed above were completed past their out-of-compliance dates.

III. Field Inspection

During the field inspection, ESRB inspected the following substations:

Substation	City
Vacaville	Vacaville
Peabody	Fairfield
Maine Prairie	Dixon
Jameson	Cordelia
Cordelia	Cordelia
Suisun	Fairfield
Winters	Winters
Madison	Madison
Rice	Princeton
Colusa	Colusa
Colusa Junction	Colusa
Maxwell	Maxwell
Williams	Williams
Arbuckle	Arbuckle
Dunnigan	Dunnigan
Reclamation District #108	Knights Landing
Reclamation District #2047	Knights Landing

Knights Landing	Knights Landing
Woodland	Woodland
West Sacramento	West Sacramento
Deepwater	West Sacramento
Reclamation District #999	Clarksburg
Grand Island	Ryde

IV. Field Inspection – Violations List

ESRB observed the following violations during the field inspection:

GO 174, Rule 12, General states in part:

“...Substations shall be designed, constructed and maintained for their intended use, regard being given to the conditions under which they are to be operated, to promote the safety of workers and the public and enable adequacy of service.

Design, construction, and maintenance should be performed in accordance with accepted good practices for the given local conditions known at the time by those responsible.”

PG&E Response:

We appreciate the insight and feedback from the ESRB, as well as the support in helping us achieve our stand that everyone and everything is always safe. We agree with 18 of the ESRB’s findings of violation and are committed to remedying these issues and striving to reduce and eliminate such findings in the future. However, we do not believe some of the field observations qualify as violations of GO 174, Rule 12. Our Substation Inspection Program focuses on monthly and bi-monthly station inspections, along with our Enhanced Inspections (EI), Quality Verification (QV) audits, and Annual Infrared (IR) Inspections. These different levels of visual and technical assessments are conducted to indicate abnormal conditions before the equipment fails and to prevent unsafe events. Thirty-five of the ESRB’s observations made during the field portion of the audit were previously identified and properly recorded in our system of record (SAP) as abnormal conditions during planned inspections. Each of these notifications were identified timely by our Qualified Electrical Workers (QEWs) and scheduled for the appropriate corrective action in accordance with our maintenance standard/procedures and GO 174 requirements. Therefore, we do not believe that these 35 notifications qualify as GO 174, Rule 12 violations.

1. Vacaville Substation

- 1.1. The Warning and No Trespassing signs are posted on the inside of the substation fence, which obstructs the readability of the signs from the outside. According to PG&E’s Substation Maintenance and Construction Manual, Section V.A.1, Signs on Fences, Gates, and Entrances, PG&E must “Verify ‘Danger-High Voltage Inside, Unauthorized Persons Keep Out’ signs and ‘Notice: Private Property-No Trespassing’ signs are posted and legible on the outside of the security fences and on every access gate or entrance accessible to the public.”



PG&E Response:

We agree with the finding that the signs are posted inside the fence at Vacaville Substation. We created priority B notification 128116576, added it to the workplan, and will be completed based on current work prioritization and material availability.

1.2. There is a chipped insulator skirt on the Bank 1/7A switch.



PG&E Response:

We agree with the finding of a chipped insulator skirt on Bank 1/7A switch at Vacaville Substation. We created priority B notification 127544006, added it to the workplan, and will be completed based on current work prioritization and material availability.


1.3. Several distribution feeder circuit name labels are damaged.



PG&E Response:

We agree with the finding of damaged name labels on several Distribution feeders at Vacaville Substation. We created a CAP 12813998 for Distribution underground. This will be added to the workplan and will be completed based on current work prioritization and material availability.

1.4. There is an oil leak on a valve on Transformer Bank 3.



PG&E Response:

We agree with the finding of an oil leak at the valve on Transformer Bank 3 at Vacaville Substation. We created priority B notification 127544008, added it to the workplan, and will be completed based on current work prioritization and material availability.

2. Maine Prairie Substation

2.1. The pressure inside Transformer Bank 1, B-phase is at 0 psig. PG&E corrected the issue on site during the audit.



PG&E Response:

We agree with the finding that the pressure inside Transformer Bank 1, B phase was at 0 psig at Maine Prairie Substation. This issue was corrected onsite by PG&E QEW on the day of the field audit.

- 2.2. One of the perimeter fence posts is damaged. PG&E has an existing Notification #127475594 for this issue. PG&E repaired the damaged fence post on site during the audit.



PG&E Response:

We agree with the finding that the perimeter fence post was damaged at Maine Prairie Substation, but do not agree that the finding qualifies as a violation of GO 174, Rule 12. Our QEW identified this issue prior to the CPUC field audit and documented it in our system of record as a priority B notification, 127475594. This issue was corrected onsite by PG&E QEW on the day of the field audit.

- 2.3. The oil level gauge at the top of Transformer Bank 1, A phase is cracked. PG&E has

an existing Notification #127471812 for this issue. Additionally, this transformer bank is missing a pressure gauge. PG&E has an existing Notification #127475755 to add a pressure gauge.



PG&E Response:

We agree with the findings of a cracked oil level gauge and missing pressure gauge at Transformer Bank 1 A Phase at Maine Prairie Substation, but do not agree that these findings qualify as a violation of GO 174, Rule 12. Our QEW identified these issues prior to the CPUC field audit and documented it in our system of record as priority E notifications, 127471812 and 127475755. We will complete this work based on current work prioritization and material availability.

3. Jameson Substation

3.1. There is an oil leak on one of the high-side bushings on Transformer Bank 1. PG&E has an existing Notification #126747118 for this issue.



PG&E Response:

We agree with the finding that Transformer Bank 1 had an oil leak on the high side bushing at Jameson Substation, but do not agree that the finding qualifies as a violation of GO 174, Rule 12. Our QEW identified this issue prior to the CPUC field audit and documented it in our system of record as a priority E notification, 126747118. We completed the work on 01/10/2024.

4. Cordelia Substation

- 4.1. Several terminals on the DC batteries are corroded. PG&E has an existing Notification #127452622 for this issue. PG&E cleaned off the corrosion on site during the audit.



PG&E Response:

We agree with the finding that several of the DC batteries were corroded at Cordelia Substation, but do not agree that the finding qualifies as a violation of GO 174, Rule 12. Our QEW identified this issue prior to the CPUC field audit and documented it in our system of record as a priority E notification, 127452622. This issue was corrected onsite by PG&E QEW on the day of the field audit.

5. Suisun Substation

- 5.1. The measurement labels on the rightmost winding temperature gauge on Transformer 3 are illegible.



PG&E Response:

We agree with the finding that temperature gauge was illegible at Transformer Bank 3. We created priority B notification 127544007, added it to the workplan, and will be completed based on current work prioritization and material availability.

5.2. There are oil leaks behind the radiator fins on Transformer 3. PG&E has an existing Notification #127480052 for this issue.



PG&E Response:

We agree with the finding that Transformer Bank 3 had an oil leak behind the radiator at Suisun Substation, but do not agree that the finding qualifies as a violation of GO 174, Rule 12. Our QEW identified this issue prior to the CPUC field audit and documented it in our system of record as a priority B notification, 127480052. We completed this work on 01/2/2024.

5.3. There is a missing bolt on the Transformer 3 Load Tap Changer (LTC) compartment. PG&E has an existing Notification #127480199 for this issue.



PG&E Response:

We agree with the finding that Transformer Bank 3 had a missing bolt at Suisun Substation but do not agree that the finding qualifies as a violation of GO 174, Rule 12. Our QEW identified this issue prior to the CPUC field audit and documented it in our system of record as a priority E notification, 127480199. We will complete this work based on current work prioritization and material availability.

- 5.4. The insulator on the Potential Transformer for Bus D/1A, near Circuit Breaker 1100/2, is dirty, which increases the risk of insulator flashover. PG&E cleaned the insulator on site during the audit.



PG&E Response:

We agree with the finding that the Potential Transformer for Bus D/1A, near CB 1100/2 was dirty at Suisun Substation. This issue was corrected onsite by an PG&E QEW on the day of the field audit.

6. Madison Substation

6.1. The electrolytic solution in the DC batteries is low. PG&E has an existing Notification #127440643 for this issue.



PG&E Response:

We agree with the finding of DC batteries that had low electrolytic solution at Madison Substation, but do not agree that the finding qualifies as a violation of GO 174, Rule 12. Our QEW identified this issue prior to the CPUC field audit and documented it in our system of record as a priority B notification, 127440643. We completed this work on 12/28/2023.

6.2. There are abandoned bird nests obstructing the Transformer Bank 3 radiator fins. PG&E has an existing Notification #127440642 for this issue. PG&E cleaned the radiator fins on site during the audit.



PG&E Response:

We agree with the finding of birds' nests found in the radiator fans at Transformer Bank 3 at Madison Substation, but do not agree that the finding qualifies as a violation of GO 174, Rule 12. Our QEW identified this issue prior to the CPUC field audit and documented it in our system of record as a priority E notification, 127440642. This issue was corrected onsite by PG&E QEW on the day of the field audit.

7. Colusa Substation

7.1. The LTC temperature gauge for Transformer Bank 2 is not functioning. PG&E has an existing Notification #127476993 for this issue.



PG&E Response:

We agree with the finding that Colusa Substation had a non-functioning LTC temperature gauge at Transformer Bank 2, but do not agree that the finding qualifies as a violation of GO 174, Rule 12. Our QEW identified this issue prior to the CPUC field audit and documented it in our system of record as a priority E notification, 127476993. We will complete this work based on current work prioritization and material availability.

7.2. The animal abatement wrap around the low-side C phase center bushing on Transformer Bank 2 is falling off. PG&E has existing Notification #127476922 for this issue.



PG&E Response:

We agree with the finding that Transformer Bank 2 had animal abatement tape that was falling off around the low-side C phase center bushing, but do not agree that the finding qualifies as a violation of GO 174, Rule 12. Our QEW identified this issue prior to the CPUC field audit and documented it in our system of record as a priority E notification, 127476922. We will complete this work based on current work prioritization and material availability.

8. Maxwell Substation


8.1. The spare transformer bank has an air leak. The tank pressure read 0 psig. PG&E attempted to repressurize the tank during the audit, but the pressure went back down to 0 psig. PG&E has an existing Notification #127479606 for this issue.



PG&E Response:

We agree with the finding that the Spare Transformer Bank had an air leak at Jameson Substation, but do not agree that the finding qualifies as a violation of GO 174, Rule 12. Our QEW identified this issue prior to the CPUC field audit and documented it in our system of record as a priority B notification, 127479606. We completed this work on 01/13/2024.


8.2. An abandoned bird nest is blocking the bottom of a fan on the A phase Transformer Bank 1. PG&E has an existing Notification #127478865 for this issue. During the audit, PG&E removed the abandoned nest.



PG&E Response:

We agree with the finding of birds' nests found in the radiator fan at Transformer Bank 1, A phase at Maxwell Substation, but do not agree that the finding qualifies as a violation of GO 174, Rule 12. Our QEW identified this issue prior to the CPUC field audit and documented it in our system of record as a priority E notification, 127478865. This issue was corrected onsite by PG&E QEW on the day of the field audit.

8.3. The light socket in the Circuit Breaker 1100/2 cabinet is non-functional.




PG&E Response:

We agree with the finding that the light socket was non-functional at the Circuit Breaker 1100/2 cabinet. We created priority E notification 127548989, added it to the workplan, and will be completed based on current work prioritization and material availability.

9. Williams Substation

9.1. The pressure inside Transformer Bank 1 is at 0 psig. PG&E has an existing Notification #127448946 for this issue. PG&E corrected the issue on site during the audit.



PG&E Response:

We agree with the finding of 0 psig on the pressure valve at Transformer Bank 1 at Williams Substation, but do not agree that the finding qualifies as a violation of GO 174, Rule 12. Our QEW identified this issue prior to the CPUC field audit and documented it in our system of record as a priority B notification, 127448946. This issue was corrected onsite by an PG&E QEW on the day of the field audit.


9.2. The breaker position label on Circuit Breaker 1100/2 is faded and illegible. PG&E corrected the issue on site during the audit.



PG&E Response:

We agree with the finding of the illegible breaker position label on Circuit Breaker 1100/2 at Williams Substation. This issue was corrected onsite by an PG&E QEW on the day of the field audit.

9.3. The pressure inside Transformer Bank B is at 0 psig and the nitrogen bottle is empty. PG&E has an existing Notification #127448944 for this issue.




PG&E Response:

We agree with the finding of 0 psig on the pressure valve at Transformer Bank 2 (referred to as B on response) at Williams Substation, but do not agree that the finding qualifies as a violation of GO 174, Rule 12. Our QEW identified this issue prior to the CPUC field audit and documented it in our system of record as a priority B notification, 127448944. We completed this work on 12/14/2023.

10. Arbuckle Substation

10.1. The pressure inside the Spare Transformer Bank 1 is at 0 psig. PG&E has an



existing Notification #127473981 for this issue.

PG&E Response:

We agree with the finding of 0 psig on the Spare Transformer Bank pressure valve at Arbuckle Substation, but do not agree that the finding qualifies as a violation of GO 174, Rule 12. Our QEW identified this issue prior to the CPUC field audit and documented it in our system of record as a priority B notification, 127473981. We completed this work on 12/19/2023.

10.2. The pressure inside the C Phase Transformer Bank 1 is negative. PG&E has an existing Notification #127474415 for this issue. PG&E corrected the issue on site during the audit.



PG&E Response:

We agree with the finding of negative pressure on Transformer Bank 1, C phase at Arbuckle Substation, but do not agree that the finding qualifies as a violation of GO 174, Rule 12. Our QEW identified this issue prior to the CPUC field audit and documented it in our system of record as a priority B notification, 127474415. This issue was corrected onsite by PG&E QEW on the day of the field audit.

11. Reclamation District #108 Substation

11.1. The cover for the pressure gauge on the C Phase Transformer Bank 1 is missing. PG&E has an existing Notification #127432520 for this issue.



PG&E Response:

We agree with the finding that the cover was missing on the C Phase pressure gauge on Transformer Bank 1 at Reclamation District #108 Substation, but do not agree that the finding qualifies as a violation of GO 174, Rule 12. Our QEW identified this issue prior to the CPUC field audit and documented it in our system of record as a priority E notification, 127432520. We will complete this work based on current work prioritization and material availability.


11.2. The A Phase Transformer Bank 1 has an air leak. The tank pressure is at 0 psig. PG&E attempted to repressurize the tank during the audit, but the pressure went back down to 0 psig. PG&E has an existing Notification #127432528 for this issue.



PG&E Response:

We agree with the finding an A Phase Transformer Bank 1 air leak at Reclamation District #108 Substation, but do not agree that the finding qualifies as a violation of GO 174, Rule 12. Our QEW identified this issue prior to the CPUC field audit and documented it in our system of record as a priority E notification, 127432528. We will complete this work based on current work prioritization and material availability.

11.3. The B Phase Transformer Bank 1 is at 0 psig. PG&E has an existing Notification #127432529 for this issue. PG&E corrected this issue during the audit.



PG&E Response:

We agree with the finding of 0 psig on the air pressure valve at B Phase Transformer Bank 1 at Reclamation District #108 Substation, but do not agree that the finding qualifies as a violation of GO 174, Rule 12. Our QEW identified this issue prior to the CPUC field audit and documented it in our system of record as a priority E notification, 127432529. This issue was corrected onsite by PG&E QEW on the day of the field audit.

11.4. The Spare Transformer Bank 1 has an air leak. The tank pressure is at 0 psig. PG&E attempted to repressurize the tank during the audit, but the pressure went back down to 0 psig. PG&E has an existing Notification #127432621 for this issue.



PG&E Response:

We agree with the finding of 0 psig on Spare Transformer Bank 1 at Reclamation District #108 Substation, but do not agree that the finding qualifies as a violation of GO 174, Rule 12. Our QEW identified this issue prior to the CPUC field audit and documented it in our system of record as a priority B notification, 127432621. We completed this work on 01/13/2024.

11.5. There are multiple oil leaks on the A Phase Transformer Bank 1. PG&E has an existing Notification #127447656 for this issue.



PG&E Response:

We agree with the finding of multiple oil leaks on A Phase Transformer Bank 1 at Reclamation District #108 Substation, but do not agree that the finding qualifies as a violation of GO 174,

Rule 12. Our QEW identified this issue prior to the CPUC field audit and documented it in our system of record as a priority B notification, 127447656. We will complete this work based on current work prioritization and material availability.

11.6. There is an oil leak on the C Phase Transformer Bank 1 radiator flange. PG&E has an existing Notification #127432309 for this issue.



PG&E Response:

We agree with the finding of an oil leak on C Phase Transformer Bank 1 radiator flange at Reclamation District #108 Substation, but do not agree that the finding qualifies as a violation of GO 174, Rule 12. Our QEW identified this issue prior to the CPUC field audit and documented it in our system of record as a priority B notification, 127432309. We completed this work on 01/13/2024.


11.7. The paint on the C Phase Transformer Bank 1 is chipping off and leading to corrosion of the exposed metal. PG&E has an existing Notification #127432304 for this issue.



PG&E Response:

We agree with the finding of chipped paint on C Phase Transformer Bank 1 at Reclamation District #108 Substation, but do not agree that the finding qualifies as a violation of GO 174, Rule 12. Our QEW identified this issue prior to the CPUC field audit and documented it in our system of record as a priority E notification, 127432304. We will complete this work based on current work prioritization and material availability.

11.8. The paint on the B Phase Transformer Bank 1 is chipping off and leading to corrosion of the exposed metal. PG&E has an existing Notification #127432300 for this issue.



PG&E Response:

We agree with the finding of chipped paint on B Phase Transformer Bank 1 at Reclamation District #108 Substation, but do not agree that the finding qualifies as a violation of GO 174, Rule 12. Our QEW identified this issue prior to the CPUC field audit and documented it in our system of record as a priority E notification, 127432300. We will complete this work based on current work prioritization and material availability.

11.9. The paint on the Spare Transformer Bank 1 is chipping off and leading to corrosion of the exposed metal. PG&E has an existing Notification #127432306 for this issue.



PG&E Response:

We agree with the finding of chipped paint on Spare Transformer Bank 1 at Reclamation District #108 Substation, but do not agree that the finding qualifies as a violation of GO 174, Rule 12. Our QEW identified this issue prior to the CPUC field audit and documented it in our system of record as a priority E notification, 127432306. We will complete this work based on current work prioritization and material availability.

12. Reclamation District #2047 Substation

12.1. The substation's perimeter fence is damaged. PG&E has an existing Notification #127433231 for this issue.



PG&E Response:

We agree with the finding of a damaged perimeter fence at Reclamation District #2047

Substation, but do not agree that the finding qualifies as a violation of GO 174, Rule 12. Our QEW identified this issue prior to the CPUC field audit and documented it in our system of record as a priority B notification, 127433231. We completed this work on 01/10/2024.

12.2. There is an abandoned bird's nest obstructing the A Phase Transformer Bank radiator fins. PG&E has an existing Notification #127433013 for this issue. PG&E cleaned the radiator fins on site during the audit.



PG&E Response:

We agree with the finding of a bird's nest at A Phase Transformer Bank at Reclamation Dist #2047, but do not agree that the finding qualifies as a violation of GO 174, Rule 12. Our QEW identified this issue prior to the CPUC field audit and documented it in our system of record as a priority E notification, 127433013. This issue was corrected onsite by an PG&E QEW on the day of the field audit.

12.3. There is an abandoned bird's nest with hatched eggs obstructing the B Phase

Transformer Bank radiator fins. PG&E has an existing Notification #127433015 for this issue. PG&E cleaned the radiator fins on site during the audit.



PG&E Response:

We agree with the finding of a bird's nest at B Phase Transformer Bank at Reclamation Dist #2047, but do not agree that the finding qualifies as a violation of GO 174, Rule 12. Our QEW identified this issue prior to the CPUC field audit and documented it in our system of record as a priority E notification, 127433015. This issue was corrected onsite by an PG&E QEW on the day of the field audit.

12.4. There is an abandoned bird's nest obstructing the C Phase Transformer Bank radiator fins. PG&E has an existing Notification #127433017 for this issue. PG&E cleaned the radiator fins on site during the audit.



PG&E Response:

We agree with the finding of a bird's nest at C Phase Transformer Bank at Reclamation Dist #2047, but do not agree that the finding qualifies as a violation of GO 174, Rule 12. Our QEW identified this issue prior to the CPUC field audit and documented it in our system of record as a priority E notification, 127433017. This issue was corrected onsite by an PG&E QEW on the day of the field audit.

13. Woodland Substation

13.1. There are cracked insulator skirts on Air Switch 143. PG&E has an existing Notification #127475603 for this issue.



PG&E Response:

We agree with the finding of cracked insulator skirts on Air Switch 143 at Woodland Substation, but do not agree that the finding qualifies as a violation of GO 174, Rule 12. Our QEW identified this issue prior to the CPUC field audit and documented it in our system of record as a priority E notification, 127475603. We completed this work on 01/26/2024.

13.2. During a lamp test, ESRB observed burned out lights on the substation alarm annunciator panel.



PG&E Response:

We agree with the finding of the burned-out lights on the annunciator at Woodland Substation. We created priority B notification 127564455, added it to the workplan, and it will be completed based on current work prioritization and material availability.

13.3.The emergency first aid solutions expired on April 30, 2023.



PG&E Response:

We agree with the finding of the emergency first aid solutions being expired at Woodland Substation. We created priority E notification 128121182, added it to the workplan, and it will be completed based on current work prioritization and material availability.

13.4.The breaker operations counter on Circuit Breaker 1100/2 is faded. PG&E has an existing Notification #127476309 for this issue.



PG&E Response:

We agree with the finding of a faded counter on Circuit Breaker 1100/2 at Woodland Substation, but do not agree that the finding qualifies as a violation of GO 174, Rule 12. Our QEW identified this issue prior to the CPUC field audit and documented it in our system of record as a priority E notification, 127476309. We completed this work on 01/26/2024.

13.5. There is a leak on the Transformer Bank 1 LTC. PG&E has an existing Notification #127477505 for this issue.



PG&E Response:

We agree with the finding of a leak on Transformer Bank 1 LTC at Woodland Substation, but do not agree that the finding qualifies as a violation of GO 174, Rule 12. Our QEW identified this issue prior to the CPUC field audit and documented it in our system of record as a priority B notification, 127477505. This work was completed on 12/18/2023.

13.6. There is a leak on the flange to the oil conservator tank on Transformer Bank 2. PG&E has an existing Notification #127477501 for this issue.



PG&E Response:

We agree with the finding of a leak on Transformer Bank 2 at Woodland Substation, but do not agree that the finding qualifies as a violation of GO 174, Rule 12. Our QEW identified this issue prior to the CPUC field audit and documented it in our system of record as a priority B notification, 127477501. We completed this work on 12/18/2023.

13.7. The nitrogen bottle on Transformer Bank 3 is empty. PG&E installed a new nitrogen bottle on site during the audit to correct the issue.



PG&E Response:

We agree with the finding of the nitrogen bottle being empty on Transformer Bank 3 at Woodland Substation. This issue was corrected onsite by an PG&E QEW on the day of the field audit.

13.8. There is a leak on Transformer Bank 3. PG&E has an existing Notification

#127477504 for this issue.



PG&E Response:

We agree with the finding of a leak on Transformer Bank 3 at Woodland Substation, but do not agree that the finding qualifies as a violation of GO 174, Rule 12. Our QEW identified this issue prior to the CPUC field audit and documented it in our system of record as a priority B notification, 127477504. We completed this work on 12/18/2023.


13.9.The insulator skirt on Switch 1300/1B is chipped.



PG&E Response:

We agree with the finding of a chipped insulator skirt on Switch 1300/1B at Woodland Substation. We created priority B notification 127564453 and we completed this work on 01/25/2024.

13.10. The insulator skirt on Switch 1110/1C is chipped.




PG&E Response:

We agree with the finding of a chipped insulator skirt on Switch 1110/1C at Woodland Substation. We created priority B notification 127564452, added it to the workplan, and will be completed based on current work prioritization and material availability.

14. West Sacramento Substation

14.1. The nitrogen bottle on Transformer Bank 2 is empty. PG&E has an existing Notification #127429767 for this issue. PG&E installed a new nitrogen bottle on site during the audit to correct the issue.



PG&E Response:

We agree with the finding of an empty nitrogen bottle on Transformer Bank 2 at West Sacramento Substation, but do not agree that the finding qualifies as a violation of GO 174, Rule 12. Our QEW identified this issue prior to the CPUC field audit and documented it in our system of record as a priority B notification, 127429767. This issue was corrected onsite by a PG&E QEW on the day of the field audit.

14.2. The pressure inside Transformer Bank 3 is negative. PG&E began repressurizing the transformer on site during the audit to correct the issue.



PG&E Response:

We agree with the finding of negative pressure inside Transformer Bank 3 at West Sacramento Substation. This issue was corrected onsite by an PG&E QEW on the day of the field audit.

15. Reclamation District #999 Substation

15.1. The substation's grounding grid is exposed.




PG&E Response:

We agree with the finding of exposed ground grid at Reclamation District #999 Substation. We created priority A notification 127568956 and we completed this work on 12/20/2023.

16. Grand Island Substation


16.1. There are abandoned bird nests obstructing the operation of Fans 4 and 6 on Transformer Bank 3. PG&E corrected the issue on site during the audit.



PG&E Response:

We agree with the observation of bird nests on Transformer Bank 3 at Grand Island Substation. This issue was corrected onsite by an PG&E QEW on the day of the field audit.

16.2. The cover on the Transformer Bank 2, B phase winding temperature gauge is cracked.



PG&E Response:

We agree with the finding of a cracked Temperature Gauge cover on Transformer Bank 2 at Grand Island Substation. We created priority B notification 127568958, added it to the workplan, and will be completed based on current work prioritization and material availability.