



1919 McKinney Ave., Dallas, TX 75201
Frontier.com

SENT VIA ELECTRONIC MAIL

September 25, 2025

Fadi Daye, P.E.
Program and Project Supervisor
Electric Safety and Reliability Branch
Safety and Enforcement Division
California Public Utilities Commission

Re: Response to Frontier San Bernardino East Metropolitan District Audit Report

Dear Fadi Daye,

Frontier California Inc (U-1002-C) ("Frontier") hereby responds to the September 3, 2025 California Public Utilities Commission (Commission) audit report regarding the San Bernardino East Metropolitan District Communications Infrastructure Provider (CIP) Audit conducted July 7- 11, 2025.

I. Records Review

- Overhead detailed and patrol inspection records.
- Completed and pending corrective action work orders
- Pole loading calculations
- Frontier's Overhead Lines Maintenance Plan
- Frontier's Visual Inspections of Overhead Lines

II. Field Inspection

III. Field Inspection – Violations List

ESRB observed the following violations during the field inspections portion of the audit:

GO 95, Rule 31.1, Design, Construction and Maintenance, states in part:

Electrical supply and communication systems shall be designed, constructed, and maintained for their intended use, regard being given to the conditions under which they are to be operated, to enable the furnishing of safe, proper, and adequate service.

The Frontier facilities on each of the following poles required maintenance:

- The Frontier lashing wire supported on pole 1714996E was broken.
- The Frontier communication span supported on pole CIT37130 was attached to a third-party communication conductor via a rope.
- The Frontier ground wire attached to pole located at [REDACTED] Ave was damaged.
- A Frontier pole located at [REDACTED] Blvd had a rope tied around the pole.
- The Frontier service drop was not properly secured to pole 7407BV.

Response: Tickets were issued for the noted infractions. See the file "CA2025-1328 San Bernardino East Metro tickets.xls".

A damaged visibility strip was observed on each of the following poles:

- [REDACTED] St
- [REDACTED] St

Response: Tickets were issued for the noted infractions. See the file "Confidential CA2025-1328 San Bernardino East Metro.xls".

Incomplete pole transfer on each of the following poles:

- 1714999E
- 12690BV
- 4879008E
- 4631047E
- 3713BV
- 4879009E
- 1714995E
- 1056841E
- 1588994E

Response: Tickets were issued for the noted infractions. See the file "CA2025-1328 San Bernardino East Metro tickets.xls".

GO 95, Rule 91.3 Stepping, B. Location of Steps, states in part:

The lowest step shall be not less than 8 feet from the ground line, or any easily climbable foreign structure from which one could reach or step. Above this point steps shall be placed, with spacing between steps on the same side of the pole not exceeding 36 inches, at least to that conductor level above which only circuits operated and maintained by one party remain. Steps or fixtures for temporary steps shall be installed as part of a pole restoration process. Steps shall be so placed that runs or risers do not interfere with the free use of the steps.

The lowest pole step on each of the following poles was located at a height less than eight feet:

- [REDACTED] Blvd
- [REDACTED] St

Response: Tickets were issued for the noted infractions. See the file "CA2025-1328 San Bernardino East Metro tickets.xls".

GO 95, Rule 35, Vegetation Management, states in part:

When a supply or communication company has actual knowledge, obtained either through normal operating practices or notification to the company, that its circuit energized at 750 volts or less shows strain or evidences abrasion from vegetation contact, the condition shall be corrected by reducing conductor tension, rearranging or replacing the conductor, pruning the vegetation, or placing mechanical protection on the conductor(s).

A Frontier communication conductor attached to each of the following poles was strained by vegetation:

- 1261352E
- 405487E
- 1818829E
- 405486E
- 405488E
- 4323899E

The Frontier service drop attached to Pole 4450226E was strained by a tree branch.

Response: Tickets were issued for the noted infractions. See the file "CA2025-1328 San Bernardino East Metro tickets.xls".

GO 95, Rule 87.7-D1, Covered from Ground Level to 8 Feet above the Ground, states in part: *Risers shall be protected from the ground level to a level not less than 8 feet above the ground...*

The Frontier riser casing on pole 1818829E was missing.

Response: Ticket # T-00489855 was issued for the noted infractions. See the file "CA2025-1328 San Bernardino East Metro tickets.xls".

GO 95, Rule 38 - Minimum Clearances of Wires from Other Wires, Table 2, Column C, Case 8, requires the minimum vertical clearance of "Communication Conductors (Including Open Wire, Cables and Service Drops)," and "Communication Conductors and Supply Drops" supported on the same pole to be 12 inches.

Frontier communications conductor was in contact with a third-party communications conductor on or near each of the following poles:

- 405489E
- CIT37131

A Frontier communications service drop on Pole 4450226E was in contact with a third-party communication service drop.

Response: Tickets were issued for the noted infractions. See the file "CA2025-1328 San Bernardino East Metro tickets.xls".

GO 95, Rule 86.2, Use, states in part:

Guys shall be attached to structures as nearly as practicable at the center of load. They shall be maintained taut and of such strength as to meet the safety factors of Rule 44.

A Frontier down guy wire attached to each of the following poles was not taut:

- 1884601E
- 4323900E
- GT140867
- CIT37129
- 1056803E
- [REDACTED] St.
- 4323899E
- 2042510E

Response: Tickets were issued for the noted infractions. See the file "CA2025-1328 San Bernardino East Metro tickets.xls".

GO 95, Rule 31.6, Abandoned Lines, states:

Lines or portions of lines permanently abandoned shall be removed by their owners so that such lines shall not become a public nuisance or a hazard to life or property. For the purposes of this rule, lines that are permanently abandoned shall be defined as those lines that are determined by their owner to have no foreseeable future use.

Abandoned service drops were observed on or near the following poles:

- 1884601E
- 709873E
- [REDACTED] St.
- 1261353E
- 4691105E
- [REDACTED] Ave
- 405486E
- [REDACTED] St.
- 1215193E
- F15033Y
- 2042510E
- [REDACTED] Dr.
- 1056842E
- 4323900E

Response: Tickets were issued for the noted infractions. See the file "CA2025-1328 San Bernardino East Metro tickets.xls".

GO 95, Rule 86.9 - Guy Marker (Guy Guard), states in part:

A substantial marker of suitable material, including but not limited to metal or plastic, not less than 8 feet in length, shall be securely attached to all anchor guys. Where more than one guy is attached to an anchor rod, only the outermost guy is required to have a marker.

The marker (guard) on the down guy wire supporting each of the following poles was missing:

- 1714955E
- [REDACTED] St
- 2042510E

Response: Tickets were issued for the noted infractions. See the file "CA2025-1328 San Bernardino East Metro tickets.xls".

GO 95, Rule 38, Minimum Clearances of Wires from other Wires, Table 2, Case 8, Column D requires the vertical separation between secondary, and communications conductors supported on the same pole to be not less than 48 inches.

Frontier's service drop was in contact with an SCE's secondary service drop on Pole 1056803E.

Response: Tickets were issued for the noted infractions. See the file "CA2025-1328 San Bernardino East Metro tickets.xls".

GO 95, Rule 84.4-A6, Clearances, Across or Along Public Thoroughfares, states in part: *Communication conductors over or across public thoroughfares shall have a clearance of 18 feet above ground.*

- The above ground clearance of a Frontier conductor attached to Pole 2250603E was approximately 14 feet over a public thoroughfare.
- The above ground clearance of a Frontier conductor attached to Pole 4323899E was approximately 14 feet over a public thoroughfare.
- The above ground clearance of a Frontier conductor attached to Pole 549381E was approximately 14 feet over a public thoroughfare.

Response: Tickets were issued for the noted infractions. See the file "CA2025-1328 San Bernardino East Metro tickets.xls".

GO 128, Rule 17.1 – Design, Construction and Maintenance, states in part: *For all particulars not specified in these rules, design, construction, and maintenance should be done in accordance with accepted good practice for the given local conditions known at the time by those responsible for the design, construction, or maintenance of [the] communication or supply lines and equipment.*

The following facilities required maintenance:

- The cover of the underground vault located in front of [REDACTED] St was corroded.
- The cover of the pedestal T8167A was damaged.
- The cover of the pedestal T8169A was damaged.

Response: Tickets were issued for the noted infractions. See the file "CA2025-1328 San Bernardino East Metro tickets.xls".

Each of the following Frontier handhole covers was missing bolts (not properly secured):

- FT2055202
- FT2055203
- FT2055204
- H2051
- H2052

Response: Tickets were issued for the noted infractions. See the file "CA2025-1328 San Bernardino East Metro tickets.xls".

If you have any questions, please do not hesitate to contact me at 214-724-7719, or judy.geise@ftr.com.

Sincerely,

/s/ Judy Geise
Manager, Regulatory
Frontier
judy.geise@ftr.com

Attachment

cc:

Leslie Palmer, Director, Safety and Enforcement Division, CPUC
Eric Wu, Program Manager, ESRB, CPUC
Majed Ibrahim, Senior Utilities Engineer Supervisor, ESRB, SED, CPUC
Stacey Ocampo, Utilities Engineer, ESRB, SED, CPUC
SM Arafat Kamal, Utilities Engineer, ESRB, SED, CPUC
Jenny Smith, Director Government and Regulatory Affairs, Frontier



**FRONTIER DECLARATION FOR CONFIDENTIAL TREATMENT OF INFORMATION PROVIDED IN
RESPONSE TO SAN BERNARDINO EAST METRO AUDIT REPORT**

DECLARATION OF JUDY GEISE

I, JUDY GEISE, hereby declare:

1. I am Manager – Regulatory for Frontier California Inc (U-1002-C) (“Frontier”) and designated by Allison M. Ellis, Senior Vice President Business Development, of Frontier Communications Parent, Inc. (“Frontier”), the “Parent company” of Frontier California Inc. If called as a witness, I could and would competently testify as to the matters stated herein from my own personal knowledge, except as to any matters that I state upon information and belief, and as to those matters, I am informed and believe them to be true.

2. Pursuant to the California Public Utilities Commission’s rules governing the submission of confidential information by parties to Commission proceedings, as set forth in D.17-09-023, General Order (“G.O.”) 66-D, I submit this declaration in support of Frontier’s confidential designations of information contained in its attachments responsive to the San Bernardino East Metro Audit Report issued by the California Public Utilities Commission’s Electric Safety and Reliability Branch (ESRB) on September 3, 2025 (“San Bernardino Audit Report”).

3. I am familiar with the information contained in Frontier’s response to the San Bernardino Audit Report, portions of which Frontier has designated as confidential pursuant to Public Utilities Code Section 583 and Commission G.O. 66-D, Section 3.2(a)-(b). The information that Frontier has designated as confidential is appropriately marked and the factual basis for treating that information as confidential is as follows.

4. Frontier’s response “Frontier Confidential Response CA2025 1328_San Bernardino East Metro.pdf” contains street addresses for certain Frontier overhead and underground facilities included in the PUC audit field inspections. The response concerns Critical Infrastructure Information and is being voluntarily provided to the Commission in expectation of protection from disclosure as provided by 6 U.S.C. § 673(a)(1)(E). This information is therefore restricted from disclosure as material specifically precluded from disclosure by statute. *See* Cal. Gov’t. Code § 6254(k); *see also* Cal. Gov’t Code § 6254(e). The information is critical to maintaining the proper functioning and security of Frontier’s network. The public disclosure of this information would compromise network security and public safety. This information also constitutes a “compilation” of competitively sensitive information that derives economic, market and competitive value from not being known to the public or actual and potential competitors. *See* Evid. Code § 1060; Civ. Code § 3426.1(d); Government Code § 6254(k). If disclosed, Frontier’s competitors could leverage this information to direct their deployment, operations or marketing decisions to Frontier’s economic detriment, resulting in unfair competition and harm to the competitive market for telecommunications services.



5. I am not aware of any material public benefit to be advanced by releasing the information described in Paragraph 4 publicly. Any public benefit associated with the disclosure of this type of information is far outweighed by the extensive harm caused to the public interest and public safety that would occur from forcing Frontier to disgorge this information through the regulatory process and hand it over to its competitors. See Gov. Code § 6255(a).

6. For the foregoing reasons, I am informed and believe that the information described in Paragraph 4 is appropriate for confidential treatment and should be withheld from public view.

Dated this 25th day of September at Dallas, Texas.

/s/ Judy Geise
Manager, Regulatory Reporting

No.	Structure ID	Site	Structure T	Location
1	CRLNCAXF 1884601E		Pole	Crestline
4	CRLNCAXF GT140867		Pole	Crestline
5	CRLNCAXF 1056803E		Pole	Crestline
7	CRLNCAXF 2250603E		Pole	Crestline
11	CRLNCAXF 1261352E		Pole	Crestline
12	CRLNCAXF 1261353E		Pole	Crestline
13	ARHDCAXF 405486E		Pole	Lake Arrowhead
14	ARHDCAXF 405487E		Pole	Lake Arrowhead
15	ARHDCAXF 405488E		Pole	Lake Arrowhead
16	405489E		Pole	Lake Arrowhead
19	ARHDCAXF 1818829E		Pole	Lake Arrowhead
20	ARHDCAXF 4323899E		Pole	Lake Arrowhead
21	4323900E		Pole	Lake Arrowhead
23	ARHDCAXF 549381E		Pole	Lake Arrowhead
26	MSCYCAXF 4450226E		Pole	Muscoy
27	F15033Y	MSCYCAXF GT71155	Pole	Muscoy
29	18556 Arrowhead Blvd.		Pole	Muscoy
30	MSCYCAXF 1714955E		Pole	Muscoy
31	MSCYCAXF 1714999E		Pole	Muscoy
32	4631047E		Pole	Muscoy
34	1714996E	MSCYCAXF 1714996E	Pole	Muscoy
35	MSCYCAXF 1714995E		Pole	Muscoy
36	BBLKCAXF 37130.CIT		Pole	Big Bear Lake
37	BBLKCAXF 37131.CIT		Pole	Big Bear Lake
38	BBLKCAXF 37129.CIT		Pole	Big Bear Lake
40	BBLKCAXF 7407.BV		Pole	Big Bear Lake
45	12690BV		Pole	Big Bear Lake
49	3717BV	BBLKCAXF 13840BV	Pole	Big Bear Lake
52	RNSPCAXF 1056841.E		Pole	Running Springs
53	RNSPCAXF 1056842.E		Pole	Running Springs
55	4879008E		Pole	Running Springs
62	4879009E		Pole	Running Springs
64	709873E		Pole	Running Springs
67	103 E Ninth St.		Pole	San Bernardino
69	4691105E		Pole	San Bernardino
75	215 E Ninth St.		Pole	San Bernardino
76	SNBRCAK 2042510E		Pole	San Bernardino
87	1004 Columbia St.		Pole	Redlands
88	930 Columbia St.		Pole	Redlands
89	918 Columbia St.		Pole	Redlands
90	420 W Sun Ave.		Pole	Redlands
91	YUCPCAXF 1588994E		Pole	Yucaipa
95	YUCPCAXF 1215193E		Pole	Yucaipa
98	33792 Washington Dr.		Pole	Yucaipa

102	FT2055202	Handhole	Banning
103	FT2055203	Handhole	Banning
104	FT2055204	Handhole	Banning
105	H2051	Fiber Distributio	Banning
106	H2052	Fiber Distributio	Banning
108	1054 Gilman St.	Vault	Banning
115	T8167	Pedestal	Beaumont
117	T8169A	Pedestal	Beaumont

Approximate GPS Coordinates	Address	Ticket Number
34.2481277, -117.2715006		T-00489844
34.2491176, -117.2715293		T-00489845
34.2495137, -117.2712747		T-00489846
34.2488846, -117.2729252		T-00489847
34.2501266, -117.2733791		T-00489848
34.2504759, -117.2733352		T-00489849
34.2362453, -117.177253		T-00489850
34.236607, -117.1773941		T-00489852
34.2369574, -117.1775439		T-00489851
237281994578915, -117.17746504992124		T-00489854
34.2379714, -117.1778564		T-00489855
34.2382386, -117.1782198		T-00489856
34.238629, -117.178453	E/S 1090' N/O SYCAM	T-00489853
34.2386374, -117.1785796		T-00489857
34.2229052, -117.400325		T-00489858
34.2229897, -117.4006785		T-00489859
22305065300694, -117.39933653051975		T-00489861
34.2277929, -117.4045824		T-00489860
34.2277771, -117.4043166		T-00489864
22747661086259, -117.40459016825132		T-00489862
34.2265316, -117.4039194		T-00356485
34.2261772, -117.4038296		T-00489863
34.2320824, -116.9303057		T-00489865
34.2325167, -116.9300531		T-00489866
34.2315656, -116.9300572		T-00489867
34.2308738, -116.9303851		T-00489868
34.236909 -116.927345	34.236909 -116.927345	T-00490092
34.2370509, -116.9274843	4.2370509, -116.927484	T-00490085
34.2056273, -117.1011455		T-00489871
34.2060014, -117.1010665		T-00489870
NEED COORDINATES		T-00492977
NEED COORDINATES		T-00492978
34.2049222, -117.1008347		T-00489869
115821022562734, -117.28495010399067		T-00489876
34.1157171, -117.2842654		T-00489872
115751100149566, -117.28232457700906		T-00489875
34.1156016, -117.2820248		T-00489873
066459291889494, -117.18765554387906		T-00489879
06513815578933, -117.18764984632026		T-00489881
4.0647815662103, -117.18774111933872		T-00489882
4.0643718154371, -117.18750863282956		T-00489883
34.0324091, -117.0699821		T-00489887
34.0326426, -117.0683157		DUPLICATE
033324613422494, -117.06727064632172		T-00489890

8.94001726179125, -116.932506664554	5081 Maverick st.	T-00490102
.94040736149086, -116.933304376199	5161Maverick st.	T-00490103
.94056315523737, -116.934066647363	5227 Maverick st.	T-00490107
33.9428961, -116.9294379	3.9428961, -116.92943	T-00490106
33.9428961, -116.9294379	3.9428961, -116.92943	T-00490109
936148103087824, -116.888052728324	1054 W. Gilman street	T-00490108
8.9382300960597, -116.9957991323632	1146 Gainsborough Ct.	T-00490119
938481309072465, -116.995601433609	1156 Gainsborough Ct	T-00490120

Violation	Priority Level	Affected Company	Due Date	Inspection Date
Frontier down guy wire attached to each of the following poles was not taut, Abandoned service drops were observed				9/3/2025
Frontier down guy wire attached to each of the following poles was not taut				9/3/2025
Frontier's service drop was in contact with an SCE's secondary service drop, Frontier down guy wire attached to each of the following poles was not taut				9/3/2025
The above ground clearance of a Frontier conductor attached to Pole 2250603E was approximately 10 feet				9/3/2025
Frontier communication conductor attached to each of the following poles was strained by vegetation				9/3/2025
Abandoned service drops were observed				9/3/2025
Frontier communication conductor attached to each of the following poles was strained by vegetation				9/3/2025
Frontier communication conductor attached to each of the following poles was strained by vegetation				9/3/2025
Frontier communication conductor attached to each of the following poles was strained by vegetation				9/3/2025
Frontier communications conductor was in contact with a third-party communications conductor				9/3/2025
Frontier communication conductor attached to each of the following poles was strained by vegetation				9/3/2025
Frontier communication conductor attached to each of the following poles was strained by vegetation				9/3/2025
Frontier down guy wire attached to each of the following poles was not taut, Abandoned service drops were observed				9/3/2025
The above ground clearance of a Frontier conductor attached to Pole 549381E was approximately 10 feet				9/3/2025
Frontier communications service drop on Pole 4450226E was in contact with a third-party communication conductor				9/3/2025
Abandoned service drops were observed				9/3/2025
rope tied around the pole, lowest pole step on each of the following poles was located at a height less than eight feet				9/3/2025
The marker (guard) on the down guy wire supporting each of the following poles was missing				9/3/2025
Incomplete pole transfer				9/3/2025
Incomplete pole transfer				9/3/2025
The Frontier lashing wire supported on pole 1714996E was broken				9/3/2025
Incomplete pole transfer				9/3/2025
communication span supported on pole attached to a thirdparty communication conductor via a rope				9/3/2025
lashng wire broken, Frontier communications conductor was in contact with a third-party communication conductor				9/3/2025
Frontier down guy wire attached to each of the following poles was not taut				9/3/2025
service drop was not properly secured to pole				9/3/2025
Incomplete pole transfer				9/3/2025
Incomplete pole transfer				9/3/2025
Incomplete pole transfer				9/3/2025
Abandoned service drops were observed				9/3/2025
Incomplete pole transfer				9/3/2025
Incomplete pole transfer				9/3/2025
Abandoned service drops were observed				9/3/2025
damaged visibility strip, The marker (guard) on the down guy wire supporting each of the following poles was missing				9/3/2025
Abandoned service drops were observed				9/3/2025
Abandoned service drops were observed				9/3/2025
The marker (guard) on the down guy wire supporting each of the following poles was missing, Frontier communication conductor attached to each of the following poles was strained by vegetation				9/3/2025
Abandoned service drops were observed				9/3/2025
damaged visibility strip				9/3/2025
lowest pole step on each of the following poles was located at a height less than eight feet				9/3/2025
Frontier ground wire attached to pole damaged, Abandoned service drops were observed				9/3/2025
Incomplete pole transfer				9/3/2025
Abandoned service drops were observed				9/3/2025
Abandoned service drops were observed				9/3/2025

Frontier handhole covers was missing bolts			9/3/2025
Frontier handhole covers was missing bolts			9/3/2025
Frontier handhole covers was missing bolts			9/3/2025
Frontier handhole covers was missing bolts			9/3/2025
Frontier handhole covers was missing bolts			9/3/2025
The cover of the underground vault located in front of 1054 Gilman St was corroded			9/3/2025
The cover of the pedestal T8167A was damaged			9/3/2025
The cover of the pedestal T8169A was damaged			9/3/2025

HF Tier	TKT Status	Assigned To	Frontier Response
TIER 3	LOGGED	RANDY ORTEGA	CON-CA-SAN BERNARDINO
TIER 3	LOGGED	RANDY ORTEGA	CON-CA-SAN BERNARDINO
TIER 3	LOGGED	RANDY ORTEGA	CON-CA-SAN BERNARDINO
TIER 3	LOGGED	RANDY ORTEGA	CON-CA-SAN BERNARDINO
TIER 3	LOGGED	RANDY ORTEGA	CON-CA-SAN BERNARDINO
TIER 3	LOGGED	RANDY ORTEGA	CON-CA-SAN BERNARDINO
TIER 3	LOGGED	RANDY ORTEGA	CON-CA-SAN BERNARDINO
TIER 3	LOGGED	RANDY ORTEGA	CON-CA-SAN BERNARDINO
TIER 3	LOGGED	RANDY ORTEGA	CON-CA-SAN BERNARDINO
TIER 3	LOGGED	RANDY ORTEGA	CON-CA-SAN BERNARDINO
TIER 3	LOGGED	RANDY ORTEGA	CON-CA-SAN BERNARDINO
TIER 3	LOGGED	RANDY ORTEGA	CON-CA-SAN BERNARDINO
TIER 3	LOGGED	RANDY ORTEGA	CON-CA-SAN BERNARDINO
TIER 3	LOGGED	RANDY ORTEGA	CON-CA-SAN BERNARDINO
TIER 3	LOGGED	RANDY ORTEGA	CON-CA-SAN BERNARDINO
TIER 2	LOGGED	RANDY ORTEGA	CON-CA-SAN BERNARDINO
TIER 2	LOGGED	RANDY ORTEGA	CON-CA-SAN BERNARDINO
TIER 2	LOGGED	RANDY ORTEGA	CON-CA-SAN BERNARDINO
TIER 2	LOGGED	RANDY ORTEGA	CON-CA-SAN BERNARDINO
TIER 2	LOGGED	MICHELE TABER	CA POLE ADMIN
TIER 2	LOGGED	MICHELE TABER	CA POLE ADMIN
Toer 2	LOGGED	RANDY ORTEGA	CON-CA-SAN BERNARDINO
TIER 2	LOGGED	MICHELE TABER	CA POLE ADMIN
TIER 2	LOGGED	JARED HAWK	CON-CA-VICTORVILLE-SP
TIER 2	LOGGED	JARED HAWK	CON-CA-VICTORVILLE-SP
TIER 2	LOGGED	JARED HAWK	CON-CA-VICTORVILLE-SP
TIER 2	LOGGED	JARED HAWK	CON-CA-VICTORVILLE-SP
TIER 2		MICHELE TABER	CA POLE ADMIN
TIER 2		MICHELE TABER	CA POLE ADMIN
TIER 3	LOGGED	MICHELE TABER	CA POLE ADMIN
TIER 3	LOGGED	JARED HAWK	CON-CA-VICTORVILLE-SP
GEN	LOGGED	MICHELE TABER	CA POLE ADMIN
GEN	LOGGED	MICHELE TABER	CA POLE ADMIN
TIER 3	LOGGED	JARED HAWK	CON-CA-VICTORVILLE-SP
GEN	LOGGED	RANDY ORTEGA	CON-CA-SAN BERNARDINO
GEN	LOGGED	RANDY ORTEGA	CON-CA-SAN BERNARDINO
GEN	LOGGED	RANDY ORTEGA	CON-CA-SAN BERNARDINO
GEN	LOGGED	RANDY ORTEGA	CON-CA-SAN BERNARDINO
GEN	LOGGED	RANDY ORTEGA	CON-CA-SAN BERNARDINO
GEN	LOGGED	RANDY ORTEGA	CON-CA-SAN BERNARDINO
GEN	LOGGED	RANDY ORTEGA	CON-CA-SAN BERNARDINO
GEN	LOGGED	RANDY ORTEGA	CON-CA-SAN BERNARDINO
GEN	LOGGED	MICHELE TABER	CA POLE ADMIN
GEN		RANDY ORTEGA	CON-CA-SAN BERNARDINO
GEN	LOGGED	RANDY ORTEGA	CON-CA-SAN BERNARDINO

