From:	webmaster@cpuc.ca.gov
To:	USRB
Cc:	paul.pimentel@sce.com
Subject:	Electric Safety Incident Reported- Southern California Edison Company Incident No: 261105-18286
Date:	Thursday, November 5, 2026 5:17:54 PM

The Following information regarding this incident has been reported:

Reporting Date: 11/5/2026 5:12:45 PM
Incident Date: 6/5/2026 @ 2:30 p.m.
Reported By: Paul C. Pimentel, Principal Manager
Utility Name: Southern California Edison Company
Phone Number: (626)302-5830
Email Address: paul.pimentel@sce.com

Incident Location: Highway 138 (W. Avenue D)/122nd Street West Lancaster, Los Angeles County

Reasons For Reporting:
- Fatalities? No (Utility: , Others:)
- Names of Fatalities:
- Injuries? (Utility: , Others:)
- Names of Injured:
- Damage? No (Utility: , Others:)
- Interruption? (Total Customers: , Total Hours:)
- Operator Judgement? Yes
- Media Coverage? No

Cause of Incident: Unknown (Other Cause:)

Agencies on Scene:

Facilities Affected:
- Utilities Facilities:
- Voltage (KV):
- Customer's Facilities:

DigIn Information:
- Excavator Name:
- Contact:
- Phone: (___)___-____

Incident Recovery:
- On Scene Date & Time: @ 00:00 a.m.
- Service Restored: @ 00:00 a.m.

Summary: SCE submits this report out of an abundance of caution and should not be construed as a determination that SCE infrastructure caused or contributed to the ignition of the Macy Fire because the incident may fall within the reporting requirement applicable when a government entity investigates whether utility-owned or operated infrastructure caused a wildfire. SCE obtained the Los Angeles County Fire Department's investigation report

regarding the Macy Fire. The report determined the fire was accidental and identified the most probable ignition sequence as a Mylar balloon contacting an energized electrical wire, creating an ignition source, with heated material falling to and igniting the grass below. The Macy Fire was reported on June 5, 2026 at approximately 2:33 p.m. SCE had no reported circuit relay activity at or around the time the fire was reported and no reported damaged or downed conductor in the area where the fire originated. Later in the event, portions of circuits in the area were de-energized in response to the fire or as a result of infrastructure damaged during the course of the fire. Forward progress was stopped shortly after 7:00 p.m. that same day, after the fire had burned approximately 2,000 acres. SCE is unaware of any third-party structures reported as damaged or destroyed by the Macy Fire. The County has not requested at any time that SCE remove or retain any infrastructure as part of its investigation.