Ross Johnson
Director- Regulatory

AT&T Services, Inc.
430 Bush Street, 5th Floor
San Francisco, CA 94108

att-regulatory-ca@att.com
www.att.com
415.417.5028

May 8, 2025

Via Email
Rickey Tse
Program and Project Supervisor
Electric Safety and Reliability Branch
Safety and Enforcement Division
California Public Utilities Commission

Subject: Communication Infrastructure Provider (CIP) Audit of Merced, Tuolumne, Mariposa, & Madera County Region

Dear Mr. Tse,

The following is AT&T California's ("AT&T") response to your letter dated April 10, 2025 (“April Letter”) regarding the audit of AT&T’s Merced, Tuolumne, Mariposa, & Madera County region conducted from December 16 to December 20, 2024 (“December Audit”).

The April Letter requested that we advise you of actions taken by AT&T to address alleged conditions identified during the December Audit and requested a response by May 8, 2025.

I am enclosing AT&T’s Response to the December Audit.

Regards,

Ross Johnson
Director
AT&T Regulatory
415-417-5028
rj2397@att.com

Enclosure:

AT&T’s Response to the December Audit

Cc:
Lee Palmer, Director, Safety and Enforcement Division (SED), CPUC
Eric Wu, Program Manager, ESRB, SED, CPUC
Fadi Daye, Program and Project Supervisor, ESRB, SED, CPUC
Yi “Rocky” Yang, Senior Utilities Engineer (Supervisor), ESRB, SED, CPUC
Stephen Lee, Senior Utilities Engineer (Supervisor), ESRB, SED, CPUC
Emiliano Solorio, Utilities Engineer, ESRB, SED, CPUC
Nora Nguyen, Utilities Engineer, ESRB, SED, CPUC
Madonna Ebrahimof, Staff Services Analyst, ESRB, SED, CPUC

AT&T'S RESPONSE TO AUDIT RELATED TO MERCED, TUOLUMNE, MARIPOSA & MADERA COUNTY CONDUCTED DECEMBER 16 – 20, 2024

Alleged Records Violation #1: ESRB's review of AT&T's work orders from November 2019 through October 2024 found that AT&T had 250 out of 5,801 (or 4.3%) pending work orders that were overdue and 319 out of 2,168 (or 14.7%) closed work orders that were completed late. Late-pending work orders are pending work orders that have not been completed by their assigned due date based on their hazard level, and late- closed work orders are work orders that were completed past their assigned due date based on their hazard level. Table 1 below breaks down the 569 late work orders by hazard level.

Table 1: Late Work Orders

Hazard Level	Late-Pending Work Orders	Late-Closed Work Orders	Total Late Work Orders
1	1	31	32
2	11	19	30
2a	40	13	53
2b	66	226	292
2c	122	29	151
3	10	1	11
Total	250	319	569

AT&T must provide ESRB with its corrective action plan to complete the 250 late pending work orders and its preventive measures to prevent any work orders from being addressed late in the future.

AT&T Response: Without admitting that AT&T violated GO 95, Rule 18, the information AT&T produced in response to the pre-audit data request appears to indicate that 250 tickets are pending and 319 were closed; however, that does not necessarily mean that any related corrective action had not been completed by the assigned due date. Closing repair tickets is a time-consuming manual process.

That said, AT&T has been reviewing and is continuing to review each of the 250 work orders identified as past due to determine whether the work order should be cancelled/invalidated (meaning they will be closed out) or requires work to be performed in the field. To date, 52 have been closed out. AT&T intends to complete current and past due work orders that require work to be performed in the field.

Alleged Records Violation #2:

Table 2: Most Overdue Work Orders

Priority Code	Most Overdue Work Orders (WO#s)	Number of Days Past Assigned Due Date
1	613016	1,626

2	526740	727
2a	517214	1,452
2b	1055036	874
2c	526086	1,458
3	498977	62

- AT&T identified work order #613016 on April 16, 2020, to repair a broken B-box handle with a required end date of April 19, 2020. AT&T has not yet completed the work.
- AT&T identified work order #526740 on December 12, 2019, for a pole transfer with a required end date of October 5, 2022. AT&T has not yet completed the work.
- AT&T identified work order #517214 on November 28, 2019, to repair a leaning pole with a required end date of October 10, 2020. AT&T has not yet completed the work.
- AT&T identified work order #1055036 on March 8, 2022, to replace a down guy with a required end date of May 11, 2022. AT&T has not yet completed the work.
- AT&T identified work order #526086 on December 12, 2019, to replace a deteriorated pole with a required end date of October 4, 2020. AT&T has not yet completed the work.
- AT&T identified work order #498977 on November 2, 2019, to transfer facilities to a new pole with a required end date of July 31, 2024. AT&T has not yet completed the work.
- AT&T identified work order #1063926 on March 16, 2022, for replacement of the underground vault. During the field audit, ESRB visited the location for this work order and identified that the underground vault was not replaced, and the condition still existed. The work order was closed inadvertently on April 26, 2022, before the work was completed.

AT&T Response:

- Regarding work order #613016, the work was completed, and the ticket was closed on 12/18/24.
- Work order #526740 has been sent out for completion, and the work should be completed by 6/30/2025.
- Regarding work order #517214, the guy wire was tightened. A request for a new pole was submitted to AT&T's Construction & Engineering Department.
- Work order #1055036 has been sent out for completion, and the work should be completed by 5/11/2025.
- Work order #526086 has been sent out for completion on job A02NKPN, and the work should be completed by 6/30/2025.
- Regarding work order #498977, the work was completed, and the ticket was closed on 4/25/2025.
- Regarding work order #1063926, a new work order #1680298 was opened for sub box replacement.

AT&T'S RESPONSE TO AUDIT RELATED TO
MERCED, TUOLUMNE, MARIPOSA & MADERA COUNTY
CONDUCTED DECEMBER 16 – 20, 2024

Alleged Records Violation #3: AT&T has a total of 2,064 late patrol inspections conducted from 2019 to 2024. The AT&T DA sites with late patrol inspections are listed Table 3 below. There are a total of 623 days in between patrol inspections for AT&T DA 320501-NTN1110. AT&T DA 110101-NGO4203 did not have any record of a patrol inspection conducted. A detailed inspection was conducted on 6/19/2023. A patrol inspection is required every year for a joint use pole in a Tier 3 HFTD (High Fire Threat District).

Table 3: Late Patrol Inspections

DA_PSA_CD	UN_DA_NA	CLLI_ID	Fire Tier	Pole Count	Initial Patrol Inspection	Following Patrol or Detailed Inspection
2101	NTN3134	TWHRCA11	3	71	9/19/2020	~~5/25/2022~~ 1/2/2022
321901	NTN1201	TWHRCA11	3	311	9/16/2020	1/2/2022
4304	NTN2107	TWHRCA11	3	56	9/22/2020	1/5/2022
412901	NTN2208	TWHRCA11	3	311	9/24/2020	~~5/25/2022~~ 1/11/2022
2203	NTN2109	TWHRCA11	3	175	9/22/2020	~~5/22/2022~~ 1/18/2022
1313	NTN2203	TWHRCA11	3	147	9/22/2020	~~5/22/2022~~ 1/6/2022
320501	NTN1110	TWHRCA11	3	149	9/10/2020	~~5/26/2022~~ 1/5/2022
410301	NTN1202	TWHRCA11	3	287	9/16/2020	~~5/25/2022~~ 1/14/2022
120101	NTN2202	TWHRCA11	3	91	9/22/2020	~~5/23/2022~~ 1/8/2022
1139	NTN1204	TWHRCA11	3	70	9/17/2020	~~5/26/2022~~ 1/4/2022
1133	NTN2108	TWHRCA11	3	135	9/22/2020	~~5/22/2022~~ 1/10/2022
2301	NTN1205	TWHRCA11	3	256	9/13/2020	~~5/26/2022~~ 1/5/2022
110101	NGO4203	GVLDCA11	~~3~~ **2**	5	NA	6/19/2023
Total				**2,064**		

AT&T Response: Regarding the pole inspections conducted, some of the dates in the column titled "Following Patrol or Detailed Inspection" of the ESRB's Table 3, above, are incorrect. AT&T has revised Table 3 above in redline to note the errors/corrections, which reduces the number of days in between patrol inspections. That said, without admitting that AT&T violated GO 95, Rule 80.1-A(1), AT&T will endeavor to meet the due date moving forward.

Regarding DA 110101-NGO4203, that DA is not in HFTD Tier 3 as alleged. AT&T has revised Table 3 above in redline to note the error/correction. Moreover, AT&T did not conduct patrols for that DA during the 2020–2022 time frame because AT&T did not have aerial cable extending into a tier 2 area when GO95 inspection planning was conducted for inspections to be performed during the 2020–2022 time frame. But when AT&T conducted GO95 inspection planning at the end of 2022 for purposes of scheduling 2023 inspections, AT&T found two new aerial cables in DA 110101-NGO4203 that crossed into a tier 2 area. Because these two new aerial cables crossed into a tier 2 area within the boundary of DA 110101-NGO4203, AT&T scheduled DA 110101-NGO4203 for 2023 inspection during the GO95 inspection planning that took place at the end of 2022. As previously provided, the detailed inspection for DA 110101-NGO4203 took place on 6/19/2023.

Alleged Records Violation #4: AT&T's inspection spreadsheets are missing the personnel who performed each inspection, and the personnel who performed each corrective action.

AT&T Response: AT&T pole inspection work is contracted to Osmose Utilities Services, Inc. and has been since 2019. For the corrective actions, a revised spreadsheet has been provided with the AT&T personnel ID that identifies the AT&T employee who was involved in resolving the issue or oversaw the corrective action along with the closure notes for the workorders.

Alleged Field Inspection Violation #1:

Table 5: GO 95, Rule 31.1 Findings

Location #	Findings
18	Facilities need to be transferred to new pole.
28	Conductor was not securely attached to pole.
55	Facilities need to be transferred to new pole.
56	Facilities need to be transferred to new pole.
57	Facilities need to be transferred to new pole.
61	Broken ground wire attached to pole needs to be removed.
68	Old pole stump needs to be removed.
70	Facilities need to be transferred to new pole.
72	Facilities need to be transferred to new pole.
76	Junction box is missing a cover.
77	Facilities need to be transferred to new pole.
78	Facilities need to be transferred to new pole.
81	Facilities need to be transferred to new pole.
82	Conductor was not securely attached to pole.
86	Facilities need to be transferred to new pole.
87	Facilities need to be transferred to new pole.
119	Junction box was broken.

.
Location #28: Ticket 1683638 was created for the alleged finding with a due date of 5/1/2028.
Location #55: Ticket 1512575 was created for the alleged finding with a due date of 6/12/2029.
Location #56: Ticket 1685213 was created for the alleged finding with a due date of 5/3/2030.
Location #57: Ticket 1685214 was created for the alleged finding with a due date of 5/3/2030.
Location #61: Ticket 1685217 was created for the alleged finding with a due date of 5/05/2028.
Location #68: Ticket 1018452 was created for the alleged finding with a due date of 12/9/2026.
Location #70: Ticket 1018410 was created for the alleged finding with a due date of 12/10/2026.
Location #72: Ticket 1675261 was created for the alleged finding with a due date of 3/23/2030.
Location #76: Ticket 1685222 was created for the alleged finding with a due date of 5/5/2030.
Location #77: Ticket 1675645 was created for the alleged finding with a due date of 3/20/2030.
Location #78: Ticket 1685221 was created for the alleged finding with a due date of 5/1/2030.
Location #81: Ticket 1675216 was created for the alleged finding with a due date of 3/20/2026.
Location #82: Ticket 1685220 was created for the alleged finding with a due date of 5/1/2030.
Location #86: Ticket1683936 was created for the alleged finding with a due date of 5/1/2030.
Location #87: Ticket 1674780 was created for the alleged finding with a due date of 3/20/2030.
Location #119: Ticket 1685223 was created for the alleged finding with a due date of 5/5/2026.

Alleged Field Inspection Violation #2:

Table 6: GO 95, Rule 31.6 Findings

Location #	Findings
11	There was an abandoned AT&T service drop.
13	There was an abandoned AT&T service drop.
115	There was an abandoned AT&T service drop. Service drop was removed in field.
127	There was an abandoned AT&T service drop.

AT&T Response:
Location #11: Ticket 1683096 was created for the alleged finding with a due date of 4/30/2030.
Location #13: Ticket 1683091 was created for the alleged finding with a due date of 4/30/2030.
Location #115: Ticket 1683958 was created for the alleged finding with a due date of 5/1/2028.
Location #127: Ticket 1683955 was created for the alleged finding with a due date of 5/3/2026.

Alleged Field Inspection Violation #3:

Table 7: GO 95, Rule 34 Findings

Location #	Findings
59	There was a foreign object attached to the pole.
67	There was a foreign object attached to the pole.

AT&T Response:
AT&T does not agree it is in violation of General Order 95 ("GO 95"), Rule 34. Even if these poles had unauthorized attachments, Rule 34 does not impose a duty on AT&T to routinely or actively remove all unauthorized attachments.[1] Nevertheless, without admitting that AT&T violated GO 95, Rule 34, the alleged conditions were entered into AT&T's RWM System to be worked in the field.

Location #59: Ticket 1685215 was created for the alleged finding with a due date of 5/3/2026.
Location #67: Ticket 1685218 was created for the alleged finding with a due date of 5/5/2026.

Alleged Field Inspection Violation #4:

Table 8: GO 95, Rule 35 Findings

Location #	Findings
15	There was vegetation grown into the messenger midspan. There is vegetation strain on the conductor.
32	There is vegetation strain on the conductor.
39	There is vegetation strain on the conductor.
118	There is vegetation strain on the conductor.

AT&T Response:
Location #15: Ticket 1683169 was created for the alleged finding with a due date of 10/31/2025.
Location #32: Ticket 1101739 was created for the alleged finding with a due date of 11/15/2026.
Location #39: Ticket 1683635 was created for the alleged finding with a due date of 11/1/2025.
Location #118: Ticket 1683957 was created for the alleged finding with a date of 11/1/2025.

Alleged Field Inspection Violation #5:

Table 9: GO 95, Rule 37 Findings

Location #	Findings
20	There was a low hanging supply drop. Table 1 requires a minimum clearance of 10 feet for service drops above ground in areas accessible to pedestrians only.
46	There was a low hanging supply drop. Table 1 requires a minimum clearance of 10 feet for service drops above ground in areas accessible to pedestrians only.

AT&T Response:
Location #20: Ticket 1683307 was created for the alleged finding with a due date of 4/30/2028.
Location #46: Ticket 1398479 was created for the alleged finding with a due date of 11/27/2026.

[1] See D.99-04-001, Opinion Dismissing Complaint, Case 98-09-036, at 10 (April 1, 1999)

Alleged Field Inspection Violation #6:

Table 10: GO 95, Rule 38 Finding

Location #	Findings
20	There was a terminal and conductor in contact with a guy wire. Table 2 requires a minimum clearance of 3 inches between communication conductors and guys and spans wires passing conductors supported on the same poles.

AT&T Response:
Location #20: Ticket 1683309 was created for the alleged finding with a due date of 4/30/2030.

Alleged Field Inspection Violation #7:

Table 11: GO 95, Rule 86.9 Findings

Location #	Findings
14	Guy wire was missing a guy guard.
16	Guy guard on guy wire is broken.
48	Guy wire was missing a guy guard.
78	Guy wire was missing a guy guard.
81	Guy wire was missing a guy guard.

AT&T Response:
Location #14: Ticket 1202168 was created for the alleged finding with a due date of 12/14/2025.
Location #16: Ticket 1683171 was created for the alleged finding with a due date of 4/30/2030.
Location #48: Ticket 1021036 was created for the alleged finding with a due date of 11/2/2026.
Location #78: Ticket 517755 was created for the alleged finding with a date of 10/8/2024.
Location #81: Ticket 1675216 was created for the alleged finding with a due date of 3/20/2026.

Alleged Field Inspection Violation #8:

Table 12: GO 95, Rule 84.7A Findings

Location #	Findings
119	Vegetation impedes climbing space.
136	Vegetation impedes climbing space.

AT&T Response:
Location #119: Ticket 1683957 was created for the alleged finding with a due date of 11/1/2025.
Location #136: Ticket 1018452 was created for the alleged finding with a due date of 2/16/2029.

Alleged Field Inspection Violation #9:

Table 13: GO 95, Rule 87.7-D(1) Findings

Location #	Findings
25	Riser was below 8 feet.
28	Riser was below 8 feet.
30	Riser was broken.
41	Riser was broken.
42	Conductor was uncovered at base of riser.
51	Conductor was not in riser.
66	Riser was below 8 feet.
82	Riser was missing for conductor along pole.
89	Conductor was not in riser.
102	Riser was below 8 feet.
122	Riser was broken.
130	Riser was broken.

AT&T Response:
Location #25: Ticket 1683637 was created for the alleged finding with a due date of 5/1/2028.
Location #28: Ticket 1683638 was created for the alleged finding with a due date of 5/1/2028.
Location #30: Ticket 1050668 was created for the alleged finding with a due date of 10/30/2024.
Location #41: Ticket 1683636 was created for the alleged finding with a date of 5/1/2030.
Location #42: Ticket 1683943 was created for the alleged finding with a due date of 5/1/2028.
Location #51: Ticket 1683944 was created for the alleged finding with a due date of 5/1/2030.
Location #66: Ticket 1685219 was created for the alleged finding with a due date of 5/5/2028.
Location #82: Ticket 1685220 was created for the alleged finding with a due date of 5/5/2030.
Location #89: Ticket 1683906 was created for the alleged finding with a due date of 5/1/2030.
Location #102: Ticket 1683903 was created for the alleged finding with a due date of 5/1/2030.
Location #122: Ticket 1683956 was created for the alleged finding with a due date of 5/1/2030.
Location #130: Ticket 1683946 was created for the alleged finding with a due date of 5/1/2030.

Alleged Field Inspection Violation #10:

Table 14: GO 95, Rule 91.3-C Finding

Location #	Finding
115	There was a pole step below 8 feet.

AT&T Response:
Location #115: Ticket 1683958 was created for the alleged finding with a due date of 5/1/2028.

Alleged Field Inspection Violation #11:

Table 15: GO 95, Rule 92.4-C(1)(a) Finding

Location #	Finding
88	The ground rod was exposed above ground.

AT&T Response:
Location #88: Ticket 1683904 was created for the alleged finding with a due date of 5/1/2030.

Alleged Field Inspection Violation #12:

Table 16: GO 128, Rule 17.1 Findings

Location #	Findings
1	Vault lid was broken.
9	Vault lid was broken.
111	Pedestal was missing a cover.
132	Pedestal was broken.
133	Pedestal was missing a cover.

AT&T Response:
Location #1: Ticket 1063926 was re-visited and completed 3/18/2025.
Location #9: Ticket 1682895 was created for the alleged finding with a due date of 11/1/2025.
Location #111: Ticket 1682895 was created for the alleged finding with a due date of 11/1/2025.
Location #132: Ticket 1683656 was created for the alleged finding with a date of 11/1/2025.
Location #133: Ticket 1683652 was created for the alleged finding with a due date of 11/1/2025.

Alleged Field Inspection Violation #13:

Table 17: GO 128, Rule 17.8 Findings

Location #	Findings
1	No mark of ownership on vault lid.
3	No mark of ownership on vault lid.
4	No mark of ownership on vault lid.
95	No mark of ownership on pedestal. Ownership label was added in field.
101	No mark of ownership on pedestal. Ownership label was added in field.
109	No mark of ownership on pedestal. Ownership label was added in field.
135	No mark of ownership on vault lid.

142	No mark of ownership on pedestal. Ownership label was added in field.
143	No mark of ownership on pedestal. Ownership label was added in field.
144	No mark of ownership on pedestal. Ownership label was added in field.

AT&T Response:
Location #1: Ticket 1063926 was re-visited and completed 3/18/2025.
Location #3: Ticket 1682924 was created for the alleged finding with a due date of 11/1/2025.
Location #4: Ticket 1682899 was created for the alleged finding with a due date of 11/1/2025.
Location #95: Corrected in the field as noted in the ESRB's Table 17, above.
Location #101: Corrected in the field as noted in the ESRB's Table 17, above.
Location #109: Corrected in the field as noted in the ESRB's Table 17, above.
Location #135: Ticket 1683645 was created for the alleged finding with a due date of 11/1/2025.
Location #142: Corrected in the field as noted in the ESRB's Table 17, above.
Location #143: Corrected in the field as noted in the ESRB's Table 17, above.
Location #144: Corrected in the field as noted in the ESRB's Table 17, above.

Noted Observations:

Location #	Findings
18	Cable TV conductor is in contact with AT&T line.
20	Electrical ground wire is exposed.
21	Electrical ground wire is exposed.
23	Cable TV riser is below 8 feet.
28	Cable TV conductor is not securely attached to the pole.
31	Cable TV conductor is not in riser.
31	Cable TV guy wire guard is missing on outermost guy wire.
38	Cable TV conductor is not covered by the riser.
39	There is vegetation strain on cable TV conductor.
45	Cable TV service drop is in contact with messenger and AT&T conductor.
106	Cable TV ground rod and ground wire are exposed.
107	Cable TV has an abandoned service drop.
116	Cable TV has an abandoned service drop.
131	Cable TV ground wire is exposed.

AT&T Response:
Third Party Notifications have been created for each of these alleged findings.

PACKAGE_ID	MARKIT_ID	STATE	AREA	DISTRICT	WC_ID	CLLI
516636	100105133	CA	Valley	Merced Foothills	209161	CTVLCA11
517217	100105944	CA	Valley	Merced Foothills	209185	LGRNCA12
517232	100106020	CA	Valley	Merced Foothills	209185	LGRNCA12
517233	100105990	CA	Valley	Merced Foothills	209185	LGRNCA12
517237	100106044	CA	Valley	Merced Foothills	209185	LGRNCA12
517239	100106128	CA	Valley	Merced Foothills	209185	LGRNCA12
517241	100106088	CA	Valley	Merced Foothills	209185	LGRNCA12
517242	100106087	CA	Valley	Merced Foothills	209185	LGRNCA12
517245	100106041	CA	Valley	Merced Foothills	209185	LGRNCA12
517246	100106073	CA	Valley	Merced Foothills	209185	LGRNCA12
517253	100105919	CA	Valley	Merced Foothills	209185	LGRNCA12
517254	100105917	CA	Valley	Merced Foothills	209185	LGRNCA12
517255	100105915	CA	Valley	Merced Foothills	209185	LGRNCA12
517256	100105912	CA	Valley	Merced Foothills	209185	LGRNCA12
517258	100105905	CA	Valley	Merced Foothills	209185	LGRNCA12
517269	100106013	CA	Valley	Merced Foothills	209185	LGRNCA12
517311	100105901	CA	Valley	Merced Foothills	209185	LGRNCA12
517313	100106122	CA	Valley	Merced Foothills	209185	LGRNCA12
517322	100105898	CA	Valley	Merced Foothills	209185	LGRNCA12
517328	100105882	CA	Valley	Merced Foothills	209185	LGRNCA12
517342	100105872	CA	Valley	Merced Foothills	209185	LGRNCA12

517345	100106097	CA	Valley	Merced Foothills	209185	LGRNCA12
517347	100105960	CA	Valley	Merced Foothills	209185	LGRNCA12
517354	100105949	CA	Valley	Merced Foothills	209185	LGRNCA12
517355	100105945	CA	Valley	Merced Foothills	209185	LGRNCA12
517356	100105943	CA	Valley	Merced Foothills	209185	LGRNCA12
517358	100105936	CA	Valley	Merced Foothills	209185	LGRNCA12
517359	100105935	CA	Valley	Merced Foothills	209185	LGRNCA12
517360	100105933	CA	Valley	Merced Foothills	209185	LGRNCA12
517363	100105927	CA	Valley	Merced Foothills	209185	LGRNCA12
517414	100105852	CA	Valley	Merced Foothills	209241	YSMTCA12
517418	100105845	CA	Valley	Merced Foothills	209241	YSMTCA12
517500	100105871	CA	Valley	Merced Foothills	209185	LGRNCA12
517501	100105870	CA	Valley	Merced Foothills	209185	LGRNCA12
517502	100105869	CA	Valley	Merced Foothills	209185	LGRNCA12
517503	100105868	CA	Valley	Merced Foothills	209185	LGRNCA12
517504	100105867	CA	Valley	Merced Foothills	209185	LGRNCA12
517505	100105865	CA	Valley	Merced Foothills	209173	GVLDCA11
517507	100105863	CA	Valley	Merced Foothills	209173	GVLDCA11
517510	100105860	CA	Valley	Merced Foothills	209173	GVLDCA11
517588	100105922	CA	Valley	Merced Foothills	209185	LGRNCA12
517589	100105921	CA	Valley	Merced Foothills	209185	LGRNCA12

517590	100105920	CA	Valley	Merced Foothills	209185	LGRNCA12
517591	100105918	CA	Valley	Merced Foothills	209185	LGRNCA12
517592	100105916	CA	Valley	Merced Foothills	209185	LGRNCA12
517593	100105914	CA	Valley	Merced Foothills	209185	LGRNCA12
517594	100105913	CA	Valley	Merced Foothills	209185	LGRNCA12
517595	100105911	CA	Valley	Merced Foothills	209185	LGRNCA12
517596	100105910	CA	Valley	Merced Foothills	209185	LGRNCA12
517597	100105909	CA	Valley	Merced Foothills	209185	LGRNCA12
517598	100105908	CA	Valley	Merced Foothills	209185	LGRNCA12
517599	100105906	CA	Valley	Merced Foothills	209185	LGRNCA12
517600	100106035	CA	Valley	Merced Foothills	209185	LGRNCA12
517601	100106033	CA	Valley	Merced Foothills	209185	LGRNCA12
517602	100106031	CA	Valley	Merced Foothills	209185	LGRNCA12
517603	100106029	CA	Valley	Merced Foothills	209185	LGRNCA12
517604	100106028	CA	Valley	Merced Foothills	209185	LGRNCA12
517605	100106027	CA	Valley	Merced Foothills	209185	LGRNCA12
517606	100106025	CA	Valley	Merced Foothills	209185	LGRNCA12
517607	100106024	CA	Valley	Merced Foothills	209185	LGRNCA12
517608	100106022	CA	Valley	Merced Foothills	209185	LGRNCA12
517609	100106021	CA	Valley	Merced Foothills	209185	LGRNCA12
517610	100106019	CA	Valley	Merced Foothills	209185	LGRNCA12
517611	100106014	CA	Valley	Merced Foothills	209185	LGRNCA12

517612	100106009	CA	Valley	Merced Foothills	209185	LGRNCA12
517613	100106008	CA	Valley	Merced Foothills	209185	LGRNCA12
517615	100106005	CA	Valley	Merced Foothills	209185	LGRNCA12
517630	100106002	CA	Valley	Merced Foothills	209185	LGRNCA12
517631	100106001	CA	Valley	Merced Foothills	209185	LGRNCA12
517633	100105997	CA	Valley	Merced Foothills	209185	LGRNCA12
517634	100105995	CA	Valley	Merced Foothills	209185	LGRNCA12
517635	100105989	CA	Valley	Merced Foothills	209185	LGRNCA12
517645	100105986	CA	Valley	Merced Foothills	209185	LGRNCA12
517646	100105985	CA	Valley	Merced Foothills	209185	LGRNCA12
517649	100105981	CA	Valley	Merced Foothills	209185	LGRNCA12
517650	100105979	CA	Valley	Merced Foothills	209185	LGRNCA12
517651	100105978	CA	Valley	Merced Foothills	209185	LGRNCA12
517652	100105975	CA	Valley	Merced Foothills	209185	LGRNCA12
517654	100106058	CA	Valley	Merced Foothills	209185	LGRNCA12
517655	100106056	CA	Valley	Merced Foothills	209185	LGRNCA12
517660	100106049	CA	Valley	Merced Foothills	209185	LGRNCA12
517663	100106046	CA	Valley	Merced Foothills	209185	LGRNCA12
517666	100105969	CA	Valley	Merced Foothills	209185	LGRNCA12
517668	100105967	CA	Valley	Merced Foothills	209185	LGRNCA12
517670	100105965	CA	Valley	Merced Foothills	209185	LGRNCA12
517708	100106092	CA	Valley	Merced Foothills	209185	LGRNCA12

517709	100106086	CA	Valley	Merced Foothills	209185	LGRNCA12
517710	100106085	CA	Valley	Merced Foothills	209185	LGRNCA12
517715	100106078	CA	Valley	Merced Foothills	209185	LGRNCA12
517732	100106037	CA	Valley	Merced Foothills	209185	LGRNCA12
517758	100106117	CA	Valley	Merced Foothills	209185	LGRNCA12
517760	100106113	CA	Valley	Merced Foothills	209185	LGRNCA12
517765	100105896	CA	Valley	Merced Foothills	209185	LGRNCA12
517768	100105891	CA	Valley	Merced Foothills	209185	LGRNCA12
517770	100105887	CA	Valley	Merced Foothills	209185	LGRNCA12
517776	100106067	CA	Valley	Merced Foothills	209185	LGRNCA12
517778	100106061	CA	Valley	Merced Foothills	209185	LGRNCA12
517781	100105879	CA	Valley	Merced Foothills	209185	LGRNCA12
517815	100106103	CA	Valley	Merced Foothills	209185	LGRNCA12
517823	100105956	CA	Valley	Merced Foothills	209185	LGRNCA12
517828	100105946	CA	Valley	Merced Foothills	209185	LGRNCA12
517829	100105942	CA	Valley	Merced Foothills	209185	LGRNCA12
517830	100105941	CA	Valley	Merced Foothills	209185	LGRNCA12
517833	100105937	CA	Valley	Merced Foothills	209185	LGRNCA12
517836	100105931	CA	Valley	Merced Foothills	209185	LGRNCA12
517850	100105850	CA	Valley	Merced Foothills	209241	YSMTCA12
517851	100105848	CA	Valley	Merced Foothills	209241	YSMTCA12
517852	100105847	CA	Valley	Merced Foothills	209241	YSMTCA12

517866	100105855	CA	Valley	Merced Foothills	209173	GVLDCA11
518440	100106653	CA	Valley	Merced Foothills	209240	YSMTCA11
518534	100106656	CA	Valley	Merced Foothills	209240	YSMTCA11
523602	100111174	CA	Valley	Merced Foothills	209218	SNRACA13
523608	100110418	CA	Valley	Merced Foothills	209218	SNRACA13
523784	100111176	CA	Valley	Merced Foothills	209218	SNRACA13
523786	100111172	CA	Valley	Merced Foothills	209218	SNRACA13
524093	100111175	CA	Valley	Merced Foothills	209218	SNRACA13
526026	100113331	CA	Valley	Merced Foothills	209218	SNRACA13
526033	100113365	CA	Valley	Merced Foothills	209218	SNRACA13
526034	100113394	CA	Valley	Merced Foothills	209218	SNRACA13
526050	100113367	CA	Valley	Merced Foothills	209218	SNRACA13
526073	100113377	CA	Valley	Merced Foothills	209218	SNRACA13
526076	100113349	CA	Valley	Merced Foothills	209218	SNRACA13
526081	100113198	CA	Valley	Merced Foothills	209182	JMTWCA11
526083	100113330	CA	Valley	Merced Foothills	209218	SNRACA13
526090	100113254	CA	Valley	Merced Foothills	209182	JMTWCA11
526095	100113216	CA	Valley	Merced Foothills	209182	JMTWCA11
526098	100113243	CA	Valley	Merced Foothills	209182	JMTWCA11
526105	100113206	CA	Valley	Merced Foothills	209182	JMTWCA11
526117	100113214	CA	Valley	Merced Foothills	209182	JMTWCA11
526118	100113222	CA	Valley	Merced Foothills	209182	JMTWCA11

526136	100113210	CA	Valley	Merced Foothills	209182	JMTWCA11
526137	100113244	CA	Valley	Merced Foothills	209182	JMTWCA11
526139	100113204	CA	Valley	Merced Foothills	209182	JMTWCA11
526144	100113247	CA	Valley	Merced Foothills	209182	JMTWCA11
526161	100113353	CA	Valley	Merced Foothills	209218	SNRACA13
526172	100113407	CA	Valley	Merced Foothills	209218	SNRACA13
526180	100113242	CA	Valley	Merced Foothills	209182	JMTWCA11
526186	100113251	CA	Valley	Merced Foothills	209182	JMTWCA11
526192	100113317	CA	Valley	Merced Foothills	209218	SNRACA13
526193	100113236	CA	Valley	Merced Foothills	209182	JMTWCA11
526194	100113343	CA	Valley	Merced Foothills	209218	SNRACA13
526198	100113196	CA	Valley	Merced Foothills	209182	JMTWCA11
526200	100113199	CA	Valley	Merced Foothills	209182	JMTWCA11
526205	100113225	CA	Valley	Merced Foothills	209182	JMTWCA11
526217	100113218	CA	Valley	Merced Foothills	209182	JMTWCA11
526232	100113202	CA	Valley	Merced Foothills	209182	JMTWCA11
526234	100113208	CA	Valley	Merced Foothills	209182	JMTWCA11
526248	100113352	CA	Valley	Merced Foothills	209218	SNRACA13
526253	100113250	CA	Valley	Merced Foothills	209182	JMTWCA11
526279	100113362	CA	Valley	Merced Foothills	209218	SNRACA13
526282	100113203	CA	Valley	Merced Foothills	209182	JMTWCA11
526298	100113309	CA	Valley	Merced Foothills	209218	SNRACA13

526313	100113310	CA	Valley	Merced Foothills	209218	SNRACA13
526322	100113239	CA	Valley	Merced Foothills	209182	JMTWCA11
526332	100113207	CA	Valley	Merced Foothills	209182	JMTWCA11
526333	100113255	CA	Valley	Merced Foothills	209182	JMTWCA11
526358	100113332	CA	Valley	Merced Foothills	209218	SNRACA13
526359	100113329	CA	Valley	Merced Foothills	209218	SNRACA13
526370	100113364	CA	Valley	Merced Foothills	209218	SNRACA13
526388	100113259	CA	Valley	Merced Foothills	209182	JMTWCA11
526393	100113382	CA	Valley	Merced Foothills	209218	SNRACA13
526400	100113305	CA	Valley	Merced Foothills	209218	SNRACA13
526401	100113350	CA	Valley	Merced Foothills	209218	SNRACA13
526407	100113200	CA	Valley	Merced Foothills	209182	JMTWCA11
526409	100113219	CA	Valley	Merced Foothills	209182	JMTWCA11
526412	100113249	CA	Valley	Merced Foothills	209182	JMTWCA11
526441	100113209	CA	Valley	Merced Foothills	209182	JMTWCA11
526442	100113248	CA	Valley	Merced Foothills	209182	JMTWCA11
526452	100113334	CA	Valley	Merced Foothills	209218	SNRACA13
526456	100113307	CA	Valley	Merced Foothills	209218	SNRACA13
526464	100113234	CA	Valley	Merced Foothills	209182	JMTWCA11
526470	100113221	CA	Valley	Merced Foothills	209182	JMTWCA11
526479	100113359	CA	Valley	Merced Foothills	209218	SNRACA13

526484	100113235	CA	Valley	Merced Foothills	209182	JMTWCA11
526496	100113260	CA	Valley	Merced Foothills	209182	JMTWCA11
526513	100113237	CA	Valley	Merced Foothills	209182	JMTWCA11
526541	100113230	CA	Valley	Merced Foothills	209182	JMTWCA11
526563	100113197	CA	Valley	Merced Foothills	209182	JMTWCA11
526566	100113212	CA	Valley	Merced Foothills	209182	JMTWCA11
526572	100113355	CA	Valley	Merced Foothills	209218	SNRACA13
526579	100113358	CA	Valley	Merced Foothills	209218	SNRACA13
526591	100113252	CA	Valley	Merced Foothills	209182	JMTWCA11
526601	100113217	CA	Valley	Merced Foothills	209182	JMTWCA11
526608	100113372	CA	Valley	Merced Foothills	209218	SNRACA13
526611	100113224	CA	Valley	Merced Foothills	209182	JMTWCA11
526614	100113319	CA	Valley	Merced Foothills	209218	SNRACA13
526632	100113215	CA	Valley	Merced Foothills	209182	JMTWCA11
526640	100113201	CA	Valley	Merced Foothills	209182	JMTWCA11
526642	100113238	CA	Valley	Merced Foothills	209182	JMTWCA11
526661	100113399	CA	Valley	Merced Foothills	209218	SNRACA13
526665	100113298	CA	Valley	Merced Foothills	209218	SNRACA13
526669	100113205	CA	Valley	Merced Foothills	209182	JMTWCA11
526671	100113361	CA	Valley	Merced Foothills	209218	SNRACA13
526681	100113356	CA	Valley	Merced Foothills	209218	SNRACA13
526684	100113328	CA	Valley	Merced Foothills	209218	SNRACA13

526688	100113226	CA	Valley	Merced Foothills	209182	JMTWCA11
526716	100113339	CA	Valley	Merced Foothills	209218	SNRACA13
526717	100113312	CA	Valley	Merced Foothills	209218	SNRACA13
526742	100113335	CA	Valley	Merced Foothills	209218	SNRACA13
527262	100114881	CA	Valley	Merced Foothills	209218	SNRACA13
527264	100114854	CA	Valley	Merced Foothills	209218	SNRACA13
527282	100114889	CA	Valley	Merced Foothills	209218	SNRACA13
527283	100114874	CA	Valley	Merced Foothills	209218	SNRACA13
527287	100114861	CA	Valley	Merced Foothills	209218	SNRACA13
527288	100114860	CA	Valley	Merced Foothills	209218	SNRACA13
527289	100114857	CA	Valley	Merced Foothills	209218	SNRACA13
527290	100114851	CA	Valley	Merced Foothills	209218	SNRACA13
527291	100114843	CA	Valley	Merced Foothills	209218	SNRACA13
527330	100114830	CA	Valley	Merced Foothills	209173	GVLDCA11
527347	100114965	CA	Valley	Merced Foothills	209209	PNCRCA11
527520	100114892	CA	Valley	Merced Foothills	209218	SNRACA13
527572	100114882	CA	Valley	Merced Foothills	209218	SNRACA13
527573	100114880	CA	Valley	Merced Foothills	209218	SNRACA13
527574	100114879	CA	Valley	Merced Foothills	209218	SNRACA13
527575	100114876	CA	Valley	Merced Foothills	209218	SNRACA13
527621	100114869	CA	Valley	Merced Foothills	209218	SNRACA13
527623	100114867	CA	Valley	Merced Foothills	209218	SNRACA13

527624	100114866	CA	Valley	Merced Foothills	209218	SNRACA13
527625	100114864	CA	Valley	Merced Foothills	209218	SNRACA13
527734	100114833	CA	Valley	Merced Foothills	209173	GVLDCA11
527735	100114832	CA	Valley	Merced Foothills	209173	GVLDCA11
527736	100114831	CA	Valley	Merced Foothills	209173	GVLDCA11
527739	100114827	CA	Valley	Merced Foothills	209173	GVLDCA11
527740	100114826	CA	Valley	Merced Foothills	209173	GVLDCA11
527742	100114824	CA	Valley	Merced Foothills	209173	GVLDCA11
527746	100114820	CA	Valley	Merced Foothills	209173	GVLDCA11
527747	100114819	CA	Valley	Merced Foothills	209173	GVLDCA11
527798	100114810	CA	Valley	Merced Foothills	209173	GVLDCA11
527803	100114805	CA	Valley	Merced Foothills	209173	GVLDCA11
527805	100114803	CA	Valley	Merced Foothills	209173	GVLDCA11
527864	100114924	CA	Valley	Merced Foothills	209218	SNRACA13
527865	100114923	CA	Valley	Merced Foothills	209218	SNRACA13
527912	100114911	CA	Valley	Merced Foothills	209218	SNRACA13
528103	100114957	CA	Valley	Merced Foothills	209209	PNCRCA11
528252	100114872	CA	Valley	Merced Foothills	209218	SNRACA13
528301	100114888	CA	Valley	Merced Foothills	209218	SNRACA13
528302	100114878	CA	Valley	Merced Foothills	209218	SNRACA13
528303	100114877	CA	Valley	Merced Foothills	209218	SNRACA13
528309	100114865	CA	Valley	Merced Foothills	209218	SNRACA13

528310	100114856	CA	Valley	Merced Foothills	209218	SNRACA13
528316	100114847	CA	Valley	Merced Foothills	209218	SNRACA13
528317	100114839	CA	Valley	Merced Foothills	209218	SNRACA13
528323	100114834	CA	Valley	Merced Foothills	209218	SNRACA13
528333	100114794	CA	Valley	Merced Foothills	209173	GVLDCA11
528336	100114922	CA	Valley	Merced Foothills	209218	SNRACA13
528342	100114917	CA	Valley	Merced Foothills	209218	SNRACA13
528343	100114910	CA	Valley	Merced Foothills	209218	SNRACA13
528344	100114901	CA	Valley	Merced Foothills	209218	SNRACA13
528365	100114974	CA	Valley	Merced Foothills	209209	PNCRCA11
528366	100114966	CA	Valley	Merced Foothills	209209	PNCRCA11
528371	100114952	CA	Valley	Merced Foothills	209209	PNCRCA11
538503	100123739	CA	Valley	Merced Foothills	209193	LSBNCA12
567017	100141304	CA	Valley	Merced Foothills	209218	SNRACA13
572007	100144743	CA	Valley	Merced Foothills	209153	ATWRCA12
584058	100153778	CA	Valley	Merced Foothills	209196	MRCDCA01
599309	100166918	CA	Valley	Merced Foothills	209218	SNRACA13
696444		California	Valley	Merced Foothills	209233	TWHRCA11
706555	100235431	CA	Valley	Merced Foothills	209218	SNRACA13
706556	100235398	CA	Valley	Merced Foothills	209218	SNRACA13
742244	100257392	CA	Valley	Fresno	559243	MADRCA12
755678	100266171	CA	Valley	Merced Foothills	209161	CTVLCA11

756221	100266350	CA	Valley	Merced Foothills	209182	JMTWCA11
756222	100266348	CA	Valley	Merced Foothills	209182	JMTWCA11
756223	100266347	CA	Valley	Merced Foothills	209182	JMTWCA11
756224	100266306	CA	Valley	Merced Foothills	209182	JMTWCA11
756226	100266303	CA	Valley	Merced Foothills	209182	JMTWCA11
756227	100266302	CA	Valley	Merced Foothills	209182	JMTWCA11
756228	100266300	CA	Valley	Merced Foothills	209182	JMTWCA11
756230	100266296	CA	Valley	Merced Foothills	209182	JMTWCA11
756231	100266295	CA	Valley	Merced Foothills	209182	JMTWCA11
756233	100266406	CA	Valley	Merced Foothills	209182	JMTWCA11
756234	100266404	CA	Valley	Merced Foothills	209182	JMTWCA11
756235	100266401	CA	Valley	Merced Foothills	209182	JMTWCA11
756236	100266400	CA	Valley	Merced Foothills	209182	JMTWCA11
756238	100266397	CA	Valley	Merced Foothills	209182	JMTWCA11
756239	100266395	CA	Valley	Merced Foothills	209182	JMTWCA11
756240	100266392	CA	Valley	Merced Foothills	209182	JMTWCA11
756241	100266381	CA	Valley	Merced Foothills	209182	JMTWCA11
756244	100266378	CA	Valley	Merced Foothills	209182	JMTWCA11
756245	100266376	CA	Valley	Merced Foothills	209182	JMTWCA11
756246	100266374	CA	Valley	Merced Foothills	209182	JMTWCA11
756247	100266373	CA	Valley	Merced Foothills	209182	JMTWCA11
756248	100266372	CA	Valley	Merced Foothills	209182	JMTWCA11

756251	100266469	CA	Valley	Merced Foothills	209185	LGRNCA12
756252	100266468	CA	Valley	Merced Foothills	209185	LGRNCA12
756253	100266455	CA	Valley	Merced Foothills	209182	JMTWCA11
756254	100266454	CA	Valley	Merced Foothills	209182	JMTWCA11
756255	100266452	CA	Valley	Merced Foothills	209182	JMTWCA11
756256	100266451	CA	Valley	Merced Foothills	209182	JMTWCA11
756257	100266448	CA	Valley	Merced Foothills	209182	JMTWCA11
756261	100266446	CA	Valley	Merced Foothills	209182	JMTWCA11
756262	100266444	CA	Valley	Merced Foothills	209182	JMTWCA11
756263	100266443	CA	Valley	Merced Foothills	209182	JMTWCA11
756264	100266441	CA	Valley	Merced Foothills	209182	JMTWCA11
756265	100266440	CA	Valley	Merced Foothills	209182	JMTWCA11
756266	100266437	CA	Valley	Merced Foothills	209182	JMTWCA11
756267	100266436	CA	Valley	Merced Foothills	209182	JMTWCA11
756268	100266433	CA	Valley	Merced Foothills	209182	JMTWCA11
756269	100266431	CA	Valley	Merced Foothills	209182	JMTWCA11
756270	100266430	CA	Valley	Merced Foothills	209182	JMTWCA11
756271	100266428	CA	Valley	Merced Foothills	209182	JMTWCA11
756272	100266426	CA	Valley	Merced Foothills	209182	JMTWCA11
756273	100266425	CA	Valley	Merced Foothills	209182	JMTWCA11
756274	100266423	CA	Valley	Merced Foothills	209182	JMTWCA11
756275	100266421	CA	Valley	Merced Foothills	209182	JMTWCA11

756276	100266414	CA	Valley	Merced Foothills	209182	JMTWCA11
756277	100266411	CA	Valley	Merced Foothills	209182	JMTWCA11
756278	100266409	CA	Valley	Merced Foothills	209182	JMTWCA11
756279	100266408	CA	Valley	Merced Foothills	209182	JMTWCA11
756280	100266345	CA	Valley	Merced Foothills	209182	JMTWCA11
756281	100266340	CA	Valley	Merced Foothills	209182	JMTWCA11
756282	100266339	CA	Valley	Merced Foothills	209182	JMTWCA11
756283	100266335	CA	Valley	Merced Foothills	209182	JMTWCA11
756284	100266332	CA	Valley	Merced Foothills	209182	JMTWCA11
756285	100266329	CA	Valley	Merced Foothills	209182	JMTWCA11
756286	100266328	CA	Valley	Merced Foothills	209182	JMTWCA11
756287	100266327	CA	Valley	Merced Foothills	209182	JMTWCA11
756288	100266325	CA	Valley	Merced Foothills	209182	JMTWCA11
756289	100266323	CA	Valley	Merced Foothills	209182	JMTWCA11
756290	100266321	CA	Valley	Merced Foothills	209182	JMTWCA11
756291	100266319	CA	Valley	Merced Foothills	209182	JMTWCA11
756292	100266318	CA	Valley	Merced Foothills	209182	JMTWCA11
756293	100266316	CA	Valley	Merced Foothills	209182	JMTWCA11
756294	100266315	CA	Valley	Merced Foothills	209182	JMTWCA11
756297	100266313	CA	Valley	Merced Foothills	209182	JMTWCA11
756298	100266312	CA	Valley	Merced Foothills	209182	JMTWCA11
756299	100266309	CA	Valley	Merced Foothills	209182	JMTWCA11

756300	100266308	CA	Valley	Merced Foothills	209182	JMTWCA11
756301	100266307	CA	Valley	Merced Foothills	209182	JMTWCA11
756302	100266366	CA	Valley	Merced Foothills	209182	JMTWCA11
756303	100266363	CA	Valley	Merced Foothills	209182	JMTWCA11
756304	100266359	CA	Valley	Merced Foothills	209182	JMTWCA11
756305	100266358	CA	Valley	Merced Foothills	209182	JMTWCA11
756319	100266355	CA	Valley	Merced Foothills	209182	JMTWCA11
756320	100266354	CA	Valley	Merced Foothills	209182	JMTWCA11
756321	100266353	CA	Valley	Merced Foothills	209182	JMTWCA11
756323	100266351	CA	Valley	Merced Foothills	209182	JMTWCA11
756327	100266299	CA	Valley	Merced Foothills	209182	JMTWCA11
756328	100266298	CA	Valley	Merced Foothills	209182	JMTWCA11
756333	100266294	CA	Valley	Merced Foothills	209182	JMTWCA11
756346	100266399	CA	Valley	Merced Foothills	209182	JMTWCA11
756365	100266396	CA	Valley	Merced Foothills	209182	JMTWCA11
756368	100266391	CA	Valley	Merced Foothills	209182	JMTWCA11
756370	100266389	CA	Valley	Merced Foothills	209182	JMTWCA11
756371	100266387	CA	Valley	Merced Foothills	209182	JMTWCA11
756373	100266384	CA	Valley	Merced Foothills	209182	JMTWCA11
756375	100266382	CA	Valley	Merced Foothills	209182	JMTWCA11
756377	100266379	CA	Valley	Merced Foothills	209182	JMTWCA11
756389	100266375	CA	Valley	Merced Foothills	209182	JMTWCA11

756391	100266370	CA	Valley	Merced Foothills	209182	JMTWCA11
756392	100266369	CA	Valley	Merced Foothills	209182	JMTWCA11
756393	100266368	CA	Valley	Merced Foothills	209182	JMTWCA11
756419	100266447	CA	Valley	Merced Foothills	209182	JMTWCA11
756438	100266434	CA	Valley	Merced Foothills	209182	JMTWCA11
756441	100266424	CA	Valley	Merced Foothills	209182	JMTWCA11
756442	100266422	CA	Valley	Merced Foothills	209182	JMTWCA11
756448	100266410	CA	Valley	Merced Foothills	209182	JMTWCA11
756467	100266346	CA	Valley	Merced Foothills	209182	JMTWCA11
756468	100266344	CA	Valley	Merced Foothills	209182	JMTWCA11
756470	100266342	CA	Valley	Merced Foothills	209182	JMTWCA11
756471	100266341	CA	Valley	Merced Foothills	209182	JMTWCA11
756494	100266311	CA	Valley	Merced Foothills	209182	JMTWCA11
756495	100266364	CA	Valley	Merced Foothills	209182	JMTWCA11
756496	100266362	CA	Valley	Merced Foothills	209182	JMTWCA11
756498	100266310	CA	Valley	Merced Foothills	209182	JMTWCA11
756501	100266357	CA	Valley	Merced Foothills	209182	JMTWCA11
756510	100266388	CA	Valley	Merced Foothills	209182	JMTWCA11
756511	100266385	CA	Valley	Merced Foothills	209182	JMTWCA11
756520	100266439	CA	Valley	Merced Foothills	209182	JMTWCA11
756521	100266427	CA	Valley	Merced Foothills	209182	JMTWCA11
756522	100266418	CA	Valley	Merced Foothills	209182	JMTWCA11

756523	100266415	CA	Valley	Merced Foothills	209182	JMTWCA11
756524	100266412	CA	Valley	Merced Foothills	209182	JMTWCA11
756525	100266331	CA	Valley	Merced Foothills	209182	JMTWCA11
756943	100267375	CA	Valley	Merced Foothills	209209	PNCRCA11
756944	100267374	CA	Valley	Merced Foothills	209209	PNCRCA11
756945	100267373	CA	Valley	Merced Foothills	209209	PNCRCA11
756946	100267371	CA	Valley	Merced Foothills	209209	PNCRCA11
756947	100267368	CA	Valley	Merced Foothills	209209	PNCRCA11
756948	100267367	CA	Valley	Merced Foothills	209209	PNCRCA11
756949	100267366	CA	Valley	Merced Foothills	209209	PNCRCA11
756950	100267365	CA	Valley	Merced Foothills	209209	PNCRCA11
756951	100267363	CA	Valley	Merced Foothills	209209	PNCRCA11
756952	100267362	CA	Valley	Merced Foothills	209209	PNCRCA11
756953	100267361	CA	Valley	Merced Foothills	209209	PNCRCA11
756955	100267359	CA	Valley	Merced Foothills	209209	PNCRCA11
756956	100267358	CA	Valley	Merced Foothills	209209	PNCRCA11
756957	100267357	CA	Valley	Merced Foothills	209209	PNCRCA11
756958	100267355	CA	Valley	Merced Foothills	209209	PNCRCA11
757074	100267167	CA	Valley	Merced Foothills	209173	GVLDCA11
757097	100267157	CA	Valley	Merced Foothills	209173	GVLDCA11
757098	100267155	CA	Valley	Merced Foothills	209173	GVLDCA11
757104	100267148	CA	Valley	Merced Foothills	209173	GVLDCA11

757125	100267144	CA	Valley	Merced Foothills	209173	GVLDCA11
757127	100267142	CA	Valley	Merced Foothills	209173	GVLDCA11
757129	100267140	CA	Valley	Merced Foothills	209173	GVLDCA11
757286	100267138	CA	Valley	Merced Foothills	209173	GVLDCA11
757314	100267133	CA	Valley	Merced Foothills	209173	GVLDCA11
757435	100267174	CA	Valley	Merced Foothills	209173	GVLDCA11
757438	100267171	CA	Valley	Merced Foothills	209173	GVLDCA11
757440	100267169	CA	Valley	Merced Foothills	209173	GVLDCA11
757443	100267163	CA	Valley	Merced Foothills	209173	GVLDCA11
757448	100267156	CA	Valley	Merced Foothills	209173	GVLDCA11
757449	100267151	CA	Valley	Merced Foothills	209173	GVLDCA11
757496	100267139	CA	Valley	Merced Foothills	209173	GVLDCA11
757500	100267132	CA	Valley	Merced Foothills	209173	GVLDCA11
757868	100267803	CA	Valley	Merced Foothills	209218	SNRACA13
757869	100267800	CA	Valley	Merced Foothills	209218	SNRACA13
758055	100267890	CA	Valley	Merced Foothills	209218	SNRACA13
758056	100267884	CA	Valley	Merced Foothills	209218	SNRACA13
758103	100267825	CA	Valley	Merced Foothills	209218	SNRACA13
758105	100267823	CA	Valley	Merced Foothills	209218	SNRACA13
758106	100267822	CA	Valley	Merced Foothills	209218	SNRACA13
758108	100267820	CA	Valley	Merced Foothills	209218	SNRACA13
758114	100267813	CA	Valley	Merced Foothills	209218	SNRACA13

758136	100267811	CA	Valley	Merced Foothills	209218	SNRACA13
758137	100267810	CA	Valley	Merced Foothills	209218	SNRACA13
758143	100267804	CA	Valley	Merced Foothills	209218	SNRACA13
758145	100267801	CA	Valley	Merced Foothills	209218	SNRACA13
758166	100267794	CA	Valley	Merced Foothills	209218	SNRACA13
758169	100267791	CA	Valley	Merced Foothills	209218	SNRACA13
758171	100267789	CA	Valley	Merced Foothills	209218	SNRACA13
758172	100267788	CA	Valley	Merced Foothills	209218	SNRACA13
758173	100267787	CA	Valley	Merced Foothills	209218	SNRACA13
758174	100267786	CA	Valley	Merced Foothills	209218	SNRACA13
758177	100267783	CA	Valley	Merced Foothills	209218	SNRACA13
758182	100267778	CA	Valley	Merced Foothills	209218	SNRACA13
758183	100267777	CA	Valley	Merced Foothills	209218	SNRACA13
758198	100267911	CA	Valley	Merced Foothills	209218	SNRACA13
758218	100267908	CA	Valley	Merced Foothills	209218	SNRACA13
758219	100267907	CA	Valley	Merced Foothills	209218	SNRACA13
758220	100267906	CA	Valley	Merced Foothills	209218	SNRACA13
758221	100267905	CA	Valley	Merced Foothills	209218	SNRACA13
758222	100267904	CA	Valley	Merced Foothills	209218	SNRACA13
758318	100267757	CA	Valley	Merced Foothills	209218	SNRACA13
758346	100267746	CA	Valley	Merced Foothills	209218	SNRACA13

758378	100267722	CA	Valley	Merced Foothills	209218	SNRACA13
758381	100267719	CA	Valley	Merced Foothills	209218	SNRACA13
758501	100267900	CA	Valley	Merced Foothills	209218	SNRACA13
758511	100267888	CA	Valley	Merced Foothills	209218	SNRACA13
758512	100267887	CA	Valley	Merced Foothills	209218	SNRACA13
758513	100267886	CA	Valley	Merced Foothills	209218	SNRACA13
758515	100267883	CA	Valley	Merced Foothills	209218	SNRACA13
758545	100267877	CA	Valley	Merced Foothills	209218	SNRACA13
758547	100267874	CA	Valley	Merced Foothills	209218	SNRACA13
758549	100267872	CA	Valley	Merced Foothills	209218	SNRACA13
758550	100267871	CA	Valley	Merced Foothills	209218	SNRACA13
758553	100267868	CA	Valley	Merced Foothills	209218	SNRACA13
758554	100267867	CA	Valley	Merced Foothills	209218	SNRACA13
758556	100267865	CA	Valley	Merced Foothills	209218	SNRACA13
758569	100267863	CA	Valley	Merced Foothills	209218	SNRACA13
758574	100267858	CA	Valley	Merced Foothills	209218	SNRACA13
758575	100267857	CA	Valley	Merced Foothills	209218	SNRACA13
758577	100267855	CA	Valley	Merced Foothills	209218	SNRACA13
758579	100267853	CA	Valley	Merced Foothills	209218	SNRACA13
758582	100267850	CA	Valley	Merced Foothills	209218	SNRACA13

758584	100267848	CA	Valley	Merced Foothills	209218	SNRACA13
758597	100267847	CA	Valley	Merced Foothills	209218	SNRACA13
758598	100267846	CA	Valley	Merced Foothills	209218	SNRACA13
758603	100267840	CA	Valley	Merced Foothills	209218	SNRACA13
758606	100267837	CA	Valley	Merced Foothills	209218	SNRACA13
758611	100267832	CA	Valley	Merced Foothills	209218	SNRACA13
758612	100267831	CA	Valley	Merced Foothills	209218	SNRACA13
758642	100267816	CA	Valley	Merced Foothills	209218	SNRACA13
758651	100267796	CA	Valley	Merced Foothills	209218	SNRACA13
758674	100267743	CA	Valley	Merced Foothills	209218	SNRACA13
758675	100267738	CA	Valley	Merced Foothills	209218	SNRACA13
758679	100267726	CA	Valley	Merced Foothills	209218	SNRACA13
758680	100267718	CA	Valley	Merced Foothills	209218	SNRACA13
758706	100267895	CA	Valley	Merced Foothills	209218	SNRACA13
758728	100267876	CA	Valley	Merced Foothills	209218	SNRACA13
758754	100267841	CA	Valley	Merced Foothills	209218	SNRACA13
761483	100271589	CA	Valley	Merced Foothills	209233	TWHRCA11
761484	100271588	CA	Valley	Merced Foothills	209233	TWHRCA11
761485	100271585	CA	Valley	Merced Foothills	209233	TWHRCA11
761486	100271580	CA	Valley	Merced Foothills	209233	TWHRCA11

761487	100271558	CA	Valley	Merced Foothills	209233	TWHRCA11
761488	100271557	CA	Valley	Merced Foothills	209233	TWHRCA11
761489	100271551	CA	Valley	Merced Foothills	209233	TWHRCA11
761490	100271549	CA	Valley	Merced Foothills	209233	TWHRCA11
761491	100271546	CA	Valley	Merced Foothills	209233	TWHRCA11
761492	100271541	CA	Valley	Merced Foothills	209233	TWHRCA11
761493	100271533	CA	Valley	Merced Foothills	209233	TWHRCA11
761494	100271530	CA	Valley	Merced Foothills	209233	TWHRCA11
761495	100271525	CA	Valley	Merced Foothills	209233	TWHRCA11
761496	100271523	CA	Valley	Merced Foothills	209233	TWHRCA11
761497	100271520	CA	Valley	Merced Foothills	209233	TWHRCA11
761498	100271519	CA	Valley	Merced Foothills	209233	TWHRCA11
761499	100271517	CA	Valley	Merced Foothills	209233	TWHRCA11
761500	100271515	CA	Valley	Merced Foothills	209233	TWHRCA11
761501	100271513	CA	Valley	Merced Foothills	209233	TWHRCA11
761502	100271507	CA	Valley	Merced Foothills	209233	TWHRCA11
761503	100271496	CA	Valley	Merced Foothills	209233	TWHRCA11
761505	100271599	CA	Valley	Merced Foothills	209233	TWHRCA11
761506	100271598	CA	Valley	Merced Foothills	209233	TWHRCA11
761507	100271596	CA	Valley	Merced Foothills	209233	TWHRCA11
761508	100271594	CA	Valley	Merced Foothills	209233	TWHRCA11
761509	100271575	CA	Valley	Merced Foothills	209233	TWHRCA11

761510	100271572	CA	Valley	Merced Foothills	209233	TWHRCA11
761511	100271571	CA	Valley	Merced Foothills	209233	TWHRCA11
761512	100271570	CA	Valley	Merced Foothills	209233	TWHRCA11
761513	100271569	CA	Valley	Merced Foothills	209233	TWHRCA11
761514	100271566	CA	Valley	Merced Foothills	209233	TWHRCA11
761515	100271565	CA	Valley	Merced Foothills	209233	TWHRCA11
761516	100271244	CA	Valley	Merced Foothills	209233	TWHRCA11
761517	100271236	CA	Valley	Merced Foothills	209233	TWHRCA11
761518	100271233	CA	Valley	Merced Foothills	209233	TWHRCA11
761519	100271232	CA	Valley	Merced Foothills	209233	TWHRCA11
761520	100271384	CA	Valley	Merced Foothills	209233	TWHRCA11
761521	100271382	CA	Valley	Merced Foothills	209233	TWHRCA11
761522	100271373	CA	Valley	Merced Foothills	209233	TWHRCA11
761523	100271372	CA	Valley	Merced Foothills	209233	TWHRCA11
761524	100271228	CA	Valley	Merced Foothills	209233	TWHRCA11
761525	100271223	CA	Valley	Merced Foothills	209233	TWHRCA11
761526	100271216	CA	Valley	Merced Foothills	209233	TWHRCA11
761527	100271215	CA	Valley	Merced Foothills	209233	TWHRCA11
761528	100271211	CA	Valley	Merced Foothills	209233	TWHRCA11
761529	100271210	CA	Valley	Merced Foothills	209233	TWHRCA11
761530	100271203	CA	Valley	Merced Foothills	209233	TWHRCA11
761531	100271290	CA	Valley	Merced Foothills	209233	TWHRCA11

761532	100271282	CA	Valley	Merced Foothills	209233	TWHRCA11
761534	100271308	CA	Valley	Merced Foothills	209233	TWHRCA11
761535	100271301	CA	Valley	Merced Foothills	209233	TWHRCA11
761536	100271367	CA	Valley	Merced Foothills	209233	TWHRCA11
761537	100271366	CA	Valley	Merced Foothills	209233	TWHRCA11
761538	100271362	CA	Valley	Merced Foothills	209233	TWHRCA11
761539	100271356	CA	Valley	Merced Foothills	209233	TWHRCA11
761540	100271397	CA	Valley	Merced Foothills	209233	TWHRCA11
761541	100271342	CA	Valley	Merced Foothills	209233	TWHRCA11
761542	100271337	CA	Valley	Merced Foothills	209233	TWHRCA11
761543	100271488	CA	Valley	Merced Foothills	209233	TWHRCA11
761544	100271487	CA	Valley	Merced Foothills	209233	TWHRCA11
761545	100271482	CA	Valley	Merced Foothills	209233	TWHRCA11
761546	100271480	CA	Valley	Merced Foothills	209233	TWHRCA11
761547	100271478	CA	Valley	Merced Foothills	209233	TWHRCA11
761548	100271321	CA	Valley	Merced Foothills	209233	TWHRCA11
761549	100271471	CA	Valley	Merced Foothills	209233	TWHRCA11
761550	100271469	CA	Valley	Merced Foothills	209233	TWHRCA11
761551	100271464	CA	Valley	Merced Foothills	209233	TWHRCA11
761552	100271460	CA	Valley	Merced Foothills	209233	TWHRCA11
761553	100271458	CA	Valley	Merced Foothills	209233	TWHRCA11
761554	100271295	CA	Valley	Merced Foothills	209233	TWHRCA11

761555	100271422	CA	Valley	Merced Foothills	209233	TWHRCA11
761556	100271417	CA	Valley	Merced Foothills	209233	TWHRCA11
761557	100271415	CA	Valley	Merced Foothills	209233	TWHRCA11
761558	100271457	CA	Valley	Merced Foothills	209233	TWHRCA11
761559	100271455	CA	Valley	Merced Foothills	209233	TWHRCA11
761560	100271454	CA	Valley	Merced Foothills	209233	TWHRCA11
761561	100271452	CA	Valley	Merced Foothills	209233	TWHRCA11
761562	100271449	CA	Valley	Merced Foothills	209233	TWHRCA11
761563	100271445	CA	Valley	Merced Foothills	209233	TWHRCA11
761564	100271442	CA	Valley	Merced Foothills	209233	TWHRCA11
761565	100271441	CA	Valley	Merced Foothills	209233	TWHRCA11
761566	100271392	CA	Valley	Merced Foothills	209233	TWHRCA11
761567	100271265	CA	Valley	Merced Foothills	209233	TWHRCA11
761568	100271438	CA	Valley	Merced Foothills	209233	TWHRCA11
761569	100271431	CA	Valley	Merced Foothills	209233	TWHRCA11
761570	100271427	CA	Valley	Merced Foothills	209233	TWHRCA11
761571	100271254	CA	Valley	Merced Foothills	209233	TWHRCA11
761572	100271253	CA	Valley	Merced Foothills	209233	TWHRCA11
761573	100271252	CA	Valley	Merced Foothills	209233	TWHRCA11
761574	100271250	CA	Valley	Merced Foothills	209233	TWHRCA11
761575	100271248	CA	Valley	Merced Foothills	209233	TWHRCA11
761648	100271601	CA	Valley	Merced Foothills	209233	TWHRCA11

761650	100271597	CA	Valley	Merced Foothills	209233	TWHRCA11
761655	100271590	CA	Valley	Merced Foothills	209233	TWHRCA11
761659	100271568	CA	Valley	Merced Foothills	209233	TWHRCA11
761694	100271227	CA	Valley	Merced Foothills	209233	TWHRCA11
761807	100271359	CA	Valley	Merced Foothills	209233	TWHRCA11
761826	100271404	CA	Valley	Merced Foothills	209233	TWHRCA11
761832	100271398	CA	Valley	Merced Foothills	209233	TWHRCA11
761849	100271491	CA	Valley	Merced Foothills	209233	TWHRCA11
761854	100271483	CA	Valley	Merced Foothills	209233	TWHRCA11
761863	100271328	CA	Valley	Merced Foothills	209233	TWHRCA11
761884	100271461	CA	Valley	Merced Foothills	209233	TWHRCA11
761916	100271388	CA	Valley	Merced Foothills	209233	TWHRCA11
761961	100271550	CA	Valley	Merced Foothills	209233	TWHRCA11
761962	100271509	CA	Valley	Merced Foothills	209233	TWHRCA11
761964	100271561	CA	Valley	Merced Foothills	209233	TWHRCA11
761965	100271370	CA	Valley	Merced Foothills	209233	TWHRCA11
761972	100271288	CA	Valley	Merced Foothills	209233	TWHRCA11
761974	100271360	CA	Valley	Merced Foothills	209233	TWHRCA11
761976	100271344	CA	Valley	Merced Foothills	209233	TWHRCA11
761977	100271490	CA	Valley	Merced Foothills	209233	TWHRCA11
761978	100271327	CA	Valley	Merced Foothills	209233	TWHRCA11
761979	100271468	CA	Valley	Merced Foothills	209233	TWHRCA11

761981	100271435	CA	Valley	Merced Foothills	209233	TWHRCA11
761982	100271578	CA	Valley	Merced Foothills	209233	TWHRCA11
761984	100271255	CA	Valley	Merced Foothills	209233	TWHRCA11
777324	100283998	CA	Valley	Merced Foothills	209218	SNRACA13
797653		California	Valley	Merced Foothills	209218	SNRACA13
801535	100302528	CA	Valley	Merced Foothills	209185	LGRNCA12
833900	100325949	CA	Valley	Merced Foothills	209187	LGRDCA11
853608	100341482	CA	Valley	Merced Foothills	209233	TWHRCA11
880007	100358851	CA	Valley	Merced Foothills	209174	GUSTCA11
890552	100368293	CA	Valley	Merced Foothills	209233	TWHRCA11
898946	100376219	CA	Valley	Fresno	559194	MADRCA11
908898	100382140	CA	Valley	Fresno	559194	MADRCA11
948652		California	Valley	Merced Foothills	209218	SNRACA13
951275		California	Valley	Merced Foothills	209218	SNRACA13
954262		California	Valley	Merced Foothills	209218	SNRACA13
955468		California	Valley	Merced Foothills	209182	JMTWCA11
959940		California	Valley	Merced Foothills	209173	GVLDCA11
972269		California	Valley	Merced Foothills	209240	YSMTCA11
972270		California	Valley	Merced Foothills	209240	YSMTCA11
972274		California	Valley	Merced Foothills	209240	YSMTCA11
972276		California	Valley	Merced Foothills	209240	YSMTCA11
972277		California	Valley	Merced Foothills	209240	YSMTCA11

972279		California	Valley	Merced Foothills	209240	YSMTCA11
972280		California	Valley	Merced Foothills	209240	YSMTCA11
1011675	100462956	CA	Valley	Merced Foothills	209173	GVLDCA11
1011687	100462869	CA	Valley	Merced Foothills	209173	GVLDCA11
1011690	100462872	CA	Valley	Merced Foothills	209173	GVLDCA11
1011691	100462873	CA	Valley	Merced Foothills	209173	GVLDCA11
1011692	100462874	CA	Valley	Merced Foothills	209173	GVLDCA11
1011715	100462879	CA	Valley	Merced Foothills	209173	GVLDCA11
1011717	100462881	CA	Valley	Merced Foothills	209173	GVLDCA11
1011719	100462883	CA	Valley	Merced Foothills	209173	GVLDCA11
1011721	100462885	CA	Valley	Merced Foothills	209173	GVLDCA11
1011726	100462811	CA	Valley	Merced Foothills	209173	GVLDCA11
1011727	100462812	CA	Valley	Merced Foothills	209173	GVLDCA11
1011728	100462813	CA	Valley	Merced Foothills	209173	GVLDCA11
1011748	100462816	CA	Valley	Merced Foothills	209173	GVLDCA11
1011762	100463008	CA	Valley	Merced Foothills	209173	GVLDCA11
1011787	100463017	CA	Valley	Merced Foothills	209173	GVLDCA11
1011813	100462749	CA	Valley	Merced Foothills	209173	GVLDCA11
1011815	100462751	CA	Valley	Merced Foothills	209173	GVLDCA11
1011818	100462754	CA	Valley	Merced Foothills	209173	GVLDCA11
1011848	100463372	CA	Valley	Merced Foothills	209209	PNCRCA11
1011849	100463373	CA	Valley	Merced Foothills	209209	PNCRCA11

1011857	100462759	CA	Valley	Merced Foothills	209173	GVLDCA11
1011860	100462762	CA	Valley	Merced Foothills	209173	GVLDCA11
1011861	100462763	CA	Valley	Merced Foothills	209173	GVLDCA11
1011868	100462770	CA	Valley	Merced Foothills	209173	GVLDCA11
1011879	100463028	CA	Valley	Merced Foothills	209173	GVLDCA11
1011892	100463381	CA	Valley	Merced Foothills	209209	PNCRCA11
1011898	100463387	CA	Valley	Merced Foothills	209209	PNCRCA11
1011903	100463314	CA	Valley	Merced Foothills	209209	PNCRCA11
1011905	100463316	CA	Valley	Merced Foothills	209209	PNCRCA11
1011911	100462779	CA	Valley	Merced Foothills	209173	GVLDCA11
1011917	100462785	CA	Valley	Merced Foothills	209173	GVLDCA11
1011919	100462787	CA	Valley	Merced Foothills	209173	GVLDCA11
1011924	100462792	CA	Valley	Merced Foothills	209173	GVLDCA11
1011931	100463045	CA	Valley	Merced Foothills	209173	GVLDCA11
1011935	100463049	CA	Valley	Merced Foothills	209173	GVLDCA11
1011952	100463326	CA	Valley	Merced Foothills	209209	PNCRCA11
1011953	100463327	CA	Valley	Merced Foothills	209209	PNCRCA11
1011954	100463328	CA	Valley	Merced Foothills	209209	PNCRCA11
1011958	100463332	CA	Valley	Merced Foothills	209209	PNCRCA11
1011967	100462798	CA	Valley	Merced Foothills	209173	GVLDCA11
1011972	100462803	CA	Valley	Merced Foothills	209173	GVLDCA11
1011973	100462804	CA	Valley	Merced Foothills	209173	GVLDCA11

1011974	100462805	CA	Valley	Merced Foothills	209173	GVLDCA11
1011982	100463061	CA	Valley	Merced Foothills	209173	GVLDCA11
1011987	100463066	CA	Valley	Merced Foothills	209173	GVLDCA11
1011989	100463068	CA	Valley	Merced Foothills	209173	GVLDCA11
1012000	100463339	CA	Valley	Merced Foothills	209209	PNCRCA11
1012005	100463344	CA	Valley	Merced Foothills	209209	PNCRCA11
1012015	100463354	CA	Valley	Merced Foothills	209209	PNCRCA11
1012016	100463355	CA	Valley	Merced Foothills	209209	PNCRCA11
1012044	100462970	CA	Valley	Merced Foothills	209173	GVLDCA11
1012046	100462972	CA	Valley	Merced Foothills	209173	GVLDCA11
1012054	100463357	CA	Valley	Merced Foothills	209209	PNCRCA11
1012057	100463360	CA	Valley	Merced Foothills	209209	PNCRCA11
1012058	100463361	CA	Valley	Merced Foothills	209209	PNCRCA11
1012059	100463362	CA	Valley	Merced Foothills	209209	PNCRCA11
1012063	100463366	CA	Valley	Merced Foothills	209209	PNCRCA11
1012066	100463369	CA	Valley	Merced Foothills	209209	PNCRCA11
1012078	100462739	CA	Valley	Merced Foothills	209173	GVLDCA11
1012079	100462740	CA	Valley	Merced Foothills	209173	GVLDCA11
1012080	100462741	CA	Valley	Merced Foothills	209173	GVLDCA11
1012081	100462743	CA	Valley	Merced Foothills	209173	GVLDCA11
1012083	100462745	CA	Valley	Merced Foothills	209173	GVLDCA11

1012101	100462992	CA	Valley	Merced Foothills	209173	GVLDCA11
1012132	100462838	CA	Valley	Merced Foothills	209173	GVLDCA11
1012135	100462841	CA	Valley	Merced Foothills	209173	GVLDCA11
1012137	100462843	CA	Valley	Merced Foothills	209173	GVLDCA11
1012142	100462999	CA	Valley	Merced Foothills	209173	GVLDCA11
1012144	100463001	CA	Valley	Merced Foothills	209173	GVLDCA11
1012147	100463004	CA	Valley	Merced Foothills	209173	GVLDCA11
1012174	100462846	CA	Valley	Merced Foothills	209173	GVLDCA11
1012175	100462847	CA	Valley	Merced Foothills	209173	GVLDCA11
1012178	100462850	CA	Valley	Merced Foothills	209173	GVLDCA11
1012211	100463412	CA	Valley	Merced Foothills	209209	PNCRCA11
1012213	100463414	CA	Valley	Merced Foothills	209209	PNCRCA11
1012214	100463415	CA	Valley	Merced Foothills	209209	PNCRCA11
1012217	100463418	CA	Valley	Merced Foothills	209209	PNCRCA11
1012219	100463420	CA	Valley	Merced Foothills	209209	PNCRCA11
1012220	100463421	CA	Valley	Merced Foothills	209209	PNCRCA11
1012221	100463422	CA	Valley	Merced Foothills	209209	PNCRCA11
1012223	100463424	CA	Valley	Merced Foothills	209209	PNCRCA11
1012224	100463425	CA	Valley	Merced Foothills	209209	PNCRCA11
1012227	100463428	CA	Valley	Merced Foothills	209209	PNCRCA11
1012229	100462865	CA	Valley	Merced Foothills	209173	GVLDCA11
1012232	100462888	CA	Valley	Merced Foothills	209173	GVLDCA11

1012234	100462890	CA	Valley	Merced Foothills	209173	GVLDCA11
1012237	100462893	CA	Valley	Merced Foothills	209173	GVLDCA11
1012238	100462894	CA	Valley	Merced Foothills	209173	GVLDCA11
1012239	100462895	CA	Valley	Merced Foothills	209173	GVLDCA11
1012240	100462896	CA	Valley	Merced Foothills	209173	GVLDCA11
1012242	100462898	CA	Valley	Merced Foothills	209173	GVLDCA11
1012265	100463429	CA	Valley	Merced Foothills	209209	PNCRCA11
1012267	100463431	CA	Valley	Merced Foothills	209209	PNCRCA11
1012268	100463432	CA	Valley	Merced Foothills	209209	PNCRCA11
1012270	100463434	CA	Valley	Merced Foothills	209209	PNCRCA11
1012271	100463435	CA	Valley	Merced Foothills	209209	PNCRCA11
1012276	100463440	CA	Valley	Merced Foothills	209209	PNCRCA11
1012278	100463442	CA	Valley	Merced Foothills	209209	PNCRCA11
1012286	100462906	CA	Valley	Merced Foothills	209173	GVLDCA11
1012287	100462907	CA	Valley	Merced Foothills	209173	GVLDCA11
1012291	100462911	CA	Valley	Merced Foothills	209173	GVLDCA11
1012296	100462916	CA	Valley	Merced Foothills	209173	GVLDCA11
1012297	100462917	CA	Valley	Merced Foothills	209173	GVLDCA11
1012299	100462919	CA	Valley	Merced Foothills	209173	GVLDCA11
1012300	100462920	CA	Valley	Merced Foothills	209173	GVLDCA11
1012318	100463447	CA	Valley	Merced Foothills	209209	PNCRCA11
1012320	100463449	CA	Valley	Merced Foothills	209209	PNCRCA11

1012324	100463473	CA	Valley	Merced Foothills	209209	PNCRCA11
1012328	100463477	CA	Valley	Merced Foothills	209209	PNCRCA11
1012329	100463478	CA	Valley	Merced Foothills	209209	PNCRCA11
1012330	100463452	CA	Valley	Merced Foothills	209209	PNCRCA11
1012332	100463454	CA	Valley	Merced Foothills	209209	PNCRCA11
1012339	100462924	CA	Valley	Merced Foothills	209173	GVLDCA11
1012340	100462925	CA	Valley	Merced Foothills	209173	GVLDCA11
1012349	100462934	CA	Valley	Merced Foothills	209173	GVLDCA11
1012350	100462935	CA	Valley	Merced Foothills	209173	GVLDCA11
1012351	100462936	CA	Valley	Merced Foothills	209173	GVLDCA11
1012371	100463459	CA	Valley	Merced Foothills	209209	PNCRCA11
1012375	100463463	CA	Valley	Merced Foothills	209209	PNCRCA11
1012378	100463466	CA	Valley	Merced Foothills	209209	PNCRCA11
1012380	100463468	CA	Valley	Merced Foothills	209209	PNCRCA11
1012382	100463470	CA	Valley	Merced Foothills	209209	PNCRCA11
1012383	100463471	CA	Valley	Merced Foothills	209209	PNCRCA11
1012384	100463390	CA	Valley	Merced Foothills	209209	PNCRCA11
1012385	100463391	CA	Valley	Merced Foothills	209209	PNCRCA11
1012386	100463392	CA	Valley	Merced Foothills	209209	PNCRCA11
1012391	100462941	CA	Valley	Merced Foothills	209173	GVLDCA11
1012393	100462943	CA	Valley	Merced Foothills	209173	GVLDCA11
1012395	100462945	CA	Valley	Merced Foothills	209173	GVLDCA11

1012399	100462949	CA	Valley	Merced Foothills	209173	GVLDCA11
1012425	100463395	CA	Valley	Merced Foothills	209209	PNCRCA11
1012426	100463396	CA	Valley	Merced Foothills	209209	PNCRCA11
1012427	100463397	CA	Valley	Merced Foothills	209209	PNCRCA11
1012430	100463400	CA	Valley	Merced Foothills	209209	PNCRCA11
1012431	100463401	CA	Valley	Merced Foothills	209209	PNCRCA11
1012432	100463402	CA	Valley	Merced Foothills	209209	PNCRCA11
1012433	100463403	CA	Valley	Merced Foothills	209209	PNCRCA11
1012434	100463404	CA	Valley	Merced Foothills	209209	PNCRCA11
1012435	100463405	CA	Valley	Merced Foothills	209209	PNCRCA11
1012438	100463408	CA	Valley	Merced Foothills	209209	PNCRCA11
1018129	100469010	CA	Valley	Merced Foothills	209185	LGRNCA12
1018164	100469026	CA	Valley	Merced Foothills	209185	LGRNCA12
1018165	100469027	CA	Valley	Merced Foothills	209185	LGRNCA12
1018180	100468913	CA	Valley	Merced Foothills	209185	LGRNCA12
1018200	100468916	CA	Valley	Merced Foothills	209185	LGRNCA12
1018203	100468919	CA	Valley	Merced Foothills	209185	LGRNCA12
1018205	100468921	CA	Valley	Merced Foothills	209185	LGRNCA12
1018206	100468922	CA	Valley	Merced Foothills	209185	LGRNCA12
1018210	100468926	CA	Valley	Merced Foothills	209185	LGRNCA12
1018268	100468949	CA	Valley	Merced Foothills	209185	LGRNCA12
1018275	100468956	CA	Valley	Merced Foothills	209185	LGRNCA12

1018278	100468959	CA	Valley	Merced Foothills	209185	LGRNCA12
1018309	100468973	CA	Valley	Merced Foothills	209185	LGRNCA12
1018312	100468976	CA	Valley	Merced Foothills	209185	LGRNCA12
1018338	100468983	CA	Valley	Merced Foothills	209185	LGRNCA12
1018339	100468984	CA	Valley	Merced Foothills	209185	LGRNCA12
1018342	100469042	CA	Valley	Merced Foothills	209185	LGRNCA12
1018352	100469052	CA	Valley	Merced Foothills	209185	LGRNCA12
1018370	100469053	CA	Valley	Merced Foothills	209185	LGRNCA12
1018373	100469056	CA	Valley	Merced Foothills	209185	LGRNCA12
1018381	100469064	CA	Valley	Merced Foothills	209185	LGRNCA12
1018384	100469067	CA	Valley	Merced Foothills	209185	LGRNCA12
1018385	100469068	CA	Valley	Merced Foothills	209185	LGRNCA12
1018391	100468880	CA	Valley	Merced Foothills	209185	LGRNCA12
1018392	100468881	CA	Valley	Merced Foothills	209185	LGRNCA12
1018393	100468882	CA	Valley	Merced Foothills	209185	LGRNCA12
1018394	100468883	CA	Valley	Merced Foothills	209185	LGRNCA12
1018395	100468884	CA	Valley	Merced Foothills	209185	LGRNCA12
1018397	100468886	CA	Valley	Merced Foothills	209185	LGRNCA12
1018401	100468890	CA	Valley	Merced Foothills	209185	LGRNCA12
1018405	100469071	CA	Valley	Merced Foothills	209185	LGRNCA12
1018421	100468893	CA	Valley	Merced Foothills	209185	LGRNCA12
1018422	100468894	CA	Valley	Merced Foothills	209185	LGRNCA12

1018424	100468896	CA	Valley	Merced Foothills	209185	LGRNCA12
1018428	100468900	CA	Valley	Merced Foothills	209185	LGRNCA12
1018429	100468901	CA	Valley	Merced Foothills	209185	LGRNCA12
1018430	100468902	CA	Valley	Merced Foothills	209185	LGRNCA12
1018435	100468907	CA	Valley	Merced Foothills	209185	LGRNCA12
1018440	100469163	CA	Valley	Merced Foothills	209240	YSMTCA11
1018449	100469172	CA	Valley	Merced Foothills	209240	YSMTCA11
1018453	100469081	CA	Valley	Merced Foothills	209185	LGRNCA12
1018456	100468911	CA	Valley	Merced Foothills	209185	LGRNCA12
1018472	100469083	CA	Valley	Merced Foothills	209185	LGRNCA12
1018474	100469085	CA	Valley	Merced Foothills	209185	LGRNCA12
1018475	100469086	CA	Valley	Merced Foothills	209185	LGRNCA12
1018478	100469089	CA	Valley	Merced Foothills	209185	LGRNCA12
1018479	100469090	CA	Valley	Merced Foothills	209185	LGRNCA12
1018482	100469093	CA	Valley	Merced Foothills	209185	LGRNCA12
1018484	100469095	CA	Valley	Merced Foothills	209185	LGRNCA12
1018485	100469096	CA	Valley	Merced Foothills	209185	LGRNCA12
1018486	100469097	CA	Valley	Merced Foothills	209185	LGRNCA12
1018487	100469098	CA	Valley	Merced Foothills	209185	LGRNCA12
1018488	100469099	CA	Valley	Merced Foothills	209185	LGRNCA12
1018507	100469100	CA	Valley	Merced Foothills	209185	LGRNCA12
1018508	100469101	CA	Valley	Merced Foothills	209185	LGRNCA12

1018509	100469102	CA	Valley	Merced Foothills	209185	LGRNCA12
1018510	100469103	CA	Valley	Merced Foothills	209185	LGRNCA12
1018512	100469105	CA	Valley	Merced Foothills	209185	LGRNCA12
1018513	100469106	CA	Valley	Merced Foothills	209185	LGRNCA12
1018514	100469107	CA	Valley	Merced Foothills	209185	LGRNCA12
1018516	100469109	CA	Valley	Merced Foothills	209185	LGRNCA12
1018517	100469110	CA	Valley	Merced Foothills	209185	LGRNCA12
1018518	100469111	CA	Valley	Merced Foothills	209185	LGRNCA12
1018519	100469112	CA	Valley	Merced Foothills	209185	LGRNCA12
1018520	100469113	CA	Valley	Merced Foothills	209185	LGRNCA12
1018521	100469114	CA	Valley	Merced Foothills	209185	LGRNCA12
1018522	100469115	CA	Valley	Merced Foothills	209185	LGRNCA12
1018523	100469116	CA	Valley	Merced Foothills	209185	LGRNCA12
1018536	100468842	CA	Valley	Merced Foothills	209185	LGRNCA12
1018539	100468845	CA	Valley	Merced Foothills	209185	LGRNCA12
1018540	100468846	CA	Valley	Merced Foothills	209185	LGRNCA12
1018541	100469117	CA	Valley	Merced Foothills	209185	LGRNCA12
1018542	100469118	CA	Valley	Merced Foothills	209185	LGRNCA12
1018543	100469119	CA	Valley	Merced Foothills	209185	LGRNCA12
1018544	100469120	CA	Valley	Merced Foothills	209185	LGRNCA12
1018545	100469121	CA	Valley	Merced Foothills	209185	LGRNCA12
1018547	100469123	CA	Valley	Merced Foothills	209185	LGRNCA12

1018548	100469124	CA	Valley	Merced Foothills	209185	LGRNCA12
1018549	100469125	CA	Valley	Merced Foothills	209185	LGRNCA12
1018553	100469129	CA	Valley	Merced Foothills	209185	LGRNCA12
1018554	100469130	CA	Valley	Merced Foothills	209185	LGRNCA12
1018555	100469131	CA	Valley	Merced Foothills	209185	LGRNCA12
1018557	100469133	CA	Valley	Merced Foothills	209185	LGRNCA12
1018560	100468849	CA	Valley	Merced Foothills	209185	LGRNCA12
1018561	100468850	CA	Valley	Merced Foothills	209185	LGRNCA12
1018562	100468851	CA	Valley	Merced Foothills	209185	LGRNCA12
1018563	100468852	CA	Valley	Merced Foothills	209185	LGRNCA12
1018564	100468853	CA	Valley	Merced Foothills	209185	LGRNCA12
1018565	100468854	CA	Valley	Merced Foothills	209185	LGRNCA12
1018566	100468855	CA	Valley	Merced Foothills	209185	LGRNCA12
1018568	100468857	CA	Valley	Merced Foothills	209185	LGRNCA12
1018570	100468859	CA	Valley	Merced Foothills	209185	LGRNCA12
1018571	100468860	CA	Valley	Merced Foothills	209185	LGRNCA12
1018573	100468862	CA	Valley	Merced Foothills	209185	LGRNCA12
1018574	100468863	CA	Valley	Merced Foothills	209185	LGRNCA12
1018575	100469134	CA	Valley	Merced Foothills	209185	LGRNCA12
1018576	100469135	CA	Valley	Merced Foothills	209185	LGRNCA12
1018582	100469141	CA	Valley	Merced Foothills	209238	WANACA11
1018593	100468864	CA	Valley	Merced Foothills	209185	LGRNCA12

1018595	100468866	CA	Valley	Merced Foothills	209185	LGRNCA12
1018596	100468867	CA	Valley	Merced Foothills	209185	LGRNCA12
1018597	100468868	CA	Valley	Merced Foothills	209185	LGRNCA12
1018598	100468869	CA	Valley	Merced Foothills	209185	LGRNCA12
1018599	100468870	CA	Valley	Merced Foothills	209185	LGRNCA12
1018600	100468871	CA	Valley	Merced Foothills	209185	LGRNCA12
1018601	100468872	CA	Valley	Merced Foothills	209185	LGRNCA12
1018602	100468873	CA	Valley	Merced Foothills	209185	LGRNCA12
1018603	100468986	CA	Valley	Merced Foothills	209185	LGRNCA12
1018604	100468987	CA	Valley	Merced Foothills	209185	LGRNCA12
1018605	100468988	CA	Valley	Merced Foothills	209185	LGRNCA12
1018606	100468989	CA	Valley	Merced Foothills	209185	LGRNCA12
1018607	100468990	CA	Valley	Merced Foothills	209185	LGRNCA12
1018608	100468991	CA	Valley	Merced Foothills	209185	LGRNCA12
1018609	100468992	CA	Valley	Merced Foothills	209185	LGRNCA12
1018611	100468993	CA	Valley	Merced Foothills	209185	LGRNCA12
1018612	100468994	CA	Valley	Merced Foothills	209185	LGRNCA12
1018613	100468995	CA	Valley	Merced Foothills	209185	LGRNCA12
1018614	100468996	CA	Valley	Merced Foothills	209185	LGRNCA12
1018615	100468997	CA	Valley	Merced Foothills	209185	LGRNCA12
1018616	100468998	CA	Valley	Merced Foothills	209185	LGRNCA12
1018617	100468999	CA	Valley	Merced Foothills	209185	LGRNCA12

1018618	100469000	CA	Valley	Merced Foothills	209185	LGRNCA12
1018619	100469001	CA	Valley	Merced Foothills	209185	LGRNCA12
1018620	100469002	CA	Valley	Merced Foothills	209185	LGRNCA12
1018621	100469003	CA	Valley	Merced Foothills	209185	LGRNCA12
1018622	100469004	CA	Valley	Merced Foothills	209185	LGRNCA12
1018623	100469005	CA	Valley	Merced Foothills	209185	LGRNCA12
1018624	100469006	CA	Valley	Merced Foothills	209185	LGRNCA12
1018625	100469007	CA	Valley	Merced Foothills	209185	LGRNCA12
1018626	100469008	CA	Valley	Merced Foothills	209185	LGRNCA12
1018627	100469009	CA	Valley	Merced Foothills	209185	LGRNCA12
1019940	100470209	CA	Valley	Merced Foothills	209161	CTVLCA11
1019941	100470189	CA	Valley	Merced Foothills	209161	CTVLCA11
1019942	100470184	CA	Valley	Merced Foothills	209161	CTVLCA11
1019943	100470183	CA	Valley	Merced Foothills	209161	CTVLCA11
1019944	100470164	CA	Valley	Merced Foothills	209161	CTVLCA11
1019945	100470156	CA	Valley	Merced Foothills	209161	CTVLCA11
1019949	100470248	CA	Valley	Merced Foothills	209241	YSMTCA12
1019951	100470244	CA	Valley	Merced Foothills	209241	YSMTCA12
1019952	100470237	CA	Valley	Merced Foothills	209161	CTVLCA11
1019953	100470194	CA	Valley	Merced Foothills	209161	CTVLCA11

1019954	100470166	CA	Valley	Merced Foothills	209161	CTVLCA11
1019968	100470249	CA	Valley	Merced Foothills	209241	YSMTCA12
1019972	100470203	CA	Valley	Merced Foothills	209161	CTVLCA11
1019979	100470212	CA	Valley	Merced Foothills	209161	CTVLCA11
1019982	100470239	CA	Valley	Merced Foothills	209161	CTVLCA11
1019984	100470218	CA	Valley	Merced Foothills	209161	CTVLCA11
1019986	100470205	CA	Valley	Merced Foothills	209161	CTVLCA11
1019988	100470182	CA	Valley	Merced Foothills	209161	CTVLCA11
1019991	100470163	CA	Valley	Merced Foothills	209161	CTVLCA11
1019995	100470236	CA	Valley	Merced Foothills	209161	CTVLCA11
1019996	100470230	CA	Valley	Merced Foothills	209161	CTVLCA11
1019997	100470225	CA	Valley	Merced Foothills	209161	CTVLCA11
1019998	100470223	CA	Valley	Merced Foothills	209161	CTVLCA11
1019999	100470222	CA	Valley	Merced Foothills	209161	CTVLCA11
1020000	100470192	CA	Valley	Merced Foothills	209161	CTVLCA11
1020001	100470214	CA	Valley	Merced Foothills	209161	CTVLCA11
1020661	100471098	CA	Valley	Merced Foothills	209182	JMTWCA11
1020666	100471103	CA	Valley	Merced Foothills	209182	JMTWCA11
1020667	100471104	CA	Valley	Merced Foothills	209182	JMTWCA11
1020668	100471105	CA	Valley	Merced Foothills	209182	JMTWCA11
1020670	100471107	CA	Valley	Merced Foothills	209182	JMTWCA11

1020674	100471111	CA	Valley	Merced Foothills	209182	JMTWCA11
1020675	100471112	CA	Valley	Merced Foothills	209182	JMTWCA11
1020677	100471234	CA	Valley	Merced Foothills	209182	JMTWCA11
1020678	100471235	CA	Valley	Merced Foothills	209182	JMTWCA11
1020679	100471236	CA	Valley	Merced Foothills	209182	JMTWCA11
1020681	100471238	CA	Valley	Merced Foothills	209182	JMTWCA11
1020689	100471246	CA	Valley	Merced Foothills	209182	JMTWCA11
1020690	100471247	CA	Valley	Merced Foothills	209182	JMTWCA11
1020691	100471248	CA	Valley	Merced Foothills	209182	JMTWCA11
1020693	100471250	CA	Valley	Merced Foothills	209182	JMTWCA11
1020694	100471251	CA	Valley	Merced Foothills	209182	JMTWCA11
1020700	100471412	CA	Valley	Merced Foothills	209182	JMTWCA11
1020702	100471414	CA	Valley	Merced Foothills	209182	JMTWCA11
1020704	100471416	CA	Valley	Merced Foothills	209182	JMTWCA11
1020708	100471420	CA	Valley	Merced Foothills	209182	JMTWCA11
1020747	100471116	CA	Valley	Merced Foothills	209182	JMTWCA11
1020756	100471125	CA	Valley	Merced Foothills	209182	JMTWCA11
1020761	100471130	CA	Valley	Merced Foothills	209182	JMTWCA11
1020762	100471252	CA	Valley	Merced Foothills	209182	JMTWCA11
1020763	100471253	CA	Valley	Merced Foothills	209182	JMTWCA11

1020770	100471260	CA	Valley	Merced Foothills	209182	JMTWCA11
1020772	100471262	CA	Valley	Merced Foothills	209182	JMTWCA11
1020773	100471263	CA	Valley	Merced Foothills	209182	JMTWCA11
1020774	100471264	CA	Valley	Merced Foothills	209182	JMTWCA11
1020777	100471267	CA	Valley	Merced Foothills	209182	JMTWCA11
1020780	100471425	CA	Valley	Merced Foothills	209182	JMTWCA11
1020781	100471426	CA	Valley	Merced Foothills	209182	JMTWCA11
1020782	100471427	CA	Valley	Merced Foothills	209182	JMTWCA11
1020783	100471428	CA	Valley	Merced Foothills	209182	JMTWCA11
1020787	100471432	CA	Valley	Merced Foothills	209182	JMTWCA11
1020832	100471133	CA	Valley	Merced Foothills	209182	JMTWCA11
1020833	100471134	CA	Valley	Merced Foothills	209182	JMTWCA11
1020835	100471136	CA	Valley	Merced Foothills	209182	JMTWCA11
1020836	100471137	CA	Valley	Merced Foothills	209182	JMTWCA11
1020838	100471139	CA	Valley	Merced Foothills	209182	JMTWCA11
1020839	100471140	CA	Valley	Merced Foothills	209182	JMTWCA11
1020840	100471141	CA	Valley	Merced Foothills	209182	JMTWCA11
1020844	100471145	CA	Valley	Merced Foothills	209182	JMTWCA11
1020845	100471146	CA	Valley	Merced Foothills	209182	JMTWCA11
1020846	100471147	CA	Valley	Merced Foothills	209182	JMTWCA11
1020850	100471273	CA	Valley	Merced Foothills	209182	JMTWCA11

1020854	100471277	CA	Valley	Merced Foothills	209182	JMTWCA11
1020855	100471278	CA	Valley	Merced Foothills	209182	JMTWCA11
1020856	100471279	CA	Valley	Merced Foothills	209182	JMTWCA11
1020858	100471281	CA	Valley	Merced Foothills	209182	JMTWCA11
1020859	100471282	CA	Valley	Merced Foothills	209182	JMTWCA11
1020860	100471283	CA	Valley	Merced Foothills	209182	JMTWCA11
1020862	100471285	CA	Valley	Merced Foothills	209182	JMTWCA11
1020871	100471470	CA	Valley	Merced Foothills	209182	JMTWCA11
1020876	100471475	CA	Valley	Merced Foothills	209182	JMTWCA11
1020911	100471149	CA	Valley	Merced Foothills	209182	JMTWCA11
1020914	100471152	CA	Valley	Merced Foothills	209182	JMTWCA11
1020915	100471153	CA	Valley	Merced Foothills	209182	JMTWCA11
1020920	100471158	CA	Valley	Merced Foothills	209182	JMTWCA11
1020923	100471297	CA	Valley	Merced Foothills	209182	JMTWCA11
1020925	100471299	CA	Valley	Merced Foothills	209182	JMTWCA11
1020926	100471300	CA	Valley	Merced Foothills	209182	JMTWCA11
1020927	100471286	CA	Valley	Merced Foothills	209182	JMTWCA11
1020928	100471288	CA	Valley	Merced Foothills	209182	JMTWCA11
1020929	100471289	CA	Valley	Merced Foothills	209182	JMTWCA11
1020930	100471290	CA	Valley	Merced Foothills	209182	JMTWCA11
1020931	100471291	CA	Valley	Merced Foothills	209182	JMTWCA11

1020942	100471453	CA	Valley	Merced Foothills	209182	JMTWCA11
1020992	100471313	CA	Valley	Merced Foothills	209182	JMTWCA11
1020994	100471315	CA	Valley	Merced Foothills	209182	JMTWCA11
1020995	100471316	CA	Valley	Merced Foothills	209182	JMTWCA11
1020996	100471317	CA	Valley	Merced Foothills	209182	JMTWCA11
1020999	100471456	CA	Valley	Merced Foothills	209182	JMTWCA11
1021001	100471458	CA	Valley	Merced Foothills	209182	JMTWCA11
1021002	100471459	CA	Valley	Merced Foothills	209182	JMTWCA11
1021003	100471460	CA	Valley	Merced Foothills	209182	JMTWCA11
1021007	100471464	CA	Valley	Merced Foothills	209182	JMTWCA11
1021008	100471465	CA	Valley	Merced Foothills	209182	JMTWCA11
1021011	100471334	CA	Valley	Merced Foothills	209182	JMTWCA11
1021012	100471335	CA	Valley	Merced Foothills	209182	JMTWCA11
1021014	100471337	CA	Valley	Merced Foothills	209182	JMTWCA11
1021033	100471162	CA	Valley	Merced Foothills	209182	JMTWCA11
1021034	100471163	CA	Valley	Merced Foothills	209182	JMTWCA11
1021038	100471167	CA	Valley	Merced Foothills	209182	JMTWCA11
1021042	100471171	CA	Valley	Merced Foothills	209182	JMTWCA11
1021043	100471172	CA	Valley	Merced Foothills	209182	JMTWCA11
1021045	100471174	CA	Valley	Merced Foothills	209182	JMTWCA11
1021048	100471177	CA	Valley	Merced Foothills	209182	JMTWCA11
1021050	100471319	CA	Valley	Merced Foothills	209182	JMTWCA11

1021051	100471320	CA	Valley	Merced Foothills	209182	JMTWCA11
1021052	100471321	CA	Valley	Merced Foothills	209182	JMTWCA11
1021054	100471323	CA	Valley	Merced Foothills	209182	JMTWCA11
1021055	100471324	CA	Valley	Merced Foothills	209182	JMTWCA11
1021056	100471325	CA	Valley	Merced Foothills	209182	JMTWCA11
1021057	100471326	CA	Valley	Merced Foothills	209182	JMTWCA11
1021059	100471328	CA	Valley	Merced Foothills	209182	JMTWCA11
1021060	100471329	CA	Valley	Merced Foothills	209182	JMTWCA11
1021061	100471330	CA	Valley	Merced Foothills	209182	JMTWCA11
1021064	100471180	CA	Valley	Merced Foothills	209182	JMTWCA11
1021074	100471346	CA	Valley	Merced Foothills	209182	JMTWCA11
1021075	100471347	CA	Valley	Merced Foothills	209182	JMTWCA11
1021077	100471349	CA	Valley	Merced Foothills	209182	JMTWCA11
1021078	100471350	CA	Valley	Merced Foothills	209182	JMTWCA11
1021079	100471351	CA	Valley	Merced Foothills	209182	JMTWCA11
1021080	100471352	CA	Valley	Merced Foothills	209182	JMTWCA11
1021100	100471178	CA	Valley	Merced Foothills	209182	JMTWCA11
1021101	100471179	CA	Valley	Merced Foothills	209182	JMTWCA11
1021117	100471182	CA	Valley	Merced Foothills	209182	JMTWCA11
1021119	100471184	CA	Valley	Merced Foothills	209182	JMTWCA11
1021121	100471186	CA	Valley	Merced Foothills	209182	JMTWCA11

1021125	100471190	CA	Valley	Merced Foothills	209182	JMTWCA11
1021130	100471195	CA	Valley	Merced Foothills	209182	JMTWCA11
1021131	100471196	CA	Valley	Merced Foothills	209182	JMTWCA11
1021133	100471198	CA	Valley	Merced Foothills	209182	JMTWCA11
1021135	100471356	CA	Valley	Merced Foothills	209182	JMTWCA11
1021136	100471357	CA	Valley	Merced Foothills	209182	JMTWCA11
1021137	100471358	CA	Valley	Merced Foothills	209182	JMTWCA11
1021141	100471362	CA	Valley	Merced Foothills	209182	JMTWCA11
1021142	100471363	CA	Valley	Merced Foothills	209182	JMTWCA11
1021143	100471364	CA	Valley	Merced Foothills	209182	JMTWCA11
1021145	100471366	CA	Valley	Merced Foothills	209182	JMTWCA11
1021182	100471199	CA	Valley	Merced Foothills	209182	JMTWCA11
1021183	100471200	CA	Valley	Merced Foothills	209182	JMTWCA11
1021184	100471201	CA	Valley	Merced Foothills	209182	JMTWCA11
1021186	100471203	CA	Valley	Merced Foothills	209182	JMTWCA11
1021187	100471204	CA	Valley	Merced Foothills	209182	JMTWCA11
1021188	100471205	CA	Valley	Merced Foothills	209182	JMTWCA11
1021189	100471206	CA	Valley	Merced Foothills	209182	JMTWCA11
1021191	100471208	CA	Valley	Merced Foothills	209182	JMTWCA11
1021192	100471209	CA	Valley	Merced Foothills	209182	JMTWCA11
1021193	100471210	CA	Valley	Merced Foothills	209182	JMTWCA11
1021194	100471211	CA	Valley	Merced Foothills	209182	JMTWCA11

1021196	100471213	CA	Valley	Merced Foothills	209182	JMTWCA11
1021197	100471214	CA	Valley	Merced Foothills	209182	JMTWCA11
1021209	100471382	CA	Valley	Merced Foothills	209182	JMTWCA11
1021210	100471383	CA	Valley	Merced Foothills	209182	JMTWCA11
1021211	100471384	CA	Valley	Merced Foothills	209182	JMTWCA11
1021212	100471385	CA	Valley	Merced Foothills	209182	JMTWCA11
1021213	100471386	CA	Valley	Merced Foothills	209182	JMTWCA11
1021214	100471387	CA	Valley	Merced Foothills	209182	JMTWCA11
1021215	100471388	CA	Valley	Merced Foothills	209182	JMTWCA11
1021237	100471084	CA	Valley	Merced Foothills	209182	JMTWCA11
1021238	100471085	CA	Valley	Merced Foothills	209182	JMTWCA11
1021239	100471086	CA	Valley	Merced Foothills	209182	JMTWCA11
1021240	100471087	CA	Valley	Merced Foothills	209182	JMTWCA11
1021242	100471089	CA	Valley	Merced Foothills	209182	JMTWCA11
1021243	100471090	CA	Valley	Merced Foothills	209182	JMTWCA11
1021244	100471091	CA	Valley	Merced Foothills	209182	JMTWCA11
1021246	100471093	CA	Valley	Merced Foothills	209182	JMTWCA11
1021247	100471094	CA	Valley	Merced Foothills	209182	JMTWCA11
1021249	100471096	CA	Valley	Merced Foothills	209182	JMTWCA11
1021250	100471216	CA	Valley	Merced Foothills	209182	JMTWCA11
1021251	100471217	CA	Valley	Merced Foothills	209182	JMTWCA11

1021253	100471219	CA	Valley	Merced Foothills	209182	JMTWCA11
1021254	100471220	CA	Valley	Merced Foothills	209182	JMTWCA11
1021255	100471221	CA	Valley	Merced Foothills	209182	JMTWCA11
1021256	100471222	CA	Valley	Merced Foothills	209182	JMTWCA11
1021257	100471223	CA	Valley	Merced Foothills	209182	JMTWCA11
1021258	100471224	CA	Valley	Merced Foothills	209182	JMTWCA11
1021259	100471225	CA	Valley	Merced Foothills	209182	JMTWCA11
1021260	100471226	CA	Valley	Merced Foothills	209182	JMTWCA11
1021264	100471230	CA	Valley	Merced Foothills	209182	JMTWCA11
1021265	100471231	CA	Valley	Merced Foothills	209182	JMTWCA11
1021266	100471232	CA	Valley	Merced Foothills	209182	JMTWCA11
1021268	100471389	CA	Valley	Merced Foothills	209182	JMTWCA11
1021271	100471392	CA	Valley	Merced Foothills	209182	JMTWCA11
1021272	100471393	CA	Valley	Merced Foothills	209182	JMTWCA11
1021273	100471394	CA	Valley	Merced Foothills	209182	JMTWCA11
1021274	100471395	CA	Valley	Merced Foothills	209182	JMTWCA11
1021276	100471397	CA	Valley	Merced Foothills	209182	JMTWCA11
1021277	100471398	CA	Valley	Merced Foothills	209182	JMTWCA11
1021280	100471401	CA	Valley	Merced Foothills	209182	JMTWCA11
1021281	100471402	CA	Valley	Merced Foothills	209182	JMTWCA11
1021282	100471403	CA	Valley	Merced Foothills	209182	JMTWCA11

1023858		California	Valley	Merced Foothills	209233	TWHRCA11
1025254		California	Valley	Merced Foothills	209233	TWHRCA11
1031638	100475038	CA	Valley	Merced Foothills	209233	TWHRCA11
1050498	100494011	CA	Valley	Merced Foothills	209218	SNRACA13
1050500	100494013	CA	Valley	Merced Foothills	209218	SNRACA13
1050501	100494014	CA	Valley	Merced Foothills	209218	SNRACA13
1050505	100494018	CA	Valley	Merced Foothills	209218	SNRACA13
1050506	100494019	CA	Valley	Merced Foothills	209218	SNRACA13
1050507	100494020	CA	Valley	Merced Foothills	209218	SNRACA13
1050508	100494021	CA	Valley	Merced Foothills	209218	SNRACA13
1050509	100494022	CA	Valley	Merced Foothills	209218	SNRACA13
1050510	100494023	CA	Valley	Merced Foothills	209218	SNRACA13
1050511	100494024	CA	Valley	Merced Foothills	209218	SNRACA13
1050514	100494027	CA	Valley	Merced Foothills	209218	SNRACA13
1050515	100494028	CA	Valley	Merced Foothills	209218	SNRACA13
1050520	100493202	CA	Valley	Merced Foothills	209218	SNRACA13
1050523	100493205	CA	Valley	Merced Foothills	209218	SNRACA13
1050525	100493266	CA	Valley	Merced Foothills	209218	SNRACA13
1050538	100493509	CA	Valley	Merced Foothills	209218	SNRACA13
1050541	100493512	CA	Valley	Merced Foothills	209218	SNRACA13
1050542	100493513	CA	Valley	Merced Foothills	209218	SNRACA13
1050547	100493518	CA	Valley	Merced Foothills	209218	SNRACA13

1050549	100493520	CA	Valley	Merced Foothills	209218	SNRACA13
1050557	100493862	CA	Valley	Merced Foothills	209218	SNRACA13
1050560	100493865	CA	Valley	Merced Foothills	209218	SNRACA13
1050561	100493866	CA	Valley	Merced Foothills	209218	SNRACA13
1050562	100493867	CA	Valley	Merced Foothills	209218	SNRACA13
1050563	100493868	CA	Valley	Merced Foothills	209218	SNRACA13
1050567	100493872	CA	Valley	Merced Foothills	209218	SNRACA13
1050570	100494029	CA	Valley	Merced Foothills	209218	SNRACA13
1050574	100494033	CA	Valley	Merced Foothills	209218	SNRACA13
1050575	100494034	CA	Valley	Merced Foothills	209218	SNRACA13
1050577	100494036	CA	Valley	Merced Foothills	209218	SNRACA13
1050578	100494037	CA	Valley	Merced Foothills	209218	SNRACA13
1050579	100494038	CA	Valley	Merced Foothills	209218	SNRACA13
1050581	100494041	CA	Valley	Merced Foothills	209218	SNRACA13
1050582	100494042	CA	Valley	Merced Foothills	209218	SNRACA13
1050583	100494043	CA	Valley	Merced Foothills	209218	SNRACA13
1050584	100494044	CA	Valley	Merced Foothills	209218	SNRACA13
1050586	100494046	CA	Valley	Merced Foothills	209218	SNRACA13
1050587	100493275	CA	Valley	Merced Foothills	209218	SNRACA13
1050591	100493279	CA	Valley	Merced Foothills	209218	SNRACA13
1050595	100493283	CA	Valley	Merced Foothills	209218	SNRACA13
1050596	100493284	CA	Valley	Merced Foothills	209218	SNRACA13

1050600	100493288	CA	Valley	Merced Foothills	209218	SNRACA13
1050619	100493537	CA	Valley	Merced Foothills	209218	SNRACA13
1050627	100493658	CA	Valley	Merced Foothills	209218	SNRACA13
1050628	100493659	CA	Valley	Merced Foothills	209218	SNRACA13
1050630	100493661	CA	Valley	Merced Foothills	209218	SNRACA13
1050632	100493663	CA	Valley	Merced Foothills	209218	SNRACA13
1050633	100493664	CA	Valley	Merced Foothills	209218	SNRACA13
1050634	100493665	CA	Valley	Merced Foothills	209218	SNRACA13
1050635	100493666	CA	Valley	Merced Foothills	209218	SNRACA13
1050636	100493667	CA	Valley	Merced Foothills	209218	SNRACA13
1050638	100493669	CA	Valley	Merced Foothills	209218	SNRACA13
1050639	100493875	CA	Valley	Merced Foothills	209218	SNRACA13
1050640	100493876	CA	Valley	Merced Foothills	209218	SNRACA13
1050642	100493878	CA	Valley	Merced Foothills	209218	SNRACA13
1050643	100493879	CA	Valley	Merced Foothills	209218	SNRACA13
1050646	100493882	CA	Valley	Merced Foothills	209218	SNRACA13
1050650	100493886	CA	Valley	Merced Foothills	209218	SNRACA13
1050653	100493889	CA	Valley	Merced Foothills	209218	SNRACA13
1050654	100493948	CA	Valley	Merced Foothills	209218	SNRACA13
1050657	100494048	CA	Valley	Merced Foothills	209218	SNRACA13
1050658	100494049	CA	Valley	Merced Foothills	209218	SNRACA13

1050659	100494050	CA	Valley	Merced Foothills	209218	SNRACA13
1050662	100494053	CA	Valley	Merced Foothills	209218	SNRACA13
1050666	100494057	CA	Valley	Merced Foothills	209218	SNRACA13
1050669	100493295	CA	Valley	Merced Foothills	209218	SNRACA13
1050670	100493296	CA	Valley	Merced Foothills	209218	SNRACA13
1050673	100493299	CA	Valley	Merced Foothills	209218	SNRACA13
1050675	100493301	CA	Valley	Merced Foothills	209218	SNRACA13
1050679	100493305	CA	Valley	Merced Foothills	209218	SNRACA13
1050686	100493542	CA	Valley	Merced Foothills	209218	SNRACA13
1050687	100493543	CA	Valley	Merced Foothills	209218	SNRACA13
1050690	100493546	CA	Valley	Merced Foothills	209218	SNRACA13
1050692	100493548	CA	Valley	Merced Foothills	209218	SNRACA13
1050713	100493681	CA	Valley	Merced Foothills	209218	SNRACA13
1050722	100493953	CA	Valley	Merced Foothills	209218	SNRACA13
1050726	100493957	CA	Valley	Merced Foothills	209218	SNRACA13
1050728	100493959	CA	Valley	Merced Foothills	209218	SNRACA13
1050732	100493963	CA	Valley	Merced Foothills	209218	SNRACA13
1050737	100493369	CA	Valley	Merced Foothills	209218	SNRACA13
1050739	100493371	CA	Valley	Merced Foothills	209218	SNRACA13
1050740	100493372	CA	Valley	Merced Foothills	209218	SNRACA13
1050741	100493373	CA	Valley	Merced Foothills	209218	SNRACA13
1050743	100493375	CA	Valley	Merced Foothills	209218	SNRACA13

1050746	100493378	CA	Valley	Merced Foothills	209218	SNRACA13
1050750	100493382	CA	Valley	Merced Foothills	209218	SNRACA13
1050752	100493384	CA	Valley	Merced Foothills	209218	SNRACA13
1050760	100493430	CA	Valley	Merced Foothills	209218	SNRACA13
1050761	100493431	CA	Valley	Merced Foothills	209218	SNRACA13
1050762	100493432	CA	Valley	Merced Foothills	209218	SNRACA13
1050763	100493433	CA	Valley	Merced Foothills	209218	SNRACA13
1050764	100493434	CA	Valley	Merced Foothills	209218	SNRACA13
1050766	100493436	CA	Valley	Merced Foothills	209218	SNRACA13
1050772	100493572	CA	Valley	Merced Foothills	209218	SNRACA13
1050775	100493575	CA	Valley	Merced Foothills	209218	SNRACA13
1050779	100493690	CA	Valley	Merced Foothills	209218	SNRACA13
1050781	100493692	CA	Valley	Merced Foothills	209218	SNRACA13
1050783	100493694	CA	Valley	Merced Foothills	209218	SNRACA13
1050786	100493697	CA	Valley	Merced Foothills	209218	SNRACA13
1050787	100493698	CA	Valley	Merced Foothills	209218	SNRACA13
1050789	100493700	CA	Valley	Merced Foothills	209218	SNRACA13
1050791	100493702	CA	Valley	Merced Foothills	209218	SNRACA13
1050792	100493703	CA	Valley	Merced Foothills	209218	SNRACA13
1050793	100493704	CA	Valley	Merced Foothills	209218	SNRACA13
1050797	100493970	CA	Valley	Merced Foothills	209218	SNRACA13
1050799	100493972	CA	Valley	Merced Foothills	209218	SNRACA13

1050800	100493973	CA	Valley	Merced Foothills	209218	SNRACA13
1050801	100493974	CA	Valley	Merced Foothills	209218	SNRACA13
1050803	100493976	CA	Valley	Merced Foothills	209218	SNRACA13
1050804	100493977	CA	Valley	Merced Foothills	209218	SNRACA13
1050808	100493981	CA	Valley	Merced Foothills	209218	SNRACA13
1050811	100493386	CA	Valley	Merced Foothills	209218	SNRACA13
1050815	100493390	CA	Valley	Merced Foothills	209218	SNRACA13
1050816	100493391	CA	Valley	Merced Foothills	209218	SNRACA13
1050817	100493392	CA	Valley	Merced Foothills	209218	SNRACA13
1050819	100493394	CA	Valley	Merced Foothills	209218	SNRACA13
1050826	100493401	CA	Valley	Merced Foothills	209218	SNRACA13
1050827	100493402	CA	Valley	Merced Foothills	209218	SNRACA13
1050834	100493445	CA	Valley	Merced Foothills	209218	SNRACA13
1050836	100493447	CA	Valley	Merced Foothills	209218	SNRACA13
1050839	100493450	CA	Valley	Merced Foothills	209218	SNRACA13
1050842	100493453	CA	Valley	Merced Foothills	209218	SNRACA13
1050848	100493577	CA	Valley	Merced Foothills	209218	SNRACA13
1050850	100493579	CA	Valley	Merced Foothills	209218	SNRACA13
1050853	100493582	CA	Valley	Merced Foothills	209218	SNRACA13
1050854	100493583	CA	Valley	Merced Foothills	209218	SNRACA13
1050862	100493591	CA	Valley	Merced Foothills	209218	SNRACA13
1050866	100493707	CA	Valley	Merced Foothills	209218	SNRACA13

1050867	100493708	CA	Valley	Merced Foothills	209218	SNRACA13
1050869	100493710	CA	Valley	Merced Foothills	209218	SNRACA13
1050873	100493714	CA	Valley	Merced Foothills	209218	SNRACA13
1050879	100493602	CA	Valley	Merced Foothills	209218	SNRACA13
1050880	100493603	CA	Valley	Merced Foothills	209218	SNRACA13
1050885	100493987	CA	Valley	Merced Foothills	209218	SNRACA13
1050894	100493996	CA	Valley	Merced Foothills	209218	SNRACA13
1050896	100493998	CA	Valley	Merced Foothills	209218	SNRACA13
1050897	100493999	CA	Valley	Merced Foothills	209218	SNRACA13
1050898	100493404	CA	Valley	Merced Foothills	209218	SNRACA13
1050902	100493408	CA	Valley	Merced Foothills	209218	SNRACA13
1050903	100493409	CA	Valley	Merced Foothills	209218	SNRACA13
1050904	100493410	CA	Valley	Merced Foothills	209218	SNRACA13
1050907	100493413	CA	Valley	Merced Foothills	209218	SNRACA13
1050910	100493416	CA	Valley	Merced Foothills	209218	SNRACA13
1050912	100493418	CA	Valley	Merced Foothills	209218	SNRACA13
1050920	100493463	CA	Valley	Merced Foothills	209218	SNRACA13
1050921	100493464	CA	Valley	Merced Foothills	209218	SNRACA13
1050923	100493466	CA	Valley	Merced Foothills	209218	SNRACA13
1050925	100493468	CA	Valley	Merced Foothills	209218	SNRACA13
1050932	100493605	CA	Valley	Merced Foothills	209218	SNRACA13

1050939	100493612	CA	Valley	Merced Foothills	209218	SNRACA13
1050945	100493618	CA	Valley	Merced Foothills	209218	SNRACA13
1050946	100493619	CA	Valley	Merced Foothills	209218	SNRACA13
1050949	100493622	CA	Valley	Merced Foothills	209218	SNRACA13
1050953	100494003	CA	Valley	Merced Foothills	209218	SNRACA13
1050954	100493890	CA	Valley	Merced Foothills	209218	SNRACA13
1050955	100493891	CA	Valley	Merced Foothills	209218	SNRACA13
1050959	100493895	CA	Valley	Merced Foothills	209218	SNRACA13
1050961	100493897	CA	Valley	Merced Foothills	209218	SNRACA13
1050966	100493902	CA	Valley	Merced Foothills	209218	SNRACA13
1050967	100493903	CA	Valley	Merced Foothills	209218	SNRACA13
1050970	100493307	CA	Valley	Merced Foothills	209218	SNRACA13
1050971	100493308	CA	Valley	Merced Foothills	209218	SNRACA13
1050973	100493310	CA	Valley	Merced Foothills	209218	SNRACA13
1050984	100493321	CA	Valley	Merced Foothills	209218	SNRACA13
1050985	100493475	CA	Valley	Merced Foothills	209218	SNRACA13
1050986	100493476	CA	Valley	Merced Foothills	209218	SNRACA13
1050988	100493478	CA	Valley	Merced Foothills	209218	SNRACA13
1050992	100493560	CA	Valley	Merced Foothills	209218	SNRACA13
1050994	100493562	CA	Valley	Merced Foothills	209218	SNRACA13
1051003	100493624	CA	Valley	Merced Foothills	209218	SNRACA13
1051005	100493626	CA	Valley	Merced Foothills	209218	SNRACA13

1051006	100493627	CA	Valley	Merced Foothills	209218	SNRACA13
1051008	100493629	CA	Valley	Merced Foothills	209218	SNRACA13
1051010	100493631	CA	Valley	Merced Foothills	209218	SNRACA13
1051018	100493639	CA	Valley	Merced Foothills	209218	SNRACA13
1051021	100493905	CA	Valley	Merced Foothills	209218	SNRACA13
1051023	100493907	CA	Valley	Merced Foothills	209218	SNRACA13
1051026	100493910	CA	Valley	Merced Foothills	209218	SNRACA13
1051044	100493329	CA	Valley	Merced Foothills	209218	SNRACA13
1051045	100493330	CA	Valley	Merced Foothills	209218	SNRACA13
1051053	100493338	CA	Valley	Merced Foothills	209218	SNRACA13
1051056	100493643	CA	Valley	Merced Foothills	209218	SNRACA13
1051059	100493646	CA	Valley	Merced Foothills	209218	SNRACA13
1051060	100493647	CA	Valley	Merced Foothills	209218	SNRACA13
1051066	100493653	CA	Valley	Merced Foothills	209218	SNRACA13
1051067	100493654	CA	Valley	Merced Foothills	209218	SNRACA13
1051069	100493656	CA	Valley	Merced Foothills	209218	SNRACA13
1051070	100493773	CA	Valley	Merced Foothills	209218	SNRACA13
1051071	100493339	CA	Valley	Merced Foothills	209218	SNRACA13
1051076	100493344	CA	Valley	Merced Foothills	209218	SNRACA13
1051078	100493346	CA	Valley	Merced Foothills	209218	SNRACA13
1051079	100493347	CA	Valley	Merced Foothills	209218	SNRACA13

1051080	100493348	CA	Valley	Merced Foothills	209218	SNRACA13
1051085	100493353	CA	Valley	Merced Foothills	209218	SNRACA13
1051086	100493354	CA	Valley	Merced Foothills	209218	SNRACA13
1051087	100493355	CA	Valley	Merced Foothills	209218	SNRACA13
1051093	100493778	CA	Valley	Merced Foothills	209218	SNRACA13
1051095	100493780	CA	Valley	Merced Foothills	209218	SNRACA13
1051102	100493787	CA	Valley	Merced Foothills	209218	SNRACA13
1051105	100493790	CA	Valley	Merced Foothills	209218	SNRACA13
1051106	100493791	CA	Valley	Merced Foothills	209218	SNRACA13
1051109	100493359	CA	Valley	Merced Foothills	209218	SNRACA13
1051110	100493360	CA	Valley	Merced Foothills	209218	SNRACA13
1051111	100493361	CA	Valley	Merced Foothills	209218	SNRACA13
1051118	100493484	CA	Valley	Merced Foothills	209218	SNRACA13
1051120	100493486	CA	Valley	Merced Foothills	209218	SNRACA13
1051123	100493489	CA	Valley	Merced Foothills	209218	SNRACA13
1051125	100493792	CA	Valley	Merced Foothills	209218	SNRACA13
1051130	100493797	CA	Valley	Merced Foothills	209218	SNRACA13
1051141	100493808	CA	Valley	Merced Foothills	209218	SNRACA13
1051143	100493810	CA	Valley	Merced Foothills	209218	SNRACA13
1051151	100493818	CA	Valley	Merced Foothills	209218	SNRACA13
1051152	100493819	CA	Valley	Merced Foothills	209218	SNRACA13
1051153	100493820	CA	Valley	Merced Foothills	209218	SNRACA13

1051160	100493207	CA	Valley	Merced Foothills	209218	SNRACA13
1051169	100493216	CA	Valley	Merced Foothills	209218	SNRACA13
1051170	100493217	CA	Valley	Merced Foothills	209218	SNRACA13
1051172	100493219	CA	Valley	Merced Foothills	209218	SNRACA13
1051174	100493221	CA	Valley	Merced Foothills	209218	SNRACA13
1051175	100493222	CA	Valley	Merced Foothills	209218	SNRACA13
1051177	100493224	CA	Valley	Merced Foothills	209218	SNRACA13
1051179	100493828	CA	Valley	Merced Foothills	209218	SNRACA13
1051182	100493831	CA	Valley	Merced Foothills	209218	SNRACA13
1051183	100493832	CA	Valley	Merced Foothills	209218	SNRACA13
1051188	100493837	CA	Valley	Merced Foothills	209218	SNRACA13
1051191	100493840	CA	Valley	Merced Foothills	209218	SNRACA13
1051192	100493841	CA	Valley	Merced Foothills	209218	SNRACA13
1051193	100493842	CA	Valley	Merced Foothills	209218	SNRACA13
1051196	100493225	CA	Valley	Merced Foothills	209218	SNRACA13
1051199	100493228	CA	Valley	Merced Foothills	209218	SNRACA13
1051200	100493229	CA	Valley	Merced Foothills	209218	SNRACA13
1051201	100493230	CA	Valley	Merced Foothills	209218	SNRACA13
1051203	100493232	CA	Valley	Merced Foothills	209218	SNRACA13
1051210	100493240	CA	Valley	Merced Foothills	209218	SNRACA13
1051211	100493241	CA	Valley	Merced Foothills	209218	SNRACA13
1051213	100493847	CA	Valley	Merced Foothills	209218	SNRACA13

1051219	100493718	CA	Valley	Merced Foothills	209218	SNRACA13
1051231	100493245	CA	Valley	Merced Foothills	209218	SNRACA13
1051233	100493247	CA	Valley	Merced Foothills	209218	SNRACA13
1051234	100493248	CA	Valley	Merced Foothills	209218	SNRACA13
1051236	100493250	CA	Valley	Merced Foothills	209218	SNRACA13
1051237	100493251	CA	Valley	Merced Foothills	209218	SNRACA13
1051238	100493252	CA	Valley	Merced Foothills	209218	SNRACA13
1051240	100493254	CA	Valley	Merced Foothills	209218	SNRACA13
1051242	100493256	CA	Valley	Merced Foothills	209218	SNRACA13
1051245	100493259	CA	Valley	Merced Foothills	209218	SNRACA13
1051246	100493727	CA	Valley	Merced Foothills	209218	SNRACA13
1051247	100493728	CA	Valley	Merced Foothills	209218	SNRACA13
1051249	100493730	CA	Valley	Merced Foothills	209218	SNRACA13
1051251	100493732	CA	Valley	Merced Foothills	209218	SNRACA13
1051252	100493733	CA	Valley	Merced Foothills	209218	SNRACA13
1051254	100493736	CA	Valley	Merced Foothills	209218	SNRACA13
1051255	100493737	CA	Valley	Merced Foothills	209218	SNRACA13
1051257	100493739	CA	Valley	Merced Foothills	209218	SNRACA13
1051258	100493740	CA	Valley	Merced Foothills	209218	SNRACA13
1051260	100493742	CA	Valley	Merced Foothills	209218	SNRACA13
1051262	100493744	CA	Valley	Merced Foothills	209218	SNRACA13
1051265	100493923	CA	Valley	Merced Foothills	209218	SNRACA13

1051267	100493925	CA	Valley	Merced Foothills	209218	SNRACA13
1051269	100493927	CA	Valley	Merced Foothills	209218	SNRACA13
1051275	100493933	CA	Valley	Merced Foothills	209218	SNRACA13
1051284	100493264	CA	Valley	Merced Foothills	209218	SNRACA13
1051287	100493170	CA	Valley	Merced Foothills	209218	SNRACA13
1051288	100493171	CA	Valley	Merced Foothills	209218	SNRACA13
1051289	100493172	CA	Valley	Merced Foothills	209218	SNRACA13
1051293	100493176	CA	Valley	Merced Foothills	209218	SNRACA13
1051294	100493177	CA	Valley	Merced Foothills	209218	SNRACA13
1051296	100493179	CA	Valley	Merced Foothills	209218	SNRACA13
1051297	100493745	CA	Valley	Merced Foothills	209218	SNRACA13
1051301	100493749	CA	Valley	Merced Foothills	209218	SNRACA13
1051310	100493758	CA	Valley	Merced Foothills	209218	SNRACA13
1051312	100493760	CA	Valley	Merced Foothills	209218	SNRACA13
1051317	100493941	CA	Valley	Merced Foothills	209218	SNRACA13
1051320	100493944	CA	Valley	Merced Foothills	209218	SNRACA13
1051323	100493947	CA	Valley	Merced Foothills	209218	SNRACA13
1051326	100494006	CA	Valley	Merced Foothills	209218	SNRACA13
1051330	100493180	CA	Valley	Merced Foothills	209218	SNRACA13
1051332	100493182	CA	Valley	Merced Foothills	209218	SNRACA13
1051333	100493183	CA	Valley	Merced Foothills	209218	SNRACA13
1051334	100493184	CA	Valley	Merced Foothills	209218	SNRACA13

1051341	100493191	CA	Valley	Merced Foothills	209218	SNRACA13
1051342	100493192	CA	Valley	Merced Foothills	209218	SNRACA13
1051344	100493194	CA	Valley	Merced Foothills	209218	SNRACA13
1051349	100493492	CA	Valley	Merced Foothills	209218	SNRACA13
1051351	100493494	CA	Valley	Merced Foothills	209218	SNRACA13
1051352	100493495	CA	Valley	Merced Foothills	209218	SNRACA13
1051354	100493497	CA	Valley	Merced Foothills	209218	SNRACA13
1051359	100493502	CA	Valley	Merced Foothills	209218	SNRACA13
1051360	100493503	CA	Valley	Merced Foothills	209218	SNRACA13
1051361	100493504	CA	Valley	Merced Foothills	209218	SNRACA13
1051366	100493766	CA	Valley	Merced Foothills	209218	SNRACA13
1051367	100493767	CA	Valley	Merced Foothills	209218	SNRACA13
1051368	100493768	CA	Valley	Merced Foothills	209218	SNRACA13
1051369	100493769	CA	Valley	Merced Foothills	209218	SNRACA13
1051371	100493771	CA	Valley	Merced Foothills	209218	SNRACA13
1051373	100493851	CA	Valley	Merced Foothills	209218	SNRACA13
1054272	100496280	CA	Valley	Merced Foothills	209233	TWHRCA11
1054273	100496281	CA	Valley	Merced Foothills	209233	TWHRCA11
1054275	100496283	CA	Valley	Merced Foothills	209233	TWHRCA11
1054279	100496287	CA	Valley	Merced Foothills	209233	TWHRCA11
1054285	100496546	CA	Valley	Merced Foothills	209233	TWHRCA11
1054286	100496547	CA	Valley	Merced Foothills	209233	TWHRCA11

1054288	100496550	CA	Valley	Merced Foothills	209233	TWHRCA11
1054295	100496557	CA	Valley	Merced Foothills	209233	TWHRCA11
1054299	100496742	CA	Valley	Merced Foothills	209233	TWHRCA11
1054308	100496897	CA	Valley	Merced Foothills	209233	TWHRCA11
1054309	100496898	CA	Valley	Merced Foothills	209233	TWHRCA11
1054316	100497026	CA	Valley	Merced Foothills	209233	TWHRCA11
1054317	100497027	CA	Valley	Merced Foothills	209233	TWHRCA11
1054319	100497029	CA	Valley	Merced Foothills	209233	TWHRCA11
1054320	100497030	CA	Valley	Merced Foothills	209233	TWHRCA11
1054323	100497033	CA	Valley	Merced Foothills	209233	TWHRCA11
1054344	100497275	CA	Valley	Merced Foothills	209233	TWHRCA11
1054348	100496292	CA	Valley	Merced Foothills	209233	TWHRCA11
1054349	100496293	CA	Valley	Merced Foothills	209233	TWHRCA11
1054350	100496294	CA	Valley	Merced Foothills	209233	TWHRCA11
1054351	100496295	CA	Valley	Merced Foothills	209233	TWHRCA11
1054352	100496296	CA	Valley	Merced Foothills	209233	TWHRCA11
1054353	100496297	CA	Valley	Merced Foothills	209233	TWHRCA11
1054355	100496299	CA	Valley	Merced Foothills	209233	TWHRCA11
1054356	100496300	CA	Valley	Merced Foothills	209233	TWHRCA11
1054361	100496305	CA	Valley	Merced Foothills	209233	TWHRCA11
1054369	100496565	CA	Valley	Merced Foothills	209233	TWHRCA11

1054377	100496573	CA	Valley	Merced Foothills	209233	TWHRCA11
1054378	100496574	CA	Valley	Merced Foothills	209233	TWHRCA11
1054389	100496912	CA	Valley	Merced Foothills	209233	TWHRCA11
1054390	100496913	CA	Valley	Merced Foothills	209233	TWHRCA11
1054392	100496915	CA	Valley	Merced Foothills	209233	TWHRCA11
1054396	100497166	CA	Valley	Merced Foothills	209233	TWHRCA11
1054401	100497171	CA	Valley	Merced Foothills	209233	TWHRCA11
1054403	100497173	CA	Valley	Merced Foothills	209233	TWHRCA11
1054404	100497174	CA	Valley	Merced Foothills	209233	TWHRCA11
1054407	100497177	CA	Valley	Merced Foothills	209233	TWHRCA11
1054421	100497286	CA	Valley	Merced Foothills	209233	TWHRCA11
1054429	100496309	CA	Valley	Merced Foothills	209233	TWHRCA11
1054444	100496577	CA	Valley	Merced Foothills	209233	TWHRCA11
1054445	100496578	CA	Valley	Merced Foothills	209233	TWHRCA11
1054448	100496581	CA	Valley	Merced Foothills	209233	TWHRCA11
1054451	100496584	CA	Valley	Merced Foothills	209233	TWHRCA11
1054453	100496586	CA	Valley	Merced Foothills	209233	TWHRCA11
1054454	100496587	CA	Valley	Merced Foothills	209233	TWHRCA11
1054459	100496918	CA	Valley	Merced Foothills	209233	TWHRCA11
1054460	100496919	CA	Valley	Merced Foothills	209233	TWHRCA11
1054462	100496921	CA	Valley	Merced Foothills	209233	TWHRCA11
1054464	100496923	CA	Valley	Merced Foothills	209233	TWHRCA11

1054465	100496924	CA	Valley	Merced Foothills	209233	TWHRCA11
1054468	100496927	CA	Valley	Merced Foothills	209233	TWHRCA11
1054469	100496799	CA	Valley	Merced Foothills	209233	TWHRCA11
1054470	100496800	CA	Valley	Merced Foothills	209233	TWHRCA11
1054472	100496802	CA	Valley	Merced Foothills	209233	TWHRCA11
1054475	100496805	CA	Valley	Merced Foothills	209233	TWHRCA11
1054476	100496806	CA	Valley	Merced Foothills	209233	TWHRCA11
1054494	100497293	CA	Valley	Merced Foothills	209233	TWHRCA11
1054495	100497294	CA	Valley	Merced Foothills	209233	TWHRCA11
1054497	100497296	CA	Valley	Merced Foothills	209233	TWHRCA11
1054505	100497341	CA	Valley	Merced Foothills	209233	TWHRCA11
1054506	100497342	CA	Valley	Merced Foothills	209233	TWHRCA11
1054508	100497344	CA	Valley	Merced Foothills	209233	TWHRCA11
1054512	100496325	CA	Valley	Merced Foothills	209233	TWHRCA11
1054523	100496466	CA	Valley	Merced Foothills	209233	TWHRCA11
1054524	100496467	CA	Valley	Merced Foothills	209233	TWHRCA11
1054542	100496807	CA	Valley	Merced Foothills	209233	TWHRCA11
1054545	100496810	CA	Valley	Merced Foothills	209233	TWHRCA11
1054552	100496817	CA	Valley	Merced Foothills	209233	TWHRCA11
1054555	100496820	CA	Valley	Merced Foothills	209233	TWHRCA11
1054557	100496822	CA	Valley	Merced Foothills	209233	TWHRCA11
1054559	100497197	CA	Valley	Merced Foothills	209233	TWHRCA11

1054570	100497208	CA	Valley	Merced Foothills	209233	TWHRCA11
1054580	100497351	CA	Valley	Merced Foothills	209233	TWHRCA11
1054581	100497352	CA	Valley	Merced Foothills	209233	TWHRCA11
1054591	100496477	CA	Valley	Merced Foothills	209233	TWHRCA11
1054595	100496481	CA	Valley	Merced Foothills	209233	TWHRCA11
1054597	100496483	CA	Valley	Merced Foothills	209233	TWHRCA11
1054599	100496485	CA	Valley	Merced Foothills	209233	TWHRCA11
1054603	100496611	CA	Valley	Merced Foothills	209233	TWHRCA11
1054615	100496756	CA	Valley	Merced Foothills	209233	TWHRCA11
1054620	100496826	CA	Valley	Merced Foothills	209233	TWHRCA11
1054626	100496832	CA	Valley	Merced Foothills	209233	TWHRCA11
1054627	100496833	CA	Valley	Merced Foothills	209233	TWHRCA11
1054630	100496836	CA	Valley	Merced Foothills	209233	TWHRCA11
1054631	100496837	CA	Valley	Merced Foothills	209233	TWHRCA11
1054633	100496839	CA	Valley	Merced Foothills	209233	TWHRCA11
1054635	100497070	CA	Valley	Merced Foothills	209233	TWHRCA11
1054636	100497071	CA	Valley	Merced Foothills	209233	TWHRCA11
1054637	100497072	CA	Valley	Merced Foothills	209233	TWHRCA11
1054639	100497074	CA	Valley	Merced Foothills	209233	TWHRCA11
1054648	100497083	CA	Valley	Merced Foothills	209233	TWHRCA11
1054651	100496486	CA	Valley	Merced Foothills	209233	TWHRCA11
1054660	100496497	CA	Valley	Merced Foothills	209233	TWHRCA11

1054667	100496759	CA	Valley	Merced Foothills	209233	TWHRCA11
1054683	100496842	CA	Valley	Merced Foothills	209233	TWHRCA11
1054695	100496854	CA	Valley	Merced Foothills	209233	TWHRCA11
1054699	100497087	CA	Valley	Merced Foothills	209233	TWHRCA11
1054700	100497088	CA	Valley	Merced Foothills	209233	TWHRCA11
1054701	100497089	CA	Valley	Merced Foothills	209233	TWHRCA11
1054703	100497091	CA	Valley	Merced Foothills	209233	TWHRCA11
1054710	100497099	CA	Valley	Merced Foothills	209233	TWHRCA11
1054712	100497101	CA	Valley	Merced Foothills	209233	TWHRCA11
1054713	100497102	CA	Valley	Merced Foothills	209233	TWHRCA11
1054724	100496514	CA	Valley	Merced Foothills	209233	TWHRCA11
1054727	100496517	CA	Valley	Merced Foothills	209233	TWHRCA11
1054733	100496777	CA	Valley	Merced Foothills	209233	TWHRCA11
1054740	100496784	CA	Valley	Merced Foothills	209233	TWHRCA11
1054743	100496787	CA	Valley	Merced Foothills	209233	TWHRCA11
1054748	100496861	CA	Valley	Merced Foothills	209233	TWHRCA11
1054762	100497104	CA	Valley	Merced Foothills	209233	TWHRCA11
1054764	100497106	CA	Valley	Merced Foothills	209233	TWHRCA11
1054768	100497110	CA	Valley	Merced Foothills	209233	TWHRCA11
1054769	100497111	CA	Valley	Merced Foothills	209233	TWHRCA11
1054770	100497112	CA	Valley	Merced Foothills	209233	TWHRCA11
1054771	100497113	CA	Valley	Merced Foothills	209233	TWHRCA11

1054776	100497118	CA	Valley	Merced Foothills	209233	TWHRCA11
1054780	100496374	CA	Valley	Merced Foothills	209233	TWHRCA11
1054784	100496378	CA	Valley	Merced Foothills	209233	TWHRCA11
1054787	100496381	CA	Valley	Merced Foothills	209233	TWHRCA11
1054791	100496385	CA	Valley	Merced Foothills	209233	TWHRCA11
1054794	100496874	CA	Valley	Merced Foothills	209233	TWHRCA11
1054796	100496876	CA	Valley	Merced Foothills	209233	TWHRCA11
1054801	100496881	CA	Valley	Merced Foothills	209233	TWHRCA11
1054803	100496883	CA	Valley	Merced Foothills	209233	TWHRCA11
1054804	100496884	CA	Valley	Merced Foothills	209233	TWHRCA11
1054811	100497119	CA	Valley	Merced Foothills	209233	TWHRCA11
1054812	100497120	CA	Valley	Merced Foothills	209233	TWHRCA11
1054816	100497124	CA	Valley	Merced Foothills	209233	TWHRCA11
1054817	100497125	CA	Valley	Merced Foothills	209233	TWHRCA11
1054819	100497127	CA	Valley	Merced Foothills	209233	TWHRCA11
1054821	100497129	CA	Valley	Merced Foothills	209233	TWHRCA11
1054825	100497133	CA	Valley	Merced Foothills	209233	TWHRCA11
1054827	100497135	CA	Valley	Merced Foothills	209233	TWHRCA11
1054831	100496391	CA	Valley	Merced Foothills	209233	TWHRCA11
1054834	100496394	CA	Valley	Merced Foothills	209233	TWHRCA11
1054844	100496404	CA	Valley	Merced Foothills	209233	TWHRCA11
1054851	100496933	CA	Valley	Merced Foothills	209233	TWHRCA11

1054868	100496412	CA	Valley	Merced Foothills	209233	TWHRCA11
1054870	100496415	CA	Valley	Merced Foothills	209233	TWHRCA11
1054873	100496418	CA	Valley	Merced Foothills	209233	TWHRCA11
1054875	100496420	CA	Valley	Merced Foothills	209233	TWHRCA11
1054876	100496421	CA	Valley	Merced Foothills	209233	TWHRCA11
1054883	100496949	CA	Valley	Merced Foothills	209233	TWHRCA11
1054884	100496950	CA	Valley	Merced Foothills	209233	TWHRCA11
1054893	100497136	CA	Valley	Merced Foothills	209233	TWHRCA11
1054894	100497137	CA	Valley	Merced Foothills	209233	TWHRCA11
1054899	100497142	CA	Valley	Merced Foothills	209233	TWHRCA11
1054910	100496431	CA	Valley	Merced Foothills	209233	TWHRCA11
1054928	100496654	CA	Valley	Merced Foothills	209233	TWHRCA11
1054939	100496969	CA	Valley	Merced Foothills	209233	TWHRCA11
1054944	100496974	CA	Valley	Merced Foothills	209233	TWHRCA11
1054948	100497148	CA	Valley	Merced Foothills	209233	TWHRCA11
1054965	100496442	CA	Valley	Merced Foothills	209233	TWHRCA11
1054969	100496446	CA	Valley	Merced Foothills	209233	TWHRCA11
1054977	100496655	CA	Valley	Merced Foothills	209233	TWHRCA11
1054979	100496657	CA	Valley	Merced Foothills	209233	TWHRCA11
1054980	100496658	CA	Valley	Merced Foothills	209233	TWHRCA11
1054982	100496660	CA	Valley	Merced Foothills	209233	TWHRCA11
1054983	100496661	CA	Valley	Merced Foothills	209233	TWHRCA11

1054984	100496662	CA	Valley	Merced Foothills	209233	TWHRCA11
1054986	100496664	CA	Valley	Merced Foothills	209233	TWHRCA11
1054987	100496665	CA	Valley	Merced Foothills	209233	TWHRCA11
1054988	100496666	CA	Valley	Merced Foothills	209233	TWHRCA11
1054989	100496667	CA	Valley	Merced Foothills	209233	TWHRCA11
1054990	100496668	CA	Valley	Merced Foothills	209233	TWHRCA11
1054991	100496669	CA	Valley	Merced Foothills	209233	TWHRCA11
1054996	100496975	CA	Valley	Merced Foothills	209233	TWHRCA11
1055003	100497038	CA	Valley	Merced Foothills	209233	TWHRCA11
1055004	100497039	CA	Valley	Merced Foothills	209233	TWHRCA11
1055007	100497042	CA	Valley	Merced Foothills	209233	TWHRCA11
1055008	100497043	CA	Valley	Merced Foothills	209233	TWHRCA11
1055010	100497045	CA	Valley	Merced Foothills	209233	TWHRCA11
1055039	100496614	CA	Valley	Merced Foothills	209233	TWHRCA11
1055041	100496616	CA	Valley	Merced Foothills	209233	TWHRCA11
1055044	100496619	CA	Valley	Merced Foothills	209233	TWHRCA11
1055045	100496620	CA	Valley	Merced Foothills	209233	TWHRCA11
1055046	100496674	CA	Valley	Merced Foothills	209233	TWHRCA11
1055048	100496676	CA	Valley	Merced Foothills	209233	TWHRCA11
1055049	100496677	CA	Valley	Merced Foothills	209233	TWHRCA11
1055050	100496678	CA	Valley	Merced Foothills	209233	TWHRCA11
1055052	100496680	CA	Valley	Merced Foothills	209233	TWHRCA11

1055054	100496682	CA	Valley	Merced Foothills	209233	TWHRCA11
1055068	100497053	CA	Valley	Merced Foothills	209233	TWHRCA11
1055078	100497063	CA	Valley	Merced Foothills	209233	TWHRCA11
1055081	100497320	CA	Valley	Merced Foothills	209233	TWHRCA11
1055082	100497321	CA	Valley	Merced Foothills	209233	TWHRCA11
1055083	100497322	CA	Valley	Merced Foothills	209233	TWHRCA11
1055085	100497324	CA	Valley	Merced Foothills	209233	TWHRCA11
1055089	100497328	CA	Valley	Merced Foothills	209233	TWHRCA11
1055095	100497334	CA	Valley	Merced Foothills	209233	TWHRCA11
1055096	100496621	CA	Valley	Merced Foothills	209233	TWHRCA11
1055098	100496623	CA	Valley	Merced Foothills	209233	TWHRCA11
1055099	100496624	CA	Valley	Merced Foothills	209233	TWHRCA11
1055101	100496626	CA	Valley	Merced Foothills	209233	TWHRCA11
1055102	100496627	CA	Valley	Merced Foothills	209233	TWHRCA11
1055103	100496628	CA	Valley	Merced Foothills	209233	TWHRCA11
1055105	100496630	CA	Valley	Merced Foothills	209233	TWHRCA11
1055106	100496631	CA	Valley	Merced Foothills	209233	TWHRCA11
1055109	100496634	CA	Valley	Merced Foothills	209233	TWHRCA11
1055112	100496637	CA	Valley	Merced Foothills	209233	TWHRCA11
1055114	100496639	CA	Valley	Merced Foothills	209233	TWHRCA11
1055123	100496699	CA	Valley	Merced Foothills	209233	TWHRCA11
1055130	100496706	CA	Valley	Merced Foothills	209233	TWHRCA11

1055131	100497064	CA	Valley	Merced Foothills	209233	TWHRCA11
1055136	100496978	CA	Valley	Merced Foothills	209233	TWHRCA11
1055140	100496982	CA	Valley	Merced Foothills	209233	TWHRCA11
1055142	100496984	CA	Valley	Merced Foothills	209233	TWHRCA11
1055144	100496986	CA	Valley	Merced Foothills	209233	TWHRCA11
1055162	100497224	CA	Valley	Merced Foothills	209233	TWHRCA11
1055165	100496335	CA	Valley	Merced Foothills	209233	TWHRCA11
1055167	100496337	CA	Valley	Merced Foothills	209233	TWHRCA11
1055171	100496341	CA	Valley	Merced Foothills	209233	TWHRCA11
1055172	100496342	CA	Valley	Merced Foothills	209233	TWHRCA11
1055177	100496347	CA	Valley	Merced Foothills	209233	TWHRCA11
1055180	100496641	CA	Valley	Merced Foothills	209233	TWHRCA11
1055186	100496647	CA	Valley	Merced Foothills	209233	TWHRCA11
1055187	100496648	CA	Valley	Merced Foothills	209233	TWHRCA11
1055188	100496649	CA	Valley	Merced Foothills	209233	TWHRCA11
1055191	100496652	CA	Valley	Merced Foothills	209233	TWHRCA11
1055193	100496521	CA	Valley	Merced Foothills	209233	TWHRCA11
1055200	100496710	CA	Valley	Merced Foothills	209233	TWHRCA11
1055208	100496718	CA	Valley	Merced Foothills	209233	TWHRCA11
1055218	100496995	CA	Valley	Merced Foothills	209233	TWHRCA11
1055222	100496999	CA	Valley	Merced Foothills	209233	TWHRCA11

1055225	100497002	CA	Valley	Merced Foothills	209233	TWHRCA11
1055226	100497003	CA	Valley	Merced Foothills	209233	TWHRCA11
1055228	100497005	CA	Valley	Merced Foothills	209233	TWHRCA11
1055233	100497230	CA	Valley	Merced Foothills	209233	TWHRCA11
1055238	100497235	CA	Valley	Merced Foothills	209233	TWHRCA11
1055239	100497236	CA	Valley	Merced Foothills	209233	TWHRCA11
1055241	100497238	CA	Valley	Merced Foothills	209233	TWHRCA11
1055243	100497240	CA	Valley	Merced Foothills	209233	TWHRCA11
1055245	100497242	CA	Valley	Merced Foothills	209233	TWHRCA11
1055254	100496357	CA	Valley	Merced Foothills	209233	TWHRCA11
1055271	100496534	CA	Valley	Merced Foothills	209233	TWHRCA11
1055277	100496540	CA	Valley	Merced Foothills	209233	TWHRCA11
1055280	100496723	CA	Valley	Merced Foothills	209233	TWHRCA11
1055282	100496725	CA	Valley	Merced Foothills	209233	TWHRCA11
1055285	100496728	CA	Valley	Merced Foothills	209233	TWHRCA11
1055294	100496737	CA	Valley	Merced Foothills	209233	TWHRCA11
1055297	100497007	CA	Valley	Merced Foothills	209233	TWHRCA11
1055299	100497009	CA	Valley	Merced Foothills	209233	TWHRCA11
1055303	100497013	CA	Valley	Merced Foothills	209233	TWHRCA11
1055309	100497019	CA	Valley	Merced Foothills	209233	TWHRCA11
1055310	100497020	CA	Valley	Merced Foothills	209233	TWHRCA11
1055311	100497021	CA	Valley	Merced Foothills	209233	TWHRCA11

1055316	100497246	CA	Valley	Merced Foothills	209233	TWHRCA11
1055317	100497247	CA	Valley	Merced Foothills	209233	TWHRCA11
1055318	100497248	CA	Valley	Merced Foothills	209233	TWHRCA11
1055320	100497250	CA	Valley	Merced Foothills	209233	TWHRCA11
1055322	100497252	CA	Valley	Merced Foothills	209233	TWHRCA11
1055326	100497256	CA	Valley	Merced Foothills	209233	TWHRCA11
1055329	100497259	CA	Valley	Merced Foothills	209233	TWHRCA11
1095568	100532822	CA	Valley	Merced Foothills	209233	TWHRCA11
1101693	100538292	CA	Valley	Merced Foothills	209218	SNRACA13
1101695	100538294	CA	Valley	Merced Foothills	209218	SNRACA13
1101698	100538297	CA	Valley	Merced Foothills	209218	SNRACA13
1101702	100538301	CA	Valley	Merced Foothills	209218	SNRACA13
1101712	100538284	CA	Valley	Merced Foothills	209218	SNRACA13
1101713	100538285	CA	Valley	Merced Foothills	209218	SNRACA13
1101720	100538411	CA	Valley	Merced Foothills	209218	SNRACA13
1101721	100538412	CA	Valley	Merced Foothills	209218	SNRACA13
1101723	100538414	CA	Valley	Merced Foothills	209218	SNRACA13
1101724	100538415	CA	Valley	Merced Foothills	209218	SNRACA13
1101725	100538416	CA	Valley	Merced Foothills	209218	SNRACA13
1101726	100538417	CA	Valley	Merced Foothills	209218	SNRACA13
1101728	100538419	CA	Valley	Merced Foothills	209218	SNRACA13
1101734	100538465	CA	Valley	Merced Foothills	209218	SNRACA13

1101735	100538466	CA	Valley	Merced Foothills	209218	SNRACA13
1101740	100538634	CA	Valley	Merced Foothills	209218	SNRACA13
1101747	100538641	CA	Valley	Merced Foothills	209218	SNRACA13
1101748	100538642	CA	Valley	Merced Foothills	209218	SNRACA13
1101749	100538643	CA	Valley	Merced Foothills	209218	SNRACA13
1101764	100538478	CA	Valley	Merced Foothills	209218	SNRACA13
1101775	100538653	CA	Valley	Merced Foothills	209218	SNRACA13
1101777	100538655	CA	Valley	Merced Foothills	209218	SNRACA13
1101778	100538656	CA	Valley	Merced Foothills	209218	SNRACA13
1101786	100538857	CA	Valley	Merced Foothills	209218	SNRACA13
1101791	100538489	CA	Valley	Merced Foothills	209218	SNRACA13
1101795	100538493	CA	Valley	Merced Foothills	209218	SNRACA13
1101802	100538500	CA	Valley	Merced Foothills	209218	SNRACA13
1101813	100538866	CA	Valley	Merced Foothills	209218	SNRACA13
1101819	100538872	CA	Valley	Merced Foothills	209218	SNRACA13
1101821	100538874	CA	Valley	Merced Foothills	209218	SNRACA13
1101822	100538504	CA	Valley	Merced Foothills	209218	SNRACA13
1101829	100538550	CA	Valley	Merced Foothills	209218	SNRACA13
1101830	100538551	CA	Valley	Merced Foothills	209218	SNRACA13
1101833	100538554	CA	Valley	Merced Foothills	209218	SNRACA13
1101838	100538559	CA	Valley	Merced Foothills	209218	SNRACA13
1101852	100538887	CA	Valley	Merced Foothills	209218	SNRACA13

1101854	100538889	CA	Valley	Merced Foothills	209218	SNRACA13
1101859	100538563	CA	Valley	Merced Foothills	209218	SNRACA13
1101860	100538564	CA	Valley	Merced Foothills	209218	SNRACA13
1101863	100538567	CA	Valley	Merced Foothills	209218	SNRACA13
1101865	100538588	CA	Valley	Merced Foothills	209218	SNRACA13
1101867	100538590	CA	Valley	Merced Foothills	209218	SNRACA13
1101868	100538591	CA	Valley	Merced Foothills	209218	SNRACA13
1101871	100538760	CA	Valley	Merced Foothills	209218	SNRACA13
1101876	100538765	CA	Valley	Merced Foothills	209218	SNRACA13
1101877	100538766	CA	Valley	Merced Foothills	209218	SNRACA13
1101879	100538768	CA	Valley	Merced Foothills	209218	SNRACA13
1101882	100538771	CA	Valley	Merced Foothills	209218	SNRACA13
1101883	100538772	CA	Valley	Merced Foothills	209218	SNRACA13
1101885	100538774	CA	Valley	Merced Foothills	209218	SNRACA13
1101886	100538775	CA	Valley	Merced Foothills	209218	SNRACA13
1101888	100538777	CA	Valley	Merced Foothills	209218	SNRACA13
1101893	100538600	CA	Valley	Merced Foothills	209218	SNRACA13
1101894	100538601	CA	Valley	Merced Foothills	209218	SNRACA13
1101895	100538602	CA	Valley	Merced Foothills	209218	SNRACA13
1101899	100538569	CA	Valley	Merced Foothills	209218	SNRACA13
1101908	100538779	CA	Valley	Merced Foothills	209218	SNRACA13
1101911	100538782	CA	Valley	Merced Foothills	209218	SNRACA13

1101915	100538786	CA	Valley	Merced Foothills	209218	SNRACA13
1101920	100538791	CA	Valley	Merced Foothills	209218	SNRACA13
1101926	100538579	CA	Valley	Merced Foothills	209218	SNRACA13
1101938	100538514	CA	Valley	Merced Foothills	209218	SNRACA13
1101940	100538795	CA	Valley	Merced Foothills	209218	SNRACA13
1101946	100538801	CA	Valley	Merced Foothills	209218	SNRACA13
1101949	100538804	CA	Valley	Merced Foothills	209218	SNRACA13
1101956	100538811	CA	Valley	Merced Foothills	209218	SNRACA13
1101957	100538421	CA	Valley	Merced Foothills	209218	SNRACA13
1101958	100538422	CA	Valley	Merced Foothills	209218	SNRACA13
1101959	100538423	CA	Valley	Merced Foothills	209218	SNRACA13
1101961	100538425	CA	Valley	Merced Foothills	209218	SNRACA13
1101965	100538518	CA	Valley	Merced Foothills	209218	SNRACA13
1101970	100538523	CA	Valley	Merced Foothills	209218	SNRACA13
1101976	100538529	CA	Valley	Merced Foothills	209218	SNRACA13
1101978	100538531	CA	Valley	Merced Foothills	209218	SNRACA13
1101980	100538533	CA	Valley	Merced Foothills	209218	SNRACA13
1101982	100538813	CA	Valley	Merced Foothills	209218	SNRACA13
1101989	100538820	CA	Valley	Merced Foothills	209218	SNRACA13
1102000	100538429	CA	Valley	Merced Foothills	209218	SNRACA13
1102002	100538431	CA	Valley	Merced Foothills	209218	SNRACA13
1102004	100538433	CA	Valley	Merced Foothills	209218	SNRACA13

1102008	100538437	CA	Valley	Merced Foothills	209218	SNRACA13
1102009	100538438	CA	Valley	Merced Foothills	209218	SNRACA13
1102010	100538439	CA	Valley	Merced Foothills	209218	SNRACA13
1102014	100538443	CA	Valley	Merced Foothills	209218	SNRACA13
1102021	100538540	CA	Valley	Merced Foothills	209218	SNRACA13
1102023	100538542	CA	Valley	Merced Foothills	209218	SNRACA13
1102031	100538664	CA	Valley	Merced Foothills	209218	SNRACA13
1102032	100538665	CA	Valley	Merced Foothills	209218	SNRACA13
1102036	100538832	CA	Valley	Merced Foothills	209218	SNRACA13
1102038	100538834	CA	Valley	Merced Foothills	209218	SNRACA13
1102046	100538842	CA	Valley	Merced Foothills	209218	SNRACA13
1102048	100538844	CA	Valley	Merced Foothills	209218	SNRACA13
1102049	100538845	CA	Valley	Merced Foothills	209218	SNRACA13
1102053	100538446	CA	Valley	Merced Foothills	209218	SNRACA13
1102054	100538447	CA	Valley	Merced Foothills	209218	SNRACA13
1102055	100538448	CA	Valley	Merced Foothills	209218	SNRACA13
1102060	100538453	CA	Valley	Merced Foothills	209218	SNRACA13
1102062	100538455	CA	Valley	Merced Foothills	209218	SNRACA13
1102066	100538459	CA	Valley	Merced Foothills	209218	SNRACA13
1102067	100538460	CA	Valley	Merced Foothills	209218	SNRACA13
1102075	100538672	CA	Valley	Merced Foothills	209218	SNRACA13
1102078	100538675	CA	Valley	Merced Foothills	209218	SNRACA13

1102082	100538680	CA	Valley	Merced Foothills	209218	SNRACA13
1102083	100538681	CA	Valley	Merced Foothills	209218	SNRACA13
1102087	100538849	CA	Valley	Merced Foothills	209218	SNRACA13
1102091	100538853	CA	Valley	Merced Foothills	209218	SNRACA13
1102093	100538891	CA	Valley	Merced Foothills	209218	SNRACA13
1102094	100538892	CA	Valley	Merced Foothills	209218	SNRACA13
1102095	100538893	CA	Valley	Merced Foothills	209218	SNRACA13
1102096	100538894	CA	Valley	Merced Foothills	209218	SNRACA13
1102102	100538900	CA	Valley	Merced Foothills	209218	SNRACA13
1102105	100538313	CA	Valley	Merced Foothills	209218	SNRACA13
1102107	100538315	CA	Valley	Merced Foothills	209218	SNRACA13
1102110	100538318	CA	Valley	Merced Foothills	209218	SNRACA13
1102115	100538324	CA	Valley	Merced Foothills	209218	SNRACA13
1102117	100538326	CA	Valley	Merced Foothills	209218	SNRACA13
1102122	100538687	CA	Valley	Merced Foothills	209218	SNRACA13
1102123	100538688	CA	Valley	Merced Foothills	209218	SNRACA13
1102130	100538695	CA	Valley	Merced Foothills	209218	SNRACA13
1102132	100538697	CA	Valley	Merced Foothills	209218	SNRACA13
1102137	100538903	CA	Valley	Merced Foothills	209218	SNRACA13
1102140	100538906	CA	Valley	Merced Foothills	209218	SNRACA13
1102143	100538909	CA	Valley	Merced Foothills	209218	SNRACA13
1102144	100538910	CA	Valley	Merced Foothills	209218	SNRACA13

1102149	100538915	CA	Valley	Merced Foothills	209218	SNRACA13
1102152	100538328	CA	Valley	Merced Foothills	209218	SNRACA13
1102153	100538329	CA	Valley	Merced Foothills	209218	SNRACA13
1102156	100538332	CA	Valley	Merced Foothills	209218	SNRACA13
1102158	100538334	CA	Valley	Merced Foothills	209218	SNRACA13
1102159	100538335	CA	Valley	Merced Foothills	209218	SNRACA13
1102164	100538340	CA	Valley	Merced Foothills	209218	SNRACA13
1102165	100538341	CA	Valley	Merced Foothills	209218	SNRACA13
1102167	100538343	CA	Valley	Merced Foothills	209218	SNRACA13
1102172	100538743	CA	Valley	Merced Foothills	209218	SNRACA13
1102176	100538747	CA	Valley	Merced Foothills	209218	SNRACA13
1102178	100538749	CA	Valley	Merced Foothills	209218	SNRACA13
1102180	100538751	CA	Valley	Merced Foothills	209218	SNRACA13
1102183	100538754	CA	Valley	Merced Foothills	209218	SNRACA13
1102185	100538918	CA	Valley	Merced Foothills	209218	SNRACA13
1102189	100538922	CA	Valley	Merced Foothills	209218	SNRACA13
1102191	100538924	CA	Valley	Merced Foothills	209218	SNRACA13
1102192	100538925	CA	Valley	Merced Foothills	209218	SNRACA13
1102193	100538926	CA	Valley	Merced Foothills	209218	SNRACA13
1102195	100538928	CA	Valley	Merced Foothills	209218	SNRACA13
1102197	100538930	CA	Valley	Merced Foothills	209218	SNRACA13
1102202	100538935	CA	Valley	Merced Foothills	209218	SNRACA13

1102203	100538344	CA	Valley	Merced Foothills	209218	SNRACA13
1102204	100538345	CA	Valley	Merced Foothills	209218	SNRACA13
1102210	100538352	CA	Valley	Merced Foothills	209218	SNRACA13
1102211	100538353	CA	Valley	Merced Foothills	209218	SNRACA13
1102212	100538354	CA	Valley	Merced Foothills	209218	SNRACA13
1102213	100538355	CA	Valley	Merced Foothills	209218	SNRACA13
1102215	100538357	CA	Valley	Merced Foothills	209218	SNRACA13
1102216	100538358	CA	Valley	Merced Foothills	209218	SNRACA13
1102217	100538359	CA	Valley	Merced Foothills	209218	SNRACA13
1102219	100538756	CA	Valley	Merced Foothills	209218	SNRACA13
1102220	100538757	CA	Valley	Merced Foothills	209218	SNRACA13
1102222	100538701	CA	Valley	Merced Foothills	209218	SNRACA13
1102223	100538702	CA	Valley	Merced Foothills	209218	SNRACA13
1102225	100538704	CA	Valley	Merced Foothills	209218	SNRACA13
1102227	100538706	CA	Valley	Merced Foothills	209218	SNRACA13
1102228	100538707	CA	Valley	Merced Foothills	209218	SNRACA13
1102230	100538709	CA	Valley	Merced Foothills	209218	SNRACA13
1102234	100538713	CA	Valley	Merced Foothills	209218	SNRACA13
1102238	100538938	CA	Valley	Merced Foothills	209218	SNRACA13
1102239	100538939	CA	Valley	Merced Foothills	209218	SNRACA13
1102240	100538940	CA	Valley	Merced Foothills	209218	SNRACA13
1102242	100538942	CA	Valley	Merced Foothills	209218	SNRACA13

1102244	100538362	CA	Valley	Merced Foothills	209218	SNRACA13
1102245	100538363	CA	Valley	Merced Foothills	209218	SNRACA13
1102247	100538365	CA	Valley	Merced Foothills	209218	SNRACA13
1102249	100538367	CA	Valley	Merced Foothills	209218	SNRACA13
1102251	100538369	CA	Valley	Merced Foothills	209218	SNRACA13
1102255	100538373	CA	Valley	Merced Foothills	209218	SNRACA13
1102260	100538716	CA	Valley	Merced Foothills	209218	SNRACA13
1102261	100538717	CA	Valley	Merced Foothills	209218	SNRACA13
1102262	100538718	CA	Valley	Merced Foothills	209218	SNRACA13
1102265	100538721	CA	Valley	Merced Foothills	209218	SNRACA13
1102269	100538725	CA	Valley	Merced Foothills	209218	SNRACA13
1102271	100538727	CA	Valley	Merced Foothills	209218	SNRACA13
1102274	100538730	CA	Valley	Merced Foothills	209218	SNRACA13
1102280	100538380	CA	Valley	Merced Foothills	209218	SNRACA13
1102281	100538381	CA	Valley	Merced Foothills	209218	SNRACA13
1102288	100538388	CA	Valley	Merced Foothills	209218	SNRACA13
1102289	100538389	CA	Valley	Merced Foothills	209218	SNRACA13
1102290	100538390	CA	Valley	Merced Foothills	209218	SNRACA13
1102294	100538733	CA	Valley	Merced Foothills	209218	SNRACA13
1102297	100538736	CA	Valley	Merced Foothills	209218	SNRACA13
1102301	100538605	CA	Valley	Merced Foothills	209218	SNRACA13
1102302	100538606	CA	Valley	Merced Foothills	209218	SNRACA13

1102304	100538608	CA	Valley	Merced Foothills	209218	SNRACA13
1102306	100538610	CA	Valley	Merced Foothills	209218	SNRACA13
1102308	100538612	CA	Valley	Merced Foothills	209218	SNRACA13
1102314	100538397	CA	Valley	Merced Foothills	209218	SNRACA13
1102320	100538404	CA	Valley	Merced Foothills	209218	SNRACA13
1102321	100538405	CA	Valley	Merced Foothills	209218	SNRACA13
1102324	100538408	CA	Valley	Merced Foothills	209218	SNRACA13
1102327	100538615	CA	Valley	Merced Foothills	209218	SNRACA13
1102328	100538617	CA	Valley	Merced Foothills	209218	SNRACA13
1102329	100538618	CA	Valley	Merced Foothills	209218	SNRACA13
1102334	100538623	CA	Valley	Merced Foothills	209218	SNRACA13
1102336	100538625	CA	Valley	Merced Foothills	209218	SNRACA13
1102338	100538627	CA	Valley	Merced Foothills	209218	SNRACA13
1102342	100538631	CA	Valley	Merced Foothills	209218	SNRACA13
1126198	100555068	CA	Valley	Merced Foothills	209218	SNRACA13
1135915	100563239	CA	Valley	Merced Foothills	209218	SNRACA13
1135916	100563225	CA	Valley	Merced Foothills	209209	PNCRCA11
1135917	100563221	CA	Valley	Merced Foothills	209209	PNCRCA11
1135918	100563219	CA	Valley	Merced Foothills	209209	PNCRCA11
1135919	100563217	CA	Valley	Merced Foothills	209209	PNCRCA11
1135920	100563215	CA	Valley	Merced Foothills	209209	PNCRCA11
1135921	100563214	CA	Valley	Merced Foothills	209209	PNCRCA11

1135922	100563212	CA	Valley	Merced Foothills	209209	PNCRCA11
1135923	100563211	CA	Valley	Merced Foothills	209209	PNCRCA11
1135924	100563332	CA	Valley	Merced Foothills	209233	TWHRCA11
1135925	100563331	CA	Valley	Merced Foothills	209233	TWHRCA11
1135926	100563317	CA	Valley	Merced Foothills	209233	TWHRCA11
1135927	100563316	CA	Valley	Merced Foothills	209233	TWHRCA11
1135928	100563315	CA	Valley	Merced Foothills	209233	TWHRCA11
1135929	100563313	CA	Valley	Merced Foothills	209233	TWHRCA11
1135930	100563312	CA	Valley	Merced Foothills	209233	TWHRCA11
1135931	100563308	CA	Valley	Merced Foothills	209233	TWHRCA11
1135932	100563301	CA	Valley	Merced Foothills	209233	TWHRCA11
1135933	100563300	CA	Valley	Merced Foothills	209233	TWHRCA11
1135934	100563346	CA	Valley	Merced Foothills	209233	TWHRCA11
1135935	100563345	CA	Valley	Merced Foothills	209233	TWHRCA11
1135936	100563343	CA	Valley	Merced Foothills	209233	TWHRCA11
1135937	100563340	CA	Valley	Merced Foothills	209233	TWHRCA11
1135938	100563274	CA	Valley	Merced Foothills	209218	SNRACA13
1135939	100563190	CA	Valley	Merced Foothills	209173	GVLDCA11
1135940	100563188	CA	Valley	Merced Foothills	209173	GVLDCA11
1135941	100563182	CA	Valley	Merced Foothills	209173	GVLDCA11
1135942	100563175	CA	Valley	Merced Foothills	209173	GVLDCA11
1135943	100563173	CA	Valley	Merced Foothills	209173	GVLDCA11

1135944	100563203	CA	Valley	Merced Foothills	209173	GVLDCA11
1135949	100563241	CA	Valley	Merced Foothills	209218	SNRACA13
1135950	100563237	CA	Valley	Merced Foothills	209218	SNRACA13
1135951	100563236	CA	Valley	Merced Foothills	209218	SNRACA13
1135952	100563233	CA	Valley	Merced Foothills	209218	SNRACA13
1135953	100563231	CA	Valley	Merced Foothills	209218	SNRACA13
1135954	100563229	CA	Valley	Merced Foothills	209218	SNRACA13
1135955	100563227	CA	Valley	Merced Foothills	209218	SNRACA13
1135956	100563293	CA	Valley	Merced Foothills	209218	SNRACA13
1135957	100563277	CA	Valley	Merced Foothills	209218	SNRACA13
1135958	100563275	CA	Valley	Merced Foothills	209218	SNRACA13
1135959	100563273	CA	Valley	Merced Foothills	209218	SNRACA13
1135965	100563292	CA	Valley	Merced Foothills	209218	SNRACA13
1135966	100563287	CA	Valley	Merced Foothills	209218	SNRACA13
1135975	100563269	CA	Valley	Merced Foothills	209218	SNRACA13
1135997	100563334	CA	Valley	Merced Foothills	209233	TWHRCA11
1135999	100563230	CA	Valley	Merced Foothills	209218	SNRACA13
1136009	100563272	CA	Valley	Merced Foothills	209218	SNRACA13
1136010	100563207	CA	Valley	Merced Foothills	209209	PNCRCA11
1136011	100563240	CA	Valley	Merced Foothills	209218	SNRACA13
1136012	100563234	CA	Valley	Merced Foothills	209218	SNRACA13
1136013	100563232	CA	Valley	Merced Foothills	209218	SNRACA13

1136014	100563228	CA	Valley	Merced Foothills	209218	SNRACA13
1136015	100563226	CA	Valley	Merced Foothills	209218	SNRACA13
1136033	100563298	CA	Valley	Merced Foothills	209218	SNRACA13
1136034	100563296	CA	Valley	Merced Foothills	209218	SNRACA13
1136035	100563295	CA	Valley	Merced Foothills	209218	SNRACA13
1136036	100563294	CA	Valley	Merced Foothills	209218	SNRACA13
1136037	100563291	CA	Valley	Merced Foothills	209218	SNRACA13
1136038	100563290	CA	Valley	Merced Foothills	209218	SNRACA13
1136039	100563289	CA	Valley	Merced Foothills	209218	SNRACA13
1136040	100563288	CA	Valley	Merced Foothills	209218	SNRACA13
1136041	100563286	CA	Valley	Merced Foothills	209218	SNRACA13
1136042	100563284	CA	Valley	Merced Foothills	209218	SNRACA13
1136043	100563282	CA	Valley	Merced Foothills	209218	SNRACA13
1136049	100563280	CA	Valley	Merced Foothills	209218	SNRACA13
1136050	100563279	CA	Valley	Merced Foothills	209218	SNRACA13
1136051	100563276	CA	Valley	Merced Foothills	209218	SNRACA13
1136052	100563271	CA	Valley	Merced Foothills	209218	SNRACA13
1136053	100563270	CA	Valley	Merced Foothills	209218	SNRACA13
1136054	100563267	CA	Valley	Merced Foothills	209218	SNRACA13
1136055	100563264	CA	Valley	Merced Foothills	209218	SNRACA13
1136056	100563263	CA	Valley	Merced Foothills	209218	SNRACA13
1136057	100563262	CA	Valley	Merced Foothills	209218	SNRACA13

1136058	100563261	CA	Valley	Merced Foothills	209218	SNRACA13
1136059	100563260	CA	Valley	Merced Foothills	209218	SNRACA13
1136060	100563258	CA	Valley	Merced Foothills	209218	SNRACA13
1136061	100563255	CA	Valley	Merced Foothills	209218	SNRACA13
1136062	100563252	CA	Valley	Merced Foothills	209218	SNRACA13
1136063	100563251	CA	Valley	Merced Foothills	209218	SNRACA13
1136064	100563250	CA	Valley	Merced Foothills	209218	SNRACA13
1136065	100563249	CA	Valley	Merced Foothills	209218	SNRACA13
1136066	100563248	CA	Valley	Merced Foothills	209218	SNRACA13
1136069	100563184	CA	Valley	Merced Foothills	209173	GVLDCA11
1136071	100563180	CA	Valley	Merced Foothills	209173	GVLDCA11
1136072	100563178	CA	Valley	Merced Foothills	209173	GVLDCA11
1136073	100563176	CA	Valley	Merced Foothills	209173	GVLDCA11
1136074	100563172	CA	Valley	Merced Foothills	209173	GVLDCA11
1136075	100563171	CA	Valley	Merced Foothills	209173	GVLDCA11
1136078	100563205	CA	Valley	Merced Foothills	209173	GVLDCA11
1136079	100563200	CA	Valley	Merced Foothills	209173	GVLDCA11
1136080	100563197	CA	Valley	Merced Foothills	209173	GVLDCA11
1136081	100563196	CA	Valley	Merced Foothills	209173	GVLDCA11
1136082	100563193	CA	Valley	Merced Foothills	209173	GVLDCA11
1136083	100563247	CA	Valley	Merced Foothills	209218	SNRACA13
1136084	100563246	CA	Valley	Merced Foothills	209218	SNRACA13

1136085	100563245	CA	Valley	Merced Foothills	209218	SNRACA13
1136086	100563244	CA	Valley	Merced Foothills	209218	SNRACA13
1136087	100563243	CA	Valley	Merced Foothills	209218	SNRACA13
1136088	100563242	CA	Valley	Merced Foothills	209218	SNRACA13
1136170	100563499	CA	Valley	Merced Foothills	209233	TWHRCA11
1136197	100563973	CA	Valley	Merced Foothills	209233	TWHRCA11
1136216	100563669	CA	Valley	Merced Foothills	209233	TWHRCA11
1136224	100563695	CA	Valley	Merced Foothills	209233	TWHRCA11
1136228	100563699	CA	Valley	Merced Foothills	209233	TWHRCA11
1136232	100563703	CA	Valley	Merced Foothills	209233	TWHRCA11
1136236	100563707	CA	Valley	Merced Foothills	209233	TWHRCA11
1136243	100563986	CA	Valley	Merced Foothills	209233	TWHRCA11
1136244	100563987	CA	Valley	Merced Foothills	209233	TWHRCA11
1136248	100563991	CA	Valley	Merced Foothills	209233	TWHRCA11
1136256	100563349	CA	Valley	Merced Foothills	209233	TWHRCA11
1136259	100563352	CA	Valley	Merced Foothills	209233	TWHRCA11
1136260	100563353	CA	Valley	Merced Foothills	209233	TWHRCA11
1136262	100563355	CA	Valley	Merced Foothills	209233	TWHRCA11
1136264	100563357	CA	Valley	Merced Foothills	209233	TWHRCA11
1136267	100563360	CA	Valley	Merced Foothills	209233	TWHRCA11
1136274	100563678	CA	Valley	Merced Foothills	209233	TWHRCA11

1136285	100563689	CA	Valley	Merced Foothills	209233	TWHRCA11
1136287	100563711	CA	Valley	Merced Foothills	209233	TWHRCA11
1136289	100563713	CA	Valley	Merced Foothills	209233	TWHRCA11
1136293	100563717	CA	Valley	Merced Foothills	209233	TWHRCA11
1136296	100563721	CA	Valley	Merced Foothills	209233	TWHRCA11
1136297	100563722	CA	Valley	Merced Foothills	209233	TWHRCA11
1136303	100564000	CA	Valley	Merced Foothills	209233	TWHRCA11
1136307	100564004	CA	Valley	Merced Foothills	209233	TWHRCA11
1136321	100563369	CA	Valley	Merced Foothills	209233	TWHRCA11
1136325	100563373	CA	Valley	Merced Foothills	209233	TWHRCA11
1136329	100563377	CA	Valley	Merced Foothills	209233	TWHRCA11
1136337	100563573	CA	Valley	Merced Foothills	209233	TWHRCA11
1136342	100563578	CA	Valley	Merced Foothills	209233	TWHRCA11
1136346	100563582	CA	Valley	Merced Foothills	209233	TWHRCA11
1136348	100563584	CA	Valley	Merced Foothills	209233	TWHRCA11
1136351	100563728	CA	Valley	Merced Foothills	209233	TWHRCA11
1136358	100563735	CA	Valley	Merced Foothills	209233	TWHRCA11
1136373	100563389	CA	Valley	Merced Foothills	209233	TWHRCA11
1136377	100563393	CA	Valley	Merced Foothills	209233	TWHRCA11
1136386	100563590	CA	Valley	Merced Foothills	209233	TWHRCA11
1136389	100563593	CA	Valley	Merced Foothills	209233	TWHRCA11
1136394	100563598	CA	Valley	Merced Foothills	209233	TWHRCA11

1136399	100563744	CA	Valley	Merced Foothills	209233	TWHRCA11
1136400	100563745	CA	Valley	Merced Foothills	209233	TWHRCA11
1136408	100563753	CA	Valley	Merced Foothills	209233	TWHRCA11
1136411	100563756	CA	Valley	Merced Foothills	209233	TWHRCA11
1136414	100563759	CA	Valley	Merced Foothills	209233	TWHRCA11
1136418	100563916	CA	Valley	Merced Foothills	209233	TWHRCA11
1136419	100563917	CA	Valley	Merced Foothills	209233	TWHRCA11
1136423	100563921	CA	Valley	Merced Foothills	209233	TWHRCA11
1136425	100563923	CA	Valley	Merced Foothills	209233	TWHRCA11
1136441	100563411	CA	Valley	Merced Foothills	209233	TWHRCA11
1136447	100563930	CA	Valley	Merced Foothills	209233	TWHRCA11
1136454	100563937	CA	Valley	Merced Foothills	209233	TWHRCA11
1136462	100563417	CA	Valley	Merced Foothills	209233	TWHRCA11
1136479	100563946	CA	Valley	Merced Foothills	209233	TWHRCA11
1136482	100563832	CA	Valley	Merced Foothills	209233	TWHRCA11
1136487	100563837	CA	Valley	Merced Foothills	209233	TWHRCA11
1136493	100563433	CA	Valley	Merced Foothills	209233	TWHRCA11
1136504	100563512	CA	Valley	Merced Foothills	209233	TWHRCA11
1136505	100563601	CA	Valley	Merced Foothills	209233	TWHRCA11
1136509	100563516	CA	Valley	Merced Foothills	209233	TWHRCA11
1136512	100563519	CA	Valley	Merced Foothills	209233	TWHRCA11
1136525	100563605	CA	Valley	Merced Foothills	209233	TWHRCA11

1136526	100563606	CA	Valley	Merced Foothills	209233	TWHRCA11
1136538	100563840	CA	Valley	Merced Foothills	209233	TWHRCA11
1136546	100563848	CA	Valley	Merced Foothills	209233	TWHRCA11
1136556	100563555	CA	Valley	Merced Foothills	209233	TWHRCA11
1136562	100563561	CA	Valley	Merced Foothills	209233	TWHRCA11
1136580	100563851	CA	Valley	Merced Foothills	209233	TWHRCA11
1136585	100563856	CA	Valley	Merced Foothills	209233	TWHRCA11
1136591	100563862	CA	Valley	Merced Foothills	209233	TWHRCA11
1136597	100563566	CA	Valley	Merced Foothills	209233	TWHRCA11
1136605	100563541	CA	Valley	Merced Foothills	209233	TWHRCA11
1136610	100563634	CA	Valley	Merced Foothills	209233	TWHRCA11
1136619	100563643	CA	Valley	Merced Foothills	209233	TWHRCA11
1136621	100563645	CA	Valley	Merced Foothills	209233	TWHRCA11
1136622	100563646	CA	Valley	Merced Foothills	209233	TWHRCA11
1136623	100563647	CA	Valley	Merced Foothills	209233	TWHRCA11
1136630	100563870	CA	Valley	Merced Foothills	209233	TWHRCA11
1136639	100563879	CA	Valley	Merced Foothills	209233	TWHRCA11
1136641	100563545	CA	Valley	Merced Foothills	209233	TWHRCA11
1136642	100563546	CA	Valley	Merced Foothills	209233	TWHRCA11
1136652	100563436	CA	Valley	Merced Foothills	209233	TWHRCA11
1136657	100563649	CA	Valley	Merced Foothills	209233	TWHRCA11
1136659	100563651	CA	Valley	Merced Foothills	209233	TWHRCA11

1136660	100563652	CA	Valley	Merced Foothills	209233	TWHRCA11
1136668	100563763	CA	Valley	Merced Foothills	209233	TWHRCA11
1136679	100563887	CA	Valley	Merced Foothills	209233	TWHRCA11
1136692	100563445	CA	Valley	Merced Foothills	209233	TWHRCA11
1136696	100563449	CA	Valley	Merced Foothills	209233	TWHRCA11
1136705	100563770	CA	Valley	Merced Foothills	209233	TWHRCA11
1136709	100563774	CA	Valley	Merced Foothills	209233	TWHRCA11
1136731	100563908	CA	Valley	Merced Foothills	209233	TWHRCA11
1136735	100563458	CA	Valley	Merced Foothills	209233	TWHRCA11
1136740	100563463	CA	Valley	Merced Foothills	209233	TWHRCA11
1136741	100563464	CA	Valley	Merced Foothills	209233	TWHRCA11
1136744	100563468	CA	Valley	Merced Foothills	209233	TWHRCA11
1136748	100563783	CA	Valley	Merced Foothills	209233	TWHRCA11
1136751	100563786	CA	Valley	Merced Foothills	209233	TWHRCA11
1136754	100563789	CA	Valley	Merced Foothills	209233	TWHRCA11
1136756	100563791	CA	Valley	Merced Foothills	209233	TWHRCA11
1136757	100563792	CA	Valley	Merced Foothills	209233	TWHRCA11
1136759	100563794	CA	Valley	Merced Foothills	209233	TWHRCA11
1136760	100563812	CA	Valley	Merced Foothills	209233	TWHRCA11
1136763	100563816	CA	Valley	Merced Foothills	209233	TWHRCA11
1136765	100563911	CA	Valley	Merced Foothills	209233	TWHRCA11
1136768	100564015	CA	Valley	Merced Foothills	209233	TWHRCA11

1136771	100564018	CA	Valley	Merced Foothills	209233	TWHRCA11
1136773	100564020	CA	Valley	Merced Foothills	209233	TWHRCA11
1136790	100563482	CA	Valley	Merced Foothills	209233	TWHRCA11
1136797	100563818	CA	Valley	Merced Foothills	209233	TWHRCA11
1136802	100563823	CA	Valley	Merced Foothills	209233	TWHRCA11
1136813	100563952	CA	Valley	Merced Foothills	209233	TWHRCA11
1136815	100563954	CA	Valley	Merced Foothills	209233	TWHRCA11
1136831	100564023	CA	Valley	Merced Foothills	209233	TWHRCA11
1136834	100564026	CA	Valley	Merced Foothills	209233	TWHRCA11
1136839	100564031	CA	Valley	Merced Foothills	209233	TWHRCA11
1136847	100564039	CA	Valley	Merced Foothills	209233	TWHRCA11
1136848	100564040	CA	Valley	Merced Foothills	209233	TWHRCA11
1136856	100564048	CA	Valley	Merced Foothills	209233	TWHRCA11
1136861	100564053	CA	Valley	Merced Foothills	209233	TWHRCA11
1137320	100564205	CA	Valley	Merced Foothills	209193	LSBNCA12
1138257	100565033	CA	Valley	Merced Foothills	209161	CTVLCA11
1160962	100578358	CA	Valley	Fresno	559194	MADRCA11
1176943	100589348	CA	Valley	Merced Foothills	209233	TWHRCA11
1176944	100589351	CA	Valley	Merced Foothills	209233	TWHRCA11
1208095	100613780	CA	Valley	Merced Foothills	209196	MRCDCA01
1370997	100736975	CA	Valley	Merced Foothills	209218	SNRACA13
1380274	100744377	CA	Valley	Merced Foothills	209233	TWHRCA11

1392685		California	Valley	Merced Foothills	209209	PNCRCA11
1397466	100756996	CA	Valley	Merced Foothills	209182	JMTWCA11
1403017	100760677	CA	Valley	Merced Foothills	209240	YSMTCA11
1405654	100763166	CA	Valley	Merced Foothills	209218	SNRACA13
1405661	100763271	CA	Valley	Merced Foothills	209218	SNRACA13
1457769	100805569	CA	Valley	Merced Foothills	209233	TWHRCA11
1474766	100820014	CA	Valley	Merced Foothills	209233	TWHRCA11
1479376	100824119	CA	Valley	Merced Foothills	209233	TWHRCA11
1480453	100824302	CA	Valley	Merced Foothills	559158	CHWCCA11
1480454	100824298	CA	Valley	Merced Foothills	559158	CHWCCA11
1568046	100895815	CA	Valley	Merced Foothills	209218	SNRACA13

WC_NAME	CREATE_DATE	DUE_DATE	CLOSED_DATE	CREATED_UUID	FORCE_TECH
COULTERVILLE	11/27/2019	4/15/2020	5/23/2020	INSPTR	MD1646
LAGRANGE/D PEDRO	11/28/2019	10/8/2020	9/8/2020	INSPTR	
LAGRANGE/D PEDRO	11/28/2019	10/9/2020	9/30/2020	INSPTR	
LAGRANGE/D PEDRO	11/28/2019	10/7/2020	9/24/2020	INSPTR	
LAGRANGE/D PEDRO	11/28/2019	10/7/2020	9/29/2020	INSPTR	
LAGRANGE/D PEDRO	11/28/2019	10/9/2020	9/29/2020	INSPTR	
LAGRANGE/D PEDRO	11/28/2019	10/9/2020	9/30/2020	INSPTR	
LAGRANGE/D PEDRO	11/28/2019	10/7/2020	9/24/2020	INSPTR	
LAGRANGE/D PEDRO	11/28/2019	10/9/2020	9/24/2020	INSPTR	
LAGRANGE/D PEDRO	11/28/2019	10/9/2020	9/30/2020	INSPTR	
LAGRANGE/D PEDRO	11/28/2019	10/7/2020	8/13/2021	INSPTR	
LAGRANGE/D PEDRO	11/28/2019	10/8/2020	8/13/2021	INSPTR	
LAGRANGE/D PEDRO	11/28/2019	10/7/2020	8/13/2021	INSPTR	
LAGRANGE/D PEDRO	11/28/2019	10/7/2020	8/13/2021	INSPTR	PE4219
LAGRANGE/D PEDRO	11/28/2019	10/9/2020	10/20/2020	INSPTR	
LAGRANGE/D PEDRO	11/28/2019	10/8/2020	8/13/2021	INSPTR	
LAGRANGE/D PEDRO	11/28/2019	10/8/2020	4/25/2022	INSPTR	
LAGRANGE/D PEDRO	11/28/2019	10/7/2020	4/23/2021	INSPTR	
LAGRANGE/D PEDRO	11/28/2019	10/8/2020	4/25/2022	INSPTR	
LAGRANGE/D PEDRO	11/28/2019	10/9/2020	10/20/2020	INSPTR	
LAGRANGE/D PEDRO	11/28/2019	10/9/2020	10/20/2020	INSPTR	

LAGRANGE/D PEDRO	11/28/2019	10/7/2020	6/3/2021	INSPTR	
LAGRANGE/D PEDRO	11/28/2019	10/9/2020	10/20/2020	INSPTR	
LAGRANGE/D PEDRO	11/28/2019	10/9/2020	10/20/2020	INSPTR	
LAGRANGE/D PEDRO	11/28/2019	10/9/2020	10/20/2020	INSPTR	
LAGRANGE/D PEDRO	11/28/2019	10/8/2020	10/19/2020	INSPTR	
LAGRANGE/D PEDRO	11/28/2019	10/9/2020	10/20/2020	INSPTR	
LAGRANGE/D PEDRO	11/28/2019	10/9/2020	10/20/2020	INSPTR	
LAGRANGE/D PEDRO	11/28/2019	10/8/2020	10/19/2020	INSPTR	
LAGRANGE/D PEDRO	11/28/2019	10/8/2020	10/19/2020	INSPTR	
EL PORTAL	11/28/2019	10/10/2024	10/9/2024	INSPTR	CH2861
EL PORTAL	11/28/2019	10/10/2024	10/15/2024	INSPTR	EA2979
LAGRANGE/D PEDRO	11/28/2019	10/7/2024	8/11/2021	INSPTR	
LAGRANGE/D PEDRO	11/28/2019	10/8/2024	8/12/2021	INSPTR	RR2576
LAGRANGE/D PEDRO	11/28/2019	10/8/2024	11/1/2023	INSPTR	DG3424
LAGRANGE/D PEDRO	11/28/2019	10/9/2024	8/10/2021	INSPTR	
LAGRANGE/D PEDRO	11/28/2019	10/8/2024	11/2/2023	INSPTR	DG3424
GROVELAND	11/28/2019	10/5/2024	6/7/2024	INSPTR	JM687J
GROVELAND	11/28/2019	10/5/2024	6/7/2024	INSPTR	JM687J
GROVELAND	11/28/2019	10/5/2024	6/11/2024	INSPTR	JM687J
LAGRANGE/D PEDRO	11/28/2019	10/7/2024	8/4/2021	INSPTR	
LAGRANGE/D PEDRO	11/28/2019	10/7/2024	11/30/2023	INSPTR	EM3528

LAGRANGE/D PEDRO	11/28/2019	10/7/2024	8/4/2021	INSPTR	
LAGRANGE/D PEDRO	11/28/2019	10/7/2024	8/4/2021	INSPTR	
LAGRANGE/D PEDRO	11/28/2019	10/8/2024	8/4/2021	INSPTR	
LAGRANGE/D PEDRO	11/28/2019	10/7/2024	8/4/2021	INSPTR	
LAGRANGE/D PEDRO	11/28/2019	10/7/2024	12/1/2023	INSPTR	CH8326
LAGRANGE/D PEDRO	11/28/2019	10/8/2024	8/3/2021	INSPTR	RR2576
LAGRANGE/D PEDRO	11/28/2019	10/7/2024	12/4/2023	INSPTR	RN8732
LAGRANGE/D PEDRO	11/28/2019	10/7/2024	8/4/2021	INSPTR	
LAGRANGE/D PEDRO	11/28/2019	10/8/2024	8/4/2021	INSPTR	
LAGRANGE/D PEDRO	11/28/2019	10/7/2024	6/10/2021	INSPTR	RR2576
LAGRANGE/D PEDRO	11/28/2019	10/7/2024	6/10/2021	INSPTR	
LAGRANGE/D PEDRO	11/28/2019	10/8/2024	6/10/2021	INSPTR	
LAGRANGE/D PEDRO	11/28/2019	10/8/2024	8/4/2021	INSPTR	
LAGRANGE/D PEDRO	11/28/2019	10/9/2024	8/10/2021	INSPTR	
LAGRANGE/D PEDRO	11/28/2019	10/9/2024	6/10/2021	INSPTR	
LAGRANGE/D PEDRO	11/28/2019	10/7/2024	6/10/2021	INSPTR	
LAGRANGE/D PEDRO	11/28/2019	10/7/2024	6/10/2021	INSPTR	
LAGRANGE/D PEDRO	11/28/2019	10/7/2024	8/10/2021	INSPTR	
LAGRANGE/D PEDRO	11/28/2019	10/9/2024	6/10/2021	INSPTR	
LAGRANGE/D PEDRO	11/28/2019	10/9/2024	8/4/2021	INSPTR	
LAGRANGE/D PEDRO	11/28/2019	10/9/2024	8/10/2021	INSPTR	
LAGRANGE/D PEDRO	11/28/2019	10/8/2024	8/10/2021	INSPTR	

LAGRANGE/D PEDRO	11/28/2019	10/7/2024	8/11/2021	INSPTR	
LAGRANGE/D PEDRO	11/28/2019	10/7/2024	8/5/2021	INSPTR	RR2576
LAGRANGE/D PEDRO	11/28/2019	10/7/2024	8/4/2021	INSPTR	
LAGRANGE/D PEDRO	11/28/2019	10/7/2024	8/4/2021	INSPTR	
LAGRANGE/D PEDRO	11/28/2019	10/7/2024	12/7/2023	INSPTR	CF1419
LAGRANGE/D PEDRO	11/28/2019	10/9/2024	12/8/2023	INSPTR	DG3424
LAGRANGE/D PEDRO	11/28/2019	10/7/2024	12/6/2023	INSPTR	CH8326
LAGRANGE/D PEDRO	11/28/2019	10/8/2024	12/7/2023	INSPTR	CH8326
LAGRANGE/D PEDRO	11/28/2019	10/8/2024	8/11/2021	INSPTR	
LAGRANGE/D PEDRO	11/28/2019	10/8/2024	12/7/2023	INSPTR	CH8326
LAGRANGE/D PEDRO	11/28/2019	10/9/2024	8/11/2021	INSPTR	
LAGRANGE/D PEDRO	11/28/2019	10/9/2024	12/6/2023	INSPTR	JB7519
LAGRANGE/D PEDRO	11/28/2019	10/9/2024	4/9/2024	INSPTR	BS2864
LAGRANGE/D PEDRO	11/28/2019	10/7/2024	8/13/2021	INSPTR	RR2576
LAGRANGE/D PEDRO	11/28/2019	10/8/2024	8/4/2021	INSPTR	
LAGRANGE/D PEDRO	11/28/2019	10/9/2024	12/7/2023	INSPTR	DS6453
LAGRANGE/D PEDRO	11/28/2019	10/8/2024	11/30/2023	INSPTR	EM3528
LAGRANGE/D PEDRO	11/28/2019	10/7/2024	12/7/2023	INSPTR	CF1419
LAGRANGE/D PEDRO	11/28/2019	10/9/2024	12/4/2023	INSPTR	DA1367
LAGRANGE/D PEDRO	11/28/2019	10/8/2024	12/15/2023	INSPTR	JG9626
LAGRANGE/D PEDRO	11/28/2019	10/8/2024	11/30/2023	INSPTR	EM3528
LAGRANGE/D PEDRO	11/28/2019	10/8/2024	8/12/2021	INSPTR	RR2576

LAGRANGE/D PEDRO	11/28/2019	10/7/2024	8/10/2021	INSPTR	
LAGRANGE/D PEDRO	11/28/2019	10/7/2024	11/29/2023	INSPTR	EM3528
LAGRANGE/D PEDRO	11/28/2019	10/8/2024	8/10/2021	INSPTR	
LAGRANGE/D PEDRO	11/28/2019	10/7/2024	11/29/2023	INSPTR	EM3528
LAGRANGE/D PEDRO	11/28/2019	10/9/2024	12/8/2023	INSPTR	DG3424
LAGRANGE/D PEDRO	11/28/2019	10/7/2024	12/15/2023	INSPTR	SD9656
LAGRANGE/D PEDRO	11/28/2019	10/9/2024	11/30/2023	INSPTR	DG3175
LAGRANGE/D PEDRO	11/28/2019	10/8/2024	11/30/2023	INSPTR	DG3175
LAGRANGE/D PEDRO	11/28/2019	10/8/2024	10/31/2023	INSPTR	DS6453
LAGRANGE/D PEDRO	11/28/2019	10/8/2024	11/29/2023	INSPTR	LH5743
LAGRANGE/D PEDRO	11/28/2019	10/9/2024	11/29/2023	INSPTR	EM3528
LAGRANGE/D PEDRO	11/28/2019	10/7/2024	12/15/2023	INSPTR	AD2932
LAGRANGE/D PEDRO	11/28/2019	10/7/2024	11/8/2023	INSPTR	DG3424
LAGRANGE/D PEDRO	11/28/2019	10/7/2024	10/31/2023	INSPTR	JG9626
LAGRANGE/D PEDRO	11/28/2019	10/8/2024	11/2/2023	INSPTR	JG9626
LAGRANGE/D PEDRO	11/28/2019	10/8/2024	11/2/2023	INSPTR	DG3424
LAGRANGE/D PEDRO	11/28/2019	10/9/2024	11/7/2023	INSPTR	DG3424
LAGRANGE/D PEDRO	11/28/2019	10/8/2024	11/3/2023	INSPTR	DG3424
LAGRANGE/D PEDRO	11/28/2019	10/9/2024	10/31/2023	INSPTR	DG3175
EL PORTAL	11/28/2019	10/10/2022	10/26/2022	INSPTR	AL1824
EL PORTAL	11/28/2019	10/10/2022	10/26/2022	INSPTR	AL1824
EL PORTAL	11/28/2019	10/10/2022	10/26/2022	INSPTR	AL1824

GROVELAND	11/28/2019	10/5/2022	2/28/2022	INSPTR	NK5685
YOSEMITE MAIN	11/29/2019	10/10/2024	10/4/2024	INSPTR	CH2861
YOSEMITE MAIN	11/29/2019	10/10/2022	12/30/2022	INSPTR	CH2861
SONORA	12/10/2019	10/4/2020	9/4/2020	INSPTR	
SONORA	12/10/2019	12/9/2020	12/14/2020	MT3262	
SONORA	12/10/2019	10/4/2024	1/26/2024	INSPTR	KW5925
SONORA	12/10/2019	10/4/2024	5/15/2024	INSPTR	KW5925
SONORA	12/10/2019	10/4/2022	2/14/2023	INSPTR	CH8326
SONORA	12/12/2019	10/7/2020	9/30/2020	INSPTR	
SONORA	12/12/2019	10/7/2020	9/8/2020	INSPTR	
SONORA	12/12/2019	10/9/2020	10/8/2020	INSPTR	DM9879
SONORA	12/12/2019	10/9/2020	10/1/2020	INSPTR	
SONORA	12/12/2019	10/7/2020	9/29/2020	INSPTR	
SONORA	12/12/2019	10/8/2020	3/10/2021	INSPTR	
JAMESTOWN	12/12/2019	10/4/2020	12/9/2020	INSPTR	
SONORA	12/12/2019	10/7/2020	9/20/2023	INSPTR	
JAMESTOWN	12/12/2019	10/4/2020	12/3/2020	INSPTR	
JAMESTOWN	12/12/2019	10/4/2020	12/3/2020	INSPTR	
JAMESTOWN	12/12/2019	10/4/2020	6/21/2021	INSPTR	
JAMESTOWN	12/12/2019	10/4/2024	4/12/2022	INSPTR	
JAMESTOWN	12/12/2019	10/4/2024	11/29/2023	INSPTR	JB8576
JAMESTOWN	12/12/2019	10/4/2024	4/12/2022	INSPTR	

JAMESTOWN	12/12/2019	10/4/2024	2/24/2023	INSPTR	
JAMESTOWN	12/12/2019	10/4/2024	4/12/2022	INSPTR	
JAMESTOWN	12/12/2019	10/4/2024	4/12/2022	INSPTR	
JAMESTOWN	12/12/2019	10/4/2024	11/30/2023	INSPTR	TJ4856
SONORA	12/12/2019	10/8/2024	6/10/2024	INSPTR	JX5547
SONORA	12/12/2019	10/10/2024	5/24/2024	INSPTR	JA2756
JAMESTOWN	12/12/2019	10/4/2024	4/12/2022	INSPTR	
JAMESTOWN	12/12/2019	10/4/2024	2/24/2023	INSPTR	
SONORA	12/12/2019	10/9/2024	5/23/2024	INSPTR	JA2756
JAMESTOWN	12/12/2019	10/4/2024	11/30/2023	INSPTR	JB7519
SONORA	12/12/2019	10/7/2024	6/6/2024	INSPTR	JA2756
JAMESTOWN	12/12/2019	10/4/2024	4/11/2022	INSPTR	
JAMESTOWN	12/12/2019	10/4/2024	4/11/2022	INSPTR	
JAMESTOWN	12/12/2019	10/4/2024	4/11/2022	INSPTR	
JAMESTOWN	12/12/2019	10/4/2024	12/1/2023	INSPTR	CS1623
JAMESTOWN	12/12/2019	10/4/2024	4/11/2022	INSPTR	
JAMESTOWN	12/12/2019	10/4/2024	10/31/2023	INSPTR	RS8367
SONORA	12/12/2019	10/9/2024	6/10/2024	INSPTR	JM687J
JAMESTOWN	12/12/2019	10/4/2024	4/11/2022	INSPTR	
SONORA	12/12/2019	10/9/2024	6/10/2024	INSPTR	JM687J
JAMESTOWN	12/12/2019	10/4/2024	4/11/2022	INSPTR	
SONORA	12/12/2019	10/2/2024	10/3/2023	INSPTR	CS1623

SONORA	12/12/2019	10/3/2024	5/2/2024	INSPTR	RS8367
JAMESTOWN	12/12/2019	10/4/2024	4/8/2022	INSPTR	
JAMESTOWN	12/12/2019	10/4/2024	4/11/2022	INSPTR	
JAMESTOWN	12/12/2019	10/5/2024	4/7/2022	INSPTR	
SONORA	12/12/2019	10/7/2024	6/4/2024	INSPTR	RB2924
SONORA	12/12/2019	10/7/2024	5/28/2024	INSPTR	CR1893
SONORA	12/12/2019	10/7/2024	6/5/2024	INSPTR	DG3424
JAMESTOWN	12/12/2019	10/5/2024	4/13/2022	INSPTR	
SONORA	12/12/2019	10/7/2024	6/6/2024	INSPTR	DK332Q
SONORA	12/12/2019	10/2/2024	10/27/2023	INSPTR	JG9626
SONORA	12/12/2019	10/9/2024	6/5/2024	INSPTR	DA1367
JAMESTOWN	12/12/2019	10/4/2024	4/13/2022	INSPTR	
JAMESTOWN	12/12/2019	10/4/2024	10/31/2023	INSPTR	CS1623
JAMESTOWN	12/12/2019	10/4/2024	4/13/2022	INSPTR	
JAMESTOWN	12/12/2019	10/4/2024	12/13/2023	INSPTR	CS1623
JAMESTOWN	12/12/2019	10/4/2024	4/14/2022	INSPTR	
SONORA	12/12/2019	10/7/2024	10/27/2023	INSPTR	JG9626
SONORA	12/12/2019	10/2/2024	10/2/2023	INSPTR	RN8732
JAMESTOWN	12/12/2019	10/4/2024	12/6/2023	INSPTR	BS2864
JAMESTOWN	12/12/2019	10/4/2024	4/14/2022	INSPTR	
SONORA	12/12/2019	10/8/2024	6/5/2024	INSPTR	CR1893

JAMESTOWN	12/12/2019	10/4/2024	12/19/2023	INSPTR	JG9626
JAMESTOWN	12/12/2019	10/5/2024	4/14/2022	INSPTR	
JAMESTOWN	12/12/2019	10/4/2024	5/1/2024	INSPTR	DA1367
JAMESTOWN	12/12/2019	10/4/2024	5/1/2024	INSPTR	DA1367
JAMESTOWN	12/12/2019	10/4/2024	5/1/2024	INSPTR	BS2864
JAMESTOWN	12/12/2019	10/4/2024	4/14/2022	INSPTR	
SONORA	12/12/2019	10/7/2024	6/6/2024	INSPTR	UV639W
SONORA	12/12/2019	10/8/2024	6/5/2024	INSPTR	RX1696
JAMESTOWN	12/12/2019	10/4/2024	4/14/2022	INSPTR	
JAMESTOWN	12/12/2019	10/4/2024	4/14/2022	INSPTR	
SONORA	12/12/2019	10/8/2024	6/5/2024	INSPTR	RX1696
JAMESTOWN	12/12/2019	10/4/2024	4/14/2022	INSPTR	
SONORA	12/12/2019	10/8/2024	6/6/2024	INSPTR	IS3295
JAMESTOWN	12/12/2019	10/4/2024	4/15/2022	INSPTR	
JAMESTOWN	12/12/2019	10/4/2024	4/15/2022	INSPTR	
JAMESTOWN	12/12/2019	10/4/2024	4/15/2022	INSPTR	
SONORA	12/12/2019	10/10/2022	2/22/2022	INSPTR	NS1598
SONORA	12/12/2019	10/2/2022	8/24/2022	INSPTR	RS8367
JAMESTOWN	12/12/2019	10/4/2022	11/9/2021	INSPTR	CS9743
SONORA	12/12/2019	10/7/2022	2/14/2022	INSPTR	RN8732
SONORA	12/12/2019	10/7/2022	2/14/2023	INSPTR	CH8326
SONORA	12/12/2019	10/7/2022	8/4/2022	INSPTR	CH8326

JAMESTOWN	12/12/2019	10/4/2022	11/9/2021	INSPTR	CS9743
SONORA	12/12/2019	10/8/2022	2/14/2023	INSPTR	MJ1746
SONORA	12/12/2019	10/8/2022	2/14/2023	INSPTR	RB2924
SONORA	12/12/2019	10/7/2022	4/4/2022	INSPTR	WM9343
SONORA	12/13/2019	10/4/2020	9/11/2020	INSPTR	
SONORA	12/13/2019	10/1/2020	9/4/2020	INSPTR	
SONORA	12/13/2019	4/4/2020	4/14/2020	INSPTR	
SONORA	12/13/2019	4/4/2020	7/23/2020	INSPTR	MT3262
SONORA	12/13/2019	4/2/2020	7/23/2020	INSPTR	MT3262
SONORA	12/13/2019	4/1/2020	7/21/2020	INSPTR	MT3262
SONORA	12/13/2019	4/1/2020	9/27/2020	INSPTR	MG5372
SONORA	12/13/2019	4/2/2020	4/14/2020	INSPTR	
SONORA	12/13/2019	4/2/2020	7/23/2020	INSPTR	MT3262
GROVELAND	12/13/2019	4/6/2020	9/10/2021	INSPTR	
PINECREST	12/13/2019	4/1/2020	7/14/2020	INSPTR	MT3262
SONORA	12/13/2019	10/8/2024	6/6/2024	INSPTR	JM687J
SONORA	12/13/2019	10/4/2024	5/31/2024	INSPTR	RN8732
SONORA	12/13/2019	10/4/2024	6/10/2024	INSPTR	JX5547
SONORA	12/13/2019	10/4/2024	6/4/2024	INSPTR	SM1615
SONORA	12/13/2019	10/4/2024	6/13/2024	INSPTR	RN8732
SONORA	12/13/2019	10/3/2024	6/4/2024	INSPTR	KB5463
SONORA	12/13/2019	10/3/2024	6/4/2024	INSPTR	KB5463

SONORA	12/13/2019	10/3/2024	10/3/2023	INSPTR	DG3424
SONORA	12/13/2019	10/3/2024	5/7/2024	INSPTR	MJ1746
GROVELAND	12/13/2019	10/6/2024	6/7/2024	INSPTR	DK332Q
GROVELAND	12/13/2019	10/6/2024	8/30/2024	INSPTR	ML5474
GROVELAND	12/13/2019	10/6/2024	6/11/2024	INSPTR	UV639W
GROVELAND	12/13/2019	10/6/2024	6/11/2024	INSPTR	JM687J
GROVELAND	12/13/2019	10/6/2024	6/7/2024	INSPTR	DP7958
GROVELAND	12/13/2019	10/6/2024	6/11/2024	INSPTR	JX5547
GROVELAND	12/13/2019	10/6/2024	6/7/2024	INSPTR	JX5547
GROVELAND	12/13/2019	10/6/2024	6/7/2024	INSPTR	DP7958
GROVELAND	12/13/2019	10/6/2024	6/11/2024	INSPTR	IS3295
GROVELAND	12/13/2019	10/6/2024	6/11/2024	INSPTR	DK332Q
GROVELAND	12/13/2019	10/6/2024	8/5/2024	INSPTR	NK5685
SONORA	12/13/2019	10/8/2024	6/5/2024	INSPTR	DG3424
SONORA	12/13/2019	10/8/2024	6/5/2024	INSPTR	CR1893
SONORA	12/13/2019	10/9/2024	6/5/2024	INSPTR	DA1367
PINECREST	12/13/2019	10/1/2024	5/23/2024	INSPTR	RB2924
SONORA	12/13/2019	10/6/2019	3/18/2020	INSPTR	JQ1534
SONORA	12/13/2019	10/4/2022	2/24/2023	INSPTR	
SONORA	12/13/2019	10/4/2022	2/14/2023	INSPTR	KW5925
SONORA	12/13/2019	10/4/2022	2/14/2023	INSPTR	KW5925
SONORA	12/13/2019	10/3/2022	2/14/2023	INSPTR	KW5925

SONORA	12/13/2019	10/2/2022	2/14/2023	INSPTR	CE2563
SONORA	12/13/2019	10/1/2022	11/30/2022	INSPTR	HC3283
SONORA	12/13/2019	10/1/2022	11/30/2022	INSPTR	RS8367
SONORA	12/13/2019	10/2/2022	2/14/2023	INSPTR	CE2563
GROVELAND	12/13/2019	10/5/2022	2/28/2022	INSPTR	ML5474
SONORA	12/13/2019	10/9/2022	2/14/2023	INSPTR	RB2924
SONORA	12/13/2019	10/8/2022	2/14/2023	INSPTR	MJ1746
SONORA	12/13/2019	10/9/2022	2/22/2022	INSPTR	NS1598
SONORA	12/13/2019	10/9/2022	2/18/2023	INSPTR	RB2924
PINECREST	12/13/2019	10/1/2022	2/8/2022	INSPTR	EM3528
PINECREST	12/13/2019	10/1/2022	2/11/2022	INSPTR	SD9656
PINECREST	12/13/2019	10/1/2022	2/10/2022	INSPTR	JA2756
LOS BANOS	12/27/2019	12/26/2022	1/3/2022	JE8457	DB4196
SONORA	2/11/2020	2/10/2021	1/26/2021	PR2872	
ATWATER	2/19/2020	2/18/2025	5/11/2022	JG9658	JH4935
MERCED	3/6/2020	3/5/2025	3/4/2022	JG9658	JA2891
SONORA	4/8/2020	4/10/2020	1/12/2021	BC8519	
TWAIN HARTE	9/15/2020	9/18/2020	9/21/2020	MR2414	
SONORA	10/9/2020	10/8/2025	10/8/2024	MG5372	CH8326
SONORA	10/9/2020	10/8/2025	10/15/2024	MG5372	JB7519
BONNADELLI	12/16/2020	12/15/2023	2/24/2022	MS8561	JM6318
COULTERVILLE	1/9/2021	9/10/2025	10/16/2024	INSPTR	ML5474

JAMESTOWN	1/10/2021	9/5/2021	5/6/2021	INSPTR	RC1373
JAMESTOWN	1/10/2021	9/5/2021	5/14/2021	INSPTR	AL1824
JAMESTOWN	1/10/2021	9/5/2021	5/5/2021	INSPTR	RC1373
JAMESTOWN	1/10/2021	9/4/2021	5/4/2021	INSPTR	BB6851
JAMESTOWN	1/10/2021	9/4/2021	5/4/2021	INSPTR	BB6851
JAMESTOWN	1/10/2021	9/4/2021	5/4/2021	INSPTR	BB6851
JAMESTOWN	1/10/2021	9/4/2021	5/4/2021	INSPTR	BB6851
JAMESTOWN	1/10/2021	9/4/2021	8/18/2021	INSPTR	
JAMESTOWN	1/10/2021	9/4/2021	5/3/2021	INSPTR	BB6851
JAMESTOWN	1/10/2021	9/9/2021	5/3/2021	INSPTR	BB6851
JAMESTOWN	1/10/2021	9/9/2021	5/5/2021	INSPTR	JS3194
JAMESTOWN	1/10/2021	9/9/2021	5/3/2021	INSPTR	SM1615
JAMESTOWN	1/10/2021	9/8/2021	5/3/2021	INSPTR	SM1615
JAMESTOWN	1/10/2021	9/8/2021	5/3/2021	INSPTR	SM1615
JAMESTOWN	1/10/2021	9/8/2021	5/3/2021	INSPTR	SM1615
JAMESTOWN	1/10/2021	9/9/2021	5/3/2021	INSPTR	SM1615
JAMESTOWN	1/10/2021	9/9/2021	5/3/2021	INSPTR	SM1615
JAMESTOWN	1/10/2021	9/8/2021	5/3/2021	INSPTR	SM1615
JAMESTOWN	1/10/2021	9/8/2021	5/3/2021	INSPTR	SM1615
JAMESTOWN	1/10/2021	9/5/2021	5/3/2021	INSPTR	SM1615
JAMESTOWN	1/10/2021	9/5/2021	5/3/2021	INSPTR	DG9898
JAMESTOWN	1/10/2021	9/5/2021	5/5/2021	INSPTR	DG9898

LAGRANGE/D PEDRO	1/10/2021	9/17/2021	1/16/2021	INSPTR	DD378R
LAGRANGE/D PEDRO	1/10/2021	9/17/2021	8/18/2021	INSPTR	
JAMESTOWN	1/10/2021	9/9/2021	5/3/2021	INSPTR	DG9898
JAMESTOWN	1/10/2021	9/8/2021	5/5/2021	INSPTR	DG9898
JAMESTOWN	1/10/2021	9/8/2021	5/3/2021	INSPTR	DG9898
JAMESTOWN	1/10/2021	9/8/2021	5/3/2021	INSPTR	DG9898
JAMESTOWN	1/10/2021	9/8/2021	11/8/2021	INSPTR	CS9743
JAMESTOWN	1/10/2021	9/9/2021	5/3/2021	INSPTR	DG9898
JAMESTOWN	1/10/2021	9/9/2021	5/3/2021	INSPTR	DG9898
JAMESTOWN	1/10/2021	9/9/2021	5/3/2021	INSPTR	DG9898
JAMESTOWN	1/10/2021	9/8/2021	5/3/2021	INSPTR	DG9898
JAMESTOWN	1/10/2021	9/9/2021	5/3/2021	INSPTR	BB6851
JAMESTOWN	1/10/2021	9/9/2021	5/3/2021	INSPTR	BB6851
JAMESTOWN	1/10/2021	9/9/2021	5/3/2021	INSPTR	BB6851
JAMESTOWN	1/10/2021	9/8/2021	11/8/2021	INSPTR	CS9743
JAMESTOWN	1/10/2021	9/9/2021	5/3/2021	INSPTR	BB6851
JAMESTOWN	1/10/2021	9/9/2021	5/3/2021	INSPTR	BB6851
JAMESTOWN	1/10/2021	9/8/2021	5/5/2021	INSPTR	JS3194
JAMESTOWN	1/10/2021	9/9/2021	5/5/2021	INSPTR	JS3194
JAMESTOWN	1/10/2021	9/8/2021	5/5/2021	INSPTR	JS3194
JAMESTOWN	1/10/2021	9/9/2021	5/5/2021	INSPTR	JS3194
JAMESTOWN	1/10/2021	9/9/2021	11/8/2021	INSPTR	CS9743

JAMESTOWN	1/10/2021	9/8/2021	5/5/2021	INSPTR	DG9898
JAMESTOWN	1/10/2021	9/9/2021	5/5/2021	INSPTR	DG9898
JAMESTOWN	1/10/2021	9/8/2021	5/6/2021	INSPTR	DG9898
JAMESTOWN	1/10/2021	9/8/2021	11/8/2021	INSPTR	CS9743
JAMESTOWN	1/10/2021	9/5/2021	5/5/2021	INSPTR	BB6851
JAMESTOWN	1/10/2021	9/5/2021	5/5/2021	INSPTR	BB6851
JAMESTOWN	1/10/2021	9/5/2021	5/5/2021	INSPTR	BB6851
JAMESTOWN	1/10/2021	9/4/2021	5/5/2021	INSPTR	AL1824
JAMESTOWN	1/10/2021	9/4/2021	5/6/2021	INSPTR	AL1824
JAMESTOWN	1/10/2021	9/4/2021	5/6/2021	INSPTR	AL1824
JAMESTOWN	1/10/2021	9/4/2021	5/5/2021	INSPTR	AL1824
JAMESTOWN	1/10/2021	9/4/2021	5/5/2021	INSPTR	AL1824
JAMESTOWN	1/10/2021	9/4/2021	5/5/2021	INSPTR	AL1824
JAMESTOWN	1/10/2021	9/4/2021	5/5/2021	INSPTR	AL1824
JAMESTOWN	1/10/2021	9/4/2021	5/5/2021	INSPTR	AL1824
JAMESTOWN	1/10/2021	9/4/2021	6/2/2021	INSPTR	WM9343
JAMESTOWN	1/10/2021	9/4/2021	11/8/2021	INSPTR	CS9743
JAMESTOWN	1/10/2021	9/4/2021	5/6/2021	INSPTR	RC1373
JAMESTOWN	1/10/2021	9/4/2021	5/6/2021	INSPTR	RC1373
JAMESTOWN	1/10/2021	9/4/2021	5/6/2021	INSPTR	RC1373
JAMESTOWN	1/10/2021	9/4/2021	5/6/2021	INSPTR	AL1824
JAMESTOWN	1/10/2021	9/4/2021	5/6/2021	INSPTR	AL1824

JAMESTOWN	1/10/2021	9/4/2021	5/6/2021	INSPTR	AL1824
JAMESTOWN	1/10/2021	9/4/2021	5/6/2021	INSPTR	AL1824
JAMESTOWN	1/10/2021	9/5/2021	5/6/2021	INSPTR	AL1824
JAMESTOWN	1/10/2021	9/5/2021	5/6/2021	INSPTR	DG9898
JAMESTOWN	1/10/2021	9/5/2021	5/6/2021	INSPTR	DG9898
JAMESTOWN	1/10/2021	9/5/2021	5/6/2021	INSPTR	DG9898
JAMESTOWN	1/10/2021	9/5/2025	4/15/2022	INSPTR	
JAMESTOWN	1/10/2021	9/5/2025	4/15/2022	INSPTR	
JAMESTOWN	1/10/2021	9/5/2025	4/15/2022	INSPTR	
JAMESTOWN	1/10/2021	9/5/2025	2/24/2023	INSPTR	
JAMESTOWN	1/10/2021	9/4/2025	4/15/2022	INSPTR	
JAMESTOWN	1/10/2021	9/4/2025	2/24/2023	INSPTR	
JAMESTOWN	1/10/2021	9/4/2025	2/24/2023	INSPTR	
JAMESTOWN	1/10/2021	9/8/2025	2/24/2023	INSPTR	
JAMESTOWN	1/10/2021	9/9/2025	2/24/2023	INSPTR	
JAMESTOWN	1/10/2021	9/9/2025	2/24/2023	INSPTR	
JAMESTOWN	1/10/2021	9/8/2025	2/24/2023	INSPTR	
JAMESTOWN	1/10/2021	9/8/2025	2/24/2023	INSPTR	
JAMESTOWN	1/10/2021	9/8/2025	2/24/2023	INSPTR	
JAMESTOWN	1/10/2021	9/8/2025	2/24/2023	INSPTR	
JAMESTOWN	1/10/2021	9/8/2025	2/24/2023	INSPTR	
JAMESTOWN	1/10/2021	9/9/2025	2/24/2023	INSPTR	
JAMESTOWN	1/10/2021	9/5/2025	2/24/2023	INSPTR	

JAMESTOWN	1/10/2021	9/5/2025	2/24/2023	INSPTR	
JAMESTOWN	1/10/2021	9/5/2025	2/24/2023	INSPTR	
JAMESTOWN	1/10/2021	9/5/2025	5/12/2023	INSPTR	
JAMESTOWN	1/10/2021	9/8/2025	2/24/2023	INSPTR	
JAMESTOWN	1/10/2021	9/8/2025	2/24/2023	INSPTR	
JAMESTOWN	1/10/2021	9/8/2025	2/24/2023	INSPTR	
JAMESTOWN	1/10/2021	9/9/2025	2/24/2023	INSPTR	
JAMESTOWN	1/10/2021	9/8/2025	2/24/2023	INSPTR	
JAMESTOWN	1/10/2021	9/5/2025	2/24/2023	INSPTR	
JAMESTOWN	1/10/2021	9/5/2025	2/24/2023	INSPTR	
JAMESTOWN	1/10/2021	9/5/2025	2/24/2023	INSPTR	
JAMESTOWN	1/10/2021	9/5/2025	9/10/2024	INSPTR	MH3568
JAMESTOWN	1/10/2021	9/4/2025	2/24/2023	INSPTR	
JAMESTOWN	1/10/2021	9/5/2025	2/24/2023	INSPTR	
JAMESTOWN	1/10/2021	9/5/2025	2/24/2023	INSPTR	
JAMESTOWN	1/10/2021	9/4/2025	2/24/2023	INSPTR	
JAMESTOWN	1/10/2021	9/5/2025	2/24/2023	INSPTR	
JAMESTOWN	1/10/2021	9/8/2023	2/20/2023	INSPTR	CE2563
JAMESTOWN	1/10/2021	9/9/2023	2/21/2023	INSPTR	RX1696
JAMESTOWN	1/10/2021	9/8/2023	2/20/2023	INSPTR	TJ4856
JAMESTOWN	1/10/2021	9/8/2023	2/20/2023	INSPTR	RX1696
JAMESTOWN	1/10/2021	9/8/2023	2/20/2023	INSPTR	CE2563

JAMESTOWN	1/10/2021	9/9/2023	2/20/2023	INSPTR	TJ4856
JAMESTOWN	1/10/2021	9/8/2023	2/20/2023	INSPTR	TJ4856
JAMESTOWN	1/10/2021	9/4/2023	2/21/2023	INSPTR	RT1486
PINECREST	1/12/2021	3/14/2021	5/6/2021	INSPTR	DG9898
PINECREST	1/12/2021	3/11/2021	5/6/2021	INSPTR	BB6851
PINECREST	1/12/2021	3/11/2021	5/6/2021	INSPTR	BB6851
PINECREST	1/12/2021	3/11/2021	5/6/2021	INSPTR	BB6851
PINECREST	1/12/2021	3/11/2021	9/2/2021	INSPTR	
PINECREST	1/12/2021	3/11/2021	5/6/2021	INSPTR	BB6851
PINECREST	1/12/2021	3/11/2021	1/18/2021	INSPTR	BC8519
PINECREST	1/12/2021	3/11/2021	5/6/2021	INSPTR	BB6851
PINECREST	1/12/2021	3/11/2021	9/2/2021	INSPTR	
PINECREST	1/12/2021	3/11/2021	5/6/2021	INSPTR	JS3194
PINECREST	1/12/2021	3/11/2021	5/6/2021	INSPTR	JS3194
PINECREST	1/12/2021	3/11/2021	6/2/2021	INSPTR	BC1852
PINECREST	1/12/2021	3/11/2021	6/2/2021	INSPTR	BC1852
PINECREST	1/12/2021	3/11/2021	5/6/2021	INSPTR	JS3194
PINECREST	1/12/2021	3/11/2021	5/6/2021	INSPTR	JS3194
GROVELAND	1/12/2021	3/10/2021	8/11/2021	INSPTR	AL1824
GROVELAND	1/12/2021	9/10/2025	9/12/2024	INSPTR	ML5474
GROVELAND	1/12/2021	9/10/2025	10/29/2024	INSPTR	NK5685
GROVELAND	1/12/2021	9/10/2025	10/15/2024	INSPTR	RB2924

GROVELAND	1/12/2021	9/10/2025	9/12/2024	INSPTR	ML5474
GROVELAND	1/12/2021	9/10/2025	9/16/2024	INSPTR	ML5474
GROVELAND	1/12/2021	9/10/2025	10/22/2024	INSPTR	NK5685
GROVELAND	1/12/2021	9/10/2025	9/14/2024	INSPTR	NK5685
GROVELAND	1/12/2021	9/10/2025	10/29/2024	INSPTR	ML5474
GROVELAND	1/12/2021	9/10/2025	11/2/2024	INSPTR	ML5474
GROVELAND	1/12/2021	9/10/2025	10/24/2024	INSPTR	NK5685
GROVELAND	1/12/2021	9/10/2025	9/21/2024	INSPTR	ML5474
GROVELAND	1/12/2021	9/10/2025	9/12/2024	INSPTR	ML5474
GROVELAND	1/12/2021	9/10/2023	2/21/2023	INSPTR	RX1696
GROVELAND	1/12/2021	9/10/2023	2/21/2023	INSPTR	CR1893
GROVELAND	1/12/2021	9/10/2023	2/21/2023	INSPTR	CR1893
GROVELAND	1/12/2021	9/10/2023	2/21/2023	INSPTR	RX1696
SONORA	1/13/2021	3/16/2021	2/6/2021	INSPTR	JB7519
SONORA	1/13/2021	3/14/2021	8/11/2021	INSPTR	AL1824
SONORA	1/13/2021	3/14/2021	3/12/2021	INSPTR	
SONORA	1/13/2021	3/14/2021	3/12/2021	INSPTR	
SONORA	1/13/2021	9/15/2025	9/30/2024	INSPTR	RB2924
SONORA	1/13/2021	9/14/2025	9/30/2024	INSPTR	RB2924
SONORA	1/13/2021	9/16/2025	9/30/2024	INSPTR	TJ4856
SONORA	1/13/2021	9/14/2025	10/2/2024	INSPTR	EC2732
SONORA	1/13/2021	9/14/2025	10/1/2024	INSPTR	EW042G

SONORA	1/13/2021	9/17/2025	9/20/2024	INSPTR	DS6453
SONORA	1/13/2021	9/14/2025	10/1/2024	INSPTR	IS3295
SONORA	1/13/2021	9/16/2025	10/2/2024	INSPTR	KW5925
SONORA	1/13/2021	9/16/2025	9/25/2024	INSPTR	GB3598
SONORA	1/13/2021	9/14/2025	10/3/2024	INSPTR	IS3295
SONORA	1/13/2021	9/17/2025	9/20/2024	INSPTR	DS6453
SONORA	1/13/2021	9/14/2025	10/7/2024	INSPTR	GC408J
SONORA	1/13/2021	9/15/2025	10/9/2024	INSPTR	GC408J
SONORA	1/13/2021	9/14/2025	10/7/2024	INSPTR	GC408J
SONORA	1/13/2021	9/16/2025	9/21/2024	INSPTR	DG3424
SONORA	1/13/2021	9/15/2025	10/1/2024	INSPTR	GC408J
SONORA	1/13/2021	9/15/2025	10/9/2024	INSPTR	EW042G
SONORA	1/13/2021	9/17/2025	9/20/2024	INSPTR	DS6453
SONORA	1/13/2021	9/14/2025	10/9/2024	INSPTR	GC408J
SONORA	1/13/2021	9/15/2025	9/25/2024	INSPTR	MJ1746
SONORA	1/13/2021	9/15/2025	10/2/2024	INSPTR	EC2732
SONORA	1/13/2021	9/15/2025	10/2/2024	INSPTR	GC408J
SONORA	1/13/2021	9/15/2025	10/9/2024	INSPTR	EW042G
SONORA	1/13/2021	9/14/2025	10/1/2024	INSPTR	IS3295
SONORA	1/13/2021	9/15/2025	9/25/2024	INSPTR	MJ1746
SONORA	1/13/2021	9/8/2025	10/8/2024	INSPTR	EC2732

SONORA	1/13/2021	9/8/2025	10/8/2024	INSPTR	EC2732
SONORA	1/13/2021	9/8/2025	10/3/2024	INSPTR	EW042G
SONORA	1/13/2021	9/15/2025	9/25/2024	INSPTR	MJ1746
SONORA	1/13/2021	9/15/2025	10/4/2024	INSPTR	EW042G
SONORA	1/13/2021	9/15/2025	10/2/2024	INSPTR	EW042G
SONORA	1/13/2021	9/16/2025	9/21/2024	INSPTR	DG3424
SONORA	1/13/2021	9/14/2025	10/1/2024	INSPTR	EW042G
SONORA	1/13/2021	9/14/2025	10/2/2024	INSPTR	TJ4856
SONORA	1/13/2021	9/15/2025	10/4/2024	INSPTR	EW042G
SONORA	1/13/2021	9/16/2025	9/21/2024	INSPTR	DG3424
SONORA	1/13/2021	9/15/2025	10/2/2024	INSPTR	EW042G
SONORA	1/13/2021	9/14/2025	10/8/2024	INSPTR	EC2732
SONORA	1/13/2021	9/14/2025	10/7/2024	INSPTR	KW5925
SONORA	1/13/2021	9/15/2025	10/9/2024	INSPTR	IS3295
SONORA	1/13/2021	9/16/2025	9/21/2024	INSPTR	DG3424
SONORA	1/13/2021	9/14/2025	10/2/2024	INSPTR	IS3295
SONORA	1/13/2021	9/17/2025	9/20/2024	INSPTR	DS6453
SONORA	1/13/2021	9/15/2025	9/25/2024	INSPTR	GB3598
SONORA	1/13/2021	9/15/2025	10/2/2024	INSPTR	EC2732
SONORA	1/13/2021	9/17/2025	10/10/2024	INSPTR	EW042G

SONORA	1/13/2021	9/15/2025	10/1/2024	INSPTR	GC408J
SONORA	1/13/2021	9/14/2025	10/2/2024	INSPTR	TJ4856
SONORA	1/13/2021	9/15/2025	10/9/2024	INSPTR	IS3295
SONORA	1/13/2021	9/14/2025	10/2/2024	INSPTR	IS3295
SONORA	1/13/2021	9/15/2025	10/10/2024	INSPTR	IS3295
SONORA	1/13/2021	9/14/2025	10/4/2024	INSPTR	GC408J
SONORA	1/13/2021	9/14/2025	10/4/2024	INSPTR	GC408J
SONORA	1/13/2021	9/15/2023	2/20/2023	INSPTR	DG3175
SONORA	1/13/2021	9/16/2023	2/20/2023	INSPTR	DG3175
SONORA	1/13/2021	9/8/2023	2/20/2023	INSPTR	DA1367
SONORA	1/13/2021	9/8/2023	12/24/2021	INSPTR	CL1646
SONORA	1/13/2021	9/8/2023	2/19/2023	INSPTR	EM3528
SONORA	1/13/2021	9/8/2023	2/20/2023	INSPTR	DA1367
SONORA	1/13/2021	9/17/2023	2/19/2023	INSPTR	RN8732
SONORA	1/13/2021	9/17/2023	2/21/2023	INSPTR	CH8326
SONORA	1/13/2021	9/17/2023	2/19/2023	INSPTR	RN8732
TWAIN HARTE	1/21/2021	3/21/2021	6/2/2021	INSPTR	BC1852
TWAIN HARTE	1/21/2021	3/22/2021	6/2/2021	INSPTR	BC1852
TWAIN HARTE	1/21/2021	3/21/2021	6/2/2021	INSPTR	DG9898
TWAIN HARTE	1/21/2021	3/21/2021	8/12/2021	INSPTR	AL1824

TWAIN HARTE	1/21/2021	3/21/2021	6/2/2021	INSPTR	DG9898
TWAIN HARTE	1/21/2021	3/22/2021	5/7/2021	INSPTR	AL1824
TWAIN HARTE	1/21/2021	3/21/2021	5/7/2021	INSPTR	AL1824
TWAIN HARTE	1/21/2021	3/22/2021	5/7/2021	INSPTR	AL1824
TWAIN HARTE	1/21/2021	3/21/2021	5/7/2021	INSPTR	AL1824
TWAIN HARTE	1/21/2021	3/22/2021	5/7/2021	INSPTR	AL1824
TWAIN HARTE	1/21/2021	3/21/2021	5/7/2021	INSPTR	AL1824
TWAIN HARTE	1/21/2021	3/21/2021	5/7/2021	INSPTR	AL1824
TWAIN HARTE	1/21/2021	3/21/2021	5/7/2021	INSPTR	DG9898
TWAIN HARTE	1/21/2021	3/22/2021	5/7/2021	INSPTR	DG9898
TWAIN HARTE	1/21/2021	3/22/2021	5/7/2021	INSPTR	DG9898
TWAIN HARTE	1/21/2021	3/22/2021	5/7/2021	INSPTR	DG9898
TWAIN HARTE	1/21/2021	3/22/2021	5/7/2021	INSPTR	DG9898
TWAIN HARTE	1/21/2021	3/22/2021	5/7/2021	INSPTR	DG9898
TWAIN HARTE	1/21/2021	3/19/2021	5/7/2021	INSPTR	DG9898
TWAIN HARTE	1/21/2021	3/19/2021	5/7/2021	INSPTR	DG9898
TWAIN HARTE	1/21/2021	3/19/2021	5/7/2021	INSPTR	BB6851
TWAIN HARTE	1/21/2021	3/22/2021	5/7/2021	INSPTR	BB6851
TWAIN HARTE	1/21/2021	3/22/2021	5/7/2021	INSPTR	BB6851
TWAIN HARTE	1/21/2021	3/22/2021	5/7/2021	INSPTR	BB6851
TWAIN HARTE	1/21/2021	3/21/2021	5/7/2021	INSPTR	BB6851
TWAIN HARTE	1/21/2021	3/21/2021	5/7/2021	INSPTR	BB6851

TWAIN HARTE	1/21/2021	3/21/2021	5/7/2021	INSPTR	BB6851
TWAIN HARTE	1/21/2021	3/21/2021	5/7/2021	INSPTR	BB6851
TWAIN HARTE	1/21/2021	3/21/2021	5/7/2021	INSPTR	JS3194
TWAIN HARTE	1/21/2021	3/22/2021	5/7/2021	INSPTR	JS3194
TWAIN HARTE	1/21/2021	3/22/2021	5/7/2021	INSPTR	JS3194
TWAIN HARTE	1/21/2021	3/22/2021	5/7/2021	INSPTR	JS3194
TWAIN HARTE	1/21/2021	3/10/2021	5/3/2021	INSPTR	AL1824
TWAIN HARTE	1/21/2021	3/10/2021	5/3/2021	INSPTR	AL1824
TWAIN HARTE	1/21/2021	3/10/2021	6/2/2021	INSPTR	DG9898
TWAIN HARTE	1/21/2021	3/10/2021	5/7/2021	INSPTR	JS3194
TWAIN HARTE	1/21/2021	3/17/2021	5/6/2021	INSPTR	RC1373
TWAIN HARTE	1/21/2021	3/16/2021	5/3/2021	INSPTR	AL1824
TWAIN HARTE	1/21/2021	3/17/2021	5/4/2021	INSPTR	AL1824
TWAIN HARTE	1/21/2021	3/17/2021	5/4/2021	INSPTR	BB6851
TWAIN HARTE	1/21/2021	3/10/2021	5/7/2021	INSPTR	JS3194
TWAIN HARTE	1/21/2021	3/10/2021	2/10/2023	INSPTR	
TWAIN HARTE	1/21/2021	3/10/2021	5/6/2021	INSPTR	RC1373
TWAIN HARTE	1/21/2021	3/10/2021	5/7/2021	INSPTR	JS3194
TWAIN HARTE	1/21/2021	3/10/2021	5/3/2021	INSPTR	AL1824
TWAIN HARTE	1/21/2021	3/10/2021	5/5/2021	INSPTR	BB6851
TWAIN HARTE	1/21/2021	3/10/2021	8/11/2021	INSPTR	AL1824
TWAIN HARTE	1/21/2021	3/15/2021	6/2/2021	INSPTR	DG9898

TWAIN HARTE	1/21/2021	3/11/2021	6/2/2021	INSPTR	DG9898
TWAIN HARTE	1/21/2021	3/15/2021	6/2/2021	INSPTR	DG9898
TWAIN HARTE	1/21/2021	3/17/2021	6/1/2021	INSPTR	CV3817
TWAIN HARTE	1/21/2021	3/17/2021	6/1/2021	INSPTR	CV3817
TWAIN HARTE	1/21/2021	3/17/2021	6/1/2021	INSPTR	CV3817
TWAIN HARTE	1/21/2021	3/17/2021	6/1/2021	INSPTR	CV3817
TWAIN HARTE	1/21/2021	3/17/2021	6/1/2021	INSPTR	CV3817
TWAIN HARTE	1/21/2021	3/16/2021	6/1/2021	INSPTR	CV3817
TWAIN HARTE	1/21/2021	3/17/2021	6/1/2021	INSPTR	CV3817
TWAIN HARTE	1/21/2021	3/16/2021	6/1/2021	INSPTR	CV3817
TWAIN HARTE	1/21/2021	3/19/2021	6/1/2021	INSPTR	CV3817
TWAIN HARTE	1/21/2021	3/19/2021	6/1/2021	INSPTR	CV3817
TWAIN HARTE	1/21/2021	3/19/2021	6/1/2021	INSPTR	CV3817
TWAIN HARTE	1/21/2021	3/19/2021	6/1/2021	INSPTR	DG9898
TWAIN HARTE	1/21/2021	3/19/2021	6/1/2021	INSPTR	DG9898
TWAIN HARTE	1/21/2021	3/16/2021	6/1/2021	INSPTR	DG9898
TWAIN HARTE	1/21/2021	3/19/2021	6/1/2021	INSPTR	DG9898
TWAIN HARTE	1/21/2021	3/19/2021	8/12/2021	INSPTR	AL1824
TWAIN HARTE	1/21/2021	3/19/2021	6/1/2021	INSPTR	DG9898
TWAIN HARTE	1/21/2021	3/18/2021	6/1/2021	INSPTR	DG9898
TWAIN HARTE	1/21/2021	3/18/2021	8/12/2021	INSPTR	AL1824
TWAIN HARTE	1/21/2021	3/16/2021	6/1/2021	INSPTR	BC1852

TWAIN HARTE	1/21/2021	3/16/2021	8/11/2021	INSPTR	AL1824
TWAIN HARTE	1/21/2021	3/16/2021	6/1/2021	INSPTR	BC1852
TWAIN HARTE	1/21/2021	3/15/2021	8/12/2021	INSPTR	AL1824
TWAIN HARTE	1/21/2021	3/18/2021	8/12/2021	INSPTR	AL1824
TWAIN HARTE	1/21/2021	3/18/2021	6/1/2021	INSPTR	BC1852
TWAIN HARTE	1/21/2021	3/18/2021	6/1/2021	INSPTR	BC1852
TWAIN HARTE	1/21/2021	3/18/2021	5/4/2021	INSPTR	DG9898
TWAIN HARTE	1/21/2021	3/18/2021	5/4/2021	INSPTR	DG9898
TWAIN HARTE	1/21/2021	3/18/2021	5/4/2021	INSPTR	DG9898
TWAIN HARTE	1/21/2021	3/18/2021	5/4/2021	INSPTR	DG9898
TWAIN HARTE	1/21/2021	3/18/2021	5/4/2021	INSPTR	DG9898
TWAIN HARTE	1/21/2021	3/15/2021	5/4/2021	INSPTR	BB6851
TWAIN HARTE	1/21/2021	3/11/2021	5/4/2021	INSPTR	BB6851
TWAIN HARTE	1/21/2021	3/18/2021	5/4/2021	INSPTR	SM1615
TWAIN HARTE	1/21/2021	3/18/2021	5/4/2021	INSPTR	SM1615
TWAIN HARTE	1/21/2021	3/18/2021	5/4/2021	INSPTR	SM1615
TWAIN HARTE	1/21/2021	3/10/2021	5/4/2021	INSPTR	SM1615
TWAIN HARTE	1/21/2021	3/10/2021	5/4/2021	INSPTR	SM1615
TWAIN HARTE	1/21/2021	3/10/2021	5/4/2021	INSPTR	SM1615
TWAIN HARTE	1/21/2021	3/10/2021	2/22/2021	INSPTR	SG5282
TWAIN HARTE	1/21/2021	3/10/2021	5/4/2021	INSPTR	SM1615
TWAIN HARTE	1/21/2021	10/7/2025	6/24/2022	INSPTR	

TWAIN HARTE	1/21/2021	9/21/2025	6/24/2022	INSPTR	
TWAIN HARTE	1/21/2021	9/21/2025	6/24/2022	INSPTR	
TWAIN HARTE	1/21/2021	9/22/2025	6/24/2022	INSPTR	
TWAIN HARTE	1/21/2021	9/10/2025	5/25/2022	INSPTR	
TWAIN HARTE	1/21/2021	9/17/2025	5/25/2022	INSPTR	
TWAIN HARTE	1/21/2021	9/16/2025	6/23/2022	INSPTR	
TWAIN HARTE	1/21/2021	9/16/2025	6/23/2022	INSPTR	
TWAIN HARTE	1/21/2021	9/19/2025	6/23/2022	INSPTR	
TWAIN HARTE	1/21/2021	9/19/2025	6/23/2022	INSPTR	
TWAIN HARTE	1/21/2021	9/16/2025	6/23/2022	INSPTR	
TWAIN HARTE	1/21/2021	9/19/2025	6/23/2022	INSPTR	
TWAIN HARTE	1/21/2021	9/15/2025	5/25/2022	INSPTR	
TWAIN HARTE	1/21/2021	9/21/2023	2/19/2023	INSPTR	RB2924
TWAIN HARTE	1/21/2021	9/19/2023	2/20/2023	INSPTR	RN8732
TWAIN HARTE	1/21/2021	9/22/2023	2/20/2023	INSPTR	RT1486
TWAIN HARTE	1/21/2021	9/17/2023	2/20/2023	INSPTR	CS1623
TWAIN HARTE	1/21/2021	9/17/2023	2/20/2023	INSPTR	CS1623
TWAIN HARTE	1/21/2021	9/17/2023	2/19/2023	INSPTR	RX1696
TWAIN HARTE	1/21/2021	9/17/2023	2/21/2023	INSPTR	JB8576
TWAIN HARTE	1/21/2021	9/19/2023	2/20/2023	INSPTR	RN8732
TWAIN HARTE	1/21/2021	9/16/2023	2/20/2023	INSPTR	RX1696
TWAIN HARTE	1/21/2021	9/19/2023	2/20/2023	INSPTR	CR1893

TWAIN HARTE	1/21/2021	9/18/2023	2/20/2023	INSPTR	RX1696
TWAIN HARTE	1/21/2021	9/22/2023	2/20/2023	INSPTR	RT1486
TWAIN HARTE	1/21/2021	9/10/2023	2/21/2023	INSPTR	JB8576
SONORA	2/7/2021	2/6/2024	2/19/2023	JB7519	BS2864
SONORA	3/9/2021	3/9/2022	8/8/2022	MR2414	
LAGRANGE/D PEDRO	3/18/2021	3/20/2021	4/15/2021	DD378R	
LE GRAND	5/20/2021	5/23/2021	5/28/2021	BB6851	JM9856
TWAIN HARTE	6/12/2021	6/15/2021	6/21/2021	MT3262	
GUSTINE	8/4/2021	8/4/2024	10/27/2022	JE8457	JA2891
TWAIN HARTE	8/19/2021	8/18/2022	8/9/2022	AD2932	
MADERA MAIN	8/31/2021	9/2/2021	9/8/2021	RC1373	
MADERA MAIN	9/4/2021	9/6/2021	9/15/2021	RC1373	
SONORA	11/1/2021	11/4/2021	2/2/2022	MR2414	
SONORA	11/4/2021	11/7/2021	2/2/2022	DW2564	
SONORA	11/9/2021	11/9/2022	2/7/2022	MR2414	AD2932
JAMESTOWN	11/11/2021	11/14/2021	11/16/2021	MR2414	
GROVELAND	11/16/2021	11/19/2021	2/1/2022	MR2414	
YOSEMITE MAIN	11/30/2021	11/30/2022	5/24/2023	MR2414	CH2861
YOSEMITE MAIN	11/30/2021	11/30/2022	5/24/2023	MR2414	CH2861
YOSEMITE MAIN	11/30/2021	11/30/2024	10/7/2024	MR2414	CH2861
YOSEMITE MAIN	11/30/2021	11/30/2022	5/24/2023	MR2414	CH2861
YOSEMITE MAIN	11/30/2021	11/30/2022	5/24/2023	MR2414	CH2861

YOSEMITE MAIN	11/30/2021	12/3/2021	6/28/2022	MR2414	
YOSEMITE MAIN	11/30/2021	11/30/2022	5/24/2023	MR2414	CH2861
GROVELAND	1/2/2022	11/8/2024	9/30/2024	INSPTR	NK5685
GROVELAND	1/2/2022	11/4/2024	9/5/2024	INSPTR	ML5474
GROVELAND	1/2/2022	11/4/2024	9/3/2024	INSPTR	ML5474
GROVELAND	1/2/2022	11/4/2024	9/5/2024	INSPTR	NK5685
GROVELAND	1/2/2022	11/4/2024	9/5/2024	INSPTR	NK5685
GROVELAND	1/2/2022	11/4/2024	9/18/2024	INSPTR	NK5685
GROVELAND	1/2/2022	11/5/2024	6/7/2024	INSPTR	JX5547
GROVELAND	1/2/2022	11/5/2022	2/26/2022	INSPTR	ML5474
GROVELAND	1/2/2022	11/5/2022	8/12/2022	INSPTR	
GROVELAND	1/2/2022	11/8/2024	9/19/2024	INSPTR	ML5474
GROVELAND	1/2/2022	11/8/2024	9/19/2024	INSPTR	ML5474
GROVELAND	1/2/2022	11/8/2024	10/2/2024	INSPTR	ML5474
GROVELAND	1/2/2022	11/8/2024	10/28/2024	INSPTR	ML5474
GROVELAND	1/2/2022	11/11/2026	7/9/2024	INSPTR	
GROVELAND	1/2/2022	11/9/2024	10/28/2024	INSPTR	ML5474
GROVELAND	1/2/2022	11/10/2024	8/7/2024	INSPTR	NK5685
GROVELAND	1/2/2022	11/11/2024	6/7/2024	INSPTR	RS556S
GROVELAND	1/2/2022	11/5/2024	9/21/2024	INSPTR	ML5474
PINECREST	1/2/2022	11/18/2024	7/31/2024	INSPTR	EC2732
PINECREST	1/2/2022	11/18/2024	7/31/2024	INSPTR	EC2732

GROVELAND	1/2/2022	11/4/2024	9/5/2024	INSPTR	ML5474
GROVELAND	1/2/2022	11/9/2024	10/28/2024	INSPTR	ML5474
GROVELAND	1/2/2022	11/9/2022	8/5/2022	INSPTR	
GROVELAND	1/2/2022	11/6/2024	10/18/2024	INSPTR	ML5474
GROVELAND	1/2/2022	11/9/2024	10/22/2024	INSPTR	NK5685
PINECREST	1/2/2022	11/18/2024	8/1/2024	INSPTR	EC2732
PINECREST	1/2/2022	11/18/2024	8/8/2024	INSPTR	EC2732
PINECREST	1/2/2022	11/29/2024	7/30/2024	INSPTR	KB5463
PINECREST	1/2/2022	11/15/2024	10/28/2024	INSPTR	EM3528
GROVELAND	1/2/2022	11/8/2024	10/29/2024	INSPTR	NK5685
GROVELAND	1/2/2022	11/4/2024	9/16/2024	INSPTR	ML5474
GROVELAND	1/2/2022	11/3/2024	9/3/2024	INSPTR	NK5685
GROVELAND	1/2/2022	11/4/2024	9/18/2024	INSPTR	ML5474
GROVELAND	1/2/2022	11/17/2024	10/1/2024	INSPTR	ML5474
GROVELAND	1/2/2022	11/16/2024	10/21/2024	INSPTR	ML5474
PINECREST	1/2/2022	11/16/2022	8/15/2022	INSPTR	
PINECREST	1/2/2022	11/16/2024	10/28/2024	INSPTR	EM3528
PINECREST	1/2/2022	11/19/2024	10/31/2024	INSPTR	DG3424
PINECREST	1/2/2022	11/10/2024	10/23/2024	INSPTR	DS6453
GROVELAND	1/2/2022	11/4/2024	9/18/2024	INSPTR	ML5474
GROVELAND	1/2/2022	11/5/2022	8/5/2022	INSPTR	
GROVELAND	1/2/2022	11/9/2024	8/19/2024	INSPTR	NK5685

GROVELAND	1/2/2022	11/9/2024	8/19/2024	INSPTR	NK5685
GROVELAND	1/2/2022	11/17/2024	10/1/2024	INSPTR	ML5474
GROVELAND	1/2/2022	11/16/2024	6/7/2024	INSPTR	JM687J
GROVELAND	1/2/2022	11/16/2024	10/15/2024	INSPTR	RB2924
PINECREST	1/2/2022	11/10/2024	10/25/2024	INSPTR	DG3424
PINECREST	1/2/2022	5/10/2022	6/21/2022	INSPTR	
PINECREST	1/2/2022	11/11/2024	10/25/2024	INSPTR	RS8367
PINECREST	1/2/2022	5/11/2022	6/21/2022	INSPTR	
GROVELAND	1/2/2022	11/10/2022	2/26/2022	INSPTR	ML5474
GROVELAND	1/2/2022	11/10/2022	2/26/2022	INSPTR	ML5474
PINECREST	1/2/2022	11/11/2024	10/31/2024	INSPTR	ZO2856
PINECREST	1/2/2022	11/9/2024	10/10/2024	INSPTR	EC2732
PINECREST	1/2/2022	11/9/2024	10/10/2024	INSPTR	EC2732
PINECREST	1/2/2022	11/9/2024	8/9/2024	INSPTR	EC2732
PINECREST	1/2/2022	11/12/2024	8/9/2024	INSPTR	EC2732
PINECREST	1/2/2022	11/12/2024	10/31/2024	INSPTR	FR2146
GROVELAND	1/2/2022	11/11/2024	6/7/2024	INSPTR	JM687J
GROVELAND	1/2/2022	11/11/2024	6/7/2024	INSPTR	UV639W
GROVELAND	1/2/2022	11/11/2024	6/7/2024	INSPTR	JM687J
GROVELAND	1/2/2022	11/11/2024	6/7/2024	INSPTR	ET975M
GROVELAND	1/2/2022	11/11/2024	6/7/2024	INSPTR	RS556S

GROVELAND	1/2/2022	11/9/2024	6/7/2024	INSPTR	JX5547
GROVELAND	1/2/2022	11/3/2024	9/4/2024	INSPTR	NK5685
GROVELAND	1/2/2022	11/3/2024	7/30/2024	INSPTR	NK5685
GROVELAND	1/2/2022	11/3/2024	9/3/2024	INSPTR	NK5685
GROVELAND	1/2/2022	11/11/2024	6/7/2024	INSPTR	IS3295
GROVELAND	1/2/2022	11/11/2024	6/7/2024	INSPTR	UV639W
GROVELAND	1/2/2022	11/11/2024	6/7/2024	INSPTR	IS3295
GROVELAND	1/2/2022	11/3/2024	9/3/2024	INSPTR	NK5685
GROVELAND	1/2/2022	11/4/2022	8/12/2022	INSPTR	
GROVELAND	1/2/2022	11/4/2024	9/5/2024	INSPTR	ML5474
PINECREST	1/2/2022	11/15/2024	10/22/2024	INSPTR	AD2932
PINECREST	1/2/2022	11/15/2024	10/22/2024	INSPTR	AD2932
PINECREST	1/2/2022	11/16/2024	10/30/2024	INSPTR	EM3528
PINECREST	1/2/2022	11/19/2024	10/31/2024	INSPTR	DG3424
PINECREST	1/2/2022	11/19/2024	10/31/2024	INSPTR	DG3424
PINECREST	1/2/2022	11/19/2024	11/1/2024	INSPTR	DS6453
PINECREST	1/2/2022	11/19/2024	11/1/2024	INSPTR	RT1486
PINECREST	1/2/2022	11/19/2024	11/1/2024	INSPTR	DS6453
PINECREST	1/2/2022	11/19/2024	10/31/2024	INSPTR	DG3424
PINECREST	1/2/2022	11/19/2024	11/1/2024	INSPTR	JG9626
GROVELAND	1/2/2022	11/4/2024	9/5/2024	INSPTR	NK5685
GROVELAND	1/2/2022	11/5/2024	9/10/2024	INSPTR	ML5474

GROVELAND	1/2/2022	11/5/2024	10/2/2024	INSPTR	NK5685
GROVELAND	1/2/2022	11/5/2024	10/18/2024	INSPTR	ML5474
GROVELAND	1/2/2022	11/5/2024	10/2/2024	INSPTR	NK5685
GROVELAND	1/2/2022	11/5/2024	8/30/2024	INSPTR	NK5685
GROVELAND	1/2/2022	11/5/2024	8/30/2024	INSPTR	NK5685
GROVELAND	1/2/2022	11/5/2024	10/18/2024	INSPTR	ML5474
PINECREST	1/2/2022	11/19/2024	10/31/2024	INSPTR	RT1486
PINECREST	1/2/2022	11/19/2024	10/31/2024	INSPTR	RT1486
PINECREST	1/2/2022	11/19/2024	10/31/2024	INSPTR	RT1486
PINECREST	1/2/2022	11/20/2024	11/1/2024	INSPTR	DS6453
PINECREST	1/2/2022	11/20/2024	10/31/2024	INSPTR	RT1486
PINECREST	1/2/2022	11/20/2024	10/31/2024	INSPTR	KW5925
PINECREST	1/2/2022	11/20/2024	10/31/2024	INSPTR	RT1486
GROVELAND	1/2/2022	11/5/2024	8/30/2024	INSPTR	NK5685
GROVELAND	1/2/2022	11/5/2022	8/5/2022	INSPTR	
GROVELAND	1/2/2022	11/5/2024	10/2/2024	INSPTR	ML5474
GROVELAND	1/2/2022	11/5/2024	10/18/2024	INSPTR	ML5474
GROVELAND	1/2/2022	11/5/2024	9/21/2024	INSPTR	ML5474
GROVELAND	1/2/2022	11/6/2024	9/3/2024	INSPTR	ML5474
GROVELAND	1/2/2022	11/6/2024	9/3/2024	INSPTR	ML5474
PINECREST	1/2/2022	11/20/2024	11/1/2024	INSPTR	RT1486
PINECREST	1/2/2022	11/20/2024	10/31/2024	INSPTR	AD2932

PINECREST	1/2/2022	11/30/2024	11/1/2024	INSPTR	RT1486
PINECREST	1/2/2022	11/30/2024	10/31/2024	INSPTR	ZO2856
PINECREST	1/2/2022	11/30/2024	8/13/2024	INSPTR	DG3424
PINECREST	1/2/2022	11/20/2024	10/31/2024	INSPTR	ZO2856
PINECREST	1/2/2022	11/20/2024	7/23/2024	INSPTR	AD2932
GROVELAND	1/2/2022	11/6/2022	8/5/2022	INSPTR	
GROVELAND	1/2/2022	11/6/2024	9/4/2024	INSPTR	ML5474
GROVELAND	1/2/2022	11/8/2024	10/21/2024	INSPTR	ML5474
GROVELAND	1/2/2022	11/8/2024	10/21/2024	INSPTR	ML5474
GROVELAND	1/2/2022	11/8/2022	8/5/2022	INSPTR	
PINECREST	1/2/2022	11/29/2024	11/1/2024	INSPTR	RT1486
PINECREST	1/2/2022	11/30/2024	10/31/2024	INSPTR	ZO2856
PINECREST	1/2/2022	11/30/2024	10/31/2024	INSPTR	AD2932
PINECREST	1/2/2022	11/30/2024	10/31/2024	INSPTR	KW5925
PINECREST	1/2/2022	11/30/2024	9/16/2024	INSPTR	DG3175
PINECREST	1/2/2022	11/30/2024	10/31/2024	INSPTR	KW5925
PINECREST	1/2/2022	11/18/2024	10/31/2024	INSPTR	AD2932
PINECREST	1/2/2022	11/18/2024	10/31/2024	INSPTR	AD2932
PINECREST	1/2/2022	11/16/2024	10/28/2024	INSPTR	EM3528
GROVELAND	1/2/2022	11/8/2024	10/28/2024	INSPTR	JB1568
GROVELAND	1/2/2022	11/8/2024	10/2/2024	INSPTR	ML5474
GROVELAND	1/2/2022	11/8/2022	8/5/2022	INSPTR	

GROVELAND	1/2/2022	11/8/2022	8/12/2022	INSPTR	
PINECREST	1/2/2022	11/17/2024	11/1/2024	INSPTR	DS6453
PINECREST	1/2/2022	11/17/2024	10/31/2024	INSPTR	FR2146
PINECREST	1/2/2022	11/17/2024	11/1/2024	INSPTR	DS6453
PINECREST	1/2/2022	11/17/2024	10/31/2024	INSPTR	DG3424
PINECREST	1/2/2022	11/17/2024	10/31/2024	INSPTR	FR2146
PINECREST	1/2/2022	11/17/2024	10/31/2024	INSPTR	FR2146
PINECREST	1/2/2022	11/17/2024	10/31/2024	INSPTR	FR2146
PINECREST	1/2/2022	11/17/2024	10/23/2024	INSPTR	EC2732
PINECREST	1/2/2022	11/17/2024	10/23/2024	INSPTR	EC2732
PINECREST	1/2/2022	11/15/2024	7/16/2024	INSPTR	NK5685
LAGRANGE/D PEDRO	1/8/2022	12/9/2024	2/20/2024	INSPTR	DG3424
LAGRANGE/D PEDRO	1/8/2022	12/7/2024	4/12/2024	INSPTR	KW5925
LAGRANGE/D PEDRO	1/8/2022	12/7/2024	12/18/2023	INSPTR	DG3424
LAGRANGE/D PEDRO	1/8/2022	12/2/2024	4/12/2024	INSPTR	DG3424
LAGRANGE/D PEDRO	1/8/2022	12/2/2024	4/15/2024	INSPTR	EM3528
LAGRANGE/D PEDRO	1/8/2022	12/2/2024	12/7/2023	INSPTR	BS2864
LAGRANGE/D PEDRO	1/8/2022	12/3/2024	12/7/2023	INSPTR	BS2864
LAGRANGE/D PEDRO	1/8/2022	12/3/2024	4/26/2024	INSPTR	KW5925
LAGRANGE/D PEDRO	1/8/2022	12/3/2024	5/3/2024	INSPTR	MJ1746
LAGRANGE/D PEDRO	1/8/2022	12/1/2024	12/1/2023	INSPTR	BS2864
LAGRANGE/D PEDRO	1/8/2022	12/1/2024	5/3/2024	INSPTR	MJ1746

LAGRANGE/D PEDRO	1/8/2022	12/5/2022	2/11/2022	INSPTR	JA2756
LAGRANGE/D PEDRO	1/8/2022	12/7/2024	5/3/2024	INSPTR	CH8326
LAGRANGE/D PEDRO	1/8/2022	12/8/2024	5/3/2024	INSPTR	CH8326
LAGRANGE/D PEDRO	1/8/2022	12/6/2026	7/17/2023	INSPTR	
LAGRANGE/D PEDRO	1/8/2022	12/6/2026	7/17/2023	INSPTR	
LAGRANGE/D PEDRO	1/8/2022	12/10/2024	5/8/2024	INSPTR	DG3424
LAGRANGE/D PEDRO	1/8/2022	12/9/2024	5/7/2024	INSPTR	DG3424
LAGRANGE/D PEDRO	1/8/2022	12/10/2026	7/17/2023	INSPTR	
LAGRANGE/D PEDRO	1/8/2022	12/9/2026	7/17/2023	INSPTR	
LAGRANGE/D PEDRO	1/8/2022	12/9/2026	3/28/2023	INSPTR	
LAGRANGE/D PEDRO	1/8/2022	12/9/2024	5/2/2024	INSPTR	JB7519
LAGRANGE/D PEDRO	1/8/2022	12/10/2024	5/8/2024	INSPTR	CH8326
LAGRANGE/D PEDRO	1/8/2022	12/1/2026	7/17/2023	INSPTR	
LAGRANGE/D PEDRO	1/8/2022	12/1/2026	7/17/2023	INSPTR	
LAGRANGE/D PEDRO	1/8/2022	12/1/2024	12/6/2023	INSPTR	DG3424
LAGRANGE/D PEDRO	1/8/2022	12/1/2026	7/17/2023	INSPTR	
LAGRANGE/D PEDRO	1/8/2022	12/1/2024	12/6/2023	INSPTR	DG3424
LAGRANGE/D PEDRO	1/8/2022	12/1/2026	7/17/2023	INSPTR	
LAGRANGE/D PEDRO	1/8/2022	12/2/2022	4/17/2024	INSPTR	
LAGRANGE/D PEDRO	1/8/2022	12/7/2024	5/8/2024	INSPTR	DG3424
LAGRANGE/D PEDRO	1/8/2022	12/2/2026	7/10/2023	INSPTR	
LAGRANGE/D PEDRO	1/8/2022	12/2/2024	7/10/2023	INSPTR	

LAGRANGE/D PEDRO	1/8/2022	12/2/2024	5/8/2024	INSPTR	DA1367
LAGRANGE/D PEDRO	1/8/2022	12/3/2024	12/7/2023	INSPTR	DG3424
LAGRANGE/D PEDRO	1/8/2022	12/3/2022	2/7/2022	INSPTR	DG3424
LAGRANGE/D PEDRO	1/8/2022	12/3/2024	12/7/2023	INSPTR	DG3424
LAGRANGE/D PEDRO	1/8/2022	12/4/2026	7/10/2023	INSPTR	
YOSEMITE MAIN	1/8/2022	11/29/2022	5/24/2023	INSPTR	CH2861
YOSEMITE MAIN	1/8/2022	11/29/2024	12/30/2022	INSPTR	CH2861
LAGRANGE/D PEDRO	1/8/2022	12/9/2026	8/2/2023	INSPTR	
LAGRANGE/D PEDRO	1/8/2022	12/4/2024	5/9/2024	INSPTR	CH8326
LAGRANGE/D PEDRO	1/8/2022	12/8/2026	7/19/2023	INSPTR	
LAGRANGE/D PEDRO	1/8/2022	12/8/2026	7/19/2023	INSPTR	
LAGRANGE/D PEDRO	1/8/2022	12/9/2026	8/2/2023	INSPTR	
LAGRANGE/D PEDRO	1/8/2022	12/9/2026	8/11/2023	INSPTR	
LAGRANGE/D PEDRO	1/8/2022	12/8/2026	4/10/2023	INSPTR	
LAGRANGE/D PEDRO	1/8/2022	12/8/2026	4/26/2023	INSPTR	
LAGRANGE/D PEDRO	1/8/2022	12/8/2026	7/19/2023	INSPTR	
LAGRANGE/D PEDRO	1/8/2022	12/7/2022	8/11/2023	INSPTR	
LAGRANGE/D PEDRO	1/8/2022	12/13/2026	4/6/2023	INSPTR	
LAGRANGE/D PEDRO	1/8/2022	12/13/2026	4/6/2023	INSPTR	
LAGRANGE/D PEDRO	1/8/2022	12/13/2024	5/9/2024	INSPTR	CS1623
LAGRANGE/D PEDRO	1/8/2022	12/13/2026	4/6/2023	INSPTR	
LAGRANGE/D PEDRO	1/8/2022	12/13/2026	4/10/2023	INSPTR	

LAGRANGE/D PEDRO	1/8/2022	12/13/2022	4/26/2023	INSPTR	
LAGRANGE/D PEDRO	1/8/2022	12/13/2026	4/3/2023	INSPTR	
LAGRANGE/D PEDRO	1/8/2022	12/14/2022	2/24/2022	INSPTR	DG3424
LAGRANGE/D PEDRO	1/8/2022	12/14/2022	2/11/2022	INSPTR	JA2756
LAGRANGE/D PEDRO	1/8/2022	12/14/2026	2/13/2023	INSPTR	
LAGRANGE/D PEDRO	1/8/2022	12/14/2026	2/13/2023	INSPTR	
LAGRANGE/D PEDRO	1/8/2022	12/14/2024	4/25/2024	INSPTR	RB2924
LAGRANGE/D PEDRO	1/8/2022	12/14/2024	5/2/2024	INSPTR	DS6453
LAGRANGE/D PEDRO	1/8/2022	12/14/2026	2/13/2023	INSPTR	
LAGRANGE/D PEDRO	1/8/2022	12/14/2026	4/26/2023	INSPTR	
LAGRANGE/D PEDRO	1/8/2022	12/15/2026	7/17/2023	INSPTR	
LAGRANGE/D PEDRO	1/8/2022	12/15/2024	3/21/2024	INSPTR	DG3424
LAGRANGE/D PEDRO	1/8/2022	12/15/2026	4/12/2023	INSPTR	RD2824
LAGRANGE/D PEDRO	1/8/2022	12/3/2022	2/15/2022	INSPTR	DG3424
LAGRANGE/D PEDRO	1/8/2022	12/14/2026	7/17/2023	INSPTR	
LAGRANGE/D PEDRO	1/8/2022	12/2/2024	5/9/2024	INSPTR	DG3424
LAGRANGE/D PEDRO	1/8/2022	12/14/2026	2/13/2023	INSPTR	
LAGRANGE/D PEDRO	1/8/2022	12/14/2026	8/11/2023	INSPTR	
LAGRANGE/D PEDRO	1/8/2022	12/14/2026	3/28/2023	INSPTR	
LAGRANGE/D PEDRO	1/8/2022	12/14/2026	3/28/2023	INSPTR	
LAGRANGE/D PEDRO	1/8/2022	12/14/2026	1/3/2023	INSPTR	
LAGRANGE/D PEDRO	1/8/2022	12/14/2026	4/26/2023	INSPTR	

LAGRANGE/D PEDRO	1/8/2022	12/14/2026	2/13/2023	INSPTR	
LAGRANGE/D PEDRO	1/8/2022	12/15/2026	4/11/2023	INSPTR	
LAGRANGE/D PEDRO	1/8/2022	12/16/2026	12/16/2022	INSPTR	AM4268
LAGRANGE/D PEDRO	1/8/2022	12/16/2026	4/17/2024	INSPTR	
LAGRANGE/D PEDRO	1/8/2022	12/16/2026	12/13/2022	INSPTR	AM4268
LAGRANGE/D PEDRO	1/8/2022	12/15/2024	4/25/2024	INSPTR	DG3424
LAGRANGE/D PEDRO	1/8/2022	12/11/2026	4/11/2023	INSPTR	
LAGRANGE/D PEDRO	1/8/2022	12/8/2026	12/13/2022	INSPTR	JH4935
LAGRANGE/D PEDRO	1/8/2022	12/8/2026	2/13/2023	INSPTR	
LAGRANGE/D PEDRO	1/8/2022	12/8/2026	2/13/2023	INSPTR	
LAGRANGE/D PEDRO	1/8/2022	12/2/2024	4/2/2024	INSPTR	BS2864
LAGRANGE/D PEDRO	1/8/2022	12/1/2026	4/18/2023	INSPTR	
LAGRANGE/D PEDRO	1/8/2022	12/1/2026	4/18/2023	INSPTR	
LAGRANGE/D PEDRO	1/8/2022	12/1/2024	12/1/2023	INSPTR	MJ1746
LAGRANGE/D PEDRO	1/8/2022	12/2/2024	12/15/2023	INSPTR	LH5743
LAGRANGE/D PEDRO	1/8/2022	11/30/2024	12/13/2022	INSPTR	CT4872
LAGRANGE/D PEDRO	1/8/2022	11/30/2026	12/29/2022	INSPTR	
LAGRANGE/D PEDRO	1/8/2022	11/30/2026	4/4/2023	INSPTR	
LAGRANGE/D PEDRO	1/8/2022	12/16/2026	4/4/2023	INSPTR	
LAGRANGE/D PEDRO	1/8/2022	12/16/2026	12/29/2022	INSPTR	
WAWONA	1/8/2022	12/2/2024	4/8/2024	INSPTR	CH2861
LAGRANGE/D PEDRO	1/8/2022	11/30/2022	4/4/2023	INSPTR	

LAGRANGE/D PEDRO	1/8/2022	12/14/2024	12/19/2023	INSPTR	DA1367
LAGRANGE/D PEDRO	1/8/2022	12/10/2024	4/18/2024	INSPTR	CS1623
LAGRANGE/D PEDRO	1/8/2022	12/10/2024	5/10/2024	INSPTR	JG9626
LAGRANGE/D PEDRO	1/8/2022	12/14/2026	12/29/2022	INSPTR	
LAGRANGE/D PEDRO	1/8/2022	11/11/2024	11/28/2023	INSPTR	DG3175
LAGRANGE/D PEDRO	1/8/2022	11/11/2026	12/29/2022	INSPTR	
LAGRANGE/D PEDRO	1/8/2022	11/11/2024	2/21/2023	INSPTR	
LAGRANGE/D PEDRO	1/8/2022	11/29/2022	10/31/2022	INSPTR	JA2891
LAGRANGE/D PEDRO	1/8/2022	12/6/2026	12/29/2022	INSPTR	
LAGRANGE/D PEDRO	1/8/2022	12/6/2026	12/29/2022	INSPTR	
LAGRANGE/D PEDRO	1/8/2022	12/6/2024	3/27/2024	INSPTR	MJ1746
LAGRANGE/D PEDRO	1/8/2022	12/6/2026	12/29/2022	INSPTR	
LAGRANGE/D PEDRO	1/8/2022	12/8/2024	1/26/2024	INSPTR	TJ4856
LAGRANGE/D PEDRO	1/8/2022	12/8/2026	12/29/2022	INSPTR	
LAGRANGE/D PEDRO	1/8/2022	12/8/2026	2/21/2023	INSPTR	
LAGRANGE/D PEDRO	1/8/2022	12/8/2022	1/3/2023	INSPTR	
LAGRANGE/D PEDRO	1/8/2022	12/8/2026	1/30/2023	INSPTR	
LAGRANGE/D PEDRO	1/8/2022	12/8/2022	12/29/2022	INSPTR	
LAGRANGE/D PEDRO	1/8/2022	12/8/2026	12/29/2022	INSPTR	
LAGRANGE/D PEDRO	1/8/2022	12/8/2026	10/28/2022	INSPTR	JH4935
LAGRANGE/D PEDRO	1/8/2022	12/9/2024	3/27/2024	INSPTR	EM3528
LAGRANGE/D PEDRO	1/8/2022	12/6/2026	10/27/2022	INSPTR	CT4872

LAGRANGE/D PEDRO	1/8/2022	12/6/2026	2/14/2023	INSPTR	
LAGRANGE/D PEDRO	1/8/2022	12/6/2024	3/21/2024	INSPTR	BS2864
LAGRANGE/D PEDRO	1/8/2022	12/6/2026	10/28/2022	INSPTR	CT4872
LAGRANGE/D PEDRO	1/8/2022	12/6/2026	2/21/2023	INSPTR	
LAGRANGE/D PEDRO	1/8/2022	12/6/2026	2/14/2023	INSPTR	
LAGRANGE/D PEDRO	1/8/2022	12/9/2024	3/19/2024	INSPTR	FR2146
LAGRANGE/D PEDRO	1/8/2022	12/9/2024	12/19/2023	INSPTR	DG3424
LAGRANGE/D PEDRO	1/8/2022	12/9/2026	10/28/2022	INSPTR	JM9856
LAGRANGE/D PEDRO	1/8/2022	12/9/2026	12/29/2022	INSPTR	
LAGRANGE/D PEDRO	1/8/2022	12/9/2026	10/27/2022	INSPTR	RD2824
COULTERVILLE	1/10/2022	12/2/2024	9/23/2024	INSPTR	ML5474
COULTERVILLE	1/10/2022	12/1/2024	8/28/2024	INSPTR	ML5474
COULTERVILLE	1/10/2022	11/30/2024	9/23/2024	INSPTR	NK5685
COULTERVILLE	1/10/2022	12/1/2024	8/28/2024	INSPTR	ML5474
COULTERVILLE	1/10/2022	11/30/2024	9/9/2024	INSPTR	RS8367
COULTERVILLE	1/10/2022	12/1/2024	9/17/2024	INSPTR	NK5685
EL PORTAL	1/10/2022	12/3/2024	10/28/2024	INSPTR	EA2979
EL PORTAL	1/10/2022	12/1/2024	10/28/2024	INSPTR	EA2979
COULTERVILLE	1/10/2022	12/7/2024	6/21/2024	INSPTR	NK5685
COULTERVILLE	1/10/2022	12/1/2024	9/17/2024	INSPTR	NK5685

COULTERVILLE	1/10/2022	12/2/2024	8/23/2024	INSPTR	NK5685
EL PORTAL	1/10/2022	12/3/2024	10/28/2024	INSPTR	EA2979
COULTERVILLE	1/10/2022	12/2/2026	5/24/2022	INSPTR	
COULTERVILLE	1/10/2022	12/2/2026	5/24/2022	INSPTR	
COULTERVILLE	1/10/2022	12/10/2026	5/24/2022	INSPTR	
COULTERVILLE	1/10/2022	12/2/2026	5/24/2022	INSPTR	
COULTERVILLE	1/10/2022	12/2/2026	5/24/2022	INSPTR	
COULTERVILLE	1/10/2022	12/2/2026	5/24/2022	INSPTR	
COULTERVILLE	1/10/2022	12/2/2026	5/24/2022	INSPTR	
COULTERVILLE	1/10/2022	12/7/2024	6/20/2024	INSPTR	NK5685
COULTERVILLE	1/10/2022	12/4/2024	9/23/2024	INSPTR	ML5474
COULTERVILLE	1/10/2022	12/3/2024	9/9/2024	INSPTR	RS8367
COULTERVILLE	1/10/2022	12/3/2024	8/28/2024	INSPTR	NK5685
COULTERVILLE	1/10/2022	12/3/2024	8/28/2024	INSPTR	NK5685
COULTERVILLE	1/10/2022	12/1/2024	9/25/2024	INSPTR	DG3424
COULTERVILLE	1/10/2022	12/2/2024	5/24/2022	INSPTR	
JAMESTOWN	1/12/2022	11/10/2022	3/2/2022	INSPTR	NK5685
JAMESTOWN	1/12/2022	11/5/2026	2/24/2023	INSPTR	
JAMESTOWN	1/12/2022	11/5/2026	2/24/2023	INSPTR	
JAMESTOWN	1/12/2022	11/17/2024	12/7/2023	INSPTR	DG3175
JAMESTOWN	1/12/2022	12/2/2026	2/24/2023	INSPTR	

JAMESTOWN	1/12/2022	11/16/2022	3/27/2022	INSPTR	NS1598
JAMESTOWN	1/12/2022	11/16/2022	3/27/2022	INSPTR	NS1598
JAMESTOWN	1/12/2022	11/6/2024	5/1/2024	INSPTR	DG3424
JAMESTOWN	1/12/2022	11/6/2024	5/1/2024	INSPTR	BS2864
JAMESTOWN	1/12/2022	11/6/2022	3/27/2022	INSPTR	JB8576
JAMESTOWN	1/12/2022	11/6/2022	3/27/2022	INSPTR	JB8576
JAMESTOWN	1/12/2022	11/6/2024	5/2/2024	INSPTR	MJ1746
JAMESTOWN	1/12/2022	11/6/2024	5/2/2024	INSPTR	MJ1746
JAMESTOWN	1/12/2022	11/6/2022	8/11/2022	INSPTR	
JAMESTOWN	1/12/2022	11/6/2024	5/1/2024	INSPTR	JB7519
JAMESTOWN	1/12/2022	11/6/2026	2/24/2023	INSPTR	
JAMESTOWN	1/12/2022	11/16/2022	7/25/2022	INSPTR	RS8367
JAMESTOWN	1/12/2022	11/16/2024	5/6/2024	INSPTR	KW5925
JAMESTOWN	1/12/2022	11/16/2022	8/29/2022	INSPTR	RN8732
JAMESTOWN	1/12/2022	11/29/2024	5/2/2024	INSPTR	BS2864
JAMESTOWN	1/12/2022	11/10/2022	10/25/2022	INSPTR	SV8697
JAMESTOWN	1/12/2022	11/6/2022	3/23/2022	INSPTR	NK5685
JAMESTOWN	1/12/2022	11/6/2022	3/22/2022	INSPTR	NS1598
JAMESTOWN	1/12/2022	11/6/2022	3/27/2022	INSPTR	NS1598
JAMESTOWN	1/12/2022	11/6/2024	5/2/2024	INSPTR	MJ1746

JAMESTOWN	1/12/2022	11/8/2022	8/4/2022	INSPTR	RN8732
JAMESTOWN	1/12/2022	11/8/2022	10/25/2022	INSPTR	PR2872
JAMESTOWN	1/12/2022	11/8/2024	5/7/2024	INSPTR	BS2864
JAMESTOWN	1/12/2022	11/8/2022	10/28/2022	INSPTR	JB8576
JAMESTOWN	1/12/2022	11/8/2022	4/27/2023	INSPTR	
JAMESTOWN	1/12/2022	11/29/2026	2/24/2023	INSPTR	
JAMESTOWN	1/12/2022	11/29/2026	2/24/2023	INSPTR	
JAMESTOWN	1/12/2022	11/29/2024	5/8/2024	INSPTR	KW5925
JAMESTOWN	1/12/2022	11/29/2024	5/8/2024	INSPTR	KW5925
JAMESTOWN	1/12/2022	11/29/2024	5/14/2024	INSPTR	KW5925
JAMESTOWN	1/12/2022	11/10/2024	5/14/2024	INSPTR	KW5925
JAMESTOWN	1/12/2022	11/10/2022	3/31/2022	INSPTR	SL9636
JAMESTOWN	1/12/2022	11/10/2022	10/31/2022	INSPTR	KW5925
JAMESTOWN	1/12/2022	11/10/2022	10/31/2022	INSPTR	RX1696
JAMESTOWN	1/12/2022	11/6/2026	2/24/2023	INSPTR	
JAMESTOWN	1/12/2022	11/6/2026	2/24/2023	INSPTR	
JAMESTOWN	1/12/2022	11/17/2026	5/12/2023	INSPTR	
JAMESTOWN	1/12/2022	11/6/2022	3/30/2022	INSPTR	NK5685
JAMESTOWN	1/12/2022	11/6/2022	3/30/2022	INSPTR	NK5685
JAMESTOWN	1/12/2022	11/3/2022	2/14/2022	INSPTR	HC3283
JAMESTOWN	1/12/2022	11/8/2024	5/15/2024	INSPTR	DS6453

JAMESTOWN	1/12/2022	11/10/2022	11/29/2022	INSPTR	JB8576
JAMESTOWN	1/12/2022	11/10/2022	11/29/2022	INSPTR	JB8576
JAMESTOWN	1/12/2022	11/10/2022	11/30/2022	INSPTR	CR1893
JAMESTOWN	1/12/2022	11/10/2024	5/14/2024	INSPTR	DG3424
JAMESTOWN	1/12/2022	11/10/2022	11/30/2022	INSPTR	CR1893
JAMESTOWN	1/12/2022	11/10/2022	11/30/2022	INSPTR	RX1696
JAMESTOWN	1/12/2022	11/10/2022	9/28/2022	INSPTR	TJ4856
JAMESTOWN	1/12/2022	12/3/2026	2/24/2023	INSPTR	
JAMESTOWN	1/12/2022	12/6/2026	2/24/2023	INSPTR	
JAMESTOWN	1/12/2022	11/3/2022	3/26/2022	INSPTR	BC8519
JAMESTOWN	1/12/2022	11/5/2024	5/15/2024	INSPTR	DS6453
JAMESTOWN	1/12/2022	11/5/2022	3/30/2022	INSPTR	SL9636
JAMESTOWN	1/12/2022	11/3/2022	3/26/2022	INSPTR	BC8519
JAMESTOWN	1/12/2022	11/9/2022	11/30/2022	INSPTR	RX1696
JAMESTOWN	1/12/2022	11/9/2022	11/30/2022	INSPTR	CS1623
JAMESTOWN	1/12/2022	11/9/2022	11/30/2022	INSPTR	CS1623
JAMESTOWN	1/12/2022	11/10/2022	2/19/2023	INSPTR	CE2563
JAMESTOWN	1/12/2022	11/10/2022	2/19/2023	INSPTR	CE2563
JAMESTOWN	1/12/2022	11/10/2022	2/17/2023	INSPTR	RX1696
JAMESTOWN	1/12/2022	11/10/2024	5/23/2024	INSPTR	RN8732
JAMESTOWN	1/12/2022	11/10/2022	2/19/2023	INSPTR	CE2563

JAMESTOWN	1/12/2022	12/1/2024	5/16/2024	INSPTR	BS2864
JAMESTOWN	1/12/2022	11/11/2024	5/23/2024	INSPTR	RN8732
JAMESTOWN	1/12/2022	11/11/2024	5/2/2024	INSPTR	BS2864
JAMESTOWN	1/12/2022	11/11/2024	5/2/2024	INSPTR	BS2864
JAMESTOWN	1/12/2022	11/11/2022	2/19/2023	INSPTR	SD9656
JAMESTOWN	1/12/2022	12/1/2026	2/24/2023	INSPTR	
JAMESTOWN	1/12/2022	12/1/2024	5/6/2024	INSPTR	DG3424
JAMESTOWN	1/12/2022	12/1/2024	5/16/2024	INSPTR	BS2864
JAMESTOWN	1/12/2022	12/2/2024	5/13/2024	INSPTR	DG3424
JAMESTOWN	1/12/2022	12/2/2024	5/16/2024	INSPTR	BS2864
JAMESTOWN	1/12/2022	12/2/2026	2/24/2023	INSPTR	
JAMESTOWN	1/12/2022	11/9/2024	5/16/2024	INSPTR	MJ1746
JAMESTOWN	1/12/2022	11/9/2022	2/21/2023	INSPTR	DA1367
JAMESTOWN	1/12/2022	11/9/2024	5/16/2024	INSPTR	MJ1746
JAMESTOWN	1/12/2022	11/3/2022	8/11/2022	INSPTR	
JAMESTOWN	1/12/2022	11/3/2024	5/7/2024	INSPTR	BS2864
JAMESTOWN	1/12/2022	11/3/2026	2/24/2023	INSPTR	
JAMESTOWN	1/12/2022	11/3/2024	4/25/2024	INSPTR	CS1623
JAMESTOWN	1/12/2022	11/3/2022	3/27/2022	INSPTR	DG9898
JAMESTOWN	1/12/2022	11/3/2022	3/26/2022	INSPTR	BC8519
JAMESTOWN	1/12/2022	11/3/2022	3/27/2022	INSPTR	DG9898
JAMESTOWN	1/12/2022	11/9/2024	5/7/2024	INSPTR	CH8326

JAMESTOWN	1/12/2022	11/9/2022	2/18/2023	INSPTR	RN8732
JAMESTOWN	1/12/2022	11/9/2022	2/18/2023	INSPTR	RN8732
JAMESTOWN	1/12/2022	11/9/2022	2/18/2023	INSPTR	RN8732
JAMESTOWN	1/12/2022	11/9/2024	5/8/2024	INSPTR	BS2864
JAMESTOWN	1/12/2022	11/9/2024	5/8/2024	INSPTR	MJ1746
JAMESTOWN	1/12/2022	11/9/2022	8/11/2022	INSPTR	
JAMESTOWN	1/12/2022	11/9/2022	2/20/2023	INSPTR	RX1696
JAMESTOWN	1/12/2022	11/9/2022	4/5/2022	INSPTR	ML5474
JAMESTOWN	1/12/2022	11/9/2022	2/19/2023	INSPTR	FR2146
JAMESTOWN	1/12/2022	11/3/2022	3/26/2022	INSPTR	BC8519
JAMESTOWN	1/12/2022	11/7/2024	5/16/2024	INSPTR	MJ1746
JAMESTOWN	1/12/2022	11/7/2024	5/3/2024	INSPTR	BS2864
JAMESTOWN	1/12/2022	11/7/2022	2/13/2023	INSPTR	HC3283
JAMESTOWN	1/12/2022	11/7/2022	2/13/2023	INSPTR	HC3283
JAMESTOWN	1/12/2022	11/7/2022	2/19/2023	INSPTR	RT1486
JAMESTOWN	1/12/2022	11/7/2024	11/30/2023	INSPTR	JB7519
JAMESTOWN	1/12/2022	11/3/2022	3/27/2022	INSPTR	DG9898
JAMESTOWN	1/12/2022	11/3/2024	5/3/2024	INSPTR	BS2864
JAMESTOWN	1/12/2022	11/3/2022	3/31/2022	INSPTR	RS8367
JAMESTOWN	1/12/2022	11/3/2022	3/31/2022	INSPTR	RS8367
JAMESTOWN	1/12/2022	11/4/2022	2/16/2023	INSPTR	TJ4856

JAMESTOWN	1/12/2022	11/4/2022	10/26/2022	INSPTR	HC3283
JAMESTOWN	1/12/2022	11/4/2022	2/17/2023	INSPTR	DA1367
JAMESTOWN	1/12/2022	11/4/2022	2/13/2023	INSPTR	JB8576
JAMESTOWN	1/12/2022	11/4/2022	3/30/2022	INSPTR	ML5474
JAMESTOWN	1/12/2022	11/7/2024	11/30/2023	INSPTR	JB7519
JAMESTOWN	1/12/2022	11/17/2022	2/19/2023	INSPTR	CH8326
JAMESTOWN	1/12/2022	11/17/2022	2/19/2023	INSPTR	CH8326
JAMESTOWN	1/12/2022	11/17/2024	12/5/2023	INSPTR	DG3424
JAMESTOWN	1/12/2022	11/17/2022	2/21/2023	INSPTR	DA1367
JAMESTOWN	1/12/2022	11/17/2024	12/5/2023	INSPTR	DG3424
JAMESTOWN	1/12/2022	11/17/2024	5/8/2024	INSPTR	BS2864
JAMESTOWN	1/12/2022	11/4/2022	9/30/2022	INSPTR	TJ4856
JAMESTOWN	1/12/2022	11/4/2026	2/24/2023	INSPTR	
JAMESTOWN	1/12/2022	11/4/2022	2/13/2023	INSPTR	JB8576
JAMESTOWN	1/12/2022	11/4/2022	2/13/2023	INSPTR	JB8576
JAMESTOWN	1/12/2022	11/4/2022	2/13/2023	INSPTR	CS1623
JAMESTOWN	1/12/2022	11/4/2022	2/13/2023	INSPTR	CS1623
JAMESTOWN	1/12/2022	11/4/2022	2/14/2023	INSPTR	JB8576
JAMESTOWN	1/12/2022	11/4/2022	2/17/2023	INSPTR	RX1696
JAMESTOWN	1/12/2022	11/4/2022	2/19/2023	INSPTR	CF1419
JAMESTOWN	1/12/2022	11/4/2024	5/8/2024	INSPTR	BS2864
JAMESTOWN	1/12/2022	11/4/2022	2/19/2023	INSPTR	CF1419

JAMESTOWN	1/12/2022	11/4/2022	3/30/2022	INSPTR	ML5474
JAMESTOWN	1/12/2022	11/5/2022	2/17/2023	INSPTR	GB3598
JAMESTOWN	1/12/2022	11/16/2022	3/16/2022	INSPTR	NK5685
JAMESTOWN	1/12/2022	11/16/2024	5/8/2024	INSPTR	BS2864
JAMESTOWN	1/12/2022	11/16/2022	3/15/2022	INSPTR	NK5685
JAMESTOWN	1/12/2022	11/16/2022	3/27/2022	INSPTR	NS1598
JAMESTOWN	1/12/2022	11/16/2022	2/19/2023	INSPTR	HC3283
JAMESTOWN	1/12/2022	11/16/2022	4/8/2022	INSPTR	ML5474
JAMESTOWN	1/12/2022	11/16/2022	2/19/2023	INSPTR	FR2146
JAMESTOWN	1/12/2022	11/9/2026	2/24/2023	INSPTR	
JAMESTOWN	1/12/2022	11/9/2026	2/24/2023	INSPTR	
JAMESTOWN	1/12/2022	11/9/2026	2/24/2023	INSPTR	
JAMESTOWN	1/12/2022	11/9/2026	2/24/2023	INSPTR	
JAMESTOWN	1/12/2022	11/9/2026	2/24/2023	INSPTR	
JAMESTOWN	1/12/2022	11/9/2026	2/24/2023	INSPTR	
JAMESTOWN	1/12/2022	11/9/2026	2/24/2023	INSPTR	
JAMESTOWN	1/12/2022	11/9/2026	2/24/2023	INSPTR	
JAMESTOWN	1/12/2022	11/12/2024	5/8/2024	INSPTR	MJ1746
JAMESTOWN	1/12/2022	11/9/2026	2/24/2023	INSPTR	
JAMESTOWN	1/12/2022	11/5/2022	3/16/2022	INSPTR	BC8519
JAMESTOWN	1/12/2022	11/5/2022	2/20/2023	INSPTR	RX1696

JAMESTOWN	1/12/2022	11/5/2024	5/2/2024	INSPTR	CS1623
JAMESTOWN	1/12/2022	11/5/2022	4/1/2022	INSPTR	NK5685
JAMESTOWN	1/12/2022	11/5/2022	2/17/2023	INSPTR	LH5743
JAMESTOWN	1/12/2022	11/5/2022	2/19/2023	INSPTR	RT1486
JAMESTOWN	1/12/2022	11/5/2022	2/17/2023	INSPTR	RX1696
JAMESTOWN	1/12/2022	11/5/2024	5/2/2024	INSPTR	CS1623
JAMESTOWN	1/12/2022	11/5/2024	5/7/2024	INSPTR	MJ1746
JAMESTOWN	1/12/2022	11/5/2022	3/18/2022	INSPTR	ML5474
JAMESTOWN	1/12/2022	11/5/2026	2/24/2023	INSPTR	
JAMESTOWN	1/12/2022	11/5/2024	5/8/2024	INSPTR	MJ1746
JAMESTOWN	1/12/2022	11/5/2022	3/30/2022	INSPTR	SL9636
JAMESTOWN	1/12/2022	11/16/2024	5/8/2024	INSPTR	MJ1746
JAMESTOWN	1/12/2022	11/16/2024	5/2/2024	INSPTR	CH8326
JAMESTOWN	1/12/2022	11/16/2022	3/26/2022	INSPTR	BC8519
JAMESTOWN	1/12/2022	11/16/2022	8/11/2022	INSPTR	
JAMESTOWN	1/12/2022	11/16/2024	5/2/2024	INSPTR	CH8326
JAMESTOWN	1/12/2022	11/16/2024	12/4/2023	INSPTR	TJ4856
JAMESTOWN	1/12/2022	11/16/2024	12/1/2023	INSPTR	TJ4856
JAMESTOWN	1/12/2022	11/16/2022	2/21/2023	INSPTR	RT1486
JAMESTOWN	1/12/2022	11/16/2024	5/7/2024	INSPTR	MJ1746
JAMESTOWN	1/12/2022	11/16/2022	8/11/2023	INSPTR	RN8732

TWAIN HARTE	1/14/2022	1/14/2025	10/14/2024	DW2564	GC408J
TWAIN HARTE	1/18/2022	1/21/2022	2/1/2022	DW2564	
TWAIN HARTE	1/27/2022	1/16/2025	6/11/2024	JR2827	JX5547
SONORA	3/3/2022	11/10/2024	7/18/2024	INSPTR	RS8367
SONORA	3/3/2022	11/10/2024	7/23/2024	INSPTR	KB5463
SONORA	3/3/2022	11/10/2024	7/25/2024	INSPTR	JB1568
SONORA	3/3/2022	11/8/2024	7/29/2024	INSPTR	MM5268
SONORA	3/3/2022	11/8/2024	7/26/2024	INSPTR	EC2732
SONORA	3/3/2022	11/8/2024	7/26/2024	INSPTR	EC2732
SONORA	3/3/2022	11/7/2024	8/6/2024	INSPTR	EC2732
SONORA	3/3/2022	11/7/2024	7/29/2024	INSPTR	MM5268
SONORA	3/3/2022	11/8/2022	2/14/2023	INSPTR	GB3598
SONORA	3/3/2022	11/8/2024	7/26/2024	INSPTR	MM5268
SONORA	3/3/2022	11/8/2024	6/10/2024	INSPTR	JM687J
SONORA	3/3/2022	11/8/2024	7/26/2024	INSPTR	MM5268
SONORA	3/3/2022	10/28/2024	6/10/2024	INSPTR	DP7958
SONORA	3/3/2022	10/28/2024	6/19/2024	INSPTR	JB8576
SONORA	3/3/2022	10/29/2024	6/22/2024	INSPTR	DG3424
SONORA	3/3/2022	11/3/2024	8/7/2024	INSPTR	EC2732
SONORA	3/3/2022	11/3/2026	5/26/2022	INSPTR	
SONORA	3/3/2022	11/3/2024	8/7/2024	INSPTR	KB5463
SONORA	3/3/2022	11/3/2024	8/8/2024	INSPTR	JB1568

SONORA	3/3/2022	11/3/2024	8/12/2024	INSPTR	EC2732
SONORA	3/3/2022	11/5/2022	2/24/2023	INSPTR	
SONORA	3/3/2022	11/5/2024	8/13/2024	INSPTR	EC2732
SONORA	3/3/2022	11/5/2024	8/15/2024	INSPTR	EC2732
SONORA	3/3/2022	11/4/2024	8/9/2024	INSPTR	KB5463
SONORA	3/3/2022	11/6/2024	8/15/2024	INSPTR	EC2732
SONORA	3/3/2022	11/6/2024	10/8/2024	INSPTR	EW042G
SONORA	3/3/2022	11/9/2024	10/15/2024	INSPTR	CF1419
SONORA	3/3/2022	11/8/2024	10/2/2024	INSPTR	EM3528
SONORA	3/3/2022	11/9/2024	10/2/2024	INSPTR	DG3424
SONORA	3/3/2022	11/9/2024	10/9/2024	INSPTR	EC2732
SONORA	3/3/2022	11/9/2024	10/9/2024	INSPTR	EC2732
SONORA	3/3/2022	11/9/2024	10/9/2024	INSPTR	DG3424
SONORA	3/3/2022	11/9/2024	8/8/2024	INSPTR	BS2864
SONORA	3/3/2022	11/9/2024	10/20/2024	INSPTR	TB3178
SONORA	3/3/2022	11/8/2024	10/11/2024	INSPTR	CH8326
SONORA	3/3/2022	11/9/2024	8/8/2024	INSPTR	BS2864
SONORA	3/3/2022	11/9/2024	10/8/2024	INSPTR	EW042G
SONORA	3/3/2022	10/30/2024	8/16/2024	INSPTR	CE2563
SONORA	3/3/2022	10/30/2022	7/19/2022	INSPTR	
SONORA	3/3/2022	10/30/2024	8/23/2024	INSPTR	RT1486
SONORA	3/3/2022	10/30/2024	8/21/2024	INSPTR	CE2563

SONORA	3/3/2022	10/30/2022	7/19/2022	INSPTR	
SONORA	3/3/2022	11/3/2024	9/26/2024	INSPTR	DG3424
SONORA	3/3/2022	11/4/2024	8/16/2024	INSPTR	CH8326
SONORA	3/3/2022	11/4/2024	8/16/2024	INSPTR	CH8326
SONORA	3/3/2022	11/4/2024	6/6/2024	INSPTR	AG636B
SONORA	3/3/2022	11/4/2024	8/16/2024	INSPTR	CH8326
SONORA	3/3/2022	11/4/2024	9/18/2024	INSPTR	DG3424
SONORA	3/3/2022	11/4/2024	9/18/2024	INSPTR	DG3424
SONORA	3/3/2022	11/4/2024	9/18/2024	INSPTR	DG3424
SONORA	3/3/2022	11/4/2024	6/6/2024	INSPTR	AG636B
SONORA	3/3/2022	11/4/2024	9/20/2024	INSPTR	DG3424
SONORA	3/3/2022	11/6/2024	10/1/2024	INSPTR	CH8326
SONORA	3/3/2022	11/6/2024	9/23/2024	INSPTR	KW5925
SONORA	3/3/2022	11/6/2024	10/1/2024	INSPTR	CH8326
SONORA	3/3/2022	11/6/2024	10/1/2024	INSPTR	CH8326
SONORA	3/3/2022	11/6/2024	10/3/2024	INSPTR	JB8576
SONORA	3/3/2022	11/6/2024	10/8/2024	INSPTR	EW042G
SONORA	3/3/2022	11/6/2024	9/23/2024	INSPTR	KW5925
SONORA	3/3/2022	11/8/2024	9/17/2024	INSPTR	MJ1746
SONORA	3/3/2022	11/10/2024	8/14/2024	INSPTR	KB5463
SONORA	3/3/2022	11/10/2024	10/7/2024	INSPTR	KW5925

SONORA	3/3/2022	5/10/2022	2/24/2023	INSPTR	
SONORA	3/3/2022	11/10/2024	10/18/2024	INSPTR	EC2732
SONORA	3/3/2022	11/9/2024	10/21/2024	INSPTR	KW5925
SONORA	3/3/2022	10/30/2024	8/21/2024	INSPTR	RT1486
SONORA	3/3/2022	10/30/2024	8/21/2024	INSPTR	BS2864
SONORA	3/3/2022	10/30/2024	8/7/2024	INSPTR	BS2864
SONORA	3/3/2022	10/30/2024	8/16/2024	INSPTR	CE2563
SONORA	3/3/2022	10/30/2024	8/16/2024	INSPTR	CE2563
SONORA	3/3/2022	11/3/2024	9/17/2024	INSPTR	JB8576
SONORA	3/3/2022	11/3/2024	9/17/2024	INSPTR	JB8576
SONORA	3/3/2022	11/3/2024	9/16/2024	INSPTR	TJ4856
SONORA	3/3/2022	11/3/2024	9/17/2024	INSPTR	JB8576
SONORA	3/3/2022	11/4/2022	2/14/2023	INSPTR	AL1824
SONORA	3/3/2022	11/8/2024	10/1/2024	INSPTR	EM3528
SONORA	3/3/2022	11/8/2024	10/18/2024	INSPTR	DG3424
SONORA	3/3/2022	11/8/2024	8/14/2024	INSPTR	SD9656
SONORA	3/3/2022	11/8/2024	10/16/2024	INSPTR	CF1419
SONORA	3/3/2022	11/1/2024	7/25/2024	INSPTR	BS2864
SONORA	3/3/2022	11/1/2024	9/16/2024	INSPTR	RN8732
SONORA	3/3/2022	11/1/2024	8/5/2024	INSPTR	MJ1746
SONORA	3/3/2022	11/1/2024	9/9/2024	INSPTR	DG3424
SONORA	3/3/2022	11/1/2022	6/30/2022	INSPTR	

SONORA	3/3/2022	11/1/2024	11/1/2023	INSPTR	RN8732
SONORA	3/3/2022	11/1/2024	9/16/2024	INSPTR	RN8732
SONORA	3/3/2022	11/1/2022	6/30/2022	INSPTR	
SONORA	3/3/2022	11/2/2024	7/23/2024	INSPTR	EM3528
SONORA	3/3/2022	11/2/2024	7/23/2024	INSPTR	EM3528
SONORA	3/3/2022	11/2/2024	7/23/2024	INSPTR	EM3528
SONORA	3/3/2022	11/2/2024	7/23/2024	INSPTR	EM3528
SONORA	3/3/2022	11/2/2024	9/20/2024	INSPTR	RN8732
SONORA	3/3/2022	11/2/2022	7/26/2022	INSPTR	
SONORA	3/3/2022	11/3/2022	7/26/2022	INSPTR	
SONORA	3/3/2022	11/3/2024	9/26/2024	INSPTR	DG3424
SONORA	3/3/2022	11/4/2024	9/30/2024	INSPTR	CH8326
SONORA	3/3/2022	11/4/2024	9/24/2024	INSPTR	GB3598
SONORA	3/3/2022	11/4/2024	9/20/2024	INSPTR	DG3424
SONORA	3/3/2022	11/4/2024	9/30/2024	INSPTR	EM3528
SONORA	3/3/2022	11/4/2024	9/24/2024	INSPTR	GB3598
SONORA	3/3/2022	11/4/2022	2/24/2023	INSPTR	
SONORA	3/3/2022	11/4/2024	9/18/2024	INSPTR	RN8732
SONORA	3/3/2022	11/4/2024	9/20/2024	INSPTR	DG3424
SONORA	3/3/2022	11/4/2024	9/18/2024	INSPTR	RN8732
SONORA	3/3/2022	11/8/2024	10/15/2024	INSPTR	GS3625
SONORA	3/3/2022	11/8/2022	7/26/2022	INSPTR	

SONORA	3/3/2022	11/8/2024	9/17/2024	INSPTR	RB2924
SONORA	3/3/2022	11/8/2024	8/14/2024	INSPTR	SD9656
SONORA	3/3/2022	11/8/2024	9/17/2024	INSPTR	RB2924
SONORA	3/3/2022	11/8/2024	8/14/2024	INSPTR	SD9656
SONORA	3/3/2022	11/8/2024	10/16/2024	INSPTR	RS8367
SONORA	3/3/2022	11/1/2024	9/16/2024	INSPTR	RN8732
SONORA	3/3/2022	11/1/2024	8/5/2024	INSPTR	MJ1746
SONORA	3/3/2022	11/1/2024	9/16/2024	INSPTR	RN8732
SONORA	3/3/2022	11/1/2024	9/16/2024	INSPTR	DS6453
SONORA	3/3/2022	11/1/2024	7/25/2024	INSPTR	BS2864
SONORA	3/3/2022	11/1/2024	9/16/2024	INSPTR	DS6453
SONORA	3/3/2022	11/1/2024	9/9/2024	INSPTR	DG3424
SONORA	3/3/2022	11/2/2024	9/13/2024	INSPTR	RS8367
SONORA	3/3/2022	11/2/2024	9/13/2024	INSPTR	RS8367
SONORA	3/3/2022	11/2/2024	7/31/2024	INSPTR	MJ1746
SONORA	3/3/2022	11/2/2024	9/13/2024	INSPTR	RS8367
SONORA	3/3/2022	11/3/2022	7/26/2022	INSPTR	
SONORA	3/3/2022	11/3/2024	9/26/2024	INSPTR	JB8576
SONORA	3/3/2022	11/3/2024	9/26/2024	INSPTR	JB8576
SONORA	3/3/2022	11/3/2024	9/26/2024	INSPTR	JB8576
SONORA	3/3/2022	11/3/2022	2/24/2023	INSPTR	
SONORA	3/3/2022	11/4/2024	9/24/2024	INSPTR	GB3598

SONORA	3/3/2022	11/4/2024	9/30/2024	INSPTR	EM3528
SONORA	3/3/2022	11/4/2024	9/25/2024	INSPTR	GB3598
SONORA	3/3/2022	11/4/2024	9/26/2024	INSPTR	KW5925
SONORA	3/3/2022	11/4/2024	6/6/2024	INSPTR	JM687J
SONORA	3/3/2022	11/4/2024	8/8/2024	INSPTR	DG3424
SONORA	3/3/2022	11/8/2024	10/1/2024	INSPTR	EM3528
SONORA	3/3/2022	11/8/2024	10/16/2024	INSPTR	DG3424
SONORA	3/3/2022	11/8/2024	10/1/2024	INSPTR	EM3528
SONORA	3/3/2022	5/10/2022	6/21/2022	INSPTR	
SONORA	3/3/2022	11/1/2024	9/18/2024	INSPTR	DA1367
SONORA	3/3/2022	11/1/2024	8/5/2024	INSPTR	MJ1746
SONORA	3/3/2022	11/1/2022	2/23/2023	INSPTR	
SONORA	3/3/2022	11/1/2024	9/19/2024	INSPTR	BS2864
SONORA	3/3/2022	11/1/2024	9/12/2024	INSPTR	AD2932
SONORA	3/3/2022	11/2/2024	8/15/2024	INSPTR	DG3424
SONORA	3/3/2022	11/1/2024	9/12/2024	INSPTR	AD2932
SONORA	3/3/2022	11/2/2024	9/16/2024	INSPTR	DS6453
SONORA	3/3/2022	11/2/2024	9/26/2024	INSPTR	GB3598
SONORA	3/3/2022	11/2/2024	9/13/2024	INSPTR	DA1367
SONORA	3/3/2022	11/2/2024	9/13/2024	INSPTR	DA1367
SONORA	3/3/2022	11/4/2024	9/18/2024	INSPTR	DS6453

SONORA	3/3/2022	11/4/2024	8/8/2024	INSPTR	DG3424
SONORA	3/3/2022	11/4/2024	9/26/2024	INSPTR	KW5925
SONORA	3/3/2022	11/4/2024	9/6/2024	INSPTR	TJ4856
SONORA	3/3/2022	11/4/2024	9/16/2024	INSPTR	TJ4856
SONORA	3/3/2022	11/10/2024	10/15/2024	INSPTR	GS3625
SONORA	3/3/2022	11/6/2024	9/23/2024	INSPTR	KW5925
SONORA	3/3/2022	11/6/2024	10/8/2024	INSPTR	IS3295
SONORA	3/3/2022	11/6/2024	10/1/2024	INSPTR	CH8326
SONORA	3/3/2022	11/6/2024	9/17/2024	INSPTR	TJ4856
SONORA	3/3/2022	11/6/2024	9/17/2024	INSPTR	TJ4856
SONORA	3/3/2022	11/6/2024	10/8/2024	INSPTR	IS3295
SONORA	3/3/2022	10/30/2022	7/19/2022	INSPTR	
SONORA	3/3/2022	10/30/2022	2/18/2023	INSPTR	RB2924
SONORA	3/3/2022	10/30/2024	9/9/2024	INSPTR	DG3424
SONORA	3/3/2022	10/30/2024	8/15/2024	INSPTR	CH8326
SONORA	3/3/2022	11/2/2024	9/18/2024	INSPTR	RS8367
SONORA	3/3/2022	11/2/2024	9/18/2024	INSPTR	RS8367
SONORA	3/3/2022	11/2/2022	7/26/2022	INSPTR	
SONORA	3/3/2022	11/3/2022	2/24/2023	INSPTR	
SONORA	3/3/2022	11/3/2024	9/26/2024	INSPTR	DG3424
SONORA	3/3/2022	11/4/2022	7/14/2022	INSPTR	
SONORA	3/3/2022	11/4/2024	9/24/2024	INSPTR	RS8367

SONORA	3/3/2022	11/4/2024	9/24/2024	INSPTR	DG3424
SONORA	3/3/2022	11/4/2024	9/30/2024	INSPTR	CH8326
SONORA	3/3/2022	11/4/2024	9/26/2024	INSPTR	KW5925
SONORA	3/3/2022	11/4/2024	9/30/2024	INSPTR	CH8326
SONORA	3/3/2022	11/6/2022	2/24/2023	INSPTR	
SONORA	3/3/2022	11/6/2024	10/15/2024	INSPTR	DG3424
SONORA	3/3/2022	11/6/2024	9/24/2024	INSPTR	DG3424
SONORA	3/3/2022	10/30/2024	8/15/2024	INSPTR	CH8326
SONORA	3/3/2022	10/30/2024	8/23/2024	INSPTR	RT1486
SONORA	3/3/2022	10/30/2022	8/5/2022	INSPTR	
SONORA	3/3/2022	11/4/2022	3/26/2022	INSPTR	NS1598
SONORA	3/3/2022	11/4/2024	9/30/2024	INSPTR	EM3528
SONORA	3/3/2022	11/4/2024	9/30/2024	INSPTR	CH8326
SONORA	3/3/2022	11/4/2024	9/16/2024	INSPTR	HC3283
SONORA	3/3/2022	11/4/2024	10/1/2024	INSPTR	DG3424
SONORA	3/3/2022	11/4/2024	9/16/2024	INSPTR	HC3283
SONORA	3/3/2022	11/5/2022	3/26/2022	INSPTR	NK5685
SONORA	3/3/2022	10/30/2022	7/19/2022	INSPTR	
SONORA	3/3/2022	10/31/2024	9/12/2024	INSPTR	DG3424
SONORA	3/3/2022	10/31/2022	2/23/2023	INSPTR	
SONORA	3/3/2022	10/31/2024	9/13/2024	INSPTR	CH8326

SONORA	3/3/2022	10/31/2024	9/13/2024	INSPTR	CH8326
SONORA	3/3/2022	11/1/2024	9/13/2024	INSPTR	CH8326
SONORA	3/3/2022	11/1/2024	9/13/2024	INSPTR	CH8326
SONORA	3/3/2022	11/1/2024	9/13/2024	INSPTR	CF1419
SONORA	3/3/2022	11/3/2024	9/20/2024	INSPTR	TJ4856
SONORA	3/3/2022	11/2/2024	9/17/2024	INSPTR	DG3424
SONORA	3/3/2022	11/5/2024	9/26/2024	INSPTR	MM5268
SONORA	3/3/2022	11/5/2024	10/2/2024	INSPTR	EM3528
SONORA	3/3/2022	11/4/2024	8/14/2024	INSPTR	DG3424
SONORA	3/3/2022	11/1/2024	9/16/2024	INSPTR	MJ1746
SONORA	3/3/2022	11/1/2024	9/16/2024	INSPTR	MJ1746
SONORA	3/3/2022	11/1/2024	9/19/2024	INSPTR	BS2864
SONORA	3/3/2022	11/2/2024	9/18/2024	INSPTR	RS8367
SONORA	3/3/2022	11/2/2024	9/18/2024	INSPTR	RS8367
SONORA	3/3/2022	11/2/2024	9/26/2024	INSPTR	GB3598
SONORA	3/3/2022	11/5/2024	9/26/2024	INSPTR	MM5268
SONORA	3/3/2022	11/5/2024	10/11/2024	INSPTR	CH8326
SONORA	3/3/2022	11/2/2024	9/17/2024	INSPTR	DG3424
SONORA	3/3/2022	11/2/2024	9/17/2024	INSPTR	DG3424
SONORA	3/3/2022	11/5/2024	10/21/2024	INSPTR	MM5268
SONORA	3/3/2022	11/3/2024	9/20/2024	INSPTR	TJ4856
SONORA	3/3/2022	11/2/2024	9/26/2024	INSPTR	GB3598

SONORA	3/3/2022	10/28/2022	6/30/2022	INSPTR	
SONORA	3/3/2022	10/28/2024	6/21/2024	INSPTR	DG3424
SONORA	3/3/2022	10/28/2024	6/21/2024	INSPTR	DG3424
SONORA	3/3/2022	10/29/2024	8/21/2024	INSPTR	BS2864
SONORA	3/3/2022	10/29/2024	8/13/2024	INSPTR	JB7519
SONORA	3/3/2022	10/29/2024	8/15/2024	INSPTR	BS2864
SONORA	3/3/2022	10/29/2024	8/15/2024	INSPTR	BS2864
SONORA	3/3/2022	11/4/2024	10/2/2024	INSPTR	EM3528
SONORA	3/3/2022	11/5/2026	3/22/2022	INSPTR	
SONORA	3/3/2022	11/3/2024	9/26/2024	INSPTR	DG3424
SONORA	3/3/2022	11/5/2024	10/15/2024	INSPTR	GS3625
SONORA	3/3/2022	11/5/2024	9/5/2024	INSPTR	JG9626
SONORA	3/3/2022	11/5/2024	6/11/2024	INSPTR	IS3295
SONORA	3/3/2022	11/4/2024	10/1/2024	INSPTR	DG3424
SONORA	3/3/2022	10/29/2024	8/12/2024	INSPTR	BS2864
SONORA	3/3/2022	10/29/2024	8/14/2024	INSPTR	CH8326
SONORA	3/3/2022	10/29/2024	8/12/2024	INSPTR	CH8326
SONORA	3/3/2022	10/29/2024	8/12/2024	INSPTR	BS2864
SONORA	3/3/2022	10/29/2024	8/7/2024	INSPTR	BS2864
SONORA	3/3/2022	10/29/2024	8/14/2024	INSPTR	CH8326
SONORA	3/3/2022	10/29/2024	8/15/2024	INSPTR	BS2864
SONORA	3/3/2022	11/5/2024	10/3/2024	INSPTR	JB8576

SONORA	3/3/2022	11/4/2024	9/24/2024	INSPTR	RS8367
SONORA	3/3/2022	10/29/2024	8/15/2024	INSPTR	CH8326
SONORA	3/3/2022	10/29/2024	8/12/2024	INSPTR	BS2864
SONORA	3/3/2022	10/29/2024	8/12/2024	INSPTR	CH8326
SONORA	3/3/2022	10/29/2024	8/20/2024	INSPTR	BS2864
SONORA	3/3/2022	10/29/2024	8/7/2024	INSPTR	BS2864
SONORA	3/3/2022	10/29/2024	6/21/2024	INSPTR	RB2924
SONORA	3/3/2022	10/29/2024	8/12/2024	INSPTR	CH8326
SONORA	3/3/2022	10/29/2024	8/14/2024	INSPTR	CH8326
SONORA	3/3/2022	10/29/2024	8/21/2024	INSPTR	BS2864
SONORA	3/3/2022	10/31/2024	8/23/2024	INSPTR	MJ1746
SONORA	3/3/2022	10/31/2024	8/23/2024	INSPTR	MJ1746
SONORA	3/3/2022	10/31/2024	9/16/2024	INSPTR	MJ1746
SONORA	3/3/2022	10/31/2024	8/23/2024	INSPTR	CE2563
SONORA	3/3/2022	10/31/2024	9/16/2024	INSPTR	MJ1746
SONORA	3/3/2022	10/31/2024	8/21/2024	INSPTR	RT1486
SONORA	3/3/2022	10/31/2024	9/16/2024	INSPTR	MJ1746
SONORA	3/3/2022	10/31/2024	9/16/2024	INSPTR	MJ1746
SONORA	3/3/2022	10/31/2024	8/21/2024	INSPTR	CE2563
SONORA	3/3/2022	10/31/2024	9/13/2024	INSPTR	CF1419
SONORA	3/3/2022	10/31/2022	7/26/2022	INSPTR	
SONORA	3/3/2022	11/8/2024	10/17/2024	INSPTR	DS6453

SONORA	3/3/2022	11/8/2024	9/6/2024	INSPTR	DG3424
SONORA	3/3/2022	11/8/2024	9/6/2024	INSPTR	DG3424
SONORA	3/3/2022	11/8/2024	10/17/2024	INSPTR	DG3424
SONORA	3/3/2022	10/29/2024	8/15/2024	INSPTR	CH8326
SONORA	3/3/2022	10/28/2024	10/31/2023	INSPTR	RN8732
SONORA	3/3/2022	10/28/2024	10/31/2023	INSPTR	RN8732
SONORA	3/3/2022	10/28/2024	10/31/2023	INSPTR	RN8732
SONORA	3/3/2022	10/28/2024	11/1/2023	INSPTR	RN8732
SONORA	3/3/2022	10/28/2026	3/21/2022	INSPTR	
SONORA	3/3/2022	10/28/2024	10/30/2023	INSPTR	RN8732
SONORA	3/3/2022	10/31/2024	9/13/2024	INSPTR	CF1419
SONORA	3/3/2022	10/31/2024	11/1/2023	INSPTR	RN8732
SONORA	3/3/2022	10/31/2024	9/13/2024	INSPTR	TJ4856
SONORA	3/3/2022	10/31/2024	8/23/2024	INSPTR	MJ1746
SONORA	3/3/2022	5/8/2022	6/21/2022	INSPTR	
SONORA	3/3/2022	11/8/2024	10/18/2024	INSPTR	CH8326
SONORA	3/3/2022	11/8/2024	10/18/2024	INSPTR	DG3424
SONORA	3/3/2022	11/10/2024	10/16/2024	INSPTR	TJ4856
SONORA	3/3/2022	10/28/2024	8/12/2024	INSPTR	CH8326
SONORA	3/3/2022	10/28/2022	6/30/2022	INSPTR	
SONORA	3/3/2022	10/28/2024	8/15/2024	INSPTR	BS2864
SONORA	3/3/2022	10/28/2024	10/30/2023	INSPTR	RN8732

SONORA	3/3/2022	10/28/2024	10/30/2023	INSPTR	RN8732
SONORA	3/3/2022	10/28/2024	10/30/2023	INSPTR	RN8732
SONORA	3/3/2022	10/28/2024	10/30/2023	INSPTR	RN8732
SONORA	3/3/2022	11/2/2024	7/31/2024	INSPTR	MJ1746
SONORA	3/3/2022	11/2/2026	6/3/2022	INSPTR	
SONORA	3/3/2022	11/2/2022	6/30/2022	INSPTR	
SONORA	3/3/2022	11/2/2022	7/26/2022	INSPTR	
SONORA	3/3/2022	11/2/2024	9/18/2024	INSPTR	DA1367
SONORA	3/3/2022	11/2/2024	9/20/2024	INSPTR	TJ4856
SONORA	3/3/2022	11/3/2026	6/3/2022	INSPTR	
SONORA	3/3/2022	11/5/2026	6/3/2022	INSPTR	
SONORA	3/3/2022	11/5/2026	3/21/2022	INSPTR	
SONORA	3/3/2022	11/4/2024	8/14/2024	INSPTR	DG3424
SONORA	3/3/2022	11/4/2024	6/3/2022	INSPTR	
SONORA	3/3/2022	11/5/2026	3/21/2022	INSPTR	
SONORA	3/3/2022	11/5/2026	3/21/2022	INSPTR	
TWAIN HARTE	3/8/2022	12/21/2024	8/8/2024	INSPTR	JB8576
TWAIN HARTE	3/8/2022	12/21/2024	10/29/2024	INSPTR	DG3424
TWAIN HARTE	3/8/2022	12/21/2024	10/22/2024	INSPTR	MG5372
TWAIN HARTE	3/8/2022	12/21/2024	10/29/2024	INSPTR	DG3424
TWAIN HARTE	3/8/2022	11/13/2024	10/22/2024	INSPTR	DA1367
TWAIN HARTE	3/8/2022	11/13/2024	10/23/2024	INSPTR	RT1486

TWAIN HARTE	3/8/2022	11/12/2024	10/22/2024	INSPTR	RB2924
TWAIN HARTE	3/8/2022	11/12/2024	10/11/2024	INSPTR	EW042G
TWAIN HARTE	3/8/2022	12/14/2024	10/28/2024	INSPTR	KW5925
TWAIN HARTE	3/8/2022	12/22/2024	10/30/2024	INSPTR	BS2864
TWAIN HARTE	3/8/2022	6/22/2022	5/3/2023	INSPTR	
TWAIN HARTE	3/8/2022	12/23/2024	10/23/2024	INSPTR	TJ4856
TWAIN HARTE	3/8/2022	12/23/2024	10/23/2024	INSPTR	TJ4856
TWAIN HARTE	3/8/2022	6/23/2022	3/27/2022	INSPTR	NK5685
TWAIN HARTE	3/8/2022	12/23/2024	10/30/2024	INSPTR	ZO2856
TWAIN HARTE	3/8/2022	6/23/2022	3/27/2022	INSPTR	NK5685
TWAIN HARTE	3/8/2022	1/18/2025	10/30/2024	INSPTR	FR2146
TWAIN HARTE	3/8/2022	12/6/2024	8/12/2024	INSPTR	RS8367
TWAIN HARTE	3/8/2022	12/6/2024	8/30/2024	INSPTR	RS8367
TWAIN HARTE	3/8/2022	12/6/2024	8/30/2024	INSPTR	RS8367
TWAIN HARTE	3/8/2022	6/6/2022	5/3/2023	INSPTR	
TWAIN HARTE	3/8/2022	6/6/2022	3/28/2022	INSPTR	NK5685
TWAIN HARTE	3/8/2022	12/4/2024	10/25/2024	INSPTR	DA1367
TWAIN HARTE	3/8/2022	12/4/2024	10/23/2024	INSPTR	LH5743
TWAIN HARTE	3/8/2022	12/7/2024	8/30/2024	INSPTR	RS8367
TWAIN HARTE	3/8/2022	12/21/2024	10/28/2024	INSPTR	AD2932
TWAIN HARTE	3/8/2022	11/12/2024	10/11/2024	INSPTR	EW042G

TWAIN HARTE	3/8/2022	11/12/2024	10/11/2024	INSPTR	EW042G
TWAIN HARTE	3/8/2022	11/14/2024	10/23/2024	INSPTR	RT1486
TWAIN HARTE	3/8/2022	12/22/2024	10/22/2024	INSPTR	SD9656
TWAIN HARTE	3/8/2022	6/22/2022	8/9/2022	INSPTR	RB2924
TWAIN HARTE	3/8/2022	6/22/2022	3/25/2022	INSPTR	NS1598
TWAIN HARTE	3/8/2022	7/14/2022	2/20/2023	INSPTR	CR1893
TWAIN HARTE	3/8/2022	7/14/2022	2/20/2023	INSPTR	CR1893
TWAIN HARTE	3/8/2022	7/14/2022	6/1/2022	INSPTR	JA2756
TWAIN HARTE	3/8/2022	1/14/2025	10/22/2024	INSPTR	RN8732
TWAIN HARTE	3/8/2022	1/14/2025	10/24/2024	INSPTR	CF1419
TWAIN HARTE	3/8/2022	1/18/2025	10/23/2024	INSPTR	CR1893
TWAIN HARTE	3/8/2022	12/21/2024	10/23/2024	INSPTR	CR1893
TWAIN HARTE	3/8/2022	11/14/2024	10/21/2024	INSPTR	DA1367
TWAIN HARTE	3/8/2022	11/14/2024	10/23/2024	INSPTR	RT1486
TWAIN HARTE	3/8/2022	11/14/2024	10/23/2024	INSPTR	RT1486
TWAIN HARTE	3/8/2022	11/14/2024	10/23/2024	INSPTR	RB2924
TWAIN HARTE	3/8/2022	11/14/2024	10/22/2024	INSPTR	EC2732
TWAIN HARTE	3/8/2022	11/14/2024	10/22/2024	INSPTR	EC2732
TWAIN HARTE	3/8/2022	12/22/2024	10/29/2024	INSPTR	AD2932
TWAIN HARTE	3/8/2022	12/22/2024	10/30/2024	INSPTR	TJ4856
TWAIN HARTE	3/8/2022	12/22/2024	10/25/2024	INSPTR	CF1419
TWAIN HARTE	3/8/2022	12/22/2024	10/25/2024	INSPTR	CF1419

TWAIN HARTE	3/8/2022	12/22/2024	10/29/2024	INSPTR	AD2932
TWAIN HARTE	3/8/2022	6/22/2022	9/1/2022	INSPTR	RB2924
TWAIN HARTE	3/8/2022	12/21/2024	10/29/2024	INSPTR	RB2924
TWAIN HARTE	3/8/2022	12/21/2024	10/29/2024	INSPTR	RS8367
TWAIN HARTE	3/8/2022	6/21/2022	3/23/2022	INSPTR	BC8519
TWAIN HARTE	3/8/2022	12/21/2024	10/30/2024	INSPTR	RT1486
TWAIN HARTE	3/8/2022	12/21/2024	10/24/2024	INSPTR	CF1419
TWAIN HARTE	3/8/2022	1/18/2025	10/29/2024	INSPTR	AD2932
TWAIN HARTE	3/8/2022	1/18/2025	10/30/2024	INSPTR	CF1419
TWAIN HARTE	3/8/2022	1/18/2025	10/25/2024	INSPTR	CH8326
TWAIN HARTE	3/8/2022	7/19/2022	2/20/2023	INSPTR	SD9656
TWAIN HARTE	3/8/2022	1/19/2025	10/23/2024	INSPTR	AD2932
TWAIN HARTE	3/8/2022	1/19/2025	10/28/2024	INSPTR	JB6185
TWAIN HARTE	3/8/2022	11/11/2024	10/21/2024	INSPTR	DG3424
TWAIN HARTE	3/8/2022	11/9/2024	8/13/2024	INSPTR	BS2864
TWAIN HARTE	3/8/2022	11/9/2024	8/13/2024	INSPTR	BS2864
TWAIN HARTE	3/8/2022	12/21/2024	10/30/2024	INSPTR	RT1486
TWAIN HARTE	3/8/2022	12/21/2024	10/30/2024	INSPTR	ZO2856
TWAIN HARTE	3/8/2022	12/21/2024	10/29/2024	INSPTR	EM3528
TWAIN HARTE	3/8/2022	12/21/2024	10/30/2024	INSPTR	EM3528
TWAIN HARTE	3/8/2022	12/21/2024	10/28/2024	INSPTR	DG3424
TWAIN HARTE	3/8/2022	1/14/2025	10/28/2024	INSPTR	JG9626

TWAIN HARTE	3/8/2022	1/14/2025	10/24/2024	INSPTR	CF1419
TWAIN HARTE	3/8/2022	1/19/2025	10/25/2024	INSPTR	CF1419
TWAIN HARTE	3/8/2022	1/19/2025	10/25/2024	INSPTR	CF1419
TWAIN HARTE	3/8/2022	11/9/2024	8/14/2024	INSPTR	DS6453
TWAIN HARTE	3/8/2022	11/9/2024	8/16/2024	INSPTR	RT1486
TWAIN HARTE	3/8/2022	11/9/2024	8/14/2024	INSPTR	DS6453
TWAIN HARTE	3/8/2022	11/10/2024	10/17/2024	INSPTR	RS8367
TWAIN HARTE	3/8/2022	11/30/2024	10/23/2024	INSPTR	RB2924
TWAIN HARTE	3/8/2022	12/21/2024	10/28/2024	INSPTR	KW5925
TWAIN HARTE	3/8/2022	12/21/2024	10/28/2024	INSPTR	DG3424
TWAIN HARTE	3/8/2022	12/21/2024	10/30/2024	INSPTR	ZO2856
TWAIN HARTE	3/8/2022	12/21/2024	10/28/2024	INSPTR	DG3175
TWAIN HARTE	3/8/2022	12/21/2024	10/23/2024	INSPTR	RX1696
TWAIN HARTE	3/8/2022	12/21/2024	10/28/2024	INSPTR	RS8367
TWAIN HARTE	3/8/2022	12/21/2024	10/28/2024	INSPTR	RS8367
TWAIN HARTE	3/8/2022	12/23/2024	10/25/2024	INSPTR	HC3283
TWAIN HARTE	3/8/2022	12/23/2024	10/30/2024	INSPTR	JB7519
TWAIN HARTE	3/8/2022	12/23/2024	10/30/2024	INSPTR	KW5925
TWAIN HARTE	3/8/2022	12/23/2024	6/11/2024	INSPTR	RN8732
TWAIN HARTE	3/8/2022	6/23/2022	8/8/2022	INSPTR	
TWAIN HARTE	3/8/2022	11/10/2026	6/29/2022	INSPTR	
TWAIN HARTE	3/8/2022	11/10/2024	8/16/2024	INSPTR	RS8367

TWAIN HARTE	3/8/2022	12/21/2024	10/28/2024	INSPTR	AD2932
TWAIN HARTE	3/8/2022	12/21/2024	10/28/2024	INSPTR	KW5925
TWAIN HARTE	3/8/2022	12/21/2024	10/29/2024	INSPTR	CF1419
TWAIN HARTE	3/8/2022	12/23/2024	10/30/2024	INSPTR	RS8367
TWAIN HARTE	3/8/2022	12/23/2024	10/24/2024	INSPTR	CR1893
TWAIN HARTE	3/8/2022	12/23/2024	10/24/2024	INSPTR	CH8326
TWAIN HARTE	3/8/2022	12/23/2022	8/5/2022	INSPTR	
TWAIN HARTE	3/8/2022	12/23/2024	10/28/2024	INSPTR	JG9626
TWAIN HARTE	3/8/2022	12/23/2024	6/10/2024	INSPTR	DP7958
TWAIN HARTE	3/8/2022	12/23/2024	10/28/2024	INSPTR	JG9626
TWAIN HARTE	3/8/2022	11/10/2024	8/14/2024	INSPTR	DS6453
TWAIN HARTE	3/8/2022	11/10/2024	8/16/2024	INSPTR	RT1486
TWAIN HARTE	3/8/2022	6/21/2022	4/1/2022	INSPTR	WM9343
TWAIN HARTE	3/8/2022	12/21/2024	10/29/2024	INSPTR	CF1419
TWAIN HARTE	3/8/2022	12/21/2024	10/29/2024	INSPTR	CF1419
TWAIN HARTE	3/8/2022	12/22/2024	10/29/2024	INSPTR	DG3424
TWAIN HARTE	3/8/2022	12/23/2024	10/25/2024	INSPTR	DA1367
TWAIN HARTE	3/8/2022	12/23/2024	10/30/2024	INSPTR	DG3424
TWAIN HARTE	3/8/2022	12/23/2024	10/29/2024	INSPTR	AD2932
TWAIN HARTE	3/8/2022	6/23/2022	9/5/2022	INSPTR	DS6453
TWAIN HARTE	3/8/2022	6/23/2022	2/19/2023	INSPTR	DG3175
TWAIN HARTE	3/8/2022	6/23/2022	2/19/2023	INSPTR	DG3175

TWAIN HARTE	3/8/2022	12/23/2024	10/24/2024	INSPTR	CH8326
TWAIN HARTE	3/8/2022	11/10/2024	8/16/2024	INSPTR	RS8367
TWAIN HARTE	3/8/2022	11/10/2024	10/21/2024	INSPTR	FR2146
TWAIN HARTE	3/8/2022	1/14/2025	10/24/2024	INSPTR	CF1419
TWAIN HARTE	3/8/2022	11/8/2024	8/13/2024	INSPTR	BS2864
TWAIN HARTE	3/8/2022	12/22/2024	10/28/2024	INSPTR	AD2932
TWAIN HARTE	3/8/2022	12/22/2024	10/24/2024	INSPTR	DS6453
TWAIN HARTE	3/8/2022	12/22/2024	10/28/2024	INSPTR	RS8367
TWAIN HARTE	3/8/2022	12/22/2024	10/24/2024	INSPTR	DS6453
TWAIN HARTE	3/8/2022	12/22/2024	10/28/2024	INSPTR	RS8367
TWAIN HARTE	3/8/2022	6/24/2022	3/25/2022	INSPTR	RB2924
TWAIN HARTE	3/8/2022	6/24/2022	2/18/2023	INSPTR	RX1696
TWAIN HARTE	3/8/2022	12/23/2024	10/25/2024	INSPTR	CH8326
TWAIN HARTE	3/8/2022	12/23/2024	10/25/2024	INSPTR	RB2924
TWAIN HARTE	3/8/2022	6/24/2022	3/16/2022	INSPTR	WM9343
TWAIN HARTE	3/8/2022	6/24/2022	2/18/2023	INSPTR	RX1696
TWAIN HARTE	3/8/2022	6/27/2022	8/8/2022	INSPTR	
TWAIN HARTE	3/8/2022	1/4/2025	10/30/2024	INSPTR	CF1419
TWAIN HARTE	3/8/2022	11/10/2024	5/9/2024	INSPTR	HC3283
TWAIN HARTE	3/8/2022	11/10/2024	5/9/2024	INSPTR	HC3283
TWAIN HARTE	3/8/2022	11/9/2024	5/1/2024	INSPTR	CS1623
TWAIN HARTE	3/8/2022	12/22/2024	10/25/2024	INSPTR	RB2924

TWAIN HARTE	3/8/2022	11/11/2024	10/8/2024	INSPTR	GC408J
TWAIN HARTE	3/8/2022	11/11/2024	10/8/2024	INSPTR	GC408J
TWAIN HARTE	3/8/2022	11/11/2024	10/8/2024	INSPTR	GC408J
TWAIN HARTE	3/8/2022	11/11/2024	10/21/2024	INSPTR	RS8367
TWAIN HARTE	3/8/2022	11/11/2024	10/21/2024	INSPTR	DG3424
TWAIN HARTE	3/8/2022	12/22/2024	10/25/2024	INSPTR	CH8326
TWAIN HARTE	3/8/2022	12/22/2024	10/25/2024	INSPTR	CH8326
TWAIN HARTE	3/8/2022	1/4/2025	10/29/2024	INSPTR	CH8326
TWAIN HARTE	3/8/2022	1/4/2025	10/29/2024	INSPTR	CH8326
TWAIN HARTE	3/8/2022	1/14/2025	10/28/2024	INSPTR	JG9626
TWAIN HARTE	3/8/2022	5/11/2022	8/10/2022	INSPTR	
TWAIN HARTE	3/8/2022	12/6/2024	10/30/2024	INSPTR	CF1419
TWAIN HARTE	3/8/2022	6/22/2022	2/19/2023	INSPTR	RX1696
TWAIN HARTE	3/8/2022	12/22/2024	10/25/2024	INSPTR	TJ4856
TWAIN HARTE	3/8/2022	1/14/2025	10/24/2024	INSPTR	TJ4856
TWAIN HARTE	3/8/2022	11/11/2024	10/8/2024	INSPTR	GC408J
TWAIN HARTE	3/8/2022	11/11/2024	10/8/2024	INSPTR	GC408J
TWAIN HARTE	3/8/2022	6/6/2022	8/8/2022	INSPTR	
TWAIN HARTE	3/8/2022	12/7/2024	8/30/2024	INSPTR	RS8367
TWAIN HARTE	3/8/2022	12/7/2024	3/23/2022	INSPTR	MT3262
TWAIN HARTE	3/8/2022	12/7/2024	10/24/2024	INSPTR	RB2924
TWAIN HARTE	3/8/2022	12/7/2024	10/24/2024	INSPTR	CR1893

TWAIN HARTE	3/8/2022	12/8/2024	10/25/2024	INSPTR	TJ4856
TWAIN HARTE	3/8/2022	12/8/2024	10/28/2024	INSPTR	CH8326
TWAIN HARTE	3/8/2022	12/8/2024	10/25/2024	INSPTR	TJ4856
TWAIN HARTE	3/8/2022	12/8/2024	10/28/2024	INSPTR	CH8326
TWAIN HARTE	3/8/2022	12/8/2024	10/28/2024	INSPTR	CH8326
TWAIN HARTE	3/8/2022	12/8/2024	10/28/2024	INSPTR	CH8326
TWAIN HARTE	3/8/2022	12/8/2024	5/3/2024	INSPTR	HC3283
TWAIN HARTE	3/8/2022	12/22/2024	10/29/2024	INSPTR	ZO2856
TWAIN HARTE	3/8/2022	12/23/2024	10/25/2024	INSPTR	CH8326
TWAIN HARTE	3/8/2022	12/23/2024	10/24/2024	INSPTR	DS6453
TWAIN HARTE	3/8/2022	6/23/2022	2/18/2023	INSPTR	RS8367
TWAIN HARTE	3/8/2022	6/23/2022	2/19/2023	INSPTR	RX1696
TWAIN HARTE	3/8/2022	12/23/2024	10/25/2024	INSPTR	RB2924
TWAIN HARTE	3/8/2022	12/1/2024	10/23/2024	INSPTR	DG3424
TWAIN HARTE	3/8/2022	12/1/2024	10/24/2024	INSPTR	CR1893
TWAIN HARTE	3/8/2022	12/1/2024	10/28/2024	INSPTR	CF1419
TWAIN HARTE	3/8/2022	12/1/2024	10/28/2024	INSPTR	CF1419
TWAIN HARTE	3/8/2022	12/8/2024	10/29/2024	INSPTR	CF1419
TWAIN HARTE	3/8/2022	12/6/2024	10/29/2024	INSPTR	CF1419
TWAIN HARTE	3/8/2022	12/6/2024	10/25/2024	INSPTR	DA1367
TWAIN HARTE	3/8/2022	12/6/2024	8/30/2024	INSPTR	RS8367
TWAIN HARTE	3/8/2022	12/10/2024	10/30/2024	INSPTR	BS2864

TWAIN HARTE	3/8/2022	12/10/2024	10/28/2024	INSPTR	CH8326
TWAIN HARTE	3/8/2022	12/23/2024	10/25/2024	INSPTR	RB2924
TWAIN HARTE	3/8/2022	12/23/2024	10/29/2024	INSPTR	KW5925
TWAIN HARTE	3/8/2022	7/19/2022	2/18/2023	INSPTR	RX1696
TWAIN HARTE	3/8/2022	1/19/2025	10/30/2024	INSPTR	JB7519
TWAIN HARTE	3/8/2022	1/19/2025	10/30/2024	INSPTR	RS8367
TWAIN HARTE	3/8/2022	1/19/2025	10/28/2024	INSPTR	JB6185
TWAIN HARTE	3/8/2022	7/19/2022	2/18/2023	INSPTR	RX1696
TWAIN HARTE	3/8/2022	7/19/2022	10/7/2022	INSPTR	CS1623
TWAIN HARTE	3/8/2022	12/1/2024	10/28/2024	INSPTR	RT1486
TWAIN HARTE	3/8/2022	12/1/2024	10/23/2024	INSPTR	LH5743
TWAIN HARTE	3/8/2022	12/1/2024	10/23/2024	INSPTR	RB2924
TWAIN HARTE	3/8/2022	12/2/2026	6/29/2022	INSPTR	
TWAIN HARTE	3/8/2022	12/2/2024	10/30/2024	INSPTR	BS2864
TWAIN HARTE	3/8/2022	12/2/2024	10/28/2024	INSPTR	CF1419
TWAIN HARTE	3/8/2022	12/2/2024	10/28/2024	INSPTR	CF1419
TWAIN HARTE	3/8/2022	6/2/2022	2/19/2023	INSPTR	RX1696
TWAIN HARTE	3/8/2022	12/3/2022	3/27/2022	INSPTR	NK5685
TWAIN HARTE	3/8/2022	12/3/2024	10/23/2024	INSPTR	DG3424
TWAIN HARTE	3/8/2022	12/3/2024	10/23/2024	INSPTR	ZO2856
TWAIN HARTE	3/8/2022	12/10/2024	10/23/2024	INSPTR	ZO2856
TWAIN HARTE	3/8/2022	12/10/2024	10/23/2024	INSPTR	ZO2856

TWAIN HARTE	3/8/2022	6/23/2022	8/8/2022	INSPTR	
TWAIN HARTE	3/8/2022	12/22/2024	10/23/2024	INSPTR	ZO2856
TWAIN HARTE	3/8/2022	6/22/2022	6/29/2022	INSPTR	
TWAIN HARTE	3/8/2022	12/22/2024	10/29/2024	INSPTR	RS8367
TWAIN HARTE	3/8/2022	12/22/2024	10/25/2024	INSPTR	KW5925
TWAIN HARTE	3/8/2022	1/17/2025	10/22/2024	INSPTR	HC3283
TWAIN HARTE	3/8/2022	12/21/2024	10/23/2024	INSPTR	ZO2856
TWAIN HARTE	3/8/2022	12/21/2024	10/23/2024	INSPTR	CF1419
TWAIN HARTE	3/8/2022	12/22/2024	10/23/2024	INSPTR	ZO2856
TWAIN HARTE	3/8/2022	12/21/2024	10/23/2024	INSPTR	CF1419
TWAIN HARTE	3/8/2022	12/20/2024	10/24/2024	INSPTR	TJ4856
TWAIN HARTE	3/8/2022	12/4/2024	10/23/2024	INSPTR	LH5743
TWAIN HARTE	3/8/2022	12/4/2024	10/25/2024	INSPTR	DA1367
TWAIN HARTE	3/8/2022	12/4/2024	10/30/2024	INSPTR	FR2146
TWAIN HARTE	3/8/2022	12/4/2024	10/23/2024	INSPTR	LH5743
TWAIN HARTE	3/8/2022	12/6/2024	10/25/2024	INSPTR	DA1367
TWAIN HARTE	3/8/2022	11/12/2024	10/11/2024	INSPTR	EW042G
TWAIN HARTE	3/8/2022	12/10/2024	10/14/2024	INSPTR	IS3295
TWAIN HARTE	3/8/2022	12/10/2024	6/11/2024	INSPTR	DK332Q
TWAIN HARTE	3/8/2022	12/22/2024	10/30/2024	INSPTR	KW5925
TWAIN HARTE	3/8/2022	12/22/2024	10/30/2024	INSPTR	ZO2856

TWAIN HARTE	3/8/2022	6/22/2022	5/4/2023	INSPTR	
TWAIN HARTE	3/8/2022	12/22/2024	10/29/2024	INSPTR	RB2924
TWAIN HARTE	3/8/2022	12/22/2024	10/28/2024	INSPTR	DG3424
TWAIN HARTE	3/8/2022	1/17/2025	10/30/2024	INSPTR	CF1419
TWAIN HARTE	3/8/2022	1/16/2025	10/21/2024	INSPTR	ZO2856
TWAIN HARTE	3/8/2022	1/16/2025	10/21/2024	INSPTR	ZO2856
TWAIN HARTE	3/8/2022	1/16/2025	10/24/2024	INSPTR	CH8326
TWAIN HARTE	3/8/2022	1/16/2025	10/21/2024	INSPTR	RB2924
TWAIN HARTE	3/8/2022	1/16/2025	10/21/2024	INSPTR	RB2924
TWAIN HARTE	3/8/2022	12/1/2024	10/23/2024	INSPTR	RB2924
TWAIN HARTE	3/8/2022	11/12/2024	10/11/2024	INSPTR	EW042G
TWAIN HARTE	3/8/2022	11/12/2024	10/22/2024	INSPTR	DA1367
TWAIN HARTE	3/8/2022	12/11/2024	10/28/2024	INSPTR	MG5372
TWAIN HARTE	3/8/2022	12/11/2024	10/28/2024	INSPTR	KW5925
TWAIN HARTE	3/8/2022	12/11/2024	12/15/2023	INSPTR	RS8367
TWAIN HARTE	3/8/2022	12/14/2024	10/28/2024	INSPTR	MG5372
TWAIN HARTE	3/8/2022	12/22/2024	10/28/2024	INSPTR	DG3424
TWAIN HARTE	3/8/2022	12/22/2024	10/29/2024	INSPTR	ZO2856
TWAIN HARTE	3/8/2022	12/22/2024	10/29/2024	INSPTR	CH8326
TWAIN HARTE	3/8/2022	12/22/2024	10/28/2024	INSPTR	DG3424
TWAIN HARTE	3/8/2022	12/22/2024	10/29/2024	INSPTR	RS8367
TWAIN HARTE	3/8/2022	12/22/2024	10/25/2024	INSPTR	KW5925

TWAIN HARTE	3/8/2022	1/17/2025	10/30/2024	INSPTR	BS2864
TWAIN HARTE	3/8/2022	1/17/2025	8/19/2024	INSPTR	KB5463
TWAIN HARTE	3/8/2022	1/17/2025	10/29/2024	INSPTR	CH8326
TWAIN HARTE	3/8/2022	7/17/2022	4/13/2022	INSPTR	MT3262
TWAIN HARTE	3/8/2022	7/17/2022	6/29/2022	INSPTR	
TWAIN HARTE	3/8/2022	1/17/2025	10/24/2024	INSPTR	CH8326
TWAIN HARTE	3/8/2022	1/17/2027	6/29/2022	INSPTR	
TWAIN HARTE	4/7/2022	4/10/2022	2/19/2023	JR2827	DG3175
SONORA	4/20/2022	11/9/2024	10/18/2024	INSPTR	DG3424
SONORA	4/20/2022	11/10/2024	10/21/2024	INSPTR	ZO2856
SONORA	4/20/2022	11/10/2024	10/21/2024	INSPTR	MM5268
SONORA	4/20/2022	11/9/2024	10/20/2024	INSPTR	TB3178
SONORA	4/20/2022	11/10/2024	8/14/2024	INSPTR	KB5463
SONORA	4/20/2022	11/10/2024	10/18/2024	INSPTR	EC2732
SONORA	4/20/2022	11/11/2024	10/3/2024	INSPTR	GS3625
SONORA	4/20/2022	11/11/2024	10/3/2024	INSPTR	GS3625
SONORA	4/20/2022	11/11/2024	7/31/2024	INSPTR	BS2864
SONORA	4/20/2022	11/11/2024	7/31/2024	INSPTR	BS2864
SONORA	4/20/2022	11/11/2024	7/31/2024	INSPTR	BS2864
SONORA	4/20/2022	11/11/2024	10/11/2024	INSPTR	EC2732
SONORA	4/20/2022	11/11/2024	10/11/2024	INSPTR	EC2732
SONORA	4/20/2022	11/9/2024	10/16/2024	INSPTR	EC2732

SONORA	4/20/2022	11/9/2024	10/16/2024	INSPTR	EC2732
SONORA	4/20/2022	11/16/2022	6/30/2022	INSPTR	
SONORA	4/20/2022	11/17/2024	10/1/2024	INSPTR	JB8576
SONORA	4/20/2022	11/17/2024	10/1/2024	INSPTR	JB8576
SONORA	4/20/2022	11/17/2022	2/18/2023	INSPTR	CH8326
SONORA	4/20/2022	11/9/2024	10/8/2024	INSPTR	ZO2856
SONORA	4/20/2022	11/17/2024	7/25/2024	INSPTR	PR2872
SONORA	4/20/2022	11/17/2024	10/21/2024	INSPTR	KW5925
SONORA	4/20/2022	11/17/2022	2/18/2023	INSPTR	CH8326
SONORA	4/20/2022	11/20/2024	10/7/2024	INSPTR	EM3528
SONORA	4/20/2022	11/10/2024	10/14/2024	INSPTR	GS3625
SONORA	4/20/2022	11/10/2024	5/9/2024	INSPTR	RS8367
SONORA	4/20/2022	11/10/2022	6/30/2022	INSPTR	
SONORA	4/20/2022	11/20/2024	10/7/2024	INSPTR	EM3528
SONORA	4/20/2022	11/21/2022	2/10/2023	INSPTR	
SONORA	4/20/2022	11/21/2022	6/30/2022	INSPTR	
SONORA	4/20/2022	11/10/2024	10/14/2024	INSPTR	GS3625
SONORA	4/20/2022	11/7/2024	7/23/2024	INSPTR	MJ1746
SONORA	4/20/2022	11/7/2024	7/16/2024	INSPTR	KB5463
SONORA	4/20/2022	11/7/2024	7/23/2024	INSPTR	MJ1746
SONORA	4/20/2022	11/12/2024	10/16/2024	INSPTR	GS3625
SONORA	4/20/2022	12/12/2024	7/23/2024	INSPTR	MJ1746

SONORA	4/20/2022	12/12/2026	2/23/2023	INSPTR	
SONORA	4/20/2022	11/12/2024	10/21/2024	INSPTR	MG5372
SONORA	4/20/2022	11/12/2024	7/31/2024	INSPTR	FR2146
SONORA	4/20/2022	11/12/2024	10/4/2024	INSPTR	DG3424
SONORA	4/20/2022	11/12/2024	5/11/2023	INSPTR	
SONORA	4/20/2022	11/12/2026	5/11/2023	INSPTR	
SONORA	4/20/2022	11/12/2026	5/11/2023	INSPTR	
SONORA	4/20/2022	11/16/2024	9/24/2024	INSPTR	KW5925
SONORA	4/20/2022	11/16/2024	10/21/2024	INSPTR	DA1367
SONORA	4/20/2022	11/16/2024	5/12/2023	INSPTR	
SONORA	4/20/2022	11/16/2024	10/10/2024	INSPTR	IS3295
SONORA	4/20/2022	11/16/2024	5/12/2023	INSPTR	
SONORA	4/20/2022	11/16/2026	5/11/2023	INSPTR	
SONORA	4/20/2022	11/16/2026	5/11/2023	INSPTR	
SONORA	4/20/2022	11/16/2026	5/11/2023	INSPTR	
SONORA	4/20/2022	11/16/2024	8/30/2024	INSPTR	RB2924
SONORA	4/20/2022	11/12/2024	7/25/2024	INSPTR	BS2864
SONORA	4/20/2022	11/12/2024	10/20/2024	INSPTR	ZO2856
SONORA	4/20/2022	11/12/2026	5/15/2023	INSPTR	
SONORA	4/20/2022	11/12/2024	7/25/2024	INSPTR	BS2864
SONORA	4/20/2022	11/16/2024	10/10/2024	INSPTR	IS3295
SONORA	4/20/2022	11/16/2024	10/8/2024	INSPTR	CH8326

SONORA	4/20/2022	11/16/2024	10/4/2024	INSPTR	DG3424
SONORA	4/20/2022	11/16/2024	10/21/2024	INSPTR	ZO2856
SONORA	4/20/2022	11/12/2024	10/4/2024	INSPTR	DG3424
SONORA	4/20/2022	11/10/2022	7/8/2022	INSPTR	
SONORA	4/20/2022	11/18/2022	9/8/2022	INSPTR	RN8732
SONORA	4/20/2022	11/15/2024	10/20/2024	INSPTR	ZO2856
SONORA	4/20/2022	11/19/2024	10/17/2024	INSPTR	EC2732
SONORA	4/20/2022	11/19/2022	7/8/2022	INSPTR	
SONORA	4/20/2022	11/11/2024	10/4/2024	INSPTR	TJ4856
SONORA	4/20/2022	11/11/2024	10/4/2024	INSPTR	TJ4856
SONORA	4/20/2022	11/11/2024	10/18/2024	INSPTR	CH8326
SONORA	4/20/2022	11/11/2024	10/18/2024	INSPTR	CH8326
SONORA	4/20/2022	11/10/2024	7/22/2024	INSPTR	DG3424
SONORA	4/20/2022	11/10/2024	7/22/2024	INSPTR	DG3424
SONORA	4/20/2022	11/10/2024	10/15/2024	INSPTR	GS3625
SONORA	4/20/2022	11/10/2024	9/24/2024	INSPTR	KW5925
SONORA	4/20/2022	11/10/2022	6/30/2022	INSPTR	
SONORA	4/20/2022	11/19/2022	2/23/2023	INSPTR	
SONORA	4/20/2022	11/19/2024	10/9/2024	INSPTR	ZO2856
SONORA	4/20/2022	11/9/2024	10/17/2024	INSPTR	ZO2856
SONORA	4/20/2022	11/9/2024	10/8/2024	INSPTR	ZO2856
SONORA	4/20/2022	11/9/2024	10/9/2024	INSPTR	ZO2856

SONORA	4/20/2022	11/9/2024	10/2/2024	INSPTR	DG3424
SONORA	4/20/2022	11/9/2024	10/17/2024	INSPTR	ZO2856
SONORA	4/20/2022	11/9/2024	10/9/2024	INSPTR	ZO2856
SONORA	4/20/2022	11/9/2024	10/9/2024	INSPTR	ZO2856
SONORA	4/20/2022	11/10/2024	10/16/2024	INSPTR	TJ4856
SONORA	4/20/2022	11/10/2024	10/17/2024	INSPTR	ZO2856
SONORA	4/20/2022	11/17/2024	10/3/2024	INSPTR	ZO2856
SONORA	4/20/2022	11/17/2024	10/18/2024	INSPTR	RS8367
SONORA	4/20/2022	11/19/2024	10/17/2024	INSPTR	ZO2856
SONORA	4/20/2022	11/19/2024	5/10/2023	INSPTR	
SONORA	4/20/2022	11/19/2024	10/17/2024	INSPTR	ZO2856
SONORA	4/20/2022	11/19/2024	10/14/2024	INSPTR	GS3625
SONORA	4/20/2022	11/19/2024	5/9/2023	INSPTR	
SONORA	4/20/2022	11/9/2024	10/17/2024	INSPTR	DG3175
SONORA	4/20/2022	11/9/2024	10/11/2024	INSPTR	CF1419
SONORA	4/20/2022	11/9/2024	8/21/2024	INSPTR	CR1893
SONORA	4/20/2022	11/9/2024	10/7/2024	INSPTR	ZO2856
SONORA	4/20/2022	11/9/2024	10/2/2024	INSPTR	DG3424
SONORA	4/20/2022	11/9/2022	7/19/2022	INSPTR	
SONORA	4/20/2022	11/9/2024	10/14/2024	INSPTR	GS3625
SONORA	4/20/2022	11/17/2024	10/14/2024	INSPTR	GS3625
SONORA	4/20/2022	11/17/2022	2/10/2023	INSPTR	

SONORA	4/20/2022	11/17/2026	5/10/2023	INSPTR	
SONORA	4/20/2022	11/17/2024	10/14/2024	INSPTR	EC2732
SONORA	4/20/2022	11/19/2024	10/8/2024	INSPTR	ZO2856
SONORA	4/20/2022	11/19/2024	10/3/2024	INSPTR	MG5372
SONORA	4/20/2022	12/12/2026	2/23/2023	INSPTR	
SONORA	4/20/2022	12/12/2026	2/23/2023	INSPTR	
SONORA	4/20/2022	12/12/2026	2/23/2023	INSPTR	
SONORA	4/20/2022	12/12/2024	2/23/2023	INSPTR	
SONORA	4/20/2022	12/13/2024	10/17/2024	INSPTR	EC2732
SONORA	4/20/2022	11/10/2024	4/16/2024	INSPTR	RB2924
SONORA	4/20/2022	11/11/2024	7/23/2024	INSPTR	MJ1746
SONORA	4/20/2022	11/11/2024	7/23/2024	INSPTR	BS2864
SONORA	4/20/2022	11/11/2024	7/23/2024	INSPTR	BS2864
SONORA	4/20/2022	11/11/2024	7/23/2024	INSPTR	BS2864
SONORA	4/20/2022	11/17/2024	10/14/2024	INSPTR	EC2732
SONORA	4/20/2022	11/17/2024	10/16/2024	INSPTR	ZO2856
SONORA	4/20/2022	11/17/2022	7/19/2022	INSPTR	
SONORA	4/20/2022	11/17/2024	10/16/2024	INSPTR	ZO2856
SONORA	4/20/2022	12/13/2024	1/5/2024	INSPTR	CS1623
SONORA	4/20/2022	12/13/2024	10/16/2024	INSPTR	ZO2856
SONORA	4/20/2022	12/13/2024	10/9/2024	INSPTR	ZO2856
SONORA	4/20/2022	12/13/2026	2/23/2023	INSPTR	

SONORA	4/20/2022	12/12/2026	5/12/2023	INSPTR	
SONORA	4/20/2022	11/9/2024	5/17/2024	INSPTR	MJ1746
SONORA	4/20/2022	11/9/2024	5/17/2024	INSPTR	MJ1746
SONORA	4/20/2022	11/9/2024	5/17/2024	INSPTR	MJ1746
SONORA	4/20/2022	11/9/2024	5/17/2024	INSPTR	MJ1746
SONORA	4/20/2022	11/9/2026	5/5/2023	INSPTR	
SONORA	4/20/2022	11/9/2026	5/5/2023	INSPTR	
SONORA	4/20/2022	11/9/2024	10/9/2024	INSPTR	ZO2856
SONORA	4/20/2022	11/9/2024	8/6/2024	INSPTR	DG3424
SONORA	4/20/2022	11/16/2022	6/30/2022	INSPTR	
SONORA	4/20/2022	11/16/2024	10/7/2024	INSPTR	EC2732
SONORA	4/20/2022	11/16/2024	10/3/2024	INSPTR	ZO2856
SONORA	4/20/2022	11/16/2024	10/7/2024	INSPTR	EC2732
SONORA	4/20/2022	5/16/2022	6/30/2022	INSPTR	
SONORA	4/20/2022	12/12/2024	10/16/2024	INSPTR	ZO2856
SONORA	4/20/2022	12/12/2026	6/3/2022	INSPTR	
SONORA	4/20/2022	12/12/2026	5/5/2023	INSPTR	
SONORA	4/20/2022	12/12/2024	10/1/2024	INSPTR	TJ4856
SONORA	4/20/2022	12/12/2026	5/5/2023	INSPTR	
SONORA	4/20/2022	12/12/2024	10/1/2024	INSPTR	TJ4856
SONORA	4/20/2022	12/12/2026	5/12/2023	INSPTR	
SONORA	4/20/2022	12/12/2026	6/3/2022	INSPTR	

SONORA	4/20/2022	11/9/2024	8/21/2024	INSPTR	CR1893
SONORA	4/20/2022	11/9/2026	5/5/2023	INSPTR	
SONORA	4/20/2022	11/9/2026	5/5/2023	INSPTR	
SONORA	4/20/2022	11/9/2024	10/7/2024	INSPTR	ZO2856
SONORA	4/20/2022	11/9/2026	6/3/2022	INSPTR	
SONORA	4/20/2022	11/9/2024	10/7/2024	INSPTR	ZO2856
SONORA	4/20/2022	11/9/2024	10/8/2024	INSPTR	ZO2856
SONORA	4/20/2022	11/9/2024	10/1/2024	INSPTR	EM3528
SONORA	4/20/2022	11/9/2024	10/7/2024	INSPTR	ZO2856
SONORA	4/20/2022	11/16/2026	6/13/2022	INSPTR	
SONORA	4/20/2022	11/16/2026	5/5/2023	INSPTR	
SONORA	4/20/2022	11/17/2024	10/3/2024	INSPTR	ZO2856
SONORA	4/20/2022	11/17/2024	6/13/2022	INSPTR	
SONORA	4/20/2022	11/15/2024	10/3/2024	INSPTR	GS3625
SONORA	4/20/2022	11/15/2026	6/3/2022	INSPTR	
SONORA	4/20/2022	11/15/2024	10/3/2024	INSPTR	ZO2856
SONORA	4/20/2022	11/15/2024	9/20/2024	INSPTR	RG6161
SONORA	4/20/2022	11/17/2024	10/3/2024	INSPTR	GS3625
SONORA	4/20/2022	12/12/2024	5/17/2024	INSPTR	BS2864
SONORA	4/20/2022	12/12/2024	5/17/2024	INSPTR	BS2864
SONORA	4/20/2022	12/12/2024	10/7/2024	INSPTR	ZO2856
SONORA	4/20/2022	12/12/2024	10/3/2024	INSPTR	ZO2856

SONORA	4/20/2022	11/9/2024	5/17/2024	INSPTR	BS2864
SONORA	4/20/2022	11/9/2024	5/17/2024	INSPTR	BS2864
SONORA	4/20/2022	11/9/2026	5/5/2023	INSPTR	
SONORA	4/20/2022	11/11/2026	5/5/2023	INSPTR	
SONORA	4/20/2022	11/11/2026	5/5/2023	INSPTR	
SONORA	4/20/2022	11/11/2024	5/2/2024	INSPTR	DG3424
SONORA	4/20/2022	11/18/2024	9/13/2024	INSPTR	MG5372
SONORA	4/20/2022	11/18/2024	5/9/2023	INSPTR	
SONORA	4/20/2022	11/18/2024	10/3/2024	INSPTR	GS3625
SONORA	4/20/2022	11/15/2026	5/5/2023	INSPTR	
SONORA	4/20/2022	11/18/2026	5/9/2023	INSPTR	
SONORA	4/20/2022	11/18/2024	5/2/2024	INSPTR	KW5925
SONORA	4/20/2022	11/18/2024	5/2/2024	INSPTR	KW5925
SONORA	4/20/2022	11/11/2022	6/30/2022	INSPTR	
SONORA	4/20/2022	11/11/2024	5/9/2023	INSPTR	
SONORA	4/20/2022	11/11/2024	10/1/2024	INSPTR	DG3424
SONORA	4/20/2022	11/11/2022	2/23/2023	INSPTR	
SONORA	4/20/2022	11/11/2026	5/9/2023	INSPTR	
SONORA	4/20/2022	11/18/2026	5/5/2023	INSPTR	
SONORA	4/20/2022	11/18/2024	5/2/2024	INSPTR	RB2924
SONORA	4/20/2022	11/12/2024	5/2/2024	INSPTR	RB2924
SONORA	4/20/2022	11/12/2026	5/9/2023	INSPTR	

SONORA	4/20/2022	11/12/2024	12/13/2023	INSPTR	KW5925
SONORA	4/20/2022	11/12/2024	5/10/2023	INSPTR	
SONORA	4/20/2022	11/12/2024	12/4/2023	INSPTR	KW5925
SONORA	4/20/2022	11/11/2024	12/4/2023	INSPTR	CR1893
SONORA	4/20/2022	11/11/2026	5/10/2023	INSPTR	
SONORA	4/20/2022	11/11/2024	11/30/2023	INSPTR	KW5925
SONORA	4/20/2022	11/11/2024	11/30/2023	INSPTR	KW5925
SONORA	4/20/2022	11/12/2026	5/10/2023	INSPTR	
SONORA	4/20/2022	11/12/2024	11/30/2023	INSPTR	KW5925
SONORA	4/20/2022	11/12/2026	5/10/2023	INSPTR	
SONORA	4/20/2022	11/18/2024	11/30/2023	INSPTR	KW5925
SONORA	4/20/2022	11/15/2024	5/10/2023	INSPTR	
SONORA	4/20/2022	11/15/2026	5/9/2023	INSPTR	
SONORA	4/20/2022	11/15/2022	6/6/2022	INSPTR	
SONORA	6/5/2022	6/5/2025	6/11/2024	DG2874	UV639W
SONORA	6/28/2022	5/25/2025	7/25/2024	INSPTR	BS2864
PINECREST	6/28/2022	5/24/2025	10/2/2024	INSPTR	MG5372
PINECREST	6/28/2022	5/24/2025	10/2/2024	INSPTR	MG5372
PINECREST	6/28/2022	5/24/2025	10/2/2024	INSPTR	MG5372
PINECREST	6/28/2022	5/24/2025	10/2/2024	INSPTR	MG5372
PINECREST	6/28/2022	5/24/2025	10/2/2024	INSPTR	MG5372
PINECREST	6/28/2022	5/24/2025	9/10/2024	INSPTR	MH3568

PINECREST	6/28/2022	5/24/2025	8/13/2024	INSPTR	DG3424
PINECREST	6/28/2022	5/24/2025	9/11/2024	INSPTR	MH3568
TWAIN HARTE	6/28/2022	5/21/2025	10/30/2024	INSPTR	RT1486
TWAIN HARTE	6/28/2022	5/21/2025	10/29/2024	INSPTR	RS8367
TWAIN HARTE	6/28/2022	5/21/2025	10/29/2024	INSPTR	EM3528
TWAIN HARTE	6/28/2022	5/21/2025	10/29/2024	INSPTR	ZO2856
TWAIN HARTE	6/28/2022	5/21/2025	10/30/2024	INSPTR	EM3528
TWAIN HARTE	6/28/2022	5/21/2025	9/6/2024	INSPTR	RS8367
TWAIN HARTE	6/28/2022	5/21/2025	10/25/2024	INSPTR	KW5925
TWAIN HARTE	6/28/2022	5/21/2025	10/29/2024	INSPTR	DG3424
TWAIN HARTE	6/28/2022	5/21/2025	10/29/2024	INSPTR	CH8326
TWAIN HARTE	6/28/2022	5/21/2025	10/29/2024	INSPTR	DG3424
TWAIN HARTE	6/28/2022	5/21/2025	10/25/2024	INSPTR	KW5925
TWAIN HARTE	6/28/2022	5/21/2025	10/30/2024	INSPTR	RT1486
TWAIN HARTE	6/28/2022	5/21/2025	10/25/2024	INSPTR	KW5925
TWAIN HARTE	6/28/2022	5/21/2025	10/29/2024	INSPTR	EM3528
SONORA	6/28/2022	5/25/2025	8/15/2024	INSPTR	RT1486
GROVELAND	6/28/2022	5/23/2025	9/21/2024	INSPTR	ML5474
GROVELAND	6/28/2022	5/23/2025	10/2/2024	INSPTR	ML5474
GROVELAND	6/28/2022	5/23/2025	10/24/2024	INSPTR	NK5685
GROVELAND	6/28/2022	5/23/2025	9/16/2024	INSPTR	NK5685
GROVELAND	6/28/2022	5/23/2025	8/30/2024	INSPTR	ML5474

GROVELAND	6/28/2022	5/23/2025	9/14/2024	INSPTR	NK5685
SONORA	6/28/2022	5/24/2025	8/20/2024	INSPTR	RS8367
SONORA	6/28/2022	5/25/2025	8/7/2024	INSPTR	DG3424
SONORA	6/28/2022	5/25/2025	7/3/2024	INSPTR	DG3424
SONORA	6/28/2022	5/26/2025	8/7/2024	INSPTR	DG3424
SONORA	6/28/2022	5/25/2025	8/15/2024	INSPTR	RT1486
SONORA	6/28/2022	5/25/2025	7/3/2024	INSPTR	DG3424
SONORA	6/28/2022	5/25/2025	8/15/2024	INSPTR	RT1486
SONORA	6/28/2022	5/26/2025	7/23/2024	INSPTR	BS2864
SONORA	6/28/2022	5/26/2025	8/7/2024	INSPTR	DG3424
SONORA	6/28/2022	5/24/2025	5/24/2024	INSPTR	DG3424
SONORA	6/28/2022	5/26/2025	7/23/2024	INSPTR	BS2864
SONORA	6/28/2022	5/25/2027	5/10/2023	INSPTR	
SONORA	6/28/2022	5/25/2027	5/9/2023	INSPTR	
SONORA	6/28/2022	11/24/2022	2/23/2023	INSPTR	
TWAIN HARTE	6/28/2022	11/21/2022	5/4/2023	INSPTR	
SONORA	6/28/2022	5/25/2023	5/9/2023	INSPTR	
SONORA	6/28/2022	11/24/2022	2/19/2023	INSPTR	CR1893
PINECREST	6/28/2022	11/24/2022	8/8/2023	INSPTR	KB5463
SONORA	6/28/2022	5/25/2027	5/5/2023	INSPTR	
SONORA	6/28/2022	5/24/2027	5/5/2023	INSPTR	
SONORA	6/28/2022	5/24/2027	5/5/2023	INSPTR	

SONORA	6/28/2022	5/25/2027	5/5/2023	INSPTR
SONORA	6/28/2022	5/25/2027	5/5/2023	INSPTR
SONORA	6/28/2022	5/25/2027	5/5/2023	INSPTR
SONORA	6/28/2022	5/25/2027	5/5/2023	INSPTR
SONORA	6/28/2022	5/25/2027	5/5/2023	INSPTR
SONORA	6/28/2022	5/25/2027	5/5/2023	INSPTR
SONORA	6/28/2022	5/25/2027	5/5/2023	INSPTR
SONORA	6/28/2022	5/25/2027	5/5/2023	INSPTR
SONORA	6/28/2022	5/25/2027	5/5/2023	INSPTR
SONORA	6/28/2022	5/25/2027	5/5/2023	INSPTR
SONORA	6/28/2022	5/25/2027	5/5/2023	INSPTR
SONORA	6/28/2022	5/26/2027	5/5/2023	INSPTR
SONORA	6/28/2022	5/25/2027	5/5/2023	INSPTR
SONORA	6/28/2022	5/25/2027	5/5/2023	INSPTR
SONORA	6/28/2022	5/25/2027	5/5/2023	INSPTR
SONORA	6/28/2022	5/25/2027	5/5/2023	INSPTR
SONORA	6/28/2022	5/25/2027	5/5/2023	INSPTR
SONORA	6/28/2022	5/24/2027	5/5/2023	INSPTR
SONORA	6/28/2022	5/25/2027	5/5/2023	INSPTR
SONORA	6/28/2022	5/24/2027	5/5/2023	INSPTR
SONORA	6/28/2022	5/25/2027	5/5/2023	INSPTR
SONORA	6/28/2022	5/25/2027	5/5/2023	INSPTR
SONORA	6/28/2022	5/24/2027	5/5/2023	INSPTR

SONORA	6/28/2022	5/25/2027	5/5/2023	INSPTR
SONORA	6/28/2022	5/25/2027	5/5/2023	INSPTR
SONORA	6/28/2022	5/24/2027	5/5/2023	INSPTR
SONORA	6/28/2022	5/25/2027	5/5/2023	INSPTR
SONORA	6/28/2022	5/25/2027	5/5/2023	INSPTR
SONORA	6/28/2022	5/25/2027	5/5/2023	INSPTR
SONORA	6/28/2022	5/25/2027	5/5/2023	INSPTR
SONORA	6/28/2022	5/25/2027	5/5/2023	INSPTR
SONORA	6/28/2022	5/25/2027	5/5/2023	INSPTR
GROVELAND	6/28/2022	5/23/2027	5/5/2023	INSPTR
GROVELAND	6/28/2022	5/23/2027	5/5/2023	INSPTR
GROVELAND	6/28/2022	5/23/2027	5/5/2023	INSPTR
GROVELAND	6/28/2022	5/23/2027	5/5/2023	INSPTR
GROVELAND	6/28/2022	5/23/2027	5/5/2023	INSPTR
GROVELAND	6/28/2022	5/23/2027	5/5/2023	INSPTR
GROVELAND	6/28/2022	5/23/2027	5/5/2023	INSPTR
GROVELAND	6/28/2022	5/23/2027	5/5/2023	INSPTR
GROVELAND	6/28/2022	5/23/2027	5/5/2023	INSPTR
GROVELAND	6/28/2022	5/23/2027	5/5/2023	INSPTR
GROVELAND	6/28/2022	5/23/2027	5/5/2023	INSPTR
SONORA	6/28/2022	5/24/2027	5/5/2023	INSPTR
SONORA	6/28/2022	5/25/2027	5/5/2023	INSPTR

SONORA	6/28/2022	5/25/2027	5/5/2023	INSPTR	
SONORA	6/28/2022	5/25/2027	5/5/2023	INSPTR	
SONORA	6/28/2022	5/25/2027	5/5/2023	INSPTR	
SONORA	6/28/2022	5/25/2027	5/5/2023	INSPTR	
TWAIN HARTE	6/29/2022	5/22/2025	10/29/2024	INSPTR	KW5925
TWAIN HARTE	6/29/2022	11/25/2022	2/20/2023	INSPTR	JB8576
TWAIN HARTE	6/29/2022	5/22/2025	10/29/2024	INSPTR	ZO2856
TWAIN HARTE	6/29/2022	5/24/2025	6/11/2024	INSPTR	ET975M
TWAIN HARTE	6/29/2022	5/26/2025	10/24/2024	INSPTR	RB2924
TWAIN HARTE	6/29/2022	5/22/2025	10/30/2024	INSPTR	JB7519
TWAIN HARTE	6/29/2022	5/22/2025	10/30/2024	INSPTR	RS8367
TWAIN HARTE	6/29/2022	5/23/2025	10/30/2024	INSPTR	CF1419
TWAIN HARTE	6/29/2022	5/23/2025	10/30/2024	INSPTR	BS2864
TWAIN HARTE	6/29/2022	5/26/2025	5/28/2024	INSPTR	HC3283
TWAIN HARTE	6/29/2022	5/21/2025	10/29/2024	INSPTR	RB2924
TWAIN HARTE	6/29/2022	5/21/2025	10/29/2024	INSPTR	RS8367
TWAIN HARTE	6/29/2022	5/21/2025	9/6/2024	INSPTR	RS8367
TWAIN HARTE	6/29/2022	5/21/2025	9/11/2024	INSPTR	DG3424
TWAIN HARTE	6/29/2022	5/21/2025	10/29/2024	INSPTR	ZO2856
TWAIN HARTE	6/29/2022	5/21/2025	10/29/2024	INSPTR	RB2924
TWAIN HARTE	6/29/2022	5/22/2025	10/29/2024	INSPTR	KW5925

TWAIN HARTE	6/29/2022	5/25/2025	10/30/2024	INSPTR	TJ4856
TWAIN HARTE	6/29/2022	5/24/2025	10/30/2024	INSPTR	DG3424
TWAIN HARTE	6/29/2022	5/22/2025	10/30/2024	INSPTR	KW5925
TWAIN HARTE	6/29/2022	5/24/2025	10/24/2024	INSPTR	CR1893
TWAIN HARTE	6/29/2022	5/26/2025	8/5/2024	INSPTR	KB5463
TWAIN HARTE	6/29/2022	11/26/2022	2/20/2023	INSPTR	JB8576
TWAIN HARTE	6/29/2022	5/25/2025	10/28/2024	INSPTR	SL5436
TWAIN HARTE	6/29/2022	5/25/2027	5/15/2023	INSPTR	
TWAIN HARTE	6/29/2022	5/21/2025	9/11/2024	INSPTR	MJ1746
TWAIN HARTE	6/29/2022	5/21/2025	10/28/2024	INSPTR	RS8367
TWAIN HARTE	6/29/2022	5/21/2025	10/25/2024	INSPTR	TJ4856
TWAIN HARTE	6/29/2022	5/22/2025	10/24/2024	INSPTR	ZO2856
TWAIN HARTE	6/29/2022	5/22/2025	10/28/2024	INSPTR	SL5436
TWAIN HARTE	6/29/2022	5/23/2025	10/29/2024	INSPTR	DG3424
TWAIN HARTE	6/29/2022	5/25/2025	10/24/2024	INSPTR	CF1419
TWAIN HARTE	6/29/2022	5/22/2025	10/28/2024	INSPTR	MG5372
TWAIN HARTE	6/29/2022	5/26/2025	9/11/2024	INSPTR	CH8326
TWAIN HARTE	6/29/2022	5/21/2025	10/29/2024	INSPTR	ZO2856
TWAIN HARTE	6/29/2022	5/21/2025	9/11/2024	INSPTR	MJ1746
TWAIN HARTE	6/29/2022	5/25/2025	10/24/2024	INSPTR	TJ4856
TWAIN HARTE	6/29/2022	5/24/2025	10/24/2024	INSPTR	ZO2856
TWAIN HARTE	6/29/2022	5/24/2025	10/28/2024	INSPTR	MG5372

TWAIN HARTE	6/29/2022	5/25/2025	10/24/2024	INSPTR	CH8326
TWAIN HARTE	6/29/2022	5/22/2025	10/28/2024	INSPTR	JB8576
TWAIN HARTE	6/29/2022	5/24/2025	10/24/2024	INSPTR	ZO2856
TWAIN HARTE	6/29/2022	5/26/2027	5/15/2023	INSPTR	
TWAIN HARTE	6/29/2022	5/26/2025	6/22/2024	INSPTR	DG3424
TWAIN HARTE	6/29/2022	5/26/2027	5/15/2023	INSPTR	
TWAIN HARTE	6/29/2022	5/22/2025	10/24/2024	INSPTR	ZO2856
TWAIN HARTE	6/29/2022	5/22/2025	10/28/2024	INSPTR	MG5372
TWAIN HARTE	6/29/2022	5/23/2025	10/24/2024	INSPTR	ZO2856
TWAIN HARTE	6/29/2022	5/23/2025	10/28/2024	INSPTR	MG5372
TWAIN HARTE	6/29/2022	5/22/2025	10/28/2024	INSPTR	RB2924
TWAIN HARTE	6/29/2022	5/22/2025	10/22/2024	INSPTR	ZO2856
TWAIN HARTE	6/29/2022	5/22/2025	10/25/2024	INSPTR	RB2924
TWAIN HARTE	6/29/2022	11/25/2022	10/25/2022	INSPTR	PR2872
TWAIN HARTE	6/29/2022	5/25/2025	10/28/2024	INSPTR	JB6185
TWAIN HARTE	6/29/2022	5/22/2025	10/28/2024	INSPTR	TJ4856
TWAIN HARTE	6/29/2022	5/23/2025	10/24/2024	INSPTR	DS6453
TWAIN HARTE	6/29/2022	5/25/2025	10/21/2024	INSPTR	ZO2856
TWAIN HARTE	6/29/2022	5/25/2025	10/24/2024	INSPTR	TJ4856
TWAIN HARTE	6/29/2022	5/26/2025	10/28/2024	INSPTR	TJ4856
TWAIN HARTE	6/29/2022	5/23/2025	10/28/2024	INSPTR	MG5372
TWAIN HARTE	6/29/2022	5/26/2025	9/11/2024	INSPTR	CH8326

TWAIN HARTE	6/29/2022	5/26/2025	9/11/2024	INSPTR	CH8326
TWAIN HARTE	6/29/2022	5/23/2025	10/22/2024	INSPTR	ZO2856
TWAIN HARTE	6/29/2022	5/24/2025	10/28/2024	INSPTR	MG5372
TWAIN HARTE	6/29/2022	5/23/2025	10/22/2024	INSPTR	ZO2856
TWAIN HARTE	6/29/2022	11/22/2022	5/4/2023	INSPTR	
TWAIN HARTE	6/29/2022	5/26/2025	10/22/2024	INSPTR	ZO2856
TWAIN HARTE	6/29/2022	11/26/2022	2/19/2023	INSPTR	CS1623
TWAIN HARTE	6/29/2022	5/23/2025	10/28/2024	INSPTR	RB2924
TWAIN HARTE	6/29/2022	5/24/2025	10/24/2024	INSPTR	CR1893
TWAIN HARTE	6/29/2022	5/25/2025	9/10/2024	INSPTR	DG3424
TWAIN HARTE	6/29/2022	5/25/2025	8/30/2024	INSPTR	RS8367
TWAIN HARTE	6/29/2022	5/22/2025	6/12/2024	INSPTR	RN8732
TWAIN HARTE	6/29/2022	11/24/2022	10/26/2022	INSPTR	PR2872
TWAIN HARTE	6/29/2022	5/24/2025	10/28/2024	INSPTR	RB2924
TWAIN HARTE	6/29/2022	5/24/2025	10/28/2024	INSPTR	MG5372
TWAIN HARTE	6/29/2022	5/23/2025	9/11/2024	INSPTR	DG3424
TWAIN HARTE	6/29/2022	5/26/2025	10/24/2024	INSPTR	ZO2856
TWAIN HARTE	6/29/2022	5/22/2025	10/16/2024	INSPTR	GS3625
TWAIN HARTE	6/29/2022	5/22/2025	9/11/2024	INSPTR	BS2864
TWAIN HARTE	6/29/2022	5/23/2025	10/28/2024	INSPTR	TJ4856
TWAIN HARTE	6/29/2022	5/23/2025	9/20/2024	INSPTR	RG6161
TWAIN HARTE	6/29/2022	5/26/2025	10/28/2024	INSPTR	SL5436

TWAIN HARTE	6/29/2022	11/26/2022	5/4/2023	INSPTR	
TWAIN HARTE	6/29/2022	5/24/2027	5/15/2023	INSPTR	
TWAIN HARTE	6/29/2022	5/24/2025	10/28/2024	INSPTR	RB2924
TWAIN HARTE	6/29/2022	5/22/2025	10/16/2024	INSPTR	GS3625
TWAIN HARTE	6/29/2022	5/22/2025	9/11/2024	INSPTR	BS2864
TWAIN HARTE	6/29/2022	5/23/2025	9/19/2024	INSPTR	RG6161
TWAIN HARTE	6/29/2022	5/22/2025	10/22/2024	INSPTR	ZO2856
TWAIN HARTE	6/29/2022	5/22/2025	10/16/2024	INSPTR	GS3625
TWAIN HARTE	6/29/2022	5/23/2025	10/22/2024	INSPTR	ZO2856
TWAIN HARTE	6/29/2022	5/22/2025	10/16/2024	INSPTR	GS3625
TWAIN HARTE	6/29/2022	5/22/2025	10/16/2024	INSPTR	GS3625
TWAIN HARTE	6/29/2022	5/22/2025	10/22/2024	INSPTR	ZO2856
TWAIN HARTE	6/29/2022	5/26/2025	10/22/2024	INSPTR	ZO2856
TWAIN HARTE	6/29/2022	5/23/2025	9/20/2024	INSPTR	RG6161
TWAIN HARTE	6/29/2022	5/25/2025	9/20/2024	INSPTR	RG6161
TWAIN HARTE	6/29/2022	5/26/2025	8/23/2024	INSPTR	BS2864
TWAIN HARTE	6/29/2022	5/25/2025	9/10/2024	INSPTR	DG3424
TWAIN HARTE	6/29/2022	5/25/2025	9/20/2024	INSPTR	RG6161
TWAIN HARTE	6/29/2022	5/26/2025	8/23/2024	INSPTR	BS2864
TWAIN HARTE	6/29/2022	5/22/2025	9/19/2024	INSPTR	RG6161
TWAIN HARTE	6/29/2022	5/23/2025	9/17/2024	INSPTR	RG6161
TWAIN HARTE	6/29/2022	5/23/2025	8/29/2024	INSPTR	BS2864

TWAIN HARTE	6/29/2022	5/25/2025	8/28/2024	INSPTR	BS2864
TWAIN HARTE	6/29/2022	5/26/2025	8/23/2024	INSPTR	BS2864
TWAIN HARTE	6/29/2022	5/23/2025	9/3/2024	INSPTR	CF1419
TWAIN HARTE	6/29/2022	5/22/2025	8/29/2024	INSPTR	TJ4856
TWAIN HARTE	6/29/2022	5/26/2025	8/29/2024	INSPTR	ML5474
TWAIN HARTE	6/29/2022	5/25/2025	8/29/2024	INSPTR	BS2864
TWAIN HARTE	6/29/2022	5/22/2025	8/29/2024	INSPTR	ML5474
TWAIN HARTE	6/29/2022	5/22/2025	8/28/2024	INSPTR	BS2864
TWAIN HARTE	6/29/2022	5/26/2025	8/23/2024	INSPTR	DG3424
TWAIN HARTE	6/29/2022	5/24/2025	8/20/2024	INSPTR	BS2864
TWAIN HARTE	6/29/2022	5/24/2025	8/20/2024	INSPTR	BS2864
TWAIN HARTE	6/29/2022	5/22/2025	8/26/2024	INSPTR	BS2864
TWAIN HARTE	6/29/2022	11/25/2022	5/4/2023	INSPTR	
TWAIN HARTE	6/29/2022	5/25/2025	8/14/2024	INSPTR	EC2732
LOS BANOS	6/29/2022	6/29/2025	10/28/2022	JE8457	RD2824
COULTERVILLE	6/30/2022	5/27/2025	8/26/2024	INSPTR	BS2864
MADERA MAIN	9/2/2022	9/2/2025	9/7/2024	MS8561	JE7418
TWAIN HARTE	10/17/2022	10/20/2022	11/27/2022	HC3283	
TWAIN HARTE	10/17/2022	10/17/2025	11/27/2022	HC3283	
MERCED	1/9/2023	1/12/2023	1/11/2023	YM2794	
SONORA	10/25/2023	10/28/2023	11/3/2023	RS8367	
TWAIN HARTE	11/10/2023	11/13/2023	11/30/2023	KM1231	JB8576

PINECREST	12/7/2023	12/10/2023	12/14/2023	MR2414	
JAMESTOWN	12/15/2023	11/17/2024	5/7/2024	INSPTR	MJ1746
YOSEMITE MAIN	12/29/2023	12/14/2024	10/15/2024	INSPTR	CH2861
SONORA	1/3/2024	12/21/2024	5/2/2024	INSPTR	RB2924
SONORA	1/3/2024	12/20/2024	1/5/2024	INSPTR	KW5925
TWAIN HARTE	4/16/2024	4/19/2024	4/18/2024	KB5463	
TWAIN HARTE	5/15/2024	5/18/2024	5/30/2024	KM1231	RB2924
TWAIN HARTE	5/21/2024	5/24/2024	5/24/2024	KM1231	
CHOWCHILLA	5/22/2024	5/21/2029	6/17/2024	BB6851	AO8154
CHOWCHILLA	5/22/2024	5/24/2024	5/24/2024	BB6851	BB6851
SONORA	10/16/2024	10/19/2024	10/25/2024	ZO2856	

PACKAGE_STATUS	BPC_OWNER	TOWN	ADDRESS
Complete	TFS	Coulterville	10585 Pine Lake Dr
Complete	CON	La Grange	4080 Ladera Way
Complete	CON	La Grange	9294 Banderilla Dr
Complete	CON	La Grange	13574 Hoyito Circle
Complete	CON	Coulterville	10390 Lirio Ct
Complete	CON	La Grange	9651 Banderilla Dr
Complete	CON	La Grange	9751 Alamo Dr
Complete	CON	La Grange	13605 Molina St
Complete	CON	La Grange	9828 Torito Way
Complete	CON	La Grange	14531 Avenida Central
Complete	ENG	Coulterville	13910 Hatch Creek Ln
Complete	ENG	La Grange	3805 Castillo Way
Complete	ENG	Coulterville	3328 Chicharra Way
Complete	ENG	Coulterville	10410 Violeta Way
Complete	ENG	La Grange	9876 Villareal Dr
Complete	ENG	La Grange	2438 El Naranjo St
Complete	ENG	La Grange	14346 Potrero Way
Complete	ENG	Coulterville	3271 Granite Springs Rd
Complete	ENG	La Grange	3473 Merced Falls Rd
Complete	ENG	La Grange	9766 Villareal Dr
Complete	ENG	La Grange	9107 Capullo Circle

Complete	ENG	Coulterville	10438 Violeta Way
Complete	ENG	La Grange	9897 Villareal Dr
Complete	ENG	La Grange	10118 Banderilla Dr
Complete	ENG	La Grange	9757 Caracol Circle
Complete	ENG	La Grange	4080 Ladera Way
Complete	ENG	La Grange	9757 Mirasol Way
Complete	ENG	La Grange	9699 Paraje Way
Complete	ENG	La Grange	2045 Navarro St
Complete	ENG	La Grange	2353 Hidalgo St
Complete	TFS	El Portal	Oak Rd
Complete	TFS	El Portal	9721 Barium Mine Rd
Complete	ENG	Coulterville	3185 Chicharra Way
Complete	CON	Coulterville	3210 CA-132
Complete	TFS	Coulterville	3210 CA-132
Complete	CON	La Grange	14445 Buena Vista Ct
Complete	TFS	Coulterville	3218 CA-132
Complete	TFS	Groveland	18835 Powder House St
Complete	TFS	Groveland	11833 Powder House St
Complete	TFS	Groveland	18453 Main St
Complete	CON	La Grange	13888 Cedro Ct
Complete	TFS	Coulterville	10363 Gusanillo Way

Complete	CON	Coulterville	10363 Gusanillo Way
Complete	CON	Coulterville	10430 Blanchard Rd
Complete	CON	La Grange	12994 Bonds Flat Rd
Complete	ENG	Coulterville	3328 Chicharra Way
Complete	TFS	Coulterville	10410 Violeta Way
Complete	CON	La Grange	2398 CA-132
Complete	TFS	Coulterville	3101 Granite Springs Rd
Complete	CON	Coulterville	3101 Granite Springs Rd
Complete	CON	La Grange	3709 Castillo Way
Complete	CON	Coulterville	5754 Lozano Way
Complete	CON	La Grange	5954 Frio Ct
Complete	CON	La Grange	15088 Parra Ct
Complete	CON	La Grange	15088 Parra Ct
Complete	CON	La Grange	9232 Jalisco Way
Complete	CON	La Grange	9653 Hernandez Dr
Complete	CON	La Grange	13685 Cano Ct
Complete	CON	La Grange	13605 Molina St
Complete	ENG	Coulterville	10426 Violeta Way
Complete	CON	La Grange	9596 Banderilla Dr
Complete	ENG	La Grange	9393 Merced Falls Rd
Complete	CON	La Grange	2841 Ranchito Dr
Complete	CON	La Grange	2865 Zarzamora St

Complete	CON	Coulterville	13808 Cadena Way
Complete	CON	Coulterville	10450 Violeta Way
Complete	CON	Coulterville	10478 Lozano Way
Complete	CON	Coulterville	10347 Narcisco Way
Complete	TFS	Coulterville	10347 Narcisco Way
Complete	TFS	La Grange	9536 Banderilla Dr
Complete	TFS	La Grange	5520 Llanura Dr
Complete	TFS	La Grange	10345 Josefina Way
Complete	CON	La Grange	3686 Arbolada Dr
Complete	TFS	La Grange	2779 Merced Falls Rd
Complete	CON	La Grange	2011 Buena Vista Dr
Complete	TFS	La Grange	9457 Coronado Dr
Complete	TFS	La Grange	9401 Banderilla Dr
Complete	CON	Coulterville	10304 Narcisco Way
Complete	CON	La Grange	3535 Castillo Way
Complete	TFS	La Grange	9757 Mirasol Way
Complete	TFS	Coulterville	10294 Gusanillo Way
Complete	TFS	Coulterville	3152 Granite Springs Rd
Complete	TFS	La Grange	9194 Lazo Way
Complete	TFS	La Grange	15088 Parra Ct
Complete	TFS	Coulterville	3303 Rosa Ct
Complete	CON	La Grange	10372 Jalapa Way

Complete	ENG	Coulterville	10359 Chapulin Way
Complete	TFS	Coulterville	10387 Tulipan Way
Complete	ENG	La Grange	3299 CA-132
Complete	TFS	Coulterville	10390 Tulipan Way
Complete	TFS	La Grange	9536 Banderilla Dr
Complete	TFS	La Grange	5879 Arbolada Dr
Complete	TFS	La Grange	9401 Merced Falls Rd
Complete	TFS	La Grange	3025 CA-132
Complete	TFS	La Grange	14130 Isabel Way
Complete	TFS	Coulterville	2931 Granite Springs Rd
Complete	TFS	La Grange	9757 Caracol Circle
Complete	TFS	Coulterville	3353 Granite Springs Rd
Complete	TFS	La Grange	5606 Llanura Dr
Complete	TFS	Coulterville	3190 Azucena Ct
Complete	TFS	La Grange	14531 Potrero Way
Complete	TFS	La Grange	3561 Ladera Way
Complete	TFS	La Grange	9494 Mercado Dr
Complete	TFS	Coulterville	10312 Gusanillo Way
Complete	TFS	La Grange	2266 Golfito Way
Complete	TFS	El Portal	9738 Chapel Ln
Complete	TFS	El Portal	5563 Foresta Rd
Complete	TFS	El Portal	5052 El Portal Trailer Ct

Complete	TFS	Groveland	18763 Foote St
Complete	TFS	Yosemite National Park	Southside Dr
Complete	TFS	Yosemite National Park	El Portal Rd
Complete	CON	Soulsbyville	19450 Mountain Hope Ln
Complete	CON	Sonora	18137 Old Wards Ferry Rd
Complete	TFS	Soulsbyville	19451 Mountain Hope Ln
Complete	TFS	Soulsbyville	17170 Monte Grande Dr
Complete	TFS	Soulsbyville	19451 Mountain Hope Ln
Complete	CON	Jamestown	11310 McKibbon Dr
Complete	CON	Jamestown	18717 Mill Villa Rd
Complete	TFS	Sonora	16769 Draper Mine Rd
Complete	CON	Soulsbyville	19597 Soulsbyville Rd
Complete	CON	Sonora	16360 Lime Kiln Rd
Complete	CON	Sonora	14698 Tuolumne Rd
Complete	ENG	Jamestown	16202 Placer St
Complete	ENG	Jamestown	11310 McKibbon Dr
Complete	ENG	Jamestown	15700 Egan Rd
Complete	ENG	Jamestown	15655 Egan Rd
Complete	ENG	Jamestown	10180 Shawmut Rd
Complete	CON	Jamestown	12831 Harney Dr
Complete	TFS	Chinese Camp	13740 Red Hills Rd
Complete	ENG	Jamestown	16227 Jacksonville Rd

Complete	CON	Jamestown	13333 Red Hills Rd
Complete	CON	Jamestown	13980 Jacksonville Rd
Complete	CON	Jamestown	13440 Jacksonville Rd
Complete	TFS	Jamestown	16175 Placer St
Complete	TFS	Sonora	17860 Tinnin Rd
Complete	TFS	Sonora	20398 N Sunshine Rd
Complete	CON	Jamestown	16366 Jacksonville Rd
Complete	CON	Jamestown	16351 Lucio St
Complete	TFS	Soulsbyville	17190 Monte Grande Dr
Complete	TFS	Jamestown	13901 Park Ave
Complete	TFS	Jamestown	11112 Constance Ln
Complete	CON	Jamestown	11761 Mammoth Mine Rd
Complete	CON	Jamestown	16202 Placer St
Complete	CON	Jamestown	13900 Twist Rd
Complete	TFS	Jamestown	13913 Twist Rd
Complete	CON	Jamestown	12938 Harney Dr
Complete	TFS	Chinese Camp	13611 Red Hills Rd
Complete	TFS	Soulsbyville	19721 Soulsbyville Rd
Complete	CON	Jamestown	16351 Lucio St
Complete	TFS	Soulsbyville	19595 Soulsbyville Rd
Complete	CON	Jamestown	12938 Harney Dr
Complete	TFS	Sonora	84 Linoberg St

Complete	TFS	Sonora	801 W Stockton St
Complete	CON	Jamestown	13908 Lake Dr
Complete	CON	Jamestown	13850 Twist Rd
Complete	CON	Jamestown	13005 Kanaka Dr
Complete	TFS	Sonora	18015 Plaza Oriente Rd
Complete	TFS	Jamestown	11310 McKibbon Dr
Complete	TFS	Jamestown	11208 Circle Dr
Complete	ENG	Jamestown	11409 Jacksonville Rd
Complete	TFS	Sonora	18033 Plaza Oriente Rd
Complete	TFS	Sonora	305 W Jackson St
Complete	TFS	Soulsbyville	20408 Willow Springs Dr
Complete	ENG	Jamestown	16328 Jacksonville Rd
Complete	TFS	Jamestown	14080 Park Ave
Complete	CON	Chinese Camp	13580 Red Hills Rd
Complete	TFS	Jamestown	13003 Jacksonville Rd
Complete	ENG	Jamestown	13480 Red Hills Rd
Complete	TFS	Jamestown	11209 Circle Dr
Complete	TFS	Sonora	220 W Church St
Complete	TFS	Jamestown	13760 Park Ave
Complete	CON	Jamestown	14153 Park Ave
Complete	TFS	Sonora	18445 Hatler Dr

Complete	TFS	Jamestown	14031 Joint Venture Rd
Complete	ENG	Jamestown	12282 Wahine Dr
Complete	TFS	Jamestown	13808 Park Ave
Complete	TFS	Jamestown	10640 Quartz Alley
Complete	TFS	Chinese Camp	13740 Red Hills Rd
Complete	CON	Jamestown	14069 Jacksonville Rd
Complete	TFS	Jamestown	11292 McKibbon Dr
Complete	TFS	Sonora	17887 Elaine Way
Complete	CON	Jamestown	16351 Lucio St
Complete	ENG	Jamestown	14076 Jacksonville Rd
Complete	TFS	Sonora	18153 Old Wards Ferry Rd
Complete	CON	Jamestown	Montezuma Rd
Complete	TFS	Sonora	13520 Tres Casas
Complete	ENG	Jamestown	14145 Park Ave
Complete	CON	Jamestown	16328 Jacksonville Rd
Complete	CON	Jamestown	Montezuma Rd
Complete	TFS	Sonora	16948 Amy Dr
Complete	TFS	Sonora	4 N Forest Rd
Complete	TFS	Jamestown	13947 Park Ave
Complete	TFS	Sonora	17806 Campbell Flat Rd
Complete	TFS	Jamestown	11292 McKibbon Dr
Complete	TFS	Sonora	17922 Campbell Flat Rd

Complete	TFS	Jamestown	16120 Jacksonville Rd
Complete	TFS	Sonora	15775 Bev Barron Rd
Complete	TFS	Sonora	18165 Wards Ferry Rd
Complete	TFS	Jamestown	11209 Circle Dr
Complete	CON	Sonora	14886 Big Hill Rd
Complete	CON	Sonora	21220 Old Sonora Columbia Rd
Complete	CON	Sonora	22030 Sawmill Flat Rd
Complete	TFS	Sonora	22747 Sawmill Flat Rd
Complete	TFS	Sonora	21892 Sawmill Flat Rd
Complete	TFS	Sonora	20625 Lyons Bald Mountain Rd
Complete	TFS	Sonora	624 E Jackson St
Complete	CON	Sonora	21960 Sawmill Flat Rd
Complete	TFS	Sonora	22502 Sawmill Flat Rd
Complete	ENG	Groveland	18271 CA-120
Complete	TFS	Long Barn	29461 Shasta Dr
Complete	TFS	Sonora	15433 Camino del Parque Rd S
Complete	TFS	Sonora	14766 Rosy Ridge Ct
Complete	TFS	Sonora	21920 Sawmill Flat Rd
Complete	TFS	Sonora	14522 Old Oak Ranch Rd
Complete	TFS	Sonora	15455 Old Oak Ranch Rd
Complete	TFS	Sonora	23351 Rancho Castanea Rd
Complete	TFS	Columbia	12215 Yankee Hill Rd

Complete	TFS	Columbia	12285 Yankee Hill Rd
Complete	TFS	Sonora	22669 Sawmill Flat Rd
Complete	TFS	Groveland	11699 Merrell Rd
Complete	TFS	Groveland	10912 Merrell Rd
Complete	TFS	Groveland	18271 CA-120
Complete	TFS	Groveland	19618 Old CA-120
Complete	TFS	Groveland	11700 Merrell Rd
Complete	TFS	Groveland	20488 Whites Gulch Rd
Complete	TFS	Groveland	20601 Morgan Dr
Complete	TFS	Groveland	11293 Merrell Rd
Complete	TFS	Groveland	18500 El Capitan Way
Complete	TFS	Groveland	14000 Old CA-120
Complete	TFS	Groveland	20601 Morgan Dr
Complete	TFS	Sonora	21886 Paseo de los Portales Rd
Complete	TFS	Sonora	21732 El Puma Circle
Complete	TFS	Sonora	21929 W Crystal Falls Dr
Complete	TFS	Long Barn	29565 Yuba Ct
Complete	CON	Sonora	14650 Big Hill Rd
Complete	CON	Sonora	22030 Sawmill Flat Rd
Complete	TFS	Sonora	21241 Old Sonora Columbia Rd
Complete	TFS	Sonora	21241 Old Sonora Columbia Rd
Complete	TFS	Sonora	13829 Jenny Lind Rd

Complete	TFS	Columbia	23025 Knickerbocker Flat Rd
Complete	TFS	Columbia	12037 Yankee Hill Rd
Complete	TFS	Sonora	1194 CA-49
Complete	TFS	Sonora	22433 Gunsight Rd
Complete	TFS	Groveland	12734 Old CA-120
Complete	TFS	Sonora	21622 Crestview Dr
Complete	TFS	Sonora	21988 El Coyote Dr
Complete	TFS	Sonora	21929 W Crystal Falls Dr
Complete	TFS	Sonora	21871 Belleview Rd
Complete	TFS	Long Barn	29678 Lassen Dr
Complete	TFS	Long Barn	26566 Old Mono Rd
Complete	TFS	Long Barn	26499 Old Mono Rd
Complete	TFS	Los Banos	1060 I St
Complete	CON	Sonora	9309 CA-49
Complete	CON	Atwater	6509 Camellia Dr
Complete	CON	Merced	860 Vassar Ave
Complete	ENG	Jamestown	18760 Chabroullian Ln
Complete	CON		22556 LONGE WAY RD
Complete	TFS	Sonora	21324 Evergreen Way
Complete	TFS	Sonora	16560 S Creekside Dr
Complete	TFS	Madera	30525 Heather Ave
Complete	TFS	Coulterville	10362 Dexter Ln

Complete	TFS	Sonora	17022 Nelson Rd
Complete	TFS	Sonora	17125 Table Mountain Rd
Complete	TFS	Sonora	8920 Montezuma Rd
Complete	TFS	Sonora	11980 Shotgun Creek Dr
Complete	TFS	Sonora	15400 New Peoria Flat Rd
Complete	TFS	Chinese Camp	13790 Sims Rd
Complete	TFS	Sonora	7699 State Highway 120
Complete	CON	Sonora	8975 State Highway 120
Complete	TFS	Sonora	15325 State Highway 108
Complete	TFS	Jamestown	9870 Pulpit Rock Rd
Complete	TFS	Jamestown	18708 State Highway 108
Complete	TFS	Jamestown	10080 Mountain Vista Ct
Complete	TFS	Jamestown	17733 Woods Way
Complete	TFS	Jamestown	17556 Twin Oak Dr
Complete	TFS	Jamestown	17817 Seco St
Complete	TFS	Jamestown	10970 Golf Links Rd
Complete	TFS	Jamestown	10628 Wigwam Rd
Complete	TFS	Jamestown	17965 Seco St
Complete	TFS	Jamestown	17851 State Highway 108
Complete	TFS	Sonora	17146 Table Mountain Rd
Complete	TFS	Sonora	17141 Chicken Ranch Rd
Complete	TFS	Sonora	17171 Jeanese Dr

Complete	TFS	La Grange	3264 Bonds Flat Rd
Complete	CON	La Grange	3264 Bonds Flat Rd
Complete	TFS	Jamestown	10177 Pulpit Rock Rd
Complete	TFS	Jamestown	18151 7th Ave
Complete	TFS	Jamestown	17727 Seco St
Complete	TFS	Jamestown	17707 State Highway 108
Complete	TFS	Jamestown	17600 State Highway 108
Complete	TFS	Jamestown	18885 Rawhide Rd
Complete	TFS	Jamestown	10072 Pulpit Rock Rd
Complete	TFS	Jamestown	9890 Pulpit Rock Rd
Complete	TFS	Jamestown	17984 Harvard Mine Rd
Complete	TFS	Jamestown	9856 Pulpit Rock Rd
Complete	TFS	Jamestown	18930 Rawhide Rd
Complete	TFS	Jamestown	18431 Railbed Rd
Complete	TFS	Jamestown	18074 Seco St
Complete	TFS	Jamestown	11000 Mountain Vista Ct
Complete	TFS	Jamestown	10799 Wigwam Rd
Complete	TFS	Jamestown	18141 8th Ave
Complete	TFS	Jamestown	18517 Rawhide Rd
Complete	TFS	Jamestown	18385 5th Ave
Complete	TFS	Jamestown	18790 Rawhide Rd
Complete	TFS	Jamestown	10767 Golf Links Rd

Complete	TFS	Jamestown	17888 Harvard Mine Rd
Complete	TFS	Jamestown	9856 Pulpit Rock Rd
Complete	TFS	Jamestown	17572 Twin Oak Dr
Complete	TFS	Jamestown	17701 Seco St
Complete	TFS	Sonora	17306 Jacksonville Rd
Complete	TFS	Sonora	16446 Stamp Mill Loop Rd E
Complete	TFS	Sonora	17100 Chicken Ranch Rd
Complete	TFS	Sonora	5090 Obyrnes Ferry Rd
Complete	TFS	Sonora	15082 State Highway 108
Complete	TFS	Sonora	15109 State Highway 108
Complete	TFS	Sonora	5981 Obyrnes Ferry Rd
Complete	TFS	Sonora	5959 Obyrnes Ferry Rd
Complete	TFS	Sonora	13000 Shotgun Creek Dr
Complete	TFS	Sonora	Old Melones Dam Rd
Complete	TFS	Sonora	5170 Obyrnes Ferry Rd
Complete	TFS	Sonora	15351 New Peoria Flat Rd
Complete	TFS	Sonora	14427 Sims Rd
Complete	TFS	Sonora	15396 New Peoria Flat Rd
Complete	TFS	Sonora	5498 Obyrnes Ferry Rd
Complete	TFS	Sonora	6553 Obyrnes Ferry Rd
Complete	TFS	Sonora	5450 Obyrnes Ferry Rd
Complete	TFS	Sonora	14667 State Highway 108

Complete	TFS	Sonora	5015 Obyrnes Ferry Rd
Complete	TFS	Sonora	6783 Obyrnes Ferry Rd
Complete	TFS	Sonora	17013 Jacksonville Rd
Complete	TFS	Sonora	17151 Nelson Rd
Complete	TFS	Sonora	8553 Montezuma Rd
Complete	TFS	Sonora	8920 Montezuma Rd
Complete	CON	Chinese Camp	13333 Red Hills Rd
Complete	CON	Chinese Camp	13255 Red Hills Rd
Complete	CON	Chinese Camp	13255 Red Hills Rd
Complete	CON	Sonora	8920 Montezuma Rd
Complete	CON	Sonora	15503 State Highway 108
Complete	CON	Sonora	8937 State Highway 120
Complete	CON	Sonora	7190 Obyrnes Ferry Rd
Complete	CON	Jamestown	17733 Woods Way
Complete	CON	Jamestown	11870 Justin Ct
Complete	CON	Jamestown	8495 French Flat Rd
Complete	CON	Jamestown	18141 7th Ave
Complete	CON	Jamestown	17851 State Highway 108
Complete	CON	Jamestown	10141 Bell Mooney Rd
Complete	CON	Jamestown	17830 Woods Way
Complete	CON	Jamestown	18003 Shell Rd
Complete	CON	Sonora	10111 Hitchcock Ct

Complete	CON	Sonora	8800 Montezuma Rd
Complete	CON	Sonora	16450 State Highway 108
Complete	CON	Sonora	16996 Nelson Rd
Complete	CON	Jamestown	17600 State Highway 108
Complete	CON	Jamestown	18074 Seco St
Complete	CON	Jamestown	18385 5th Ave
Complete	CON	Jamestown	18790 Rawhide Rd
Complete	CON	Jamestown	17572 Twin Oak Dr
Complete	CON	Sonora	Montezuma Rd
Complete	CON	Sonora	17191 Chicken Ranch Rd
Complete	CON	Chinese Camp	13281 Red Hills Rd
Complete	TFS	Sonora	8920 Montezuma Rd
Complete	CON	Sonora	14649 State Highway 108
Complete	CON	Sonora	Sims Rd
Complete	CON	Sonora	8920 Montezuma Rd
Complete	CON	Sonora	16004 State Highway 108
Complete	CON	Sonora	8800 Montezuma Rd
Complete	TFS	Jamestown	18305 9th Ave
Complete	TFS	Jamestown	18515 Railbed Rd
Complete	TFS	Jamestown	17561 Harvard Mine Rd
Complete	TFS	Jamestown	18141 8th Ave
Complete	TFS	Jamestown	18238 9th Ave

Complete	TFS	Jamestown	18591 Railbed Rd
Complete	TFS	Jamestown	17712 Harvard Mine Rd
Complete	TFS	Sonora	8975 State Highway 120
Complete	TFS	Long Barn	23 Highland Way
Complete	TFS	Long Barn	28745 Herring Creek Ln
Complete	TFS	Long Barn	29380 Modoc Dr
Complete	TFS	Long Barn	29380 Modoc Dr
Complete	CON	Long Barn	28722 Herring Creek Ln
Complete	TFS	Long Barn	29682 Lassen Dr
Complete	TFS	Long Barn	29682 Lassen Dr
Complete	TFS	Long Barn	29682 Lassen Dr
Complete	CON	Long Barn	29571 Lassen Dr
Complete	TFS	Long Barn	28685 Herring Creek Ln
Complete	TFS	Long Barn	28685 Herring Creek Ln
Complete	TFS	Long Barn	29579 Yuba Ct
Complete	TFS	Long Barn	29522 Kerns Dr
Complete	TFS	Long Barn	25495 Bambi Ln
Complete	TFS	Long Barn	29970 Mariposa Dr
Complete	TFS	Groveland	18195 State Highway 120
Complete	TFS	Groveland	11700 Merrell Rd
Complete	TFS	Groveland	18601 Harper Rd
Complete	TFS	Groveland	18453 Main St

Complete	TFS	Groveland	10916 Merrell Rd
Complete	TFS	Groveland	18989 Ferretti Rd
Complete	TFS	Groveland	11255 Merrell Rd
Complete	TFS	Groveland	18537 N Dome Ct
Complete	TFS	Groveland	20892 McKinley Way
Complete	TFS	Groveland	23121 Hells Hollow Rd
Complete	TFS	Groveland	20488 Whites Gulch Rd
Complete	TFS	Groveland	20590 Morgan Dr
Complete	TFS	Groveland	11293 Merrell Rd
Complete	TFS	Groveland	21060 Morgan Dr
Complete	TFS	Groveland	21011 Morgan Dr
Complete	TFS	Groveland	19952 Big Oak Flat Rd
Complete	TFS	Groveland	20875 Morgan Dr
Complete	TFS	Sonora	22445 Gunsight Rd
Complete	TFS	Columbia	22690 Sawmill Flat Rd
Complete	CON	Columbia	12037 Yankee Hill Rd
Complete	CON	Sonora	22003 Marcus Ln
Complete	TFS	Sonora	21816 El Conejo Way
Complete	TFS	Sonora	1180 Highway 49
Complete	TFS	Sonora	21681 Fern Ln
Complete	TFS	Sonora	20390 Lyons Bald Mountain Rd
Complete	TFS	Sonora	22747 Sawmill Flat Rd

Complete	TFS	Soulsbyville	20550 Gordon Ct
Complete	TFS	Columbia	12285 Yankee Hill Rd
Complete	TFS	Sonora	21913 Fallview Dr
Complete	TFS	Sonora	21866 Phoenix Lake Rd
Complete	TFS	Sonora	453 E Jackson St
Complete	TFS	Soulsbyville	20550 Charlotte Ct
Complete	TFS	Columbia	12081 Yankee Hill Rd
Complete	TFS	Sonora	21938 El Coyote Dr
Complete	TFS	Columbia	23740 Italian Bar Rd
Complete	TFS	Sonora	16420 Creekside Dr
Complete	TFS	Sonora	15433 Camino del Parque Rd S
Complete	TFS	Sonora	15342 El Venada Trail
Complete	TFS	Soulsbyville	20537 Charlotte Ct
Complete	TFS	Sonora	580 E Oakside Dr
Complete	TFS	Sonora	15409 Camino del Parque Rd S
Complete	TFS	Sonora	20828 Lyons Bald Mountain Rd
Complete	TFS	Sonora	15520 Paseo de Los Robles Rd
Complete	TFS	Sonora	15472 Paseo de Los Robles Rd
Complete	TFS	Columbia	12252 Yankee Hill Rd
Complete	TFS	Sonora	15378 Camino del Parque Rd S
Complete	TFS	Sonora	30 Columbia Way

Complete	TFS	Sonora	20610 Columbia Way
Complete	TFS	Sonora	136 Columbia Way
Complete	TFS	Sonora	15347 Camino del Parque Rd N
Complete	TFS	Sonora	14918 Potato Ranch Rd
Complete	TFS	Sonora	15517 Paseo de Los Robles Rd
Complete	TFS	Sonora	16541 Creekside Dr
Complete	TFS	Sonora	21831 Sawmill Flat Rd
Complete	TFS	Sonora	21241 Old Sonora Columbia Rd
Complete	TFS	Sonora	15405 Danata Way
Complete	TFS	Sonora	16529 Creekside Dr
Complete	TFS	Sonora	15413 Paseo de Los Robles Rd
Complete	TFS	Sonora	136 Columbia Way
Complete	TFS	Sonora	21900 Sawmill Flat Rd
Complete	TFS	Sonora	21740 Apple Hill Dr
Complete	TFS	Sonora	16336 Creekside Dr
Complete	TFS	Sonora	429 E Jackson St
Complete	TFS	Soulsbyville	20920 Caylor Dr
Complete	TFS	Sonora	21555 Phoenix Lake Rd
Complete	TFS	Sonora	21950 Lyons Bald Mountain Rd
Complete	TFS	Soulsbyville	20680 Charlotte Ct

Complete	TFS	Sonora	15489 Camino del Parque Rd S
Complete	TFS	Sonora	21241 Old Sonora Columbia Rd
Complete	TFS	Sonora	16837 W American River Dr
Complete	TFS	Sonora	564 E Jackson St
Complete	TFS	Sonora	21551 Phoenix Lake Rd
Complete	TFS	Sonora	11910 Highway 49
Complete	TFS	Sonora	21920 Sawmill Flat Rd
Complete	TFS	Sonora	21280 Ridgeview Dr
Complete	TFS	Sonora	13457 Jenny Lind Rd
Complete	TFS	Sonora	21189 Jack Page Rd
Complete	ENG	Sonora	50 Columbia Way
Complete	TFS	Sonora	21241 Old Sonora Columbia Rd
Complete	TFS	Sonora	136 Columbia Way
Complete	TFS	Soulsbyville	20697 W Willow Springs Dr
Complete	TFS	Soulsbyville	20870 Caylor Dr
Complete	TFS	Soulsbyville	20660 Willow Springs Dr
Complete	TFS	Twain Harte	20472 Hekeke Ln
Complete	TFS	Mi-Wuk Village	20559 Kutci Dr
Complete	TFS	Twain Harte	24181 Sonora Pass Hwy
Complete	TFS	Twain Harte	18741 Middle Camp Rd

Complete	TFS	Twain Harte	23885 Yellow Pine Rd
Complete	TFS	Mi-Wuk Village	20811 Koteo Ln
Complete	TFS	Twain Harte	24029 Golf Links Dr
Complete	TFS	Mi-Wuk Village	24246 Nuka Ct
Complete	TFS	Twain Harte	18750 Beatrice Ave
Complete	TFS	Mi-Wuk Village	24214 Lama Rd
Complete	TFS	Twain Harte	18817 Middle Camp Rd
Complete	TFS	Twain Harte	23856 Pine Lake Dr
Complete	TFS	Twain Harte	20260 Lilac Ln
Complete	TFS	Mi-Wuk Village	24315 Lama Road Tamalin
Complete	TFS	Mi-Wuk Village	24776 Bonanza Dr
Complete	TFS	Mi-Wuk Village	20904 Lama Road Teumete
Complete	TFS	Mi-Wuk Village	20679 Lama Road Teumete
Complete	TFS	Mi-Wuk Village	20662 Lama Road Tamalin
Complete	TFS	Twain Harte	23532 Lakewood Dr
Complete	TFS	Twain Harte	18925 Sycamore Circle
Complete	TFS	Twain Harte	19201 Huron Dr
Complete	TFS	Mi-Wuk Village	24015 Lama Rd
Complete	TFS	Mi-Wuk Village	20751 Haiapo Rd
Complete	TFS	Mi-Wuk Village	20846 Telele Trail
Complete	TFS	Twain Harte	18803 Middle Camp Rd
Complete	TFS	Twain Harte	18774 Middle Camp Rd

Complete	TFS	Twain Harte	19837 Wanita Ln
Complete	TFS	Twain Harte	23933 Pine Lake Dr
Complete	TFS	Twain Harte	24316 Jeffrey St
Complete	TFS	Mi-Wuk Village	20734 Lama Road Teumete
Complete	TFS	Mi-Wuk Village	24233 Lama Rd
Complete	TFS	Mi-Wuk Village	24349 Jeanita Ln
Complete	TFS	Sonora	17443 Smokey River Dr
Complete	TFS	Sonora	22364 Longeway Rd
Complete	TFS	Sonora	21890 Longeway Rd
Complete	TFS	Sonora	22005 Longeway Rd
Complete	TFS	Twain Harte	22479 Ponderosa Dr
Complete	TFS	Sonora	16869 E Brookside Dr
Complete	TFS	Twain Harte	18740 Columbia Dr
Complete	TFS	Twain Harte	23747 Fremont Way
Complete	TFS	Sonora	21472 Longeway Rd
Complete	CON	Sonora	22101 Longeway Rd
Complete	TFS	Sonora	17300 Smokey River Dr
Complete	TFS	Sonora	17220 Smokey River Dr
Complete	TFS	Sonora	17100 N Colorado River Dr
Complete	TFS	Sonora	22352 Longeway Rd
Complete	TFS	Sonora	17317 Scenic Heights Dr
Complete	TFS	Twain Harte	17974 Kinglet Ct

Complete	TFS	Twain Harte	23031 Thrush Pl
Complete	TFS	Twain Harte	23295 Middle Camp Rd
Complete	TFS	Twain Harte	22991 Black Oak Dr
Complete	TFS	Twain Harte	22585 Golf Club Dr
Complete	TFS	Twain Harte	22366 Ponderosa Dr
Complete	TFS	Twain Harte	23191 Mark Twain Dr
Complete	TFS	Twain Harte	23100 Mark Twain Dr
Complete	TFS	Sonora	24049 Oxbow Ln N
Complete	TFS	Twain Harte	18558 Wildwood Dr
Complete	TFS	Sonora	24238 Oxbow Ln N
Complete	TFS	Twain Harte	19424 Superior Dr
Complete	TFS	Twain Harte	23577 Lakewood Dr
Complete	TFS	Twain Harte	18947 Huron Dr
Complete	TFS	Twain Harte	23549 Lakewood Dr
Complete	TFS	Twain Harte	19201 Huron Dr
Complete	TFS	Sonora	24025 Oxbow Ln N
Complete	TFS	Twain Harte	23564 Lakewood Dr
Complete	TFS	Twain Harte	19365 Superior Dr
Complete	TFS	Twain Harte	19429 Michigan Dr
Complete	TFS	Twain Harte	22120 N Tuolumne Rd
Complete	TFS	Twain Harte	22817 Highland Dr
Complete	TFS	Sonora	16889 E Brookside Dr

Complete	TFS	Sonora	24477 Lodge Way
Complete	TFS	Sonora	17087 E Brookside Dr
Complete	TFS	Twain Harte	23337 Tanager Dr
Complete	TFS	Twain Harte	22834 Black Hawk Dr
Complete	TFS	Twain Harte	18844 Fir Dr
Complete	TFS	Twain Harte	22523 Twain Harte Dr
Complete	TFS	Twain Harte	18826 Laurel Ave
Complete	TFS	Twain Harte	22671 Twain Harte Dr
Complete	TFS	Twain Harte	22576 Twain Harte Dr
Complete	TFS	Twain Harte	22805 Highland Dr
Complete	TFS	Twain Harte	18864 Fir Dr
Complete	TFS	Twain Harte	23394 Tanager Dr
Complete	TFS	Sonora	17155 Forest Lake Rd
Complete	TFS	Twain Harte	22118 N Tuolumne Rd
Complete	TFS	Twain Harte	21803 Confidence Rd
Complete	TFS	Twain Harte	22777 Maple Ave
Complete	TFS	Sonora	17689 Lucky Strike Trail
Complete	TFS	Sonora	21767 Longeway Rd
Complete	TFS	Sonora	22050 Fair Oaks Ct
Complete	TFS	Sonora	21350 Longeway Rd
Complete	TFS	Sonora	21245 Longeway Rd
Complete	CON	Twain Harte	24770 Tramway Rd

Complete	CON	Twain Harte	18862 Broadhurst Dr
Complete	CON	Twain Harte	20472 Hekeke Ln
Complete	CON	Mi-Wuk Village	20692 Hekeke Ln
Complete	CON	Sonora	22455 S Fork Rd
Complete	CON	Twain Harte	23191 Mark Twain Dr
Complete	CON	Sonora	16454 W Brookside Dr
Complete	CON	Sonora	24049 Oxbow Ln N
Complete	CON	Twain Harte	23025 Twain Harte Dr
Complete	CON	Twain Harte	18947 Huron Dr
Complete	CON	Sonora	24030 S Bear Clover Ct
Complete	CON	Twain Harte	19351 Middle Camp Rd
Complete	CON	Twain Harte	17962 Towhee Ln
Complete	TFS	Twain Harte	23825 Yellow Pine Rd
Complete	TFS	Twain Harte	19126 Middle Camp Rd
Complete	TFS	Mi-Wuk Village	20825 Haiapo Rd
Complete	TFS	Twain Harte	23747 Fremont Way
Complete	TFS	Twain Harte	23485 Mountain Dr
Complete	TFS	Twain Harte	23191 Mark Twain Dr
Complete	TFS	Twain Harte	23859 Marshall Way
Complete	TFS	Twain Harte	19471 Middle Camp Rd
Complete	TFS	Sonora	24030 S Bear Clover Ct
Complete	TFS	Twain Harte	19365 Superior Dr

Complete	TFS	Twain Harte	22715 Black Hawk Dr
Complete	TFS	Mi-Wuk Village	20712 Telele Trail
Complete	TFS	Sonora	22315 S Fork Rd
Complete	TFS	Sonora	22427 Gunsight Rd
Complete	CON		18299 Lime Kiln Rd
Complete	ENG	La Grange	3080-3098 CA-132
Complete	CON	Le Grand	5301-5417 S Santa Fe Ave
Complete	CON	Twain Harte	22623 Twain Harte Dr
Complete	CON	Gustine	291 Fifth St
Complete	ENG	Twain Harte	23875 S Fork Rd
Complete	CON	Madera	29590-29656 CA-145
Complete	ENG	Madera	1028 Daulton Ave
Complete	CON		RACE TRACK RD.
Complete	CON	Sonora	20 yards west of Quarry RD
Complete	TFS		TRUCKENMILLER RD.
Complete	CON		INTERSECTION HWY 108 & 120
Complete	ENG		7514 CA-120
Complete	TFS		CA-140
Complete	TFS		CA-140
Complete	TFS		CA-140
Complete	TFS		CA-140
Complete	TFS		CA-140

Complete	ENG		CA-140
Complete	TFS		CA-140
Complete	TFS	Groveland	20995 Hemlock St
Complete	TFS	Groveland	17725 Shop St
Complete	TFS	Groveland	20213 Pine Mountain Dr
Complete	TFS	Groveland	20831 Big Foot Circle
Complete	TFS	Groveland	20847 Big Foot Cir
Complete	TFS	Groveland	20148 Lower Skyridge Dr
Complete	TFS	Groveland	20550 Morgan Dr
Complete	TFS	Groveland	19584 Chaffee Circle
Complete	CON	Groveland	19749 Butler Way
Complete	TFS	Groveland	12765 Mueller Dr
Complete	TFS	Groveland	12754 Mueller Dr
Complete	TFS	Groveland	20125 Pleasantview Dr
Complete	TFS	Groveland	19600 Golden Rock Circle
Complete	ENG	Groveland	19819 Old Highway 120
Complete	TFS	Groveland	14135 Boitano Rd
Complete	TFS	Groveland	11190 Big Creek Shaft Rd
Complete	TFS	Groveland	Big Oat Flat Rd
Complete	TFS	Groveland	20709 Morgan Dr
Complete	TFS	Long Barn	28635 Herring Creek Ln
Complete	TFS	Long Barn	28635 Herring Creek Ln

Complete	TFS	Groveland	20742 Forestwood Way
Complete	TFS	Groveland	22500 Ferretti Rd
Complete	CON	Groveland	22500 Ferretti Rd
Complete	TFS	Groveland	20451 Pine Mountain Dr
Complete	TFS	Groveland	11050 S Ponderosa Way
Complete	TFS	Long Barn	31701 Quail Dr
Complete	TFS	Long Barn	31893 Whip-Poor-Will Dr
Complete	TFS	Long Barn	29005 State Highway 108
Complete	TFS	Pinecrest	353 Lakeshore Dr
Complete	TFS	Groveland	12991 Clements Rd
Complete	TFS	Big Oak Flat	17640 State Highway 120
Complete	TFS	Big Oak Flat	11170 Big Oak Rd
Complete	TFS	Big Oak Flat	17895 State Highway 120
Complete	TFS	Groveland	Cherry Lake Rd
Complete	TFS	Groveland	11450 Buck Meadows Rd
Complete	CON	Pinecrest	Lakeshore Dr
Complete	TFS	Pinecrest	Lakeshore Dr
Complete	TFS	Long Barn	28165 Meadowview Dr
Complete	TFS	Cold Springs	29599 Alpine Dr
Complete	TFS	Groveland	18497 State Highway 120
Complete	CON	Groveland	19267 Pine Mountain Dr
Complete	TFS	Groveland	19267 Pine Mountain Dr

Complete	TFS	Groveland	19415 Pine Mountain Dr
Complete	TFS	Groveland	13565 Cherry Lake Rd
Complete	TFS	Groveland	11785 Powder House St
Complete	TFS	Groveland	18521 Main St
Complete	TFS	Long Barn	29675 Lassen Dr
Complete	CON	Long Barn	29670 Lassen Dr
Complete	TFS	Long Barn	29522 Kerns Dr
Complete	CON	Long Barn	29791 Mariposa Dr
Complete	TFS	Groveland	18985 Ferretti Rd
Complete	TFS	Groveland	18971 Ferretti Rd
Complete	TFS	Long Barn	29481 Yuba Ct
Complete	TFS	Long Barn	28833 Snowwhite Ridge Dr
Complete	TFS	Long Barn	29022 Snowwhite Ridge Dr
Complete	TFS	Long Barn	29415 Old Mono Rd
Complete	TFS	Long Barn	26465 Old Mono Rd
Complete	TFS	Long Barn	29672 Butte Ct
Complete	TFS	Groveland	23350 Big Oak Flat Rd
Complete	TFS	Groveland	23350 Big Oak Flat Rd
Complete	TFS	Groveland	23350 Big Oak Flat Rd
Complete	TFS	Groveland	Big Oat Flat Rd
Complete	TFS	Groveland	Big Oat Flat Rd

Complete	TFS	Groveland	19401 Ferretti Rd
Complete	TFS	Groveland	13023 Mokelumnes Circle
Complete	TFS	Groveland	12913 Mueller Dr
Complete	TFS	Groveland	17401 State Highway 120
Complete	TFS	Groveland	23135 Hells Hollow Rd
Complete	TFS	Groveland	23350 Big Oak Flat Rd
Complete	TFS	Groveland	23121 Hells Hollow Rd
Complete	TFS	Big Oak Flat	11133 Scofield St
Complete	CON	Groveland	11971 Myer Ct
Complete	TFS	Groveland	20858 McKinley Way
Complete	TFS	Pinecrest	90 Pinecrest Ave
Complete	TFS	Pinecrest	76 Pinecrest Ave
Complete	TFS	Pinecrest	Lakeshore Dr
Complete	TFS	Long Barn	28280 Tanager Dr
Complete	TFS	Long Barn	28292 Tanager Dr
Complete	TFS	Long Barn	28243 Old Strawberry Dr
Complete	TFS	Long Barn	28124 Strawberry Dr
Complete	TFS	Long Barn	28534 Georges Dr
Complete	TFS	Long Barn	28217 Tanager Dr
Complete	TFS	Long Barn	28257 Old Strawberry Rd
Complete	TFS	Groveland	20754 Big Foot Cir
Complete	TFS	Groveland	20554 Morgan Dr

Complete	TFS	Groveland	20621 Nob Hill Circle
Complete	TFS	Groveland	12889 Green Valley Circle
Complete	TFS	Groveland	20551 Nob Hill Cir
Complete	TFS	Groveland	12767 Cresthaven Dr
Complete	TFS	Groveland	12889 Green Valley Circle
Complete	TFS	Groveland	21044 Morgan Dr
Complete	TFS	Long Barn	28429 Georges Dr
Complete	TFS	Long Barn	28484 Georges Dr
Complete	TFS	Long Barn	28288 Georges Dr
Complete	TFS	Long Barn	28141 Meadow View Dr
Complete	TFS	Long Barn	28209 Pine Ave
Complete	TFS	Long Barn	31885 Old Strawberry Rd
Complete	TFS	Long Barn	28149 Pine Ave
Complete	TFS	Groveland	12884 Green Valley Circle
Complete	CON	Groveland	12699 Mount Jefferson St
Complete	TFS	Groveland	20885 Elderberry Way
Complete	TFS	Groveland	19566 Butler Way
Complete	TFS	Groveland	11598 Noels Dirt Rd
Complete	TFS	Groveland	20012 Dunn Ct
Complete	TFS	Groveland	20002 Dunn Ct
Complete	TFS	Long Barn	31541 Wild Oats Trail
Complete	TFS	Long Barn	33427 Sonora Pass Hwy

Complete	TFS	Long Barn	30667 Old Strawberry Rd
Complete	TFS	Long Barn	29812 Mariposa Dr
Complete	TFS	Long Barn	29844 Mariposa Dr
Complete	TFS	Long Barn	28085 Pine Ave
Complete	TFS	Long Barn	28085 Pine Ave
Complete	CON	Groveland	20433 Pine Mountain Dr
Complete	TFS	Groveland	20378 Pine Mountain Dr
Complete	TFS	Groveland	20500 Echo Ct
Complete	TFS	Groveland	12475 Tannahill Dr
Complete	CON	Groveland	12475 Tannahill Dr
Complete	TFS	Long Barn	29005 State Highway 108
Complete	TFS	Long Barn	26571 Old Mono Rd
Complete	TFS	Long Barn	30000 Sonora Pass Hwy
Complete	TFS	Long Barn	30505 Old Strawberry Rd
Complete	TFS	Long Barn	30555 Old Strawberry Rd
Complete	TFS	Long Barn	30587 Old Strawberry Rd
Complete	TFS	Long Barn	28428 River Dr
Complete	TFS	Long Barn	28370 River Dr
Complete	TFS	Pinecrest	Lakeshore Dr
Complete	TFS	Groveland	13320 Cliffton Way
Complete	TFS	Groveland	20265 Pleasantview Dr
Complete	CON	Groveland	12850 Mueller Dr

Complete	CON	Groveland	12430 Punch Bowl Rd
Complete	TFS	Pinecrest	226 Sugar Pine Ave
Complete	TFS	Pinecrest	142 Rustic Rd
Complete	TFS	Pinecrest	252 Meadow View Rd
Complete	TFS	Pinecrest	224 Sugar Pine Ave
Complete	TFS	Pinecrest	132 Rustic Rd
Complete	TFS	Pinecrest	147 Rustic Rd
Complete	TFS	Pinecrest	150 Rustic Rd
Complete	TFS	Pinecrest	254 Meadow View Rd
Complete	TFS	Pinecrest	247 Meadow View Rd
Complete	TFS	Pinecrest	105 Pinecrest Lake Rd
Complete	TFS	La Grange	9902 Villarreal Dr
Complete	TFS	La Grange	5270 Arbolada Dr
Complete	TFS	La Grange	5690 Arbolada Dr
Complete	TFS	La Grange	3601 Ladera Way
Complete	TFS	La Grange	1974 Navarro St
Complete	TFS	La Grange	3650 Merced Falls Rd
Complete	TFS	La Grange	3373 Merced Falls Rd
Complete	TFS	La Grange	3891 Castillo Way
Complete	TFS	La Grange	3996 Arbolada Dr
Complete	TFS	La Grange	3050 Merced Falls Rd
Complete	TFS	La Grange	2626 Pepito Dr

Complete	TFS	La Grange	2845 Ranchito Dr
Complete	TFS	La Grange	2358 Adelfa St
Complete	TFS	La Grange	9662 Villarreal Dr
Complete	CON	La Grange	2397 Ranchito Dr
Complete	CON	La Grange	2403 Ranchito Dr
Complete	TFS	Coulterville	3159 Azucena Ct
Complete	TFS	Coulterville	3299 Rosa Ct
Complete	ENG	Coulterville	3314 Granite Springs Rd
Complete	CON	Coulterville	2815 Granite Springs Rd
Complete	CON	Coulterville	10330 Gusanillo Way
Complete	TFS	Coulterville	2844 Granite Springs Rd
Complete	TFS	Coulterville	3203 Granite Springs Rd
Complete	ENG	La Grange	9405 Coronado Dr
Complete	ENG	La Grange	9502 Coronado Dr
Complete	TFS	La Grange	9458 Coronado Dr
Complete	CON	La Grange	9508 Coronado Dr
Complete	TFS	La Grange	9637 Coronado Dr
Complete	CON	La Grange	9546 Coronado Dr
Complete	CON	La Grange	9480 Banderilla Dr
Complete	TFS	La Grange	13442 Molina St
Complete	CON	La Grange	9476 Banderilla Dr
Complete	CON	La Grange	9429 Banderilla Dr

Complete	TFS	La Grange	9410 Mojica Way
Complete	TFS	La Grange	9209 Jalisco Way
Complete	TFS	La Grange	9194 Jalisco Way
Complete	TFS	La Grange	9184 Jalisco Way
Complete	CON	La Grange	9208 Banderilla Dr
Complete	TFS	Yosemite Village	13979 Old Coulterville
Complete	TFS	Yosemite Village	13979 Old Coulterville
Complete	CON	Coulterville	10422 Blanchard Rd
Complete	TFS	La Grange	9121 Capullo Cir
Complete	CON	Coulterville	10401 Gusano Way
Complete	CON	Coulterville	10451 Gusano Way
Complete	CON	Coulterville	10447 Blanchard Rd
Complete	CON	La Grange	4542 Enramada Dr
Complete	CON	Coulterville	3001 Cadena Way
Complete	ENG	Coulterville	14770 Azucena Ct
Complete	CON	Coulterville	10401 Gusano Way
Complete	CON	La Grange	5587 Enramada Dr
Complete	ENG	La Grange	9726 Laredo St
Complete	ENG	La Grange	9748 Laredo St
Complete	TFS	La Grange	2737 Zamora St
Complete	CON	La Grange	9794 Laredo St
Complete	CON	La Grange	9762 Rastro Way

Complete	CON	La Grange	9762 Rastro Way
Complete	CON	La Grange	9824 Buena Vista Dr
Complete	TFS	La Grange	14181 Avenida Central
Complete	TFS	La Grange	14226 Avenida Central
Complete	CON	La Grange	14226 Avenida Central
Complete	CON	La Grange	14687 Avenida Central
Complete	TFS	La Grange	14615 Avenida Central
Complete	TFS	La Grange	14505 Avenida Central
Complete	ENG	La Grange	14365 Avenida Central
Complete	ENG	La Grange	1810 Buena Vista Dr
Complete	CON	La Grange	1888 Carmelita Ln
Complete	TFS	La Grange	1725 Zarzamora St
Complete	CON	La Grange	14696 Valverde
Complete	TFS	La Grange	9190 Jalisco Way
Complete	ENG	La Grange	1581 Carmelita Ln
Complete	TFS	La Grange	1770 Merced Falls Rd
Complete	ENG	Coulterville	3275 Grillo Dr
Complete	ENG	La Grange	4876 Enramada Dr
Complete	CON	Coulterville	10284 Gusanillo Way
Complete	CON	Coulterville	10288 Gusanillo Way
Complete	CON	Coulterville	10442 Chapulin Way
Complete	CON	Coulterville	3343 Jasmin Ct

Complete	ENG	Coulterville	3285 Grillo Dr
Complete	ENG	Coulterville	10304 Narciso Way
Complete	CON	La Grange	2847 Zarzamora St
Complete	CON	La Grange	2911 Zarzamora St
Complete	CON	La Grange	2928 Zarzamora St
Complete	TFS	La Grange	4649 Madreselva St
Complete	ENG	La Grange	9919 Banderilla Dr
Complete	CON	La Grange	9989 Alamo Dr
Complete	ENG	La Grange	10004 Alamo Dr
Complete	ENG	La Grange	10021 Alamo Dr
Complete	TFS	La Grange	2095 Navarro St
Complete	ENG	La Grange	2336 Pepito Dr
Complete	ENG	La Grange	14406 Potrero Way
Complete	TFS	La Grange	3111 Merced Falls Rd
Complete	TFS	La Grange	3280 State Highway 132
Complete	CON	La Grange	3819 Bonds Flat Rd
Complete	CON	La Grange	5261 Bonds Flat Rd
Complete	CON	La Grange	35 Bonds Flat Rd
Complete	ENG	La Grange	10378 Jalapa Way
Complete	CON	La Grange	10421 Jalapa Way
Complete	TFS	Fish Camp	2621 Spelt
Complete	CON	La Grange	10181 Bonds Flat Rd

Complete	TFS	Coulterville	10372 Liro Ct
Complete	TFS	Coulterville	10367 Tulipan Way
Complete	TFS	Coulterville	10368 Tulipan Way
Complete	CON	Coulterville	10406 Chapulin Way
Complete	TFS	Coulterville	14600 Azucena Ct
Complete	ENG	Coulterville	3148 Azucena Ct
Complete	CON	Coulterville	3148 Azucena Ct
Complete	CON	La Grange	12086 Bonds Flat Rd
Complete	ENG	La Grange	2403 Ranchito Dr
Complete	CON	La Grange	2320 Ranchito Dr
Complete	TFS	La Grange	9591 Carrillo Way
Complete	CON	La Grange	9582 Panchito Way
Complete	TFS	La Grange	9893 Alamo Dr
Complete	ENG	La Grange	9955 Alamo Dr
Complete	CON	La Grange	9955 Alamo Dr
Complete	ENG	La Grange	9860 Villarreal Dr
Complete	ENG	La Grange	9846 Alamo Dr
Complete	CON	La Grange	10004 Alamo Dr
Complete	CON	La Grange	10004 Alamo Dr
Complete	ENG	La Grange	9989 Alamo Dr
Complete	TFS	La Grange	9714 Picadero Way
Complete	CON	La Grange	9618 Gaza Way

Complete	CON	La Grange	2265 Golfito Way
Complete	TFS	La Grange	2265 Golfito Way
Complete	CON	La Grange	2265 Golfito Way
Complete	ENG	La Grange	9618 Gaza Way
Complete	ENG	La Grange	2265 Golfito Way
Complete	TFS	La Grange	9759 Banderilla Dr
Complete	TFS	La Grange	9703 Paraiso Blvd
Complete	CON	La Grange	9776 Carrizo Way
Complete	CON	La Grange	9811 Carrizo Way
Complete	ENG	La Grange	9897 Villarreal Dr
Complete	TFS	Coulterville	11012 Stout Ln
Complete	TFS	Coulterville	4406 Penon Blanco Rd
Complete	TFS	Coulterville	10457 Oak Ridge Ct
Complete	TFS	Coulterville	4145 Penon Blanco Rd
Complete	TFS	Coulterville	5536 Greeley Hill Rd
Complete	TFS	Coulterville	4902 State Highway 132
Complete	TFS	El Portal	9754 Redbud Ln
Complete	TFS	El Portal	5000 Trailer Ct
Complete	TFS	Coulterville	10368 Dexter Ln
Complete	TFS	Coulterville	9667 Wagner Rd

Complete	TFS	Coulterville	10162 Holtzel Rd
Complete	TFS	El Portal	9748 Redbud Ln
Complete	CON	Coulterville	10153-1015 Piney Creek Rd
Complete	CON	Coulterville	10134 Holtzel Rd
Complete	CON	Coulterville	3391 Granite Springs Rd
Complete	CON	Coulterville	10134 Holtzel Rd
Complete	CON	Coulterville	9981 Piney Creek Rd
Complete	CON	Coulterville	9998 Ernst Rd
Complete	CON	Coulterville	11046 Ernst Rd
Complete	TFS	Coulterville	10341 Dexter Ln
Complete	TFS	Coulterville	10736 Pine Lake Dr
Complete	TFS	Coulterville	6364 Greeley Hill Rd
Complete	TFS	Coulterville	10240 Holtzel Rd
Complete	TFS	Coulterville	10236 Holtzel Rd
Complete	TFS	Coulterville	9718 Texas Hill Rd
Complete	CON	Coulterville	10147 Holtzel Rd
Complete	TFS	Jamestown	15265 State Highway 108
Complete	CON	Jamestown	8553 Montezuma Rd
Complete	CON	Jamestown	16450 State Highway 108
Complete	TFS	Jamestown	16900 Chicken Ranch Rd
Complete	CON	Jamestown	16915 State Highway 108

Complete	TFS	Jamestown	Old Melones Dam Rd
Complete	TFS	Jamestown	Old Melones Dam Rd
Complete	TFS	Jamestown	9994 Washington St
Complete	TFS	Jamestown	17121 Jeni Ct
Complete	TFS	Jamestown	17405 Jacksonville Rd
Complete	TFS	Jamestown	10716 Algerine Rd
Complete	TFS	Jamestown	9300 Montezuma Rd
Complete	TFS	Jamestown	9300 Montezuma Rd
Complete	CON	Jamestown	10633 Campo Seco Rd
Complete	TFS	Jamestown	17546 Jacksonville Rd
Complete	CON	Jamestown	9879 Main St
Complete	TFS	Jamestown	11858 Justin Ct
Complete	TFS	Jamestown	11870 Justin Ct
Complete	TFS	Jamestown	15507 Peoria Flat Rd
Complete	TFS	Jamestown	18545 Railbed Rd
Complete	TFS	Jamestown	15109 State Highway 108
Complete	TFS	Jamestown	13611 Red Hills Rd
Complete	TFS	Jamestown	13773 Red Hills Rd
Complete	TFS	Jamestown	10144 Bell Mooney Rd
Complete	TFS	Jamestown	10200 Bell Mooney Rd

Complete	TFS	Jamestown	16578 Dutch Mine Rd
Complete	TFS	Jamestown	16578 Dutch Mine Rd
Complete	TFS	Jamestown	10259 Rojo Ln
Complete	TFS	Jamestown	10367 Shawmut Rd
Complete	CON	Jamestown	10484 Shawmut Rd
Complete	CON	Jamestown	10177 Pulpit Rock Rd
Complete	CON	Jamestown	10177 Pulpit Rock Rd
Complete	TFS	Jamestown	18550 Rawhide Rd
Complete	TFS	Jamestown	18790 Railbed Rd
Complete	TFS	Jamestown	9870 Pulpit Rock Rd
Complete	TFS	Jamestown	13706 Twist Rd
Complete	TFS	Jamestown	13808 Park Ave
Complete	TFS	Jamestown	14037 Jacksonville Rd
Complete	TFS	Jamestown	14069 Jacksonville Rd
Complete	CON	Jamestown	10185 Montezuma Rd
Complete	CON	Jamestown	9300 Montezuma Rd
Complete	CON	Jamestown	15540 Jumper Mine Rd
Complete	TFS	Jamestown	17671 Seco St
Complete	TFS	Jamestown	17701 Seco St
Complete	TFS	Jamestown	17992 Seco St
Complete	TFS	Jamestown	13323 Red Hills Rd

Complete	TFS	Jamestown	14145 Park Ave
Complete	TFS	Jamestown	14200 Lulu Mine Rd
Complete	TFS	Jamestown	14012 Park Ave
Complete	TFS	Jamestown	14056 Park Ave
Complete	TFS	Jamestown	14200 Lulu Mine Rd
Complete	TFS	Jamestown	14145 Park Ave
Complete	TFS	Jamestown	13708 Twist Rd
Complete	CON	Jamestown	17450 State Highway 108
Complete	CON	Jamestown	17851 State Highway 108
Complete	TFS	Jamestown	18084 Seco St
Complete	TFS	Jamestown	18595 5th Ave
Complete	TFS	Jamestown	18650 State Highway 108
Complete	TFS	Jamestown	18306 Seco St
Complete	TFS	Sonora	18155 Golden Oaks Dr
Complete	TFS	Sonora	18131 Pond View Ct
Complete	TFS	Sonora	18155 Golden Oaks Dr
Complete	TFS	Jamestown	13812 Park Ave
Complete	TFS	Jamestown	14001 Park Ave
Complete	TFS	Jamestown	13900 Twist Rd
Complete	TFS	Jamestown	13901 Park Ave
Complete	TFS	Jamestown	13901 Park Ave

Complete	TFS	Jamestown	8155 Dante Dr
Complete	TFS	Jamestown	13051 Harney Dr
Complete	TFS	Jamestown	12340 Mammoth Mine Rd
Complete	TFS	Jamestown	12808 Mammoth Mine Rd
Complete	TFS	Jamestown	12750 Mammoth Mine Rd
Complete	CON	Jamestown	17984 Harvard Mine Rd
Complete	TFS	Jamestown	17428 Harvard Mine Rd
Complete	TFS	Jamestown	17968 High School Rd
Complete	TFS	Jamestown	16971 Chicken Ranch Rd
Complete	TFS	Jamestown	17262 Jeanese Dr
Complete	CON	Jamestown	17330 High School Rd
Complete	TFS	Jamestown	8975 State Highway 120
Complete	TFS	Jamestown	8975 State Highway 120
Complete	TFS	Jamestown	14333 Perricone Rd
Complete	CON	Jamestown	17964 Seco St
Complete	TFS	Jamestown	18028 Seco St
Complete	CON	Jamestown	17868 Seco St
Complete	TFS	Jamestown	17843 Seco St
Complete	TFS	Jamestown	18110 6th Ave
Complete	TFS	Jamestown	18103 7th Ave
Complete	TFS	Jamestown	18136 8th Ave
Complete	TFS	Jamestown	13267 Red Hills Rd

Complete	TFS	Jamestown	16299 Jacksonville Rd
Complete	TFS	Jamestown	16138 Jacksonville Rd
Complete	TFS	Jamestown	16138 Jacksonville Rd
Complete	TFS	Jamestown	9489 State Hwy 120
Complete	TFS	Jamestown	9045 Friendship Hill Rd
Complete	CON	Jamestown	9090 Friendship Hill Rd
Complete	TFS	Jamestown	9060 Friendship Hill Rd
Complete	TFS	Jamestown	13001 Jacksonville Rd
Complete	TFS	Jamestown	12651 Jacksonville Rd
Complete	TFS	Jamestown	10602 7th St
Complete	TFS	Jamestown	13155 Kanaka Dr
Complete	TFS	Jamestown	18427 5th Ave
Complete	TFS	Jamestown	18427 5th Ave
Complete	TFS	Jamestown	18385 5th Ave
Complete	TFS	Jamestown	18355 5th Ave
Complete	TFS	Jamestown	18427 5th Ave
Complete	TFS	Jamestown	10607 8th Ave
Complete	TFS	Jamestown	18135 8th Ave
Complete	TFS	Jamestown	18119 7th Ave
Complete	TFS	Jamestown	18141 7th Ave
Complete	TFS	Jamestown	19601 Jamestown Rd

Complete	TFS	Jamestown	18394 State Highway 108
Complete	TFS	Jamestown	18985 Old Bridge Rd
Complete	TFS	Jamestown	10783 Golf Links Rd
Complete	TFS	Jamestown	18725 State Highway 108
Complete	TFS	Jamestown	18464 5th Ave
Complete	TFS	Jamestown	15700 Egan Rd
Complete	TFS	Jamestown	15700 Egan Rd
Complete	TFS	Jamestown	16760 Chicken Ranch Rd
Complete	TFS	Jamestown	16760 Chicken Ranch Rd
Complete	TFS	Jamestown	16755 Chicken Ranch Rd
Complete	TFS	Jamestown	16233 Stamp Mill Loop Rd
Complete	TFS	Jamestown	11025 Golf Links Rd
Complete	CON	Jamestown	18725 State Highway 108
Complete	TFS	Jamestown	10767 Golf Links Rd
Complete	TFS	Jamestown	10819 Golf Links Rd
Complete	TFS	Jamestown	10970 Golf Links Rd
Complete	TFS	Jamestown	10970 Golf Links Rd
Complete	TFS	Jamestown	10833 Golf Links Rd
Complete	TFS	Jamestown	18730 State Highway 108
Complete	TFS	Jamestown	18760 Chabroullian Ln
Complete	TFS	Jamestown	18760 Chabroullian Ln
Complete	TFS	Jamestown	18760 Chabroullian Ln

Complete	TFS	Jamestown	18720 State Highway 108
Complete	TFS	Jamestown	18188 Seco St
Complete	TFS	Jamestown	9785 Peppermint Circle
Complete	TFS	Jamestown	10089 Peppermint Circle
Complete	TFS	Jamestown	9995 Peppermint Cir
Complete	TFS	Jamestown	10101 Peppermint Circle
Complete	TFS	Jamestown	10125 Peppermint Cir
Complete	TFS	Jamestown	10647 Resevoir Rd
Complete	TFS	Jamestown	10647 Resevoir Rd
Complete	ENG	Jamestown	14337 Sims Rd
Complete	ENG	Jamestown	14355 Sims Rd
Complete	ENG	Jamestown	14387 Sims Rd
Complete	ENG	Jamestown	14431 Sims Rd
Complete	ENG	Jamestown	14301 Sims Rd
Complete	ENG	Jamestown	14301 Sims Rd
Complete	ENG	Jamestown	14301 Sims Rd
Complete	ENG	Jamestown	14489 Sims Rd
Complete	TFS	Jamestown	5090 Obyrnes Ferry Rd
Complete	ENG	Jamestown	14493 Sims Rd
Complete	TFS	Jamestown	10670 Wigwam Rd
Complete	TFS	Jamestown	18234 4th Ave

Complete	TFS	Jamestown	8800 Montezuma Rd
Complete	TFS	Jamestown	18144 Seco St
Complete	TFS	Jamestown	10678 Wigwam Rd
Complete	TFS	Jamestown	18535 5th Ave
Complete	TFS	Jamestown	18671 State Highway 108
Complete	TFS	Jamestown	8500 Montezuma Rd
Complete	TFS	Jamestown	10410 Willow St
Complete	TFS	Jamestown	10799 Wigwam Rd
Complete	CON	Jamestown	18671 State Highway 108
Complete	TFS	Jamestown	10760 Wigwam Rd
Complete	TFS	Jamestown	18650 State Highway 108
Complete	TFS	Jamestown	10636 7th St
Complete	TFS	Jamestown	18241 9th Ave
Complete	TFS	Jamestown	18241 9th Ave
Complete	CON	Jamestown	18241 9th Ave
Complete	TFS	Jamestown	18300 9th Ave
Complete	TFS	Jamestown	18230 9th Ave
Complete	TFS	Jamestown	18245 9th Ave
Complete	TFS	Jamestown	10559 Jim Brady Rd
Complete	TFS	Jamestown	10559 Jim Brady Rd
Complete	TFS	Jamestown	10579 Jim Brady Rd

Complete	TFS	TWAIN HARTE	17550 MOUNT ELIZABETH DR
Complete	CON	TWAIN HARTE	23116 middle camp rd
Complete	TFS	Twain Harte	Joaquin Gully at Wildwood
Complete	TFS	Sonora	22090 Feather River Dr
Complete	TFS	Soulsbyville	20870 Caylor Dr
Complete	TFS	Sonora	21803 Russian River Dr
Complete	TFS	Columbia	22722 Piper Ct
Complete	TFS	Columbia	10620 N Airport Rd
Complete	TFS	Columbia	10634 N Airport Rd
Complete	TFS	Sonora	22416 Lakeview Hts
Complete	TFS	Sonora	22422 Bennett Rd
Complete	TFS	Columbia	22466 Church Ln
Complete	TFS	Columbia	10706 N Airport Rd
Complete	TFS	Columbia	23020 Kumquat Ct
Complete	TFS	Columbia	10080 N Airport Rd
Complete	TFS	Sonora	634 Lyons St
Complete	TFS	Sonora	556 Lyons St
Complete	TFS	Sonora	18356 Lambert Lake Rd
Complete	TFS	Sonora	10242 Highway 49
Complete	CON	Sonora	9801 Highway 49
Complete	TFS	Sonora	13545 Mono Way
Complete	TFS	Sonora	17215 Murphy Rd

Complete	TFS	Sonora	17901 Old Wards Ferry Rd
Complete	CON	Sonora	9186 Highway 49
Complete	TFS	Columbia	23876 Italian Bar Rd
Complete	TFS	Sonora	18333 Toyon Way
Complete	TFS	Columbia	11142 State St
Complete	TFS	Sonora	18383 Corte del Montana
Complete	TFS	Columbia	12004 Yankee Hill Rd
Complete	TFS	Columbia	11500 Rocher Ct
Complete	TFS	Columbia	22411 Kennebec Ln
Complete	TFS	Sonora	22554 Upper Quail Mine Rd
Complete	TFS	Columbia	11480 Cork Oak Ln
Complete	TFS	Columbia	11480 Cork Oak Ln
Complete	TFS	Sonora	22729 Upper Quail Mine Rd
Complete	TFS	Sonora	22733 Ledge Ln
Complete	TFS	Columbia	22865 Northrup Ct
Complete	TFS	Columbia	22525 Kennebec Ln
Complete	TFS	Sonora	22734 Ledge Ln
Complete	TFS	Columbia	11784 Yankee Hill Rd
Complete	TFS	Sonora	18360 Wards Ferry Rd
Complete	CON	East Sonora	12828 Mono Way
Complete	TFS	Sonora	13744 Borden Rd
Complete	TFS	Sonora	18978 Hess Ave

Complete	CON	Sonora	842 Mono Way
Complete	TFS	Sonora	665 S Washington St
Complete	TFS	Sonora	18008 Via Serena Rd
Complete	TFS	Sonora	17945 Via Serena Rd
Complete	TFS	Sonora	17855 Via Serena Rd
Complete	TFS	Sonora	17890 Via Serena Rd
Complete	TFS	Sonora	17836 Via Serena Rd
Complete	TFS	Sonora	17836 Via Serena Rd
Complete	TFS	Sonora	17836 Via Serena Rd
Complete	TFS	Sonora	17836 Via Serena Rd
Complete	TFS	Sonora	18213 Via Serena Rd
Complete	TFS	Sonora	18320 Avenida Bonita
Complete	TFS	Sonora	18306 Corte del Montana
Complete	TFS	Sonora	18325 Avenida Bonita N
Complete	TFS	Sonora	18325 Avenida Bonita N
Complete	TFS	Jamestown	18715 Mill Villa Rd
Complete	TFS	Sonora	11814 Ellinwood Acres Rd
Complete	TFS	Sonora	18395 Corte del Montana
Complete	TFS	Sonora	17746 Lime Kiln Rd
Complete	TFS	Sonora	22624 Sawmill Flat Rd
Complete	TFS	Sonora	21911 Sawmill Flat Rd

Complete	CON	Sonora	21892 Sawmill Flat Rd
Complete	TFS	Columbia	22010 Sawmill Flat Rd
Complete	TFS	Sonora	12662 Gunsight Rd W
Complete	TFS	Sonora	10886 Racetrack Rd
Complete	TFS	Sonora	18881 Lambert Lake Rd
Complete	TFS	Sonora	14160 Kelly Loop
Complete	TFS	Sonora	18320 Wards Ferry Rd
Complete	TFS	Sonora	18446 Wards Ferry Rd
Complete	TFS	Sonora	20132 Rawhide Rd
Complete	TFS	Sonora	20023 Rawhide Rd
Complete	TFS	Sonora	19976 Rawhide Rd
Complete	TFS	Sonora	19845 Rawhide Rd
Complete	TFS	Sonora	20315 Tuttletown Rd
Complete	TFS	Sonora	21259 Paseo de Los Portales Rd
Complete	TFS	Sonora	15385 Camino Del Parque S
Complete	TFS	Sonora	15410 Camino del Parque Rd S
Complete	TFS	Sonora	20523 Jackass Hill Rd
Complete	TFS	Sonora	20694 Lower Hillview Dr
Complete	TFS	Sonora	14356 Sandy Ct
Complete	TFS	Sonora	20760 Lower Hillview Dr
Complete	TFS	Sonora	20557 Lower Hillview Dr
Complete	CON	Sonora	20073 Phoenix Lake Rd

Complete	TFS	Sonora	20747 Lower Hillview Dr
Complete	TFS	Sonora	20057 Phoenix Lake Rd
Complete	CON	Sonora	20405 Phoenix Lake Rd
Complete	TFS	Sonora	20240 Sommette Dr
Complete	TFS	Sonora	19993 Sommette Dr
Complete	TFS	Sonora	20045 Sommette Dr
Complete	TFS	Sonora	20320 Sommette Dr
Complete	TFS	Sonora	20228 Sommette Dr
Complete	CON	Sonora	18290 Wards Ferry Rd
Complete	CON	Sonora	32 Truckenmiller Rd
Complete	TFS	East Sonora	12912 Mountain View Rd
Complete	TFS	Sonora	20550 Tuttletown Rd
Complete	TFS	Sonora	18033 Plaza Oriente Rd
Complete	TFS	Sonora	17865 Via Serena Rd
Complete	TFS	Sonora	22979 Dolly Ln
Complete	TFS	Sonora	17775 Plaza Del Sur Rd
Complete	CON	Sonora	23055 Dolly Ln
Complete	TFS	Sonora	17791 Lime Rock Dr
Complete	TFS	Sonora	18007 Via Serena Rd
Complete	TFS	Sonora	18037 Lime Rock Dr
Complete	TFS	Sonora	20590 N Sunshine Rd
Complete	CON	Sonora	20590 N Sunshine Rd

Complete	TFS	Sonora	15306 Camino Del Parque S
Complete	TFS	Sonora	15306 Camino Del Parque S
Complete	TFS	Sonora	15362 Camino del Parque Rd N
Complete	TFS	Sonora	15290 Camino del Parque Rd N
Complete	TFS	Sonora	15397 El Venada Trail
Complete	TFS	Sonora	20421 Brook Dr
Complete	TFS	Sonora	20736 Lower Hillview Dr
Complete	TFS	Sonora	14398 Sandy Ct
Complete	TFS	Sonora	20668 Lower Hillview Dr
Complete	TFS	Sonora	20677 Lower Hillview Dr
Complete	TFS	Sonora	20287 Brook Dr
Complete	TFS	Sonora	20799 Lower Hillview Dr
Complete	TFS	Sonora	20437 Silver Dawn Dr
Complete	TFS	Sonora	20463 Silver Dawn Dr
Complete	TFS	Sonora	20557 Silver Dawn Dr
Complete	TFS	Sonora	20630 Silver Dawn Dr
Complete	CON	Sonora	142 Truckenmiller Rd
Complete	TFS	Sonora	19673 Cedar Rd
Complete	TFS	Sonora	19682 Pine Rd
Complete	TFS	Sonora	241 Hospital Rd
Complete	CON	Sonora	12920 Mountain View Rd
Complete	TFS	Sonora	18033 Plaza Oriente Rd

Complete	TFS	Sonora	18161 Calle Oeste Rd
Complete	TFS	Sonora	17847 Plaza del Sur Rd
Complete	TFS	Sonora	17941 Avenida Bonita
Complete	TFS	Sonora	18536 Lime Kiln Rd
Complete	TFS	Sonora	9514 Rimrock Rd
Complete	TFS	Sonora	21886 Paseo De Los Portales Rd
Complete	TFS	Sonora	16806 Chaunin Rd
Complete	TFS	Sonora	22135 Paseo De Los Portales Rd
Complete	CON	Soulsbyville	21082 Oman Dr
Complete	TFS	Sonora	20405 Phoenix Lake Rd
Complete	TFS	Sonora	20747 Lower Hillview Dr
Complete	CON	Sonora	20495 Brook Dr
Complete	TFS	Sonora	14405 Expedition Dr
Complete	TFS	Sonora	20480 Midland Dr
Complete	TFS	Sonora	20175 Sommette Dr
Complete	TFS	Sonora	20411 Midland Dr
Complete	TFS	Sonora	17965 Tinnin Rd
Complete	TFS	Sonora	17965 Tinnin Rd
Complete	TFS	Sonora	17452 Uplands Dr
Complete	TFS	Sonora	17637 Uplands Dr
Complete	TFS	Sonora	13119 Sanguinetti Rd

Complete	TFS	Sonora	9461 Rimrock Rd
Complete	TFS	Sonora	12999 Sanguinetti Rd
Complete	TFS	Sonora	12999 Sanguinetti Rd
Complete	TFS	Sonora	19573 Rawhide Rd
Complete	TFS	Sonora	74 N Stewart St
Complete	TFS	Sonora	18395 Corte del Montana
Complete	TFS	Columbia	12450 Old Home Ct
Complete	TFS	Sonora	18390 Avenida Bonita N
Complete	TFS	Sonora	18336 Avenida Bonita N
Complete	TFS	Sonora	18302 Avenida Bonita N
Complete	TFS	Sonora	22767 Sawmill Flat Rd
Complete	CON	Sonora	720 Racetrack Rd
Complete	TFS	Sonora	18971 Hess Ave
Complete	TFS	Sonora	18999 Industry Way
Complete	TFS	Sonora	20675 Gopher Dr
Complete	TFS	Sonora	16551 Wards Ferry Rd
Complete	TFS	Sonora	16551 Wards Ferry Rd
Complete	CON	Sonora	16551 Wards Ferry Rd
Complete	CON	Sonora	19673 Rawhide Rd
Complete	TFS	Sonora	18137 Old Wards Ferry Rd
Complete	CON	East Sonora	13613 Tuolumne Rd
Complete	TFS	Sonora	17806 Campbell Flat Rd

Complete	TFS	Sonora	11639 Campo Seco Rd
Complete	TFS	Sonora	13676 Tuolumne Rd
Complete	TFS	Sonora	19379 Rocky Rd
Complete	TFS	Sonora	14185 Northridge Rd
Complete	CON	Sonora	11841 Appey Way
Complete	TFS	Sonora	11798 Essen Ln
Complete	TFS	Sonora	11961 Campo Seco Rd
Complete	TFS	Sonora	20657 Gopher Dr
Complete	TFS	Sonora	18456 Wards Ferry Rd
Complete	CON	Sonora	14325 Tuolumne Rd
Complete	TFS	Sonora	19538 Rawhide Rd
Complete	TFS	Sonora	17490 Blackbird Ln
Complete	TFS	Sonora	14230 Northridge Rd
Complete	TFS	Sonora	17755 Campbells Flat Rd
Complete	TFS	Sonora	12966 Lake Valley Ln
Complete	TFS	Sonora	17807 Campbell Flat Rd
Complete	TFS	Columbia	22822 Northrup Ct
Complete	CON	Sonora	12884 Mono Way
Complete	TFS	Sonora	20391 Meadow Brook Dr
Complete	CON	Sonora	20234 Phoenix Lake Rd
Complete	TFS	Sonora	14126 Oak Knoll Rd

Complete	TFS	Sonora	14173 Oak Knoll Rd
Complete	TFS	Sonora	20135 Gibbs Dr
Complete	TFS	Sonora	20232 Gibbs Dr
Complete	TFS	Sonora	20151 Gibbs Dr
Complete	TFS	Columbia	22489 Parrotts Ferry Rd
Complete	TFS	Sonora	22176 Parrotts Ferry Rd
Complete	TFS	Sonora	18038 Lime Rock Dr
Complete	TFS	Sonora	18271 Berry Ln
Complete	TFS	Columbia	22992 Parrotts Ferry Rd
Complete	TFS	Sonora	20050 Rough and Ready Trail
Complete	TFS	Sonora	20010 Rough And Ready Trl
Complete	TFS	Sonora	19883 Panorama Pl S
Complete	TFS	Sonora	14790 Booker Rd
Complete	TFS	Sonora	14790 Booker Rd
Complete	TFS	Sonora	13561 Bergel Rd
Complete	TFS	Columbia	11511 Yankee Hill Rd
Complete	TFS	Jamestown	11147 McKibbon Dr
Complete	TFS	Sonora	21820 Parrotts Ferry Rd
Complete	TFS	Sonora	22134 Parrotts Ferry Rd
Complete	TFS	Sonora	7551 Reynolds Ferry Rd
Complete	TFS	Columbia	22652 Parrotts Ferry Rd
Complete	TFS	Sonora	11294 Damin Rd

Complete	CON	Sonora	624 E Jackson St
Complete	TFS	Sonora	447 E Oakside Dr
Complete	TFS	Sonora	585 E Oakside Dr
Complete	TFS	Sonora	18475 Lambert Lake Rd
Complete	TFS	Sonora	13656 Mark Trl
Complete	TFS	Sonora	19941 Kelly Dr
Complete	TFS	Sonora	14242 Kelly Loop
Complete	TFS	Columbia	11191 Heidi Ln
Complete	CON	Sonora	12097 Campo Seco Rd
Complete	TFS	Columbia	22668 S Gold St
Complete	TFS	Jamestown	11241 Alley Dr
Complete	TFS	Jamestown	11170 Golf Links Rd
Complete	TFS	Sonora	11564 Campo Seco Rd
Complete	TFS	Columbia	11037 Green St
Complete	TFS	Sonora	18400 Lambert Lake Rd
Complete	TFS	Sonora	18741 Olov Rd
Complete	TFS	Sonora	14000 Florence Way
Complete	TFS	Sonora	18580 Lambert Lake Rd
Complete	TFS	Sonora	14269 Kelly Loop
Complete	TFS	Sonora	18475 Olov Rd
Complete	TFS	East Sonora	21197 Lyons Bald Mountain Rd
Complete	TFS	Sonora	18280 Martin Ln

Complete	TFS	Sonora	17897 Campbells Flat Rd
Complete	TFS	Sonora	13575 Joshua Way
Complete	TFS	Sonora	18620 Lambert Lake Rd
Complete	TFS	Sonora	13922 Florence Way
Complete	TFS	Sonora	20132 High Meadow Dr
Complete	TFS	Sonora	14191 Kelly Loop
Complete	TFS	Sonora	14221 Kelly Loop
Complete	TFS	Sonora	13955 Florence Way
Complete	TFS	Sonora	18718 Olov Rd
Complete	TFS	East Sonora	13115 Sylva Ln
Complete	TFS	Sonora	14338 Kirk Alan Ln
Complete	TFS	East Sonora	21461 Apple Hill Dr
Complete	TFS	Phoenix Lake	14300 Burlupi Rd
Complete	TFS	East Sonora	14529 Lorraine Ln
Complete	TFS	East Sonora	14436 Lorraine Ln
Complete	TFS	Sonora	21797 Apple Hill Dr
Complete	TFS	Sonora	21900 Lyons Bald Mountain Rd
Complete	TFS	Phoenix Lake	14501 Phillip Ln
Complete	TFS	Sonora	21686 Apple Hill Dr
Complete	TFS	Sonora	20483 Upper Hillview Dr
Complete	CON	Sonora	20663 Upper Hillview Dr
Complete	TFS	Sonora	10815 Racetrack Rd

Complete	TFS	Sonora	17691 Lime Kiln Rd
Complete	TFS	Sonora	17691 Lime Kiln Rd
Complete	TFS	Sonora	17609 Lime Kiln Rd
Complete	TFS	Sonora	13630 Joshua Way
Complete	TFS	Sonora	13933 Tuolumne Rd
Complete	TFS	Sonora	13889 Tuolumne Rd
Complete	TFS	Sonora	13969 Tuolumne Rd
Complete	TFS	Sonora	13500 Joshua Way
Complete	CON	Sonora	13500 Joshua Way
Complete	TFS	Sonora	701 Old Bald Mountain Rd
Complete	TFS	Sonora	20513 Upper Hillview Dr
Complete	TFS	Sonora	14136 Alder Ln
Complete	TFS	Sonora	14300 Alder Ln
Complete	TFS	Sonora	20577 Meadow Brook Dr
Complete	CON	Sonora	21331 Phoenix Lake Rd
Complete	TFS	Sonora	9220 Highway 49
Complete	TFS	Sonora	14833 Peaceful Valley Rd
Complete	TFS	Sonora	21837 Feather River Dr
Complete	TFS	Sonora	13290 Terrace Dr
Complete	CON	Sonora	519 Lyons St
Complete	TFS	Sonora	519 Lyons St
Complete	TFS	Sonora	701 Old Bald Mountain Rd

Complete	TFS	Sonora	780 E Bald Mountain Rd
Complete	TFS	Sonora	447 Bald Mountain Rd N
Complete	TFS	Sonora	565 E Bald Mountain Rd
Complete	TFS	Sonora	20558 Silver Dawn Dr
Complete	CON	Sonora	19742 Ivy Ln
Complete	CON	Sonora	20537 Phoenix Lake Rd
Complete	CON	Sonora	19760 Ivy Ln
Complete	TFS	Sonora	20521 Phoenix Lake Rd
Complete	TFS	Sonora	19760 Ivy Ln
Complete	CON	Sonora	21155 Flume Rd
Complete	CON	Jamestown	19026 North Dr
Complete	CON	Sonora	12132 Campo Seco Rd
Complete	TFS	Columbia	22992 Parrotts Ferry Rd
Complete	CON	Columbia	10989 N Airport Rd
Complete	CON	Columbia	11633 Yankee Hill Rd
Complete	CON	Sonora	18175 Martin Ln
Complete	TFS	Mi-Wuk Village	24464 Pela Rd
Complete	TFS	Mi-Wuk Village	24326 Lavene Ct
Complete	TFS	Mi-Wuk Village	24431 Lavene Ln
Complete	TFS	Mi-Wuk Village	24445 Pela Rd
Complete	TFS	Sonora	17351 Mount Everest Ct
Complete	TFS	Sonora	22111 Thunderbolt Dr

Complete	TFS	Twain Harte	18930 Middle Camp Sugar Pine R
Complete	TFS	Twain Harte	23882 Marshall Way
Complete	TFS	Twain Harte	17970 Little Fuller Rd
Complete	TFS	Twain Harte	23680 State Highway 108
Complete	CON	Twain Harte	22071 Cedar Springs Rd
Complete	TFS	Mi-Wuk Village	20724 Koteo Ln
Complete	TFS	Mi-Wuk Village	20780 Koteo Ln
Complete	TFS	Twain Harte	20157 Manzanita St
Complete	TFS	Mi-Wuk Village	24287 Koteo Ct
Complete	TFS	Twain Harte	20163 Manzanita St
Complete	TFS	Mi-Wuk Village	21178 Nuggett Dr
Complete	TFS	Twain Harte	22576 Golf Club Dr
Complete	TFS	Twain Harte	22462 Golf Club Dr
Complete	TFS	Twain Harte	22461 Golf Club Dr
Complete	CON	Twain Harte	22717 Virginia Ave
Complete	TFS	Twain Harte	22717 Virginia Ave
Complete	TFS	Twain Harte	22705 Bret Harte Dr
Complete	TFS	Twain Harte	22775 Black Oak Dr
Complete	TFS	Twain Harte	22886 Golf Club Dr
Complete	TFS	Mi-Wuk Village	24312 Kome Rd
Complete	TFS	Twain Harte	23852 Marshall Way

Complete	TFS	Twain Harte	23687 Fremont Way
Complete	TFS	Sonora	16501 Oakhaven Ln
Complete	TFS	Mi-Wuk Village	20527 Kutci Dr
Complete	TFS	Twain Harte	24315 Sugar Pine Rd
Complete	TFS	Twain Harte	24315 Sugar Pine Rd
Complete	TFS	Sonora	16636 Madrone Cir
Complete	TFS	Sonora	16585 Hillside Dr
Complete	TFS	Sonora	17325 Mount Elizabeth Dr
Complete	TFS	Sonora	16498 W Brookside Dr
Complete	TFS	Sonora	16432 W Brookside Dr
Complete	TFS	Mi-Wuk Village	21241 Nugget Ave
Complete	TFS	Mi-Wuk Village	20568 Chief Fuller Rd
Complete	TFS	Sonora	22860 Meadow Ct
Complete	TFS	Sonora	22810 Meadow Ln
Complete	TFS	Sonora	17151 Nile River Dr
Complete	TFS	Sonora	22446 Colorado River Dr
Complete	TFS	Sonora	17136 Nile River Dr
Complete	TFS	Sonora	17276 Nile River Dr
Complete	TFS	Twain Harte	24281 Sugar Pine Rd
Complete	TFS	Mi-Wuk Village	24096 Lama Rd
Complete	TFS	Mi-Wuk Village	20620 Lama Rd Tamalin
Complete	TFS	Mi-Wuk Village	20635 Lama Road Tamalin

Complete	TFS	Twain Harte	24249 Sugar Pine Rd
Complete	TFS	Twain Harte	24250 Sugar Pine Rd
Complete	TFS	Mi-Wuk Village	26591 CRYSTAL
Complete	TFS	Mi-Wuk Village	25107 Merrill Springs Rd
Complete	TFS	Twain Harte	23770 Sonora Pass Hwy
Complete	TFS	Mi-Wuk Village	26555 Long Barn Ct
Complete	TFS	Mi-Wuk Village	15825 CREEK
Complete	TFS	Mi-Wuk Village	24242 Nuka Ct
Complete	TFS	Mi-Wuk Village	20704 Telele Trail
Complete	TFS	Mi-Wuk Village	20612 Hekeke Ln
Complete	TFS	Mi-Wuk Village	24733 State Highway 108
Complete	TFS	Mi-Wuk Village	24733 State Highway 108
Complete	TFS	Twain Harte	24548 Sonora Pass Hwy
Complete	TFS	Twain Harte	18806 Broadhurst Dr
Complete	TFS	Twain Harte	19360 Michigan Dr
Complete	TFS	Twain Harte	19465 Michigan Ct
Complete	TFS	Mi-Wuk Village	26464 Long Barn Ct
Complete	TFS	Mi-Wuk Village	26125 Slide Inn St
Complete	TFS	Mi-Wuk Village	25843 Long Barn Sugarpine Rd
Complete	TFS	Mi-Wuk Village	25970 Long Barn Rd
Complete	TFS	Twain Harte	19770 Six Point Ct
Complete	TFS	Sonora	24289 Awahanee Rd

Complete	TFS	Sonora	16653 Madrone Cir
Complete	TFS	Mi-Wuk Village	20998 Lama Road Teumete
Complete	TFS	Mi-Wuk Village	20993 Lama Road Teumete
Complete	TFS	Twain Harte	19011 Huron Dr
Complete	TFS	Twain Harte	23451 Lakewood Dr
Complete	TFS	Twain Harte	18950 Huron Dr
Complete	TFS	Twain Harte	19414 Superior Dr
Complete	TFS	Twain Harte	23240 Cherokee Dr
Complete	TFS	Sonora	22581 E Rhine River Dr
Complete	TFS	Mi-Wuk Village	25320 Jonathan Ln
Complete	TFS	Mi-Wuk Village	25698 Upper Scenic Dr
Complete	TFS	Twain Harte	21785 Confidence Rd
Complete	TFS	Mi-Wuk Village	25468 David Dr
Complete	TFS	Mi-Wuk Village	25435 David Dr
Complete	TFS	Mi-Wuk Village	25393 David Dr
Complete	TFS	Twain Harte	23945 Crossley Way
Complete	TFS	Twain Harte	24029 Pine Cone Rd
Complete	TFS	Twain Harte	23931 Pine Lake Dr
Complete	TFS	Twain Harte	23931 Pine Lake Dr
Complete	CON	Twain Harte	23930 Yellow Pine Rd
Complete	CON	Twain Harte	19255 Superior Dr
Complete	TFS	Twain Harte	23649 Ontario Dr

Complete	TFS	Sonora	22446 Colorado River Dr
Complete	TFS	Mi-Wuk Village	25430 Wheeler Rd
Complete	TFS	Twain Harte	22610 Confidence Rd
Complete	TFS	Twain Harte	22828 Highland Dr
Complete	TFS	Twain Harte	18844 Sequoia Ln
Complete	TFS	Sonora	16956 Broken Pine Rd
Complete	CON	Sonora	23888 Stable Rd
Complete	TFS	Mi-Wuk Village	25110 State Hwy 108
Complete	TFS	Sonora	24226 Oxbow Ln N
Complete	TFS	Mi-Wuk Village	24900 State Highway 108
Complete	TFS	Twain Harte	19011 Huron Dr
Complete	TFS	Twain Harte	23532 Lakewood Dr
Complete	TFS	Mi-Wuk Village	24650 State Highway 108
Complete	TFS	Twain Harte	22787 East Ave
Complete	TFS	Twain Harte	22547 Robin Hood Dr
Complete	TFS	Mi-Wuk Village	24347 Kiku Ln
Complete	TFS	Twain Harte	22714 Black Hawk Dr
Complete	TFS	Twain Harte	24267 Pela Rd
Complete	TFS	Sonora	24241 Oxbow Ln N
Complete	TFS	Twain Harte	24155 Red Cedar St
Complete	TFS	Twain Harte	24243 Black Oak Ct
Complete	TFS	Twain Harte	24276 White Fir Dr

Complete	TFS	Sonora	17067 Carriage Rd
Complete	TFS	Twain Harte	19215 Superior Dr
Complete	TFS	Twain Harte	19111 Middle Camp Rd
Complete	TFS	Sonora	16727 Hillside Dr
Complete	TFS	Twain Harte	19640 Michigan Dr
Complete	TFS	Mi-Wuk Village	24110 Paipu Rd
Complete	TFS	Mi-Wuk Village	20415 Kutci Dr
Complete	TFS	Mi-Wuk Village	24123 Wuuya Way
Complete	TFS	Mi-Wuk Village	20504 Kutci Dr
Complete	TFS	Mi-Wuk Village	24082 Wuuya Way
Complete	TFS	Mi-Wuk Village	24247 Sierra Park Rd
Complete	TFS	Mi-Wuk Village	20724 Koteo Ln
Complete	TFS	Mi-Wuk Village	20784 Hekeke Ln
Complete	TFS	Mi-Wuk Village	20755 Muheli Rd
Complete	TFS	Mi-Wuk Village	24279 Koteo Ct
Complete	TFS	Mi-Wuk Village	24302 Koteo Ct
Complete	CON	Sonora	23830 Buckboard Ct
Complete	TFS	Twain Harte	18414 Poppy Terrace Dr
Complete	TFS	Twain Harte	18991 Middle Camp Rd
Complete	TFS	Twain Harte	19131 Middle Camp Rd
Complete	TFS	Twain Harte	23835 Confidence South Fork Rd
Complete	TFS	Mi-Wuk Village	20851 Hiki Pl

Complete	TFS	Twain Harte	24220 S Fork Rd
Complete	TFS	Twain Harte	24174 S Fork Rd
Complete	TFS	Twain Harte	24198 S Fork Rd
Complete	TFS	Sonora	21864 Longeway Rd
Complete	TFS	Sonora	17520 Scenic Heights Dr
Complete	TFS	Mi-Wuk Village	20695 Haiapo Rd
Complete	TFS	Mi-Wuk Village	20772 Haiapo Rd
Complete	TFS	Twain Harte	22375 Ponderosa Dr
Complete	TFS	Twain Harte	22443 Ponderosa Dr
Complete	TFS	Sonora	24192 Awahanee Rd
Complete	CON	Sonora	21767 Longeway Rd
Complete	TFS	Twain Harte	18423 Marquis Dr
Complete	TFS	Twain Harte	20123 Manzanita St
Complete	TFS	Mi-Wuk Village	22364 Beersheba
Complete	TFS	Sonora	17344 Mount Elizabeth Dr
Complete	TFS	Sonora	21350 Longeway Rd
Complete	TFS	Sonora	21472 Longeway Rd
Complete	CON	Twain Harte	22615 Golf Club Dr
Complete	TFS	Twain Harte	22881 Golf Club Dr
Complete	TFS	Twain Harte	23001 Golf Club Dr
Complete	TFS	Twain Harte	17904 Good Shepherd Dr
Complete	TFS	Twain Harte	18884 Sequoia Ln

Complete	TFS	Twain Harte	22298 Twain Harte Dr
Complete	TFS	Twain Harte	22404 Mono Dr
Complete	TFS	Twain Harte	22243 Twain Harte Dr
Complete	TFS	Twain Harte	22450 Mono Dr
Complete	TFS	Twain Harte	22420 Mono Dr
Complete	TFS	Twain Harte	22486 Mono Dr
Complete	TFS	Twain Harte	22486 Mono Dr
Complete	TFS	Mi-Wuk Village	25207 Abraham Ave
Complete	TFS	Mi-Wuk Village	20811 Koteo Ln
Complete	TFS	Twain Harte	20235 Lilac Ln
Complete	TFS	Twain Harte	20260 Lilac Ln
Complete	TFS	Twain Harte	20240 Lilac Ln
Complete	TFS	Mi-Wuk Village	20890 Muheli Rd
Complete	TFS	Twain Harte	23287 Tuolumne Dr
Complete	TFS	Twain Harte	18890 Manzanita Dr
Complete	TFS	Twain Harte	23272 Cresta Dr
Complete	TFS	Twain Harte	23221 Cresta Dr
Complete	TFS	Twain Harte	22576 Twain Harte Dr
Complete	TFS	Twain Harte	22498 Sonora Dr
Complete	TFS	Twain Harte	22717 Virginia Ave
Complete	TFS	Twain Harte	22533 Golf Club Dr
Complete	TFS	Twain Harte	23464 Oriole Ln

Complete	TFS	Twain Harte	23336 Tanager Dr
Complete	TFS	Mi-Wuk Village	20910 Muheli Rd
Complete	TFS	Twain Harte	23890 Yellow Pine Rd
Complete	TFS	Mi-Wuk Village	24109 Nuka Trail
Complete	TFS	Mi-Wuk Village	24050 Wakalu Trail
Complete	TFS	Mi-Wuk Village	24144 Olo Win Trl
Complete	TFS	Mi-Wuk Village	24092 Olo-Win Trail
Complete	TFS	Mi-Wuk Village	24840 Sonora Pass Hwy
Complete	TFS	Mi-Wuk Village	24748 State Highway 108
Complete	TFS	Twain Harte	18870 Lookout Dr
Complete	TFS	Twain Harte	23187 Oak View Dr
Complete	TFS	Twain Harte	23045 Joaquin Gully Rd
Complete	CON	Twain Harte	22936 Sierra Dr
Complete	TFS	Twain Harte	22936 Sierra Dr
Complete	TFS	Twain Harte	22984 Mark Twain Dr
Complete	TFS	Twain Harte	23102 Mark Twain Dr
Complete	TFS	Twain Harte	23118 Mark Twain Dr
Complete	TFS	Twain Harte	22822 Fuller Rd
Complete	TFS	Twain Harte	22709 Fuller Rd
Complete	TFS	Twain Harte	22733 Fuller Rd
Complete	TFS	Twain Harte	23450 Oriole Ln
Complete	TFS	Twain Harte	17925 Bluejay Ct

Complete	CON	Twain Harte	23800 Pine Lake Dr
Complete	TFS	Twain Harte	23911 Redwood Dr
Complete	CON	Twain Harte	24026 Pine Lake Dr
Complete	TFS	Mi-Wuk Village	25004 Jordan Way W
Complete	TFS	Mi-Wuk Village	22150 Sarah Cir
Complete	TFS	Twain Harte	22922 Middle Camp Rd
Complete	TFS	Mi-Wuk Village	24368 Kome Rd
Complete	TFS	Mi-Wuk Village	24350 Lavene Ln
Complete	TFS	Mi-Wuk Village	21960 Sunrise Dr
Complete	TFS	Mi-Wuk Village	24399 Lavene Ln
Complete	TFS	Sonora	17264 Nile River Dr
Complete	TFS	Twain Harte	22775 Black Oak Dr
Complete	TFS	Twain Harte	22758 Bret Harte Dr
Complete	TFS	Twain Harte	22839 Miners Ave
Complete	TFS	Twain Harte	22879 Black Oak Dr
Complete	TFS	Twain Harte	22717 Virginia Ave
Complete	TFS	Twain Harte	23702 Fremont Way
Complete	TFS	Twain Harte	17854 Lark Dr
Complete	TFS	Twain Harte	17951 Robin Rd
Complete	TFS	Twain Harte	24034 Pine Lake Dr
Complete	TFS	Mi-Wuk Village	25075 Deborah Dr

Complete	CON	Twain Harte	23958 Pine Lake Dr
Complete	TFS	Mi-Wuk Village	25332 Esther Ave
Complete	TFS	Mi-Wuk Village	25215 Rebekah Rd
Complete	TFS	Twain Harte	17606 Laredo Ct
Complete	TFS	Sonora	16912 Estralita Dr
Complete	TFS	Sonora	16878 Estralita Dr
Complete	TFS	Sonora	16975 E Brookside Dr
Complete	TFS	Sonora	16796 E Brookside Dr
Complete	TFS	Sonora	16869 E Brookside Dr
Complete	TFS	Twain Harte	18661 Wildwood Dr
Complete	TFS	Twain Harte	23702 Fremont Way
Complete	TFS	Twain Harte	18751 Middle Camp Rd
Complete	TFS	Sonora	22538 W Rhine River Dr
Complete	TFS	Sonora	22280 Longeway Rd
Complete	TFS	Sonora	17689 Lucky Strike Trl
Complete	TFS	Sonora	22457 Longeway Rd
Complete	TFS	Mi-Wuk Village	25264 Rebekah Rd
Complete	TFS	Mi-Wuk Village	25254 Deborah Dr
Complete	TFS	Mi-Wuk Village	21937 Sunrise Dr
Complete	TFS	Mi-Wuk Village	25163 Rebekah Rd
Complete	TFS	Mi-Wuk Village	24934 Bottini Apple Ranch Rd
Complete	TFS	Mi-Wuk Village	22016 Lakeview Dr

Complete	TFS	Twain Harte	22951 Middle Camp Rd
Complete	TFS	Sonora	22380 Wildcat Ridge Rd
Complete	TFS	Sonora	22421 Wildcat Ridge Rd
Complete	TFS	Sonora	22483 Wildcat Ridge Rd
Complete	CON	Sonora	22535 Wildcat Ridge Rd
Complete	TFS	Sonora	16781 Big Hill Rd
Complete	CON	Twain Harte	29595 Italian Bar Rd
Complete	TFS	Twain Harte	23050 Twain Harte Dr
Complete	TFS	Sonora	13250 Shale Rock Rd
Complete	TFS	Sonora	22131 Columbia Crest Dr
Complete	TFS	Sonora	21893 Bald Mountain Rd N
Complete	TFS	Sonora	22320 Ridgemont Dr
Complete	TFS	Sonora	22211 Sawmill Flat Rd
Complete	TFS	Sonora	22039 Sawmill Flat Rd
Complete	TFS	Sonora	16647 S Creekside Dr
Complete	TFS	Sonora	16647 S Creekside Dr
Complete	TFS	Sonora	16689 S Creekside Dr
Complete	TFS	Sonora	16830 S Creekside Dr
Complete	TFS	Sonora	16689 S Creekside Dr
Complete	TFS	Sonora	11411 Highway 49
Complete	TFS	Sonora	1216 Highway 49
Complete	TFS	Sonora	15159 Victory Way

Complete	TFS	Sonora	15194 Victory Way
Complete	CON	Sonora	537 Shaws Flat Rd
Complete	TFS	Sonora	14764 Curtis Circle
Complete	TFS	Sonora	14881 Curtis Circle
Complete	TFS	Sonora	720 Shaws Flat Rd
Complete	TFS	Sonora	16250 Corte de Las Ninas
Complete	TFS	Sonora	15252 Curtis Circle
Complete	TFS	Sonora	15811 Bev Barron Rd
Complete	TFS	Sonora	582 Shaws Flat Rd
Complete	TFS	Sonora	14611 Northridge Rd
Complete	TFS	Sonora	509 S Stewart St
Complete	TFS	Sonora	400 S Stewart St
Complete	CON	East Sonora	16818 Draper Mine Rd
Complete	TFS	Sonora	14591 Northridge Rd
Complete	CON	Sonora	10834 Highway 49
Complete	CON	Sonora	21875 Shaws Flat Rd
Complete	TFS	Sonora	22067 Fallview Ln
Complete	TFS	Sonora	14599 Tuolumne Rd
Complete	TFS	Sonora	18446 Wards Ferry Rd
Complete	TFS	Sonora	14451 Tuolumne Rd
Complete	TFS	Sonora	21583 Hidden Valley Rd
Complete	TFS	Sonora	15275 Tuolumne Rd

Complete	CON	Sonora	15045 Camage Ave
Complete	TFS	Sonora	21300 Evergreen Way
Complete	TFS	Sonora	16526 Sallander Dr
Complete	TFS	Sonora	21181 Crestview Dr
Complete	CON	Sonora	21520 Bellview Creek Rd
Complete	CON	Sonora	21346 Evergreen Way
Complete	CON	Sonora	21346 Evergreen Way
Complete	TFS	Sonora	22053 Elizabeth Ln
Complete	TFS	Sonora	21984 Elizabeth Ln
Complete	CON	Sonora	85 Hope Ln
Complete	TFS	Sonora	20931 Old Phoenix Lake Rd
Complete	CON	Sonora	232 Pasadena Ave
Complete	CON	Sonora	21569 Phoenix Lake Rd
Complete	CON	Sonora	21578 Phoenix Lake Rd
Complete	CON	Sonora	21578 Phoenix Lake Rd
Complete	TFS	Sonora	21756 Water Oak Dr
Complete	TFS	Sonora	21430 Green Meadow Ln
Complete	TFS	Sonora	16740 Woodside Way
Complete	CON	Sonora	21097 Crestview Dr
Complete	TFS	Sonora	21396 Green Meadow Ln
Complete	TFS	Sonora	21720 Phoenix Lake Rd
Complete	TFS	Sonora	15275 Ridgewood Ct

Complete	TFS	Sonora	21891 Belleview Rd
Complete	TFS	Sonora	21287 American River Dr
Complete	TFS	Sonora	21348 Crestview Dr
Complete	CON	Sonora	311 S Shepherd St
Complete	TFS	Sonora	87 Upper Sunset Dr
Complete	TFS	Sonora	21197 Jack Page Rd
Complete	TFS	Sonora	2 S Forest Rd
Complete	CON	Sonora	454 W Stockton St
Complete	TFS	Sonora	21241 Old Sonora Columbia Rd
Complete	TFS	Sonora	21220 Old Sonora Columbia Rd
Complete	TFS	Sonora	11289 Highway 49
Complete	TFS	Sonora	1197 Highway 49
Complete	TFS	Sonora	45 S Shepherd St
Complete	TFS	Sonora	66 N Shepherd St
Complete	TFS	Sonora	171 N Washington St
Complete	TFS	Sonora	22284 Crystal Falls Ct
Complete	CON	Sonora	20705 Soulsbyville Rd
Complete	CON	Sonora	71 Leonard Addition Rd
Complete	TFS	Sonora	2 S Forest Rd
Complete	TFS	Sonora	23329 Rancho Castanea Rd
Complete	TFS	Sonora	4955 Poco Calle Dr
Complete	TFS	Sonora	15331 Poco Calle Dr

Complete	TFS	Groveland	10485 Moccasin Switchback Rd
Complete	TFS	Sonora	15346 Poco Calle Dr
Complete	TFS	Sonora	15549 Buena Vista Avenida
Complete	TFS	Sonora	15575 Buena Vista Avenida
Complete	TFS	Sonora	21893 Crystal Falls Dr
Complete	TFS	Sonora	21899 Russian River Dr
Complete	TFS	Sonora	444 Shaws Flat Rd
Complete	TFS	Sonora	20798 Longeway Rd
Complete	TFS	Sonora	14960 Sena Ln
Complete	CON	Sonora	19866 Mono Way
Complete	TFS	Sonora	15025 Potato Ranch Rd
Complete	TFS	Sonora	22235 Conklin Trl
Complete	CON	Sonora	22235 Conklin Trl
Complete	TFS	Columbia	13180 Mountain Boy Mine Rd
Complete	TFS	Sonora	20980 Jamestown Rd
Complete	TFS	Sonora	11007 Mount Brow Rd
Complete	TFS	Sonora	21686 Paseo De Los Portales Rd
Complete	TFS	Groveland	10445 Moccasin Switchback Rd
Complete	CON	Sonora	11031 Union Hill Rd
Complete	TFS	Groveland	12 COOPER
Complete	TFS	Sonora	20962 Maurice Ln
Complete	CON	Sonora	21072 Maurice Ln

Complete	CON	Sonora	17179 Alderman Rd
Complete	TFS	Sonora	21162 Longeway Rd
Complete	TFS	Sonora	22021 El Coyote Dr
Complete	TFS	Sonora	16335 Draper Mine Rd
Complete	CON	Sonora	15045 Camage Ave
Complete	CON	Sonora	18527 Standard Rd
Complete	CON	Sonora	18798 Standard Rd
Complete	CON	Sonora	18490 Standard Rd
Complete	TFS	Jamestown	14420 Twist Rd
Complete	TFS	Sonora	20894 Lyons Bald Mountain Rd
Complete	TFS	Sonora	21618 Crystal Falls Dr
Complete	TFS	Sonora	21677 Crystal Lake Dr
Complete	TFS	Sonora	21626 Wasatch Mountain Rd
Complete	TFS	Sonora	21626 Wasatch Mountain Rd
Complete	TFS	Sonora	21195 Longeway Rd
Complete	TFS	Sonora	21184 Longeway Rd
Complete	CON	Sonora	19632 Mono Way
Complete	TFS	Sonora	19966 Sommette Dr
Complete	TFS	Jamestown	14420 Twist Rd
Complete	TFS	Sonora	16869 Chaunin Rd
Complete	TFS	Sonora	15021 Camage Ave
Complete	CON	Sonora	14900 Camage Ave

Complete	CON	Sonora	16185 Tuolumne Rd
Complete	TFS	Sonora	22240 Paseo De Los Portales Rd
Complete	TFS	Sonora	22295 Paseo de Los Portales Rd
Complete	TFS	East Sonora	21522 Paseo de Los Portales Rd
Complete	TFS	Sonora	22240 Paseo De Los Portales Rd
Complete	ENG	Sonora	22150 Paseo De Los Portales Rd
Complete	ENG	Sonora	10683 Mountain Brow Rd
Complete	TFS	Sonora	15690 Allenby Dr
Complete	TFS	Jamestown	19909 Peppermint Falls Rd
Complete	CON	Sonora	330 Calaveras Way
Complete	TFS	Sonora	16526 Creekside Dr
Complete	TFS	Sonora	300 Bonanza Rd
Complete	TFS	Sonora	16558 Creekside Dr
Complete	CON	Sonora	16590 Creekside Dr
Complete	TFS	Sonora	18601 Zekarias Ct
Complete	CON	Sonora	15980 Morris Rd
Complete	ENG	Sonora	15925 Morris Rd
Complete	TFS	Sonora	15925 Morris Rd
Complete	CON	Sonora	16009 Morris Rd
Complete	TFS	Sonora	15961 Morris Rd
Complete	CON	Sonora	16057 Morris Rd
Complete	CON	Sonora	18210 Aarondale Rd

Complete	TFS	Sonora	10731 Mountain Brow Rd
Complete	ENG	Sonora	10731 Mountain Brow Rd
Complete	ENG	Sonora	10858 Mountain Brow Rd
Complete	TFS	Sonora	21848 El Oso Way
Complete	CON	Sonora	8773 Fraguero Rd
Complete	TFS	Sonora	8773 Fraguero Rd
Complete	TFS	Sonora	21686 Paseo De Los Portales Rd
Complete	TFS	Sonora	15496 Paseo De Los Robles Rd
Complete	TFS	Sonora	21748 El Puma Cir
Complete	CON	Sonora	16572 Creekside Dr
Complete	ENG	Sonora	21707 Phoenix Lake Rd
Complete	TFS	Sonora	236 Sylvan Dr
Complete	CON	Sonora	15380 Country Club Ln
Complete	TFS	Sonora	73 Elm St
Complete	CON	Sonora	21370 Shaws Flat Rd
Complete	TFS	Sonora	21348 Shaws Flat Rd
Complete	TFS	Sonora	16857 June Ct
Complete	TFS	Sonora	16899 Tehachapi Ct
Complete	TFS	Sonora	18351 Aarondale Rd
Complete	TFS	Sonora	18351 Aarondale Rd
Complete	TFS	Sonora	17691 Delores Ln
Complete	TFS	Sonora	18130 Aarondale Rd

Complete	TFS	Sonora	21716 El Puma Cir
Complete	TFS	Sonora	21734 El Puma Circle
Complete	ENG	Sonora	19404 Rockridge Way
Complete	ENG	Sonora	16985 W American River Dr
Complete	ENG	Sonora	16956 W American River Dr
Complete	TFS	Sonora	16902 W American River Dr
Complete	TFS	Sonora	203 Theall St
Complete	CON	Sonora	235 Theall St
Complete	TFS	Sonora	16860 Tehachapi Ct
Complete	ENG	Sonora	594 High St
Complete	CON	Sonora	31 William St
Complete	TFS	Sonora	21379 Crystal Falls Dr
Complete	TFS	Sonora	21352 Crystal Falls Dr
Complete	CON	Sonora	16837 W American River Dr
Complete	CON	Sonora	14280 Mono Way
Complete	TFS	Sonora	20142 Dambacher Dr
Complete	CON	Sonora	20142 Dambacher Dr
Complete	CON	Sonora	20142 Dambacher Dr
Complete	ENG	Sonora	20884 Old Phoenix Lake Rd
Complete	TFS	Sonora	21528 Crestview Dr
Complete	TFS	Sonora	21390 Green Meadow Ln
Complete	CON	Sonora	21650 Bellview Creek Rd

Complete	TFS	Sonora	21546 Bellview Creek Rd
Complete	CON	Sonora	21583 Hidden Valley Rd
Complete	TFS	Sonora	21200 Crestview Dr
Complete	TFS	Sonora	21501 American River Dr
Complete	CON	Sonora	11455 Highway 49
Complete	TFS	Sonora	16555 S Creekside Dr
Complete	TFS	Sonora	16545 S Creekside Dr
Complete	CON	Sonora	21572 Bellview Creek Rd
Complete	TFS	Soulsbyville	19847 Soulsbyville Rd
Complete	CON	Sonora	16591 Sallander Dr
Complete	TFS	Sonora	21952 Phoenix Lake Rd
Complete	CON	Sonora	101 Pine St
Complete	CON	Sonora	75 Yaney Ave
Complete	ENG	Sonora	16420 Parkridge Ave
Complete	TFS	Sonora	11944 Campo Seco Rd
Complete	TFS	Sonora	21373 Green Meadow Ln
Complete	TFS	Long Barn	29461 Shasta Dr
Complete	TFS	Long Barn	29831 Mono Trl
Complete	TFS	Long Barn	25590 Bambi Ln
Complete	TFS	Long Barn	26579 Old Mono Rd
Complete	TFS	Long Barn	29651 Lassen Dr
Complete	TFS	Long Barn	29678 Lassen Dr

Complete	TFS	Long Barn	29970 Mariposa Dr
Complete	TFS	Long Barn	29723 Mono Trail
Complete	TFS	Mi-Wuk Village	25293 Rebekah Rd
Complete	TFS	Mi-Wuk Village	24881 Sonora Pass Hwy
Complete	TFS	Mi-Wuk Village	25986 Long Barn Rd
Complete	TFS	Mi-Wuk Village	25198 Deborah Dr
Complete	TFS	Mi-Wuk Village	24023 N Fork Rd
Complete	TFS	Mi-Wuk Village	25970 Long Barn Rd
Complete	TFS	Mi-Wuk Village	22000 Lakeview Dr
Complete	TFS	Mi-Wuk Village	24822 Quartz Ave
Complete	TFS	Mi-Wuk Village	22305 Jesse
Complete	TFS	Mi-Wuk Village	24791 Quartz Ave
Complete	TFS	Mi-Wuk Village	22150 Sarah Cir
Complete	TFS	Mi-Wuk Village	25163 Rebekah Rd
Complete	TFS	Mi-Wuk Village	22165 Sarah Circle
Complete	TFS	Mi-Wuk Village	25744 Long Barn Sugar Pine Rd
Complete	TFS	Soulsbyville	20020 Blackberry Ln
Complete	TFS	Groveland	20601 Morgan Dr
Complete	TFS	Groveland	20715 Morgan Dr
Complete	TFS	Groveland	19048 Second Garrotte Ridge Rd
Complete	TFS	Groveland	21014 Morgan Dr
Complete	TFS	Groveland	10085 Merrell Rd

Complete	TFS	Groveland	20401 Whites Gulch Rd
Complete	TFS	Sonora	21583 Hidden Valley Rd
Complete	TFS	Sonora	483 E Jackson St
Complete	TFS	Sonora	22460 Gunsight Rd
Complete	TFS	Sonora	11928 Highway 49
Complete	TFS	Sonora	449 Lyons St
Complete	TFS	Sonora	22288 Gunsight Rd
Complete	TFS	Sonora	13457 Jenny Lind Rd
Complete	TFS	Sonora	21220 Old Sonora Columbia Rd
Complete	TFS	Sonora	1199 Highway 49
Complete	TFS	Sonora	21748 El Oso Way
Complete	TFS	Sonora	21241 Old Sonora Columbia Rd
Complete	CON	Sonora	16537 Creekside Dr
Complete	CON	Sonora	21692 Bellview Creek Rd
Complete	CON	Sonora	21491 Phoenix Lake Rd
Complete	CON	Mi-Wuk Village	22859 E Ellmaro
Complete	CON	Sonora	449 Lyons St
Complete	TFS	Sonora	15401 Camino Del Parque S
Complete	TFS	Long Barn	31700 Old Strawberry Rd
Complete	ENG	Sonora	22387 Belleview Rd
Complete	ENG	Sonora	22150 Paseo De Los Portales Rd
Complete	ENG	Sonora	21820 Paseo De Los Portales Rd

Complete	ENG	Sonora	21892 Glenwood Rd
Complete	ENG	Sonora	21667 Crystal Lake Dr
Complete	ENG	Sonora	21825 Phoenix Lake Rd
Complete	ENG	Sonora	16542 Creekside Dr
Complete	ENG	Sonora	13324 Shale Rock Rd
Complete	ENG	Sonora	16670 Granite Ridge Ln
Complete	ENG	Sonora	16964 W American River Dr
Complete	ENG	Sonora	22141 Crystal Falls Dr
Complete	ENG	Sonora	21756 Water Oak Dr
Complete	ENG	Mono Vista	21346 Evergreen Way
Complete	ENG	Sonora	22451 Spring Creek Rd
Complete	ENG	Sonora	22404 Gunsight Rd
Complete	ENG	Sonora	16980 Columbia River Dr
Complete	ENG	Sonora	16990 W American River Dr
Complete	ENG	Sonora	13707 Jenny Lind Rd
Complete	ENG	Soulsbyville	20525 Charlotte Ct
Complete	ENG	Sonora	16503 Creekside Dr
Complete	ENG	Soulsbyville	20680 Charlotte Ct
Complete	ENG	Sonora	15559 Del Parque Ct
Complete	ENG	Sonora	21301 American River Dr
Complete	ENG	Sonora	16548 S Creekside Dr
Complete	ENG	Sonora	15424 Paseo De Los Robles Rd

Complete	ENG	Sonora	22265 Crystal Falls Ct
Complete	ENG	Sonora	16555 S Creekside Dr
Complete	ENG	Sonora	21778 El Coyote Dr
Complete	ENG	Sonora	16932 W American River Dr
Complete	ENG	Soulsbyville	17384 Carlozzi Dr
Complete	ENG	Soulsbyville	20615 Steven Ct
Complete	ENG	Sonora	21639 Crystal Lake Dr
Complete	ENG	Sonora	16080 Hidden Valley Rd
Complete	ENG	Sonora	21379 Crystal Falls Dr
Complete	ENG	Groveland	11050 S Ponderosa Way
Complete	ENG	Groveland	19048 Second Garrotte Ridge Rd
Complete	ENG	Groveland	23071 Hells Hollow Rd
Complete	ENG	Groveland	11220 Inspiration Dr
Complete	ENG	Groveland	20010 Cherokee Trl
Complete	ENG	Groveland	19701 Old Highway 120
Complete	ENG	Groveland	20892 McKinley Way
Complete	ENG	Groveland	20010 Cherokee Trl
Complete	ENG	Groveland	10831 Merrell Rd
Complete	ENG	Groveland	19060 Second Garrotte Ridge Rd
Complete	ENG	Groveland	11090 Yosemite Springs Rd
Complete	ENG	Sonora	15485 Paseo De Los Robles Rd
Complete	ENG	Sonora	21488 American River Dr

Complete	ENG	Sonora	16879 W American River Dr
Complete	ENG	Soulsbyville	17326 Kelleher Ct
Complete	ENG	Mono Vista	21301 Ridgeview Dr
Complete	ENG	Sonora	21413 Green Oaks Ct
Complete	TFS	Twain Harte	23918 Redwood Dr
Complete	TFS	Sonora	17545 Mount Elizabeth Dr
Complete	TFS	Mi-Wuk Village	21101 Taismu Ct
Complete	TFS	Twain Harte	23310 Sonora Pass Hwy
Complete	TFS	Sonora	17765 Good Shepherd Dr
Complete	TFS	Twain Harte	23945 Crossley Way
Complete	TFS	Mi-Wuk Village	20720 Chief Fuller Rd
Complete	TFS	Twain Harte	19495 Confidence Mine Ct
Complete	TFS	Twain Harte	23705 Sonora Pass Hwy
Complete	TFS	Sonora	17710 Lucky Strike Trl
Complete	TFS	Mi-Wuk Village	26591 Crystal Rd
Complete	TFS	Mi-Wuk Village	24934 Bottini Apple Ranch Rd
Complete	TFS	Mi-Wuk Village	25880 Long Barn Rd
Complete	TFS	Mi-Wuk Village	25088 Sonora Pass Hwy
Complete	TFS	Mi-Wuk Village	25096 Deborah Dr
Complete	TFS	Mi-Wuk Village	25312 Esther Ave
Complete	TFS	Twain Harte	23957 Redwood Ct

Complete	TFS	Twain Harte	22919 Meadow Dr
Complete	TFS	Twain Harte	24220 S Fork Rd
Complete	TFS	Twain Harte	24211 Golf Links Dr
Complete	TFS	Twain Harte	18911 Middle Camp Rd
Complete	TFS	Sonora	17220 Smokey River Dr
Complete	TFS	Sonora	17220 Smokey River Dr
Complete	TFS	Sonora	24471 Quarter Horse Dr
Complete	CON	Twain Harte	18443 Hillcrest Rd
Complete	TFS	Mi-Wuk Village	25110 Sonora Pass Hwy
Complete	TFS	Mi-Wuk Village	25375 David Dr
Complete	TFS	Mi-Wuk Village	22364 Beersheba
Complete	TFS	Mi-Wuk Village	20846 Telele Trl
Complete	TFS	Twain Harte	23937 Pine Lake Dr
Complete	TFS	Twain Harte	24295 Juniper St
Complete	TFS	Sonora	16669 Madrone Cir
Complete	TFS	Twain Harte	23954 Pine Lake Dr
Complete	TFS	Sonora	22533 Longeway Rd
Complete	TFS	Mi-Wuk Village	25210 Abraham Ave
Complete	TFS	Mi-Wuk Village	24967 Sonora Pass Hwy
Complete	TFS	Sonora	17344 Mount Elizabeth Dr
Complete	TFS	Twain Harte	22524 Little John Dr
Complete	TFS	Twain Harte	23233 Cresta Dr

Complete	TFS	Sonora	17081 Carriage Rd
Complete	TFS	Twain Harte	24046 Golf Links Dr
Complete	TFS	Twain Harte	19775 Westview Dr
Complete	CON	Sonora	22918 Lazy Z Ln
Complete	TFS	Sonora	16961 Broken Pine Rd
Complete	CON	Sonora	22932 Lazy Z Ln
Complete	TFS	Mi-Wuk Village	20911 Lama Road Tamalin
Complete	TFS	Mi-Wuk Village	24360 Pela Rd
Complete	TFS	Twain Harte	24309 Jeffrey St
Complete	TFS	Twain Harte	23532 Lakewood Dr
Complete	TFS	Twain Harte	24030 Pine Cone Rd
Complete	TFS	Mi-Wuk Village	24110 Paipu Rd
Complete	TFS	Mi-Wuk Village	20825 Koinonia Ct
Complete	TFS	Twain Harte	22523 Twain Harte Dr
Complete	TFS	Twain Harte	22356 N Tuolumne Rd
Complete	TFS	Twain Harte	23882 Pine Lake Dr
Complete	TFS	Twain Harte	20260 Lilac Ln
Complete	TFS	Sonora	16911 Estralita Dr
Complete	TFS	Sonora	17278 Mount Elizabeth Dr
Complete	TFS	Sonora	22545 Wildcat Ridge Rd
Complete	TFS	Twain Harte	24172 Golf Links Dr
Complete	TFS	Sonora	22590 Longeway Rd

Complete	TFS	Sonora	22590 Longeway Rd
Complete	TFS	Mi-Wuk Village	24280 Golf Links Dr
Complete	TFS	Twain Harte	23280 Cresta Dr
Complete	TFS	Twain Harte	24291 White Fir Dr
Complete	CON	Mi-Wuk Village	20803 Muheli Rd
Complete	TFS	Sonora	17276 Nile River Dr
Complete	TFS	Sonora	17689 Lucky Strike Trail
Complete	TFS	Twain Harte	23835 Confidence South Fork Rd
Complete	TFS	Twain Harte	18991 Middle Camp Rd
Complete	TFS	Sonora	16869 E Brookside Dr
Complete	TFS	Twain Harte	22929 Golf Club Dr
Complete	TFS	Twain Harte	23816 Pine Lake Dr
Complete	TFS	Twain Harte	23056 Twain Harte Dr
Complete	TFS	Twain Harte	23056 Twain Harte Dr
Complete	TFS	Twain Harte	23862 Marshall Way
Complete	TFS	Twain Harte	23699 Sonora Pass Hwy
Complete	TFS	Sonora	22870 Lazy Z Ln
Complete	TFS	Mi-Wuk Village	20998 Lama Road Teumete
Complete	TFS	Mi-Wuk Village	24740 Sonora Pass Hwy
Complete	TFS	Twain Harte	23760 Confidence South Fork Rd
Complete	TFS	Twain Harte	23598 Ontario Dr
Complete	TFS	Sonora	22497 S Fork Rd

Complete	CON	Sonora	22497 S Fork Rd
Complete	CON	Twain Harte	23763 Fremont Way
Complete	TFS	Twain Harte	23227 Cresta Dr
Complete	TFS	Mi-Wuk Village	20811 Koteo Ln
Complete	TFS	Twain Harte	24548 Sonora Pass Hwy
Complete	TFS	Twain Harte	24083 Pine Lake Dr
Complete	TFS	Mi-Wuk Village	24326 Lavene Ct
Complete	TFS	Mi-Wuk Village	24123 Wuuya Way
Complete	TFS	Twain Harte	19414 Superior Dr
Complete	TFS	Mi-Wuk Village	24230 Kalanu Pl
Complete	TFS	Mi-Wuk Village	20992 Lama Road Teumete
Complete	TFS	Twain Harte	24034 Pine Lake Dr
Complete	TFS	Sonora	17247 Nile River Dr
Complete	TFS	Twain Harte	24091 Golf Links Dr
Complete	TFS	Sonora	16632 Saddle Ct
Complete	TFS	Sonora	17457 Smokey River Dr
Complete	TFS	Sonora	16961 E Brookside Dr
Complete	TFS	Sonora	16688 W Brookside Dr
Complete	TFS	Sonora	22330 Geraldine Cir
Complete	TFS	Mi-Wuk Village	20704 Telele Trail
Complete	TFS	Twain Harte	19778 Wanita Ln
Complete	TFS	Twain Harte	19215 Superior Dr

Complete	TFS	Twain Harte	22709 Twain Harte Dr
Complete	TFS	Sonora	22932 Lazy Z Ln
Complete	TFS	Twain Harte	18950 Huron Dr
Complete	TFS	Twain Harte	23819 Pine Lake Dr
Complete	TFS	Sonora	22581 E Rhine River Dr
Complete	TFS	Twain Harte	22358 Robin Hood Dr
Complete	TFS	Mi-Wuk Village	24152 Olo Win Trl
Complete	TFS	Mi-Wuk Village	24039 Lama Rd
Complete	TFS	Sonora	22470 Colorado River Dr
Complete	TFS	Twain Harte	18890 Middle Camp Sugar Pine R
Complete	TFS	Twain Harte	18920 Middle Camp Rd
Complete	TFS	Mi-Wuk Village	20668 Hekeke Ln
Complete	CON	Twain Harte	22814 Black Hawk Dr
Complete	TFS	Twain Harte	22120 N Tuolumne Rd
Complete	CON	Los Banos	24205-24399 Henry Miller Rd
Complete	TFS	Coulterville	10386 Fiske Hill Rd
Complete	TFS	Chowchilla	14062-14312 Avenue 18 1/2
Complete	CON	Sonora	23924-23954 Mount Elizabeth Rd
Complete	CON	Twain Harte	23884-23922 Mount Elizabeth Rd
Complete	CON	Merced	2997 E State Hwy 140
Complete	ENG	Sonora	20795 Columbia Way
Complete	TFS	Mi Wuk Village	20725 Hekeke Ln

Complete	CON		28540 HILLTOP LN
Complete	TFS	Jamestown	15611 New Peoria Flat Rd
Complete	TFS	White Wolf	13979 Old Coultervil
Complete	TFS	Sonora	18508 Lime Kiln Rd
Complete	TFS	Sonora	20129 Mono Hwy
Complete	CON	Mi Wuk Village	20707 Koteo Ln
Complete	TFS	Sonora	16591 Caddo Cir
Complete	CON	Mi Wuk Village	20988 Lama Teumete Rd
Complete	TFS	Chowchilla	555 N Fifth St
Complete	TFS	Chowchilla	515 Sonoma Ave
Complete	CON	Sonora	18404-18444 Zekarias Ct

TROUBLE_LOCATION	SERVICE_PRIORITY	CATEGORY
Street Address	GO95	GO95 Vegetation
Pole Address	GO95	GO95 Pole
Street Address	GO95	GO95 Cable
Street Address	GO95	GO95 Cable
Street Address	GO95	GO95 Cable
Street Address	GO95	GO95 Cable
Street Address	GO95	GO95 Cable
Street Address	GO95	GO95 Cable
Street Address	GO95	GO95 Cable
Street Address	GO95	GO95 Cable
Pole Address	GO95	GO95 Pole
Pole Address	GO95	GO95 Pole
Pole Address	GO95	GO95 Pole
Pole Address	GO95	GO95 Pole
Pole Address	GO95	GO95 Pole
Pole Address	GO95	GO95 Pole
Pole Address	GO95	GO95 Pole
Pole Address	GO95	GO95 Pole
Pole Address	GO95	GO95 Pole
Pole Address	GO95	GO95 Pole
Pole Address	GO95	GO95 Pole

Pole Address	GO95	GO95 Pole
Pole Address	GO95	GO95 Pole
Pole Address	GO95	GO95 Pole
Pole Address	GO95	GO95 Pole
Pole Address	GO95	GO95 Pole
Pole Address	GO95	GO95 Pole
Pole Address	GO95	GO95 Pole
Pole Address	GO95	GO95 Pole
Pole Address	GO95	GO95 Pole
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Vegetation
Pole Address	GO95	GO95 Pole
Street Address	GO95	GO95 Guys/Anchors
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Guys/Anchors
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Guys/Anchors
Street Address	GO95	GO95 Vegetation

Street Address	GO95	GO95 Guys/Anchors
Street Address	GO95	GO95 Cable
Street Address	GO95	GO95 Cable
Pole Address	GO95	GO95 Pole
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Cable
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Cable
Street Address	GO95	GO95 Guys/Anchors
Street Address	GO95	GO95 Cable
Street Address	GO95	GO95 Guys/Anchors
Street Address	GO95	GO95 Cable
Street Address	GO95	GO95 Guys/Anchors
Street Address	GO95	GO95 Guys/Anchors
Street Address	GO95	GO95 Guys/Anchors
Street Address	GO95	GO95 Guys/Anchors
Street Address	GO95	GO95 Cable
Pole Address	GO95	GO95 Pole
Street Address	GO95	GO95 Guys/Anchors
Pole Address	GO95	GO95 Pole
Street Address	GO95	GO95 Guys/Anchors
Street Address	GO95	GO95 Guys/Anchors

Street Address	GO95	GO95 Guys/Anchors
Street Address	GO95	GO95 Cable
Street Address	GO95	GO95 Guys/Anchors
Street Address	GO95	GO95 Cable
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Cable
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Cable
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Cable
Street Address	GO95	GO95 Cable
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Cable

Pole Address	GO95	GO95 Pole
Street Address	GO95	GO95 Vegetation
Pole Address	GO95	GO95 Pole
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop

Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Pole Address	GO95	GO95 Pole
Pole Address	GO95	GO95 Pole
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Service Drop
Pole Address	GO95	GO95 Pole
Pole Address	GO95	GO95 Pole
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Cable
Street Address	GO95	GO95 Cable
Street Address	GO95	GO95 Cable
Pole Address	GO95	GO95 Pole
Pole Address	GO95	GO95 Pole
Pole Address	GO95	GO95 Pole
Pole Address	GO95	GO95 Pole
Pole Address	GO95	GO95 Pole
Street Address	GO95	GO95 Cable
Street Address	GO95	GO95 Service Drop
Pole Address	GO95	GO95 Pole

Street Address	GO95	GO95 Guys/Anchors
Street Address	GO95	GO95 Cable
Street Address	GO95	GO95 Guys/Anchors
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Cable
Street Address	GO95	GO95 Cable
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Cable
Street Address	GO95	GO95 Guys/Anchors
Street Address	GO95	GO95 Guys/Anchors
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Cable
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Cable
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Guys/Anchors
Street Address	GO95	GO95 Vegetation

Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Cable
Street Address	GO95	GO95 Cable
Street Address	GO95	GO95 Guys/Anchors
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Pole Address	GO95	GO95 Pole
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Pole Address	GO95	GO95 Pole
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Guys/Anchors
Street Address	GO95	GO95 Vegetation
Pole Address	GO95	GO95 Pole
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Cable
Street Address	GO95	GO95 Service Drop

Street Address	GO95	GO95 Vegetation
Pole Address	GO95	GO95 Pole
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Cable
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Guys/Anchors
Pole Address	GO95	GO95 Pole
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Guys/Anchors
Street Address	GO95	GO95 Vegetation
Pole Address	GO95	GO95 Pole
Street Address	GO95	GO95 Cable
Street Address	GO95	GO95 Guys/Anchors
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop

Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Pole Address	GO95	GO95 Pole
Pole Address	GO95	GO95 Pole
Street Address	GO95	GO95 Guys/Anchors
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Cable
Street Address	GO95	GO95 Vegetation
Pole Address	GO95	GO95 Pole
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation

Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Cable
Street Address	GO95	GO95 Cable
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop

Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Pole Address	GO95	GO95 Pole
Street Address	GO95	GO95 Cable
Street Address	GO95	GO95 Cable
Pole Address	GO95	GO95 Pole
	GO95	GO95 Cable
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Vegetation

Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Cable
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation

Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Guys/Anchors
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation

Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation

Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Guys/Anchors
Street Address	GO95	GO95 Guys/Anchors
Street Address	GO95	GO95 Cable
Street Address	GO95	GO95 Cable
Street Address	GO95	GO95 Guys/Anchors
Street Address	GO95	GO95 Cable
Street Address	GO95	GO95 Cable
Street Address	GO95	GO95 Cable
Street Address	GO95	GO95 Cable
Street Address	GO95	GO95 Cable
Street Address	GO95	GO95 Cable
Street Address	GO95	GO95 Cable
Street Address	GO95	GO95 Cable
Street Address	GO95	GO95 Cable
Street Address	GO95	GO95 Cable
Street Address	GO95	GO95 Cable

Street Address	GO95	GO95 Cable
Street Address	GO95	GO95 Cable
Street Address	GO95	GO95 Guys/Anchors
Street Address	GO95	GO95 Cable
Street Address	GO95	GO95 Cable
Street Address	GO95	GO95 Cable
Street Address	GO95	GO95 Cable
Street Address	GO95	GO95 Cable
Street Address	GO95	GO95 Cable
Street Address	GO95	GO95 Cable
Street Address	GO95	GO95 Cable
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Cable
Street Address	GO95	GO95 Cable
Street Address	GO95	GO95 Cable
Street Address	GO95	GO95 Cable
Street Address	GO95	GO95 Cable
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop

Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Cable
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Cable
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation

Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Cable
Street Address	GO95	GO95 Guys/Anchors
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation

Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Service Drop

Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation

Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Pole Address	GO95	GO95 Pole
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation

Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation

Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Cable
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation

Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation

Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation

Street Address	GO95	GO95 Cable
Street Address	GO95	GO95 Cable
Street Address	GO95	GO95 Cable
Street Address	GO95	GO95 Cable
Street Address	GO95	GO95 Cable
Street Address	GO95	GO95 Cable
Street Address	GO95	GO95 Cable
Street Address	GO95	GO95 Cable
Street Address	GO95	GO95 Cable
Street Address	GO95	GO95 Cable
Street Address	GO95	GO95 Guys/Anchors
Street Address	GO95	GO95 Cable
Street Address	GO95	GO95 Cable
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop

Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Pole
Pole Address	GO95	GO95 Pole
Street Address	GO95	GO95 Cable
Street Address	GO95	GO95 Cable
Street Address	GO95	GO95 Cable
Pole Address	GO95	GO95 Pole
Street Address	GO95	GO95 Cable
Pole Address	GO95	GO95 Pole
Street Address	GO95	GO95 Cable
Pole Address	GO95	GO95 Cable
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Cable
Street Address	GO95	GO95 Pole
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation

Street Address	GO95	GO95 Pole
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Vegetation
Pole Address	GO95	GO95 Pole
Street Address	GO95	GO95 Cable
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Pole Address	GO95	GO95 Pole
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop

Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Guys/Anchors
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Pole Address	GO95	GO95 Pole
Pole Address	GO95	GO95 Pole
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Guys/Anchors
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Cable
Street Address	GO95	GO95 Service Drop

Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Cable
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Cable
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation

Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Service Drop
Pole Address	GO95	GO95 Pole
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Pole Address	GO95	GO95 Pole
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop

Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Guys/Anchors
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop

Pole Address	GO95	GO95 Pole
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Pole Address	GO95	GO95 Pole
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Cable
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Pole Address	GO95	GO95 Pole
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Cable

Street Address	GO95	GO95 Cable
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Pole Address	GO95	GO95 Pole
Pole Address	GO95	GO95 Pole
Street Address	GO95	GO95 Service Drop
Pole Address	GO95	GO95 Pole
Street Address	GO95	GO95 Service Drop
Pole Address	GO95	GO95 Pole
Pole Address	GO95	GO95 Pole
Pole Address	GO95	GO95 Pole
Pole Address	GO95	GO95 Pole

Pole Address	GO95	GO95 Pole
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Guys/Anchors
Street Address	GO95	GO95 Guys/Anchors
Street Address	GO95	GO95 Service Drop
Pole Address	GO95	GO95 Pole
Pole Address	GO95	GO95 Pole
Street Address	GO95	GO95 Guys/Anchors
Street Address	GO95	GO95 Guys/Anchors
Street Address	GO95	GO95 Service Drop
Pole Address	GO95	GO95 Pole
Pole Address	GO95	GO95 Pole
Pole Address	GO95	GO95 Pole
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Guys/Anchors
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Guys/Anchors
Street Address	GO95	GO95 Guys/Anchors
Pole Address	GO95	GO95 Pole
Street Address	GO95	GO95 Cable
Pole Address	GO95	GO95 Pole

Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Guys/Anchors
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Guys/Anchors
Pole Address	GO95	GO95 Pole
Street Address	GO95	GO95 Guys/Anchors
Street Address	GO95	GO95 Guys/Anchors
Street Address	GO95	GO95 Guys/Anchors
Street Address	GO95	GO95 Guys/Anchors
Street Address	GO95	GO95 Guys/Anchors
Pole Address	GO95	GO95 Pole
Street Address	GO95	GO95 Guys/Anchors
Pole Address	GO95	GO95 Pole
Pole Address	GO95	GO95 Pole
Pole Address	GO95	GO95 Pole
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Guys/Anchors
Street Address	GO95	GO95 Guys/Anchors

Street Address	GO95	GO95 Guys/Anchors
Street Address	GO95	GO95 Guys/Anchors
Pole Address	GO95	GO95 Pole
Pole Address	GO95	GO95 Pole
Street Address	GO95	GO95 Cable
Street Address	GO95	GO95 Guys/Anchors
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Pole Address	GO95	GO95 Pole
Pole Address	GO95	GO95 Pole
Street Address	GO95	GO95 Guys/Anchors
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Guys/Anchors
Street Address	GO95	GO95 Service Drop
Pole Address	GO95	GO95 Pole
Pole Address	GO95	GO95 Pole
Pole Address	GO95	GO95 Pole
Pole Address	GO95	GO95 Pole
Street Address	GO95	GO95 Guys/Anchors
Street Address	GO95	GO95 Cable
Street Address	GO95	GO95 Guys/Anchors
Street Address	GO95	GO95 Cable

Pole Address	GO95	GO95 Pole
Pole Address	GO95	GO95 Pole
Street Address	GO95	GO95 Guys/Anchors
Street Address	GO95	GO95 Guys/Anchors
Street Address	GO95	GO95 Guys/Anchors
Street Address	GO95	GO95 Service Drop
Pole Address	GO95	GO95 Pole
Street Address	GO95	GO95 Cable
Pole Address	GO95	GO95 Pole
Pole Address	GO95	GO95 Pole
Pole Address	GO95	GO95 Pole
Pole Address	GO95	GO95 Pole
Pole Address	GO95	GO95 Pole
Pole Address	GO95	GO95 Pole
Street Address	GO95	GO95 Service Drop
Pole Address	GO95	GO95 Pole
Street Address	GO95	GO95 Guys/Anchors
Street Address	GO95	GO95 Guys/Anchors
Pole Address	GO95	GO95 Pole
Street Address	GO95	GO95 Cable
Street Address	GO95	GO95 Service Drop
Pole Address	GO95	GO95 Pole

Pole Address	GO95	GO95 Pole
Street Address	GO95	GO95 Service Drop
Pole Address	GO95	GO95 Pole
Street Address	GO95	GO95 Guys/Anchors
Street Address	GO95	GO95 Service Drop
Pole Address	GO95	GO95 Pole
Pole Address	GO95	GO95 Pole
Street Address	GO95	GO95 Guys/Anchors
Pole Address	GO95	GO95 Pole
Street Address	GO95	GO95 Guys/Anchors
Pole Address	GO95	GO95 Pole
Street Address	GO95	GO95 Guys/Anchors
Street Address	GO95	GO95 Service Drop
Pole Address	GO95	GO95 Pole
Street Address	GO95	GO95 Guys/Anchors
Pole Address	GO95	GO95 Pole
Pole Address	GO95	GO95 Pole
Street Address	GO95	GO95 Cable
Street Address	GO95	GO95 Cable
Pole Address	GO95	GO95 Pole
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Guys/Anchors

Street Address	GO95	GO95 Cable
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Cable
Pole Address	GO95	GO95 Pole
Pole Address	GO95	GO95 Pole
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Guys/Anchors
Street Address	GO95	GO95 Cable
Pole Address	GO95	GO95 Pole
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop

Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Guys/Anchors
Street Address	GO95	GO95 Guys/Anchors
Street Address	GO95	GO95 Guys/Anchors
Street Address	GO95	GO95 Guys/Anchors
Street Address	GO95	GO95 Guys/Anchors
Street Address	GO95	GO95 Guys/Anchors
Street Address	GO95	GO95 Guys/Anchors
Pole Address	GO95	GO95 Pole
Pole Address	GO95	GO95 Pole
Pole Address	GO95	GO95 Pole
Pole Address	GO95	GO95 Pole
Pole Address	GO95	GO95 Pole
Pole Address	GO95	GO95 Pole
Street Address	GO95	GO95 Cable
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Guys/Anchors
Street Address	GO95	GO95 Cable
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Guys/Anchors

Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Service Drop
Pole Address	GO95	GO95 Pole
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Guys/Anchors
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Cable
Street Address	GO95	GO95 Vegetation
Pole Address	GO95	GO95 Pole
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Service Drop

Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Cable
Street Address	GO95	GO95 Cable
Street Address	GO95	GO95 Cable
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Guys/Anchors
Street Address	GO95	GO95 Guys/Anchors
Street Address	GO95	GO95 Guys/Anchors
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Service Drop

Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Cable
Street Address	GO95	GO95 Cable
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Pole Address	GO95	GO95 Pole
Street Address	GO95	GO95 Vegetation

Street Address	GO95	GO95 Service Drop
Pole Address	GO95	GO95 Pole
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Cable
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Guys/Anchors
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Guys/Anchors
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Cable
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Service Drop

Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Cable
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Pole Address	GO95	GO95 Pole
Street Address	GO95	GO95 Service Drop

Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation

Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Cable
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Vegetation

Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Pole Address	GO95	GO95 Pole
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Pole Address	GO95	GO95 Pole
Pole Address	GO95	GO95 Pole
Pole Address	GO95	GO95 Pole
Pole Address	GO95	GO95 Pole
Pole Address	GO95	GO95 Pole
Pole Address	GO95	GO95 Pole
Pole Address	GO95	GO95 Pole
Pole Address	GO95	GO95 Pole
Street Address	GO95	GO95 Service Drop
Pole Address	GO95	GO95 Pole
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation

Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Service Drop
Pole Address	GO95	GO95 Pole
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Cable
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Guys/Anchors
Street Address	GO95	GO95 Service Drop
Pole Address	GO95	GO95 Pole
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Vegetation

	GO95	GO95 Vegetation
Pole Address	GO95	GO95 Cable
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Pole Address	GO95	GO95 Pole
Pole Address	GO95	GO95 Pole
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Pole Address	GO95	GO95 Pole
Street Address	GO95	GO95 Service Drop
Pole Address	GO95	GO95 Pole
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Guys/Anchors
Pole Address	GO95	GO95 Pole
Pole Address	GO95	GO95 Pole

Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Guys/Anchors
Pole Address	GO95	GO95 Pole
Pole Address	GO95	GO95 Pole
Street Address	GO95	GO95 Service Drop
Pole Address	GO95	GO95 Pole
Street Address	GO95	GO95 Service Drop
Pole Address	GO95	GO95 Pole
Street Address	GO95	GO95 Service Drop
Pole Address	GO95	GO95 Pole
Pole Address	GO95	GO95 Pole
Pole Address	GO95	GO95 Pole
Street Address	GO95	GO95 Service Drop
Pole Address	GO95	GO95 Pole
Pole Address	GO95	GO95 Pole
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Cable
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop

Pole Address	GO95	GO95 Pole
Pole Address	GO95	GO95 Pole
Pole Address	GO95	GO95 Pole
Pole Address	GO95	GO95 Pole
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Pole Address	GO95	GO95 Pole
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Vegetation
Pole Address	GO95	GO95 Pole
Street Address	GO95	GO95 Service Drop
Pole Address	GO95	GO95 Pole
Street Address	GO95	GO95 Service Drop
Pole Address	GO95	GO95 Pole
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Pole Address	GO95	GO95 Pole
Pole Address	GO95	GO95 Pole
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop

Street Address	GO95	GO95 Guys/Anchors
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Pole Address	GO95	GO95 Pole
Pole Address	GO95	GO95 Pole
Pole Address	GO95	GO95 Pole
Street Address	GO95	GO95 Service Drop
Pole Address	GO95	GO95 Pole
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Vegetation
Pole Address	GO95	GO95 Pole
Pole Address	GO95	GO95 Pole
Pole Address	GO95	GO95 Pole
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Pole Address	GO95	GO95 Pole
Pole Address	GO95	GO95 Pole
Pole Address	GO95	GO95 Pole
Pole Address	GO95	GO95 Pole

Street Address	GO95	GO95 Service Drop
Pole Address	GO95	GO95 Pole
Pole Address	GO95	GO95 Pole
Pole Address	GO95	GO95 Pole
Pole Address	GO95	GO95 Pole
Pole Address	GO95	GO95 Pole
Street Address	GO95	GO95 Service Drop
Pole Address	GO95	GO95 Pole
Street Address	GO95	GO95 Cable
Street Address	GO95	GO95 Cable
Street Address	GO95	GO95 Service Drop
Pole Address	GO95	GO95 Pole
Pole Address	GO95	GO95 Pole
Pole Address	GO95	GO95 Pole
Street Address	GO95	GO95 Service Drop
Pole Address	GO95	GO95 Pole
Pole Address	GO95	GO95 Pole
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Pole Address	GO95	GO95 Pole
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Cable

Street Address	GO95	GO95 Service Drop
Pole Address	GO95	GO95 Pole
Pole Address	GO95	GO95 Pole
Pole Address	GO95	GO95 Pole
Pole Address	GO95	GO95 Pole
Pole Address	GO95	GO95 Pole
Pole Address	GO95	GO95 Pole
Pole Address	GO95	GO95 Pole
Pole Address	GO95	GO95 Pole
Pole Address	GO95	GO95 Pole
Pole Address	GO95	GO95 Pole
Pole Address	GO95	GO95 Pole
Pole Address	GO95	GO95 Pole
Pole Address	GO95	GO95 Pole
Pole Address	GO95	GO95 Pole
Pole Address	GO95	GO95 Pole
Pole Address	GO95	GO95 Pole
Pole Address	GO95	GO95 Pole
Pole Address	GO95	GO95 Pole
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Pole Address	GO95	GO95 Pole
Street Address	GO95	GO95 Guys/Anchors
Pole Address	GO95	GO95 Pole

Pole Address	GO95	GO95 Pole
Pole Address	GO95	GO95 Pole
Pole Address	GO95	GO95 Pole
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Service Drop
Pole Address	GO95	GO95 Pole
Pole Address	GO95	GO95 Pole
Pole Address	GO95	GO95 Pole
Street Address	GO95	GO95 Cable
Pole Address	GO95	GO95 Pole
Pole Address	GO95	GO95 Pole
Pole Address	GO95	GO95 Pole
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Pole Address	GO95	GO95 Pole
Pole Address	GO95	GO95 Pole
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Pole Address	GO95	GO95 Pole
Pole Address	GO95	GO95 Pole
Street Address	GO95	GO95 Service Drop

Street Address	GO95	GO95 Service Drop
Pole Address	GO95	GO95 Pole
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Pole Address	GO95	GO95 Pole
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Guys/Anchors
Pole Address	GO95	GO95 Pole
Pole Address	GO95	GO95 Pole
Pole Address	GO95	GO95 Pole
Pole Address	GO95	GO95 Pole
Pole Address	GO95	GO95 Pole
Street Address	GO95	GO95 Guys/Anchors
Street Address	GO95	GO95 Guys/Anchors
Street Address	GO95	GO95 Service Drop
Pole Address	GO95	GO95 Pole
Pole Address	GO95	GO95 Pole

Pole Address	GO95	GO95 Pole
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Pole Address	GO95	GO95 Pole
Street Address	GO95	GO95 Cable
Pole Address	GO95	GO95 Pole
Street Address	GO95	GO95 Service Drop
Pole Address	GO95	GO95 Pole
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Guys/Anchors
Street Address	GO95	GO95 Vegetation
Pole Address	GO95	GO95 Pole
Pole Address	GO95	GO95 Pole
Pole Address	GO95	GO95 Pole
Pole Address	GO95	GO95 Pole
Pole Address	GO95	GO95 Pole
Street Address	GO95	GO95 Vegetation
Pole Address	GO95	GO95 Pole
Pole Address	GO95	GO95 Pole
Street Address	GO95	GO95 Cable
Street Address	GO95	GO95 Service Drop

Pole Address	GO95	GO95 Pole
Pole Address	GO95	GO95 Pole
Street Address	GO95	GO95 Service Drop
Pole Address	GO95	GO95 Pole
Street Address	GO95	GO95 Service Drop
Pole Address	GO95	GO95 Pole
Street Address	GO95	GO95 Service Drop
Pole Address	GO95	GO95 Pole
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Pole Address	GO95	GO95 Pole
Pole Address	GO95	GO95 Pole
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Pole Address	GO95	GO95 Pole
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Pole Address	GO95	GO95 Pole
Street Address	GO95	GO95 Service Drop
Pole Address	GO95	GO95 Pole
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop

Pole Address	GO95	GO95 Pole
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Pole Address	GO95	GO95 Pole
Pole Address	GO95	GO95 Pole
Pole Address	GO95	GO95 Pole
Pole Address	GO95	GO95 Pole
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Guys/Anchors
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Service Drop
Pole Address	GO95	GO95 Pole
Pole Address	GO95	GO95 Pole
Pole Address	GO95	GO95 Pole
Pole Address	GO95	GO95 Pole
Pole Address	GO95	GO95 Pole
Pole Address	GO95	GO95 Pole
Pole Address	GO95	GO95 Pole
Pole Address	GO95	GO95 Pole

Pole Address	GO95	GO95 Pole
Pole Address	GO95	GO95 Pole
Street Address	GO95	GO95 Service Drop
Pole Address	GO95	GO95 Pole
Pole Address	GO95	GO95 Pole
Pole Address	GO95	GO95 Pole
Street Address	GO95	GO95 Service Drop
Pole Address	GO95	GO95 Pole
Pole Address	GO95	GO95 Pole
Pole Address	GO95	GO95 Pole
Pole Address	GO95	GO95 Pole
Pole Address	GO95	GO95 Pole
Pole Address	GO95	GO95 Pole
Pole Address	GO95	GO95 Pole
Pole Address	GO95	GO95 Pole
Pole Address	GO95	GO95 Pole
Pole Address	GO95	GO95 Pole
Street Address	GO95	GO95 Service Drop
Pole Address	GO95	GO95 Pole
Pole Address	GO95	GO95 Pole
Pole Address	GO95	GO95 Pole
Street Address	GO95	GO95 Service Drop

Pole Address	GO95	GO95 Pole
Street Address	GO95	GO95 Service Drop
Pole Address	GO95	GO95 Pole
Pole Address	GO95	GO95 Pole
Pole Address	GO95	GO95 Pole
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Pole Address	GO95	GO95 Pole
Street Address	GO95	GO95 Guys/Anchors
Street Address	GO95	GO95 Service Drop
Pole Address	GO95	GO95 Pole
Pole Address	GO95	GO95 Pole
Pole Address	GO95	GO95 Pole
Pole Address	GO95	GO95 Pole
Street Address	GO95	GO95 Guys/Anchors
Pole Address	GO95	GO95 Pole
Street Address	GO95	GO95 Service Drop
Pole Address	GO95	GO95 Pole
Pole Address	GO95	GO95 Pole
Pole Address	GO95	GO95 Pole
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop

Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Guys/Anchors
Pole Address	GO95	GO95 Pole
Pole Address	GO95	GO95 Pole
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Guys/Anchors
Street Address	GO95	GO95 Cable
Street Address	GO95	GO95 Cable
Street Address	GO95	GO95 Service Drop
Pole Address	GO95	GO95 Pole
Street Address	GO95	GO95 Cable
Street Address	GO95	GO95 Guys/Anchors
Street Address	GO95	GO95 Service Drop
Pole Address	GO95	GO95 Pole
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Pole Address	GO95	GO95 Pole
Pole Address	GO95	GO95 Pole

Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Cable
Pole Address	GO95	GO95 Pole
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Cable
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Pole Address	GO95	GO95 Pole
Street Address	GO95	GO95 Service Drop

Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Pole Address	GO95	GO95 Pole
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Pole Address	GO95	GO95 Pole
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Pole Address	GO95	GO95 Pole
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Pole Address	GO95	GO95 Pole
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop

Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop

Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop

Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Pole Address	GO95	GO95 Pole
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Vegetation
Pole Address	GO95	GO95 Pole
Pole Address	GO95	GO95 Pole
Pole Address	GO95	GO95 Pole
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation

Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Pole Address	GO95	GO95 Pole
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Pole Address	GO95	GO95 Pole
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Cable
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop

Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Pole Address	GO95	GO95 Pole
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Guys/Anchors
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Pole Address	GO95	GO95 Pole
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Guys/Anchors
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop

Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop

Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Cable
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop

Street Address	GO95	GO95 Cable
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Cable
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Pole Address	GO95	GO95 Pole
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop

Street Address	GO95	GO95 Cable
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop

Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Cable
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Guys/Anchors
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Service Drop
Pole Address	GO95	GO95 Pole
Pole Address	GO95	GO95 Pole
Pole Address	GO95	GO95 Pole
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Pole Address	GO95	GO95 Pole
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Pole Address	GO95	GO95 Pole

Pole Address	GO95	GO95 Pole
Street Address	GO95	GO95 Guys/Anchors
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Cable
Pole Address	GO95	GO95 Pole
Street Address	GO95	GO95 Cable
Street Address	GO95	GO95 Cable
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Pole Address	GO95	GO95 Pole

Street Address	GO95	GO95 Guys/Anchors
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Pole Address	GO95	GO95 Pole
Pole Address	GO95	GO95 Pole
Street Address	GO95	GO95 Guys/Anchors
Street Address	GO95	GO95 Guys/Anchors
Pole Address	GO95	GO95 Pole
Pole Address	GO95	GO95 Pole
Pole Address	GO95	GO95 Pole
Street Address	GO95	GO95 Service Drop
Pole Address	GO95	GO95 Pole
Street Address	GO95	GO95 Guys/Anchors
Street Address	GO95	GO95 Guys/Anchors
Street Address	GO95	GO95 Guys/Anchors
Pole Address	GO95	GO95 Pole
Street Address	GO95	GO95 Service Drop
Pole Address	GO95	GO95 Pole
Street Address	GO95	GO95 Cable
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop

Street Address	GO95	GO95 Service Drop
Pole Address	GO95	GO95 Pole
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Guardarm/Crossarm
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Guardarm/Crossarm
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Pole Address	GO95	GO95 Pole
Street Address	GO95	GO95 Cable
Street Address	GO95	GO95 Guys/Anchors
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Pole Address	GO95	GO95 Pole
Pole Address	GO95	GO95 Pole

Street Address	GO95	GO95 Service Drop
Pole Address	GO95	GO95 Pole
Pole Address	GO95	GO95 Pole
Pole Address	GO95	GO95 Pole
Pole Address	GO95	GO95 Pole
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Pole Address	GO95	GO95 Pole
Pole Address	GO95	GO95 Pole
Pole Address	GO95	GO95 Pole
Pole Address	GO95	GO95 Pole
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Cable
Pole Address	GO95	GO95 Pole
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Pole Address	GO95	GO95 Pole
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Guardarm/Crossarm
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Cable

Street Address	GO95	GO95 Guys/Anchors
Pole Address	GO95	GO95 Pole
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Guys/Anchors
Street Address	GO95	GO95 Guys/Anchors
Street Address	GO95	GO95 Guys/Anchors
Pole Address	GO95	GO95 Pole
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Pole Address	GO95	GO95 Pole
Street Address	GO95	GO95 Service Drop
Pole Address	GO95	GO95 Pole
Pole Address	GO95	GO95 Pole
Street Address	GO95	GO95 Cable
Street Address	GO95	GO95 Service Drop
Pole Address	GO95	GO95 Pole
Pole Address	GO95	GO95 Pole
Pole Address	GO95	GO95 Pole
Street Address	GO95	GO95 Guys/Anchors

Street Address	GO95	GO95 Guys/Anchors
Pole Address	GO95	GO95 Pole
Pole Address	GO95	GO95 Pole
Street Address	GO95	GO95 Service Drop
Pole Address	GO95	GO95 Pole
Pole Address	GO95	GO95 Pole
Pole Address	GO95	GO95 Pole
Pole Address	GO95	GO95 Pole
Pole Address	GO95	GO95 Pole
Street Address	GO95	GO95 Guardarm/Crossarm
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Guys/Anchors
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Guys/Anchors
Pole Address	GO95	GO95 Pole
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Cable
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Guys/Anchors
Street Address	GO95	GO95 Guys/Anchors

Street Address	GO95	GO95 Service Drop
Pole Address	GO95	GO95 Pole
Pole Address	GO95	GO95 Pole
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Guys/Anchors
Pole Address	GO95	GO95 Pole
Pole Address	GO95	GO95 Pole
Pole Address	GO95	GO95 Pole
Pole Address	GO95	GO95 Pole
Street Address	GO95	GO95 Guys/Anchors
Pole Address	GO95	GO95 Pole
Street Address	GO95	GO95 Service Drop
Pole Address	GO95	GO95 Pole
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Equipment/Antenna/Splice
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Pole Address	GO95	GO95 Pole
Street Address	GO95	GO95 Service Drop
Pole Address	GO95	GO95 Pole
Pole Address	GO95	GO95 Pole

Pole Address	GO95	GO95 Pole
Pole Address	GO95	GO95 Pole
Pole Address	GO95	GO95 Pole
Pole Address	GO95	GO95 Pole
Pole Address	GO95	GO95 Pole
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Pole Address	GO95	GO95 Pole
Street Address	GO95	GO95 Service Drop
Pole Address	GO95	GO95 Pole
Pole Address	GO95	GO95 Pole
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Cable
Pole Address	GO95	GO95 Pole
Pole Address	GO95	GO95 Pole
Pole Address	GO95	GO95 Pole
Street Address	GO95	GO95 Guys/Anchors
Pole Address	GO95	GO95 Pole
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Cable

Street Address	GO95	GO95 Service Drop
Pole Address	GO95	GO95 Pole
Pole Address	GO95	GO95 Pole
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Cable
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Cable
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Cable
Street Address	GO95	GO95 Service Drop
Pole Address	GO95	GO95 Pole
Street Address	GO95	GO95 Guys/Anchors
Pole Address	GO95	GO95 Pole
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop

Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop

Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Cable
Street Address	GO95	GO95 Cable
Street Address	GO95	GO95 Cable
Street Address	GO95	GO95 Guys/Anchors
Pole Address	GO95	GO95 Pole
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Pole Address	GO95	GO95 Pole
Pole Address	GO95	GO95 Pole
Pole Address	GO95	GO95 Pole

Pole Address	GO95	GO95 Pole
Pole Address	GO95	GO95 Pole
Pole Address	GO95	GO95 Pole
Pole Address	GO95	GO95 Pole
Pole Address	GO95	GO95 Pole
Pole Address	GO95	GO95 Pole
Pole Address	GO95	GO95 Pole
Pole Address	GO95	GO95 Pole
Pole Address	GO95	GO95 Pole
Pole Address	GO95	GO95 Pole
Pole Address	GO95	GO95 Pole
Pole Address	GO95	GO95 Pole
Pole Address	GO95	GO95 Pole
Pole Address	GO95	GO95 Pole
Pole Address	GO95	GO95 Pole
Pole Address	GO95	GO95 Pole
Pole Address	GO95	GO95 Pole
Pole Address	GO95	GO95 Pole
Pole Address	GO95	GO95 Pole
Pole Address	GO95	GO95 Pole
Pole Address	GO95	GO95 Pole
Pole Address	GO95	GO95 Pole
Pole Address	GO95	GO95 Pole
Pole Address	GO95	GO95 Pole

Pole Address	GO95	GO95 Pole
Pole Address	GO95	GO95 Pole
Pole Address	GO95	GO95 Pole
Pole Address	GO95	GO95 Pole
Pole Address	GO95	GO95 Pole
Pole Address	GO95	GO95 Pole
Pole Address	GO95	GO95 Pole
Pole Address	GO95	GO95 Pole
Pole Address	GO95	GO95 Pole
Pole Address	GO95	GO95 Pole
Pole Address	GO95	GO95 Pole
Pole Address	GO95	GO95 Pole
Pole Address	GO95	GO95 Pole
Pole Address	GO95	GO95 Pole
Pole Address	GO95	GO95 Pole
Pole Address	GO95	GO95 Pole
Pole Address	GO95	GO95 Pole
Pole Address	GO95	GO95 Pole
Pole Address	GO95	GO95 Pole
Pole Address	GO95	GO95 Pole
Pole Address	GO95	GO95 Pole
Pole Address	GO95	GO95 Pole
Pole Address	GO95	GO95 Pole
Pole Address	GO95	GO95 Pole

Pole Address	GO95	GO95 Pole
Pole Address	GO95	GO95 Pole
Pole Address	GO95	GO95 Pole
Pole Address	GO95	GO95 Pole
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop

Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Cable
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop

Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Guys/Anchors
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Guys/Anchors
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop

Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Cable
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop

Street Address	GO95	GO95 Cable
Street Address	GO95	GO95 Guys/Anchors
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop

Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Cable
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Cable
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Cable
Street Address	GO95	GO95 Cable
Street Address	GO95	GO95 Cable
Pole Address	GO95	GO95 Pole
Street Address	GO95	GO95 Service Drop

Street Address	GO95	GO95 Cable
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Vegetation
Street Address	GO95	GO95 Cable
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Cable
Street Address	GO95	GO95 Service Drop
Street Address	GO95	GO95 Vegetation
Pole Address	GO95	GO95 Pole

SUB_CAT

Strain

Leaning

Clearance to ground

Broken lashing wire

Clearance to ground

Clearance to ground

Clearance to ground

Clearance to ground

Clearance to ground

Clearance to ground

Deteriorated/Decayed/Damaged

Deteriorated/Decayed/Damaged

Deteriorated/Decayed/Damaged

Deteriorated/Decayed/Damaged

Deteriorated/Decayed/Damaged

Deteriorated/Decayed/Damaged

Deteriorated/Decayed/Damaged

Deteriorated/Decayed/Damaged

Deteriorated/Decayed/Damaged

Deteriorated/Decayed/Damaged

Deteriorated/Decayed/Damaged

Deteriorated/Decayed/Damaged

Deteriorated/Decayed/Damaged

Deteriorated/Decayed/Damaged

Deteriorated/Decayed/Damaged

Deteriorated/Decayed/Damaged

Deteriorated/Decayed/Damaged

Deteriorated/Decayed/Damaged

Deteriorated/Decayed/Damaged

Deteriorated/Decayed/Damaged

Clearance to ground

Cable Damage

Complete pole transfer / buddy pole

Down guy

Cable Damage

Down guy

Cable Damage

Cable Damage

Cable Damage

Cable Damage

Down guy

Cable Damage

Down guy

Broken lashing wire

Clearance to ground

Complete pole transfer / buddy pole

Cable Damage

Clearance to ground

Cable Damage

Hardware

Down guy

Hardware

Down guy

Clearance to ground

Down guy

Down guy

Down guy

Down guy

Hardware

Complete pole transfer / buddy pole

Down guy

Complete pole transfer / buddy pole

Down guy

Down guy

Down guy

Hardware

Down guy

Broken lashing wire

Cable Damage

Cable Damage

Cable Damage

Cable Damage

Hardware

Cable Damage

Hardware

Cable Damage

Lines down

Clearance to ground

Clearance to ground

Cable Damage

Cable Damage

Cable Damage

Cable Damage

Cable Damage

Cable Damage

Hardware

Complete pole transfer / buddy pole

Cable Damage

Complete pole transfer / buddy pole

Cable Damage

Cable Damage

Cable Damage

Cable Damage

Cable Damage

Cable Damage

Cable Damage

Cable Damage

Cable Damage

Cable Damage

Cable Damage

Cable Damage

Cable Damage

Cable Damage

Cable Damage

Cable Damage

Lines down

Clearance to ground

Clearance to ground

Lines down

Clearance to ground

Cable Damage

Causing low cable

Leaning

Leaning

Cable Damage

Cable Damage

Clearance to ground

Leaning

Leaning

Strain

Broken lashing wire

Broken lashing wire

Clearance to ground

Deteriorated/Decayed/Damaged

Complete pole transfer / buddy pole

Deteriorated/Decayed/Damaged

Deteriorated/Decayed/Damaged

Deteriorated/Decayed/Damaged

Hardware

Lines down

Complete pole transfer / buddy pole

Down guy

Clearance to ground

Down guy

Cable Damage

Cable Damage

Clearance to ground

Hardware

Hardware

Cable Damage

Cable Damage

Cable Damage

Hardware

Down guy

Down guy

Cable Damage

Clearance to ground

Cable Damage

Cable Damage

Hardware

Cable Damage

Down guy

Cable Damage

Cable Damage

Hardware

Clearance to ground

Down guy

Cable Damage

Cable Damage

Cable Damage

Complete pole transfer / buddy pole

Cable Damage

Cable Damage

Cable Damage

Complete pole transfer / buddy pole

Cable Damage

Down guy

Cable Damage

Complete pole transfer / buddy pole

Cable Damage

Cable Damage

Lines down

Hardware

Lines down

Cable Damage

Complete pole transfer / buddy pole

Cable Damage

Cable Damage

Cable Damage

Hardware

Cable Damage

Cable Damage

Down guy

Complete pole transfer / buddy pole

Cable Damage

Down guy

Cable Damage

Complete pole transfer / buddy pole

Hardware

Down guy

Clearance to ground

Clearance to ground

Clearance to ground

Lines down

Lines down

Lines down

Clearance to ground

Lines down

Lines down

Lines down

Leaning

Leaning

Down guy

Strain

Strain

Strain

Strain

Broken lashing wire

Strain

Deteriorated/Decayed/Damaged

Clearance to power

Cable Damage

Causing low service drop

Cable Damage

Clearance to ground

Clearance to ground

Cable Damage

Cable Damage

Cable Damage

Cable Damage

Cable Damage

Lines down

Cable Damage

Cable Damage

Cable Damage

Cable Damage

Cable Damage

Cable Damage

Cable Damage

Cable Damage

Lines down

Cable Damage

Cable Damage

Cable Damage

Causing low service drop

Lines down

Lines down

Clearance to ground

Clearance to ground

Lines down

Lines down

Lines down

Lines down

Lines down

Clearance to ground

Clearance to ground

Lines down

Clearance to ground

Lines down

Clearance to ground

Clearance to ground

Clearance to ground

Hardware loose/missing/damaged

Leaning

Broken lashing wire

Broken lashing wire

Deteriorated/Decayed/Damaged

Clearance to ground

Clearance to ground

Clearance to ground
Lines down

Cable Damage

Strain

Strain

Strain

Strain

Strain

Strain

Strain

Clearance to ground

Strain

Strain

Strain

Strain

Strain

Strain

Strain

Strain

Strain

Strain

Strain

Strain

Strain

Strain

Strain

Strain

Down guy

Strain

Strain

Strain

Strain

Strain

Strain

Strain

Strain

Strain

Strain

Strain

Strain

Strain

Strain

Strain

Strain

Strain

Strain

Strain

Strain

Strain

Strain

Strain

Strain

Strain

Strain

Strain

Strain

Strain

Strain

Strain

Strain

Strain

Strain

Strain

Strain

Strain

Strain

Strain

Strain

Strain

Strain

Strain

Strain

Strain

Strain

Strain

Strain

Strain

Strain

Strain

Strain

Strain

Strain

Down guy

Down guy

Broken lashing wire

Broken lashing wire

Down guy

Broken lashing wire

Broken lashing wire

Broken lashing wire

Broken lashing wire

Hardware

Hardware

Hardware

Broken lashing wire

Broken lashing wire

Broken lashing wire

Broken lashing wire

Broken lashing wire

Broken lashing wire

Down guy

Broken lashing wire

Broken lashing wire

Hardware

Broken lashing wire

Broken lashing wire

Broken lashing wire

Hardware

Broken lashing wire

Clearance to ground

Broken lashing wire

Broken lashing wire

Broken lashing wire

Broken lashing wire

Hardware

Clearance to ground

Clearance to ground

Clearance to ground

Clearance to ground

Clearance to ground

Clearance to ground

Clearance to ground

Clearance to ground

Strain

Strain

Strain

Strain

Broken lashing wire

Strain

Strain

Strain

Broken lashing wire

Strain

Strain

Strain

Strain

Strain

Strain

Strain

Cable Damage

Cable Damage

Cable Damage

Cable Damage

Cable Damage

Cable Damage

Lines down

Cable Damage

Cable Damage

Cable Damage

Cable Damage

Cable Damage

Lines down

Lines down

Clearance to ground

Lines down

Strain

Strain

Broken lashing wire

Down guy

Cable Damage

Lines down

Cable Damage

Cable Damage

Cable Damage

Cable Damage

Cable Damage

Cable Damage

Cable Damage

Cable Damage

Cable Damage

Cable Damage

Cable Damage

Cable Damage

Cable Damage

Cable Damage

Cable Damage

Cable Damage

Cable Damage

Cable Damage

Cable Damage

Cable Damage

Cable Damage

Cable Damage

Cable Damage

Cable Damage

Cable Damage

Clearance to ground

Clearance to ground

Cable Damage

Cable Damage

Cable Damage

Cable Damage

Cable Damage

Cable Damage

Lines down

Cable Damage

Cable Damage

Cable Damage

Cable Damage

Cable Damage

Cable Damage

Cable Damage

Cable Damage

Cable Damage

Cable Damage

Cable Damage

Cable Damage

Cable Damage

Lines down

Cable Damage

Cable Damage

Cable Damage

Cable Damage

Cable Damage

Lines down

Lines down

Clearance to ground

Complete pole transfer / buddy pole

Clearance to ground

Causing low cable

Lines down

Lines down

Lines down

Strain

Strain

Strain

Strain

Strain

Strain

Strain

Strain

Strain

Strain

Strain

Strain

Strain

Strain

Strain

Strain

Strain

Strain

Strain

Strain

Strain

Strain

Strain

Strain

Strain

Strain

Strain

Strain

Strain

Strain

Strain

Strain

Strain

Strain

Strain

Strain

Strain

Strain

Strain

Strain

Strain

Strain

Strain

Strain

Clearance to ground

Strain

Strain

Strain

Strain

Strain

Strain

Strain

Strain

Strain

Strain

Strain

Strain

Strain

Strain

Strain

Strain

Strain

Strain

Strain

Strain

Strain

Strain

Strain

Strain

Strain

Strain

Strain

Strain

Strain

Strain

Strain

Strain

Strain

Strain

Strain

Strain

Strain

Strain

Strain

Strain

Strain

Strain

Strain

Strain

Strain

Strain

Strain

Strain

Strain

Strain

Strain

Strain

Strain

Strain

Hardware

Hardware

Broken lashing wire

Broken lashing wire

Hardware

Hardware

Hardware

Broken lashing wire

Broken lashing wire

Hardware

Down guy

Hardware

Hardware

Clearance to ground

Clearance to ground

Clearance to ground

Clearance to ground

Clearance to ground

Clearance to ground

Clearance to ground

Clearance to ground

Clearance to ground

Clearance to ground

Clearance to ground

Clearance to ground

Clearance to ground

Strain

Leaning

Deteriorated/Decayed/Damaged

Clearance to ground

Lines down

Broken lashing wire

Deteriorated/Decayed/Damaged
Lines down

Deteriorated/Decayed/Damaged

Clearance to ground

Clearance to ground

Hazardous strain

Clearance to ground

Deteriorated/Decayed/Damaged

Hazardous strain

Hazardous strain

Hazardous strain

Hazardous strain

Hazardous strain

Deteriorated/Decayed/Damaged

Hazardous strain

Clearance to ground

Clearance to ground

Clearance to ground

Clearance to ground

Clearance to ground

Clearance to ground

Causing low cable

Climbing/Working space impaired

Broken lashing wire

Clearance to ground

Clearance to ground

Clearance to ground

Clearance to ground

Complete pole transfer / buddy pole

Clearance to ground

Clearance to ground

Causing low cable

Clearance to ground

Clearance to ground

Clearance to ground

Clearance to ground

Clearance to ground

Down guy

Clearance to ground

Clearance to ground

Clearance to ground

Clearance to ground

Lines down

Service drop riser

Service drop riser

Clearance to ground

Clearance to ground

Clearance to ground

Clearance to ground

Clearance to ground

Down guy

Clearance to ground

Lines down

Clearance to ground

Clearance to ground

Broken lashing wire

Clearance to ground

Clearance to ground

Clearance to ground

Clearance to ground

Clearance to ground

Clearance to ground

Clearance to ground

Clearance to ground

Clearance to ground

Hazard tree

Hazard tree

Lines down

Lines down

Clearance to ground

Clearance to ground

Lines down

Lines down

Causing low cable

Causing low cable

Causing low cable

Causing low cable

Causing low cable

Clearance to ground

Clearance to ground

Clearance to ground

Clearance to ground

Causing low cable

Causing low cable

Causing low cable

Clearance to ground

Climbing/Working space impaired

Clearance to ground

Lines down

Lines down

Clearance to ground

Clearance to ground

Clearance to ground

Clearance to ground

Clearance to ground

Service drop riser

Clearance to ground

Lines down

Clearance to ground

Clearance to ground

Clearance to ground

Clearance to ground

Clearance to ground

Clearance to ground

Clearance to ground

Clearance to ground

Clearance to ground

Lines down

Clearance to ground

Clearance to ground

Clearance to ground

Clearance to ground

Lines down

Clearance to ground

Down guy

Clearance to ground

Clearance to ground

Clearance to ground

Clearance to ground

Clearance to ground

Clearance to ground

Clearance to ground

Service drop riser

Clearance to ground

Clearance to ground

Lines down

Lines down

Leaning

Clearance to ground

Clearance to ground

Clearance to ground

Broken lashing wire

Clearance to ground

Clearance to ground

Lines down

Lines down

Clearance to ground

Lines down

Clearance to ground

Lines down

Lines down

Service drop riser

Clearance to ground

Broken lashing wire

Broken lashing wire

Lines down

Lines down

Clearance to ground

Clearance to ground

Clearance to ground

Lines down

Clearance to ground

Lines down

Lines down

Lines down

Lines down

Clearance to ground

Service drop riser

Service drop riser

Hardware loose/missing/damaged

Service drop riser

Lines down

Service drop riser

Service drop riser

Service drop riser

Service drop riser

Climbing/Working space impaired

Lines down

Lines down

Down guy

Down guy

Lines down

Service drop riser

Complete pole transfer / buddy pole

Down guy

Down guy anchor

Lines down

Service drop riser

Complete pole transfer / buddy pole

Complete pole transfer / buddy pole

Lines down

Down guy

Lines down

Down guy

Down guy

Service drop riser

Hardware

Steps

Lines down

Clearance to ground

Clearance to power

Lines down

Down guy

Hazard tree

Clearance to ground

Down guy

Service drop riser

Down guy

Down guy

Down guy

Down guy anchor

Down guy

Complete pole transfer / buddy pole

Down guy anchor

Leaning

Complete pole transfer / buddy pole

Complete pole transfer / buddy pole

Hardware loose/missing/damaged

Down guy

Down guy

Down guy

Down guy

Climbing/Working space impaired

Climbing/Working space impaired

Hardware

Down guy anchor

Lines down

Hardware loose/missing/damaged

Complete pole transfer / buddy pole

Complete pole transfer / buddy pole

Down guy

Lines down

Down guy

Clearance to power

Complete pole transfer / buddy pole

Service drop riser

Complete pole transfer / buddy pole

Complete pole transfer / buddy pole

Down guy anchor

Broken lashing wire

Down guy anchor

Hardware

Complete pole transfer / buddy pole

Complete pole transfer / buddy pole

Down guy

Down guy

Down guy

Lines down

Complete pole transfer / buddy pole

Hardware

Complete pole transfer / buddy pole

Complete pole transfer / buddy pole

Service drop riser

Complete pole transfer / buddy pole

Complete pole transfer / buddy pole

Service drop riser

Lines down

Cable Riser

Down guy

Down guy

Complete pole transfer / buddy pole

Hardware

Lines down

Leaning

Service drop riser

Lines down

Service drop riser

Down guy anchor

Lines down

Complete pole transfer / buddy pole

Cable Riser

Span-guy or pole-to-pole guy

Complete pole transfer / buddy pole

Down guy

Service drop riser

Down guy

Lines down

Complete pole transfer / buddy pole

Down guy

Deteriorated/Decayed/Damaged

Complete pole transfer / buddy pole

Broken lashing wire

Hardware

Complete pole transfer / buddy pole

Lines down

Down guy

Hardware

Lines down

Hardware

Complete pole transfer / buddy pole

Complete pole transfer / buddy pole

Lines down

Lines down

Down guy

Broken lashing wire

Complete pole transfer / buddy pole

Clearance to ground

Clearance to ground

Clearance to ground

Clearance to ground

Clearance to ground

Clearance to ground

Lines down

Lines down

Lines down

Lines down

Lines down

Hardware loose/missing/damaged

Down guy

Down guy

Down guy anchor

Down guy anchor

Down guy anchor

Down guy anchor

Down guy anchor

Service drop riser

Service drop riser

Service drop riser

Service drop riser

Service drop riser

Service drop riser

Broken lashing wire

Strain

Down guy

Hardware

Lines down

Down guy anchor

Strain

Strain

Lines down

Service drop riser

Strain

Strain

Lines down

Lines down

Down guy

Lines down

Hardware

Strain

Service drop riser

Strain

Lines down

Strain

Strain

Strain

Strain

Lines down

Strain

Strain

Lines down

Strain

Clearance to power

Hardware

Broken lashing wire

Lines down

Lines down

Lines down

Lines down

Strain

Strain

Strain

Down guy

Down guy anchor

Down guy

Strain

Strain

Strain

Clearance to ground

Strain

Strain

Strain

Hardware loose/missing/damaged

Strain

Strain

Strain

Hardware

Hardware

Strain

Clearance to power

Strain

Strain

Strain

Strain

Strain

Strain

Strain

Strain

Service drop riser

Strain

Lines down

Service drop riser

Clearance to ground

Lines down

Strain

Hardware

Lines down

Lines down

Lines down

Lines down

Down guy anchor

Lines down

Strain

Lines down

Down guy

Lines down

Broken lashing wire

Clearance to ground

Strain

Strain

Strain

Lines down

Strain

Strain

Strain

Hardware loose/missing/damaged

Clearance to ground

Clearance to power

Strain

Strain

Strain

Strain

Service drop riser

Lines down

Strain

Strain

Strain

Lines down

Strain

Clearance to ground

Strain

Strain

Strain

Strain

Strain

Strain

Strain

Lines down

Strain

Strain

Clearance to ground

Strain

Clearance to ground

Lines down

Strain

Broken lashing wire

Strain

Strain

Strain

Strain

Strain

Strain

Strain

Clearance to ground

Strain

Strain

Strain

Strain

Service drop riser

Strain

Strain

Strain

Strain

Strain

Complete pole transfer / buddy pole

Complete pole transfer / buddy pole

Complete pole transfer / buddy pole

Complete pole transfer / buddy pole

Complete pole transfer / buddy pole

Complete pole transfer / buddy pole

Complete pole transfer / buddy pole

Complete pole transfer / buddy pole

Lines down

Complete pole transfer / buddy pole

Strain

Strain

Hardware loose/missing/damaged

Strain

Strain

Strain

Strain

Lines down

Service drop riser

Strain

Broken lashing wire

Lines down

Strain

Clearance to ground

Clearance to ground

Strain

Down guy

Clearance to ground

Service drop riser

Clearance to ground

Strain

Lines down

Strain

Hazardous strain

Clearance to ground

Hazard tree

Lines down

Lines down

Lines down

Clearance to ground

Clearance to ground

Clearance to ground

Service drop riser

Service drop riser

Strain

Clearance to ground

Clearance to ground

Clearance to ground

Service drop riser

Lines down

Service drop riser

Clearance to ground

Down guy anchor

Service drop riser

Service drop riser

Lines down

Down guy

Service drop riser

Service drop riser

Clearance to ground

Service drop riser

Clearance to ground

Service drop riser

Clearance to ground

Service drop riser

Service drop riser

Service drop riser

Clearance to ground

Service drop riser

Service drop riser

Clearance to ground

Clearance to ground

Clearance to ground

Lines down

Broken lashing wire

Lines down

Lines down

Leaning

Service drop riser

Service drop riser

Service drop riser

Causing low cable

Hardware loose/missing/damaged

Lines down

Service drop riser

Hardware loose/missing/damaged

Causing low cable

Service drop riser

Hardware loose/missing/damaged

Service drop riser

Hardware loose/missing/damaged

Service drop riser

Hardware loose/missing/damaged

Clearance to ground

Service drop riser

Service drop riser

Clearance to ground

Clearance to ground

Down guy

Clearance to ground

Clearance to ground

Service drop riser

Service drop riser

Service drop riser

Lines down

Service drop riser

Hardware loose/missing/damaged

Hardware loose/missing/damaged

Hardware loose/missing/damaged

Hardware loose/missing/damaged

Hazard tree

Service drop riser

Service drop riser

Service drop riser

Clearance to ground

Lines down

Service drop riser

Service drop riser

Service drop riser

Leaning

Lines down

Service drop riser

Leaning

Service drop riser

Service drop riser

Service drop riser

Lines down

Service drop riser

Broken lashing wire

Clearance to ground

Clearance to ground

Service drop riser

Service drop riser

Service drop riser

Lines down

Service drop riser

Leaning

Lines down

Clearance to ground

Service drop riser

Lines down

Broken lashing wire

Clearance to ground

Service drop riser

Service drop riser

Service drop riser

Service drop riser

Service drop riser

Service drop riser

Service drop riser

Service drop riser

Service drop riser

Service drop riser

Service drop riser

Service drop riser

Service drop riser

Service drop riser

Service drop riser

Service drop riser

Service drop riser

Leaning

Lines down

Lines down

Service drop riser

Span-guy or pole-to-pole guy

Service drop riser

Service drop riser

Service drop riser

Service drop riser

Causing low cable

Clearance to ground

Service drop riser

Service drop riser

Service drop riser

Clearance to ground

Service drop riser

Service drop riser

Leaning

Lines down

Lines down

Service drop riser

Service drop riser

Lines down

Hardware loose/missing/damaged

Service drop riser

Service drop riser

Lines down

Clearance to ground

Service drop riser

Lines down

Clearance to ground

Lines down

Clearance to ground

Clearance to ground

Service drop riser

Lines down

Lines down

Clearance to ground

Down guy

Climbing/Working space impaired

Service drop riser

Service drop riser

Service drop riser

Service drop riser

Span-guy or pole-to-pole guy

Down guy

Lines down

Leaning

Service drop riser

Service drop riser

Lines down

Clearance to ground

Service drop riser

Clearance to power

Service drop riser

Lines down

Service drop riser

Lines down

Down guy

Strain

Service drop riser

Service drop riser

Service drop riser

Service drop riser

Service drop riser

Strain

Leaning

Service drop riser

Broken lashing wire

Lines down

Service drop riser

Service drop riser

Hardware loose/missing/damaged

Service drop riser

Clearance to ground

Service drop riser

Lines down

Service drop riser

Clearance to ground

Hardware loose/missing/damaged

Service drop riser

Service drop riser

Lines down

Lines down

Service drop riser

Clearance to ground

Clearance to ground

Service drop riser

Clearance to ground

Service drop riser

Clearance to ground

Clearance to ground

Leaning

Lines down

Lines down

Service drop riser

Service drop riser

Service drop riser

Service drop riser

Clearance to ground

Down guy

Clearance to ground

Clearance to ground

Lines down

Causing low cable

Clearance to ground

Service drop riser

Service drop riser

Service drop riser

Service drop riser

Service drop riser

Service drop riser

Service drop riser

Service drop riser

Service drop riser

Service drop riser

Lines down

Service drop riser

Service drop riser

Service drop riser

Lines down

Service drop riser

Service drop riser

Service drop riser

Service drop riser

Service drop riser

Service drop riser

Service drop riser

Service drop riser

Service drop riser

Service drop riser

Service drop riser

Lines down

Service drop riser

Service drop riser

Leaning

Clearance to ground

Service drop riser

Lines down

Service drop riser

Service drop riser

Service drop riser

Lines down

Lines down

Service drop riser

Down guy

Lines down

Service drop riser

Service drop riser

Service drop riser

Service drop riser

Down guy

Service drop riser

Lines down

Service drop riser

Service drop riser

Leaning

Lines down

Lines down

Clearance to ground

Lines down

Clearance to ground

Lines down

Down guy

Leaning

Leaning

Lines down

Lines down

Down guy anchor

Hardware

Hardware

Clearance to ground

Cable Riser

Hardware

Down guy

Lines down

Service drop riser

Lines down

Lines down

Service drop riser

Service drop riser

Clearance to ground

Clearance to ground

Clearance to ground

Clearance to ground

Broken lashing wire

Service drop riser

Hardware loose/missing/damaged

Strain

Lines down

Strain

Lines down

Clearance to ground

Clearance to ground

Clearance to ground

Broken lashing wire

Hazard tree

Clearance to ground

Clearance to ground

Clearance to ground

Service drop riser

Clearance to ground

Clearance to ground

Lines down

Service drop riser

Strain

Strain

Hazard tree

Hazard tree

Hazard tree

Lines down

Lines down

Lines down

Service drop riser

Clearance to ground

Hardware loose/missing/damaged

Hardware loose/missing/damaged

Hardware loose/missing/damaged

Service drop riser

Hardware loose/missing/damaged

Clearance to ground

Service drop riser

Lines down

Lines down

Clearance to ground

Strain

Clearance to ground

Clearance to ground

Hazard tree

Clearance to ground

Clearance to ground

Lines down

Lines down

Lines down

Hazard tree

Lines down

Lines down

Clearance to ground

Clearance to ground

Clearance to ground

Clearance to ground

Clearance to ground

Clearance to ground

Clearance to ground

Clearance to ground

Lines down

Lines down

Lines down

Lines down

Clearance to ground

Clearance to ground

Clearance to ground

Clearance to ground

Clearance to ground

Clearance to ground

Clearance to ground

Clearance to ground

Clearance to ground

Clearance to ground

Clearance to ground

Clearance to ground

Clearance to ground

Clearance to ground

Clearance to ground

Clearance to ground

Clearance to ground

Broken lashing wire

Down guy

Clearance to ground

Clearance to ground

Clearance to ground

Clearance to ground

Lines down

Lines down

Clearance to ground

Leaning

Clearance to ground

Causing low cable

Clearance to ground

Clearance to ground

Clearance to ground

Strain

Service drop riser

Service drop riser

Service drop riser

Lines down

Clearance to ground

Clearance to ground

Strain

Strain

Strain

Clearance to ground

Clearance to ground

Clearance to ground

Lines down

Clearance to ground

Hardware loose/missing/damaged

Service drop riser

Hardware loose/missing/damaged

Hardware loose/missing/damaged

Service drop riser

Strain

Strain

Lines down

Hardware loose/missing/damaged

Strain

Strain

Clearance to ground

Lines down

Clearance to ground

Clearance to ground

Clearance to ground

Lines down

Clearance to ground

Clearance to ground

Clearance to ground

Service drop riser

Hardware loose/missing/damaged

Lines down

Lines down

Lines down

Lines down

Lines down

Down guy

Clearance to ground

Strain

Clearance to ground

Lines down

Service drop riser

Clearance to ground

Down guy

Clearance to ground

Clearance to ground

Clearance to ground

Clearance to ground

Clearance to ground

Clearance to ground

Clearance to ground

Clearance to ground

Clearance to ground

Clearance to ground

Clearance to ground

Clearance to ground

Hardware loose/missing/damaged

Clearance to ground

Strain

Strain

Hardware loose/missing/damaged

Clearance to ground

Clearance to ground

Clearance to ground

Clearance to ground

Clearance to ground

Clearance to ground

Clearance to ground

Clearance to ground

Clearance to ground

Clearance to ground

Hardware loose/missing/damaged

Clearance to ground

Hazard tree

Lines down

Lines down

Lines down

Hazard tree

Hazard tree

Clearance to ground

Clearance to ground

Clearance to ground

Broken lashing wire

Clearance to ground

Clearance to ground

Clearance to ground

Hazard tree

Clearance to power

Clearance to ground

Clearance to ground

Clearance to ground

Clearance to ground

Broken lashing wire

Clearance to ground

Broken lashing wire

Clearance to ground

Clearance to ground

Lines down

Service drop riser

Hardware loose/missing/damaged

Clearance to ground

Lines down

Clearance to ground

Clearance to ground

Clearance to ground

Clearance to ground

Clearance to ground

Clearance to ground

Clearance to ground

Clearance to ground

Causing low cable

Causing low cable

Clearance to ground

Clearance to ground

Broken lashing wire

Clearance to ground

Clearance to ground

Lines down

Lines down

Lines down

Lines down

Lines down

Lines down

Clearance to ground

Clearance to ground

Clearance to ground

Clearance to ground

Clearance to ground

Causing low cable

Clearance to ground

Clearance to ground

Clearance to ground

Clearance to ground

Clearance to ground

Clearance to ground

Clearance to ground

Lines down

Lines down

Lines down

Hazard tree

Clearance to power

Lines down

Down guy anchor

Hazardous strain

Lines down

Service drop riser

Service drop riser

Service drop riser

Clearance to ground

Clearance to ground

Hardware loose/missing/damaged

Clearance to ground

Service drop riser

Clearance to ground

Lines down

Clearance to ground

Clearance to ground

Service drop riser

Service drop riser

Down guy

Hardware loose/missing/damaged

Hardware loose/missing/damaged

Strain

Hardware loose/missing/damaged

Hardware loose/missing/damaged

Hardware loose/missing/damaged

Strain

Clearance to ground

Lines down

Lines down

Clearance to power

Service drop riser

Broken lashing wire

Broken lashing wire

Lines down

Lines down

Lines down

Lines down

Lines down

Service drop riser

Down guy anchor

Clearance to ground

Clearance to ground

Service drop riser

Cable Riser

Down guy

Down guy anchor

Service drop riser

Service drop riser

Cable Riser

Lines down

Steps

Down guy

Down guy

Down guy anchor

Service drop riser

Lines down

Service drop riser

Broken lashing wire

Lines down

Lines down

Hardware loose/missing/damaged

Lines down

Service drop riser

Hardware loose/missing/damaged

New guard arm required

Strain

Clearance to ground

Lines down

New guard arm required

Clearance to ground

Clearance to ground

Clearance to ground

Clearance to ground

Lines down

Lines down

Lines down

Service drop riser

Clearance to ground

Span-guy or pole-to-pole guy

Lines down

Lines down

Service drop riser

Service drop riser

Lines down

Service drop riser

Service drop riser

Service drop riser

Service drop riser

Lines down

Lines down

Service drop riser

Service drop riser

Steps

Service drop riser

Lines down

Broken lashing wire

Service drop riser

Lines down

Lines down

Service drop riser

Lines down

New guard arm required

Lines down

Lines down

Clearance to power

Down guy

Service drop riser

Lines down

Lines down

Down guy anchor

Down guy

Down guy anchor

Cable Riser

Lines down

Lines down

Lines down

Lines down

Service drop riser

Clearance to ground

Service drop riser

Service drop riser

Broken lashing wire

Hardware loose/missing/damaged

Service drop riser

Service drop riser

Service drop riser

Down guy

Down guy anchor

Service drop riser

Service drop riser

Clearance to ground

Service drop riser

Complete pole transfer / buddy pole

Complete pole transfer / buddy pole

Service drop riser

Service drop riser

New guard arm required

Clearance to ground

Clearance to ground

Lines down

Down guy

Clearance to ground

Down guy

Complete pole transfer / buddy pole

Lines down

Clearance to communications

Lines down

Down guy anchor

Down guy anchor

Lines down

Complete pole transfer / buddy pole

Complete pole transfer / buddy pole

Lines down

Down guy anchor

Service drop riser

Service drop riser

Service drop riser

Service drop riser

Down guy

Complete pole transfer / buddy pole

Clearance to ground

Cable Riser

Lines down

Equipment within 8ft of ground

Lines down

Lines down

Clearance to ground

Service drop riser

Lines down

Service drop riser

Service drop riser

Service drop riser

Service drop riser

Complete pole transfer / buddy pole

Complete pole transfer / buddy pole

Complete pole transfer / buddy pole

Clearance to ground

Lines down

Cable Riser

Clearance to ground

Complete pole transfer / buddy pole

Cable Riser

Clearance to ground

Lines down

Clearance to power

Steps

Service drop riser

Leaning

Down guy

Complete pole transfer / buddy pole

Lines down

Lines down

Broken lashing wire

Clearance to ground

Cable Riser

Service drop riser

Hardware loose/missing/damaged

Broken lashing wire

Clearance to ground

Clearance to ground

Broken lashing wire

Hardware loose/missing/damaged

Broken lashing wire

Lines down

Cable Riser

Down guy anchor

Deteriorated/Decayed/Damaged

Hazard tree

Clearance to ground

Clearance to ground

Clearance to ground

Clearance to ground

Clearance to ground

Clearance to ground

Clearance to ground

Clearance to ground

Clearance to ground

Clearance to ground

Clearance to ground

Clearance to ground

Clearance to ground

Clearance to ground

Clearance to ground

Clearance to ground

Clearance to ground

Clearance to ground

Clearance to ground

Clearance to ground

Clearance to ground

Clearance to ground

Clearance to ground

Clearance to ground

Clearance to ground

Clearance to ground

Clearance to ground

Clearance to ground

Clearance to ground

Clearance to ground

Clearance to ground

Lines down

Lines down

Lines down

Lines down

Lines down

Lines down

Lines down

Lines down

Lines down

Lines down

Lines down

Broken lashing wire

Broken lashing wire

Broken lashing wire

Down guy

Leaning

Strain

Strain

Complete pole transfer / buddy pole

Complete pole transfer / buddy pole

Complete pole transfer / buddy pole

Complete pole transfer / buddy pole

Complete pole transfer / buddy pole

Complete pole transfer / buddy pole

Complete pole transfer / buddy pole

Complete pole transfer / buddy pole

Complete pole transfer / buddy pole

Complete pole transfer / buddy pole

Complete pole transfer / buddy pole

Complete pole transfer / buddy pole

Complete pole transfer / buddy pole

Complete pole transfer / buddy pole

Complete pole transfer / buddy pole

Complete pole transfer / buddy pole

Complete pole transfer / buddy pole

Complete pole transfer / buddy pole

Complete pole transfer / buddy pole

Complete pole transfer / buddy pole

Complete pole transfer / buddy pole

Complete pole transfer / buddy pole

Complete pole transfer / buddy pole

Complete pole transfer / buddy pole

Complete pole transfer / buddy pole

Complete pole transfer / buddy pole

Complete pole transfer / buddy pole

Complete pole transfer / buddy pole

Complete pole transfer / buddy pole

Complete pole transfer / buddy pole

Complete pole transfer / buddy pole

Complete pole transfer / buddy pole

Complete pole transfer / buddy pole

Complete pole transfer / buddy pole

Complete pole transfer / buddy pole

Complete pole transfer / buddy pole

Complete pole transfer / buddy pole

Complete pole transfer / buddy pole

Complete pole transfer / buddy pole

Complete pole transfer / buddy pole

Complete pole transfer / buddy pole

Complete pole transfer / buddy pole

Complete pole transfer / buddy pole

Complete pole transfer / buddy pole

Complete pole transfer / buddy pole

Complete pole transfer / buddy pole

Complete pole transfer / buddy pole

Complete pole transfer / buddy pole

Complete pole transfer / buddy pole

Complete pole transfer / buddy pole

Complete pole transfer / buddy pole

Complete pole transfer / buddy pole

Complete pole transfer / buddy pole

Complete pole transfer / buddy pole

Complete pole transfer / buddy pole

Clearance to ground

Strain

Clearance to ground

Causing low cable

Clearance to ground

Clearance to ground

Clearance to ground

Clearance to ground

Clearance to ground

Clearance to ground

Clearance to ground

Clearance to ground

Clearance to ground

Clearance to ground

Clearance to ground

Clearance to ground

Clearance to ground

Clearance to ground

Clearance to ground

Clearance to ground

Clearance to ground

Clearance to ground

Clearance to ground

Strain

Clearance to ground

Broken lashing wire

Clearance to ground

Clearance to ground

Clearance to ground

Clearance to ground

Clearance to ground

Clearance to ground

Clearance to ground

Clearance to ground

Clearance to ground

Clearance to ground

Clearance to ground

Clearance to ground

Clearance to ground

Clearance to ground

Clearance to ground

Clearance to ground

Clearance to ground

Clearance to ground

Clearance to ground

Down guy

Clearance to ground

Down guy

Clearance to ground

Clearance to ground

Clearance to ground

Clearance to ground

Clearance to ground

Clearance to ground

Clearance to ground

Strain

Clearance to ground

Clearance to ground

Clearance to ground

Clearance to ground

Clearance to ground

Clearance to ground

Clearance to ground

Clearance to ground

Clearance to ground

Clearance to ground

Clearance to ground

Clearance to ground

Broken lashing wire

Clearance to ground

Strain

Clearance to ground

Clearance to ground

Clearance to ground

Lines down

Clearance to ground

Strain

Clearance to ground

Clearance to ground

Clearance to ground

Clearance to ground

Clearance to ground

Clearance to ground

Clearance to ground

Clearance to ground

Clearance to ground

Broken lashing wire

Down guy

Clearance to ground

Clearance to ground

Clearance to ground

Clearance to ground

Clearance to ground

Clearance to ground

Clearance to ground

Clearance to ground

Clearance to ground

Clearance to ground

Clearance to ground

Clearance to ground

Clearance to ground

Clearance to ground

Clearance to ground

Clearance to ground

Clearance to ground

Clearance to ground

Clearance to ground

Clearance to ground

Clearance to ground

Clearance to ground

Clearance to ground

Clearance to ground

Clearance to ground

Clearance to ground

Clearance to ground

Clearance to ground

Clearance to ground

Clearance to ground

Clearance to ground

Clearance to ground

Clearance to ground

Clearance to ground

Clearance to ground

Broken lashing wire

Lines down

Lines down

Clearance to ground

Broken lashing wire

Lines down

Deteriorated/Decayed/Damaged

Lines down

Clearance to ground

Strain

Strain

Strain

Strain

Lines down

Lines down

Broken lashing wire

Clearance to ground

Hazard tree

Deteriorated/Decayed/Damaged

TYPE_OF_TROUBLE

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Pole Lean of 10 percent or more of height above ground

Clearance to Ground Between 12 and 15ft over roadway

Broken lashing wire hanging More Than 3ft above or below strand

Clearance to ground between 8 and 12ft parallel to roadway

Clearance to Ground Between 12 and 15ft over roadway

Clearance to Ground Between 12 and 15ft over roadway

Clearance to Ground Between 12 and 15ft over roadway

Clearance to Ground between 18 and 25ft over Railroad Tracks

Clearance to Ground Between 12 and 15ft over roadway

Pole Deterioration, Insect or Bird Damage, or Damage by any other means that requires evaluation for replacement

Pole Deterioration, Insect or Bird Damage, or Damage by any other means that requires evaluation for replacement

Pole Deterioration, Insect or Bird Damage, or Damage by any other means that requires evaluation for replacement

Pole Deterioration, Insect or Bird Damage, or Damage by any other means that requires evaluation for replacement

Pole Deterioration, Insect or Bird Damage, or Damage by any other means that requires evaluation for replacement

Pole Deterioration, Insect or Bird Damage, or Damage by any other means that requires evaluation for replacement

Pole Deterioration, Insect or Bird Damage, or Damage by any other means that requires evaluation for replacement

Pole Deterioration, Insect or Bird Damage, or Damage by any other means that requires evaluation for replacement

Pole Deterioration, Insect or Bird Damage, or Damage by any other means that requires evaluation for replacement

Pole Deterioration, Insect or Bird Damage, or Damage by any other means that requires evaluation for replacement

Pole Deterioration, Insect or Bird Damage, or Damage by any other means that requires evaluation for replacement

Pole Deterioration, Insect or Bird Damage, or Damage by any other means that requires evaluation for replacement

Pole Deterioration, Insect or Bird Damage, or Damage by any other means that requires evaluation for replacement

Pole Deterioration, Insect or Bird Damage, or Damage by any other means that requires evaluation for replacement

Pole Deterioration, Insect or Bird Damage, or Damage by any other means that requires evaluation for replacement

Pole Deterioration, Insect or Bird Damage, or Damage by any other means that requires evaluation for replacement

Pole Deterioration, Insect or Bird Damage, or Damage by any other means that requires evaluation for replacement

Pole Deterioration, Insect or Bird Damage, or Damage by any other means that requires evaluation for replacement

Pole Deterioration, Insect or Bird Damage, or Damage by any other means that requires evaluation for replacement

Pole Deterioration, Insect or Bird Damage, or Damage by any other means that requires evaluation for replacement

Clearance to Ground <8ft inaccessible to public Service Drop

Vegetation Causing Damage to Interior of Cable Due to Abrasion

Pole Transfer Required with old pole set in ground

Place New Guy Marker that is Loose/Damaged/Missing - Guy Marker required on outermost guy on each anchor

Vegetation Causing Damage to Interior of Cable Due to Abrasion

Place New Guy Marker that is Loose/Damaged/Missing - Guy Marker required on outermost guy on each anchor

Vegetation Causing Damage to Interior of Cable Due to Abrasion

Vegetation Causing Damage to Interior of Cable Due to Abrasion

Vegetation Causing Damage to Interior of Cable Due to Abrasion

Vegetation Causing Damage to Interior of Cable Due to Abrasion

Place New Guy Marker that is Loose/Damaged/Missing - Guy Marker required on outermost guy on each anchor

Vegetation Causing Damage to Interior of Cable Due to Abrasion

Place New Guy Marker that is Loose/Damaged/Missing - Guy Marker required on outermost guy on each anchor

Broken lashing wire hanging Less Than 3ft above or below strand

Clearance to Ground Between 15 and 18ft over roadway

Pole Transfer Required with old pole set in ground

Vegetation Causing Damage to Interior of Cable Due to Abrasion

Clearance to ground between 12 and 18ft (Urban) or 15ft (Rural/Suburban) parallel to roadway

Vegetation Causing Damage to Interior of Cable Due to Abrasion

Loose/Missing/Damaged -Inaccessible to Public or Not Immediate Risk

Place New Guy Marker that is Loose/Damaged/Missing - Guy Marker required on outermost guy on each anchor

Loose/Missing/Damaged -Inaccessible to Public or Not Immediate Risk

Place New Guy Marker that is Loose/Damaged/Missing - Guy Marker required on outermost guy on each anchor

Clearance to Ground Between 15 and 18ft over roadway

Place New Guy Marker that is Loose/Damaged/Missing - Guy Marker required on outermost guy on each anchor

Place New Guy Marker that is Loose/Damaged/Missing - Guy Marker required on outermost guy on each anchor

Place New Guy Marker that is Loose/Damaged/Missing - Guy Marker required on outermost guy on each anchor

Place New Guy Marker that is Loose/Damaged/Missing - Guy Marker required on outermost guy on each anchor

Loose/Missing/Damaged -Inaccessible to Public or Not Immediate Risk

Pole Transfer Required with old pole set in ground

Place New Guy Marker that is Loose/Damaged/Missing - Guy Marker required on outermost guy on each anchor

Pole Transfer Required with old pole set in ground

Place New Guy Marker that is Loose/Damaged/Missing - Guy Marker required on outermost guy on each anchor

Place New Guy Marker that is Loose/Damaged/Missing - Guy Marker required on outermost guy on each anchor

Place New Guy Marker that is Loose/Damaged/Missing - Guy Marker required on outermost guy on each anchor

Loose/Missing/Damaged -Inaccessible to Public or Not Immediate Risk

Place New Guy Marker that is Loose/Damaged/Missing - Guy Marker required on outermost guy on each anchor

Broken lashing wire hanging Less Than 3ft above or below strand

Vegetation Causing Damage to Interior of Cable Due to Abrasion

Vegetation Causing Damage to Interior of Cable Due to Abrasion

Vegetation Causing Damage to Interior of Cable Due to Abrasion

Vegetation Causing Damage to Interior of Cable Due to Abrasion

Loose/Missing/Damaged -Inaccessible to Public or Not Immediate Risk

Vegetation Causing Damage to Interior of Cable Due to Abrasion

Loose/Missing/Damaged -Inaccessible to Public or Not Immediate Risk

Vegetation Causing Damage to Interior of Cable Due to Abrasion

Inaccessible to Public Lines Down

Clearance to ground between 12 and 18ft (Urban) or 15ft (Rural/Suburban) parallel to roadway

Clearance to Ground Between 15 and 18ft over roadway

Vegetation Causing Damage to Interior of Cable Due to Abrasion

Vegetation Causing Damage to Interior of Cable Due to Abrasion

Vegetation Causing Damage to Interior of Cable Due to Abrasion

Vegetation Causing Damage to Interior of Cable Due to Abrasion

Vegetation Causing Damage to Interior of Cable Due to Abrasion

Vegetation Causing Damage to Interior of Cable Due to Abrasion

Loose/Missing/Damaged -Inaccessible to Public or Not Immediate Risk

Pole Transfer Required with old pole set in ground

Vegetation Causing Damage to Interior of Cable Due to Abrasion

Pole Transfer Required with old pole set in ground

Vegetation Causing Damage to Interior of Cable Due to Abrasion

Vegetation Causing Damage to Interior of Cable Due to Abrasion

Vegetation Causing Damage to Interior of Cable Due to Abrasion

Vegetation Causing Damage to Interior of Cable Due to Abrasion

Vegetation Causing Damage to Interior of Cable Due to Abrasion

Vegetation Causing Damage to Interior of Cable Due to Abrasion

Vegetation Causing Damage to Interior of Cable Due to Abrasion

Vegetation Causing Damage to Interior of Cable Due to Abrasion

Vegetation Causing Damage to Interior of Cable Due to Abrasion

Vegetation Causing Damage to Interior of Cable Due to Abrasion

Vegetation Causing Damage to Interior of Cable Due to Abrasion

Vegetation Causing Damage to Interior of Cable Due to Abrasion

Vegetation Causing Damage to Interior of Cable Due to Abrasion

Vegetation Causing Damage to Interior of Cable Due to Abrasion

Vegetation Causing Damage to Interior of Cable Due to Abrasion

Inaccessible to Public Lines Down

Hanging or Cut Drop

Hanging or Cut Drop

Accessible to Public Lines Down

Hanging or Cut Drop

Vegetation Causing Damage to Interior of Cable Due to Abrasion

Vegetation management required to resolve low cable

Pole Lean of 10 percent or more of height above ground

Pole Lean of 10 percent or more of height above ground

Vegetation Causing Damage to Interior of Cable Due to Abrasion

Vegetation Causing Damage to Interior of Cable Due to Abrasion

Hanging or Cut Drop

Pole Lean of 10 percent or more of height above ground

Pole Lean of 10 percent or more of height above ground

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Broken lashing wire hanging More Than 3ft above or below strand

Broken lashing wire hanging More Than 3ft above or below strand

Clearance to ground between 8 and 12ft parallel to roadway

Pole Deterioration, Insect or Bird Damage, or Damage by any other means that requires evaluation for replacement

Pole Transfer Required with Impairments (Clearances, leaning, etc.)

Pole Deterioration, Insect or Bird Damage, or Damage by any other means that requires evaluation for replacement

Pole Deterioration, Insect or Bird Damage, or Damage by any other means that requires evaluation for replacement

Pole Deterioration, Insect or Bird Damage, or Damage by any other means that requires evaluation for replacement

Loose/Missing/Damaged -Inaccessible to Public or Not Immediate Risk

Inaccessible to Public Lines Down

Pole Transfer Required with old pole set in ground

Re-Tension Guy

Clearance to ground between 12 and 18ft (Urban) or 15ft (Rural/Suburban) parallel to roadway

Place New Guy Marker that is Loose/Damaged/Missing - Guy Marker required on outermost guy on each anchor

Vegetation Causing Damage to Interior of Cable Due to Abrasion

Vegetation Causing Damage to Interior of Cable Due to Abrasion

Clearance to Ground <8ft inaccessible to public Service Drop

Loose/Missing/Damaged -Inaccessible to Public or Not Immediate Risk

Loose/Missing/Damaged -Inaccessible to Public or Not Immediate Risk

Vegetation Causing Damage to Interior of Cable Due to Abrasion

Vegetation Causing Damage to Interior of Cable Due to Abrasion

Vegetation Causing Damage to Interior of Cable Due to Abrasion

Loose/Missing/Damaged -Inaccessible to Public or Not Immediate Risk

Re-Tension Guy

Place New Guy Marker that is Loose/Damaged/Missing - Guy Marker required on outermost guy on each anchor

Vegetation Causing Damage to Interior of Cable Due to Abrasion

Clearance to ground between 12 and 18ft (Urban) or 15ft (Rural/Suburban) parallel to roadway

Vegetation Causing Damage to Interior of Cable Due to Abrasion

Vegetation Causing Damage to Interior of Cable Due to Abrasion

Loose/Missing/Damaged -Inaccessible to Public or Not Immediate Risk

Vegetation Causing Damage to Interior of Cable Due to Abrasion

Place New Guy Marker that is Loose/Damaged/Missing - Guy Marker required on outermost guy on each anchor

Vegetation Causing Damage to Interior of Cable Due to Abrasion

Vegetation Causing Damage to Interior of Cable Due to Abrasion

Loose/Missing/Damaged -Inaccessible to Public or Not Immediate Risk

Clearance to Ground Between 15 and 18ft over roadway

Place New Guy Marker that is Loose/Damaged/Missing - Guy Marker required on outermost guy on each anchor

Vegetation Causing Damage to Interior of Cable Due to Abrasion

Vegetation Causing Damage to Interior of Cable Due to Abrasion

Vegetation Causing Damage to Interior of Cable Due to Abrasion

Pole Transfer Required with old pole set in ground

Vegetation Causing Damage to Interior of Cable Due to Abrasion

Vegetation Causing Damage to Interior of Cable Due to Abrasion

Vegetation Causing Damage to Interior of Cable Due to Abrasion

Pole Transfer Required with old pole set in ground

Vegetation Causing Damage to Interior of Cable Due to Abrasion

Place New Guy Marker that is Loose/Damaged/Missing - Guy Marker required on outermost guy on each anchor

Vegetation Causing Damage to Interior of Cable Due to Abrasion

Pole Transfer Required with old pole set in ground

Vegetation Causing Damage to Interior of Cable Due to Abrasion

Vegetation Causing Damage to Interior of Cable Due to Abrasion

Inaccessible to Public Lines Down

Loose/Missing/Damaged -Inaccessible to Public or Not Immediate Risk

Inaccessible to Public Lines Down

Vegetation Causing Damage to Interior of Cable Due to Abrasion

Pole Transfer Required with old pole set in ground

Vegetation Causing Damage to Interior of Cable Due to Abrasion

Vegetation Causing Damage to Interior of Cable Due to Abrasion

Vegetation Causing Damage to Interior of Cable Due to Abrasion

Loose/Missing/Damaged -Inaccessible to Public or Not Immediate Risk

Vegetation Causing Damage to Interior of Cable Due to Abrasion

Vegetation Causing Damage to Interior of Cable Due to Abrasion

Place New Guy Marker that is Loose/Damaged/Missing - Guy Marker required on outermost guy on each anchor

Pole Transfer Required with old pole set in ground

Vegetation Causing Damage to Interior of Cable Due to Abrasion

Place New Guy Marker that is Loose/Damaged/Missing - Guy Marker required on outermost guy on each anchor

Vegetation Causing Damage to Interior of Cable Due to Abrasion

Pole Transfer Required with old pole set in ground

Loose/Missing/Damaged -Inaccessible to Public or Not Immediate Risk

Place New Guy Marker that is Loose/Damaged/Missing - Guy Marker required on outermost guy on each anchor

Hanging or Cut Drop

Hanging or Cut Drop

Hanging or Cut Drop

Accessible to Public Lines Down

Accessible to Public Lines Down

Accessible to Public Lines Down

Hanging or Cut Drop

Accessible to Public Lines Down

Accessible to Public Lines Down

Accessible to Public Lines Down

Pole Lean of 10 percent or more of height above ground

Pole Lean of 10 percent or more of height above ground

Place/Replace Down Guy and/or Down Guy Hardware - Insufficient or Loose/Damaged/Missing

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Broken lashing wire hanging More Than 3ft above or below strand

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Pole Deterioration, Insect or Bird Damage, or Damage by any other means that requires evaluation for replacement

Primary Power to Service Drop Less Than 36in at Pole

Vegetation Causing Damage to Interior of Cable Due to Abrasion

Vegetation management required to resolve low service drop

Vegetation Causing Damage to Interior of Cable Due to Abrasion

Clearance to Ground <8ft inaccessible to public Service Drop

Clearance to Ground <8ft inaccessible to public Service Drop

Vegetation Causing Damage to Interior of Cable Due to Abrasion

Vegetation Causing Damage to Interior of Cable Due to Abrasion

Vegetation Causing Damage to Interior of Cable Due to Abrasion

Vegetation Causing Damage to Interior of Cable Due to Abrasion

Vegetation Causing Damage to Interior of Cable Due to Abrasion

Inaccessible to Public Lines Down

Vegetation Causing Damage to Interior of Cable Due to Abrasion

Vegetation Causing Damage to Interior of Cable Due to Abrasion

Vegetation Causing Damage to Interior of Cable Due to Abrasion

Vegetation Causing Damage to Interior of Cable Due to Abrasion

Vegetation Causing Damage to Interior of Cable Due to Abrasion

Vegetation Causing Damage to Interior of Cable Due to Abrasion

Vegetation Causing Damage to Interior of Cable Due to Abrasion

Vegetation Causing Damage to Interior of Cable Due to Abrasion

Inaccessible to Public Lines Down

Vegetation Causing Damage to Interior of Cable Due to Abrasion

Vegetation Causing Damage to Interior of Cable Due to Abrasion

Vegetation Causing Damage to Interior of Cable Due to Abrasion

Vegetation management required to resolve low service drop

Accessible to Public

Inaccessible to Public

Hanging or Cut Drop

Hanging or Cut Drop

Accessible to Public Lines Down

Accessible to Public Lines Down

Accessible to Public Lines Down

Accessible to Public Lines Down

Accessible to Public Lines Down

Hanging or Cut Drop

Hanging or Cut Drop

Accessible to Public Lines Down

Hanging or Cut Drop

Accessible to Public Lines Down

Hanging or Cut Drop

Hanging or Cut Drop

Hanging or Cut Drop

Loose/Missing/Damaged - Accessible to Public

Pole Lean of 10 percent or more of height above ground

Broken lashing wire hanging Less Than 3ft above or below strand

Broken lashing wire hanging Less Than 3ft above or below strand

Hazardous Pole with Immediate Risk due to Deterioration, Insect or Bird Damage, or Damage by any other means

GO95 Cable

Clearance to Ground <8ft inaccessible to public Service Drop

Clearance to Ground Between 12 and 18ft over roadway or 16ft at the curb
Accessible to Public Lines Down

Vegetation Causing Damage to Interior of Cable Due to Abrasion

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Clearance to ground between 8 and 12ft parallel to roadway

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Loose Down Guy with Pole Lean or Deflection

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Re-Tension Guy

Place New Guy Marker that is Loose/Damaged/Missing - Guy Marker required on outermost guy on each anchor

Broken lashing wire hanging Less Than 3ft above or below strand

Broken lashing wire hanging Less Than 3ft above or below strand

Place New Guy Marker that is Loose/Damaged/Missing - Guy Marker required on outermost guy on each anchor

Broken lashing wire hanging Less Than 3ft above or below strand

Broken lashing wire hanging Less Than 3ft above or below strand

Broken lashing wire hanging Less Than 3ft above or below strand

Broken lashing wire hanging Less Than 3ft above or below strand

Loose/Missing/Damaged -Inaccessible to Public or Not Immediate Risk

Loose/Missing/Damaged -Inaccessible to Public or Not Immediate Risk

Loose/Missing/Damaged -Inaccessible to Public or Not Immediate Risk

Broken lashing wire hanging Less Than 3ft above or below strand

Broken lashing wire hanging Less Than 3ft above or below strand

Broken lashing wire hanging Less Than 3ft above or below strand

Broken lashing wire hanging Less Than 3ft above or below strand

Broken lashing wire hanging Less Than 3ft above or below strand

Broken lashing wire hanging Less Than 3ft above or below strand

Place New Guy Marker that is Loose/Damaged/Missing - Guy Marker required on outermost guy on each anchor

Broken lashing wire hanging Less Than 3ft above or below strand

Broken lashing wire hanging Less Than 3ft above or below strand

Loose/Missing/Damaged -Inaccessible to Public or Not Immediate Risk

Broken lashing wire hanging Less Than 3ft above or below strand

Broken lashing wire hanging Less Than 3ft above or below strand

Broken lashing wire hanging Less Than 3ft above or below strand

Loose/Missing/Damaged -Inaccessible to Public or Not Immediate Risk

Broken lashing wire hanging Less Than 3ft above or below strand

Clearance to Ground <8ft inaccessible to public Service Drop

Broken lashing wire hanging Less Than 3ft above or below strand

Broken lashing wire hanging Less Than 3ft above or below strand

Broken lashing wire hanging Less Than 3ft above or below strand

Broken lashing wire hanging Less Than 3ft above or below strand

Broken lashing wire hanging Less Than 3ft above or below strand

Loose/Missing/Damaged -Inaccessible to Public or Not Immediate Risk

Clearance to Ground <8ft accessible to public

Clearance to Ground <8ft accessible to public

Clearance to Ground <8ft accessible to public

Clearance to Ground <8ft accessible to public

Clearance to Ground <8ft accessible to public

Clearance to Ground <8ft accessible to public

Clearance to Ground <8ft accessible to public

Clearance to Ground <8ft accessible to public

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Broken lashing wire hanging More Than 3ft above or below strand

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Broken lashing wire hanging More Than 3ft above or below strand

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Vegetation Causing Damage to Interior of Cable Due to Abrasion

Vegetation Causing Damage to Interior of Cable Due to Abrasion

Vegetation Causing Damage to Interior of Cable Due to Abrasion

Vegetation Causing Damage to Interior of Cable Due to Abrasion

Vegetation Causing Damage to Interior of Cable Due to Abrasion

Vegetation Causing Damage to Interior of Cable Due to Abrasion

Inaccessible to Public Lines Down

Vegetation Causing Damage to Interior of Cable Due to Abrasion

Vegetation Causing Damage to Interior of Cable Due to Abrasion

Vegetation Causing Damage to Interior of Cable Due to Abrasion

Vegetation Causing Damage to Interior of Cable Due to Abrasion

Vegetation Causing Damage to Interior of Cable Due to Abrasion

Accessible to Public Lines Down

Accessible to Public Lines Down

Clearance to Ground <8ft accessible to public

Accessible to Public Lines Down

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Broken lashing wire hanging More Than 3ft above or below strand

Loose Down Guy with Pole Lean or Deflection

Vegetation Causing Damage to Interior of Cable Due to Abrasion

Inaccessible to Public Lines Down

Vegetation Causing Damage to Interior of Cable Due to Abrasion

Vegetation Causing Damage to Interior of Cable Due to Abrasion

Vegetation Causing Damage to Interior of Cable Due to Abrasion

Vegetation Causing Damage to Interior of Cable Due to Abrasion

Vegetation Causing Damage to Interior of Cable Due to Abrasion

Vegetation Causing Damage to Interior of Cable Due to Abrasion

Vegetation Causing Damage to Interior of Cable Due to Abrasion

Vegetation Causing Damage to Interior of Cable Due to Abrasion

Vegetation Causing Damage to Interior of Cable Due to Abrasion

Vegetation Causing Damage to Interior of Cable Due to Abrasion

Vegetation Causing Damage to Interior of Cable Due to Abrasion

Vegetation Causing Damage to Interior of Cable Due to Abrasion

Vegetation Causing Damage to Interior of Cable Due to Abrasion

Vegetation Causing Damage to Interior of Cable Due to Abrasion

Vegetation Causing Damage to Interior of Cable Due to Abrasion

Vegetation Causing Damage to Interior of Cable Due to Abrasion

Vegetation Causing Damage to Interior of Cable Due to Abrasion

Vegetation Causing Damage to Interior of Cable Due to Abrasion

Vegetation Causing Damage to Interior of Cable Due to Abrasion

Vegetation Causing Damage to Interior of Cable Due to Abrasion

Vegetation Causing Damage to Interior of Cable Due to Abrasion

Vegetation Causing Damage to Interior of Cable Due to Abrasion

Vegetation Causing Damage to Interior of Cable Due to Abrasion

Vegetation Causing Damage to Interior of Cable Due to Abrasion

Vegetation Causing Damage to Interior of Cable Due to Abrasion

Clearance to Ground Between 12 and 18ft over roadway or 16ft at the curb

Clearance to Ground Between 12 and 18ft over roadway or 16ft at the curb

Vegetation Causing Damage to Interior of Cable Due to Abrasion

Vegetation Causing Damage to Interior of Cable Due to Abrasion

Vegetation Causing Damage to Interior of Cable Due to Abrasion

Vegetation Causing Damage to Interior of Cable Due to Abrasion

Vegetation Causing Damage to Interior of Cable Due to Abrasion

Vegetation Causing Damage to Interior of Cable Due to Abrasion

Inaccessible to Public Lines Down

Vegetation Causing Damage to Interior of Cable Due to Abrasion

Vegetation Causing Damage to Interior of Cable Due to Abrasion

Vegetation Causing Damage to Interior of Cable Due to Abrasion

Vegetation Causing Damage to Interior of Cable Due to Abrasion

Vegetation Causing Damage to Interior of Cable Due to Abrasion

Vegetation Causing Damage to Interior of Cable Due to Abrasion

Vegetation Causing Damage to Interior of Cable Due to Abrasion

Vegetation Causing Damage to Interior of Cable Due to Abrasion

Vegetation Causing Damage to Interior of Cable Due to Abrasion

Vegetation Causing Damage to Interior of Cable Due to Abrasion

Vegetation Causing Damage to Interior of Cable Due to Abrasion

Vegetation Causing Damage to Interior of Cable Due to Abrasion

Vegetation Causing Damage to Interior of Cable Due to Abrasion

Inaccessible to Public Lines Down

Vegetation Causing Damage to Interior of Cable Due to Abrasion

Vegetation Causing Damage to Interior of Cable Due to Abrasion

Vegetation Causing Damage to Interior of Cable Due to Abrasion

Vegetation Causing Damage to Interior of Cable Due to Abrasion

Vegetation Causing Damage to Interior of Cable Due to Abrasion

Accessible to Public Lines Down

Accessible to Public Lines Down

Hanging or Cut Drop

Pole Transfer Required - Section of old pole attached to new pole (Cut/Kick)

Hanging or Cut Drop

Vegetation management required to resolve low cable

Accessible to Public Lines Down

Accessible to Public Lines Down

Accessible to Public Lines Down

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Clearance to ground between 8 and 12ft parallel to roadway

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Loose/Missing/Damaged -Inaccessible to Public or Not Immediate Risk

Loose/Missing/Damaged -Inaccessible to Public or Not Immediate Risk

Broken lashing wire hanging Less Than 3ft above or below strand

Broken lashing wire hanging Less Than 3ft above or below strand

Loose/Missing/Damaged -Inaccessible to Public or Not Immediate Risk

Loose/Missing/Damaged -Inaccessible to Public or Not Immediate Risk

Loose/Missing/Damaged -Inaccessible to Public or Not Immediate Risk

Broken lashing wire hanging Less Than 3ft above or below strand

Broken lashing wire hanging Less Than 3ft above or below strand

Loose/Missing/Damaged -Inaccessible to Public or Not Immediate Risk

Place New Guy Marker that is Loose/Damaged/Missing - Guy Marker required on outermost guy on each anchor

Loose/Missing/Damaged -Inaccessible to Public or Not Immediate Risk

Loose/Missing/Damaged -Inaccessible to Public or Not Immediate Risk

Clearance to Ground <8ft accessible to public

Clearance to Ground <8ft accessible to public

Clearance to Ground <8ft accessible to public

Clearance to Ground <8ft accessible to public

Clearance to Ground <8ft accessible to public

Clearance to Ground <8ft accessible to public

Clearance to Ground <8ft accessible to public

Clearance to Ground <8ft accessible to public

Clearance to Ground <8ft accessible to public

Clearance to Ground <8ft accessible to public

Clearance to Ground <8ft accessible to public

Clearance to Ground <8ft accessible to public

Clearance to Ground <8ft accessible to public

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

GO95 Pole

Hazardous Pole with Immediate Risk due to Deterioration, Insect or Bird Damage, or Damage by any other means

Hazardous - Clearance to Ground <8ft accessible to public

Accessible to Public

Separation between cable and strand due to broken lashing wire

Pole Deterioration, Insect or Bird Damage, or Damage by any other means that requires evaluation for replacement
Accessible to Public

Hazardous Pole with Immediate Risk due to Deterioration, Insect or Bird Damage, or Damage by any other means

GO95 Cable

GO95 Cable

GO95 Vegetation

GO95 Cable

GO95 Pole

GO95 Vegetation

GO95 Vegetation

GO95 Vegetation

GO95 Vegetation

GO95 Vegetation

GO95 Pole

GO95 Vegetation

Hanging or Cut Drop

Hanging or Cut Drop

Hanging or Cut Drop

Hanging or Cut Drop

Hanging or Cut Drop

Clearance to Ground <8ft accessible to public

Vegetation management required to resolve low cable

Drops - Service Drop (Aerial, Riser, or 6-Pair Terminal) in Climbing Space or Working Space

Broken lashing wire hanging More Than 3ft above or below strand

Clearance to Ground <8ft accessible to public

Clearance to Ground <8ft accessible to public

Clearance to Ground <8ft accessible to public

Clearance to Ground <8ft accessible to public

Pole Transfer Required with old pole set in ground

Clearance to Ground <8ft accessible to public

Hanging or Cut Drop

Vegetation management required to resolve low cable

Hanging or Cut Drop

Clearance to Ground <8ft accessible to public

Clearance to Ground <8ft accessible to public

Hanging or Cut Drop

Clearance to Ground <8ft accessible to public

Place/Replace Down Guy and/or Down Guy Hardware - Insufficient or Loose/Damaged/Missing

Hanging or Cut Drop

Hanging or Cut Drop

Clearance to Ground <8ft accessible to public

Clearance to Ground <8ft accessible to public

Accessible to Public Lines Down

Riser Cover - Loose/Missing/Damaged - Accessible to Public

Riser Cover - Loose/Missing/Damaged - Accessible to Public

Hanging or Cut Drop

Hanging or Cut Drop

Hanging or Cut Drop

Hanging or Cut Drop

Hanging or Cut Drop

Place/Replace Down Guy and/or Down Guy Hardware - Insufficient or Loose/Damaged/Missing

Clearance to Ground <8ft accessible to public

Accessible to Public Lines Down

Clearance to Ground <8ft accessible to public

Hanging or Cut Drop

Broken lashing wire hanging More Than 3ft above or below strand

Clearance to Ground <8ft accessible to public

Clearance to Ground <8ft accessible to public

Hanging or Cut Drop

Hanging or Cut Drop

Hanging or Cut Drop

Clearance to Ground <8ft accessible to public

Clearance to Ground Between 12 and 15ft over roadway

Clearance to Ground Less Than 12ft over Driveway or Private Road

Clearance to Ground Between 12 and 15ft over roadway

Hazard Tree - Dead Tree or Portion of Tree that may fall into Cable/Strand

Hazard Tree - Dead Tree or Portion of Tree that may fall into Cable/Strand

Accessible to Public Lines Down

Accessible to Public Lines Down

Clearance to Ground <8ft accessible to public

Clearance to Ground <8ft accessible to public

Accessible to Public Lines Down

Accessible to Public Lines Down

Vegetation management required to resolve low cable

Vegetation management required to resolve low cable

Vegetation management required to resolve low cable

Vegetation management required to resolve low cable

Vegetation management required to resolve low cable

Clearance to Ground <8ft accessible to public

Clearance to Ground <8ft accessible to public

Clearance to Ground <8ft accessible to public

Hanging or Cut Drop

Vegetation management required to resolve low cable

Vegetation management required to resolve low cable

Vegetation management required to resolve low cable

Hanging or Cut Drop

Cable (Aerial, Riser, or Splice) in Climbing Space or Working Space

Hanging or Cut Drop

Accessible to Public Lines Down

Accessible to Public Lines Down

Clearance to Ground <8ft accessible to public

Clearance to Ground <8ft accessible to public

Clearance to Ground <8ft accessible to public

Clearance to Ground <8ft accessible to public

Clearance to Ground <8ft accessible to public

Riser Cover - Loose/Missing/Damaged - Accessible to Public

Clearance to Ground <8ft accessible to public

Accessible to Public Lines Down

Hanging or Cut Drop

Hanging or Cut Drop

Hanging or Cut Drop

Hanging or Cut Drop

Hanging or Cut Drop

Hanging or Cut Drop

Hanging or Cut Drop

Hanging or Cut Drop

Clearance to Ground <8ft accessible to public

Accessible to Public Lines Down

Clearance to Ground <8ft accessible to public

Clearance to Ground Less Than 12ft over Driveway or Private Road

Clearance to Ground <8ft accessible to public

Clearance to Ground <8ft accessible to public

Accessible to Public Lines Down

Hanging or Cut Drop

Place/Replace Down Guy and/or Down Guy Hardware - Insufficient or Loose/Damaged/Missing

Hanging or Cut Drop

Clearance to Ground <8ft accessible to public

Hanging or Cut Drop

Clearance to Ground <8ft accessible to public

Clearance to Ground <8ft accessible to public

Clearance to Ground <8ft accessible to public

Clearance to Ground <8ft accessible to public

Riser Cover - Loose/Missing/Damaged - Accessible to Public

Clearance to Ground <8ft accessible to public

Clearance to Ground <8ft accessible to public

Accessible to Public Lines Down

Accessible to Public Lines Down

Pole Lean of 10 percent or more of height above ground

Hanging or Cut Drop

Hanging or Cut Drop

Clearance to Ground <8ft accessible to public

Broken lashing wire hanging More Than 3ft above or below strand

Clearance to Ground <8ft accessible to public

Clearance to Ground <8ft accessible to public

Accessible to Public Lines Down

Accessible to Public Lines Down

Clearance to Ground <8ft accessible to public

Accessible to Public Lines Down

Clearance to Ground <8ft accessible to public

Accessible to Public Lines Down

Accessible to Public Lines Down

Riser Cover - Loose/Missing/Damaged - Accessible to Public

Clearance to Ground <8ft accessible to public

Broken lashing wire hanging More Than 3ft above or below strand

Broken lashing wire hanging More Than 3ft above or below strand

Accessible to Public Lines Down

Accessible to Public Lines Down

Clearance to Ground <8ft accessible to public

Clearance to Ground <8ft accessible to public

Clearance to Ground <8ft accessible to public

Accessible to Public Lines Down

Clearance to Ground <8ft accessible to public

Accessible to Public Lines Down

Accessible to Public Lines Down

Accessible to Public Lines Down

Accessible to Public Lines Down

Clearance to Ground <8ft accessible to public

Riser Cover - Loose/Missing/Damaged - Accessible to Public

Riser Cover - Loose/Missing/Damaged - Accessible to Public

Loose/Missing/Damaged - Accessible to Public

Riser Cover - Loose/Missing/Damaged - Accessible to Public

Accessible to Public Lines Down

Riser Cover - Loose/Missing/Damaged - Accessible to Public

Riser Cover - Loose/Missing/Damaged - Accessible to Public

Riser Cover - Loose/Missing/Damaged - Accessible to Public

Riser Cover - Loose/Missing/Damaged - Accessible to Public

Drops - Service Drop (Aerial, Riser, or 6-Pair Terminal) in Climbing Space or Working Space

Accessible to Public Lines Down

Accessible to Public Lines Down

Place New Guy Marker that is Loose/Damaged/Missing - Guy Marker required on outermost guy on each anchor

Place New Guy Marker that is Loose/Damaged/Missing - Guy Marker required on outermost guy on each anchor

Accessible to Public Lines Down

Riser Cover - Loose/Missing/Damaged - Accessible to Public

Pole Transfer Required with old pole set in ground

Place New Guy Marker that is Loose/Damaged/Missing - Guy Marker required on outermost guy on each anchor

Replace Deteriorated anchor with Loose Down Guy and exposed anchor rod of Greater than 18in

Accessible to Public Lines Down

Riser Cover - Loose/Missing/Damaged - Accessible to Public

Pole Transfer Required with old pole set in ground

Pole Transfer Required with old pole set in ground

Accessible to Public Lines Down

Place New Guy Marker that is Loose/Damaged/Missing - Guy Marker required on outermost guy on each anchor

Accessible to Public Lines Down

Place New Guy Marker that is Loose/Damaged/Missing - Guy Marker required on outermost guy on each anchor

Place/Replace Down Guy and/or Down Guy Hardware - Insufficient or Loose/Damaged/Missing

Riser Cover - Loose/Missing/Damaged - Accessible to Public

Loose/Missing/Damaged -Inaccessible to Public or Not Immediate Risk

Remove Step below 8ft Above Ground

Accessible to Public Lines Down

Clearance to Ground <8ft accessible to public

Secondary Power to Service Drop Between 36 and 48in at Pole

Accessible to Public Lines Down

Place New Guy Marker that is Loose/Damaged/Missing - Guy Marker required on outermost guy on each anchor

Hazard Tree - Dead Tree or Portion of Tree that may fall into Cable/Strand

Hanging or Cut Drop

Place New Guy Marker that is Loose/Damaged/Missing - Guy Marker required on outermost guy on each anchor

Riser Cover - Loose/Missing/Damaged - Accessible to Public

Place New Guy Marker that is Loose/Damaged/Missing - Guy Marker required on outermost guy on each anchor

Place New Guy Marker that is Loose/Damaged/Missing - Guy Marker required on outermost guy on each anchor

Re-Tension Guy

Replace Deteriorated anchor with Loose Down Guy and exposed anchor rod of Greater than 18in

Re-Tension Guy

Pole Transfer Required with old pole set in ground

Replace Deteriorated anchor with Loose Down Guy and exposed anchor rod of Greater than 18in

Pole Lean of 10 percent or more of height above ground

Pole Transfer Required with old pole set in ground

Pole Transfer Required with old pole set in ground

Loose/Missing/Damaged - Accessible to Public

Place New Guy Marker that is Loose/Damaged/Missing - Guy Marker required on outermost guy on each anchor

Place New Guy Marker that is Loose/Damaged/Missing - Guy Marker required on outermost guy on each anchor

Place/Replace Down Guy and/or Down Guy Hardware - Insufficient or Loose/Damaged/Missing

Place New Guy Marker that is Loose/Damaged/Missing - Guy Marker required on outermost guy on each anchor

Drops - Service Drop (Aerial, Riser, or 6-Pair Terminal) in Climbing Space or Working Space

Drops - Service Drop (Aerial, Riser, or 6-Pair Terminal) in Climbing Space or Working Space

Loose/Missing/Damaged -Inaccessible to Public or Not Immediate Risk

Expose Anchor with less than 6in of Anchor Rod above ground

Accessible to Public Lines Down

Loose/Missing/Damaged - Accessible to Public

Pole Transfer Required with old pole set in ground

Pole Transfer Required with old pole set in ground

Place New Guy Marker that is Loose/Damaged/Missing - Guy Marker required on outermost guy on each anchor

Accessible to Public Lines Down

Place New Guy Marker that is Loose/Damaged/Missing - Guy Marker required on outermost guy on each anchor

Secondary Power to Service Drop Between 36 and 48in at Pole

Pole Transfer Required with old pole set in ground

Riser Cover - Loose/Missing/Damaged - Accessible to Public

Pole Transfer Required with old pole set in ground

Pole Transfer Required with old pole set in ground

Replace Deteriorated anchor with Loose Down Guy and exposed anchor rod of Greater than 18in

Broken lashing wire hanging Less Than 3ft above or below strand

Expose Anchor with less than 6in of Anchor Rod above ground

Loose/Missing/Damaged -Inaccessible to Public or Not Immediate Risk

Pole Transfer Required with old pole set in ground

Pole Transfer Required with old pole set in ground

Place New Guy Marker that is Loose/Damaged/Missing - Guy Marker required on outermost guy on each anchor

Place New Guy Marker that is Loose/Damaged/Missing - Guy Marker required on outermost guy on each anchor

Place New Guy Marker that is Loose/Damaged/Missing - Guy Marker required on outermost guy on each anchor

Accessible to Public Lines Down

Pole Transfer Required with old pole set in ground

Loose/Missing/Damaged -Inaccessible to Public or Not Immediate Risk

Pole Transfer Required with old pole set in ground

Pole Transfer Required with old pole set in ground

Riser Cover - Loose/Missing/Damaged - Accessible to Public

Pole Transfer Required with old pole set in ground

Pole Transfer Required with old pole set in ground

Riser Cover - Loose/Missing/Damaged - Accessible to Public

Accessible to Public Lines Down

Riser Cover (U-Guard) - Loose/Missing/Damaged - Accessible to Public

Place New Guy Marker that is Loose/Damaged/Missing - Guy Marker required on outermost guy on each anchor

Place New Guy Marker that is Loose/Damaged/Missing - Guy Marker required on outermost guy on each anchor

Pole Transfer Required with old pole set in ground

Loose/Missing/Damaged -Inaccessible to Public or Not Immediate Risk

Accessible to Public Lines Down

Pole Lean of 10 percent or more of height above ground

Riser Cover - Loose/Missing/Damaged - Accessible to Public

Accessible to Public Lines Down

Riser Cover - Loose/Missing/Damaged - Accessible to Public

Replace Deteriorated anchor with Loose Down Guy and exposed anchor rod of Greater than 18in

Accessible to Public Lines Down

Pole Transfer Required with old pole set in ground

Riser Cover (U-Guard) - Loose/Missing/Damaged - Accessible to Public

Re-Tension Span-Guy or Pole-to-Pole Guy with Pole Lean or Deflection

Pole Transfer Required with old pole set in ground

Place New Guy Marker that is Loose/Damaged/Missing - Guy Marker required on outermost guy on each anchor

Riser Cover - Loose/Missing/Damaged - Accessible to Public

Place New Guy Marker that is Loose/Damaged/Missing - Guy Marker required on outermost guy on each anchor

Accessible to Public Lines Down

Pole Transfer Required with old pole set in ground

Place New Guy Marker that is Loose/Damaged/Missing - Guy Marker required on outermost guy on each anchor

Pole Deterioration, Insect or Bird Damage, or Damage by any other means that requires evaluation for replacement

Pole Transfer Required with old pole set in ground

Broken lashing wire hanging More Than 3ft above or below strand

Loose/Missing/Damaged -Inaccessible to Public or Not Immediate Risk

Pole Transfer Required with old pole set in ground

Accessible to Public Lines Down

Place New Guy Marker that is Loose/Damaged/Missing - Guy Marker required on outermost guy on each anchor

Loose/Missing/Damaged -Inaccessible to Public or Not Immediate Risk

Accessible to Public Lines Down

Loose/Missing/Damaged -Inaccessible to Public or Not Immediate Risk

Pole Transfer Required with old pole set in ground

Pole Transfer Required with old pole set in ground

Accessible to Public Lines Down

Accessible to Public Lines Down

Place New Guy Marker that is Loose/Damaged/Missing - Guy Marker required on outermost guy on each anchor

Broken lashing wire hanging Less Than 3ft above or below strand

Pole Transfer Required with old pole set in ground

Hanging or Cut Drop

Hanging or Cut Drop

Hanging or Cut Drop

Hanging or Cut Drop

Hanging or Cut Drop

Hanging or Cut Drop

Accessible to Public Lines Down

Accessible to Public Lines Down

Accessible to Public Lines Down

Accessible to Public Lines Down

Accessible to Public Lines Down

Loose/Missing/Damaged - Accessible to Public

Place New Guy Marker that is Loose/Damaged/Missing - Guy Marker required on outermost guy on each anchor

Re-Tension Guy

Replace Deteriorated anchor with Loose Down Guy and exposed anchor rod of Greater than 18in

Replace Deteriorated anchor with Loose Down Guy and exposed anchor rod of Greater than 18in

Replace Deteriorated anchor with Loose Down Guy and exposed anchor rod of Greater than 18in

Replace Deteriorated anchor with Loose Down Guy and exposed anchor rod of Greater than 18in

Replace Deteriorated anchor with Loose Down Guy and exposed anchor rod of Greater than 18in

Riser Cover - Loose/Missing/Damaged - Accessible to Public

Riser Cover - Loose/Missing/Damaged - Accessible to Public

Riser Cover - Loose/Missing/Damaged - Accessible to Public

Riser Cover - Loose/Missing/Damaged - Accessible to Public

Riser Cover - Loose/Missing/Damaged - Accessible to Public

Riser Cover - Loose/Missing/Damaged - Accessible to Public

Separation between cable and strand due to broken lashing wire

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Place New Guy Marker that is Loose/Damaged/Missing - Guy Marker required on outermost guy on each anchor

Loose/Missing/Damaged -Inaccessible to Public or Not Immediate Risk

Accessible to Public Lines Down

Replace Deteriorated anchor with Loose Down Guy and exposed anchor rod of Greater than 18in

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Accessible to Public Lines Down

Riser Cover - Loose/Missing/Damaged - Accessible to Public

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Accessible to Public Lines Down

Accessible to Public Lines Down

Loose Down Guy with Pole Lean or Deflection

Accessible to Public Lines Down

Loose/Missing/Damaged -Inaccessible to Public or Not Immediate Risk

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Riser More than 3in from Base of Pole, Needs to Be Moved- Accessible to Public

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Accessible to Public Lines Down

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Accessible to Public Lines Down

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Accessible to Public Lines Down

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Secondary Power to Cable Between 48 and 72in - Pl Guard Arm

Loose/Missing/Damaged -Inaccessible to Public or Not Immediate Risk

Broken lashing wire hanging Less Than 3ft above or below strand

Accessible to Public Lines Down

Accessible to Public Lines Down

Accessible to Public Lines Down

Accessible to Public Lines Down

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Place New Guy Marker that is Loose/Damaged/Missing - Guy Marker required on outermost guy on each anchor

Replace Deteriorated anchor with Loose Down Guy and exposed anchor rod of Greater than 18in

Place New Guy Marker that is Loose/Damaged/Missing - Guy Marker required on outermost guy on each anchor

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Clearance to Ground <8ft accessible to public

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Loose/Missing/Damaged - Accessible to Public

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Loose/Missing/Damaged -Inaccessible to Public or Not Immediate Risk

Loose/Missing/Damaged -Inaccessible to Public or Not Immediate Risk

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
Power Service Wire to Comm Service Drop Less than 12in within 15ft of point of attachment to Customer Structure for either service

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Riser Cover - Loose/Missing/Damaged - Accessible to Public

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Accessible to Public Lines Down

Riser Cover - Loose/Missing/Damaged - Accessible to Public

Hanging or Cut Drop

Accessible to Public Lines Down

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Loose/Missing/Damaged -Inaccessible to Public or Not Immediate Risk

Accessible to Public Lines Down

Accessible to Public Lines Down

Accessible to Public Lines Down

Accessible to Public Lines Down

Replace Deteriorated anchor with Loose Down Guy and exposed anchor rod of Greater than 18in

Accessible to Public Lines Down

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Accessible to Public Lines Down

Place/Replace Down Guy and/or Down Guy Hardware - Insufficient or Loose/Damaged/Missing

Accessible to Public Lines Down

Broken lashing wire hanging Less Than 3ft above or below strand

Hanging or Cut Drop

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Accessible to Public Lines Down

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Loose/Missing/Damaged - Accessible to Public

Clearance to Ground <8ft accessible to public

750V-20KV Primary Power to Cable 4-5ft on pole and at least 3ft at midspan

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Riser Cover - Loose/Missing/Damaged - Accessible to Public

Accessible to Public Lines Down

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Accessible to Public Lines Down

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Hanging or Cut Drop

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Accessible to Public Lines Down

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Clearance to Ground <8ft accessible to public

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Clearance to Ground <8ft accessible to public

Accessible to Public Lines Down

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Broken lashing wire hanging Less Than 3ft above or below strand

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Hanging or Cut Drop

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Riser Cover - Loose/Missing/Damaged - Accessible to Public

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Pole Transfer Required with old pole set in ground

Pole Transfer Required with old pole set in ground

Pole Transfer Required with old pole set in ground

Pole Transfer Required with old pole set in ground

Pole Transfer Required with old pole set in ground

Pole Transfer Required with old pole set in ground

Pole Transfer Required with old pole set in ground

Pole Transfer Required with old pole set in ground

Accessible to Public Lines Down

Pole Transfer Required with old pole set in ground

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Loose/Missing/Damaged - Accessible to Public

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Accessible to Public Lines Down

Riser Cover - Loose/Missing/Damaged - Accessible to Public

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Broken lashing wire hanging Less Than 3ft above or below strand

Accessible to Public Lines Down

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Clearance to Ground Less Than 12ft over Driveway or Private Road

Hanging or Cut Drop

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Place/Replace Down Guy and/or Down Guy Hardware - Insufficient or Loose/Damaged/Missing

Hanging or Cut Drop

Riser Cover - Loose/Missing/Damaged - Accessible to Public

Hanging or Cut Drop

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Accessible to Public Lines Down

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

GO95 Vegetation

GO95 Cable

Hazard Tree - Dead Tree or Portion of Tree that may fall into Cable/Strand

Accessible to Public Lines Down

Accessible to Public Lines Down

Accessible to Public Lines Down

Hanging or Cut Drop

Hanging or Cut Drop

Hanging or Cut Drop

Riser Cover - Loose/Missing/Damaged - Accessible to Public

Riser Cover - Loose/Missing/Damaged - Accessible to Public

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Hanging or Cut Drop

Hanging or Cut Drop

Hanging or Cut Drop

Riser Cover - Loose/Missing/Damaged - Accessible to Public

Accessible to Public Lines Down

Riser Cover - Loose/Missing/Damaged - Accessible to Public

Clearance to Ground <8ft accessible to public

Expose Anchor with less than 6in of Anchor Rod above ground

Riser Cover - Loose/Missing/Damaged - Accessible to Public

Riser More than 3in from Base of Pole, Needs to Be Moved- Accessible to Public

Accessible to Public Lines Down

Place/Replace Down Guy and/or Down Guy Hardware - Insufficient or Loose/Damaged/Missing

Riser Cover - Loose/Missing/Damaged - Accessible to Public

Riser Cover - Loose/Missing/Damaged - Accessible to Public

Hanging or Cut Drop

Riser Cover - Loose/Missing/Damaged - Accessible to Public

Hanging or Cut Drop

Riser Cover - Loose/Missing/Damaged - Accessible to Public

Hanging or Cut Drop

Riser Cover - Loose/Missing/Damaged - Accessible to Public

Riser Cover - Loose/Missing/Damaged - Accessible to Public

Riser More than 3in from Base of Pole, Needs to Be Moved- Accessible to Public

Hanging or Cut Drop

Riser Cover - Loose/Missing/Damaged - Accessible to Public

Riser Cover - Loose/Missing/Damaged - Accessible to Public

Hanging or Cut Drop

Hanging or Cut Drop

Hanging or Cut Drop

Accessible to Public Lines Down

Broken lashing wire hanging More Than 3ft above or below strand

Accessible to Public Lines Down

Accessible to Public Lines Down

Pole Lean of 10 percent or more of height above ground

Riser Cover - Loose/Missing/Damaged - Accessible to Public

Riser Cover - Loose/Missing/Damaged - Accessible to Public

Riser Cover - Loose/Missing/Damaged - Accessible to Public

Vegetation management required to resolve low cable

Loose/Missing/Damaged - Accessible to Public

Accessible to Public Lines Down

Riser Cover - Loose/Missing/Damaged - Accessible to Public

Loose/Missing/Damaged - Accessible to Public

Vegetation management required to resolve low cable

Riser Cover - Loose/Missing/Damaged - Accessible to Public

Loose/Missing/Damaged - Accessible to Public

Riser Cover - Loose/Missing/Damaged - Accessible to Public

Loose/Missing/Damaged - Accessible to Public

Riser Cover - Loose/Missing/Damaged - Accessible to Public

Loose/Missing/Damaged - Accessible to Public

Hanging or Cut Drop

Riser Cover - Loose/Missing/Damaged - Accessible to Public

Riser Cover - Loose/Missing/Damaged - Accessible to Public

Hanging or Cut Drop

Hanging or Cut Drop

Place/Replace Down Guy and/or Down Guy Hardware - Insufficient or Loose/Damaged/Missing

Hanging or Cut Drop

Hanging or Cut Drop

Riser Cover - Loose/Missing/Damaged - Accessible to Public

Riser Cover - Loose/Missing/Damaged - Accessible to Public

Riser Cover - Loose/Missing/Damaged - Accessible to Public

Accessible to Public Lines Down

Riser More than 3in from Base of Pole, Needs to Be Moved- Accessible to Public

Loose/Missing/Damaged - Accessible to Public

Loose/Missing/Damaged - Accessible to Public

Loose/Missing/Damaged - Accessible to Public

Loose/Missing/Damaged - Accessible to Public

Hazard Tree - Dead Tree or Portion of Tree that may fall into Cable/Strand

Riser Cover - Loose/Missing/Damaged - Accessible to Public

Riser Cover - Loose/Missing/Damaged - Accessible to Public

Riser Cover - Loose/Missing/Damaged - Accessible to Public

Clearance to Ground <8ft accessible to public

Accessible to Public Lines Down

Riser Cover - Loose/Missing/Damaged - Accessible to Public

Riser Cover - Loose/Missing/Damaged - Accessible to Public

Riser Cover - Loose/Missing/Damaged - Accessible to Public

Pole Lean of 10 percent or more of height above ground

Accessible to Public Lines Down

Riser Cover - Loose/Missing/Damaged - Accessible to Public

Pole Lean of 10 percent or more of height above ground

Riser Cover - Loose/Missing/Damaged - Accessible to Public

Riser Cover - Loose/Missing/Damaged - Accessible to Public

Riser Cover - Loose/Missing/Damaged - Accessible to Public

Accessible to Public Lines Down

Riser Cover - Loose/Missing/Damaged - Accessible to Public

Broken lashing wire hanging More Than 3ft above or below strand

Clearance to ground between 8 and 12ft parallel to roadway

Clearance to Ground <8ft accessible to public

Riser Cover - Loose/Missing/Damaged - Accessible to Public

Riser Cover - Loose/Missing/Damaged - Accessible to Public

Riser Cover - Loose/Missing/Damaged - Accessible to Public

Accessible to Public Lines Down

Riser Cover - Loose/Missing/Damaged - Accessible to Public

Pole Lean of 10 percent or more of height above ground

Accessible to Public Lines Down

Hanging or Cut Drop

Riser More than 3in from Base of Pole, Needs to Be Moved- Accessible to Public

Accessible to Public Lines Down

Broken lashing wire hanging More Than 3ft above or below strand

Hanging or Cut Drop

Riser Cover - Loose/Missing/Damaged - Accessible to Public

Riser Cover - Loose/Missing/Damaged - Accessible to Public

Riser Cover - Loose/Missing/Damaged - Accessible to Public

Riser Cover - Loose/Missing/Damaged - Accessible to Public

Riser Cover - Loose/Missing/Damaged - Accessible to Public

Riser Cover - Loose/Missing/Damaged - Accessible to Public

Riser Cover - Loose/Missing/Damaged - Accessible to Public

Riser Cover - Loose/Missing/Damaged - Accessible to Public

Riser Cover - Loose/Missing/Damaged - Accessible to Public

Riser Cover - Loose/Missing/Damaged - Accessible to Public

Riser Cover - Loose/Missing/Damaged - Accessible to Public

Riser Cover - Loose/Missing/Damaged - Accessible to Public

Riser Cover - Loose/Missing/Damaged - Accessible to Public

Riser Cover - Loose/Missing/Damaged - Accessible to Public

Riser Cover - Loose/Missing/Damaged - Accessible to Public

Pole Lean of 10 percent or more of height above ground

Accessible to Public Lines Down

Accessible to Public Lines Down

Riser Cover - Loose/Missing/Damaged - Accessible to Public

Re-Tension Span-Guy or Pole-to-Pole Guy with Pole Lean or Deflection

Riser Cover - Loose/Missing/Damaged - Accessible to Public

Riser Cover - Loose/Missing/Damaged - Accessible to Public

Riser Cover - Loose/Missing/Damaged - Accessible to Public

Riser Cover - Loose/Missing/Damaged - Accessible to Public

Vegetation management required to resolve low cable

Clearance to Ground <8ft accessible to public

Riser Cover - Loose/Missing/Damaged - Accessible to Public

Riser Cover - Loose/Missing/Damaged - Accessible to Public

Riser Cover - Loose/Missing/Damaged - Accessible to Public

Clearance to ground between 8 and 12ft parallel to roadway

Riser Cover - Loose/Missing/Damaged - Accessible to Public

Riser Cover - Loose/Missing/Damaged - Accessible to Public

Pole Lean of 10 percent or more of height above ground

Accessible to Public Lines Down

Accessible to Public Lines Down

Riser Cover - Loose/Missing/Damaged - Accessible to Public

Riser Cover - Loose/Missing/Damaged - Accessible to Public

Accessible to Public Lines Down

Loose/Missing/Damaged - Accessible to Public

Riser More than 3in from Base of Pole, Needs to Be Moved- Accessible to Public

Riser Cover - Loose/Missing/Damaged - Accessible to Public

Accessible to Public Lines Down

Clearance to Ground <8ft accessible to public

Riser Cover - Loose/Missing/Damaged - Accessible to Public

Accessible to Public Lines Down

Clearance to Ground <8ft accessible to public

Accessible to Public Lines Down

Hanging or Cut Drop

Hanging or Cut Drop

Riser Cover - Loose/Missing/Damaged - Accessible to Public

Accessible to Public Lines Down

Accessible to Public Lines Down

Hanging or Cut Drop

Place/Replace Down Guy and/or Down Guy Hardware - Insufficient or Loose/Damaged/Missing

Drops - Service Drop (Aerial, Riser, or 6-Pair Terminal) in Climbing Space or Working Space

Riser Cover - Loose/Missing/Damaged - Accessible to Public

Riser Cover - Loose/Missing/Damaged - Accessible to Public

Riser Cover - Loose/Missing/Damaged - Accessible to Public

Riser More than 3in from Base of Pole, Needs to Be Moved- Accessible to Public

Re-Tension Span-Guy or Pole-to-Pole Guy with Pole Lean or Deflection

Place/Replace Down Guy and/or Down Guy Hardware - Insufficient or Loose/Damaged/Missing

Accessible to Public Lines Down

Pole Lean of 10 percent or more of height above ground

Riser Cover - Loose/Missing/Damaged - Accessible to Public

Riser Cover - Loose/Missing/Damaged - Accessible to Public

Accessible to Public Lines Down

Clearance to Ground <8ft accessible to public

Riser Cover - Loose/Missing/Damaged - Accessible to Public

Secondary Power to Cable Between 48 and 72in - Pl Guard Arm

Riser Cover - Loose/Missing/Damaged - Accessible to Public

Accessible to Public Lines Down

Riser Cover - Loose/Missing/Damaged - Accessible to Public

Accessible to Public Lines Down

Place/Replace Down Guy and/or Down Guy Hardware - Insufficient or Loose/Damaged/Missing

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Riser Cover - Loose/Missing/Damaged - Accessible to Public

Riser Cover - Loose/Missing/Damaged - Accessible to Public

Riser Cover - Loose/Missing/Damaged - Accessible to Public

Riser More than 3in from Base of Pole, Needs to Be Moved- Accessible to Public

Riser Cover - Loose/Missing/Damaged - Accessible to Public

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Pole Lean of 10 percent or more of height above ground

Riser Cover - Loose/Missing/Damaged - Accessible to Public

Broken lashing wire hanging More Than 3ft above or below strand

Accessible to Public Lines Down

Riser Cover - Loose/Missing/Damaged - Accessible to Public

Riser Cover - Loose/Missing/Damaged - Accessible to Public

Loose/Missing/Damaged - Accessible to Public

Riser Cover - Loose/Missing/Damaged - Accessible to Public

Hanging or Cut Drop

Riser Cover - Loose/Missing/Damaged - Accessible to Public

Accessible to Public Lines Down

Riser Cover - Loose/Missing/Damaged - Accessible to Public

Hanging or Cut Drop

Loose/Missing/Damaged - Accessible to Public

Riser Cover - Loose/Missing/Damaged - Accessible to Public

Riser Cover - Loose/Missing/Damaged - Accessible to Public

Accessible to Public Lines Down

Accessible to Public Lines Down

Riser Cover - Loose/Missing/Damaged - Accessible to Public

Hanging or Cut Drop

Hanging or Cut Drop

Riser Cover - Loose/Missing/Damaged - Accessible to Public

Hanging or Cut Drop

Riser Cover - Loose/Missing/Damaged - Accessible to Public

Hanging or Cut Drop

Hanging or Cut Drop

Pole Lean of 10 percent or more of height above ground

Accessible to Public Lines Down

Accessible to Public Lines Down

Riser More than 3in from Base of Pole, Needs to Be Moved- Accessible to Public

Riser More than 3in from Base of Pole, Needs to Be Moved- Accessible to Public

Riser Cover - Loose/Missing/Damaged - Accessible to Public

Riser Cover - Loose/Missing/Damaged - Accessible to Public

Hanging or Cut Drop

Place New Guy Marker that is Loose/Damaged/Missing - Guy Marker required on outermost guy on each anchor

Hanging or Cut Drop

Hanging or Cut Drop

Accessible to Public Lines Down

Vegetation management required to resolve low cable

Hanging or Cut Drop

Riser Cover - Loose/Missing/Damaged - Accessible to Public

Riser More than 3in from Base of Pole, Needs to Be Moved- Accessible to Public

Riser More than 3in from Base of Pole, Needs to Be Moved- Accessible to Public

Riser More than 3in from Base of Pole, Needs to Be Moved- Accessible to Public

Riser Cover - Loose/Missing/Damaged - Accessible to Public

Riser More than 3in from Base of Pole, Needs to Be Moved- Accessible to Public

Riser Cover - Loose/Missing/Damaged - Accessible to Public

Riser Cover - Loose/Missing/Damaged - Accessible to Public

Riser Cover - Loose/Missing/Damaged - Accessible to Public

Riser More than 3in from Base of Pole, Needs to Be Moved- Accessible to Public

Accessible to Public Lines Down

Riser More than 3in from Base of Pole, Needs to Be Moved- Accessible to Public

Riser Cover - Loose/Missing/Damaged - Accessible to Public

Riser More than 3in from Base of Pole, Needs to Be Moved- Accessible to Public

Accessible to Public Lines Down

Riser Cover - Loose/Missing/Damaged - Accessible to Public

Riser Cover - Loose/Missing/Damaged - Accessible to Public

Riser Cover - Loose/Missing/Damaged - Accessible to Public

Riser Cover - Loose/Missing/Damaged - Accessible to Public

Riser Cover - Loose/Missing/Damaged - Accessible to Public

Riser Cover - Loose/Missing/Damaged - Accessible to Public

Riser Cover - Loose/Missing/Damaged - Accessible to Public

Riser Cover - Loose/Missing/Damaged - Accessible to Public

Riser Cover - Loose/Missing/Damaged - Accessible to Public

Riser Cover - Loose/Missing/Damaged - Accessible to Public

Accessible to Public Lines Down

Riser Cover - Loose/Missing/Damaged - Accessible to Public

Riser Cover - Loose/Missing/Damaged - Accessible to Public

Pole Lean of 10 percent or more of height above ground

Clearance to Ground <8ft accessible to public

Riser Cover - Loose/Missing/Damaged - Accessible to Public

Accessible to Public Lines Down

Riser More than 3in from Base of Pole, Needs to Be Moved- Accessible to Public

Riser Cover - Loose/Missing/Damaged - Accessible to Public

Riser More than 3in from Base of Pole, Needs to Be Moved- Accessible to Public

Accessible to Public Lines Down

Accessible to Public Lines Down

Riser Cover - Loose/Missing/Damaged - Accessible to Public

Re-Tension Guy

Accessible to Public Lines Down

Riser Cover - Loose/Missing/Damaged - Accessible to Public

Riser Cover - Loose/Missing/Damaged - Accessible to Public

Riser Cover - Loose/Missing/Damaged - Accessible to Public

Riser Cover - Loose/Missing/Damaged - Accessible to Public

Place/Replace Down Guy and/or Down Guy Hardware - Insufficient or Loose/Damaged/Missing

Riser Cover - Loose/Missing/Damaged - Accessible to Public

Accessible to Public Lines Down

Riser Cover - Loose/Missing/Damaged - Accessible to Public

Riser Cover - Loose/Missing/Damaged - Accessible to Public

Pole Lean of 10 percent or more of height above ground

Accessible to Public Lines Down

Accessible to Public Lines Down

Clearance to Ground <8ft accessible to public

Accessible to Public Lines Down

Clearance to Ground <8ft accessible to public

Accessible to Public Lines Down

Place New Guy Marker that is Loose/Damaged/Missing - Guy Marker required on outermost guy on each anchor

Pole Lean of 10 percent or more of height above ground

Pole Lean of 10 percent or more of height above ground

Accessible to Public Lines Down

Accessible to Public Lines Down

Expose Anchor with less than 6in of Anchor Rod above ground

Loose/Missing/Damaged -Inaccessible to Public or Not Immediate Risk

Loose/Missing/Damaged -Inaccessible to Public or Not Immediate Risk

Hanging or Cut Drop

Riser Cover (U-Guard) - Loose/Missing/Damaged - Accessible to Public

Loose/Missing/Damaged -Inaccessible to Public or Not Immediate Risk

Place New Guy Marker that is Loose/Damaged/Missing - Guy Marker required on outermost guy on each anchor

Accessible to Public Lines Down

Riser Cover - Loose/Missing/Damaged - Accessible to Public

Accessible to Public Lines Down

Accessible to Public Lines Down

Riser Cover - Loose/Missing/Damaged - Accessible to Public

Riser Cover - Loose/Missing/Damaged - Accessible to Public

Hanging or Cut Drop

Hanging or Cut Drop

Clearance to Ground <8ft accessible to public

Hanging or Cut Drop

Broken lashing wire hanging More Than 3ft above or below strand

Riser Cover - Loose/Missing/Damaged - Accessible to Public

Loose/Missing/Damaged - Accessible to Public

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Accessible to Public Lines Down

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Accessible to Public Lines Down

Hanging or Cut Drop

Hanging or Cut Drop

Hanging or Cut Drop

Broken lashing wire hanging More Than 3ft above or below strand

Hazard Tree - Dead Tree or Portion of Tree that may fall into Cable/Strand

Hanging or Cut Drop

Hanging or Cut Drop

Hanging or Cut Drop

Riser Cover - Loose/Missing/Damaged - Accessible to Public

Hanging or Cut Drop

Hanging or Cut Drop

Accessible to Public Lines Down

Riser Cover - Loose/Missing/Damaged - Accessible to Public

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Hazard Tree - Dead Tree or Portion of Tree that may fall into Cable/Strand

Hazard Tree - Dead Tree or Portion of Tree that may fall into Cable/Strand

Hazard Tree - Dead Tree or Portion of Tree that may fall into Cable/Strand

Accessible to Public Lines Down

Accessible to Public Lines Down

Accessible to Public Lines Down

Riser Cover - Loose/Missing/Damaged - Accessible to Public

Hanging or Cut Drop

Loose/Missing/Damaged - Accessible to Public

Loose/Missing/Damaged - Accessible to Public

Loose/Missing/Damaged - Accessible to Public

Riser Cover - Loose/Missing/Damaged - Accessible to Public

Loose/Missing/Damaged - Accessible to Public

Clearance to Ground <8ft accessible to public

Riser Cover - Loose/Missing/Damaged - Accessible to Public

Accessible to Public Lines Down

Accessible to Public Lines Down

Clearance to Ground <8ft accessible to public

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Hanging or Cut Drop

Hanging or Cut Drop

Hazard Tree - Dead Tree or Portion of Tree that may fall into Cable/Strand

Hanging or Cut Drop

Hanging or Cut Drop

Accessible to Public Lines Down

Accessible to Public Lines Down

Accessible to Public Lines Down

Hazard Tree - Dead Tree or Portion of Tree that may fall into Cable/Strand

Accessible to Public Lines Down

Accessible to Public Lines Down

Hanging or Cut Drop

Hanging or Cut Drop

Hanging or Cut Drop

Hanging or Cut Drop

Hanging or Cut Drop

Hanging or Cut Drop

Hanging or Cut Drop

Hanging or Cut Drop

Accessible to Public Lines Down

Accessible to Public Lines Down

Accessible to Public Lines Down

Accessible to Public Lines Down

Hanging or Cut Drop

Hanging or Cut Drop

Hanging or Cut Drop

Hanging or Cut Drop

Hanging or Cut Drop

Clearance to Ground <8ft accessible to public

Hanging or Cut Drop

Hanging or Cut Drop

Hanging or Cut Drop

Hanging or Cut Drop

Hanging or Cut Drop

Hanging or Cut Drop

Hanging or Cut Drop

Hanging or Cut Drop

Hanging or Cut Drop

Hanging or Cut Drop

Hanging or Cut Drop

Broken lashing wire hanging More Than 3ft above or below strand

Place New Guy Marker that is Loose/Damaged/Missing - Guy Marker required on outermost guy on each anchor

Hanging or Cut Drop

Clearance to Ground <8ft accessible to public

Hanging or Cut Drop

Hanging or Cut Drop

Accessible to Public Lines Down

Accessible to Public Lines Down

Clearance to Ground <8ft accessible to public

Pole Lean of 10 percent or more of height above ground

Hanging or Cut Drop

Vegetation management required to resolve low cable

Hanging or Cut Drop

Hanging or Cut Drop

Hanging or Cut Drop

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Riser Cover - Loose/Missing/Damaged - Accessible to Public

Riser Cover - Loose/Missing/Damaged - Accessible to Public

Riser Cover - Loose/Missing/Damaged - Accessible to Public

Accessible to Public Lines Down

Clearance to Ground <8ft accessible to public

Clearance to Ground <8ft accessible to public

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Clearance to Ground <8ft accessible to public

Hanging or Cut Drop

Hanging or Cut Drop

Accessible to Public Lines Down

Hanging or Cut Drop

Loose/Missing/Damaged - Accessible to Public

Riser Cover - Loose/Missing/Damaged - Accessible to Public

Loose/Missing/Damaged - Accessible to Public

Loose/Missing/Damaged - Accessible to Public

Riser Cover - Loose/Missing/Damaged - Accessible to Public

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Accessible to Public Lines Down

Loose/Missing/Damaged - Accessible to Public

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Clearance to Ground Between 12 and 15ft over roadway

Accessible to Public Lines Down

Hanging or Cut Drop

Hanging or Cut Drop

Hanging or Cut Drop

Accessible to Public Lines Down

Hanging or Cut Drop

Hanging or Cut Drop

Hanging or Cut Drop

Riser Cover - Loose/Missing/Damaged - Accessible to Public

Loose/Missing/Damaged - Accessible to Public

Accessible to Public Lines Down

Accessible to Public Lines Down

Accessible to Public Lines Down

Accessible to Public Lines Down

Accessible to Public Lines Down

Place/Replace Down Guy and/or Down Guy Hardware - Insufficient or Loose/Damaged/Missing

Hanging or Cut Drop

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Hanging or Cut Drop

Accessible to Public Lines Down

Riser Cover - Loose/Missing/Damaged - Accessible to Public

Clearance to Ground <8ft accessible to public

Missing Down Guy with Pole Lean or Deflection

Clearance to Ground Less Than 12ft over Driveway or Private Road

Hanging or Cut Drop

Hanging or Cut Drop

Hanging or Cut Drop

Hanging or Cut Drop

Hanging or Cut Drop

Hanging or Cut Drop

Hanging or Cut Drop

Hanging or Cut Drop

Hanging or Cut Drop

Hanging or Cut Drop

Hanging or Cut Drop

Loose/Missing/Damaged - Accessible to Public

Clearance to Ground <8ft accessible to public

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Loose/Missing/Damaged - Accessible to Public

Hanging or Cut Drop

Hanging or Cut Drop

Hanging or Cut Drop

Hanging or Cut Drop

Hanging or Cut Drop

Hanging or Cut Drop

Hanging or Cut Drop

Hanging or Cut Drop

Clearance to Ground <8ft accessible to public

Clearance to Ground <8ft accessible to public

Loose/Missing/Damaged - Accessible to Public

Hanging or Cut Drop

Hazard Tree - Dead Tree or Portion of Tree that may fall into Cable/Strand

Accessible to Public Lines Down

Accessible to Public Lines Down

Accessible to Public Lines Down

Hazard Tree - Dead Tree or Portion of Tree that may fall into Cable/Strand

Hazard Tree - Dead Tree or Portion of Tree that may fall into Cable/Strand

Hanging or Cut Drop

Hanging or Cut Drop

Hanging or Cut Drop

Broken lashing wire hanging Less Than 3ft above or below strand

Hanging or Cut Drop

Hanging or Cut Drop

Hanging or Cut Drop

Hazard Tree - Dead Tree or Portion of Tree that may fall into Cable/Strand

Secondary Power to Service Drop Between 36 and 48in at Pole

Hanging or Cut Drop

Hanging or Cut Drop

Clearance to Ground <8ft accessible to public

Clearance to Ground <8ft accessible to public

Broken lashing wire hanging More Than 3ft above or below strand

Hanging or Cut Drop

Broken lashing wire hanging More Than 3ft above or below strand

Hanging or Cut Drop

Hanging or Cut Drop

Accessible to Public Lines Down

Riser Cover - Loose/Missing/Damaged - Accessible to Public

Loose/Missing/Damaged - Accessible to Public

Hanging or Cut Drop

Accessible to Public Lines Down

Clearance to Ground <8ft accessible to public

Hanging or Cut Drop

Hanging or Cut Drop

Hanging or Cut Drop

Hanging or Cut Drop

Hanging or Cut Drop

Hanging or Cut Drop

Vegetation management required to resolve low cable

Vegetation management required to resolve low cable

Hanging or Cut Drop

Hanging or Cut Drop

Broken lashing wire hanging More Than 3ft above or below strand

Hanging or Cut Drop

Hanging or Cut Drop

Accessible to Public Lines Down

Accessible to Public Lines Down

Accessible to Public Lines Down

Accessible to Public Lines Down

Accessible to Public Lines Down

Accessible to Public Lines Down

Hanging or Cut Drop

Hanging or Cut Drop

Hanging or Cut Drop

Clearance to Ground <8ft accessible to public

Clearance to Ground <8ft accessible to public

Vegetation management required to resolve low cable

Clearance to Ground <8ft accessible to public

Hanging or Cut Drop

Hanging or Cut Drop

Hanging or Cut Drop

Hanging or Cut Drop

Hanging or Cut Drop

Hanging or Cut Drop

Accessible to Public Lines Down

Accessible to Public Lines Down

Accessible to Public Lines Down

Hazard Tree - Dead Tree or Portion of Tree that may fall into Cable/Strand

Secondary Power to Cable Less Than 24in

Accessible to Public Lines Down

Expose Anchor with less than 6in of Anchor Rod above ground

Hazardous Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Accessible to Public Lines Down

Riser Cover - Loose/Missing/Damaged - Accessible to Public

Riser Cover - Loose/Missing/Damaged - Accessible to Public

Riser Cover - Loose/Missing/Damaged - Accessible to Public

Hanging or Cut Drop

Hanging or Cut Drop

Loose/Missing/Damaged - Accessible to Public

Hanging or Cut Drop

Riser Cover - Loose/Missing/Damaged - Accessible to Public

Hanging or Cut Drop

Accessible to Public Lines Down

Clearance to Ground <8ft accessible to public

Hanging or Cut Drop

Riser Cover - Loose/Missing/Damaged - Accessible to Public

Riser Cover - Loose/Missing/Damaged - Accessible to Public

Place/Replace Down Guy and/or Down Guy Hardware - Insufficient or Loose/Damaged/Missing

Loose/Missing/Damaged - Accessible to Public

Loose/Missing/Damaged - Accessible to Public

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Loose/Missing/Damaged - Accessible to Public

Loose/Missing/Damaged - Accessible to Public

Loose/Missing/Damaged - Accessible to Public

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Hanging or Cut Drop

Accessible to Public Lines Down

Accessible to Public Lines Down

750V-20KV Primary Power to Cable 4-5ft on pole and at least 3ft at midspan

Riser Cover - Loose/Missing/Damaged - Accessible to Public

Broken lashing wire hanging More Than 3ft above or below strand

Broken lashing wire hanging More Than 3ft above or below strand

Accessible to Public Lines Down

Accessible to Public Lines Down

Accessible to Public Lines Down

Accessible to Public Lines Down

Accessible to Public Lines Down

Riser Cover - Loose/Missing/Damaged - Accessible to Public

Replace Deteriorated anchor with Loose Down Guy and exposed anchor rod of Greater than 18in

Hanging or Cut Drop

Hanging or Cut Drop

Riser Cover - Loose/Missing/Damaged - Accessible to Public

Riser Cover (U-Guard) - Loose/Missing/Damaged - Accessible to Public

Place New Guy Marker that is Loose/Damaged/Missing - Guy Marker required on outermost guy on each anchor

Expose Anchor with less than 6in of Anchor Rod above ground

Riser Cover - Loose/Missing/Damaged - Accessible to Public

Riser Cover - Loose/Missing/Damaged - Accessible to Public

Riser Cover (U-Guard) - Loose/Missing/Damaged - Accessible to Public

Accessible to Public Lines Down

Remove Step below 8ft Above Ground

Place New Guy Marker that is Loose/Damaged/Missing - Guy Marker required on outermost guy on each anchor

Place New Guy Marker that is Loose/Damaged/Missing - Guy Marker required on outermost guy on each anchor

Expose Anchor with less than 6in of Anchor Rod above ground

Riser Cover - Loose/Missing/Damaged - Accessible to Public

Accessible to Public Lines Down

Riser Cover - Loose/Missing/Damaged - Accessible to Public

Broken lashing wire hanging Less Than 3ft above or below strand

Accessible to Public Lines Down

Accessible to Public Lines Down

Loose/Missing/Damaged - Accessible to Public

Accessible to Public Lines Down

Riser Cover - Loose/Missing/Damaged - Accessible to Public

Loose/Missing/Damaged - Accessible to Public

Communications Facilities between 4 and 6ft from Secondary Power

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Hanging or Cut Drop

Accessible to Public Lines Down

Communications Facilities between 4 and 6ft from Secondary Power

Hanging or Cut Drop

Hanging or Cut Drop

Hanging or Cut Drop

Hanging or Cut Drop

Accessible to Public Lines Down

Accessible to Public Lines Down

Accessible to Public Lines Down

Riser Cover - Loose/Missing/Damaged - Accessible to Public

Clearance to ground between 8 and 12ft parallel to roadway

Re-Tension Span-Guy or Pole-to-Pole Guy with Pole Lean or Deflection

Accessible to Public Lines Down

Accessible to Public Lines Down

Riser Cover - Loose/Missing/Damaged - Accessible to Public

Riser Cover - Loose/Missing/Damaged - Accessible to Public

Accessible to Public Lines Down

Riser Cover - Loose/Missing/Damaged - Accessible to Public

Riser Cover - Loose/Missing/Damaged - Accessible to Public

Riser Cover - Loose/Missing/Damaged - Accessible to Public

Riser Cover - Loose/Missing/Damaged - Accessible to Public

Accessible to Public Lines Down

Accessible to Public Lines Down

Riser Cover - Loose/Missing/Damaged - Accessible to Public

Riser Cover - Loose/Missing/Damaged - Accessible to Public

Remove Step below 8ft Above Ground

Riser Cover - Loose/Missing/Damaged - Accessible to Public

Accessible to Public Lines Down

Separation between cable and strand due to broken lashing wire

Riser Cover - Loose/Missing/Damaged - Accessible to Public

Accessible to Public Lines Down

Accessible to Public Lines Down

Riser Cover - Loose/Missing/Damaged - Accessible to Public

Accessible to Public Lines Down

Communications Facilities between 4 and 6ft from Secondary Power

Accessible to Public Lines Down

Accessible to Public Lines Down

Secondary Power to Cable Less Than 24in

Place New Guy Marker that is Loose/Damaged/Missing - Guy Marker required on outermost guy on each anchor

Riser Cover - Loose/Missing/Damaged - Accessible to Public

Accessible to Public Lines Down

Accessible to Public Lines Down

Expose Anchor with less than 6in of Anchor Rod above ground

Place New Guy Marker that is Loose/Damaged/Missing - Guy Marker required on outermost guy on each anchor

Replace Deteriorated anchor with Loose Down Guy and exposed anchor rod of Greater than 18in

Riser Cover (U-Guard) - Loose/Missing/Damaged - Accessible to Public

Accessible to Public Lines Down

Accessible to Public Lines Down

Accessible to Public Lines Down

Accessible to Public Lines Down

Riser Cover - Loose/Missing/Damaged - Accessible to Public

Hanging or Cut Drop

Riser Cover - Loose/Missing/Damaged - Accessible to Public

Riser Cover - Loose/Missing/Damaged - Accessible to Public

Broken lashing wire hanging More Than 3ft above or below strand

Loose/Missing/Damaged - Accessible to Public

Riser Cover - Loose/Missing/Damaged - Accessible to Public

Riser Cover - Loose/Missing/Damaged - Accessible to Public

Riser Cover - Loose/Missing/Damaged - Accessible to Public

Place New Guy Marker that is Loose/Damaged/Missing - Guy Marker required on outermost guy on each anchor

Expose Anchor with less than 6in of Anchor Rod above ground

Riser Cover - Loose/Missing/Damaged - Accessible to Public

Riser Cover - Loose/Missing/Damaged - Accessible to Public

Hanging or Cut Drop

Riser Cover - Loose/Missing/Damaged - Accessible to Public

Pole Transfer Required with old pole set in ground

Pole Transfer Required with old pole set in ground

Riser Cover - Loose/Missing/Damaged - Accessible to Public

Riser Cover - Loose/Missing/Damaged - Accessible to Public

Communications Facilities between 4 and 6ft from Secondary Power

Hanging or Cut Drop

Clearance to Ground <8ft accessible to public

Accessible to Public Lines Down

Place/Replace Down Guy and/or Down Guy Hardware - Insufficient or Loose/Damaged/Missing

Clearance to Ground Less Than 12ft over Driveway or Private Road

Place New Guy Marker that is Loose/Damaged/Missing - Guy Marker required on outermost guy on each anchor

Pole Transfer Required with old pole set in ground

Accessible to Public Lines Down

Clearance between Communications Attachments on Pole Less Than 12in

Accessible to Public Lines Down

Replace Deteriorated anchor with Loose Down Guy and exposed anchor rod of Greater than 18in

Expose Anchor with less than 6in of Anchor Rod above ground

Accessible to Public Lines Down

Pole Transfer Required with old pole set in ground

Pole Transfer Required with old pole set in ground

Accessible to Public Lines Down

Expose Anchor with less than 6in of Anchor Rod above ground

Riser Cover - Loose/Missing/Damaged - Accessible to Public

Riser Cover - Loose/Missing/Damaged - Accessible to Public

Riser Cover - Loose/Missing/Damaged - Accessible to Public

Riser Cover - Loose/Missing/Damaged - Accessible to Public

Place New Guy Marker that is Loose/Damaged/Missing - Guy Marker required on outermost guy on each anchor

Pole Transfer Required with old pole set in ground

Clearance to Ground <8ft accessible to public

Riser Cover (U-Guard) - Loose/Missing/Damaged - Accessible to Public

Accessible to Public Lines Down

Equipment in public area at less than 8ft above ground level

Accessible to Public Lines Down

Accessible to Public Lines Down

Hanging or Cut Drop

Riser Cover - Loose/Missing/Damaged - Accessible to Public

Accessible to Public Lines Down

Riser Cover - Loose/Missing/Damaged - Accessible to Public

Riser Cover - Loose/Missing/Damaged - Accessible to Public

Riser Cover - Loose/Missing/Damaged - Accessible to Public

Riser Cover - Loose/Missing/Damaged - Accessible to Public

Pole Transfer Required with old pole set in ground

Pole Transfer Required with old pole set in ground

Pole Transfer Required with old pole set in ground

Hanging or Cut Drop

Accessible to Public Lines Down

Riser Cover (U-Guard) - Loose/Missing/Damaged - Accessible to Public

Hanging or Cut Drop

Pole Transfer Required with old pole set in ground

Riser Cover (U-Guard) - Loose/Missing/Damaged - Inaccessible to Public

Hanging or Cut Drop

Accessible to Public Lines Down

Secondary Power to Cable Between 48 and 72in - Pl Guard Arm

Remove Step below 8ft Above Ground

Riser Cover - Loose/Missing/Damaged - Accessible to Public

Pole Lean of 10 percent or more of height above ground

Place New Guy Marker that is Loose/Damaged/Missing - Guy Marker required on outermost guy on each anchor

Pole Transfer Required with old pole set in ground

Accessible to Public Lines Down

Accessible to Public Lines Down

Broken lashing wire hanging Less Than 3ft above or below strand

Hanging or Cut Drop

Riser Cover (U-Guard) - Loose/Missing/Damaged - Accessible to Public

Riser Cover - Loose/Missing/Damaged - Accessible to Public

Loose/Missing/Damaged - Accessible to Public

Broken lashing wire hanging Less Than 3ft above or below strand

Hanging or Cut Drop

Hanging or Cut Drop

Broken lashing wire hanging Less Than 3ft above or below strand

Loose/Missing/Damaged - Accessible to Public

Broken lashing wire hanging Less Than 3ft above or below strand

Accessible to Public Lines Down

Riser Cover (U-Guard) - Loose/Missing/Damaged - Accessible to Public

Replace Deteriorated anchor with Loose Down Guy and exposed anchor rod of Greater than 18in

Pole Deterioration, Insect or Bird Damage, or Damage by any other means that requires evaluation for replacement

Hazard Tree - Dead Tree or Portion of Tree that may fall into Cable/Strand

Hanging or Cut Drop

Hanging or Cut Drop

Hanging or Cut Drop

Hanging or Cut Drop

Hanging or Cut Drop

Hanging or Cut Drop

Hanging or Cut Drop

Hanging or Cut Drop

Hanging or Cut Drop

Hanging or Cut Drop

Hanging or Cut Drop

Hanging or Cut Drop

Hanging or Cut Drop

Hanging or Cut Drop

Hanging or Cut Drop

Hanging or Cut Drop

Hanging or Cut Drop

Hanging or Cut Drop

Hanging or Cut Drop

Hanging or Cut Drop

Hanging or Cut Drop

Hanging or Cut Drop

Hanging or Cut Drop

Hanging or Cut Drop

Hanging or Cut Drop

Hanging or Cut Drop

Hanging or Cut Drop

Hanging or Cut Drop

Hanging or Cut Drop

Hanging or Cut Drop

Hanging or Cut Drop

Hanging or Cut Drop

Accessible to Public Lines Down

Accessible to Public Lines Down

Accessible to Public Lines Down

Accessible to Public Lines Down

Accessible to Public Lines Down

Accessible to Public Lines Down

Accessible to Public Lines Down

Accessible to Public Lines Down

Accessible to Public Lines Down

Accessible to Public Lines Down

Accessible to Public Lines Down

Accessible to Public Lines Down

Broken lashing wire hanging Less Than 3ft above or below strand

Broken lashing wire hanging Less Than 3ft above or below strand

Broken lashing wire hanging More Than 3ft above or below strand

Place/Replace Down Guy and/or Down Guy Hardware - Insufficient or Loose/Damaged/Missing

Pole Lean of 10 percent or more of height above ground

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Pole Transfer Required with old pole set in ground

Pole Transfer Required with old pole set in ground

Pole Transfer Required with old pole set in ground

Pole Transfer Required with old pole set in ground

Pole Transfer Required with old pole set in ground

Pole Transfer Required with old pole set in ground

Pole Transfer Required with old pole set in ground

Pole Transfer Required with old pole set in ground

Pole Transfer Required with old pole set in ground

Pole Transfer Required with old pole set in ground

Pole Transfer Required with old pole set in ground

Pole Transfer Required with old pole set in ground

Pole Transfer Required with old pole set in ground

Hanging or Cut Drop

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Hanging or Cut Drop

Vegetation management required to resolve low cable

Hanging or Cut Drop

Hanging or Cut Drop

Hanging or Cut Drop

Hanging or Cut Drop

Hanging or Cut Drop

Hanging or Cut Drop

Hanging or Cut Drop

Hanging or Cut Drop

Hanging or Cut Drop

Hanging or Cut Drop

Hanging or Cut Drop

Hanging or Cut Drop

Hanging or Cut Drop

Hanging or Cut Drop

Hanging or Cut Drop

Hanging or Cut Drop

Hanging or Cut Drop

Hanging or Cut Drop

Hanging or Cut Drop

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Hanging or Cut Drop

Broken lashing wire hanging Less Than 3ft above or below strand

Hanging or Cut Drop

Hanging or Cut Drop

Hanging or Cut Drop

Hanging or Cut Drop

Hanging or Cut Drop

Hanging or Cut Drop

Hanging or Cut Drop

Hanging or Cut Drop

Hanging or Cut Drop

Hanging or Cut Drop

Hanging or Cut Drop

Hanging or Cut Drop

Hanging or Cut Drop

Hanging or Cut Drop

Hanging or Cut Drop

Hanging or Cut Drop

Hanging or Cut Drop

Hanging or Cut Drop

Place New Guy Marker that is Loose/Damaged/Missing - Guy Marker required on outermost guy on each anchor

Hanging or Cut Drop

Place New Guy Marker that is Loose/Damaged/Missing - Guy Marker required on outermost guy on each anchor

Hanging or Cut Drop

Hanging or Cut Drop

Hanging or Cut Drop

Hanging or Cut Drop

Hanging or Cut Drop

Hanging or Cut Drop

Hanging or Cut Drop

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Hanging or Cut Drop

Hanging or Cut Drop

Hanging or Cut Drop

Hanging or Cut Drop

Hanging or Cut Drop

Hanging or Cut Drop

Hanging or Cut Drop

Hanging or Cut Drop

Hanging or Cut Drop

Hanging or Cut Drop

Hanging or Cut Drop

Hanging or Cut Drop

Broken lashing wire hanging More Than 3ft above or below strand

Hanging or Cut Drop

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Hanging or Cut Drop

Hanging or Cut Drop

Hanging or Cut Drop

Accessible to Public Lines Down

Hanging or Cut Drop

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Hanging or Cut Drop

Hanging or Cut Drop

Hanging or Cut Drop

Hanging or Cut Drop

Hanging or Cut Drop

Hanging or Cut Drop

Hanging or Cut Drop

Hanging or Cut Drop

Hanging or Cut Drop

Broken lashing wire hanging More Than 3ft above or below strand

Place New Guy Marker that is Loose/Damaged/Missing - Guy Marker required on outermost guy on each anchor

Clearance to Ground Less Than 12ft over roadway

Hanging or Cut Drop

Hanging or Cut Drop

Hanging or Cut Drop

Hanging or Cut Drop

Hanging or Cut Drop

Hanging or Cut Drop

Hanging or Cut Drop

Hanging or Cut Drop

Hanging or Cut Drop

Hanging or Cut Drop

Hanging or Cut Drop

Hanging or Cut Drop

Hanging or Cut Drop

Hanging or Cut Drop

Hanging or Cut Drop

Hanging or Cut Drop

Hanging or Cut Drop

Hanging or Cut Drop

Hanging or Cut Drop

Hanging or Cut Drop

Hanging or Cut Drop

Hanging or Cut Drop

Hanging or Cut Drop

Hanging or Cut Drop

Hanging or Cut Drop

Hanging or Cut Drop

Hanging or Cut Drop

Hanging or Cut Drop

Hanging or Cut Drop

Hanging or Cut Drop

Hanging or Cut Drop

Hanging or Cut Drop

Clearance to ground between 8 and 12ft parallel to roadway

Hanging or Cut Drop

Separation between cable and strand due to broken lashing wire

Accessible to Public Lines Down

Accessible to Public Lines Down

Hazardous - Clearance to Ground <12ft over roadway

Separation between cable and strand due to broken lashing wire

Accessible to Public

Hazardous Pole with Immediate Risk due to Deterioration, Insect or Bird Damage, or Damage by any other means

Crossing or Parallel to Public Roadway

GO95 Cable

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Accessible to Public

Crossing or Parallel to Public Roadway

Broken lashing wire likely to Contact High Voltage (Primary/Transmission) Conductor

Clearance to Ground Between 12 and 18ft over roadway or 16ft at the curb

Hazard Tree - Dead Tree or Portion of Tree that may fall into Cable/Strand

Hazardous Pole with Immediate Risk due to Deterioration, Insect or Bird Damage, or Damage by any other means

DESCRIPTION

MARKIT Vegetation Removal Required - 10585 Pine Lake Dr

MARKIT Straighten In-Line Pole - 4080 Ladera Way

MARKIT Raise AT&T Mainline Cable - 9294 Banderilla Dr

MARKIT Relash Existing Cables - 13574 Hoyito Circle

MARKIT Raise AT&T Mainline Cable - 10390 Lirio Ct

MARKIT Raise AT&T Mainline Cable - 9651 Banderilla Dr

MARKIT Raise AT&T Mainline Cable - 9751 Alamo Dr

MARKIT Raise AT&T Mainline Cable - 13605 Molina St

MARKIT Raise AT&T Mainline Cable - 9828 Torito Way

MARKIT Raise AT&T Mainline Cable - 14531 Avenida Central

MARKIT Intrusive Inspection Required - 13910 Hatch Creek Ln

MARKIT Intrusive Inspection Required - 3805 Castillo Way

MARKIT Intrusive Inspection Required - 3328 Chicharra Way

MARKIT Intrusive Inspection Required - 10410 Violeta Way

MARKIT Intrusive Inspection Required - 9876 Villareal Dr

MARKIT Intrusive Inspection Required - 2438 El Naranjo St

MARKIT Intrusive Inspection Required - 14346 Potrero Way

MARKIT Intrusive Inspection Required - 3271 Granite Springs Rd

MARKIT Intrusive Inspection Required - 3473 Merced Falls Rd

MARKIT Intrusive Inspection Required - 9766 Villareal Dr

MARKIT Intrusive Inspection Required - 9107 Capullo Circle

MARKIT Intrusive Inspection Required - 10438 Violeta Way

MARKIT Intrusive Inspection Required - 9897 Villareal Dr

MARKIT Intrusive Inspection Required - 10118 Banderilla Dr

MARKIT Intrusive Inspection Required - 9757 Caracol Circle

MARKIT Intrusive Inspection Required - 4080 Ladera Way

MARKIT Intrusive Inspection Required - 9757 Mirasol Way

MARKIT Intrusive Inspection Required - 9699 Paraje Way

MARKIT Intrusive Inspection Required - 2045 Navarro St

MARKIT Intrusive Inspection Required - 2353 Hidalgo St

MARKIT Raise AT&T Service Drop - Oak Rd

MARKIT Tree Trimming Required - 9721 Barium Mine Rd
MARKIT Remove AnchorReplace/Install Down GuyTransfer AT&T Cable(s)Transfer AT&T Drop(s);Pull Old Pole;Lead Tails No;Cable Swing No;Trasfer 3 - 3185 Chicharra Way

MARKIT Place/Replace Down Guy Guard - 3210 CA-132

MARKIT Vegetation Removal Required - 3210 CA-132

MARKIT Place/Replace Down Guy Guard - 14445 Buena Vista Ct

MARKIT Vegetation Removal Required - 3218 CA-132

MARKIT Vegetation Removal Required - 18835 Powder House St

MARKIT Vegetation Removal Required - 11833 Powder House St

MARKIT Vegetation Removal Required - 18453 Main St

MARKIT Place/Replace Down Guy Guard - 13888 Cedro Ct

MARKIT Vegetation Removal Required - 10363 Gusanillo Way

MARKIT Place/Replace Down Guy Guard - 10363 Gusanillo Way

MARKIT Relash Existing Cables - 10430 Blanchard Rd

MARKIT Raise AT&T Mainline Cable - 12994 Bonds Flat Rd
MARKIT Remove AnchorReplace/Install Down GuyTransfer AT&T Cable(s)Transfer AT&T Drop(s);Pull Old Pole;Lead Tails No;Cable Swing Yes;Trasfer 3 - 3328 Chicharra Way

MARKIT Vegetation Removal Required - 10410 Violeta Way

MARKIT Raise AT&T Mainline Cable - 2398 CA-132

MARKIT Vegetation Removal Required - 3101 Granite Springs Rd

MARKIT Repair/Replace Hardware - 3101 Granite Springs Rd

MARKIT Place/Replace Down Guy Guard - 3709 Castillo Way

MARKIT Repair/Replace Hardware - 5754 Lozano Way

MARKIT Place/Replace Down Guy Guard - 5954 Frio Ct

MARKIT Raise AT&T Mainline Cable - 15088 Parra Ct

MARKIT Place/Replace Down Guy Guard - 15088 Parra Ct

MARKIT Place/Replace Down Guy Guard - 9232 Jalisco Way

MARKIT Place/Replace Down Guy Guard - 9653 Hernandez Dr

MARKIT Place/Replace Down Guy Guard - 13685 Cano Ct

MARKIT Repair/Replace Hardware - 13605 Molina St
MARKIT Remove AnchorReplace/Install Down GuyTransfer AT&T Cable(s);Pull Old Pole;Lead Tails No;Cable Swing Yes;Trasfer 2 - 10426 Violeta Way

MARKIT Place/Replace Down Guy Guard - 9596 Banderilla Dr
MARKIT Remove AnchorReplace/Install Down GuyTransfer AT&T Cable(s)Transfer AT&T Drop(s);Pull Old Pole;Lead Tails No;Cable Swing Yes;Trasfer 3 - 9393 Merced Falls Rd

MARKIT Place/Replace Down Guy Guard - 2841 Ranchito Dr

MARKIT Place/Replace Down Guy Guard - 2865 Zarzamora St

MARKIT Place/Replace Down Guy Guard - 13808 Cadena Way

MARKIT Repair/Replace Hardware - 10450 Violeta Way

MARKIT Place/Replace Down Guy Guard - 10478 Lozano Way

MARKIT Relash Existing Cables - 10347 Narcisco Way

MARKIT Vegetation Removal Required - 10347 Narcisco Way

MARKIT Vegetation Removal Required - 9536 Banderilla Dr

MARKIT Vegetation Removal Required - 5520 Llanura Dr

MARKIT Vegetation Removal Required - 10345 Josefina Way

MARKIT Repair/Replace Hardware - 3686 Arbolada Dr

MARKIT Vegetation Removal Required - 2779 Merced Falls Rd

MARKIT Repair/Replace Hardware - 2011 Buena Vista Dr

MARKIT Vegetation Removal Required - 9457 Coronado Dr

MARKIT Remove Drop - 9401 Banderilla Dr

MARKIT Raise AT&T Mainline Cable - 10304 Narcisco Way

MARKIT Raise AT&T Mainline Cable - 3535 Castillo Way

MARKIT Vegetation Removal Required - 9757 Mirasol Way

MARKIT Vegetation Removal Required - 10294 Gusanillo Way

MARKIT Vegetation Removal Required - 3152 Granite Springs Rd

MARKIT Vegetation Removal Required - 9194 Lazo Way

MARKIT Vegetation Removal Required - 15088 Parra Ct

MARKIT Vegetation Removal Required - 3303 Rosa Ct

MARKIT Repair/Replace Hardware - 10372 Jalapa Way

MARKIT Remove AnchorReplace/Install Down GuyTransfer AT&T Cable(s);Pull Old Pole;Lead Tails No;Cable Swing Yes;Trasfer 2 - 10359 Chapulin Way

MARKIT Vegetation Removal Required - 10387 Tulipan Way
MARKIT Remove AnchorReplace/Install Down GuyTransfer AT&T Cable(s)Transfer AT&T Terminal(s)Transfer AT&T Drop(s);Pull Old Pole;Lead Tails No;Cable Swing Yes;Trasfer 4 - 3299 CA-132

MARKIT Vegetation Removal Required - 10390 Tulipan Way

MARKIT Vegetation Removal Required - 9536 Banderilla Dr

MARKIT Vegetation Removal Required - 5879 Arbolada Dr

MARKIT Vegetation Removal Required - 9401 Merced Falls Rd

MARKIT Vegetation Removal Required - 3025 CA-132

MARKIT Vegetation Removal Required - 14130 Isabel Way

MARKIT Vegetation Removal Required - 2931 Granite Springs Rd

MARKIT Vegetation Removal Required - 9757 Caracol Circle

MARKIT Vegetation Removal Required - 3353 Granite Springs Rd

MARKIT Vegetation Removal Required - 5606 Llanura Dr

MARKIT Vegetation Removal Required - 3190 Azucena Ct

MARKIT Vegetation Removal Required - 14531 Potrero Way

MARKIT Vegetation Removal Required - 3561 Ladera Way

MARKIT Vegetation Removal Required - 9494 Mercado Dr

MARKIT Vegetation Removal Required - 10312 Gusanillo Way

MARKIT Remove Drop - 2266 Golfito Way

MARKIT Remove Drop - 9738 Chapel Ln

MARKIT Remove Drop - 5563 Foresta Rd

MARKIT Remove Drop - 5052 El Portal Trailer Ct

MARKIT Remove Drop - 18763 Foote St

MARKIT Tree Trimming Required - Southside Dr

MARKIT Vegetation Removal Required - El Portal Rd

MARKIT Straighten In-Line Pole - 19450 Mountain Hope Ln

MARKIT Pole leaning customer worried

MARKIT Vegetation Removal Required - 19451 Mountain Hope Ln

MARKIT Vegetation Removal Required - 17170 Monte Grande Dr

MARKIT Remove Drop - 19451 Mountain Hope Ln

MARKIT Straighten In-Line Pole - 11310 McKibbon Dr

MARKIT Straighten In-Line Pole - 18717 Mill Villa Rd

MARKIT Tree Trimming Required - 16769 Draper Mine Rd

MARKIT Relash to existing Messenger - 19597 Soulsbyville Rd

MARKIT Relash to existing Messenger - 16360 Lime Kiln Rd

MARKIT Raise AT&T Mainline Cable - 14698 Tuolumne Rd

MARKIT Intrusive Inspection Required - 16202 Placer St
MARKIT Transfer AT&T Cable(s)Transfer AT&T Drop(s);Pull Old Pole;Lead Tails No;Cable Swing No;Trasfer 4 - 11310 McKibbon Dr

MARKIT Intrusive Inspection Required - 15700 Egan Rd

MARKIT Intrusive Inspection Required - 15655 Egan Rd

MARKIT Intrusive Inspection Required - 10180 Shawmut Rd

MARKIT Repair/Replace Hardware - 12831 Harney Dr

MARKIT Remove Drop - 13740 Red Hills Rd
MARKIT Remove AnchorReplace/Install Down GuyTransfer AT&T Cable(s)Transfer AT&T Drop(s);Pull Old Pole;Lead Tails No;Cable Swing No;Trasfer 3 - 16227 Jacksonville Rd

MARKIT Re-tension Down Guy All Sizes - 13333 Red Hills Rd

MARKIT Raise AT&T Mainline Cable - 13980 Jacksonville Rd

MARKIT Place/Replace Down Guy Guard - 13440 Jacksonville Rd

MARKIT Vegetation Removal Required - 16175 Placer St

MARKIT Vegetation Removal Required - 17860 Tinnin Rd

MARKIT Raise AT&T Service Drop - 20398 N Sunshine Rd

MARKIT Repair/Replace Hardware - 16366 Jacksonville Rd

MARKIT Repair/Replace Hardware - 16351 Lucio St

MARKIT Tree Trimming Required - 17190 Monte Grande Dr

MARKIT Vegetation Removal Required - 13901 Park Ave

MARKIT Vegetation Removal Required - 11112 Constance Ln

MARKIT Repair/Replace Hardware - 11761 Mammoth Mine Rd

MARKIT Re-tension Down Guy All Sizes - 16202 Placer St

MARKIT Place/Replace Down Guy Guard - 13900 Twist Rd

MARKIT Vegetation Removal Required - 13913 Twist Rd

MARKIT Raise AT&T Mainline Cable - 12938 Harney Dr

MARKIT Vegetation Removal Required - 13611 Red Hills Rd

MARKIT Tree Trimming Required - 19721 Soulsbyville Rd

MARKIT Repair/Replace Hardware - 16351 Lucio St

MARKIT Vegetation Removal Required - 19595 Soulsbyville Rd

MARKIT Place/Replace Down Guy Guard - 12938 Harney Dr

MARKIT Tree Trimming Required - 84 Linoberg St

MARKIT Vegetation Removal Required - 801 W Stockton St

MARKIT Repair/Replace Hardware - 13908 Lake Dr

MARKIT Raise AT&T Mainline Cable - 13850 Twist Rd

MARKIT Place/Replace Down Guy Guard - 13005 Kanaka Dr

MARKIT Tree Trimming Required - 18015 Plaza Oriente Rd

MARKIT Tree Trimming Required - 11310 McKibbon Dr

MARKIT Tree Trimming Required - 11208 Circle Dr
MARKIT Remove AnchorReplace/Install Down GuyTransfer AT&T Cable(s);Pull Old Pole;Lead Tails No;Cable Swing Yes;Trasfer 2 - 11409 Jacksonville Rd

MARKIT Vegetation Removal Required - 18033 Plaza Oriente Rd

MARKIT Tree Trimming Required - 305 W Jackson St

MARKIT Tree Trimming Required - 20408 Willow Springs Dr

MARKIT Pull Old Pole;Lead Tails No;Cable Swing No;Trasfer 0 - 16328 Jacksonville Rd

MARKIT Vegetation Removal Required - 14080 Park Ave

MARKIT Place/Replace Down Guy Guard - 13580 Red Hills Rd

MARKIT Vegetation Removal Required - 13003 Jacksonville Rd
MARKIT Remove AnchorReplace/Install Down GuyTransfer AT&T Cable(s)Transfer AT&T Drop(s);Pull Old Pole;Lead Tails No;Cable Swing Yes;Trasfer 3 - 13480 Red Hills Rd

MARKIT Tree Trimming Required - 11209 Circle Dr

MARKIT Tree Trimming Required - 220 W Church St

MARKIT Remove Drop - 13760 Park Ave

MARKIT Repair/Replace Hardware - 14153 Park Ave

MARKIT Remove Drop - 18445 Hatler Dr

MARKIT Vegetation Removal Required - 14031 Joint Venture Rd
MARKIT Remove AnchorReplace/Install Down GuyTransfer AT&T Cable(s);Pull Old Pole;Lead Tails No;Cable Swing Yes;Trasfer 2 - 12282 Wahine Dr

MARKIT Vegetation Removal Required - 13808 Park Ave

MARKIT Vegetation Removal Required - 10640 Quartz Alley

MARKIT Vegetation Removal Required - 13740 Red Hills Rd

MARKIT Repair/Replace Hardware - 14069 Jacksonville Rd

MARKIT Tree Trimming Required - 11292 McKibbon Dr

MARKIT Tree Trimming Required - 17887 Elaine Way

MARKIT Place/Replace Down Guy Guard - 16351 Lucio St
MARKIT Remove AnchorReplace/Install Down GuyReplace/Install Overhead GuyTransfer AT&T Cable(s);Pull Old Pole;Lead Tails No;Cable Swing Yes;Trasfer 3 - 14076 Jacksonville Rd

MARKIT Tree Trimming Required - 18153 Old Wards Ferry Rd

MARKIT Place/Replace Down Guy Guard - Montezuma Rd

MARKIT Tree Trimming Required - 13520 Tres Casas
MARKIT Remove AnchorReplace/Install Down Guy;Pull Old Pole;Lead Tails No;Cable Swing Yes;Trasfer 2 - 14145 Park Ave

MARKIT Repair/Replace Hardware - 16328 Jacksonville Rd

MARKIT Place/Replace Down Guy Guard - Montezuma Rd

MARKIT Remove Drop - 16948 Amy Dr

MARKIT Raise AT&T Service Drop - 4 N Forest Rd

MARKIT Remove Drop - 13947 Park Ave

MARKIT Remove Drop - 17806 Campbell Flat Rd

MARKIT Remove Drop - 11292 McKibbon Dr

MARKIT Remove Drop - 17922 Campbell Flat Rd

MARKIT Remove Drop - 16120 Jacksonville Rd

MARKIT Remove Drop - 15775 Bev Barron Rd

MARKIT Remove Drop - 18165 Wards Ferry Rd

MARKIT Remove Drop - 11209 Circle Dr

MARKIT Straighten In-Line Pole - 14886 Big Hill Rd

MARKIT Straighten In-Line Pole - 21220 Old Sonora Columbia Rd

MARKIT Replace/Install Down Guy - 22030 Sawmill Flat Rd

MARKIT Tree Trimming Required - 22747 Sawmill Flat Rd

MARKIT Tree Trimming Required - 21892 Sawmill Flat Rd

MARKIT Tree Trimming Required - 20625 Lyons Bald Mountain Rd

MARKIT Tree Trimming Required - 624 E Jackson St

MARKIT Relash Existing Cables - 21960 Sawmill Flat Rd

MARKIT Tree Trimming Required - 22502 Sawmill Flat Rd

MARKIT Intrusive Inspection Required - 18271 CA-120

MARKIT Lower or Raise Existing Cable - 29461 Shasta Dr

MARKIT Tree Trimming Required - 15433 Camino del Parque Rd S

MARKIT Tree Trimming Required - 14766 Rosy Ridge Ct

MARKIT Tree Trimming Required - 21920 Sawmill Flat Rd

MARKIT Raise AT&T Service Drop - 14522 Old Oak Ranch Rd

MARKIT Remove Drop - 15455 Old Oak Ranch Rd

MARKIT Tree Trimming Required - 23351 Rancho Castanea Rd

MARKIT Tree Trimming Required - 12215 Yankee Hill Rd

MARKIT Vegetation Removal Required - 12285 Yankee Hill Rd

MARKIT Tree Trimming Required - 22669 Sawmill Flat Rd

MARKIT Vegetation Removal Required - 11699 Merrell Rd

MARKIT Remove Drop - 10912 Merrell Rd

MARKIT Vegetation Removal Required - 18271 CA-120

MARKIT Vegetation Removal Required - 19618 Old CA-120

MARKIT Vegetation Removal Required - 11700 Merrell Rd

MARKIT Vegetation Removal Required - 20488 Whites Gulch Rd

MARKIT Vegetation Removal Required - 20601 Morgan Dr

MARKIT Vegetation Removal Required - 11293 Merrell Rd

MARKIT Vegetation Removal Required - 18500 El Capitan Way

MARKIT Vegetation Removal Required - 14000 Old CA-120

MARKIT Remove Drop - 20601 Morgan Dr

MARKIT Tree Trimming Required - 21886 Paseo de los Portales Rd

MARKIT Tree Trimming Required - 21732 El Puma Circle

MARKIT Tree Trimming Required - 21929 W Crystal Falls Dr

MARKIT Tree Trimming Required - 29565 Yuba Ct

MARKIT Contact Local AT&T Office for Remediation - 14650 Big Hill Rd

MARKIT Remove Cable - 22030 Sawmill Flat Rd

MARKIT Remove Drop - 21241 Old Sonora Columbia Rd

MARKIT Remove Drop - 21241 Old Sonora Columbia Rd

MARKIT Remove Drop - 13829 Jenny Lind Rd

MARKIT Remove Drop - 23025 Knickerbocker Flat Rd

MARKIT Remove Drop - 12037 Yankee Hill Rd

MARKIT Remove Drop - 1194 CA-49

MARKIT Raise AT&T Service Drop - 22433 Gunsight Rd

MARKIT Remove Drop - 12734 Old CA-120

MARKIT Remove Drop - 21622 Crestview Dr

MARKIT Remove Drop - 21988 El Coyote Dr

MARKIT Remove Drop - 21929 W Crystal Falls Dr

MARKIT Remove Drop - 21871 Belleview Rd

MARKIT Remove Drop - 29678 Lassen Dr

MARKIT Remove Drop - 26566 Old Mono Rd

MARKIT Remove Drop - 26499 Old Mono Rd
MARKIT Found aerial drop hanging in street. Temporarily raised drop. Unable to access customer side to permanently raise and attach drop. Needs to be attached to house correctly.
MARKIT Pole containing 3 C type service drops leaning 25 degrees, branches on drop further down, about to come down. Need line crew to fix pole

MARKIT 6509 Camellia Dr

MARKIT 900 E Vassar

MARKIT Pole broken down on cable. Delashed further down. Cable damage to senior center coming off pole

CABLE ON GROUND ACCESSIBLE TO PUBLIC.

MARKIT Need to remove drop hanging to low to ground

MARKIT 16555 south Creekside dr. Drop to low. Needs to be pulled up and or removed
MARKIT House Drop down, low.

MARKIT Repair/Replace Hardware - 10362 Dexter Ln

MARKIT Tree Trimming Required - 17022 Nelson Rd

MARKIT Tree Trimming Required - 17125 Table Mountain Rd

MARKIT Vegetation Removal Required - 8920 Montezuma Rd

MARKIT Tree Trimming Required - 11980 Shotgun Creek Dr

MARKIT Tree Trimming Required - 15400 New Peoria Flat Rd

MARKIT Vegetation Removal Required - 13790 Sims Rd

MARKIT Tree Trimming Required - 7699 State Highway 120

MARKIT Raise AT&T Mainline Cable - 8975 State Highway 120

MARKIT Tree Trimming Required - 15325 State Highway 108

MARKIT Tree Trimming Required - 9870 Pulpit Rock Rd

MARKIT Tree Trimming Required - 18708 State Highway 108

MARKIT Tree Trimming Required - 10080 Mountain Vista Ct

MARKIT Tree Trimming Required - 17733 Woods Way

MARKIT Tree Trimming Required - 17556 Twin Oak Dr

MARKIT Tree Trimming Required - 17817 Seco St

MARKIT Tree Trimming Required - 10970 Golf Links Rd

MARKIT Tree Trimming Required - 10628 Wigwam Rd

MARKIT Tree Trimming Required - 17965 Seco St

MARKIT Tree Trimming Required - 17851 State Highway 108

MARKIT Tree Trimming Required - 17146 Table Mountain Rd

MARKIT Tree Trimming Required - 17141 Chicken Ranch Rd

MARKIT Tree Trimming Required - 17171 Jeanese Dr

MARKIT Tree Trimming Required - 3264 Bonds Flat Rd

MARKIT Straighten In-Line Pole - 3264 Bonds Flat Rd

MARKIT Tree Trimming Required - 10177 Pulpit Rock Rd

MARKIT Tree Trimming Required - 18151 7th Ave

MARKIT Tree Trimming Required - 17727 Seco St

MARKIT Tree Trimming Required - 17707 State Highway 108

MARKIT Tree Trimming Required - 17600 State Highway 108

MARKIT Tree Trimming Required - 18885 Rawhide Rd

MARKIT Tree Trimming Required - 10072 Pulpit Rock Rd

MARKIT Tree Trimming Required - 9890 Pulpit Rock Rd

MARKIT Tree Trimming Required - 17984 Harvard Mine Rd

MARKIT Tree Trimming Required - 9856 Pulpit Rock Rd

MARKIT Tree Trimming Required - 18930 Rawhide Rd

MARKIT Tree Trimming Required - 18431 Railbed Rd

MARKIT Tree Trimming Required - 18074 Seco St

MARKIT Tree Trimming Required - 11000 Mountain Vista Ct

MARKIT Tree Trimming Required - 10799 Wigwam Rd

MARKIT Tree Trimming Required - 18141 8th Ave

MARKIT Tree Trimming Required - 18517 Rawhide Rd

MARKIT Tree Trimming Required - 18385 5th Ave

MARKIT Tree Trimming Required - 18790 Rawhide Rd

MARKIT Tree Trimming Required - 10767 Golf Links Rd

MARKIT Vegetation Removal Required - 17888 Harvard Mine Rd

MARKIT Tree Trimming Required - 9856 Pulpit Rock Rd

MARKIT Tree Trimming Required - 17572 Twin Oak Dr

MARKIT Tree Trimming Required - 17701 Seco St

MARKIT Tree Trimming Required - 17306 Jacksonville Rd

MARKIT Tree Trimming Required - 16446 Stamp Mill Loop Rd E

MARKIT Tree Trimming Required - 17100 Chicken Ranch Rd

MARKIT Tree Trimming Required - 5090 Obyrnes Ferry Rd

MARKIT Tree Trimming Required - 15082 State Highway 108

MARKIT Tree Trimming Required - 15109 State Highway 108

MARKIT Tree Trimming Required - 5981 Obyrnes Ferry Rd

MARKIT Tree Trimming Required - 5959 Obyrnes Ferry Rd

MARKIT Tree Trimming Required - 13000 Shotgun Creek Dr

MARKIT Tree Trimming Required - Old Melones Dam Rd

MARKIT Tree Trimming Required - 5170 Obyrnes Ferry Rd

MARKIT Tree Trimming Required - 15351 New Peoria Flat Rd

MARKIT Tree Trimming Required - 14427 Sims Rd

MARKIT Tree Trimming Required - 15396 New Peoria Flat Rd

MARKIT Tree Trimming Required - 5498 Obyrnes Ferry Rd

MARKIT Tree Trimming Required - 6553 Obyrnes Ferry Rd

MARKIT Tree Trimming Required - 5450 Obyrnes Ferry Rd

MARKIT Tree Trimming Required - 14667 State Highway 108

MARKIT Tree Trimming Required - 5015 Obyrnes Ferry Rd

MARKIT Tree Trimming Required - 6783 Obyrnes Ferry Rd

MARKIT Tree Trimming Required - 17013 Jacksonville Rd

MARKIT Tree Trimming Required - 17151 Nelson Rd

MARKIT Tree Trimming Required - 8553 Montezuma Rd

MARKIT Tree Trimming Required - 8920 Montezuma Rd

MARKIT Re-tension Down Guy All Sizes - 13333 Red Hills Rd

MARKIT Place/Replace Down Guy Guard - 13255 Red Hills Rd

MARKIT Relash to existing Messenger - 13255 Red Hills Rd

MARKIT Relash to existing Messenger - 8920 Montezuma Rd

MARKIT Place/Replace Down Guy Guard - 15503 State Highway 108

MARKIT Relash to existing Messenger - 8937 State Highway 120

MARKIT Relash Existing Cables - 7190 Obyrnes Ferry Rd

MARKIT Relash to existing Messenger - 17733 Woods Way

MARKIT Relash to existing Messenger - 11870 Justin Ct

MARKIT Repair/Replace Hardware - 8495 French Flat Rd

MARKIT Repair/Replace Hardware - 18141 7th Ave

MARKIT Repair/Replace Hardware - 17851 State Highway 108

MARKIT Relash to existing Messenger - 10141 Bell Mooney Rd

MARKIT Relash Existing Cables - 17830 Woods Way

MARKIT Relash Existing Cables - 18003 Shell Rd

MARKIT Relash Existing Cables - 10111 Hitchcock Ct

MARKIT Relash Existing Cables - 8800 Montezuma Rd

MARKIT Relash to existing Messenger - 16450 State Highway 108

MARKIT Place/Replace Down Guy Guard - 16996 Nelson Rd

MARKIT Relash Existing Cables - 17600 State Highway 108

MARKIT Relash Existing Cables - 18074 Seco St

MARKIT Repair/Replace Hardware - 18385 5th Ave

MARKIT Relash Existing Cables - 18790 Rawhide Rd

MARKIT Relash to existing Messenger - 17572 Twin Oak Dr

MARKIT Relash to existing Messenger - Montezuma Rd

MARKIT Repair/Replace Hardware - 17191 Chicken Ranch Rd

MARKIT Relash to existing Messenger - 13281 Red Hills Rd

MARKIT Raise AT&T Service Drop - 8920 Montezuma Rd

MARKIT Relash Existing Cables - 14649 State Highway 108

MARKIT Relash to existing Messenger - Sims Rd

MARKIT Relash to existing Messenger - 8920 Montezuma Rd

MARKIT Relash to existing Messenger - 16004 State Highway 108

MARKIT Repair/Replace Hardware - 8800 Montezuma Rd

MARKIT Remove Drop - 18305 9th Ave

MARKIT Remove Drop - 18515 Railbed Rd

MARKIT Remove Drop - 17561 Harvard Mine Rd

MARKIT Remove Drop - 18141 8th Ave

MARKIT Remove Drop - 18238 9th Ave

MARKIT Remove Drop - 18591 Railbed Rd

MARKIT Remove Drop - 17712 Harvard Mine Rd

MARKIT Remove Drop - 8975 State Highway 120

MARKIT Tree Trimming Required - 23 Highland Way

MARKIT Tree Trimming Required - 28745 Herring Creek Ln

MARKIT Tree Trimming Required - 29380 Modoc Dr

MARKIT Tree Trimming Required - 29380 Modoc Dr

MARKIT Relash Existing Cables - 28722 Herring Creek Ln

MARKIT Tree Trimming Required - 29682 Lassen Dr

MARKIT Tree Trimming Required - 29682 Lassen Dr

MARKIT Tree Trimming Required - 29682 Lassen Dr

MARKIT Relash Existing Cables - 29571 Lassen Dr

MARKIT Tree Trimming Required - 28685 Herring Creek Ln

MARKIT Tree Trimming Required - 28685 Herring Creek Ln

MARKIT Tree Trimming Required - 29579 Yuba Ct

MARKIT Tree Trimming Required - 29522 Kerns Dr

MARKIT Tree Trimming Required - 25495 Bambi Ln

MARKIT Tree Trimming Required - 29970 Mariposa Dr

MARKIT Tree Trimming Required - 18195 State Highway 120

MARKIT Tree Trimming Required - 11700 Merrell Rd

MARKIT Tree Trimming Required - 18601 Harper Rd

MARKIT Tree Trimming Required - 18453 Main St

MARKIT Tree Trimming Required - 10916 Merrell Rd

MARKIT Tree Trimming Required - 18989 Ferretti Rd

MARKIT Tree Trimming Required - 11255 Merrell Rd

MARKIT Remove Drop - 18537 N Dome Ct

MARKIT Tree Trimming Required - 20892 McKinley Way

MARKIT Repair/Replace Hardware - 23121 Hells Hollow Rd

MARKIT Tree Trimming Required - 20488 Whites Gulch Rd

MARKIT Tree Trimming Required - 20590 Morgan Dr

MARKIT Tree Trimming Required - 11293 Merrell Rd

MARKIT Remove Drop - 21060 Morgan Dr

MARKIT Remove Drop - 21011 Morgan Dr

MARKIT Remove Drop - 19952 Big Oak Flat Rd

MARKIT Remove Drop - 20875 Morgan Dr

MARKIT Vegetation Removal Required - 22445 Gunsight Rd

MARKIT Tree Trimming Required - 22690 Sawmill Flat Rd

MARKIT Relash to existing Messenger - 12037 Yankee Hill Rd

MARKIT Straighten In-Line Pole - 22003 Marcus Ln

MARKIT Tree Trimming Required - 21816 El Conejo Way

MARKIT Remove Drop - 1180 Highway 49

MARKIT Tree Trimming Required - 21681 Fern Ln

MARKIT Tree Trimming Required - 20390 Lyons Bald Mountain Rd

MARKIT Tree Trimming Required - 22747 Sawmill Flat Rd

MARKIT Tree Trimming Required - 20550 Gordon Ct

MARKIT Tree Trimming Required - 12285 Yankee Hill Rd

MARKIT Tree Trimming Required - 21913 Fallview Dr

MARKIT Tree Trimming Required - 21866 Phoenix Lake Rd

MARKIT Tree Trimming Required - 453 E Jackson St

MARKIT Tree Trimming Required - 20550 Charlotte Ct

MARKIT Tree Trimming Required - 12081 Yankee Hill Rd

MARKIT Tree Trimming Required - 21938 El Coyote Dr

MARKIT Tree Trimming Required - 23740 Italian Bar Rd

MARKIT Tree Trimming Required - 16420 Creekside Dr

MARKIT Tree Trimming Required - 15433 Camino del Parque Rd S

MARKIT Tree Trimming Required - 15342 El Venada Trail

MARKIT Tree Trimming Required - 20537 Charlotte Ct

MARKIT Tree Trimming Required - 580 E Oakside Dr

MARKIT Tree Trimming Required - 15409 Camino del Parque Rd S

MARKIT Tree Trimming Required - 20828 Lyons Bald Mountain Rd

MARKIT Tree Trimming Required - 15520 Paseo de Los Robles Rd

MARKIT Tree Trimming Required - 15472 Paseo de Los Robles Rd

MARKIT Tree Trimming Required - 12252 Yankee Hill Rd

MARKIT Tree Trimming Required - 15378 Camino del Parque Rd S

MARKIT Raise AT&T Service Drop - 30 Columbia Way

MARKIT Raise AT&T Service Drop - 20610 Columbia Way

MARKIT Tree Trimming Required - 136 Columbia Way

MARKIT Tree Trimming Required - 15347 Camino del Parque Rd N

MARKIT Tree Trimming Required - 14918 Potato Ranch Rd

MARKIT Tree Trimming Required - 15517 Paseo de Los Robles Rd

MARKIT Tree Trimming Required - 16541 Creekside Dr

MARKIT Tree Trimming Required - 21831 Sawmill Flat Rd

MARKIT Remove Drop - 21241 Old Sonora Columbia Rd

MARKIT Tree Trimming Required - 15405 Danata Way

MARKIT Tree Trimming Required - 16529 Creekside Dr

MARKIT Tree Trimming Required - 15413 Paseo de Los Robles Rd

MARKIT Tree Trimming Required - 136 Columbia Way

MARKIT Tree Trimming Required - 21900 Sawmill Flat Rd

MARKIT Tree Trimming Required - 21740 Apple Hill Dr

MARKIT Tree Trimming Required - 16336 Creekside Dr

MARKIT Tree Trimming Required - 429 E Jackson St

MARKIT Tree Trimming Required - 20920 Caylor Dr

MARKIT Tree Trimming Required - 21555 Phoenix Lake Rd

MARKIT Tree Trimming Required - 21950 Lyons Bald Mountain Rd

MARKIT Tree Trimming Required - 20680 Charlotte Ct

MARKIT Tree Trimming Required - 15489 Camino del Parque Rd S

MARKIT Remove Drop - 21241 Old Sonora Columbia Rd

MARKIT Tree Trimming Required - 16837 W American River Dr

MARKIT Tree Trimming Required - 564 E Jackson St

MARKIT Tree Trimming Required - 21551 Phoenix Lake Rd

MARKIT Tree Trimming Required - 11910 Highway 49

MARKIT Tree Trimming Required - 21920 Sawmill Flat Rd

MARKIT Remove Drop - 21280 Ridgeview Dr

MARKIT Remove Drop - 13457 Jenny Lind Rd

MARKIT Remove Drop - 21189 Jack Page Rd
MARKIT Transfer AT&T Cable(s)Transfer AT&T Drop(s);Pull Old Pole;Lead Tails No;Cable Swing Yes;Trasfer 8 - 50 Columbia Way

MARKIT Remove Drop - 21241 Old Sonora Columbia Rd

MARKIT Vegetation Removal Required - 136 Columbia Way

MARKIT Remove Drop - 20697 W Willow Springs Dr

MARKIT Remove Drop - 20870 Caylor Dr

MARKIT Remove Drop - 20660 Willow Springs Dr

MARKIT Tree Trimming Required - 20472 Hekeke Ln

MARKIT Tree Trimming Required - 20559 Kutci Dr

MARKIT Tree Trimming Required - 24181 Sonora Pass Hwy

MARKIT Tree Trimming Required - 18741 Middle Camp Rd

MARKIT Tree Trimming Required - 23885 Yellow Pine Rd

MARKIT Tree Trimming Required - 20811 Koteo Ln

MARKIT Tree Trimming Required - 24029 Golf Links Dr

MARKIT Tree Trimming Required - 24246 Nuka Ct

MARKIT Tree Trimming Required - 18750 Beatrice Ave

MARKIT Tree Trimming Required - 24214 Lama Rd

MARKIT Tree Trimming Required - 18817 Middle Camp Rd

MARKIT Tree Trimming Required - 23856 Pine Lake Dr

MARKIT Tree Trimming Required - 20260 Lilac Ln

MARKIT Tree Trimming Required - 24315 Lama Road Tamalin

MARKIT Tree Trimming Required - 24776 Bonanza Dr

MARKIT Tree Trimming Required - 20904 Lama Road Teumete

MARKIT Tree Trimming Required - 20679 Lama Road Teumete

MARKIT Tree Trimming Required - 20662 Lama Road Tamalin

MARKIT Tree Trimming Required - 23532 Lakewood Dr

MARKIT Tree Trimming Required - 18925 Sycamore Circle

MARKIT Tree Trimming Required - 19201 Huron Dr

MARKIT Tree Trimming Required - 24015 Lama Rd

MARKIT Tree Trimming Required - 20751 Haiapo Rd

MARKIT Tree Trimming Required - 20846 Telele Trail

MARKIT Tree Trimming Required - 18803 Middle Camp Rd

MARKIT Tree Trimming Required - 18774 Middle Camp Rd

MARKIT Tree Trimming Required - 19837 Wanita Ln

MARKIT Tree Trimming Required - 23933 Pine Lake Dr

MARKIT Tree Trimming Required - 24316 Jeffrey St

MARKIT Tree Trimming Required - 20734 Lama Road Teumete

MARKIT Tree Trimming Required - 24233 Lama Rd

MARKIT Tree Trimming Required - 24349 Jeanita Ln

MARKIT Tree Trimming Required - 17443 Smokey River Dr

MARKIT Tree Trimming Required - 22364 Longeway Rd

MARKIT Tree Trimming Required - 21890 Longeway Rd

MARKIT Tree Trimming Required - 22005 Longeway Rd

MARKIT Tree Trimming Required - 22479 Ponderosa Dr

MARKIT Tree Trimming Required - 16869 E Brookside Dr

MARKIT Tree Trimming Required - 18740 Columbia Dr

MARKIT Tree Trimming Required - 23747 Fremont Way

MARKIT Tree Trimming Required - 21472 Longeway Rd

MARKIT Raise AT&T Mainline Cable - 22101 Longeway Rd

MARKIT Tree Trimming Required - 17300 Smokey River Dr

MARKIT Tree Trimming Required - 17220 Smokey River Dr

MARKIT Tree Trimming Required - 17100 N Colorado River Dr

MARKIT Tree Trimming Required - 22352 Longeway Rd

MARKIT Tree Trimming Required - 17317 Scenic Heights Dr

MARKIT Tree Trimming Required - 17974 Kinglet Ct

MARKIT Tree Trimming Required - 23031 Thrush Pl

MARKIT Tree Trimming Required - 23295 Middle Camp Rd

MARKIT Tree Trimming Required - 22991 Black Oak Dr

MARKIT Tree Trimming Required - 22585 Golf Club Dr

MARKIT Tree Trimming Required - 22366 Ponderosa Dr

MARKIT Tree Trimming Required - 23191 Mark Twain Dr

MARKIT Tree Trimming Required - 23100 Mark Twain Dr

MARKIT Tree Trimming Required - 24049 Oxbow Ln N

MARKIT Tree Trimming Required - 18558 Wildwood Dr

MARKIT Tree Trimming Required - 24238 Oxbow Ln N

MARKIT Tree Trimming Required - 19424 Superior Dr

MARKIT Tree Trimming Required - 23577 Lakewood Dr

MARKIT Tree Trimming Required - 18947 Huron Dr

MARKIT Tree Trimming Required - 23549 Lakewood Dr

MARKIT Tree Trimming Required - 19201 Huron Dr

MARKIT Tree Trimming Required - 24025 Oxbow Ln N

MARKIT Tree Trimming Required - 23564 Lakewood Dr

MARKIT Tree Trimming Required - 19365 Superior Dr

MARKIT Tree Trimming Required - 19429 Michigan Dr

MARKIT Tree Trimming Required - 22120 N Tuolumne Rd

MARKIT Tree Trimming Required - 22817 Highland Dr

MARKIT Tree Trimming Required - 16889 E Brookside Dr

MARKIT Tree Trimming Required - 24477 Lodge Way

MARKIT Tree Trimming Required - 17087 E Brookside Dr

MARKIT Tree Trimming Required - 23337 Tanager Dr

MARKIT Tree Trimming Required - 22834 Black Hawk Dr

MARKIT Tree Trimming Required - 18844 Fir Dr

MARKIT Tree Trimming Required - 22523 Twain Harte Dr

MARKIT Tree Trimming Required - 18826 Laurel Ave

MARKIT Tree Trimming Required - 22671 Twain Harte Dr

MARKIT Tree Trimming Required - 22576 Twain Harte Dr

MARKIT Tree Trimming Required - 22805 Highland Dr

MARKIT Tree Trimming Required - 18864 Fir Dr

MARKIT Tree Trimming Required - 23394 Tanager Dr

MARKIT Tree Trimming Required - 17155 Forest Lake Rd

MARKIT Tree Trimming Required - 22118 N Tuolumne Rd

MARKIT Tree Trimming Required - 21803 Confidence Rd

MARKIT Tree Trimming Required - 22777 Maple Ave

MARKIT Tree Trimming Required - 17689 Lucky Strike Trail

MARKIT Tree Trimming Required - 21767 Longeway Rd

MARKIT Tree Trimming Required - 22050 Fair Oaks Ct

MARKIT Tree Trimming Required - 21350 Longeway Rd

MARKIT Tree Trimming Required - 21245 Longeway Rd

MARKIT Repair/Replace Hardware - 24770 Tramway Rd

MARKIT Repair/Replace Hardware - 18862 Broadhurst Dr

MARKIT Relash Existing Cables - 20472 Hekeke Ln

MARKIT Relash Existing Cables - 20692 Hekeke Ln

MARKIT Repair/Replace Hardware - 22455 S Fork Rd

MARKIT Repair/Replace Hardware - 23191 Mark Twain Dr

MARKIT Repair/Replace Hardware - 16454 W Brookside Dr

MARKIT Relash to existing Messenger - 24049 Oxbow Ln N

MARKIT Relash Existing Cables - 23025 Twain Harte Dr

MARKIT Repair/Replace Hardware - 18947 Huron Dr

MARKIT Place/Replace Down Guy Guard - 24030 S Bear Clover Ct

MARKIT Repair/Replace Hardware - 19351 Middle Camp Rd

MARKIT Repair/Replace Hardware - 17962 Towhee Ln

MARKIT Remove Drop - 23825 Yellow Pine Rd

MARKIT Remove Drop - 19126 Middle Camp Rd

MARKIT Tree Trimming Required - 20825 Haiapo Rd

MARKIT Remove Drop - 23747 Fremont Way

MARKIT Remove Drop - 23485 Mountain Dr

MARKIT Remove Drop - 23191 Mark Twain Dr

MARKIT Remove Drop - 23859 Marshall Way

MARKIT Remove Drop - 19471 Middle Camp Rd

MARKIT Remove Drop - 24030 S Bear Clover Ct

MARKIT Remove Drop - 19365 Superior Dr

MARKIT Remove Drop - 22715 Black Hawk Dr

MARKIT Remove Drop - 20712 Telele Trail

MARKIT Remove Drop - 22315 S Fork Rd

MARKIT Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Pole Lean of 10 percent or more of height above ground

MARKIT Pole is split at top and cable bolts has come out of pole and cable laying on the ground
MARKIT Old temp repair of cable and strand over canal, needs strand tightened and new piece of cable placed and respliced

MARKIT 18591 Woodwardia rd Twain Harte CA

MARKIT Lashing wire is a broken causing main cable to sag 6 ft from ground
MARKIT PG&E topped pole and placed new pole opposite side of driveway At&t and cab,e comp. still attached to old def pole cust want to have pole,removed
MARKIT Cable is low due to lashing wire loose or broken and splice exposed to elements

MARKIT Pole is split from the top approximately 6 feet to our strand

Cable 1 - Hazardous - Clearance to Ground <8ft accessible to public

Cable 1 - Hazardous - Clearance to Ground <8ft accessible to public

Vegetation 1 - Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole

Cable 1 - Cable on Ground. Accessible to Public
This needs to go to Engineering verify cut/abandoned strand/cable and case. There's only like 30' of cable including what runs up the pole. If it's dead, they can issue a job to wreck it.

Vegetation 1 - Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Vegetation 1 - Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Vegetation 1 - Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Vegetation 1 - Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Vegetation 1 - Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Pole 1 - Pole with Immediate Risk due to Obvious Visible Damage. Potential Hazard.

Vegetation 1 - Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

MARKIT REMOVE DROP - 20995 HEMLOCK ST

MARKIT REMOVE DROP - 17725 SHOP ST

MARKIT REMOVE DROP - 20213 PINE MOUNTAIN DR

MARKIT REMOVE DROP - 20831 BIG FOOT CIRCLE

MARKIT REMOVE DROP - 20847 BIG FOOT CIR

MARKIT REMOVE DROP - 20148 LOWER SKYRIDGE DR

MARKIT TREE TRIMMING REQUIRED - 20550 MORGAN DR

MARKIT REPAIR/REPLACE HARDWARE - 19584 CHAFFEE CIRCLE

MARKIT RELASH TO EXISTING MESSENGER - 19749 BUTLER WAY

MARKIT RAISE AT&T SERVICE DROP - 12765 MUELLER DR

MARKIT REMOVE DROP - 12754 MUELLER DR

MARKIT REMOVE DROP - 20125 PLEASANTVIEW DR

MARKIT REMOVE DROP - 19600 GOLDEN ROCK CIRCLE
MARKIT TRANSFER AT&T CABLE(S);PULL OLD POLE;LEAD TAILS NO;CABLE SWING NO;TRASFER 3 - 19819 OLD HIGHWAY 120

MARKIT REMOVE DROP - 14135 BOITANO RD

MARKIT REMOVE DROP - 11190 BIG CREEK SHAFT RD

MARKIT TREE TRIMMING REQUIRED - BIG OAT FLAT RD

MARKIT REMOVE DROP - 20709 MORGAN DR

MARKIT REMOVE DROP - 28635 HERRING CREEK LN

MARKIT REMOVE DROP - 28635 HERRING CREEK LN

MARKIT REMOVE DROP - 20742 FORESTWOOD WAY

MARKIT REMOVE DROP - 22500 FERRETTI RD

MARKIT REPLACE/INSTALL DOWN GUY - 22500 FERRETTI RD

MARKIT REMOVE DROP - 20451 PINE MOUNTAIN DR

MARKIT REMOVE DROP - 11050 S PONDEROSA WAY

MARKIT REMOVE DROP - 31701 QUAIL DR

MARKIT REMOVE DROP - 31893 WHIP-POOR-WILL DR

MARKIT REMOVE DROP - 29005 STATE HIGHWAY 108

MARKIT REPAIR/REPLACE HARDWARE - 353 LAKESHORE DR

MARKIT REPAIR/REPLACE HARDWARE - 12991 CLEMENTS RD

MARKIT REMOVE DROP - 17640 STATE HIGHWAY 120

MARKIT REMOVE DROP - 11170 BIG OAK RD

MARKIT REMOVE DROP - 17895 STATE HIGHWAY 120

MARKIT REMOVE DROP - CHERRY LAKE RD

MARKIT REMOVE DROP - 11450 BUCK MEADOWS RD

MARKIT REPLACE/INSTALL DOWN GUY - LAKESHORE DR

MARKIT TREE TRIMMING REQUIRED - LAKESHORE DR

MARKIT REMOVE DROP - 28165 MEADOWVIEW DR

MARKIT REMOVE DROP - 29599 ALPINE DR

MARKIT REMOVE DROP - 18497 STATE HIGHWAY 120

MARKIT RELASH EXISTING CABLES - 19267 PINE MOUNTAIN DR

MARKIT REMOVE DROP - 19267 PINE MOUNTAIN DR

MARKIT REMOVE DROP - 19415 PINE MOUNTAIN DR

MARKIT REMOVE DROP - 13565 CHERRY LAKE RD

MARKIT REMOVE DROP - 11785 POWDER HOUSE ST

MARKIT REMOVE DROP - 18521 MAIN ST

MARKIT REMOVE DROP - 29675 LASSEN DR

MARKIT RAISE AT&T MAINLINE CABLE - 29670 LASSEN DR

MARKIT RAISE AT&T SERVICE DROP - 29522 KERNS DR/NOTES: THE LOWER SEVICE WIRE IS CATV.

MARKIT RAISE AT&T MAINLINE CABLE - 29791 MARIPOSA DR

MARKIT VEGETATION REMOVAL REQUIRED - 18985 FERRETTI RD

MARKIT VEGETATION REMOVAL REQUIRED - 18971 FERRETTI RD

MARKIT REMOVE DROP - 29481 YUBA CT

MARKIT REMOVE DROP - 28833 SNOWWHITE RIDGE DR

MARKIT REMOVE DROP - 29022 SNOWWHITE RIDGE DR

MARKIT REMOVE DROP - 29415 OLD MONO RD

MARKIT REMOVE DROP - 26465 OLD MONO RD

MARKIT REMOVE DROP - 29672 BUTTE CT

MARKIT TREE TRIMMING REQUIRED - 23350 BIG OAK FLAT RD

MARKIT TREE TRIMMING REQUIRED - 23350 BIG OAK FLAT RD

MARKIT TREE TRIMMING REQUIRED - 23350 BIG OAK FLAT RD

MARKIT TREE TRIMMING REQUIRED - BIG OAT FLAT RD

MARKIT TREE TRIMMING REQUIRED - BIG OAT FLAT RD

MARKIT REMOVE DROP - 19401 FERRETTI RD

MARKIT REMOVE DROP - 13023 MOKELUMNES CIRCLE

MARKIT REMOVE DROP - 12913 MUELLER DR

MARKIT REMOVE DROP - 17401 STATE HIGHWAY 120

MARKIT TREE TRIMMING REQUIRED - 23135 HELLS HOLLOW RD

MARKIT TREE TRIMMING REQUIRED - 23350 BIG OAK FLAT RD

MARKIT TREE TRIMMING REQUIRED - 23121 HELLS HOLLOW RD

MARKIT REMOVE DROP - 11133 SCOFIELD ST

MARKIT REPAIR/REPLACE HARDWARE - 11971 MYER CT

MARKIT REMOVE DROP - 20858 MCKINLEY WAY

MARKIT REMOVE DROP - 90 PINECREST AVE

MARKIT REMOVE DROP - 76 PINECREST AVE

MARKIT REMOVE DROP - LAKESHORE DR

MARKIT REMOVE DROP - 28280 TANAGER DR

MARKIT REMOVE DROP - 28292 TANAGER DR

MARKIT REMOVE DROP - 28243 OLD STRAWBERRY DR

MARKIT REMOVE DROP - 28124 STRAWBERRY DR

MARKIT REPAIR/REPLACE HARDWARE - 28534 GEORGES DR

MARKIT REMOVE DROP - 28217 TANAGER DR

MARKIT REMOVE DROP - 28257 OLD STRAWBERRY RD

MARKIT REMOVE DROP - 20754 BIG FOOT CIR

MARKIT REMOVE DROP - 20554 MORGAN DR

MARKIT REMOVE DROP - 20621 NOB HILL CIRCLE

MARKIT REMOVE DROP - 12889 GREEN VALLEY CIRCLE

MARKIT REMOVE DROP - 20551 NOB HILL CIR

MARKIT REMOVE DROP - 12767 CRESTHAVEN DR

MARKIT REMOVE DROP - 12889 GREEN VALLEY CIRCLE

MARKIT REMOVE DROP - 21044 MORGAN DR

MARKIT REMOVE DROP - 28429 GEORGES DR

MARKIT REMOVE DROP - 28484 GEORGES DR

MARKIT REMOVE DROP - 28288 GEORGES DR

MARKIT RAISE AT&T SERVICE DROP - 28141 MEADOW VIEW DR

MARKIT REMOVE DROP - 28209 PINE AVE

MARKIT REMOVE DROP - 31885 OLD STRAWBERRY RD

MARKIT REMOVE DROP - 28149 PINE AVE

MARKIT REMOVE DROP - 12884 GREEN VALLEY CIRCLE

MARKIT REPLACE/INSTALL DOWN GUY - 12699 MOUNT JEFFERSON ST

MARKIT REMOVE DROP - 20885 ELDERBERRY WAY

MARKIT REMOVE DROP - 19566 BUTLER WAY

MARKIT REMOVE DROP - 11598 NOELS DIRT RD

MARKIT REMOVE DROP - 20012 DUNN CT

MARKIT REMOVE DROP - 20002 DUNN CT

MARKIT RAISE AT&T SERVICE DROP - 31541 WILD OATS TRAIL

MARKIT REMOVE DROP - 33427 SONORA PASS HWY

MARKIT REPAIR/REPLACE HARDWARE - 30667 OLD STRAWBERRY RD

MARKIT RAISE AT&T SERVICE DROP - 29812 MARIPOSA DR

MARKIT REMOVE DROP - 29844 MARIPOSA DR

MARKIT REMOVE DROP - 28085 PINE AVE

MARKIT REMOVE DROP - 28085 PINE AVE

MARKIT STRAIGHTEN IN-LINE POLE - 20433 PINE MOUNTAIN DR

MARKIT REMOVE DROP - 20378 PINE MOUNTAIN DR

MARKIT REMOVE DROP - 20500 ECHO CT

MARKIT REMOVE DROP - 12475 TANNAHILL DR

MARKIT RELASH TO EXISTING MESSENGER - 12475 TANNAHILL DR

MARKIT RAISE AT&T SERVICE DROP - 29005 STATE HIGHWAY 108

MARKIT REMOVE DROP - 26571 OLD MONO RD

MARKIT REMOVE DROP - 30000 SONORA PASS HWY

MARKIT REMOVE DROP - 30505 OLD STRAWBERRY RD

MARKIT REMOVE DROP - 30555 OLD STRAWBERRY RD

MARKIT REMOVE DROP - 30587 OLD STRAWBERRY RD

MARKIT REMOVE DROP - 28428 RIVER DR

MARKIT REMOVE DROP - 28370 RIVER DR

MARKIT RAISE AT&T SERVICE DROP - LAKESHORE DR

MARKIT REPAIR/REPLACE HARDWARE - 13320 CLIFFTON WAY

MARKIT REMOVE DROP - 20265 PLEASANTVIEW DR

MARKIT RELASH TO EXISTING MESSENGER - 12850 MUELLER DR

MARKIT RELASH TO EXISTING MESSENGER - 12430 PUNCH BOWL RD

MARKIT REMOVE DROP - 226 SUGAR PINE AVE

MARKIT REMOVE DROP - 142 RUSTIC RD

MARKIT REMOVE DROP - 252 MEADOW VIEW RD

MARKIT REMOVE DROP - 224 SUGAR PINE AVE/NOTES: IDLE SERVICE DROP BETWEEN TREES.

MARKIT REMOVE DROP - 132 RUSTIC RD

MARKIT REMOVE DROP - 147 RUSTIC RD

MARKIT REMOVE DROP - 150 RUSTIC RD

MARKIT REMOVE DROP - 254 MEADOW VIEW RD

MARKIT REMOVE DROP - 247 MEADOW VIEW RD

MARKIT REMOVE DROP - 105 PINECREST LAKE RD

MARKIT REMOVE DROP - 9902 VILLARREAL DR

MARKIT RAISE AT&T SERVICE DROP - 5270 ARBOLADA DR

MARKIT REPAIR/REPLACE HARDWARE - 5690 ARBOLADA DR

MARKIT REPAIR/REPLACE HARDWARE - 3601 LADERA WAY

MARKIT REPAIR/REPLACE HARDWARE - 1974 NAVARRO ST

MARKIT REPAIR/REPLACE HARDWARE - 3650 MERCED FALLS RD

MARKIT RAISE AT&T SERVICE DROP - 3373 MERCED FALLS RD

MARKIT REPAIR/REPLACE HARDWARE - 3891 CASTILLO WAY

MARKIT REPAIR/REPLACE HARDWARE - 3996 ARBOLADA DR

MARKIT REPAIR/REPLACE HARDWARE - 3050 MERCED FALLS RD

MARKIT REPAIR/REPLACE HARDWARE - 2626 PEPITO DR

MARKIT RAISE AT&T SERVICE DROP - 2845 RANCHITO DR

MARKIT REMOVE DROP - 2358 ADELFA ST

MARKIT REMOVE DROP - 9662 VILLARREAL DR

MARKIT PLACE/REPLACE DOWN GUY GUARD - 2397 RANCHITO DR

MARKIT PLACE/REPLACE DOWN GUY GUARD - 2403 RANCHITO DR

MARKIT RAISE AT&T SERVICE DROP - 3159 AZUCENA CT

MARKIT REPAIR/REPLACE HARDWARE - 3299 ROSA CT

MARKIT PULL OLD POLE;LEAD TAILS NO;CABLE SWING NO;TRASFER 0 - 3314 GRANITE SPRINGS RD

MARKIT PLACE/REPLACE DOWN GUY GUARD - 2815 GRANITE SPRINGS RD

MARKIT PLACE ANCHOR - 10330 GUSANILLO WAY

MARKIT RAISE AT&T SERVICE DROP - 2844 GRANITE SPRINGS RD

MARKIT REPAIR/REPLACE HARDWARE - 3203 GRANITE SPRINGS RD
MARKIT REPLACE/INSTALL DOWN GUY;TRANSFER AT&T CABLE(S);PULL OLD POLE;LEAD TAILS NO;CABLE SWING YES;TRASFER 2 - 9405 CORONADO DR
MARKIT REPLACE/INSTALL DOWN GUY;TRANSFER AT&T CABLE(S);PULL OLD POLE;LEAD TAILS NO;CABLE SWING NO;TRASFER 2 - 9502 CORONADO DR

MARKIT REMOVE DROP - 9458 CORONADO DR

MARKIT PLACE/REPLACE DOWN GUY GUARD - 9508 CORONADO DR

MARKIT REMOVE DROP - 9637 CORONADO DR

MARKIT PLACE/REPLACE DOWN GUY GUARD - 9546 CORONADO DR

MARKIT REPLACE/INSTALL DOWN GUY - 9480 BANDERILLA DR

MARKIT REPAIR/REPLACE HARDWARE - 13442 MOLINA ST

MARKIT REPAIR/REPLACE HARDWARE - 9476 BANDERILLA DR

MARKIT REMOVE HARDWARE - 9429 BANDERILLA DR

MARKIT REMOVE DROP - 9410 MOJICA WAY

MARKIT RAISE AT&T SERVICE DROP - 9209 JALISCO WAY

MARKIT LOWER OR RAISE EXISTING AT&T DROP - 9194 JALISCO WAY

MARKIT REMOVE DROP - 9184 JALISCO WAY

MARKIT PLACE/REPLACE DOWN GUY GUARD - 9208 BANDERILLA DR

MARKIT TREE TRIMMING REQUIRED - 13979 OLD COULTERVILLE

MARKIT REMOVE DROP - 13979 OLD COULTERVILLE

MARKIT PLACE/REPLACE DOWN GUY GUARD - 10422 BLANCHARD RD

MARKIT REPAIR/REPLACE HARDWARE - 9121 CAPULLO CIR

MARKIT PLACE/REPLACE DOWN GUY GUARD - 10401 GUSANO WAY

MARKIT PLACE/REPLACE DOWN GUY GUARD - 10451 GUSANO WAY

MARKIT RE-TENSION DOWN GUY ALL SIZES - 10447 BLANCHARD RD

MARKIT PLACE ANCHOR - 4542 ENRAMADA DR

MARKIT RE-TENSION DOWN GUY ALL SIZES - 3001 CADENA WAY
MARKIT REPLACE/INSTALL DOWN GUY;TRANSFER AT&T CABLE(S);TRANSFER AT&T DROP(S);PULL OLD POLE;LEAD TAILS NO;CABLE SWING NO;TRASFER 4 - 14770 AZUCENA CT

MARKIT PLACE ANCHOR - 10401 GUSANO WAY

MARKIT STRAIGHTEN IN-LINE POLE - 5587 ENRAMADA DR
MARKIT REPLACE/INSTALL DOWN GUY;TRANSFER AT&T CABLE(S);PULL OLD POLE;LEAD TAILS NO;CABLE SWING NO;TRASFER 2 - 9726 LAREDO ST
MARKIT REPLACE/INSTALL DOWN GUY;TRANSFER AT&T CABLE(S);PULL OLD POLE;LEAD TAILS NO;CABLE SWING NO;TRASFER 2 - 9748 LAREDO ST

MARKIT REPAIR/REPLACE HARDWARE - 2737 ZAMORA ST

MARKIT PLACE/REPLACE DOWN GUY GUARD - 9794 LAREDO ST

MARKIT PLACE/REPLACE DOWN GUY GUARD - 9762 RASTRO WAY

MARKIT REPLACE/INSTALL DOWN GUY - 9762 RASTRO WAY

MARKIT PLACE/REPLACE DOWN GUY GUARD - 9824 BUENA VISTA DR

MARKIT REROUTE EXISTING DROP - 14181 AVENIDA CENTRAL

MARKIT REPAIR/REPLACE HARDWARE - 14226 AVENIDA CENTRAL

MARKIT REPAIR/REPLACE HARDWARE - 14226 AVENIDA CENTRAL

MARKIT PLACE ANCHOR - 14687 AVENIDA CENTRAL

MARKIT REMOVE DROP - 14615 AVENIDA CENTRAL

MARKIT REPAIR/REPLACE HARDWARE - 14505 AVENIDA CENTRAL
MARKIT REPLACE/INSTALL DOWN GUY;TRANSFER AT&T CABLE(S);TRANSFER AT&T DROP(S);PULL OLD POLE;LEAD TAILS NO;CABLE SWING NO;TRASFER 3 - 14365 AVENIDA CENTRAL
MARKIT REPLACE/INSTALL DOWN GUY;TRANSFER AT&T CABLE(S);PULL OLD POLE;LEAD TAILS NO;CABLE SWING NO;TRASFER 2 - 1810 BUENA VISTA DR

MARKIT PLACE/REPLACE DOWN GUY GUARD - 1888 CARMELITA LN

MARKIT REMOVE DROP - 1725 ZARZAMORA ST

MARKIT PLACE/REPLACE DOWN GUY GUARD - 14696 VALVERDE

MARKIT LOWER OR RAISE EXISTING AT&T DROP - 9190 JALISCO WAY
MARKIT REPLACE/INSTALL DOWN GUY;TRANSFER AT&T CABLE(S);TRANSFER AT&T DROP(S);PULL OLD POLE;LEAD TAILS NO;CABLE SWING NO;TRASFER 4 - 1581 CARMELITA LN

MARKIT REPAIR/REPLACE HARDWARE - 1770 MERCED FALLS RD
MARKIT REPLACE/INSTALL OVERHEAD GUY;TRANSFER AT&T CABLE(S);PULL OLD POLE;LEAD TAILS NO;CABLE SWING NO;TRASFER 3 - 3275 GRILLO DR

MARKIT PULL OLD POLE;LEAD TAILS NO;CABLE SWING NO;TRASFER 0 - 4876 ENRAMADA DR

MARKIT PLACE ANCHOR - 10284 GUSANILLO WAY

MARKIT RELASH EXISTING CABLES - 10288 GUSANILLO WAY

MARKIT PLACE ANCHOR - 10442 CHAPULIN WAY

MARKIT REPAIR/REPLACE HARDWARE - 3343 JASMIN CT

MARKIT TRANSFER AT&T CABLE(S);TRANSFER AT&T DROP(S);PULL OLD POLE;LEAD TAILS NO;CABLE SWING NO;TRASFER 2 - 3285 GRILLO DR

MARKIT PULL OLD POLE;LEAD TAILS NO;CABLE SWING NO;TRASFER 0 - 10304 NARCISO WAY

MARKIT PLACE/REPLACE DOWN GUY GUARD - 2847 ZARZAMORA ST

MARKIT PLACE/REPLACE DOWN GUY GUARD - 2911 ZARZAMORA ST

MARKIT PLACE/REPLACE DOWN GUY GUARD - 2928 ZARZAMORA ST

MARKIT RAISE AT&T SERVICE DROP - 4649 MADRESELVA ST
MARKIT REPLACE/INSTALL DOWN GUY;TRANSFER AT&T CABLE(S);PULL OLD POLE;LEAD TAILS NO;CABLE SWING NO;TRASFER 3 - 9919 BANDERILLA DR

MARKIT REPAIR/REPLACE HARDWARE - 9989 ALAMO DR
MARKIT REPLACE/INSTALL DOWN GUY;TRANSFER AT&T CABLE(S);PULL OLD POLE;LEAD TAILS NO;CABLE SWING NO;TRASFER 2 - 10004 ALAMO DR
MARKIT REPLACE/INSTALL DOWN GUY;TRANSFER AT&T CABLE(S);PULL OLD POLE;LEAD TAILS NO;CABLE SWING NO;TRASFER 2 - 10021 ALAMO DR

MARKIT REPAIR/REPLACE HARDWARE - 2095 NAVARRO ST

MARKIT PULL OLD POLE;LEAD TAILS NO;CABLE SWING NO;TRASFER 0 - 2336 PEPITO DR
MARKIT TRANSFER AT&T CABLE(S);PULL OLD POLE;LEAD TAILS NO;CABLE SWING NO;TRASFER 2 - 14406 POTRERO WAY

MARKIT REPAIR/REPLACE HARDWARE - 3111 MERCED FALLS RD

MARKIT RAISE AT&T SERVICE DROP - 3280 STATE HIGHWAY 132

MARKIT REPAIR/REPLACE HARDWARE - 3819 BONDS FLAT RD

MARKIT PLACE/REPLACE DOWN GUY GUARD - 5261 BONDS FLAT RD

MARKIT PLACE/REPLACE DOWN GUY GUARD - 35 BONDS FLAT RD
MARKIT REPLACE/INSTALL DOWN GUY;TRANSFER AT&T CABLE(S);TRANSFER AT&T DROP(S);PULL OLD POLE;LEAD TAILS NO;CABLE SWING YES;TRASFER 3 - 10378 JALAPA WAY

MARKIT REPAIR/REPLACE HARDWARE - 10421 JALAPA WAY

MARKIT REMOVE DROP - 2621 SPELT

MARKIT STRAIGHTEN IN-LINE POLE - 10181 BONDS FLAT RD

MARKIT REPAIR/REPLACE HARDWARE - 10372 LIRO CT

MARKIT RAISE AT&T SERVICE DROP - 10367 TULIPAN WAY

MARKIT REPAIR/REPLACE HARDWARE - 10368 TULIPAN WAY

MARKIT PLACE ANCHOR - 10406 CHAPULIN WAY

MARKIT REMOVE DROP - 14600 AZUCENA CT
MARKIT REMOVE ANCHOR;TRANSFER AT&T CABLE(S);TRANSFER AT&T TERMINAL(S);PULL OLD POLE;LEAD TAILS NO;CABLE SWING NO;TRASFER 3 - 3148 AZUCENA CT

MARKIT INSTALL HARDWARE - 3148 AZUCENA CT

MARKIT REPLACE/INSTALL OVERHEAD GUY - 12086 BONDS FLAT RD
MARKIT REPLACE/INSTALL DOWN GUY;TRANSFER AT&T CABLE(S);PULL OLD POLE;LEAD TAILS NO;CABLE SWING YES;TRASFER 2 - 2403 RANCHITO DR

MARKIT PLACE/REPLACE DOWN GUY GUARD - 2320 RANCHITO DR

MARKIT REPAIR/REPLACE HARDWARE - 9591 CARRILLO WAY

MARKIT PLACE/REPLACE DOWN GUY GUARD - 9582 PANCHITO WAY

MARKIT REMOVE DROP - 9893 ALAMO DR
MARKIT REPLACE/INSTALL DOWN GUY;TRANSFER AT&T CABLE(S);TRANSFER AT&T DROP(S);PULL OLD POLE;LEAD TAILS NO;CABLE SWING NO;TRASFER 2 - 9955 ALAMO DR

MARKIT PLACE/REPLACE DOWN GUY GUARD - 9955 ALAMO DR
MARKIT INTRUSIVE INSPECTION REQUIRED - 9860 VILLARREAL DR/NOTES: PGE POLE HAS EXCESSIVE WOODPECKER DAMAGE
MARKIT TRANSFER AT&T CABLE(S);TRANSFER AT&T DROP(S);PULL OLD POLE;LEAD TAILS NO;CABLE SWING NO;TRASFER 2 - 9846 ALAMO DR

MARKIT RELASH TO EXISTING MESSENGER - 10004 ALAMO DR

MARKIT REPAIR/REPLACE HARDWARE - 10004 ALAMO DR
MARKIT REPLACE/INSTALL DOWN GUY;TRANSFER AT&T CABLE(S);PULL OLD POLE;LEAD TAILS NO;CABLE SWING NO;TRASFER 2 - 9989 ALAMO DR

MARKIT REMOVE DROP - 9714 PICADERO WAY

MARKIT PLACE/REPLACE DOWN GUY GUARD - 9618 GAZA WAY

MARKIT REPAIR/REPLACE HARDWARE - 2265 GOLFITO WAY

MARKIT REMOVE DROP - 2265 GOLFITO WAY

MARKIT REPAIR/REPLACE HARDWARE - 2265 GOLFITO WAY
MARKIT REPLACE/INSTALL DOWN GUY;TRANSFER AT&T CABLE(S);PULL OLD POLE;LEAD TAILS NO;CABLE SWING NO;TRASFER 3 - 9618 GAZA WAY
MARKIT REPLACE/INSTALL DOWN GUY;TRANSFER AT&T CABLE(S);TRANSFER AT&T DROP(S);PULL OLD POLE;LEAD TAILS NO;CABLE SWING YES;TRASFER 3 - 2265 GOLFITO WAY

MARKIT REMOVE DROP - 9759 BANDERILLA DR

MARKIT REMOVE DROP - 9703 PARAISO BLVD

MARKIT PLACE/REPLACE DOWN GUY GUARD - 9776 CARRIZO WAY

MARKIT RELASH TO EXISTING MESSENGER - 9811 CARRIZO WAY
MARKIT REPLACE/INSTALL DOWN GUY;TRANSFER AT&T CABLE(S);PULL OLD POLE;LEAD TAILS NO;CABLE SWING NO;TRASFER 2 - 9897 VILLARREAL DR

MARKIT REMOVE DROP - 11012 STOUT LN

MARKIT REMOVE DROP - 4406 PENON BLANCO RD

MARKIT REMOVE DROP - 10457 OAK RIDGE CT

MARKIT REMOVE DROP - 4145 PENON BLANCO RD

MARKIT REMOVE DROP - 5536 GREELEY HILL RD

MARKIT REMOVE DROP - 4902 STATE HIGHWAY 132

MARKIT REMOVE DROP - 9754 REDBUD LN

MARKIT REMOVE DROP - 5000 TRAILER CT

MARKIT REMOVE DROP - 10368 DEXTER LN

MARKIT RAISE AT&T SERVICE DROP - 9667 WAGNER RD

MARKIT REMOVE DROP - 10162 HOLTZEL RD

MARKIT REPAIR/REPLACE HARDWARE - 9748 REDBUD LN

MARKIT PLACE/REPLACE DOWN GUY GUARD - 10153-1015 PINEY CREEK RD

MARKIT RE-TENSION DOWN GUY ALL SIZES - 10134 HOLTZEL RD

MARKIT PLACE ANCHOR - 3391 GRANITE SPRINGS RD

MARKIT PLACE ANCHOR - 10134 HOLTZEL RD

MARKIT PLACE ANCHOR - 9981 PINEY CREEK RD

MARKIT PLACE ANCHOR - 9998 ERNST RD

MARKIT PLACE ANCHOR - 11046 ERNST RD

MARKIT REPAIR/REPLACE HARDWARE - 10341 DEXTER LN

MARKIT REPAIR/REPLACE HARDWARE - 10736 PINE LAKE DR

MARKIT REPAIR/REPLACE HARDWARE - 6364 GREELEY HILL RD

MARKIT REPAIR/REPLACE HARDWARE - 10240 HOLTZEL RD

MARKIT REPAIR/REPLACE HARDWARE - 10236 HOLTZEL RD

MARKIT REPAIR/REPLACE HARDWARE - 9718 TEXAS HILL RD

MARKIT RELASH EXISTING CABLES - 10147 HOLTZEL RD

MARKIT TREE TRIMMING REQUIRED - 15265 STATE HIGHWAY 108

MARKIT PLACE/REPLACE DOWN GUY GUARD - 8553 MONTEZUMA RD

MARKIT REPAIR/REPLACE HARDWARE - 16450 STATE HIGHWAY 108

MARKIT REMOVE DROP - 16900 CHICKEN RANCH RD

MARKIT PLACE ANCHOR - 16915 STATE HIGHWAY 108

MARKIT TREE TRIMMING REQUIRED - OLD MELONES DAM RD

MARKIT TREE TRIMMING REQUIRED - OLD MELONES DAM RD

MARKIT REMOVE DROP - 9994 WASHINGTON ST

MARKIT REPAIR/REPLACE HARDWARE - 17121 JENI CT

MARKIT TREE TRIMMING REQUIRED - 17405 JACKSONVILLE RD

MARKIT TREE TRIMMING REQUIRED - 10716 ALGERINE RD

MARKIT REMOVE DROP - 9300 MONTEZUMA RD/NOTES: SERVICE DROP LINE

MARKIT RAISE AT&T SERVICE DROP - 9300 MONTEZUMA RD/NOTES: SERVICE DROP LINE

MARKIT REPLACE/INSTALL DOWN GUY - 10633 CAMPO SECO RD

MARKIT REMOVE DROP - 17546 JACKSONVILLE RD

MARKIT REPAIR/REPLACE HARDWARE - 9879 MAIN ST

MARKIT TREE TRIMMING REQUIRED - 11858 JUSTIN CT

MARKIT REPAIR/REPLACE HARDWARE - 11870 JUSTIN CT

MARKIT TREE TRIMMING REQUIRED - 15507 PEORIA FLAT RD

MARKIT REMOVE DROP - 18545 RAILBED RD

MARKIT VEGETATION REMOVAL REQUIRED - 15109 STATE HIGHWAY 108

MARKIT TREE TRIMMING REQUIRED - 13611 RED HILLS RD

MARKIT TREE TRIMMING REQUIRED - 13773 RED HILLS RD

MARKIT TREE TRIMMING REQUIRED - 10144 BELL MOONEY RD

MARKIT REMOVE DROP - 10200 BELL MOONEY RD

MARKIT TREE TRIMMING REQUIRED - 16578 DUTCH MINE RD

MARKIT TREE TRIMMING REQUIRED - 16578 DUTCH MINE RD

MARKIT RAISE AT&T SERVICE DROP - 10259 ROJO LN/NOTES: SERVICE DROP LINE

MARKIT TREE TRIMMING REQUIRED - 10367 SHAWMUT RD

MARKIT PLACE CROSS/GUARD ARM - 10484 SHAWMUT RD

MARKIT REPAIR/REPLACE HARDWARE - 10177 PULPIT ROCK RD

MARKIT RELASH EXISTING CABLES - 10177 PULPIT ROCK RD

MARKIT REMOVE DROP - 18550 RAWHIDE RD

MARKIT REMOVE DROP - 18790 RAILBED RD

MARKIT REMOVE DROP - 9870 PULPIT ROCK RD

MARKIT REMOVE DROP - 13706 TWIST RD

MARKIT TREE TRIMMING REQUIRED - 13808 PARK AVE

MARKIT TREE TRIMMING REQUIRED - 14037 JACKSONVILLE RD

MARKIT TREE TRIMMING REQUIRED - 14069 JACKSONVILLE RD

MARKIT PLACE/REPLACE DOWN GUY GUARD - 10185 MONTEZUMA RD

MARKIT PLACE ANCHOR - 9300 MONTEZUMA RD

MARKIT PLACE/REPLACE DOWN GUY GUARD - 15540 JUMPER MINE RD

MARKIT TREE TRIMMING REQUIRED - 17671 SECO ST

MARKIT TREE TRIMMING REQUIRED - 17701 SECO ST

MARKIT TREE TRIMMING REQUIRED - 17992 SECO ST

MARKIT REMOVE DROP - 13323 RED HILLS RD

MARKIT TREE TRIMMING REQUIRED - 14145 PARK AVE

MARKIT TREE TRIMMING REQUIRED - 14200 LULU MINE RD

MARKIT TREE TRIMMING REQUIRED - 14012 PARK AVE

MARKIT REPAIR/REPLACE HARDWARE - 14056 PARK AVE

MARKIT TREE TRIMMING REQUIRED - 14200 LULU MINE RD

MARKIT TREE TRIMMING REQUIRED - 14145 PARK AVE

MARKIT TREE TRIMMING REQUIRED - 13708 TWIST RD

MARKIT REPAIR/REPLACE HARDWARE - 17450 STATE HIGHWAY 108

MARKIT REPAIR/REPLACE HARDWARE - 17851 STATE HIGHWAY 108

MARKIT TREE TRIMMING REQUIRED - 18084 SECO ST

MARKIT LOWER OR RAISE EXISTING CABLE - 18595 5TH AVE

MARKIT TREE TRIMMING REQUIRED - 18650 STATE HIGHWAY 108

MARKIT TREE TRIMMING REQUIRED - 18306 SECO ST

MARKIT TREE TRIMMING REQUIRED - 18155 GOLDEN OAKS DR

MARKIT TREE TRIMMING REQUIRED - 18131 POND VIEW CT

MARKIT TREE TRIMMING REQUIRED - 18155 GOLDEN OAKS DR

MARKIT TREE TRIMMING REQUIRED - 13812 PARK AVE

MARKIT TREE TRIMMING REQUIRED - 14001 PARK AVE

MARKIT TREE TRIMMING REQUIRED - 13900 TWIST RD

MARKIT REPAIR/REPLACE HARDWARE - 13901 PARK AVE

MARKIT TREE TRIMMING REQUIRED - 13901 PARK AVE

MARKIT REMOVE DROP - 8155 DANTE DR

MARKIT REPAIR/REPLACE HARDWARE - 13051 HARNEY DR

MARKIT REMOVE DROP - 12340 MAMMOTH MINE RD

MARKIT REMOVE DROP - 12808 MAMMOTH MINE RD

MARKIT TREE TRIMMING REQUIRED - 12750 MAMMOTH MINE RD

MARKIT REPAIR/REPLACE HARDWARE - 17984 HARVARD MINE RD

MARKIT REMOVE DROP - 17428 HARVARD MINE RD

MARKIT REMOVE DROP - 17968 HIGH SCHOOL RD

MARKIT REMOVE DROP - 16971 CHICKEN RANCH RD

MARKIT REMOVE DROP - 17262 JEANESE DR

MARKIT PLACE ANCHOR - 17330 HIGH SCHOOL RD

MARKIT REMOVE DROP - 8975 STATE HIGHWAY 120

MARKIT TREE TRIMMING REQUIRED - 8975 STATE HIGHWAY 120

MARKIT REMOVE DROP - 14333 PERRICONE RD

MARKIT REPLACE/INSTALL DOWN GUY - 17964 SECO ST

MARKIT REMOVE DROP - 18028 SECO ST

MARKIT RELASH EXISTING CABLES - 17868 SECO ST

MARKIT REMOVE DROP - 17843 SECO ST

MARKIT TREE TRIMMING REQUIRED - 18110 6TH AVE

MARKIT TREE TRIMMING REQUIRED - 18103 7TH AVE

MARKIT TREE TRIMMING REQUIRED - 18136 8TH AVE

MARKIT REMOVE DROP - 13267 RED HILLS RD/NOTES: SERVICE DROP LINE

MARKIT TREE TRIMMING REQUIRED - 16299 JACKSONVILLE RD

MARKIT TREE TRIMMING REQUIRED - 16138 JACKSONVILLE RD

MARKIT TREE TRIMMING REQUIRED - 16138 JACKSONVILLE RD

MARKIT REPAIR/REPLACE HARDWARE - 9489 STATE HWY 120

MARKIT REMOVE DROP - 9045 FRIENDSHIP HILL RD

MARKIT LOWER OR RAISE EXISTING AT&T CABLE - 9090 FRIENDSHIP HILL RD

MARKIT TREE TRIMMING REQUIRED - 9060 FRIENDSHIP HILL RD

MARKIT TREE TRIMMING REQUIRED - 13001 JACKSONVILLE RD

MARKIT TREE TRIMMING REQUIRED - 12651 JACKSONVILLE RD

MARKIT TREE TRIMMING REQUIRED - 10602 7TH ST

MARKIT REPAIR/REPLACE HARDWARE - 13155 KANAKA DR

MARKIT REMOVE DROP - 18427 5TH AVE

MARKIT TREE TRIMMING REQUIRED - 18427 5TH AVE

MARKIT TREE TRIMMING REQUIRED - 18385 5TH AVE

MARKIT TREE TRIMMING REQUIRED - 18355 5TH AVE

MARKIT REMOVE DROP - 18427 5TH AVE

MARKIT TREE TRIMMING REQUIRED - 10607 8TH AVE

MARKIT REMOVE DROP - 18135 8TH AVE

MARKIT TREE TRIMMING REQUIRED - 18119 7TH AVE

MARKIT TREE TRIMMING REQUIRED - 18141 7TH AVE

MARKIT TREE TRIMMING REQUIRED - 19601 JAMESTOWN RD

MARKIT TREE TRIMMING REQUIRED - 18394 STATE HIGHWAY 108

MARKIT TREE TRIMMING REQUIRED - 18985 OLD BRIDGE RD

MARKIT TREE TRIMMING REQUIRED - 10783 GOLF LINKS RD

MARKIT VEGETATION REMOVAL REQUIRED - 18725 STATE HIGHWAY 108

MARKIT REMOVE DROP - 18464 5TH AVE

MARKIT TREE TRIMMING REQUIRED - 15700 EGAN RD

MARKIT TREE TRIMMING REQUIRED - 15700 EGAN RD

MARKIT REMOVE DROP - 16760 CHICKEN RANCH RD

MARKIT TREE TRIMMING REQUIRED - 16760 CHICKEN RANCH RD

MARKIT RAISE AT&T SERVICE DROP - 16755 CHICKEN RANCH RD

MARKIT REMOVE DROP - 16233 STAMP MILL LOOP RD

MARKIT TREE TRIMMING REQUIRED - 11025 GOLF LINKS RD

MARKIT RELASH TO EXISTING MESSENGER - 18725 STATE HIGHWAY 108

MARKIT TREE TRIMMING REQUIRED - 10767 GOLF LINKS RD

MARKIT TREE TRIMMING REQUIRED - 10819 GOLF LINKS RD

MARKIT TREE TRIMMING REQUIRED - 10970 GOLF LINKS RD

MARKIT TREE TRIMMING REQUIRED - 10970 GOLF LINKS RD

MARKIT TREE TRIMMING REQUIRED - 10833 GOLF LINKS RD

MARKIT TREE TRIMMING REQUIRED - 18730 STATE HIGHWAY 108

MARKIT TREE TRIMMING REQUIRED - 18760 CHABROULLIAN LN

MARKIT REMOVE DROP - 18760 CHABROULLIAN LN

MARKIT TREE TRIMMING REQUIRED - 18760 CHABROULLIAN LN

MARKIT TREE TRIMMING REQUIRED - 18720 STATE HIGHWAY 108

MARKIT TREE TRIMMING REQUIRED - 18188 SECO ST

MARKIT TREE TRIMMING REQUIRED - 9785 PEPPERMINT CIRCLE

MARKIT REPAIR/REPLACE HARDWARE - 10089 PEPPERMINT CIRCLE

MARKIT TREE TRIMMING REQUIRED - 9995 PEPPERMINT CIR

MARKIT TREE TRIMMING REQUIRED - 10101 PEPPERMINT CIRCLE

MARKIT TREE TRIMMING REQUIRED - 10125 PEPPERMINT CIR

MARKIT TREE TRIMMING REQUIRED - 10647 RESEVOIR RD

MARKIT TREE TRIMMING REQUIRED - 10647 RESEVOIR RD

MARKIT PULL OLD POLE;LEAD TAILS NO;CABLE SWING NO;TRASFER 0 - 14337 SIMS RD

MARKIT PULL OLD POLE;LEAD TAILS NO;CABLE SWING NO;TRASFER 0 - 14355 SIMS RD

MARKIT PULL OLD POLE;LEAD TAILS NO;CABLE SWING NO;TRASFER 0 - 14387 SIMS RD

MARKIT PULL OLD POLE;LEAD TAILS NO;CABLE SWING NO;TRASFER 0 - 14431 SIMS RD

MARKIT PULL OLD POLE;LEAD TAILS NO;CABLE SWING NO;TRASFER 0 - 14301 SIMS RD

MARKIT PULL OLD POLE;LEAD TAILS NO;CABLE SWING NO;TRASFER 0 - 14301 SIMS RD

MARKIT PULL OLD POLE;LEAD TAILS NO;CABLE SWING NO;TRASFER 0 - 14301 SIMS RD

MARKIT PULL OLD POLE;LEAD TAILS NO;CABLE SWING NO;TRASFER 0 - 14489 SIMS RD

MARKIT REMOVE DROP - 5090 OBYRNES FERRY RD

MARKIT PULL OLD POLE;LEAD TAILS NO;CABLE SWING NO;TRASFER 0 - 14493 SIMS RD

MARKIT TREE TRIMMING REQUIRED - 10670 WIGWAM RD

MARKIT TREE TRIMMING REQUIRED - 18234 4TH AVE

MARKIT REPAIR/REPLACE HARDWARE - 8800 MONTEZUMA RD

MARKIT TREE TRIMMING REQUIRED - 18144 SECO ST

MARKIT TREE TRIMMING REQUIRED - 10678 WIGWAM RD

MARKIT TREE TRIMMING REQUIRED - 18535 5TH AVE

MARKIT TREE TRIMMING REQUIRED - 18671 STATE HIGHWAY 108

MARKIT REMOVE DROP - 8500 MONTEZUMA RD/NOTES: SERVICE DROP LINE

MARKIT REPAIR/REPLACE HARDWARE - 10410 WILLOW ST

MARKIT TREE TRIMMING REQUIRED - 10799 WIGWAM RD

MARKIT TREE TRIMMING REQUIRED - 18671 STATE HIGHWAY 108

MARKIT REMOVE DROP - 10760 WIGWAM RD

MARKIT TREE TRIMMING REQUIRED - 18650 STATE HIGHWAY 108

MARKIT RAISE AT&T SERVICE DROP - 10636 7TH ST

MARKIT REMOVE DROP - 18241 9TH AVE

MARKIT TREE TRIMMING REQUIRED - 18241 9TH AVE

MARKIT REPLACE/INSTALL DOWN GUY - 18241 9TH AVE

MARKIT REMOVE DROP - 18300 9TH AVE

MARKIT REPAIR/REPLACE HARDWARE - 18230 9TH AVE

MARKIT REMOVE DROP - 18245 9TH AVE

MARKIT TREE TRIMMING REQUIRED - 10559 JIM BRADY RD

MARKIT REMOVE DROP - 10559 JIM BRADY RD

MARKIT TREE TRIMMING REQUIRED - 10579 JIM BRADY RD

Vegetation 1 - Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

MAINLINE DOWN PARALLEL ROADWAY

MARKIT Tree down on cable. Hazardous condition. Tree and cable over busy street.

MARKIT REMOVE DROP - 22090 FEATHER RIVER DR

MARKIT REMOVE DROP - 20870 CAYLOR DR

MARKIT REMOVE DROP - 21803 RUSSIAN RIVER DR

MARKIT REMOVE DROP - 22722 PIPER CT

MARKIT REMOVE DROP - 10620 N AIRPORT RD

MARKIT REMOVE DROP - 10634 N AIRPORT RD

MARKIT REPAIR/REPLACE HARDWARE - 22416 LAKEVIEW HTS

MARKIT REPAIR/REPLACE HARDWARE - 22422 BENNETT RD

MARKIT TREE TRIMMING REQUIRED - 22466 CHURCH LN

MARKIT REMOVE DROP - 10706 N AIRPORT RD

MARKIT REMOVE DROP - 23020 KUMQUAT CT

MARKIT REMOVE DROP - 10080 N AIRPORT RD

MARKIT REPAIR/REPLACE HARDWARE - 634 LYONS ST

MARKIT RAISE AT&T SERVICE DROP - 556 LYONS ST

MARKIT REPAIR/REPLACE HARDWARE - 18356 LAMBERT LAKE RD

MARKIT REMOVE DROP - 10242 HIGHWAY 49

MARKIT PLACE ANCHOR - 9801 HIGHWAY 49

MARKIT REPAIR/REPLACE HARDWARE - 13545 MONO WAY

MARKIT REPAIR/REPLACE HARDWARE - 17215 MURPHY RD

MARKIT REMOVE DROP - 17901 OLD WARDS FERRY RD

MARKIT REPLACE/INSTALL DOWN GUY - 9186 HIGHWAY 49

MARKIT REPAIR/REPLACE HARDWARE - 23876 ITALIAN BAR RD

MARKIT REPAIR/REPLACE HARDWARE - 18333 TOYON WAY

MARKIT REMOVE DROP - 11142 STATE ST

MARKIT REPAIR/REPLACE HARDWARE - 18383 CORTE DEL MONTANA

MARKIT REMOVE DROP - 12004 YANKEE HILL RD

MARKIT REPAIR/REPLACE HARDWARE - 11500 ROCHER CT

MARKIT REMOVE DROP - 22411 KENNEBEC LN

MARKIT REPAIR/REPLACE HARDWARE - 22554 UPPER QUAIL MINE RD

MARKIT REPAIR/REPLACE HARDWARE - 11480 CORK OAK LN

MARKIT REPAIR/REPLACE HARDWARE - 11480 CORK OAK LN

MARKIT REMOVE DROP - 22729 UPPER QUAIL MINE RD

MARKIT INSTALL HARDWARE - 22733 LEDGE LN

MARKIT REPAIR/REPLACE HARDWARE - 22865 NORTHRUP CT

MARKIT REMOVE DROP - 22525 KENNEBEC LN

MARKIT REMOVE DROP - 22734 LEDGE LN

MARKIT REMOVE DROP - 11784 YANKEE HILL RD

MARKIT REMOVE DROP - 18360 WARDS FERRY RD

MARKIT RELASH EXISTING CABLES - 12828 MONO WAY

MARKIT RAISE AT&T SERVICE DROP - 13744 BORDEN RD

MARKIT REMOVE DROP - 18978 HESS AVE

MARKIT STRAIGHTEN IN-LINE POLE - 842 MONO WAY

MARKIT REPAIR/REPLACE HARDWARE - 665 S WASHINGTON ST

MARKIT REPAIR/REPLACE HARDWARE - 18008 VIA SERENA RD

MARKIT REPAIR/REPLACE HARDWARE - 17945 VIA SERENA RD

MARKIT TREE TRIMMING REQUIRED - 17855 VIA SERENA RD

MARKIT REPAIR/REPLACE HARDWARE - 17890 VIA SERENA RD

MARKIT REMOVE DROP - 17836 VIA SERENA RD

MARKIT REPAIR/REPLACE HARDWARE - 17836 VIA SERENA RD

MARKIT REPAIR/REPLACE HARDWARE - 17836 VIA SERENA RD

MARKIT TREE TRIMMING REQUIRED - 17836 VIA SERENA RD

MARKIT REPAIR/REPLACE HARDWARE - 18213 VIA SERENA RD

MARKIT REPAIR/REPLACE HARDWARE - 18320 AVENIDA BONITA

MARKIT REPAIR/REPLACE HARDWARE - 18306 CORTE DEL MONTANA

MARKIT REPAIR/REPLACE HARDWARE - 18325 AVENIDA BONITA N

MARKIT REPAIR/REPLACE HARDWARE - 18325 AVENIDA BONITA N

MARKIT REPAIR/REPLACE HARDWARE - 18715 MILL VILLA RD

MARKIT REMOVE DROP - 11814 ELLINWOOD ACRES RD

MARKIT REPAIR/REPLACE HARDWARE - 18395 CORTE DEL MONTANA

MARKIT REPAIR/REPLACE HARDWARE - 17746 LIME KILN RD

MARKIT REMOVE DROP - 22624 SAWMILL FLAT RD

MARKIT REMOVE DROP - 21911 SAWMILL FLAT RD

MARKIT REPLACE/INSTALL DOWN GUY - 21892 SAWMILL FLAT RD

MARKIT REMOVE DROP - 22010 SAWMILL FLAT RD

MARKIT REMOVE DROP - 12662 GUNSIGHT RD W

MARKIT REPAIR/REPLACE HARDWARE - 10886 RACETRACK RD

MARKIT REPAIR/REPLACE HARDWARE - 18881 LAMBERT LAKE RD

MARKIT REPAIR/REPLACE HARDWARE - 14160 KELLY LOOP

MARKIT REMOVE DROP - 18320 WARDS FERRY RD

MARKIT REPAIR/REPLACE HARDWARE - 18446 WARDS FERRY RD

MARKIT REPAIR/REPLACE HARDWARE - 20132 RAWHIDE RD

MARKIT REPAIR/REPLACE HARDWARE - 20023 RAWHIDE RD

MARKIT REPAIR/REPLACE HARDWARE - 19976 RAWHIDE RD

MARKIT REPAIR/REPLACE HARDWARE - 19845 RAWHIDE RD

MARKIT TREE TRIMMING REQUIRED - 20315 TUTTLETOWN RD

MARKIT REPAIR/REPLACE HARDWARE - 21259 PASEO DE LOS PORTALES RD

MARKIT REPAIR/REPLACE HARDWARE - 15385 CAMINO DEL PARQUE S

MARKIT REPAIR/REPLACE HARDWARE - 15410 CAMINO DEL PARQUE RD S

MARKIT REMOVE DROP - 20523 JACKASS HILL RD

MARKIT RAISE AT&T SERVICE DROP - 20694 LOWER HILLVIEW DR

MARKIT REPAIR/REPLACE HARDWARE - 14356 SANDY CT

MARKIT REPAIR/REPLACE HARDWARE - 20760 LOWER HILLVIEW DR

MARKIT REPAIR/REPLACE HARDWARE - 20557 LOWER HILLVIEW DR

MARKIT STRAIGHTEN IN-LINE POLE - 20073 PHOENIX LAKE RD

MARKIT RAISE AT&T SERVICE DROP - 20747 LOWER HILLVIEW DR

MARKIT REPAIR/REPLACE HARDWARE - 20057 PHOENIX LAKE RD

MARKIT STRAIGHTEN IN-LINE POLE - 20405 PHOENIX LAKE RD

MARKIT REPAIR/REPLACE HARDWARE - 20240 SOMMETTE DR

MARKIT REPAIR/REPLACE HARDWARE - 19993 SOMMETTE DR

MARKIT REPAIR/REPLACE HARDWARE - 20045 SOMMETTE DR

MARKIT RAISE AT&T SERVICE DROP - 20320 SOMMETTE DR

MARKIT REPAIR/REPLACE HARDWARE - 20228 SOMMETTE DR

MARKIT RELASH EXISTING CABLES - 18290 WARDS FERRY RD

MARKIT RAISE AT&T MAINLINE CABLE - 32 TRUCKENMILLER RD

MARKIT RAISE AT&T SERVICE DROP - 12912 MOUNTAIN VIEW RD

MARKIT REPAIR/REPLACE HARDWARE - 20550 TUTTLETOWN RD

MARKIT REPAIR/REPLACE HARDWARE - 18033 PLAZA ORIENTE RD

MARKIT REPAIR/REPLACE HARDWARE - 17865 VIA SERENA RD

MARKIT RAISE AT&T SERVICE DROP - 22979 DOLLY LN

MARKIT REPAIR/REPLACE HARDWARE - 17775 PLAZA DEL SUR RD

MARKIT STRAIGHTEN IN-LINE POLE - 23055 DOLLY LN

MARKIT REMOVE DROP - 17791 LIME ROCK DR

MARKIT REMOVE DROP - 18007 VIA SERENA RD

MARKIT REPAIR/REPLACE HARDWARE - 18037 LIME ROCK DR

MARKIT REMOVE DROP - 20590 N SUNSHINE RD

MARKIT RELASH EXISTING CABLES - 20590 N SUNSHINE RD

MARKIT REMOVE DROP - 15306 CAMINO DEL PARQUE S

MARKIT REPAIR/REPLACE HARDWARE - 15306 CAMINO DEL PARQUE S

MARKIT REPAIR/REPLACE HARDWARE - 15362 CAMINO DEL PARQUE RD N

MARKIT REPAIR/REPLACE HARDWARE - 15290 CAMINO DEL PARQUE RD N

MARKIT REPAIR/REPLACE HARDWARE - 15397 EL VENADA TRAIL

MARKIT REPAIR/REPLACE HARDWARE - 20421 BROOK DR

MARKIT REPAIR/REPLACE HARDWARE - 20736 LOWER HILLVIEW DR

MARKIT REPAIR/REPLACE HARDWARE - 14398 SANDY CT

MARKIT REPAIR/REPLACE HARDWARE - 20668 LOWER HILLVIEW DR

MARKIT REPAIR/REPLACE HARDWARE - 20677 LOWER HILLVIEW DR

MARKIT REPAIR/REPLACE HARDWARE - 20287 BROOK DR

MARKIT REPAIR/REPLACE HARDWARE - 20799 LOWER HILLVIEW DR

MARKIT REPAIR/REPLACE HARDWARE - 20437 SILVER DAWN DR

MARKIT REPAIR/REPLACE HARDWARE - 20463 SILVER DAWN DR

MARKIT REPAIR/REPLACE HARDWARE - 20557 SILVER DAWN DR

MARKIT REPAIR/REPLACE HARDWARE - 20630 SILVER DAWN DR

MARKIT STRAIGHTEN IN-LINE POLE - 142 TRUCKENMILLER RD

MARKIT RAISE AT&T SERVICE DROP - 19673 CEDAR RD

MARKIT RAISE AT&T SERVICE DROP - 19682 PINE RD

MARKIT REPAIR/REPLACE HARDWARE - 241 HOSPITAL RD

MARKIT REPLACE/INSTALL OVERHEAD GUY - 12920 MOUNTAIN VIEW RD

MARKIT REPAIR/REPLACE HARDWARE - 18033 PLAZA ORIENTE RD

MARKIT REPAIR/REPLACE HARDWARE - 18161 CALLE OESTE RD

MARKIT REPAIR/REPLACE HARDWARE - 17847 PLAZA DEL SUR RD

MARKIT REPAIR/REPLACE HARDWARE - 17941 AVENIDA BONITA

MARKIT TREE TRIMMING REQUIRED - 18536 LIME KILN RD

MARKIT REMOVE DROP - 9514 RIMROCK RD

MARKIT REPAIR/REPLACE HARDWARE - 21886 PASEO DE LOS PORTALES RD

MARKIT REPAIR/REPLACE HARDWARE - 16806 CHAUNIN RD

MARKIT REPAIR/REPLACE HARDWARE - 22135 PASEO DE LOS PORTALES RD

MARKIT RAISE AT&T MAINLINE CABLE - 21082 OMAN DR

MARKIT REPAIR/REPLACE HARDWARE - 20405 PHOENIX LAKE RD

MARKIT REPAIR/REPLACE HARDWARE - 20747 LOWER HILLVIEW DR

MARKIT STRAIGHTEN IN-LINE POLE - 20495 BROOK DR

MARKIT RAISE AT&T SERVICE DROP - 14405 EXPEDITION DR

MARKIT RAISE AT&T SERVICE DROP - 20480 MIDLAND DR

MARKIT REPAIR/REPLACE HARDWARE - 20175 SOMMETTE DR

MARKIT REPAIR/REPLACE HARDWARE - 20411 MIDLAND DR

MARKIT RAISE AT&T SERVICE DROP - 17965 TINNIN RD

MARKIT REPAIR/REPLACE HARDWARE - 17965 TINNIN RD

MARKIT REPAIR/REPLACE HARDWARE - 17452 UPLANDS DR

MARKIT REPAIR/REPLACE HARDWARE - 17637 UPLANDS DR

MARKIT RAISE AT&T SERVICE DROP - 13119 SANGUINETTI RD

MARKIT REMOVE DROP - 9461 RIMROCK RD

MARKIT REPAIR/REPLACE HARDWARE - 12999 SANGUINETTI RD

MARKIT RAISE AT&T SERVICE DROP - 12999 SANGUINETTI RD

MARKIT REMOVE DROP - 19573 RAWHIDE RD

MARKIT REMOVE DROP - 74 N STEWART ST

MARKIT REMOVE DROP - 18395 CORTE DEL MONTANA

MARKIT REMOVE DROP - 12450 OLD HOME CT

MARKIT REPAIR/REPLACE HARDWARE - 18390 AVENIDA BONITA N

MARKIT REMOVE DROP - 18336 AVENIDA BONITA N

MARKIT REMOVE DROP - 18302 AVENIDA BONITA N

MARKIT REMOVE DROP - 22767 SAWMILL FLAT RD

MARKIT REPLACE/INSTALL DOWN GUY - 720 RACETRACK RD

MARKIT REPAIR/REPLACE HARDWARE - 18971 HESS AVE

MARKIT REPAIR/REPLACE HARDWARE - 18999 INDUSTRY WAY

MARKIT REPAIR/REPLACE HARDWARE - 20675 GOPHER DR

MARKIT REPAIR/REPLACE HARDWARE - 16551 WARDS FERRY RD

MARKIT REPAIR/REPLACE HARDWARE - 16551 WARDS FERRY RD

MARKIT REPLACE/INSTALL OVERHEAD GUY - 16551 WARDS FERRY RD

MARKIT REPLACE/INSTALL DOWN GUY - 19673 RAWHIDE RD

MARKIT REMOVE DROP - 18137 OLD WARDS FERRY RD

MARKIT STRAIGHTEN IN-LINE POLE - 13613 TUOLUMNE RD

MARKIT REPAIR/REPLACE HARDWARE - 17806 CAMPBELL FLAT RD

MARKIT REPAIR/REPLACE HARDWARE - 11639 CAMPO SECO RD

MARKIT RAISE AT&T SERVICE DROP - 13676 TUOLUMNE RD

MARKIT REMOVE DROP - 19379 ROCKY RD

MARKIT REPAIR/REPLACE HARDWARE - 14185 NORTHRIDGE RD

MARKIT LOWER OR RAISE EXISTING CABLE - 11841 APPEY WAY

MARKIT REPAIR/REPLACE HARDWARE - 11798 ESSEN LN

MARKIT REMOVE DROP - 11961 CAMPO SECO RD

MARKIT REPAIR/REPLACE HARDWARE - 20657 GOPHER DR

MARKIT REMOVE DROP - 18456 WARDS FERRY RD

MARKIT REPLACE/INSTALL DOWN GUY - 14325 TUOLUMNE RD

MARKIT TREE TRIMMING REQUIRED - 19538 RAWHIDE RD

MARKIT REPAIR/REPLACE HARDWARE - 17490 BLACKBIRD LN

MARKIT REPAIR/REPLACE HARDWARE - 14230 NORTHRIDGE RD

MARKIT REPAIR/REPLACE HARDWARE - 17755 CAMPBELLS FLAT RD

MARKIT REPAIR/REPLACE HARDWARE - 12966 LAKE VALLEY LN

MARKIT REPAIR/REPLACE HARDWARE - 17807 CAMPBELL FLAT RD

MARKIT TREE TRIMMING REQUIRED - 22822 NORTHRUP CT

MARKIT STRAIGHTEN IN-LINE POLE - 12884 MONO WAY

MARKIT REPAIR/REPLACE HARDWARE - 20391 MEADOW BROOK DR

MARKIT RELASH TO EXISTING MESSENGER - 20234 PHOENIX LAKE RD

MARKIT RAISE AT&T SERVICE DROP - 14126 OAK KNOLL RD

MARKIT REPAIR/REPLACE HARDWARE - 14173 OAK KNOLL RD

MARKIT REPAIR/REPLACE HARDWARE - 20135 GIBBS DR

MARKIT REPAIR/REPLACE HARDWARE - 20232 GIBBS DR

MARKIT REPAIR/REPLACE HARDWARE - 20151 GIBBS DR

MARKIT REMOVE DROP - 22489 PARROTTS FERRY RD

MARKIT REPAIR/REPLACE HARDWARE - 22176 PARROTTS FERRY RD

MARKIT RAISE AT&T SERVICE DROP - 18038 LIME ROCK DR

MARKIT REPAIR/REPLACE HARDWARE - 18271 BERRY LN

MARKIT REMOVE DROP - 22992 PARROTTS FERRY RD

MARKIT REPAIR/REPLACE HARDWARE - 20050 ROUGH AND READY TRAIL

MARKIT REPAIR/REPLACE HARDWARE - 20010 ROUGH AND READY TRL

MARKIT REPAIR/REPLACE HARDWARE - 19883 PANORAMA PL S

MARKIT REMOVE DROP - 14790 BOOKER RD

MARKIT RAISE AT&T SERVICE DROP - 14790 BOOKER RD

MARKIT REPAIR/REPLACE HARDWARE - 13561 BERGEL RD

MARKIT REMOVE DROP - 11511 YANKEE HILL RD

MARKIT REMOVE DROP - 11147 MCKIBBON DR

MARKIT REPAIR/REPLACE HARDWARE - 21820 PARROTTS FERRY RD

MARKIT REMOVE DROP - 22134 PARROTTS FERRY RD

MARKIT REPAIR/REPLACE HARDWARE - 7551 REYNOLDS FERRY RD

MARKIT REMOVE DROP - 22652 PARROTTS FERRY RD

MARKIT REMOVE DROP - 11294 DAMIN RD

MARKIT STRAIGHTEN IN-LINE POLE - 624 E JACKSON ST

MARKIT RAISE AT&T SERVICE DROP - 447 E OAKSIDE DR

MARKIT RAISE AT&T SERVICE DROP - 585 E OAKSIDE DR

MARKIT REPAIR/REPLACE HARDWARE - 18475 LAMBERT LAKE RD

MARKIT REPAIR/REPLACE HARDWARE - 13656 MARK TRL

MARKIT REPAIR/REPLACE HARDWARE - 19941 KELLY DR

MARKIT REPAIR/REPLACE HARDWARE - 14242 KELLY LOOP

MARKIT REMOVE DROP - 11191 HEIDI LN

MARKIT PLACE/REPLACE DOWN GUY GUARD - 12097 CAMPO SECO RD

MARKIT REMOVE DROP - 22668 S GOLD ST

MARKIT REMOVE DROP - 11241 ALLEY DR

MARKIT REMOVE DROP - 11170 GOLF LINKS RD

MARKIT TREE TRIMMING REQUIRED - 11564 CAMPO SECO RD

MARKIT REMOVE DROP - 11037 GREEN ST

MARKIT REPAIR/REPLACE HARDWARE - 18400 LAMBERT LAKE RD

MARKIT REPAIR/REPLACE HARDWARE - 18741 OLOV RD

MARKIT REPAIR/REPLACE HARDWARE - 14000 FLORENCE WAY

MARKIT REPAIR/REPLACE HARDWARE - 18580 LAMBERT LAKE RD

MARKIT REPAIR/REPLACE HARDWARE - 14269 KELLY LOOP

MARKIT REPAIR/REPLACE HARDWARE - 18475 OLOV RD

MARKIT REPAIR/REPLACE HARDWARE - 21197 LYONS BALD MOUNTAIN RD

MARKIT REPAIR/REPLACE HARDWARE - 18280 MARTIN LN

MARKIT REPAIR/REPLACE HARDWARE - 17897 CAMPBELLS FLAT RD

MARKIT REPAIR/REPLACE HARDWARE - 13575 JOSHUA WAY

MARKIT REMOVE DROP - 18620 LAMBERT LAKE RD

MARKIT REPAIR/REPLACE HARDWARE - 13922 FLORENCE WAY

MARKIT REPAIR/REPLACE HARDWARE - 20132 HIGH MEADOW DR

MARKIT REPAIR/REPLACE HARDWARE - 14191 KELLY LOOP

MARKIT RAISE AT&T SERVICE DROP - 14221 KELLY LOOP

MARKIT REPAIR/REPLACE HARDWARE - 13955 FLORENCE WAY

MARKIT REPAIR/REPLACE HARDWARE - 18718 OLOV RD

MARKIT REPAIR/REPLACE HARDWARE - 13115 SYLVA LN

MARKIT REPAIR/REPLACE HARDWARE - 14338 KIRK ALAN LN

MARKIT REPAIR/REPLACE HARDWARE - 21461 APPLE HILL DR

MARKIT REPAIR/REPLACE HARDWARE - 14300 BURLUPI RD

MARKIT REPAIR/REPLACE HARDWARE - 14529 LORRAINE LN

MARKIT REPAIR/REPLACE HARDWARE - 14436 LORRAINE LN

MARKIT REPAIR/REPLACE HARDWARE - 21797 APPLE HILL DR

MARKIT REPAIR/REPLACE HARDWARE - 21900 LYONS BALD MOUNTAIN RD

MARKIT RAISE AT&T SERVICE DROP - 14501 PHILLIP LN

MARKIT REPAIR/REPLACE HARDWARE - 21686 APPLE HILL DR

MARKIT REPAIR/REPLACE HARDWARE - 20483 UPPER HILLVIEW DR

MARKIT STRAIGHTEN IN-LINE POLE - 20663 UPPER HILLVIEW DR

MARKIT REMOVE DROP - 10815 RACETRACK RD

MARKIT REPAIR/REPLACE HARDWARE - 17691 LIME KILN RD

MARKIT RAISE AT&T SERVICE DROP - 17691 LIME KILN RD

MARKIT REPAIR/REPLACE HARDWARE - 17609 LIME KILN RD

MARKIT REPAIR/REPLACE HARDWARE - 13630 JOSHUA WAY

MARKIT REPAIR/REPLACE HARDWARE - 13933 TUOLUMNE RD

MARKIT REMOVE DROP - 13889 TUOLUMNE RD

MARKIT REMOVE DROP - 13969 TUOLUMNE RD

MARKIT REPAIR/REPLACE HARDWARE - 13500 JOSHUA WAY

MARKIT RE-TENSION DOWN GUY ALL SIZES - 13500 JOSHUA WAY

MARKIT RAISE AT&T SERVICE DROP - 701 OLD BALD MOUNTAIN RD

MARKIT REPAIR/REPLACE HARDWARE - 20513 UPPER HILLVIEW DR

MARKIT REPAIR/REPLACE HARDWARE - 14136 ALDER LN

MARKIT REPAIR/REPLACE HARDWARE - 14300 ALDER LN

MARKIT REPAIR/REPLACE HARDWARE - 20577 MEADOW BROOK DR

MARKIT REPLACE/INSTALL DOWN GUY - 21331 PHOENIX LAKE RD

MARKIT REPAIR/REPLACE HARDWARE - 9220 HIGHWAY 49

MARKIT REMOVE DROP - 14833 PEACEFUL VALLEY RD

MARKIT REPAIR/REPLACE HARDWARE - 21837 FEATHER RIVER DR

MARKIT REPAIR/REPLACE HARDWARE - 13290 TERRACE DR

MARKIT STRAIGHTEN IN-LINE POLE - 519 LYONS ST

MARKIT RAISE AT&T SERVICE DROP - 519 LYONS ST

MARKIT RAISE AT&T SERVICE DROP - 701 OLD BALD MOUNTAIN RD

MARKIT RAISE AT&T SERVICE DROP - 780 E BALD MOUNTAIN RD

MARKIT RAISE AT&T SERVICE DROP - 447 BALD MOUNTAIN RD N

MARKIT RAISE AT&T SERVICE DROP - 565 E BALD MOUNTAIN RD

MARKIT RAISE AT&T SERVICE DROP - 20558 SILVER DAWN DR

MARKIT PLACE/REPLACE DOWN GUY GUARD - 19742 IVY LN

MARKIT STRAIGHTEN IN-LINE POLE - 20537 PHOENIX LAKE RD

MARKIT STRAIGHTEN IN-LINE POLE - 19760 IVY LN

MARKIT RAISE AT&T SERVICE DROP - 20521 PHOENIX LAKE RD

MARKIT RAISE AT&T SERVICE DROP - 19760 IVY LN

MARKIT PLACE ANCHOR - 21155 FLUME RD

MARKIT REPAIR/REPLACE HARDWARE - 19026 NORTH DR

MARKIT REPAIR/REPLACE HARDWARE - 12132 CAMPO SECO RD

MARKIT REMOVE DROP - 22992 PARROTTS FERRY RD

MARKIT INSTALL HARDWARE - 10989 N AIRPORT RD

MARKIT REPAIR/REPLACE HARDWARE - 11633 YANKEE HILL RD/NOTES: TARP ON TERMINAL

MARKIT PLACE/REPLACE DOWN GUY GUARD - 18175 MARTIN LN

MARKIT REMOVE DROP - 24464 PELA RD

MARKIT REPAIR/REPLACE HARDWARE - 24326 LAVENE CT

MARKIT REMOVE DROP - 24431 LAVENE LN

MARKIT REMOVE DROP - 24445 PELA RD

MARKIT REPAIR/REPLACE HARDWARE - 17351 MOUNT EVEREST CT

MARKIT REPAIR/REPLACE HARDWARE - 22111 THUNDERBOLT DR

MARKIT REMOVE DROP - 18930 MIDDLE CAMP SUGAR PINE RD

MARKIT REMOVE DROP - 23882 MARSHALL WAY

MARKIT REMOVE DROP - 17970 LITTLE FULLER RD

MARKIT REMOVE DROP - 23680 STATE HIGHWAY 108

MARKIT RELASH EXISTING CABLES - 22071 CEDAR SPRINGS RD

MARKIT REPAIR/REPLACE HARDWARE - 20724 KOTEO LN

MARKIT REPAIR/REPLACE HARDWARE - 20780 KOTEO LN

MARKIT TREE TRIMMING REQUIRED - 20157 MANZANITA ST

MARKIT REMOVE DROP - 24287 KOTEO CT

MARKIT TREE TRIMMING REQUIRED - 20163 MANZANITA ST

MARKIT REMOVE DROP - 21178 NUGGETT DR

MARKIT RAISE AT&T SERVICE DROP - 22576 GOLF CLUB DR

MARKIT REMOVE DROP - 22462 GOLF CLUB DR

MARKIT REMOVE DROP - 22461 GOLF CLUB DR

MARKIT RELASH EXISTING CABLES - 22717 VIRGINIA AVE

MARKIT VEGETATION REMOVAL REQUIRED - 22717 VIRGINIA AVE

MARKIT REMOVE DROP - 22705 BRET HARTE DR

MARKIT REMOVE DROP - 22775 BLACK OAK DR

MARKIT REMOVE DROP - 22886 GOLF CLUB DR

MARKIT REPAIR/REPLACE HARDWARE - 24312 KOME RD

MARKIT REMOVE DROP - 23852 MARSHALL WAY

MARKIT REMOVE DROP - 23687 FREMONT WAY

MARKIT RAISE AT&T SERVICE DROP - 16501 OAKHAVEN LN

MARKIT REPAIR/REPLACE HARDWARE - 20527 KUTCI DR

MARKIT TREE TRIMMING REQUIRED - 24315 SUGAR PINE RD

MARKIT TREE TRIMMING REQUIRED - 24315 SUGAR PINE RD

MARKIT TREE TRIMMING REQUIRED - 16636 MADRONE CIR

MARKIT TREE TRIMMING REQUIRED - 16585 HILLSIDE DR

MARKIT TREE TRIMMING REQUIRED - 17325 MOUNT ELIZABETH DR

MARKIT REMOVE DROP - 16498 W BROOKSIDE DR

MARKIT REMOVE DROP - 16432 W BROOKSIDE DR

MARKIT REMOVE DROP - 21241 NUGGET AVE

MARKIT REPAIR/REPLACE HARDWARE - 20568 CHIEF FULLER RD

MARKIT REMOVE DROP - 22860 MEADOW CT

MARKIT REPAIR/REPLACE HARDWARE - 22810 MEADOW LN

MARKIT REPAIR/REPLACE HARDWARE - 17151 NILE RIVER DR

MARKIT REPAIR/REPLACE HARDWARE - 22446 COLORADO RIVER DR

MARKIT REPAIR/REPLACE HARDWARE - 17136 NILE RIVER DR

MARKIT REPAIR/REPLACE HARDWARE - 17276 NILE RIVER DR

MARKIT REMOVE DROP - 24281 SUGAR PINE RD

MARKIT REPAIR/REPLACE HARDWARE - 24096 LAMA RD

MARKIT REMOVE DROP - 20620 LAMA RD TAMALIN

MARKIT REMOVE DROP - 20635 LAMA ROAD TAMALIN

MARKIT REMOVE DROP - 24249 SUGAR PINE RD

MARKIT TREE TRIMMING REQUIRED - 24250 SUGAR PINE RD

MARKIT REMOVE DROP - 26591 CRYSTAL

MARKIT REMOVE DROP - 25107 MERRILL SPRINGS RD

MARKIT TREE TRIMMING REQUIRED - 23770 SONORA PASS HWY

MARKIT REMOVE DROP - 26555 LONG BARN CT

MARKIT REMOVE DROP - 15825 CREEK

MARKIT REMOVE DROP - 24242 NUKA CT

MARKIT RAISE AT&T SERVICE DROP - 20704 TELELE TRAIL

MARKIT REMOVE DROP - 20612 HEKEKE LN

MARKIT TREE TRIMMING REQUIRED - 24733 STATE HIGHWAY 108

MARKIT RAISE AT&T SERVICE DROP - 24733 STATE HIGHWAY 108

MARKIT REMOVE DROP - 24548 SONORA PASS HWY

MARKIT REMOVE DROP - 18806 BROADHURST DR

MARKIT REMOVE DROP - 19360 MICHIGAN DR

MARKIT REMOVE DROP - 19465 MICHIGAN CT

MARKIT REMOVE DROP - 26464 LONG BARN CT

MARKIT REMOVE DROP - 26125 SLIDE INN ST/NOTES: SERVICE DROP HANGING IN TREES

MARKIT REMOVE DROP - 25843 LONG BARN SUGARPINE RD

MARKIT REMOVE DROP - 25970 LONG BARN RD

MARKIT REMOVE DROP - 19770 SIX POINT CT

MARKIT RAISE AT&T SERVICE DROP - 24289 AWAHANEE RD

MARKIT RAISE AT&T SERVICE DROP - 16653 MADRONE CIR

MARKIT REMOVE DROP - 20998 LAMA ROAD TEUMETE

MARKIT REMOVE DROP - 20993 LAMA ROAD TEUMETE

MARKIT REMOVE DROP - 19011 HURON DR

MARKIT REMOVE DROP - 23451 LAKEWOOD DR

MARKIT REMOVE DROP - 18950 HURON DR

MARKIT REMOVE DROP - 19414 SUPERIOR DR

MARKIT REMOVE DROP - 23240 CHEROKEE DR

MARKIT REMOVE DROP - 22581 E RHINE RIVER DR

MARKIT REMOVE DROP - 25320 JONATHAN LN

MARKIT REMOVE DROP - 25698 UPPER SCENIC DR

MARKIT REMOVE DROP - 21785 CONFIDENCE RD

MARKIT REMOVE DROP - 25468 DAVID DR

MARKIT REMOVE DROP - 25435 DAVID DR

MARKIT REMOVE DROP - 25393 DAVID DR

MARKIT REMOVE DROP - 23945 CROSSLEY WAY

MARKIT REMOVE DROP - 24029 PINE CONE RD

MARKIT REMOVE DROP - 23931 PINE LAKE DR

MARKIT REMOVE DROP - 23931 PINE LAKE DR

MARKIT RELASH TO EXISTING MESSENGER - 23930 YELLOW PINE RD

MARKIT PLACE/REPLACE DOWN GUY GUARD - 19255 SUPERIOR DR

MARKIT REMOVE DROP - 23649 ONTARIO DR

MARKIT REMOVE DROP - 22446 COLORADO RIVER DR

MARKIT REMOVE DROP - 25430 WHEELER RD

MARKIT REMOVE DROP - 22610 CONFIDENCE RD

MARKIT REMOVE DROP - 22828 HIGHLAND DR

MARKIT REMOVE DROP - 18844 SEQUOIA LN

MARKIT REMOVE DROP - 16956 BROKEN PINE RD

MARKIT STRAIGHTEN IN-LINE POLE - 23888 STABLE RD

MARKIT REMOVE DROP - 25110 STATE HWY 108

MARKIT TREE TRIMMING REQUIRED - 24226 OXBOW LN N

MARKIT REMOVE DROP - 24900 STATE HIGHWAY 108

MARKIT REMOVE DROP - 19011 HURON DR

MARKIT REMOVE DROP - 23532 LAKEWOOD DR

MARKIT TREE TRIMMING REQUIRED - 24650 STATE HIGHWAY 108

MARKIT REPAIR/REPLACE HARDWARE - 22787 EAST AVE

MARKIT REPAIR/REPLACE HARDWARE - 22547 ROBIN HOOD DR

MARKIT REPAIR/REPLACE HARDWARE - 24347 KIKU LN

MARKIT REMOVE DROP - 22714 BLACK HAWK DR

MARKIT REMOVE DROP - 24267 PELA RD

MARKIT REMOVE DROP - 24241 OXBOW LN N

MARKIT TREE TRIMMING REQUIRED - 24155 RED CEDAR ST

MARKIT TREE TRIMMING REQUIRED - 24243 BLACK OAK CT

MARKIT TREE TRIMMING REQUIRED - 24276 WHITE FIR DR

MARKIT REMOVE DROP - 17067 CARRIAGE RD

MARKIT REMOVE DROP - 19215 SUPERIOR DR

MARKIT REMOVE DROP - 19111 MIDDLE CAMP RD

MARKIT REMOVE DROP - 16727 HILLSIDE DR

MARKIT REMOVE DROP - 19640 MICHIGAN DR

MARKIT REPAIR/REPLACE HARDWARE - 24110 PAIPU RD

MARKIT REPAIR/REPLACE HARDWARE - 20415 KUTCI DR

MARKIT REPAIR/REPLACE HARDWARE - 24123 WUUYA WAY

MARKIT REPAIR/REPLACE HARDWARE - 20504 KUTCI DR

MARKIT REPAIR/REPLACE HARDWARE - 24082 WUUYA WAY

MARKIT TREE TRIMMING REQUIRED - 24247 SIERRA PARK RD

MARKIT TREE TRIMMING REQUIRED - 20724 KOTEO LN

MARKIT REMOVE DROP - 20784 HEKEKE LN

MARKIT REPAIR/REPLACE HARDWARE - 20755 MUHELI RD

MARKIT TREE TRIMMING REQUIRED - 24279 KOTEO CT

MARKIT TREE TRIMMING REQUIRED - 24302 KOTEO CT

MARKIT RAISE AT&T MAINLINE CABLE - 23830 BUCKBOARD CT

MARKIT REMOVE DROP - 18414 POPPY TERRACE DR

MARKIT REMOVE DROP - 18991 MIDDLE CAMP RD

MARKIT REMOVE DROP - 19131 MIDDLE CAMP RD

MARKIT REMOVE DROP - 23835 CONFIDENCE SOUTH FORK RD

MARKIT REMOVE DROP - 20851 HIKI PL

MARKIT REMOVE DROP - 24220 S FORK RD

MARKIT REMOVE DROP - 24174 S FORK RD

MARKIT REMOVE DROP - 24198 S FORK RD

MARKIT REPAIR/REPLACE HARDWARE - 21864 LONGEWAY RD

MARKIT REPAIR/REPLACE HARDWARE - 17520 SCENIC HEIGHTS DR

MARKIT REMOVE DROP - 20695 HAIAPO RD

MARKIT REMOVE DROP - 20772 HAIAPO RD

MARKIT REMOVE DROP - 22375 PONDEROSA DR

MARKIT REMOVE DROP - 22443 PONDEROSA DR

MARKIT RAISE AT&T SERVICE DROP - 24192 AWAHANEE RD

MARKIT REPLACE/INSTALL DOWN GUY - 21767 LONGEWAY RD

MARKIT REMOVE DROP - 18423 MARQUIS DR

MARKIT TREE TRIMMING REQUIRED - 20123 MANZANITA ST

MARKIT REMOVE DROP - 22364 BEERSHEBA

MARKIT RAISE AT&T SERVICE DROP - 17344 MOUNT ELIZABETH DR

MARKIT REPAIR/REPLACE HARDWARE - 21350 LONGEWAY RD

MARKIT RAISE AT&T SERVICE DROP - 21472 LONGEWAY RD

MARKIT REPLACE/INSTALL DOWN GUY - 22615 GOLF CLUB DR

MARKIT RAISE AT&T SERVICE DROP - 22881 GOLF CLUB DR

MARKIT REMOVE DROP - 23001 GOLF CLUB DR

MARKIT REMOVE DROP - 17904 GOOD SHEPHERD DR

MARKIT REMOVE DROP - 18884 SEQUOIA LN

MARKIT REMOVE DROP - 22298 TWAIN HARTE DR

MARKIT REMOVE DROP - 22404 MONO DR

MARKIT REMOVE DROP - 22243 TWAIN HARTE DR

MARKIT REMOVE DROP - 22450 MONO DR

MARKIT REMOVE DROP - 22420 MONO DR

MARKIT REMOVE DROP - 22486 MONO DR

MARKIT REMOVE DROP - 22486 MONO DR

MARKIT REMOVE DROP - 25207 ABRAHAM AVE

MARKIT REPAIR/REPLACE HARDWARE - 20811 KOTEO LN

MARKIT REMOVE DROP - 20235 LILAC LN

MARKIT TREE TRIMMING REQUIRED - 20260 LILAC LN

MARKIT TREE TRIMMING REQUIRED - 20240 LILAC LN

MARKIT REPAIR/REPLACE HARDWARE - 20890 MUHELI RD

MARKIT REMOVE DROP - 23287 TUOLUMNE DR

MARKIT REMOVE DROP - 18890 MANZANITA DR

MARKIT REMOVE DROP - 23272 CRESTA DR

MARKIT REMOVE DROP - 23221 CRESTA DR

MARKIT REMOVE DROP - 22576 TWAIN HARTE DR

MARKIT REMOVE DROP - 22498 SONORA DR

MARKIT REMOVE DROP - 22717 VIRGINIA AVE

MARKIT REMOVE DROP - 22533 GOLF CLUB DR

MARKIT REMOVE DROP - 23464 ORIOLE LN

MARKIT REMOVE DROP - 23336 TANAGER DR

MARKIT REPAIR/REPLACE HARDWARE - 20910 MUHELI RD

MARKIT REMOVE DROP - 23890 YELLOW PINE RD

MARKIT TREE TRIMMING REQUIRED - 24109 NUKA TRAIL

MARKIT RAISE AT&T SERVICE DROP - 24050 WAKALU TRAIL

MARKIT RAISE AT&T SERVICE DROP - 24144 OLO WIN TRL

MARKIT RAISE AT&T SERVICE DROP - 24092 OLO-WIN TRAIL

MARKIT TREE TRIMMING REQUIRED - 24840 SONORA PASS HWY

MARKIT TREE TRIMMING REQUIRED - 24748 STATE HIGHWAY 108

MARKIT REMOVE DROP - 18870 LOOKOUT DR

MARKIT REMOVE DROP - 23187 OAK VIEW DR

MARKIT REMOVE DROP - 23045 JOAQUIN GULLY RD

MARKIT RELASH EXISTING CABLES - 22936 SIERRA DR

MARKIT REMOVE DROP - 22936 SIERRA DR

MARKIT REMOVE DROP - 22984 MARK TWAIN DR

MARKIT REMOVE DROP - 23102 MARK TWAIN DR

MARKIT VEGETATION REMOVAL REQUIRED - 23118 MARK TWAIN DR

MARKIT LOWER OR RAISE EXISTING CABLE - 22822 FULLER RD

MARKIT REMOVE DROP - 22709 FULLER RD

MARKIT REMOVE DROP - 22733 FULLER RD

MARKIT REMOVE DROP - 23450 ORIOLE LN

MARKIT REMOVE DROP - 17925 BLUEJAY CT

MARKIT RELASH TO EXISTING MESSENGER - 23800 PINE LAKE DR

MARKIT REMOVE DROP - 23911 REDWOOD DR

MARKIT RELASH TO EXISTING MESSENGER - 24026 PINE LAKE DR

MARKIT REMOVE DROP - 25004 JORDAN WAY W

MARKIT REMOVE DROP - 22150 SARAH CIR

MARKIT RAISE AT&T SERVICE DROP - 22922 MIDDLE CAMP RD

MARKIT REPAIR/REPLACE HARDWARE - 24368 KOME RD

MARKIT REPAIR/REPLACE HARDWARE - 24350 LAVENE LN

MARKIT REMOVE DROP - 21960 SUNRISE DR

MARKIT REMOVE DROP - 24399 LAVENE LN

MARKIT REMOVE DROP - 17264 NILE RIVER DR

MARKIT REMOVE DROP - 22775 BLACK OAK DR

MARKIT REMOVE DROP - 22758 BRET HARTE DR

MARKIT REMOVE DROP - 22839 MINERS AVE

MARKIT REMOVE DROP - 22879 BLACK OAK DR

MARKIT REMOVE DROP - 22717 VIRGINIA AVE

MARKIT REMOVE DROP - 23702 FREMONT WAY

MARKIT TREE TRIMMING REQUIRED - 17854 LARK DR

MARKIT TREE TRIMMING REQUIRED - 17951 ROBIN RD

MARKIT REMOVE DROP - 24034 PINE LAKE DR

MARKIT REMOVE DROP - 25075 DEBORAH DR

MARKIT RELASH TO EXISTING MESSENGER - 23958 PINE LAKE DR

MARKIT REMOVE DROP - 25332 ESTHER AVE

MARKIT REMOVE DROP - 25215 REBEKAH RD

MARKIT RAISE AT&T SERVICE DROP - 17606 LAREDO CT

MARKIT RAISE AT&T SERVICE DROP - 16912 ESTRALITA DR

MARKIT RAISE AT&T SERVICE DROP - 16878 ESTRALITA DR

MARKIT RAISE AT&T SERVICE DROP - 16975 E BROOKSIDE DR

MARKIT RAISE AT&T SERVICE DROP - 16796 E BROOKSIDE DR

MARKIT RAISE AT&T SERVICE DROP - 16869 E BROOKSIDE DR

MARKIT REMOVE DROP - 18661 WILDWOOD DR

MARKIT REMOVE DROP - 23702 FREMONT WAY

MARKIT REMOVE DROP - 18751 MIDDLE CAMP RD

MARKIT REMOVE DROP - 22538 W RHINE RIVER DR

MARKIT REMOVE DROP - 22280 LONGEWAY RD

MARKIT TREE TRIMMING REQUIRED - 17689 LUCKY STRIKE TRL

MARKIT REMOVE DROP - 22457 LONGEWAY RD

MARKIT REMOVE DROP - 25264 REBEKAH RD

MARKIT REMOVE DROP - 25254 DEBORAH DR

MARKIT REMOVE DROP - 21937 SUNRISE DR

MARKIT REMOVE DROP - 25163 REBEKAH RD

MARKIT REMOVE DROP - 24934 BOTTINI APPLE RANCH RD

MARKIT REMOVE DROP - 22016 LAKEVIEW DR

MARKIT RAISE AT&T SERVICE DROP - 22951 MIDDLE CAMP RD

MARKIT REMOVE DROP - 22380 WILDCAT RIDGE RD

MARKIT RAISE AT&T SERVICE DROP - 22421 WILDCAT RIDGE RD

MARKIT TREE TRIMMING REQUIRED - 22483 WILDCAT RIDGE RD

MARKIT LOWER OR RAISE EXISTING CABLE - 22535 WILDCAT RIDGE RD

MARKIT REMOVE DROP - 16781 BIG HILL RD

MARKIT PLACE ANCHOR - 29595 ITALIAN BAR RD

MARKIT Trees down on cable. Behind address 23056 Twain Harte Dr. Access contact David 209)770-4602.

MARKIT RAISE AT&T SERVICE DROP - 13250 SHALE ROCK RD

MARKIT REPAIR/REPLACE HARDWARE - 22131 COLUMBIA CREST DR

MARKIT REPAIR/REPLACE HARDWARE - 21893 BALD MOUNTAIN RD N

MARKIT REPAIR/REPLACE HARDWARE - 22320 RIDGEMONT DR

MARKIT REMOVE DROP - 22211 SAWMILL FLAT RD

MARKIT REMOVE DROP - 22039 SAWMILL FLAT RD

MARKIT REPAIR/REPLACE HARDWARE - 16647 S CREEKSIDE DR

MARKIT REMOVE DROP - 16647 S CREEKSIDE DR

MARKIT REPAIR/REPLACE HARDWARE - 16689 S CREEKSIDE DR

MARKIT REMOVE DROP - 16830 S CREEKSIDE DR

MARKIT REMOVE DROP - 16689 S CREEKSIDE DR

MARKIT RAISE AT&T SERVICE DROP - 11411 HIGHWAY 49

MARKIT REMOVE DROP - 1216 HIGHWAY 49

MARKIT REPAIR/REPLACE HARDWARE - 15159 VICTORY WAY

MARKIT REPAIR/REPLACE HARDWARE - 15194 VICTORY WAY

MARKIT REPLACE/INSTALL DOWN GUY - 537 SHAWS FLAT RD

MARKIT REPAIR/REPLACE HARDWARE - 14764 CURTIS CIRCLE

MARKIT REPAIR/REPLACE HARDWARE - 14881 CURTIS CIRCLE

MARKIT VEGETATION REMOVAL REQUIRED - 720 SHAWS FLAT RD

MARKIT REPAIR/REPLACE HARDWARE - 16250 CORTE DE LAS NINAS

MARKIT REPAIR/REPLACE HARDWARE - 15252 CURTIS CIRCLE

MARKIT REPAIR/REPLACE HARDWARE - 15811 BEV BARRON RD

MARKIT TREE TRIMMING REQUIRED - 582 SHAWS FLAT RD

MARKIT REMOVE DROP - 14611 NORTHRIDGE RD

MARKIT REMOVE DROP - 509 S STEWART ST

MARKIT REMOVE DROP - 400 S STEWART ST

MARKIT LOWER OR RAISE EXISTING AT&T CABLE - 16818 DRAPER MINE RD

MARKIT REPAIR/REPLACE HARDWARE - 14591 NORTHRIDGE RD

MARKIT RELASH TO EXISTING MESSENGER - 10834 HIGHWAY 49

MARKIT RELASH TO EXISTING MESSENGER - 21875 SHAWS FLAT RD

MARKIT REMOVE DROP - 22067 FALLVIEW LN

MARKIT REMOVE DROP - 14599 TUOLUMNE RD

MARKIT REMOVE DROP - 18446 WARDS FERRY RD

MARKIT REMOVE DROP - 14451 TUOLUMNE RD

MARKIT REMOVE DROP - 21583 HIDDEN VALLEY RD

MARKIT REPAIR/REPLACE HARDWARE - 15275 TUOLUMNE RD

MARKIT PLACE ANCHOR - 15045 CAMAGE AVE

MARKIT REMOVE DROP - 21300 EVERGREEN WAY

MARKIT REMOVE DROP - 16526 SALLANDER DR

MARKIT REPAIR/REPLACE HARDWARE - 21181 CRESTVIEW DR

MARKIT REPAIR/REPLACE HARDWARE - 21520 BELLVIEW CREEK RD

MARKIT PLACE/REPLACE DOWN GUY GUARD - 21346 EVERGREEN WAY

MARKIT PLACE ANCHOR - 21346 EVERGREEN WAY

MARKIT REPAIR/REPLACE HARDWARE - 22053 ELIZABETH LN

MARKIT REPAIR/REPLACE HARDWARE - 21984 ELIZABETH LN

MARKIT INSTALL HARDWARE - 85 HOPE LN

MARKIT REMOVE DROP - 20931 OLD PHOENIX LAKE RD

MARKIT REMOVE HARDWARE - 232 PASADENA AVE

MARKIT PLACE/REPLACE DOWN GUY GUARD - 21569 PHOENIX LAKE RD

MARKIT PLACE/REPLACE DOWN GUY GUARD - 21578 PHOENIX LAKE RD

MARKIT PLACE ANCHOR - 21578 PHOENIX LAKE RD

MARKIT REPAIR/REPLACE HARDWARE - 21756 WATER OAK DR

MARKIT REMOVE DROP - 21430 GREEN MEADOW LN

MARKIT REPAIR/REPLACE HARDWARE - 16740 WOODSIDE WAY

MARKIT RELASH TO EXISTING MESSENGER - 21097 CRESTVIEW DR

MARKIT REMOVE DROP - 21396 GREEN MEADOW LN

MARKIT REMOVE DROP - 21720 PHOENIX LAKE RD

MARKIT REPAIR/REPLACE HARDWARE - 15275 RIDGEWOOD CT

MARKIT REMOVE DROP - 21891 BELLEVIEW RD

MARKIT REPAIR/REPLACE HARDWARE - 21287 AMERICAN RIVER DR

MARKIT REPAIR/REPLACE HARDWARE - 21348 CRESTVIEW DR

MARKIT PLACE CROSS/GUARD ARM - 311 S SHEPHERD ST

MARKIT TREE TRIMMING REQUIRED - 87 UPPER SUNSET DR

MARKIT REMOVE DROP - 21197 JACK PAGE RD

MARKIT REMOVE DROP - 2 S FOREST RD

MARKIT PLACE CROSS/GUARD ARM - 454 W STOCKTON ST

MARKIT REMOVE DROP - 21241 OLD SONORA COLUMBIA RD

MARKIT REMOVE DROP - 21220 OLD SONORA COLUMBIA RD

MARKIT REMOVE DROP - 11289 HIGHWAY 49

MARKIT REMOVE DROP - 1197 HIGHWAY 49

MARKIT REMOVE DROP - 45 S SHEPHERD ST

MARKIT REMOVE DROP - 66 N SHEPHERD ST

MARKIT REMOVE DROP - 171 N WASHINGTON ST

MARKIT REPAIR/REPLACE HARDWARE - 22284 CRYSTAL FALLS CT

MARKIT RAISE AT&T MAINLINE CABLE - 20705 SOULSBYVILLE RD

MARKIT REPLACE/INSTALL OVERHEAD GUY - 71 LEONARD ADDITION RD

MARKIT REMOVE DROP - 2 S FOREST RD

MARKIT RAISE AT&T SERVICE DROP - 23329 RANCHO CASTANEA RD

MARKIT REPAIR/REPLACE HARDWARE - 4955 POCO CALLE DR

MARKIT REPAIR/REPLACE HARDWARE - 15331 POCO CALLE DR

MARKIT REMOVE DROP - 10485 MOCCASIN SWITCHBACK RD

MARKIT REPAIR/REPLACE HARDWARE - 15346 POCO CALLE DR

MARKIT REPAIR/REPLACE HARDWARE - 15549 BUENA VISTA AVENIDA

MARKIT REPAIR/REPLACE HARDWARE - 15575 BUENA VISTA AVENIDA

MARKIT REPAIR/REPLACE HARDWARE - 21893 CRYSTAL FALLS DR

MARKIT REMOVE DROP - 21899 RUSSIAN RIVER DR

MARKIT REMOVE DROP - 444 SHAWS FLAT RD

MARKIT REPAIR/REPLACE HARDWARE - 20798 LONGEWAY RD

MARKIT REPAIR/REPLACE HARDWARE - 14960 SENA LN

MARKIT REMOVE HARDWARE - 19866 MONO WAY

MARKIT REPAIR/REPLACE HARDWARE - 15025 POTATO RANCH RD

MARKIT REMOVE DROP - 22235 CONKLIN TRL

MARKIT RELASH EXISTING CABLES - 22235 CONKLIN TRL

MARKIT REPAIR/REPLACE HARDWARE - 13180 MOUNTAIN BOY MINE RD

MARKIT REMOVE DROP - 20980 JAMESTOWN RD

MARKIT REMOVE DROP - 11007 MOUNT BROW RD

MARKIT REPAIR/REPLACE HARDWARE - 21686 PASEO DE LOS PORTALES RD

MARKIT REMOVE DROP - 10445 MOCCASIN SWITCHBACK RD

MARKIT PLACE CROSS/GUARD ARM - 11031 UNION HILL RD

MARKIT REMOVE DROP - 12 COOPER

MARKIT REMOVE DROP - 20962 MAURICE LN

MARKIT LOWER OR RAISE EXISTING CABLE - 21072 MAURICE LN

MARKIT PLACE/REPLACE DOWN GUY GUARD - 17179 ALDERMAN RD

MARKIT REPAIR/REPLACE HARDWARE - 21162 LONGEWAY RD

MARKIT REMOVE DROP - 22021 EL COYOTE DR

MARKIT REMOVE DROP - 16335 DRAPER MINE RD

MARKIT PLACE ANCHOR - 15045 CAMAGE AVE

MARKIT PLACE/REPLACE DOWN GUY GUARD - 18527 STANDARD RD

MARKIT PLACE ANCHOR - 18798 STANDARD RD

MARKIT REPAIR/REPLACE HARDWARE - 18490 STANDARD RD

MARKIT REMOVE DROP - 14420 TWIST RD

MARKIT RAISE AT&T SERVICE DROP - 20894 LYONS BALD MOUNTAIN RD

MARKIT REMOVE DROP - 21618 CRYSTAL FALLS DR

MARKIT REMOVE DROP - 21677 CRYSTAL LAKE DR

MARKIT REPAIR/REPLACE HARDWARE - 21626 WASATCH MOUNTAIN RD

MARKIT REMOVE DROP - 21626 WASATCH MOUNTAIN RD

MARKIT REPAIR/REPLACE HARDWARE - 21195 LONGEWAY RD

MARKIT REPAIR/REPLACE HARDWARE - 21184 LONGEWAY RD

MARKIT RELASH TO EXISTING MESSENGER - 19632 MONO WAY

MARKIT REPAIR/REPLACE HARDWARE - 19966 SOMMETTE DR

MARKIT REPAIR/REPLACE HARDWARE - 14420 TWIST RD

MARKIT REPAIR/REPLACE HARDWARE - 16869 CHAUNIN RD

MARKIT REPAIR/REPLACE HARDWARE - 15021 CAMAGE AVE

MARKIT PLACE/REPLACE DOWN GUY GUARD - 14900 CAMAGE AVE

MARKIT PLACE ANCHOR - 16185 TUOLUMNE RD

MARKIT REPAIR/REPLACE HARDWARE - 22240 PASEO DE LOS PORTALES RD

MARKIT REPAIR/REPLACE HARDWARE - 22295 PASEO DE LOS PORTALES RD

MARKIT REMOVE DROP - 21522 PASEO DE LOS PORTALES RD

MARKIT REPAIR/REPLACE HARDWARE - 22240 PASEO DE LOS PORTALES RD
MARKIT TRANSFER AT&T CABLE(S);TRANSFER AT&T TERMINAL(S);PULL OLD POLE;LEAD TAILS NO;CABLE SWING NO;TRASFER 2 - 22150 PASEO DE LOS PORTALES RD

MARKIT PULL OLD POLE;LEAD TAILS NO;CABLE SWING NO;TRASFER 2 - 10683 MOUNTAIN BROW RD

MARKIT REPAIR/REPLACE HARDWARE - 15690 ALLENBY DR

MARKIT REPAIR/REPLACE HARDWARE - 19909 PEPPERMINT FALLS RD

MARKIT PLACE CROSS/GUARD ARM - 330 CALAVERAS WAY

MARKIT REMOVE DROP - 16526 CREEKSIDE DR

MARKIT REMOVE DROP - 300 BONANZA RD

MARKIT REMOVE DROP - 16558 CREEKSIDE DR

MARKIT REPLACE/INSTALL DOWN GUY - 16590 CREEKSIDE DR

MARKIT REMOVE DROP - 18601 ZEKARIAS CT

MARKIT PLACE/REPLACE DOWN GUY GUARD - 15980 MORRIS RD
MARKIT TRANSFER AT&T CABLE(S);PULL OLD POLE;LEAD TAILS NO;CABLE SWING NO;TRASFER 1 - 15925 MORRIS RD

MARKIT REMOVE DROP - 15925 MORRIS RD

MARKIT LOWER OR RAISE EXISTING AT&T CABLE - 16009 MORRIS RD

MARKIT REMOVE DROP - 15961 MORRIS RD

MARKIT PLACE ANCHOR - 16057 MORRIS RD

MARKIT PLACE ANCHOR - 18210 AARONDALE RD

MARKIT REMOVE DROP - 10731 MOUNTAIN BROW RD

MARKIT PULL OLD POLE;LEAD TAILS NO;CABLE SWING NO;TRASFER 0 - 10731 MOUNTAIN BROW RD

MARKIT PULL OLD POLE;LEAD TAILS NO;CABLE SWING NO;TRASFER 1 - 10858 MOUNTAIN BROW RD

MARKIT REMOVE DROP - 21848 EL OSO WAY

MARKIT PLACE ANCHOR - 8773 FRAGUERO RD

MARKIT REPAIR/REPLACE HARDWARE - 8773 FRAGUERO RD

MARKIT REPAIR/REPLACE HARDWARE - 21686 PASEO DE LOS PORTALES RD

MARKIT REPAIR/REPLACE HARDWARE - 15496 PASEO DE LOS ROBLES RD

MARKIT REPAIR/REPLACE HARDWARE - 21748 EL PUMA CIR

MARKIT PLACE/REPLACE DOWN GUY GUARD - 16572 CREEKSIDE DR
MARKIT REPLACE/INSTALL DOWN GUY;TRANSFER AT&T CABLE(S);TRANSFER AT&T TERMINAL(S);TRANSFER AT&T DROP(S);PULL OLD POLE;LEAD TAILS NO;CABLE SWING NO;TRASFER 4 - 21707 PHOENIX LAKE RD

MARKIT REMOVE DROP - 236 SYLVAN DR

MARKIT REPAIR/REPLACE HARDWARE - 15380 COUNTRY CLUB LN

MARKIT REMOVE DROP - 73 ELM ST

MARKIT REPAIR/REPLACE HARDWARE - 21370 SHAWS FLAT RD

MARKIT REMOVE DROP - 21348 SHAWS FLAT RD

MARKIT REMOVE DROP - 16857 JUNE CT

MARKIT REMOVE DROP - 16899 TEHACHAPI CT

MARKIT REPAIR/REPLACE HARDWARE - 18351 AARONDALE RD

MARKIT REMOVE DROP - 18351 AARONDALE RD

MARKIT REPAIR/REPLACE HARDWARE - 17691 DELORES LN

MARKIT REPAIR/REPLACE HARDWARE - 18130 AARONDALE RD

MARKIT REPAIR/REPLACE HARDWARE - 21716 EL PUMA CIR

MARKIT REPAIR/REPLACE HARDWARE - 21734 EL PUMA CIRCLE
MARKIT TRANSFER AT&T CABLE(S);PULL OLD POLE;LEAD TAILS NO;CABLE SWING NO;TRASFER 1 - 19404 ROCKRIDGE WAY
MARKIT REPLACE/INSTALL DOWN GUY;TRANSFER AT&T CABLE(S);TRANSFER AT&T TERMINAL(S);TRANSFER AT&T DROP(S);PULL OLD POLE;LEAD TAILS NO;CABLE SWING NO;TRASFER 4 - 16985 W AMERICAN RIVER DR
MARKIT REPLACE/INSTALL DOWN GUY;TRANSFER AT&T CABLE(S);TRANSFER AT&T TERMINAL(S);TRANSFER AT&T DROP(S);PULL OLD POLE;LEAD TAILS NO;CABLE SWING NO;TRASFER 4 - 16956 W AMERICAN RIVER DR

MARKIT REMOVE DROP - 16902 W AMERICAN RIVER DR

MARKIT REMOVE DROP - 203 THEALL ST

MARKIT REPAIR/REPLACE HARDWARE - 235 THEALL ST

MARKIT REMOVE DROP - 16860 TEHACHAPI CT

MARKIT PULL OLD POLE;LEAD TAILS NO;CABLE SWING NO;TRASFER 2 - 594 HIGH ST

MARKIT REPAIR/REPLACE HARDWARE - 31 WILLIAM ST

MARKIT REMOVE DROP - 21379 CRYSTAL FALLS DR

MARKIT REMOVE DROP - 21352 CRYSTAL FALLS DR

MARKIT LOWER OR RAISE EXISTING CABLE - 16837 W AMERICAN RIVER DR

MARKIT REMOVE HARDWARE - 14280 MONO WAY

MARKIT REPAIR/REPLACE HARDWARE - 20142 DAMBACHER DR

MARKIT STRAIGHTEN IN-LINE POLE - 20142 DAMBACHER DR

MARKIT PLACE/REPLACE DOWN GUY GUARD - 20142 DAMBACHER DR
MARKIT REPLACE/INSTALL DOWN GUY;REPLACE/INSTALL OVERHEAD GUY;TRANSFER AT&T CABLE(S);TRANSFER AT&T DROP(S);PULL OLD POLE;LEAD TAILS NO;CABLE SWING NO;TRASFER 9 - 20884 OLD PHOENIX LAKE RD

MARKIT REMOVE DROP - 21528 CRESTVIEW DR

MARKIT REMOVE DROP - 21390 GREEN MEADOW LN

MARKIT RELASH EXISTING CABLES - 21650 BELLVIEW CREEK RD

MARKIT REMOVE DROP - 21546 BELLVIEW CREEK RD

MARKIT REPAIR/REPLACE HARDWARE - 21583 HIDDEN VALLEY RD

MARKIT REPAIR/REPLACE HARDWARE - 21200 CRESTVIEW DR

MARKIT REPAIR/REPLACE HARDWARE - 21501 AMERICAN RIVER DR

MARKIT RELASH TO EXISTING MESSENGER - 11455 HIGHWAY 49

MARKIT REMOVE DROP - 16555 S CREEKSIDE DR

MARKIT REMOVE DROP - 16545 S CREEKSIDE DR

MARKIT TREE TRIMMING REQUIRED - 21572 BELLVIEW CREEK RD

MARKIT REPAIR/REPLACE HARDWARE - 19847 SOULSBYVILLE RD

MARKIT RELASH EXISTING CABLES - 16591 SALLANDER DR

MARKIT REMOVE DROP - 21952 PHOENIX LAKE RD

MARKIT REPAIR/REPLACE HARDWARE - 101 PINE ST

MARKIT PLACE ANCHOR - 75 YANEY AVE

MARKIT INTRUSIVE INSPECTION REQUIRED - 16420 PARKRIDGE AVE

MARKIT Branch on solo owned lead

MARKIT REMOVE DROP - 21373 GREEN MEADOW LN

MARKIT REMOVE DROP - 29461 SHASTA DR

MARKIT REMOVE DROP - 29831 MONO TRL

MARKIT REMOVE DROP - 25590 BAMBI LN

MARKIT REMOVE DROP - 26579 OLD MONO RD

MARKIT REMOVE DROP - 29651 LASSEN DR

MARKIT REMOVE DROP - 29678 LASSEN DR

MARKIT REMOVE DROP - 29970 MARIPOSA DR

MARKIT REMOVE DROP - 29723 MONO TRAIL

MARKIT REMOVE DROP - 25293 REBEKAH RD

MARKIT REMOVE DROP - 24881 SONORA PASS HWY

MARKIT REMOVE DROP - 25986 LONG BARN RD

MARKIT REMOVE DROP - 25198 DEBORAH DR

MARKIT REMOVE DROP - 24023 N FORK RD

MARKIT REMOVE DROP - 25970 LONG BARN RD

MARKIT REMOVE DROP - 22000 LAKEVIEW DR

MARKIT REMOVE DROP - 24822 QUARTZ AVE

MARKIT REMOVE DROP - 22305 JESSE

MARKIT REMOVE DROP - 24791 QUARTZ AVE

MARKIT REMOVE DROP - 22150 SARAH CIR

MARKIT REMOVE DROP - 25163 REBEKAH RD

MARKIT REMOVE DROP - 22165 SARAH CIRCLE

MARKIT REMOVE DROP - 25744 LONG BARN SUGAR PINE RD

MARKIT REMOVE DROP - 20020 BLACKBERRY LN

MARKIT REMOVE DROP - 20601 MORGAN DR

MARKIT REMOVE DROP - 20715 MORGAN DR

MARKIT REMOVE DROP - 19048 SECOND GARROTTE RIDGE RD

MARKIT REMOVE DROP - 21014 MORGAN DR

MARKIT REMOVE DROP - 10085 MERRELL RD

MARKIT REMOVE DROP - 20401 WHITES GULCH RD

MARKIT REMOVE DROP - 21583 HIDDEN VALLEY RD

MARKIT REMOVE DROP - 483 E JACKSON ST

MARKIT REMOVE DROP - 22460 GUNSIGHT RD

MARKIT REMOVE DROP - 11928 HIGHWAY 49

MARKIT REMOVE DROP - 449 LYONS ST

MARKIT REMOVE DROP - 22288 GUNSIGHT RD

MARKIT REMOVE DROP - 13457 JENNY LIND RD

MARKIT REMOVE DROP - 21220 OLD SONORA COLUMBIA RD

MARKIT REMOVE DROP - 1199 HIGHWAY 49

MARKIT REMOVE DROP - 21748 EL OSO WAY

MARKIT REMOVE DROP - 21241 OLD SONORA COLUMBIA RD

MARKIT RELASH TO EXISTING MESSENGER - 16537 CREEKSIDE DR

MARKIT RELASH TO EXISTING MESSENGER - 21692 BELLVIEW CREEK RD

MARKIT RELASH TO EXISTING MESSENGER - 21491 PHOENIX LAKE RD

MARKIT REPLACE/INSTALL DOWN GUY - 22859 E ELLMARO

MARKIT STRAIGHTEN IN-LINE POLE - 449 LYONS ST

MARKIT TREE TRIMMING REQUIRED - 15401 CAMINO DEL PARQUE S

MARKIT TREE TRIMMING REQUIRED - 31700 OLD STRAWBERRY RD
MARKIT REPLACE/INSTALL DOWN GUY;TRANSFER AT&T CABLE(S);PULL OLD POLE;LEAD TAILS NO;CABLE SWING NO;TRASFER 2 - 22387 BELLEVIEW RD
MARKIT REPLACE/INSTALL DOWN GUY;TRANSFER AT&T CABLE(S);TRANSFER AT&T DROP(S);PULL OLD POLE;LEAD TAILS NO;CABLE SWING NO;TRASFER 3 - 22150 PASEO DE LOS PORTALES RD
MARKIT REPLACE/INSTALL DOWN GUY;TRANSFER AT&T CABLE(S);TRANSFER AT&T DROP(S);PULL OLD POLE;LEAD TAILS NO;CABLE SWING NO;TRASFER 3 - 21820 PASEO DE LOS PORTALES RD

MARKIT TRANSFER AT&T CABLE(S);PULL OLD POLE;LEAD TAILS NO;CABLE SWING NO;TRASFER 2 - 21892 GLENWOOD RD
MARKIT REPLACE/INSTALL DOWN GUY;TRANSFER AT&T CABLE(S);TRANSFER AT&T DROP(S);PULL OLD POLE;LEAD TAILS NO;CABLE SWING NO;TRASFER 3 - 21667 CRYSTAL LAKE DR
MARKIT REPLACE/INSTALL DOWN GUY;TRANSFER AT&T CABLE(S);TRANSFER AT&T DROP(S);PULL OLD POLE;LEAD TAILS NO;CABLE SWING NO;TRASFER 3 - 21825 PHOENIX LAKE RD
MARKIT REPLACE/INSTALL DOWN GUY;TRANSFER AT&T CABLE(S);PULL OLD POLE;LEAD TAILS NO;CABLE SWING NO;TRASFER 3 - 16542 CREEKSIDE DR
MARKIT REPLACE/INSTALL DOWN GUY;TRANSFER AT&T CABLE(S);PULL OLD POLE;LEAD TAILS NO;CABLE SWING NO;TRASFER 2 - 13324 SHALE ROCK RD
MARKIT REPLACE/INSTALL DOWN GUY;TRANSFER AT&T CABLE(S);PULL OLD POLE;LEAD TAILS NO;CABLE SWING NO;TRASFER 2 - 16670 GRANITE RIDGE LN
MARKIT TRANSFER AT&T CABLE(S);TRANSFER AT&T DROP(S);PULL OLD POLE;LEAD TAILS NO;CABLE SWING NO;TRASFER 2 - 16964 W AMERICAN RIVER DR
MARKIT REPLACE/INSTALL DOWN GUY;TRANSFER AT&T CABLE(S);TRANSFER AT&T DROP(S);PULL OLD POLE;LEAD TAILS NO;CABLE SWING NO;TRASFER 3 - 22141 CRYSTAL FALLS DR
MARKIT REPLACE/INSTALL DOWN GUY;TRANSFER AT&T CABLE(S);PULL OLD POLE;LEAD TAILS NO;CABLE SWING NO;TRASFER 2 - 21756 WATER OAK DR
MARKIT REPLACE/INSTALL DOWN GUY;TRANSFER AT&T CABLE(S);TRANSFER AT&T DROP(S);PULL OLD POLE;LEAD TAILS NO;CABLE SWING NO;TRASFER 3 - 21346 EVERGREEN WAY
MARKIT REPLACE/INSTALL DOWN GUY;TRANSFER AT&T CABLE(S);PULL OLD POLE;LEAD TAILS NO;CABLE SWING NO;TRASFER 2 - 22451 SPRING CREEK RD
MARKIT REPLACE/INSTALL DOWN GUY;TRANSFER AT&T CABLE(S);TRANSFER AT&T DROP(S);PULL OLD POLE;LEAD TAILS NO;CABLE SWING NO;TRASFER 3 - 22404 GUNSIGHT RD
MARKIT TRANSFER AT&T CABLE(S);TRANSFER AT&T DROP(S);PULL OLD POLE;LEAD TAILS NO;CABLE SWING NO;TRASFER 2 - 16980 COLUMBIA RIVER DR
MARKIT REPLACE/INSTALL DOWN GUY;TRANSFER AT&T CABLE(S);TRANSFER AT&T DROP(S);PULL OLD POLE;LEAD TAILS NO;CABLE SWING NO;TRASFER 3 - 16990 W AMERICAN RIVER DR
MARKIT REPLACE/INSTALL DOWN GUY;TRANSFER AT&T CABLE(S);PULL OLD POLE;LEAD TAILS NO;CABLE SWING NO;TRASFER 2 - 13707 JENNY LIND RD
MARKIT REPLACE/INSTALL DOWN GUY;TRANSFER AT&T CABLE(S);PULL OLD POLE;LEAD TAILS NO;CABLE SWING NO;TRASFER 2 - 20525 CHARLOTTE CT
MARKIT REPLACE/INSTALL DOWN GUY;TRANSFER AT&T CABLE(S);TRANSFER AT&T DROP(S);PULL OLD POLE;LEAD TAILS NO;CABLE SWING NO;TRASFER 3 - 16503 CREEKSIDE DR
MARKIT TRANSFER AT&T CABLE(S);TRANSFER AT&T DROP(S);PULL OLD POLE;LEAD TAILS NO;CABLE SWING NO;TRASFER 2 - 20680 CHARLOTTE CT
MARKIT REPLACE/INSTALL DOWN GUY;TRANSFER AT&T CABLE(S);TRANSFER AT&T DROP(S);PULL OLD POLE;LEAD TAILS NO;CABLE SWING NO;TRASFER 3 - 15559 DEL PARQUE CT
MARKIT REPLACE/INSTALL DOWN GUY;TRANSFER AT&T CABLE(S);TRANSFER AT&T DROP(S);PULL OLD POLE;LEAD TAILS NO;CABLE SWING NO;TRASFER 3 - 21301 AMERICAN RIVER DR
MARKIT TRANSFER AT&T CABLE(S);TRANSFER AT&T DROP(S);PULL OLD POLE;LEAD TAILS NO;CABLE SWING NO;TRASFER 2 - 16548 S CREEKSIDE DR
MARKIT REPLACE/INSTALL DOWN GUY;TRANSFER AT&T CABLE(S);PULL OLD POLE;LEAD TAILS NO;CABLE SWING NO;TRASFER 2 - 15424 PASEO DE LOS ROBLES RD

MARKIT TRANSFER AT&T CABLE(S);TRANSFER AT&T DROP(S);PULL OLD POLE;LEAD TAILS NO;CABLE SWING NO;TRASFER 2 - 22265 CRYSTAL FALLS CT
MARKIT TRANSFER AT&T CABLE(S);TRANSFER AT&T DROP(S);PULL OLD POLE;LEAD TAILS NO;CABLE SWING NO;TRASFER 2 - 16555 S CREEKSIDE DR
MARKIT REPLACE/INSTALL DOWN GUY;TRANSFER AT&T CABLE(S);TRANSFER AT&T DROP(S);PULL OLD POLE;LEAD TAILS NO;CABLE SWING NO;TRASFER 3 - 21778 EL COYOTE DR
MARKIT REPLACE/INSTALL DOWN GUY;TRANSFER AT&T CABLE(S);TRANSFER AT&T DROP(S);PULL OLD POLE;LEAD TAILS NO;CABLE SWING NO;TRASFER 3 - 16932 W AMERICAN RIVER DR
MARKIT REPLACE/INSTALL DOWN GUY;TRANSFER AT&T CABLE(S);TRANSFER AT&T DROP(S);PULL OLD POLE;LEAD TAILS NO;CABLE SWING NO;TRASFER 3 - 17384 CARLOZZI DR
MARKIT TRANSFER AT&T CABLE(S);PULL OLD POLE;LEAD TAILS NO;CABLE SWING NO;TRASFER 1 - 20615 STEVEN CT
MARKIT REPLACE/INSTALL DOWN GUY;TRANSFER AT&T CABLE(S);TRANSFER AT&T DROP(S);PULL OLD POLE;LEAD TAILS NO;CABLE SWING NO;TRASFER 3 - 21639 CRYSTAL LAKE DR
MARKIT REPLACE/INSTALL DOWN GUY;TRANSFER AT&T CABLE(S);TRANSFER AT&T DROP(S);PULL OLD POLE;LEAD TAILS NO;CABLE SWING NO;TRASFER 3 - 16080 HIDDEN VALLEY RD
MARKIT REPLACE/INSTALL DOWN GUY;TRANSFER AT&T CABLE(S);TRANSFER AT&T TERMINAL(S);TRANSFER AT&T DROP(S);PULL OLD POLE;LEAD TAILS NO;CABLE SWING NO;TRASFER 4 - 21379 CRYSTAL FALLS DR
MARKIT TRANSFER AT&T CABLE(S);TRANSFER AT&T DROP(S);PULL OLD POLE;LEAD TAILS NO;CABLE SWING NO;TRASFER 2 - 11050 S PONDEROSA WAY
MARKIT REPLACE/INSTALL DOWN GUY;TRANSFER AT&T CABLE(S);TRANSFER AT&T DROP(S);PULL OLD POLE;LEAD TAILS NO;CABLE SWING NO;TRASFER 3 - 19048 SECOND GARROTTE RIDGE RD
MARKIT REPLACE/INSTALL DOWN GUY;TRANSFER AT&T CABLE(S);TRANSFER AT&T DROP(S);PULL OLD POLE;LEAD TAILS YES;CABLE SWING NO;TRASFER 3 - 23071 HELLS HOLLOW RD
MARKIT TRANSFER AT&T CABLE(S);TRANSFER AT&T DROP(S);PULL OLD POLE;LEAD TAILS NO;CABLE SWING NO;TRASFER 2 - 11220 INSPIRATION DR
MARKIT TRANSFER AT&T CABLE(S);TRANSFER AT&T DROP(S);PULL OLD POLE;LEAD TAILS NO;CABLE SWING NO;TRASFER 2 - 20010 CHEROKEE TRL
MARKIT TRANSFER AT&T CABLE(S);TRANSFER AT&T DROP(S);PULL OLD POLE;LEAD TAILS NO;CABLE SWING NO;TRASFER 2 - 19701 OLD HIGHWAY 120
MARKIT TRANSFER AT&T CABLE(S);TRANSFER AT&T DROP(S);PULL OLD POLE;LEAD TAILS NO;CABLE SWING NO;TRASFER 2 - 20892 MCKINLEY WAY
MARKIT TRANSFER AT&T CABLE(S);PULL OLD POLE;LEAD TAILS NO;CABLE SWING NO;TRASFER 1 - 20010 CHEROKEE TRL
MARKIT REPLACE/INSTALL DOWN GUY;TRANSFER AT&T CABLE(S);PULL OLD POLE;LEAD TAILS NO;CABLE SWING NO;TRASFER 2 - 10831 MERRELL RD
MARKIT REPLACE/INSTALL DOWN GUY;TRANSFER AT&T CABLE(S);TRANSFER AT&T DROP(S);PULL OLD POLE;LEAD TAILS YES;CABLE SWING NO;TRASFER 3 - 19060 SECOND GARROTTE RIDGE RD
MARKIT TRANSFER AT&T CABLE(S);TRANSFER AT&T DROP(S);PULL OLD POLE;LEAD TAILS NO;CABLE SWING NO;TRASFER 2 - 11090 YOSEMITE SPRINGS RD
MARKIT REPLACE/INSTALL DOWN GUY;TRANSFER AT&T CABLE(S);TRANSFER AT&T DROP(S);PULL OLD POLE;LEAD TAILS NO;CABLE SWING NO;TRASFER 3 - 15485 PASEO DE LOS ROBLES RD
MARKIT REPLACE/INSTALL DOWN GUY;TRANSFER AT&T CABLE(S);TRANSFER AT&T DROP(S);PULL OLD POLE;LEAD TAILS NO;CABLE SWING NO;TRASFER 3 - 21488 AMERICAN RIVER DR

MARKIT REPLACE/INSTALL DOWN GUY;TRANSFER AT&T CABLE(S);TRANSFER AT&T DROP(S);PULL OLD POLE;LEAD TAILS NO;CABLE SWING NO;TRASFER 3 - 16879 W AMERICAN RIVER DR
MARKIT REPLACE/INSTALL DOWN GUY;TRANSFER AT&T CABLE(S);TRANSFER AT&T DROP(S);PULL OLD POLE;LEAD TAILS NO;CABLE SWING NO;TRASFER 3 - 17326 KELLEHER CT
MARKIT REPLACE/INSTALL DOWN GUY;TRANSFER AT&T CABLE(S);TRANSFER AT&T DROP(S);PULL OLD POLE;LEAD TAILS NO;CABLE SWING NO;TRASFER 3 - 21301 RIDGEVIEW DR
MARKIT REPLACE/INSTALL DOWN GUY;TRANSFER AT&T CABLE(S);TRANSFER AT&T TERMINAL(S);TRANSFER AT&T DROP(S);PULL OLD POLE;LEAD TAILS NO;CABLE SWING NO;TRASFER 4 - 21413 GREEN OAKS CT

MARKIT REMOVE DROP - 23918 REDWOOD DR

MARKIT VEGETATION REMOVAL REQUIRED - 17545 MOUNT ELIZABETH DR

MARKIT REMOVE DROP - 21101 TAISMU CT

MARKIT TREE TRIMMING REQUIRED - 23310 SONORA PASS HWY

MARKIT REMOVE DROP - 17765 GOOD SHEPHERD DR

MARKIT REMOVE DROP - 23945 CROSSLEY WAY

MARKIT REMOVE DROP - 20720 CHIEF FULLER RD

MARKIT REMOVE DROP - 19495 CONFIDENCE MINE CT

MARKIT REMOVE DROP - 23705 SONORA PASS HWY

MARKIT REMOVE DROP - 17710 LUCKY STRIKE TRL

MARKIT REMOVE DROP - 26591 CRYSTAL RD

MARKIT REMOVE DROP - 24934 BOTTINI APPLE RANCH RD

MARKIT REMOVE DROP - 25880 LONG BARN RD

MARKIT REMOVE DROP - 25088 SONORA PASS HWY

MARKIT REMOVE DROP - 25096 DEBORAH DR

MARKIT REMOVE DROP - 25312 ESTHER AVE

MARKIT REMOVE DROP - 23957 REDWOOD CT

MARKIT REMOVE DROP - 22919 MEADOW DR

MARKIT REMOVE DROP - 24220 S FORK RD

MARKIT REMOVE DROP - 24211 GOLF LINKS DR

MARKIT REMOVE DROP - 18911 MIDDLE CAMP RD

MARKIT REMOVE DROP - 17220 SMOKEY RIVER DR

MARKIT TREE TRIMMING REQUIRED - 17220 SMOKEY RIVER DR

MARKIT REMOVE DROP - 24471 QUARTER HORSE DR

MARKIT RELASH EXISTING CABLES - 18443 HILLCREST RD

MARKIT REMOVE DROP - 25110 SONORA PASS HWY

MARKIT REMOVE DROP - 25375 DAVID DR

MARKIT REMOVE DROP - 22364 BEERSHEBA

MARKIT REMOVE DROP - 20846 TELELE TRL

MARKIT REMOVE DROP - 23937 PINE LAKE DR

MARKIT REMOVE DROP - 24295 JUNIPER ST

MARKIT REMOVE DROP - 16669 MADRONE CIR

MARKIT REMOVE DROP - 23954 PINE LAKE DR

MARKIT REMOVE DROP - 22533 LONGEWAY RD

MARKIT REMOVE DROP - 25210 ABRAHAM AVE

MARKIT REMOVE DROP - 24967 SONORA PASS HWY

MARKIT REMOVE DROP - 17344 MOUNT ELIZABETH DR

MARKIT REMOVE DROP - 22524 LITTLE JOHN DR

MARKIT REMOVE DROP - 23233 CRESTA DR

MARKIT REMOVE DROP - 17081 CARRIAGE RD

MARKIT REMOVE DROP - 24046 GOLF LINKS DR

MARKIT REMOVE DROP - 19775 WESTVIEW DR

MARKIT PLACE/REPLACE DOWN GUY GUARD - 22918 LAZY Z LN

MARKIT REMOVE DROP - 16961 BROKEN PINE RD

MARKIT PLACE/REPLACE DOWN GUY GUARD - 22932 LAZY Z LN

MARKIT REMOVE DROP - 20911 LAMA ROAD TAMALIN

MARKIT RAISE AT&T SERVICE DROP - 24360 PELA RD

MARKIT REMOVE DROP - 24309 JEFFREY ST

MARKIT REMOVE DROP - 23532 LAKEWOOD DR

MARKIT REMOVE DROP - 24030 PINE CONE RD

MARKIT REMOVE DROP - 24110 PAIPU RD

MARKIT REMOVE DROP - 20825 KOINONIA CT

MARKIT TREE TRIMMING REQUIRED - 22523 TWAIN HARTE DR

MARKIT REMOVE DROP - 22356 N TUOLUMNE RD

MARKIT REMOVE DROP - 23882 PINE LAKE DR

MARKIT REMOVE DROP - 20260 LILAC LN

MARKIT REMOVE DROP - 16911 ESTRALITA DR

MARKIT REMOVE DROP - 17278 MOUNT ELIZABETH DR

MARKIT REMOVE DROP - 22545 WILDCAT RIDGE RD

MARKIT REMOVE DROP - 24172 GOLF LINKS DR

MARKIT REMOVE DROP - 22590 LONGEWAY RD

MARKIT REMOVE DROP - 22590 LONGEWAY RD

MARKIT REMOVE DROP - 24280 GOLF LINKS DR

MARKIT REMOVE DROP - 23280 CRESTA DR

MARKIT REMOVE DROP - 24291 WHITE FIR DR

MARKIT RELASH TO EXISTING MESSENGER - 20803 MUHELI RD

MARKIT REMOVE DROP - 17276 NILE RIVER DR

MARKIT TREE TRIMMING REQUIRED - 17689 LUCKY STRIKE TRAIL

MARKIT REMOVE DROP - 23835 CONFIDENCE SOUTH FORK RD

MARKIT REMOVE DROP - 18991 MIDDLE CAMP RD

MARKIT REMOVE DROP - 16869 E BROOKSIDE DR

MARKIT REMOVE DROP - 22929 GOLF CLUB DR

MARKIT REMOVE DROP - 23816 PINE LAKE DR

MARKIT VEGETATION REMOVAL REQUIRED - 23056 TWAIN HARTE DR

MARKIT RAISE AT&T SERVICE DROP - 23056 TWAIN HARTE DR

MARKIT REMOVE DROP - 23862 MARSHALL WAY

MARKIT REMOVE DROP - 23699 SONORA PASS HWY

MARKIT REMOVE DROP - 22870 LAZY Z LN

MARKIT REMOVE DROP - 20998 LAMA ROAD TEUMETE

MARKIT REMOVE DROP - 24740 SONORA PASS HWY

MARKIT REMOVE DROP - 23760 CONFIDENCE SOUTH FORK RD

MARKIT REMOVE DROP - 23598 ONTARIO DR

MARKIT REMOVE DROP - 22497 S FORK RD

MARKIT RELASH EXISTING CABLES - 22497 S FORK RD

MARKIT PLACE/REPLACE DOWN GUY GUARD - 23763 FREMONT WAY

MARKIT RAISE AT&T SERVICE DROP - 23227 CRESTA DR

MARKIT REMOVE DROP - 20811 KOTEO LN

MARKIT REMOVE DROP - 24548 SONORA PASS HWY

MARKIT REMOVE DROP - 24083 PINE LAKE DR

MARKIT REMOVE DROP - 24326 LAVENE CT

MARKIT REMOVE DROP - 24123 WUUYA WAY

MARKIT REMOVE DROP - 19414 SUPERIOR DR

MARKIT REMOVE DROP - 24230 KALANU PL

MARKIT REMOVE DROP - 20992 LAMA ROAD TEUMETE

MARKIT REMOVE DROP - 24034 PINE LAKE DR

MARKIT REMOVE DROP - 17247 NILE RIVER DR

MARKIT REMOVE DROP - 24091 GOLF LINKS DR

MARKIT REMOVE DROP - 16632 SADDLE CT

MARKIT REMOVE DROP - 17457 SMOKEY RIVER DR

MARKIT REMOVE DROP - 16961 E BROOKSIDE DR

MARKIT REMOVE DROP - 16688 W BROOKSIDE DR

MARKIT REMOVE DROP - 22330 GERALDINE CIR

MARKIT REMOVE DROP - 20704 TELELE TRAIL

MARKIT REMOVE DROP - 19778 WANITA LN

MARKIT REMOVE DROP - 19215 SUPERIOR DR

MARKIT REMOVE DROP - 22709 TWAIN HARTE DR

MARKIT REMOVE DROP - 22932 LAZY Z LN

MARKIT REMOVE DROP - 18950 HURON DR

MARKIT REMOVE DROP - 23819 PINE LAKE DR

MARKIT REMOVE DROP - 22581 E RHINE RIVER DR

MARKIT REMOVE DROP - 22358 ROBIN HOOD DR

MARKIT REMOVE DROP - 24152 OLO WIN TRL

MARKIT REMOVE DROP - 24039 LAMA RD

MARKIT REMOVE DROP - 22470 COLORADO RIVER DR

MARKIT REMOVE DROP - 18890 MIDDLE CAMP SUGAR PINE RD

MARKIT REMOVE DROP - 18920 MIDDLE CAMP RD

MARKIT REMOVE DROP - 20668 HEKEKE LN

MARKIT REMOVE CABLE - 22814 BLACK HAWK DR

MARKIT REMOVE DROP - 22120 N TUOLUMNE RD

MARKIT Lashing wire is hanging close to the ground and cable is low as well

MARKIT REMOVE DROP - 10386 FISKE HILL RD
MARKIT CR Self-Support, Wire down. Over 500 feet. Needs Construction Department to hang high enough over corn equipment. Come-A-Long needed.
MARKIT 25 pr cable hanging low at 11 ft over private driveway that is used by large trucks. Used rope to temp pull cable up for clearance.
MARKIT Lashing separated from cable. Cable hanging below 2-3 ft. Cable also low over driveway. Poles are both end leaning in toward road.

MARKIT 3 poles down due to rains

MARKIT 20795-1 e Columbia

MARKIT PGE drop hanging low across the road goes into tree looks abandoned

Cable 1 - Cable on Ground. Accessible to Public

MARKIT TREE TRIMMING REQUIRED - 15611 NEW PEORIA FLAT RD

MARKIT VEGETATION REMOVAL REQUIRED - 13979 OLD COULTERVIL

MARKIT VEGETATION REMOVAL REQUIRED - 18508 LIME KILN RD

MARKIT TREE TRIMMING REQUIRED - 20129 MONO HWY

MARKIT Cable and drops on ground hazard to public

MARKIT Drop down pole 121265810

MARKIT Lashing wire hanging down. Pole 110534250

MARKIT Drop needs to be removed from abandoned house

MARKIT Tree needs to be trimmed away from aerial cable
MARKIT Clearance pole that supports ASW is rotten and needs to be replaced so that ASW can be raised to increase height more than 10 ft

LATITUDE	LONGITUDE	GO95_INFRACTION_ID	HAZARD_LEVEL	FIRE_TIER
37.758095	-120.158073	128732	2b	3
37.69875	-120.335342	127224	2a	2
37.631448	-120.335364	127438	2b	2
37.710049	-120.348366	127362	2b	2
37.720081	-120.314304	127503	2b	2
37.64738	-120.331106	127766	2b	2
37.647379	-120.345422	127659	2b	2
37.717524	-120.346994	127658	2b	2
37.64758	-120.356249	127490	2b	2
37.652323	-120.327589	127621	2b	2
37.745636	-120.339905	127152	2c	2
37.693063	-120.329762	127145	2c	2
37.726948	-120.313454	127140	2c	2
37.722293	-120.32025	127137	2c	2
37.653034	-120.349846	127119	2c	2
37.668747	-120.319275	127411	2c	2
37.679558	-120.330352	127103	2c	2
37.717157	-120.315272	127747	2c	2
37.68883	-120.327155	127097	2c	2
37.647474	-120.352922	127050	2c	2
37.63569	-120.349299	127031	2c	2

37.72282	-120.318283	127686	2c	2
37.653321	-120.349295	127270	2c	2
37.671456	-120.357389	127242	2c	2
37.638133	-120.358112	127228	2c	2
37.69875	-120.335342	127223	2c	2
37.639346	-120.357683	127198	2c	2
37.642222	-120.351641	127197	2c	2
37.661593	-120.31683	127193	2c	2
37.670922	-120.36239	127175	2c	2
37.676247	-119.778793	127922	3	2
37.673042	-119.807213	127854	3	2
37.725414	-120.324654	127030	3	2
37.708939	-120.33316	127029	3	2
37.708939	-120.33316	127028	3	2
37.659599	-120.328995	127027	3	2
37.709245	-120.333038	127022	3	2
37.837875	-120.23033	127005	3	2
37.83783	-120.230674	126996	3	2
37.836558	-120.236131	126980	3	2
37.702011	-120.341202	127162	3	2
37.716342	-120.330618	127156	3	2

37.716342	-120.330618	127155	3	2
37.722813	-120.332108	127147	3	2
37.67934	-120.361995	127142	3	2
37.726948	-120.313454	127139	3	2
37.722293	-120.32025	127138	3	2
37.676953	-120.3648	127136	3	2
37.717727	-120.32773	127134	3	2
37.717727	-120.32773	127133	3	2
37.691502	-120.328485	127129	3	2
37.728334	-120.339291	127124	3	2
37.731644	-120.344508	127470	3	2
37.659038	-120.314095	127466	3	2
37.659038	-120.314095	127464	3	2
37.631443	-120.340578	127462	3	2
37.637471	-120.352699	127459	3	2
37.731231	-120.345016	127451	3	2
37.717548	-120.346463	127448	3	2
37.72254	-120.318922	127444	3	2
37.646534	-120.328907	127440	3	2
37.628998	-120.308369	127439	3	2
37.645525	-120.320674	127427	3	2
37.676798	-120.333848	127415	3	2

37.727654	-120.342537	127403	3	2
37.723255	-120.317917	127400	3	2
37.72747	-120.339157	127395	3	2
37.717304	-120.325787	127390	3	2
37.717304	-120.325787	127389	3	2
37.640637	-120.324295	127383	3	2
37.724712	-120.351929	127378	3	2
37.675667	-120.367878	127357	3	2
37.69126	-120.32495	127349	3	2
37.674985	-120.320085	127348	3	2
37.661401	-120.329808	127340	3	2
37.633667	-120.310004	127338	3	2
37.633476	-120.327789	127337	3	2
37.714031	-120.325723	127333	3	2
37.687695	-120.326887	127570	3	2
37.638973	-120.357225	127558	3	2
37.711782	-120.328453	127523	3	2
37.716623	-120.324292	127508	3	2
37.630739	-120.313709	127305	3	2
37.659215	-120.313362	127298	3	2
37.715902	-120.332225	127292	3	2
37.673517	-120.36984	127674	3	2

37.719062	-120.310464	127657	3	2
37.720517	-120.323317	127654	3	2
37.684418	-120.33061	127638	3	2
37.721529	-120.323453	127476	3	2
37.641161	-120.324545	127729	3	2
37.731026	-120.350861	127724	3	2
37.629368	-120.308205	127095	3	2
37.673847	-120.343343	127085	3	2
37.69506	-120.332605	127069	3	2
37.713492	-120.336905	127604	3	2
37.638025	-120.356831	127590	3	2
37.7198	-120.309166	127042	3	2
37.726167	-120.35457	127700	3	2
37.726219	-120.322962	127261	3	2
37.676769	-120.327148	127231	3	2
37.688541	-120.33252	127220	3	2
37.635804	-120.308948	127218	3	2
37.712948	-120.329147	127202	3	2
37.631065	-120.357262	127189	3	2
37.674606	-119.78492	127917	2	2
37.675911	-119.781013	127898	2	2
37.672638	-119.796997	127897	2	2

37.838036	-120.229576	126965	2	2
37.716682	-119.656235	127773	3	2
37.720707	-119.694473	127858	2	2
37.975738	-120.269553	126767	2a	2
37.952708	-120.348908		2a	
37.976312	-120.26939	126844	3	2
37.976295	-120.265411	126746	3	2
37.976312	-120.26939	126843	2	2
37.965668	-120.40007	127205	2a	2
37.962708	-120.400734	127513	2a	2
37.982052	-120.274857	127772	2b	2
37.978214	-120.271515	127528	2b	2
37.928066	-120.353119	127598	2b	2
37.957752	-120.319969	127358	2b	2
37.917342	-120.414917	126750	2c	2
37.965668	-120.40007	127204	2c	2
37.909346	-120.416938	126956	2c	2
37.909738	-120.416165	126828	2c	2
37.867043	-120.42518	126911	2c	2
37.85596	-120.370318	126778	3	2
37.872888	-120.432908	126815	3	2
37.917537	-120.413594	126849	3	2

37.865505	-120.439325	126803	3	2
37.875153	-120.392627	126912	3	2
37.864273	-120.382858	126769	3	2
37.916275	-120.414749	126929	3	2
37.94696	-120.333931	127445	3	2
37.992718	-120.276558	127867	3	2
37.919653	-120.41455	126908	3	2
37.9179	-120.410072	126937	3	2
37.977104	-120.264839	127106	3	2
37.875063	-120.398067	126893	3	2
37.965073	-120.403503	127275	3	2
37.858394	-120.390395	126743	3	2
37.917342	-120.414917	126751	3	2
37.876091	-120.379868	126852	3	2
37.873875	-120.384666	126833	3	2
37.857306	-120.368929	126760	3	2
37.870587	-120.433095	126792	3	2
37.979618	-120.268814	127405	3	2
37.9179	-120.410072	126936	3	2
37.977764	-120.271591	127499	3	2
37.857306	-120.368929	126761	3	2
37.983765	-120.384132	126532	3	2

37.974964	-120.392738	126732	3	2
37.875121	-120.401706	126899	3	2
37.87458	-120.384278	126787	3	2
37.850935	-120.359548	126986	3	2
37.949406	-120.381638	127211	3	2
37.965668	-120.40007	127203	3	2
37.964588	-120.400948	127511	3	2
37.841274	-120.344719	127008	3	2
37.949799	-120.382225	127660	3	2
37.982777	-120.388039	126287	3	2
37.994656	-120.26535	127384	3	2
37.919404	-120.41439	126752	3	2
37.878674	-120.40052	126840	3	2
37.869865	-120.433362	126933	3	2
37.860133	-120.377478	126802	3	2
37.868365	-120.435195	126930	3	2
37.963745	-120.401909	127233	3	2
37.980103	-120.385338	126296	3	2
37.872837	-120.397285	126878	3	2
37.880581	-120.40086	126845	3	2
37.956776	-120.313911	127481	3	2

37.880234	-120.394981	126882	3	2
37.846549	-120.348444	127017	3	2
37.874329	-120.398758	126896	3	2
37.916156	-120.41411	126866	3	2
37.872524	-120.432945	126745	3	2
37.879756	-120.399039	126807	3	2
37.963696	-120.39994	127456	3	2
37.948002	-120.345749	127479	3	2
37.9179	-120.410072	126938	3	2
37.877733	-120.395561	126832	3	2
37.952637	-120.350403	127555	3	2
37.883643	-120.439527	126851	3	2
37.947971	-120.347809	127114	3	2
37.880018	-120.400305	126820	3	2
37.919404	-120.41439	126753	3	2
37.88266	-120.438663	126897	3	2
37.999043	-120.270592	127808	2	2
37.9823	-120.391052	126107	2	2
37.876575	-120.398415	126773	2	2
37.945934	-120.390442	127498	2	2
37.963696	-120.39994	127457	2	2
37.948818	-120.39016	127200	2	2

37.915558	-120.414181	126853	2	2
37.971958	-120.292976	127255	2	2
37.951729	-120.328651	127058	2	2
37.963745	-120.401909	127234	2	2
38.041817	-120.320206	126885	2a	3
38.006405	-120.387062	126329	2a	3
38.022873	-120.380508	126942	2b	3
38.035084	-120.378853	126791	2b	3
38.019588	-120.389618	126522	2b	3
37.995956	-120.360947	126460	2b	3
37.987541	-120.373589	126377	2b	3
38.019901	-120.386391	126310	2b	3
38.030617	-120.378342	126131	2b	3
37.832413	-120.243912	127721	2c	3
38.155067	-120.053902	126328	2c	3
38.007919	-120.305069	127047	3	3
38.042057	-120.319801	126891	3	3
38.020454	-120.385376	126883	3	3
38.045387	-120.323891	126869	3	3
38.050491	-120.306381	126813	3	3
38.045673	-120.34967	126628	3	3
38.039745	-120.377831	126608	3	3

38.043404	-120.376312	126588	3	3
38.033485	-120.378769	126551	3	3
37.835996	-120.238322	127760	3	3
37.82188	-120.231239	127735	3	3
37.832413	-120.243912	127722	3	3
37.834244	-120.210182	127661	3	3
37.835602	-120.238892	127606	3	3
37.834946	-120.191101	127569	3	3
37.83593	-120.187759	127480	3	3
37.828808	-120.23488	127449	3	3
37.827599	-120.235771	127126	3	3
37.835911	-120.214314	127076	3	3
37.836926	-120.189323	127052	3	3
38.019157	-120.303223	127725	3	3
38.015381	-120.306007	127653	3	3
38.02037	-120.271011	127473	3	3
38.157246	-120.052727	126121	3	3
38.045429	-120.321793	126722	1	3
38.022873	-120.380508	126941	2	3
38.008488	-120.387741	126838	2	3
38.008068	-120.38736	126829	2	3
38.041168	-120.343216	126569	2	3

38.040344	-120.375244	126367	2	3
38.037704	-120.382828	126204	2	3
38.002167	-120.383934	126087	2	3
38.028492	-120.366486	125960	2	3
37.83291	-120.208629	126976	2	3
38.014805	-120.273254	127637	2	3
38.021557	-120.305763	127582	2	3
38.02037	-120.271011	127472	2	3
38.019257	-120.280159	127279	2	3
38.158207	-120.056091	126461	2	3
38.162334	-120.050354	126330	2	3
38.162621	-120.051765	126030	2	3
37.057951	-120.840847		2	
37.986523	-120.446047		2a	
37.371275	-120.605547		3	
37.265508	-120.472213		3	
37.96283	-120.406453		1	
38.032685	-120.27005		1	1
38.009507	-120.274686		3	
38.01112	-120.279801		3	
37.051843	-119.992424		2	
37.752815	-120.128258	379386	3	3

37.932373	-120.445557	379196	2b	2
37.933376	-120.45163	379192	2b	2
37.904873	-120.453461	379190	2b	2
37.891085	-120.544945	378957	2b	2
37.905571	-120.506943	378942	2b	2
37.874317	-120.451241	378940	2b	2
37.888985	-120.486801	378927	2b	2
37.881271	-120.455505	378912	2b	2
37.896965	-120.480522	378907	2b	2
37.95697	-120.431984	379763	2b	2
37.962666	-120.407753	379747	2b	2
37.96537	-120.407745	379625	2b	2
37.944614	-120.424248	379582	2b	2
37.94099	-120.415604	379543	2b	2
37.945786	-120.417542	379510	2b	2
37.965055	-120.406999	379495	2b	2
37.962864	-120.413414	379315	2b	2
37.948188	-120.419035	379296	2b	2
37.942631	-120.430336	379286	2b	2
37.933842	-120.451591	379242	2b	2
37.934143	-120.446678	379241	2b	2
37.934814	-120.444237	379240	2b	2

37.691483	-120.383698	467090	2b	2
37.691483	-120.383698	467089	2b	2
37.956432	-120.425323	380366	2b	2
37.95253	-120.41571	380358	2b	2
37.944778	-120.417091	380355	2b	2
37.944176	-120.428215	380332	2b	2
37.942123	-120.431091	380283	2b	2
37.965656	-120.430496	380281	2b	2
37.955598	-120.426937	380273	2b	2
37.956596	-120.431252	380239	2b	2
37.949631	-120.424767	380230	2b	2
37.957901	-120.432571	380199	2b	2
37.966801	-120.432487	380131	2b	2
37.957489	-120.428268	380130	2b	2
37.950737	-120.420715	380112	2b	2
37.966373	-120.406693	380052	2b	2
37.962462	-120.410999	380051	2b	2
37.952194	-120.41468	380043	2b	2
37.958912	-120.42469	380027	2b	2
37.956184	-120.418045	380020	2b	2
37.963818	-120.428865	379956	2b	2
37.966372	-120.411307	379946	2b	2

37.948086	-120.42652	379855	2b	2
37.958439	-120.432281	379844	2b	2
37.941555	-120.415665	379836	2b	2
37.94399	-120.416731	379795	2b	2
37.936935	-120.42305	379188	2b	2
37.920216	-120.417931	379179	2b	2
37.932368	-120.449644	379176	2b	2
37.887871	-120.534325	379158	2b	2
37.900318	-120.478874	379142	2b	2
37.892464	-120.484871	379127	2b	2
37.88829	-120.519043	379123	2b	2
37.888237	-120.524773	379122	2b	2
37.89296	-120.544609	379098	2b	2
37.925505	-120.526549	379093	2b	2
37.893748	-120.551838	379081	2b	2
37.904007	-120.505836	379067	2b	2
37.88311	-120.44825	379057	2b	2
37.906567	-120.508659	379022	2b	2
37.891817	-120.549027	379004	2b	2
37.886417	-120.510185	379001	2b	2
37.888359	-120.529839	378998	2b	2
37.888844	-120.493851	378963	2b	2

37.895332	-120.553001	378961	2b	2
37.888523	-120.504379	378958	2b	2
37.931137	-120.422066	379225	2b	2
37.933552	-120.44574	379219	2b	2
37.912209	-120.451851	379210	2b	2
37.904446	-120.453545	379209	2b	2
37.865433	-120.439285	379203	3	2
37.864853	-120.445343	379201	3	2
37.864853	-120.445343	379200	3	2
37.901398	-120.453926	379198	3	2
37.900955	-120.477432	378926	3	2
37.878788	-120.451698	378925	3	2
37.885761	-120.499328	378894	3	2
37.944614	-120.424248	379581	3	2
37.956352	-120.402618	379526	3	2
37.972923	-120.461647	379494	3	2
37.95219	-120.415779	379473	3	2
37.943047	-120.42981	379454	3	2
37.93676	-120.4282	379399	3	2
37.946194	-120.426262	379350	3	2
37.952869	-120.457619	379302	3	2
37.927841	-120.426033	379246	3	2

37.906681	-120.452698	379238	3	2
37.920631	-120.449821	379234	3	2
37.931236	-120.447105	379233	3	2
37.942123	-120.431091	380282	3	2
37.950737	-120.420715	380113	3	2
37.956184	-120.418045	380019	3	2
37.963818	-120.428865	379955	3	2
37.941555	-120.415665	379837	3	2
37.892463	-120.446647	379189	3	2
37.934925	-120.443298	379185	3	2
37.864323	-120.442169	379181	3	2
37.902401	-120.453873	379180	3	2
37.888069	-120.49559	378991	3	2
37.891418	-120.445457	379222	3	2
37.904083	-120.453751	379215	3	2
37.908813	-120.466614	378968	3	2
37.909351	-120.452286	379208	3	2
37.954952	-120.413826	379467	2	2
37.959251	-120.429466	379400	2	2
37.940472	-120.434074	380186	2	2
37.952194	-120.41468	380042	2	2
37.954343	-120.413908	379921	2	2

37.960396	-120.429825	379871	2	2
37.945683	-120.43071	379847	2	2
37.880108	-120.45591	379140	2	2
38.195412	-119.991676	467134	2b	3
38.201061	-120.000801	380575	2b	3
38.155701	-120.054886	380571	2b	3
38.155701	-120.054886	380569	2b	3
38.201237	-120.001404	380538	2b	3
38.157871	-120.05632	380530	2b	3
38.157871	-120.05632	380529	2b	3
38.157871	-120.05632	380528	2b	3
38.155106	-120.055908	380515	2b	3
38.200535	-120.002213	380495	2b	3
38.200535	-120.002213	380494	2b	3
38.158764	-120.054871	380488	2b	3
38.156372	-120.050629	380474	2b	3
38.147316	-120.074341	380467	2b	3
38.161602	-120.04995	380402	2b	3
37.832405	-120.243996	380044	2b	3
37.835537	-120.2388	379862	3	3
37.825577	-120.234184	379797	3	3
37.836441	-120.236229	379701	3	3

37.821632	-120.231171	379602	3	3
37.843479	-120.224175	379578	3	2
37.828194	-120.234329	379537	3	3
37.827644	-120.235649	379516	3	3
37.841354	-120.169281	379409	3	3
37.814774	-120.130501	380360	3	3
37.83474	-120.191185	380247	3	3
37.836845	-120.188629	380211	3	3
37.828743	-120.234772	379993	3	3
37.83408	-120.17614	379859	2	3
37.837521	-120.179092	379733	2	3
37.831818	-120.201195	379536	2	3
37.836227	-120.187653	379346	2	3
38.029114	-120.36647	466990	2b	3
38.03426	-120.379135	466937	2b	3
38.037537	-120.382713	467519	2b	3
38.022041	-120.382446	467455	2b	3
38.017872	-120.306061	467073	3	3
38.002029	-120.383591	467070	3	3
38.015579	-120.2817	467069	3	3
37.993629	-120.365227	467057	3	3
38.036743	-120.378349	467017	3	3

37.995674	-120.25647	467012	3	3
38.043247	-120.376343	467008	3	3
38.02116	-120.272011	466993	3	3
38.018883	-120.275146	466938	3	3
37.987709	-120.376526	466886	3	3
37.995964	-120.253845	466876	3	3
38.037937	-120.381554	466860	3	3
38.019802	-120.307037	466850	3	3
38.053089	-120.382896	466835	3	2
38.012619	-120.281242	466829	3	3
38.007996	-120.305122	466819	3	3
38.019115	-120.30706	466791	3	3
37.995583	-120.252312	466789	3	3
37.988434	-120.375488	467625	3	3
38.007702	-120.305466	467614	3	3
38.000767	-120.356018	467613	3	3
38.014175	-120.304611	467611	3	3
38.01347	-120.306541	467593	3	3
38.040771	-120.377563	467585	3	3
38.007786	-120.306458	466700	3	3
37.990734	-120.383842	380205	3	2

37.99612	-120.382385	379360	3	2
37.993645	-120.382065	379293	3	2
38.009129	-120.306831	467557	3	3
38.010349	-120.315163	467503	3	3
38.013996	-120.303062	467486	3	3
38.01395	-120.276085	467458	3	3
38.018623	-120.39492	467454	3	3
38.008377	-120.38765	467403	3	3
38.012814	-120.305244	467394	3	3
38.013233	-120.276978	467378	3	3
38.01218	-120.306068	467371	3	3
37.993938	-120.381996	467358	3	2
38.019646	-120.389328	467345	3	3
38.016178	-120.327362	467326	3	2
38.014088	-120.275398	467322	3	3
37.987339	-120.376846	467291	3	3
37.999741	-120.254616	467290	3	3
38.012733	-120.288803	467271	3	3
38.020313	-120.327713	467256	3	2
37.998005	-120.255318	467241	3	3

38.008598	-120.303764	467225	3	3
38.007973	-120.387344	467224	3	3
38.014545	-120.272339	467214	3	3
37.987762	-120.374725	467167	3	3
38.012974	-120.289444	467161	3	3
38.003674	-120.384697	467132	3	3
38.020409	-120.385399	467131	3	3
38.008698	-120.274445	467022	2	3
38.04073	-120.343094	466890	2	3
38.007149	-120.382721	380010	2	3
37.99102	-120.383553	379875	2	2
38.008469	-120.387489	379465	2	3
37.993645	-120.382065	379292	2	2
37.997952	-120.257599	467548	2	3
38.002045	-120.254677	467400	2	3
37.997108	-120.256516	467178	2	3
38.055893	-120.19165	468497	2b	3
38.058167	-120.18792	468492	2b	3
38.05925	-120.200737	468477	2b	3
38.05163	-120.229996	468442	2b	3

38.054642	-120.192345	468248	2b	3
38.062829	-120.182381	468226	2b	3
38.057796	-120.195686	468204	2b	3
38.062141	-120.178902	468173	2b	3
38.054521	-120.229056	468168	2b	3
38.061076	-120.187108	468121	2b	3
38.051079	-120.228004	468073	2b	3
38.055962	-120.193092	468027	2b	3
38.060138	-120.195038	468003	2b	3
38.062633	-120.177346	467978	2b	3
38.070955	-120.172646	467936	2b	3
38.059399	-120.179985	467927	2b	3
38.057567	-120.185327	467909	2b	3
38.059692	-120.185825	467898	2b	3
38.048298	-120.224747	467886	2b	3
38.046094	-120.224607	467878	2b	3
38.045982	-120.22142	467858	2b	3
38.057166	-120.186617	468551	2b	3
38.059613	-120.183801	468548	2b	3
38.058242	-120.182964	468538	2b	3
38.051376	-120.22831	468512	2b	3
38.051655	-120.229393	468421	2b	3

38.052734	-120.20621	468377	2b	3
38.057426	-120.194527	468370	2b	3
38.06258	-120.194489	468365	2b	3
38.057983	-120.184334	468352	2b	3
38.061317	-120.186653	468322	2b	3
38.063715	-120.187139	468314	2b	3
38.02787	-120.259094	380080	2b	3
38.030709	-120.263427	379909	2b	3
38.018691	-120.257599	379806	2b	3
38.021961	-120.255562	379779	2b	3
38.029472	-120.236511	467341	2b	3
38.064716	-120.272095	467332	2b	3
38.042336	-120.229546	467244	2b	3
38.05278	-120.234581	467235	2b	3
38.011452	-120.260307	379742	2b	3
38.022884	-120.254662	379613	2b	3
38.028805	-120.262177	379542	2b	3
38.029994	-120.26411	379375	2b	3
38.032353	-120.265759	379341	2b	3
38.027158	-120.256855	379337	2b	3
38.015537	-120.258797	379319	2b	3
38.048229	-120.247314	466650	2b	3

38.040756	-120.251129	380622	2b	3
38.045273	-120.24646	466794	2b	3
38.039158	-120.234283	466751	2b	3
38.031345	-120.239691	467228	2b	3
38.028059	-120.23987	467223	2b	3
38.040927	-120.234827	467199	2b	3
38.040752	-120.237534	467180	2b	3
38.058765	-120.272186	467449	2b	3
38.045765	-120.234329	467076	2b	3
38.060858	-120.275267	467005	2b	3
38.053478	-120.213662	467826	2b	3
38.049351	-120.22345	467825	2b	3
38.046478	-120.224541	467817	2b	3
38.048454	-120.224243	467815	2b	3
38.046085	-120.222168	467810	2b	3
38.058411	-120.270966	466901	2b	3
38.048681	-120.2239	467797	2b	3
38.052311	-120.215141	467795	2b	3
38.051102	-120.213478	467783	2b	3
38.027454	-120.224228	467765	2b	3
38.036041	-120.228798	467759	2b	3
38.064251	-120.271507	466684	2b	3

38.066002	-120.273018	467624	2b	3
38.064495	-120.27037	467562	2b	3
38.047092	-120.247559	467551	2b	3
38.036366	-120.230896	467739	2b	3
38.037937	-120.227798	467737	2b	3
38.030908	-120.2357	467728	2b	3
38.035553	-120.227432	467711	2b	3
38.03344	-120.232506	467706	2b	3
38.03157	-120.234932	467690	2b	3
38.035412	-120.229164	467686	2b	3
38.037392	-120.227013	467682	2b	3
38.048931	-120.246681	467437	2b	3
38.049175	-120.264748	380442	2b	3
38.022903	-120.223679	467675	2b	3
38.021084	-120.222351	467657	2b	3
38.035118	-120.228416	467643	2b	3
38.024178	-120.253181	380225	2b	3
38.01683	-120.257645	380213	2b	3
38.021848	-120.25384	380206	2b	3
38.009377	-120.258797	380178	2b	3
38.007694	-120.259651	380148	2b	3
38.070869	-120.189697	485362	3	3

38.051514	-120.227097	468540	3	3
38.055893	-120.19165	468498	3	3
38.056881	-120.185158	468344	3	3
38.030079	-120.252022	379695	3	3
38.040927	-120.234827	467196	3	3
38.063183	-120.282349	467463	3	3
38.058765	-120.272186	467450	3	3
38.040058	-120.220451	467845	3	3
38.046478	-120.224541	467818	3	3
38.057587	-120.268951	466941	3	3
38.05415	-120.216423	467775	3	3
38.04651	-120.247157	467398	3	3
38.053745	-120.193169	468188	2	3
38.052193	-120.220871	467880	2	3
38.060467	-120.182243	468263	2	3
38.05278	-120.234581	467233	2	3
38.046108	-120.232674	466646	2	3
38.040927	-120.234827	467197	2	3
38.054985	-120.234001	467096	2	3
38.055046	-120.21312	467840	2	3
38.057587	-120.268951	466940	2	3
38.052311	-120.215141	467794	2	3

38.033924	-120.231094		467670	2	3
38.05632	-120.184761		468437	2	3
38.027351	-120.251778		380266	2	3
38.028538	-120.366433			2b	
37.954755	-120.370382			2a	1
37.67593	-120.338476			1	
37.209862	-120.222792			1	
38.031947	-120.232901			1	
37.257381	-121.000359			2	
38.055603	-120.230076			2c	
36.993222	-120.003731			1	
36.970696	-120.053145			1	
37.991793	-120.399577	6058d8dfbca		1	2
38.025376	-120.4072	beb3bbc53a28		1	1
37.99522	-120.465227	285a40ad5777		2b	2
		ef416e4d80a1		1	2
				1	2
37.719955	-119.690305	2f6467ba9f88		2b	2
37.7181	-119.669507	2b1e3773e762		2b	2
37.717683	-119.66703	4f432d151f11		2b	1
37.714588	-119.664495		2.9705E+11	2b	2
37.715667	-119.659145	c152be3e871e		2b	2

37.715833	-119.658482	-817a5008a219		1	2
37.716023	-119.657463			2b	2
37.866142	-120.182003		1796760	2	2
37.826523	-120.25293		1795378	2	2
37.848375	-120.185827		1795384	2	2
37.848598	-120.183097		1795396	2	2
37.848593	-120.184208		1795399	2	2
37.847191	-120.194069		1795605	2	2
37.837051	-120.189949		1795788	2	3
37.851414	-120.210716		1795818	2a	2
37.84499	-120.211502		1795834	2b	2
37.854053	-120.218399		1796413	2	2
37.854209	-120.220238		1796366	2	2
37.854267	-120.210838		1796427	2	2
37.855382	-120.210942		1796342	2	2
37.825832	-120.198509		1797580	3	3
37.878742	-120.202658		1797654	2	2
37.824632	-120.146612		1796326	2	3
37.825042	-120.13924		1796523	2	2
37.835968	-120.185417		1795738	2	3
38.200173	-120.003178		1799141	2	3
38.200292	-120.003073		1799147	2	3

37.849211	-120.182271	1794115	2	2
37.8505	-120.142875	1796496	2	2
37.8505	-120.142875	1796497	2b	2
37.857513	-120.188605	1796100	2	2
37.823818	-120.184563	1797720	2	3
38.195035	-120.017525	1799250	2	3
38.199132	-120.00709	1799292	2	3
38.139303	-120.062043	1803146	2	3
38.190182	-119.985612	1798760	2	3
37.867082	-120.173373	1796512	2	2
37.824776	-120.256233	1793991	2	2
37.825621	-120.257445	1793992	2	2
37.82823	-120.249648	1794016	2	2
37.877869	-119.953857	1799024	2	2
37.807693	-120.065735	1799428	2	2
38.194172	-119.975427	1798798	2b	2
38.19455	-119.97335	1798762	2	2
38.197548	-120.013817	1800527	2	3
38.156063	-120.056465	1796953	2	3
37.836475	-120.236153	1794023	2	3
37.847176	-120.218964	1795702	2b	2
37.847664	-120.217932	1796490	2	2

37.848423	-120.213921	1796511	2	2
37.875702	-119.958786	1800066	2	2
37.836752	-120.228058	1800153	2	3
37.836349	-120.235336	1800232	2	2
38.158403	-120.056007	1797046	2	3
38.157883	-120.055663	1797052	2b	3
38.156048	-120.050873	1797571	2	3
38.160388	-120.055293	1797574	2b	3
37.845631	-120.222313	1796910	2b	2
37.843822	-120.224205	1796921	2b	2
38.15544	-120.051225	1797576	2	3
38.145325	-120.073752	1797617	2	3
38.14737	-120.07169	1797636	2	3
38.15432	-120.058327	1797658	2	3
38.16149	-120.052423	1798316	2	3
38.159012	-120.056358	1798677	2	3
37.819517	-120.129483	1796398	2	2
37.821307	-120.13123	1796529	2	2
37.821783	-120.131205	1796300	2	2
37.823162	-120.132705	1796390	2	2
37.823687	-120.133455	1796405	2	2

37.865131	-120.218109	1797243	2	2
37.859859	-120.21357	1794928	2	2
37.858509	-120.217194	1794934	2	2
37.822308	-120.261772	1794947	2	2
37.815891	-120.12973	1797400	2	2
37.819424	-120.129959	1797407	2	2
37.815285	-120.130272	1797417	2	3
37.824959	-120.257065	1794973	2	2
37.839916	-120.197868	1795252	2a	2
37.841962	-120.172237	1795278	2	2
38.1895	-120.002612	1799925	2	3
38.192863	-119.998737	1799927	2	3
38.194247	-119.97721	1800447	2	2
38.199033	-120.010765	1800602	2	3
38.19897	-120.010302	1800620	2	3
38.19708	-120.011718	1800637	2	3
38.197288	-120.014878	1800711	2	3
38.200245	-120.009327	1800728	2	3
38.197697	-120.012268	1800749	2	3
38.196698	-120.011495	1800857	2	3
37.847467	-120.180748	1795364	2	2
37.837013	-120.188835	1795855	2	3

37.855582	-120.189792	1795863	2	2
37.857193	-120.178618	1795871	2	2
37.857215	-120.190992	1795885	2	2
37.853937	-120.179502	1795886	2	2
37.857468	-120.17877	1795890	2	2
37.834267	-120.175949	1795902	2	3
38.201347	-120.007927	1800867	2	3
38.200615	-120.007808	1800957	2	3
38.201317	-120.01094	1800962	2	3
38.197523	-120.014363	1801061	2	3
38.19297	-120.013475	1801063	2	3
38.188068	-120.0204	1801150	2	3
38.193738	-120.014275	1801177	2	3
37.85675	-120.178657	1795989	2	2
37.852715	-120.206017	1795994	2b	2
37.860515	-120.18053	1796037	2	2
37.846886	-120.211624	1796066	2	2
37.833282	-120.196129	1796078	2	3
37.854233	-120.201958	1796156	2	2
37.854214	-120.202263	1796158	2	2
38.192383	-120.013473	1801285	2	3
38.19991	-120.01301	1801312	2	3

38.176908	-120.035688	1803555	2	3
38.161503	-120.055083	1803671	2	3
38.162015	-120.054108	1803674	2	3
38.19285	-120.014358	1801351	2	3
38.193178	-120.014452	1801355	2	3
37.856583	-120.187485	1796194	2a	2
37.854368	-120.190488	1796203	2	2
37.860758	-120.191043	1796574	2	2
37.848904	-120.219879	1796575	2	2
37.848904	-120.219879	1796576	2b	2
38.139115	-120.058045	1803320	2	3
38.162322	-120.050078	1803396	2	3
38.165517	-120.04926	1803472	2	3
38.172957	-120.037337	1803505	2	3
38.174722	-120.036762	1803519	2	3
38.175	-120.036362	1803525	2	3
38.198658	-120.007338	1799299	2	3
38.197975	-120.008973	1799301	2	3
38.196223	-119.971007	1799342	2	2
37.865067	-120.169285	1796614	2	2
37.855804	-120.211922	1796624	2	2
37.856262	-120.215782	1796633	2b	2

37.847497	-120.154148	1796683	2b	2
38.185747	-119.999323	1799545	2	3
38.186948	-119.997495	1799546	2	3
38.185955	-120.0018	1799547	2	3
38.184778	-119.99908	1799550	2	3
38.187374	-119.999779	1799551	2	3
38.18682	-119.997553	1799553	2	3
38.186625	-119.996713	1799556	2	3
38.185225	-120.00249	1799557	2	3
38.186785	-120.00222	1799559	2	3
38.189598	-120.001878	1799920	2	3
37.654335	-120.348671	1806741	2	2
37.719658	-120.346344	1807359	2	2
37.727192	-120.347321	1807368	2	2
37.689751	-120.332497	1805130	2	2
37.663857	-120.318314	1805136	2	2
37.652565	-120.311267	1805139	2	2
37.685146	-120.324043	1805141	2	2
37.694679	-120.330902	1805142	2	2
37.697163	-120.329178	1805148	2	2
37.681137	-120.322884	1805190	2	2
37.671986	-120.321655	1805200	2	2

37.644901	-120.318493	1805205	2a	2
37.655778	-120.358791	1806038	2	2
37.641617	-120.347549	1806144	2	2
37.636085	-120.350833	1806269	3	2
37.636867	-120.350364	1806276	3	2
37.726257	-120.323219	1807399	2	2
37.716103	-120.332405	1807422	2	2
37.718365	-120.311897	1807429	3	2
37.706619	-120.334732	1807449	3	2
37.714424	-120.329948	1807477	3	2
37.708307	-120.335157	1807485	2	2
37.718731	-120.321007	1807487	2	2
37.62901	-120.308404	1803810	3	2
37.636288	-120.313022	1803821	3	2
37.633984	-120.310471	1803824	2	2
37.6363	-120.313023	1803844	3	2
37.640882	-120.315294	1803916	2	2
37.637496	-120.315692	1803931	3	2
37.638954	-120.324329	1804192	2b	2
37.717731	-120.350601	1807490	2	2
37.637544	-120.325095	1804361	3	2
37.635325	-120.32733	1804371	2	2

37.633415	-120.327927	1804377	2	2
37.634043	-120.341279	1804705	2	2
37.63346	-120.342358	1804731	2a	2
37.633747	-120.343224	1804750	2	2
37.631294	-120.342577	1804932	3	2
37.720298	-119.69377	1803247	2b	2
37.71748	-119.66765	1803347	2	2
37.722115	-120.33136	1807509	3	2
37.635197	-120.348083	1805060	2	2
37.725445	-120.335594	1807514	3	2
37.728172	-120.335571	1807524	3	2
37.723587	-120.332947	1807527	3	2
37.707008	-120.336594	1807538	3	2
37.726349	-120.334831	1807543	3	2
37.727154	-120.327141	1807554	3	2
37.724487	-120.336006	1807556	3	2
37.730728	-120.343109	1807558	2a	2
37.653214	-120.3339	1808169	3	2
37.654091	-120.334138	1808178	3	2
37.654839	-120.337006	1808188	2	2
37.655277	-120.336327	1808191	3	2
37.654224	-120.339453	1808197	3	2

37.654224	-120.339453	1808198	2b	2
37.6579	-120.336984	1808255	3	2
37.660145	-120.334378	1808319	2a	2
37.659279	-120.333214	1808320	2a	2
37.659279	-120.333214	1808321	3	2
37.651898	-120.322603	1808398	3	2
37.651248	-120.324134	1808436	2	2
37.651913	-120.326825	1808440	2	2
37.654369	-120.330238	1808453	3	2
37.657394	-120.330803	1808459	3	2
37.657997	-120.329208	1808565	3	2
37.656017	-120.320023	1808619	2	2
37.657902	-120.322975	1808684	3	2
37.633434	-120.342636	1803091	2a	2
37.652246	-120.322452	1807876	3	2
37.655633	-120.312787	1805110	2	2
37.720287	-120.314064	1808863	3	2
37.712223	-120.33992	1808866	3	2
37.710567	-120.328255	1808870	3	2
37.711277	-120.328293	1808871	3	2
37.724262	-120.311249	1808872	3	2
37.713577	-120.327377	1808877	3	2

37.719292	-120.31337	1808878	3	2
37.713058	-120.325462	1808882	3	2
37.676202	-120.333564	1809022	3	2
37.676775	-120.333866	1809029	3	2
37.677067	-120.334161	1809030	3	2
37.709607	-120.341016	1809120	2	2
37.65833	-120.349566	1807325	3	2
37.659613	-120.355313	1805436	3	2
37.660836	-120.355295	1805238	3	2
37.661986	-120.356223	1805219	3	2
37.663193	-120.317573	1805115	2	2
37.667014	-120.318454	1805119	3	2
37.678591	-120.329105	1805113	3	2
37.680257	-120.322685	1805094	2	2
37.683715	-120.330855	1805116	2	2
37.692272	-120.388067	1803094	2	2
37.697312	-120.397558	1802891	3	2
37.700027	-120.415027	1802892	3	2
37.674347	-120.369682	1809131	3	2
37.677138	-120.369769	1809138	3	2
37.547115	-119.647476	1804214	2	2
37.707957	-120.437892	1803034	2a	2

37.718685	-120.314921	1807779	2	2
37.719303	-120.322814	1807315	2	2
37.719518	-120.32258	1807337	2	2
37.722712	-120.309315	1807772	3	2
37.726357	-120.32328	1797464	2	2
37.726471	-120.326866	1797467	3	2
37.726471	-120.326866	1797468	2	2
37.711018	-120.440598	1803393	2b	2
37.63686	-120.350347	1806287	3	2
37.630832	-120.352943	1806293	3	2
37.630573	-120.351267	1806302	2	2
37.630712	-120.350178	1806306	3	2
37.653477	-120.353811	1806331	2	2
37.657828	-120.353753	1806354	3	2
37.657795	-120.353689	1806355	3	2
37.651805	-120.351584	1806379	2c	2
37.650768	-120.351134	1806383	3	2
37.66085	-120.355286	1806391	2b	2
37.66085	-120.355286	1806392	3	2
37.659642	-120.355311	1806394	3	2
37.645651	-120.335813	1806559	2	2
37.630086	-120.357394	1806598	3	2

37.631203	-120.357307	1806608	3	2
37.631203	-120.357307	1806609	2	2
37.631203	-120.357307	1806610	3	2
37.630072	-120.357392	1806611	3	2
37.63113	-120.357353	1806615	3	2
37.650605	-120.339828	1806656	2	2
37.646156	-120.344627	1806677	2	2
37.650074	-120.346674	1806729	3	2
37.652786	-120.347161	1806730	3	2
37.654378	-120.348622	1806738	3	2
37.778072	-120.175993	1804471	2	3
37.721205	-120.277845	1803939	2	2
37.718478	-120.19946	1803593	2	2
37.720897	-120.296038	1803127	2	2
37.73132	-120.179392	1802973	2	2
37.708512	-120.202863	1803134	2	2
37.673401	-119.805855	1804733	2	2
37.673023	-119.79702	1803940	2	2
37.753239	-120.129021	1806212	2	3
37.70652	-120.116501	1804205	2	2

37.734001	-120.123645	1802997	2	2
37.673645	-119.806175	1804739	2	2
37.693545	-120.306853	1804309	3	2
37.732426	-120.12281	1804707	3	2
37.720413	-120.306007	1807398	3	2
37.732468	-120.122971	1804726	3	2
37.691255	-120.310622	1804311	3	2
37.722294	-120.119578	1803137	3	2
37.730712	-120.123117	1803007	3	2
37.751476	-120.127281	1806211	2	3
37.764606	-120.154556	1804976	2	3
37.740265	-120.132637	1804754	2	2
37.737831	-120.127022	1804738	2	2
37.737057	-120.127869	1804736	2	2
37.700871	-120.09507	1804148	2	2
37.73307	-120.123627	1804708	2	2
37.895725	-120.481781	1796521	2b	2
37.913161	-120.452792	1795761	3	2
37.920547	-120.44973	1795774	3	2
37.92753	-120.453169	1798813	2	2
37.930155	-120.444632	1803121	3	2

37.945103	-120.530945	1798789	2b	2
37.945293	-120.530075	1798850	2b	2
37.870155	-120.431458	1796152	2	2
37.935128	-120.430183	1796157	2	2
37.938992	-120.4161	1796167	2b	2
37.933063	-120.413853	1796176	2b	2
37.89156	-120.443581	1796217	2	2
37.891403	-120.444191	1796222	2	2
37.940205	-120.415504	1796226	2b	2
37.939301	-120.415787	1796252	2	2
37.871159	-120.434677	1796257	3	2
37.955673	-120.404671	1800350	2b	2
37.956051	-120.403099	1800357	2	2
37.902969	-120.501595	1800458	2b	2
37.959253	-120.429562	1803159	2	2
37.892384	-120.484726	1796457	2b	2
37.870602	-120.433105	1796119	2b	2
37.871937	-120.432907	1796104	2b	2
37.936695	-120.428047	1796265	2b	2
37.936752	-120.425499	1796273	2	2

37.924328	-120.425514	1796618	2b	2
37.924503	-120.424332	1796641	2b	2
37.863941	-120.428116	1796649	2	2
37.868759	-120.423241	1796672	2b	2
37.871098	-120.420105	1796731	2a	2
37.956532	-120.42524	1803181	3	2
37.956532	-120.42524	1803182	3	2
37.959255	-120.427188	1803191	2	2
37.963403	-120.434505	1803200	2	2
37.957188	-120.43236	1803212	2	2
37.873685	-120.38514	1796338	2	2
37.87428	-120.39862	1796445	2b	2
37.878683	-120.397025	1796492	2b	2
37.879735	-120.399062	1796434	2b	2
37.882683	-120.438789	1796091	3	2
37.890274	-120.444534	1796116	3	2
37.904288	-120.412117	1798689	3	2
37.943683	-120.416738	1796094	2b	2
37.944128	-120.416955	1796096	2b	2
37.948982	-120.419517	1794118	2b	2
37.862816	-120.439278	1796850	2	2

37.8801	-120.400566	1797017	2b	2
37.880932	-120.40112	1797018	2b	2
37.877518	-120.400124	1797019	2b	2
37.878716	-120.400597	1797021	2	2
37.881523	-120.401522	1797022	2b	2
37.879513	-120.400818	1797023	2b	2
37.87376	-120.385147	1797025	2b	2
37.93898	-120.436815	1804571	3	2
37.942788	-120.43011	1806288	3	2
37.951032	-120.421135	1794110	2b	2
37.959955	-120.418212	1795745	2	2
37.960923	-120.41392	1795740	2b	2
37.950249	-120.420532	1794839	2b	2
37.947289	-120.410759	1797161	2b	2
37.946487	-120.411209	1797182	2b	2
37.947964	-120.410301	1797184	2b	2
37.874126	-120.397644	1797027	2b	2
37.877083	-120.398727	1797029	2b	2
37.874599	-120.381432	1797030	2b	2
37.875626	-120.398155	1797032	2	2
37.875626	-120.398155	1797033	2b	2

37.966801	-120.470566	1803919	2	2
37.859634	-120.368889	1797545	2	2
37.856857	-120.38501	1797552	2	2
37.858452	-120.388535	1797553	2	2
37.859409	-120.38739	1797554	2b	2
37.949583	-120.42481	1803993	3	2
37.94048	-120.434282	1804015	2	2
37.939865	-120.435687	1804018	2	2
37.929993	-120.452108	1804189	2	2
37.937072	-120.446625	1804237	2	2
37.936865	-120.441228	1804345	3	2
37.880154	-120.456108	1797744	2	2
37.880154	-120.456108	1797745	2b	2
37.882656	-120.454132	1797764	2	2
37.948669	-120.419281	1794863	2b	2
37.94978	-120.42067	1794868	2	2
37.946407	-120.418152	1794894	3	2
37.946144	-120.417664	1794909	2	2
37.951065	-120.416954	1794971	2b	2
37.951275	-120.415741	1794999	2b	2
37.952129	-120.414902	1795017	2b	2
37.863823	-120.443359	1797588	2	2

37.918567	-120.413453	1797590	2b	2
37.916187	-120.414413	1797604	2b	2
37.916325	-120.415245	1797615	2b	2
37.877041	-120.446243	1797625	2	2
37.87579	-120.453018	1797643	2	2
37.876038	-120.45298	1797646	2c	2
37.875984	-120.453613	1797650	2b	2
37.86033	-120.377672	1797684	2b	2
37.853092	-120.366829	1797706	2b	2
37.953592	-120.415033	1795027	2b	2
37.850063	-120.35804	1798066	2	2
37.959198	-120.416023	1798068	2	2
37.959198	-120.416023	1798070	2b	2
37.956104	-120.418091	1798071	2b	2
37.955406	-120.418015	1798072	2b	2
37.956909	-120.418083	1798076	2	2
37.952443	-120.414767	1795019	2b	2
37.952152	-120.414703	1795020	2	2
37.951729	-120.415749	1795039	2b	2
37.952087	-120.415771	1795045	2b	2
37.970406	-120.415901	1795262	2b	2

37.956593	-120.422195	1795358	2b	2
37.966717	-120.41291	1795488	2b	2
37.966255	-120.411156	1795489	2b	2
37.963025	-120.406797	1795502	2b	2
37.958084	-120.418411	1798089	2	2
37.909153	-120.417807	1799370	2b	2
37.909409	-120.416916	1799372	2b	2
37.926357	-120.45195	1799467	2	2
37.926357	-120.45195	1799468	2b	2
37.92627	-120.450165	1799490	2	2
37.918877	-120.419357	1799493	2	2
37.963757	-120.405815	1795514	2b	2
37.962784	-120.407494	1795520	3	2
37.966407	-120.411682	1795567	2b	2
37.966244	-120.41066	1795572	2b	2
37.965277	-120.408018	1795574	2b	2
37.964981	-120.407104	1795576	2b	2
37.966042	-120.410126	1795586	2b	2
37.962807	-120.405624	1795623	2b	2
37.963268	-120.406464	1795630	2b	2
37.963341	-120.406281	1795636	2	2
37.963341	-120.406281	1795637	2b	2

37.962742	-120.406403	1795640	2b	2
37.952737	-120.421857	1795790	2b	2
37.968872	-120.430191	1799977	2b	2
37.969891	-120.426651	1799986	2	2
37.969143	-120.42981	1799987	2b	2
37.969248	-120.4267	1800111	2b	2
37.968281	-120.426788	1800118	2b	2
37.949234	-120.414612	1800135	2b	2
37.949234	-120.414612	1800136	2b	2
37.879215	-120.448799	1796288	3	2
37.879932	-120.448586	1796421	3	2
37.881344	-120.448349	1796359	3	2
37.883266	-120.448486	1796539	3	2
37.885601	-120.447739	1796518	3	2
37.886383	-120.447617	1796471	3	2
37.887161	-120.447433	1796316	3	2
37.888878	-120.446411	1796341	3	2
37.88805	-120.541588	1798141	2	2
37.889484	-120.445953	1796524	3	2
37.963745	-120.411766	1795820	2b	2
37.95377	-120.419136	1795825	2b	2

37.909378	-120.451256	1795829	2	2
37.952237	-120.421757	1795868	2b	2
37.962902	-120.413284	1795887	2b	2
37.958759	-120.417976	1795915	2b	2
37.962555	-120.409782	1795935	2b	2
37.915199	-120.452553	1795944	2	2
37.954708	-120.419922	1795945	2	2
37.962364	-120.410675	1795957	2b	2
37.962765	-120.408165	1796003	3	2
37.9632	-120.412018	1796004	2	2
37.961174	-120.413368	1796073	2b	2
37.953674	-120.413803	1800181	2	2
37.954468	-120.413353	1800197	2	2
37.954468	-120.413353	1800198	2b	2
37.954468	-120.413353	1800199	2b	2
37.954735	-120.414012	1800237	2	2
37.954269	-120.413971	1800243	2	2
37.954784	-120.413345	1800247	2	2
37.94543	-120.415788	1800272	2b	2
37.94543	-120.415788	1800273	2	2
37.945648	-120.415393	1800282	2b	2

38.057545	-120.256699	0cfb9e80fe09	2b	1
38.041695	-120.250824	d8b18d9ab79	1	1
38.045676	-120.231518		2b	
38.023006	-120.268707	1796927	2	3
38.002083	-120.254677	1796932	2	3
38.018044	-120.267834	1796934	2	3
38.035121	-120.415724	1796966	2	2
38.038828	-120.416393	1796967	2	2
38.037663	-120.414803	1796968	2	2
38.028882	-120.431058	1796969	2	2
38.029077	-120.426332	1796970	2	2
38.030072	-120.403459	1796971	2b	2
38.038437	-120.412369	1796972	2	2
38.0388	-120.428232	1796975	2	2
38.038475	-120.427544	1796976	2	2
37.987686	-120.372765	1792868	2	2
37.987602	-120.374184	1792874	2	3
37.95641	-120.340037	1793599	2	2
38.011986	-120.422752	1794841	2	2
37.994622	-120.433902	1794867	3	2
37.975433	-120.348091	1794872	2	2
37.935312	-120.334125	1794903	2	2

37.947964	-120.334633	1794924	2	2
37.990438	-120.474338	1796076	2b	2
38.05566	-120.382271	1796083	2	2
37.955405	-120.391071	1796084	2	2
38.035129	-120.402693	1796088	2	2
37.954951	-120.377993	1796121	2	2
38.038165	-120.383427	1796131	2	3
38.041615	-120.39481	1796977	2	2
38.028556	-120.401256	1796981	2	2
38.031413	-120.365636	1796982	2	3
38.037813	-120.395153	1796984	2	2
38.037813	-120.395153	1796985	2	2
38.034669	-120.367147	1796986	2	3
38.034663	-120.370089	1796988	2	3
38.037079	-120.394699	1796989	2	2
38.030494	-120.400488	1796990	2	2
38.034253	-120.370697	1796991	2	3
38.039036	-120.388854	1796993	2	2
37.956345	-120.327072	1793660	2	2
37.976231	-120.36451	1793667	2b	2
38.042534	-120.343697	1793671	2	3
37.967202	-120.330223	1793672	2	2

37.974407	-120.370171	1793677	2a	2
37.976034	-120.379644	1795033	2	2
37.949164	-120.382991	1795448	2	2
37.94853	-120.383105	1795449	2	2
37.946401	-120.386215	1795452	2	2
37.947535	-120.383869	1795454	2	2
37.946416	-120.387539	1795456	2	2
37.946416	-120.387539	1795457	2	2
37.946416	-120.387539	1795458	2	2
37.946416	-120.387539	1795459	2	2
37.953047	-120.382231	1795470	2	2
37.956985	-120.382257	1796140	2	2
37.955581	-120.379096	1796142	2	2
37.958471	-120.381725	1796149	2	2
37.958471	-120.381725	1796150	2	2
37.962477	-120.400215	1796165	2	2
37.962674	-120.386898	1796197	2	2
37.956282	-120.379831	1796213	2	2
37.944447	-120.359642	1796707	2	2
38.031579	-120.381344	1796995	2	3
38.020037	-120.385922	1796996	2	3

38.01956	-120.390734	1796997	2b	3
38.022711	-120.382181	1797000	2	3
38.028839	-120.367744	1797004	2	3
37.990352	-120.408942	1793690	2	2
37.964891	-120.338077	1793691	2	2
37.962499	-120.335283	1793697	2	2
37.954956	-120.328474	1793704	2	2
37.957172	-120.323471	1793709	2	2
37.987873	-120.441849	1795059	2	2
37.986443	-120.443001	1795065	2	2
37.984943	-120.443794	1795121	2	2
37.982053	-120.444327	1795125	2	2
37.99168	-120.463173	1795506	2b	2
38.007565	-120.302595	1796728	2	3
38.007688	-120.30609	1796768	2	3
38.007889	-120.305579	1796771	2	3
37.995155	-120.475464	1796777	2	2
37.99807	-120.333199	1794368	2	2
37.998173	-120.329796	1794371	2	2
37.999645	-120.332397	1794372	2	2
37.997814	-120.330696	1794373	2	2
37.987225	-120.330048	1794375	2a	2

38.002094	-120.332298	1794378	2	2
37.986668	-120.330544	1794384	2	2
37.993019	-120.328224	1794388	2a	2
37.989887	-120.324608	1794452	2	2
37.985817	-120.324615	1794461	2	2
37.986225	-120.324371	1794464	2	2
37.99136	-120.323997	1794465	2	2
37.989315	-120.324471	1794469	2	2
37.954475	-120.328125	1794476	2b	2
37.975166	-120.375526	1795169	2b	2
37.976635	-120.362846	1795173	2	2
37.995457	-120.466187	1795529	2	2
37.949461	-120.381719	1795561	2	2
37.948816	-120.384708	1795565	2	2
38.039066	-120.342415	1795575	2	3
37.949931	-120.384675	1795578	2	2
38.039261	-120.344025	1795580	2a	3
37.945984	-120.370483	1795587	2	2
37.947652	-120.385405	1795589	2	2
37.95002	-120.368324	1795593	2	2
37.995548	-120.272552	1796791	2	2
37.996857	-120.271385	1796795	2b	2

38.00763	-120.30772	1796798	2	3
38.00763	-120.30772	1796799	2	3
38.009606	-120.30625	1796805	2	3
38.009058	-120.307539	1796806	2	3
38.019048	-120.306161	1796814	2	3
37.99258	-120.332588	1794389	2	2
37.998753	-120.332695	1794393	2	2
37.998211	-120.329269	1794394	2	2
37.997268	-120.331787	1794395	2	2
37.997635	-120.332191	1794397	2	2
37.991737	-120.335793	1794407	2	2
38.000264	-120.332484	1794408	2	2
37.992718	-120.318123	1794505	2	2
37.992786	-120.315491	1794510	2	2
37.994816	-120.316132	1794516	2	2
37.996124	-120.316673	1794532	2	2
37.97673	-120.37516	1795175	2a	2
37.979137	-120.363373	1795177	2	2
37.980019	-120.36116	1795181	2	2
37.973873	-120.375732	1795182	2	2
37.976509	-120.362366	1795191	2b	2
37.950534	-120.384907	1795596	2	2

37.951108	-120.385059	1795599	2	2
37.946151	-120.384686	1795604	2	2
37.948372	-120.388846	1795614	2	2
37.959836	-120.373314	1795250	2	2
37.982483	-120.439751	1795253	2	2
38.018917	-120.301977	1796837	2	3
37.917568	-120.358833	1796849	2	2
38.0236	-120.30221	1796852	2	3
38.004894	-120.258102	1796873	2b	3
37.993279	-120.327965	1794410	2	2
37.999058	-120.332329	1794414	2	2
37.994377	-120.332321	1794415	2a	2
37.985237	-120.330391	1794417	2	2
37.994133	-120.325745	1794422	2	2
37.98875	-120.324249	1794432	2	2
37.993134	-120.325584	1794434	2	2
37.947055	-120.333566	1794623	2	2
37.947174	-120.333778	1794624	2	2
37.939114	-120.328247	1794635	2	2
37.942956	-120.327338	1794661	2	2
37.973148	-120.358292	1795260	2	2

37.982479	-120.441025	1795276	2	2
37.972351	-120.358635	1795291	2	2
37.972351	-120.358635	1795292	2	2
37.977378	-120.443777	1795305	2	2
37.986353	-120.383458	1796894	2	2
37.956282	-120.379831	1796214	2	2
38.040999	-120.371243	1796218	2	3
37.961524	-120.380437	1796232	2	2
37.958861	-120.382645	1796238	2	2
37.957366	-120.381685	1796259	2	2
38.035877	-120.378782	1796260	2	3
37.991398	-120.393394	1793711	2b	2
37.96703	-120.330185	1793715	2a	2
37.965927	-120.333618	1793717	2	2
37.998253	-120.403625	1793744	2	2
37.945327	-120.328643	1794715	2	2
37.945327	-120.328643	1794716	2	2
37.945276	-120.328621	1794721	2b	2
37.97908	-120.444313	1795150	2b	2
37.952888	-120.348721	1795155	2	2
37.974392	-120.346207	1795313	2a	2
37.945856	-120.39045	1795320	2	2

37.952272	-120.391003	1795325	2	2
37.974354	-120.345421	1795327	2	2
37.973848	-120.439812	1795329	2	2
38.04808	-120.33287	1795381	2	3
37.9428	-120.387007	1796264	2a	2
37.956515	-120.387671	1796275	2	2
37.962489	-120.386863	1796281	2	2
37.998482	-120.403	1793756	2	2
37.957546	-120.32251	1793757	2	2
37.964357	-120.329936	1793767	2b	2
37.97691	-120.44593	1795401	2b	2
37.939307	-120.389638	1795414	2	2
38.046268	-120.332352	1795418	2	3
37.94511	-120.390107	1795431	2	2
37.955441	-120.362141	1795436	2	2
37.946654	-120.389902	1795439	2	2
38.035553	-120.39391	1795812	2b	2
37.975972	-120.363535	1793768	2a	2
37.992764	-120.330505	1794179	2	2
37.990528	-120.330856	1794205	2b	2
37.988598	-120.335037	1794209	2	2

37.988861	-120.333961	1794211	2	2
37.988064	-120.40554	1794252	2	2
37.989695	-120.40629	1794253	2	2
37.988472	-120.405438	1794254	2	2
38.030331	-120.406221	1795823	2	2
38.024581	-120.402244	1795830	2	2
37.950253	-120.368736	1795870	2	2
37.954908	-120.394062	1795877	2	2
38.038782	-120.40555	1795880	2	2
37.986729	-120.40863	1794266	2	2
37.985489	-120.408096	1794267	2	2
37.981365	-120.41011	1794268	2	2
37.945625	-120.322189	1794742	2	2
37.945119	-120.320873	1794745	2	2
37.97591	-120.347816	1794766	2	2
38.034998	-120.392859	1795881	2	2
37.965563	-120.402179	1795896	2	2
38.018503	-120.396044	1795932	2	2
38.023493	-120.40206	1795934	2	2
37.988449	-120.497925	1795961	2	2
38.03269	-120.404395	1795963	2	2
38.025758	-120.399355	1795964	2	2

37.987652	-120.373497	1792876	2a	3
37.989515	-120.377047	1792923	2	3
37.98835	-120.375389	1792927	2	3
37.957986	-120.334618	1793362	2	2
37.964481	-120.348923	1793365	2	2
37.984344	-120.351585	1793367	2	2
37.959774	-120.333142	1793383	2	2
38.04446	-120.409503	1795980	2	2
37.964818	-120.381362	1795987	3	2
38.033429	-120.403189	1795988	2	2
37.963338	-120.400967	1796007	2	2
37.963764	-120.402062	1796017	2	2
37.952057	-120.395522	1796018	2	2
38.036861	-120.40544	1796020	2	2
37.957667	-120.339183	1793387	2	2
37.96357	-120.34005	1793397	2	2
37.965339	-120.339347	1793401	2	2
37.960495	-120.339149	1793407	2	2
37.959888	-120.333807	1793418	2	2
37.958328	-120.343796	1793452	2	2
38.006622	-120.341957	1793470	2	2
37.954354	-120.397615	1796030	2	2

37.946644	-120.390151	1795622	2	2
37.967003	-120.348445	1793475	2	2
37.960758	-120.338249	1793487	2	2
37.964656	-120.342293	1793490	2	2
37.987435	-120.347543	1793493	2	2
37.961072	-120.332862	1793495	2	2
37.960528	-120.332591	1793509	2	2
37.964776	-120.340312	1793515	2	2
37.962814	-120.341553	1793540	2	2
37.984528	-120.357628	1793560	2	2
38.014042	-120.330948	1795660	2	2
38.01144	-120.327339	1795661	2	2
38.008217	-120.327759	1795663	2	2
38.012695	-120.327934	1795665	2	2
38.011253	-120.326721	1795666	2	2
38.017693	-120.327667	1795668	2	2
38.018848	-120.327728	1795669	2	2
38.015808	-120.327248	1795671	2	2
38.015373	-120.327583	1795672	2	2
37.994457	-120.335403	1795674	2	2
37.997601	-120.334671	1795676	2a	2
37.991417	-120.410347	1796582	2	2

37.944363	-120.359024	1796589	2	2
37.94453	-120.358638	1796592	2	2
37.943123	-120.358528	1796602	2	2
37.967693	-120.345049	1793594	2	2
37.972038	-120.340309	1792547	2	2
37.97304	-120.341683	1792549	2	2
37.971396	-120.339727	1792552	2	2
37.970756	-120.348081	1792721	2	2
37.970756	-120.348081	1792722	3	2
37.986786	-120.371582	1792744	2	2
37.995094	-120.335068	1795677	2	2
37.993206	-120.335106	1795681	2	2
37.996086	-120.33094	1795690	2	2
37.996784	-120.327904	1795693	2	2
38.008015	-120.295351	1796676	2b	3
37.991344	-120.446579	1796693	2	2
37.97797	-120.318932	1796701	2	2
38.018047	-120.267386	1796908	2	3
37.971384	-120.352871	1792745	2	2
37.987045	-120.374619	1792748	2a	3
37.987045	-120.374619	1792749	2	3
37.986958	-120.371986	1792752	2	2

37.990234	-120.373505	1792830	2	3
37.990768	-120.37545	1792838	2	3
37.989098	-120.375519	1792845	2	3
37.996025	-120.317909	1794770	2	2
37.978771	-120.347374	1794777	3	2
37.995308	-120.31897	1794781	2a	2
37.982136	-120.343208	1794784	2a	2
37.994587	-120.321793	1794794	2	2
37.981064	-120.34565	1794795	2	2
38.006676	-120.430122	1794799	3	2
37.968382	-120.403753	1795789	3	2
37.965496	-120.38027	1795793	3	2
38.038899	-120.405393	1795795	2	2
38.040247	-120.406333	1795798	2	2
38.037128	-120.391464	1795805	3	2
37.953732	-120.396708	1796040	3	2
38.065559	-120.188866	1902661	2	3
38.062946	-120.188118	1902713	2	3
38.06499	-120.187975	1902834	2	3
38.065121	-120.188721	1902859	2	3
38.027397	-120.261536	1798443	2	3
38.023178	-120.252754	1798468	2	3

38.050442	-120.225471	1798477	2	3
38.05544	-120.234596	1798543	2	3
38.03886	-120.247948	1808547	2	3
38.05154	-120.202454	1903686	2	3
38.023113	-120.221558	1903688	2b	3
38.06292	-120.184143	1904032	2	3
38.062862	-120.182998	1904035	2	3
38.060753	-120.196007	1904039	2b	3
38.062321	-120.184395	1904043	2	3
38.060757	-120.195633	1904051	2b	3
38.071281	-120.173813	1911466	2	3
38.03112	-120.244232	1805587	2	3
38.03091	-120.244362	1805319	2	3
38.031331	-120.24473	1805322	2	3
38.031429	-120.243729	1805455	2b	3
38.031448	-120.240316	1805403	2b	3
38.033485	-120.236908	1804849	2	3
38.035027	-120.236652	1804827	2	3
38.037	-120.233986	1805438	2	3
38.062664	-120.187416	1902818	2	3
38.054855	-120.234306	1798632	2	3

38.05291	-120.234642	1798679	2	3
38.031845	-120.278465	1798989	2	3
38.058105	-120.188774	1903716	2	3
38.063362	-120.195114	1903717	2b	3
38.063122	-120.195412	1903719	2b	3
38.066048	-120.280319	1910365	2b	3
38.064045	-120.279007	1910395	2b	3
38.060123	-120.260017	1910407	2b	3
38.062992	-120.281288	1910411	2	3
38.062797	-120.282366	1910423	2	3
38.070629	-120.172516	1911496	2	3
38.06646	-120.187889	1902742	2	3
38.036903	-120.277107	1798992	2	3
38.035381	-120.277397	1798997	2	3
38.033882	-120.264854	1799008	2	3
38.030357	-120.266693	1800097	2	3
38.033913	-120.265968	1800100	2	3
38.033085	-120.266495	1800108	2	3
38.062344	-120.196121	1903732	2	3
38.059006	-120.187004	1903742	2	3
38.059689	-120.186867	1903754	2	3
38.059478	-120.186501	1903757	2	3

38.062038	-120.196953	1903759	2	3
38.061855	-120.19735	1903764	2b	3
38.103515	-120.123913	1903474	2	3
38.096073	-120.11555	1903475	2	3
38.04493	-120.208344	1903479	2b	3
38.102585	-120.121651	1903482	2	3
38.102617	-120.12401	1903490	2	3
38.06126	-120.179428	1911597	2	3
38.056374	-120.184822	1911600	2	3
38.056587	-120.186905	1911608	2	3
38.069798	-120.181526	1912070	2b	3
38.06916	-120.181419	1912072	2	3
38.067402	-120.188599	1912093	2	3
38.052574	-120.228432	1796516	2	3
38.050472	-120.213959	1797626	2	3
38.048907	-120.213035	1797639	2	3
38.101246	-120.122002	1903491	2	3
38.095749	-120.127701	1903499	2	3
38.090133	-120.138937	1903508	2	3
38.092255	-120.134697	1903512	2	3
38.04398	-120.20713	1903514	2	3
38.061527	-120.268562	1910522	2	3

38.066406	-120.280769	1910559	2	3
38.056297	-120.178352	1912177	2	3
38.056965	-120.179115	1912178	2	3
38.046475	-120.224751	1797709	2	3
38.048249	-120.226735	1797733	2	3
38.04637	-120.223475	1797753	2	3
38.053387	-120.213966	1797842	2	3
38.043695	-120.23372	1803815	2	3
38.032036	-120.258514	1903227	2	3
38.081233	-120.147623	1903519	2	3
38.087327	-120.138252	1903526	2	3
38.035503	-120.204552	1903527	2	3
38.08377	-120.148467	1903530	2	3
38.083298	-120.148157	1903532	2	3
38.082512	-120.147415	1903535	2	3
38.05603	-120.19973	1904109	2	3
38.057823	-120.195679	1904110	2	3
38.058296	-120.194649	1904111	2	3
38.058125	-120.194679	1904113	2	3
38.055573	-120.192329	1904122	2b	3
38.050873	-120.216042	1797872	3	3
38.051537	-120.219078	1797960	2	3

38.030327	-120.266693	1903330	2	3
38.082927	-120.149447	1903539	2	3
38.032387	-120.204285	1903561	2	3
38.036404	-120.228706	1904132	2	3
38.036018	-120.227043	1904135	2	3
38.059417	-120.270823	1904136	2	3
38.055333	-120.268557	1904141	2a	3
38.07708	-120.169975	1904158	2	3
38.06123	-120.276344	1904162	2	3
38.073502	-120.177048	1904163	2	3
38.046556	-120.224637	1798029	2	3
38.048295	-120.224832	1798036	2	3
38.066811	-120.186081	1903377	2b	3
38.035049	-120.223068	1903401	2	3
38.031914	-120.220818	1903414	2	3
38.063297	-120.189301	1903579	2	3
38.034035	-120.231354	1904166	2	3
38.061958	-120.193481	1904169	2	3
38.060574	-120.275139	1904174	2	3
38.060638	-120.194824	1904175	2b	3
38.061321	-120.193871	1904178	2b	3
38.062305	-120.195068	1904179	2b	3

38.065865	-120.266663	1904191	2	3
38.051053	-120.217306	1796531	2	3
38.051918	-120.221124	1796487	2	3
38.064497	-120.275117	1910207	2	3
38.055655	-120.209943	1796833	2	3
38.05917	-120.191185	1903621	2	3
38.059147	-120.190041	1903624	2	3
38.059406	-120.188606	1903644	2	3
38.058868	-120.189026	1903650	2	3
38.058601	-120.189415	1903652	2	3
38.061558	-120.185799	1904255	2b	3
38.062843	-120.184174	1904257	2b	3
38.058331	-120.183029	1904264	2	3
38.062031	-120.183723	1904269	2	3
38.062832	-120.184662	1904274	2b	3
38.062691	-120.18396	1904276	2b	3
38.054493	-120.275608	1905290	2b	3
38.027836	-120.239853	1906263	2	3
38.050545	-120.223511	1796876	2	3
38.052055	-120.220665	1796891	2	3
38.054928	-120.21328	1797256	2	3
38.06118	-120.181442	1903776	2	3

38.059562	-120.214111	1797338	2	3
38.059509	-120.218277	1797358	2	3
38.05949	-120.216316	1797365	2	3
38.018528	-120.257652	1797370	2	3
38.01825	-120.257523	1797382	2	3
38.059376	-120.184952	1903801	2	3
38.060135	-120.18325	1903802	2	3
38.028152	-120.239479	1906272	2	3
38.029079	-120.237549	1906275	2	3
38.061218	-120.272591	1910210	2	3
38.016891	-120.257957	1797414	2b	3
38.031106	-120.236915	1805754	2	3
38.060722	-120.197388	1903903	2b	3
38.078739	-120.146721	1903925	2	3
38.060974	-120.261909	1910282	2	3
38.009415	-120.260269	1797472	2	3
38.011322	-120.260399	1797483	2	3
38.031914	-120.238609	1805767	2b	3
38.036777	-120.233252	1805829	2	3
38.03854	-120.233292	1805873	2	3
38.026203	-120.24884	1806031	2	3
38.035728	-120.226135	1806098	2	3

38.026546	-120.241585	1806206	2	3
38.028736	-120.240568	1806230	2	3
38.028885	-120.239929	1806242	2	3
38.02943	-120.238907	1806249	2	3
38.029205	-120.239418	1806250	2	3
38.029503	-120.238342	1806251	2	3
38.029625	-120.238319	1806347	2	3
38.079082	-120.145683	1903926	2	3
38.062454	-120.182625	1904058	2	3
38.060097	-120.195412	1904059	2	3
38.060158	-120.19458	1904063	2b	3
38.060089	-120.195107	1904064	2b	3
38.062256	-120.18045	1904067	2	3
38.044498	-120.231522	1803912	2	3
38.040702	-120.226483	1803946	2	3
38.044155	-120.227257	1803982	2	3
38.043797	-120.229134	1804010	2	3
38.032433	-120.234489	1806376	2	3
38.03043	-120.242924	1806568	2	3
38.031391	-120.243042	1806581	2	3
38.030876	-120.242393	1806582	2	3
38.0485	-120.245255	1807034	2	3

38.047028	-120.247612	1807036	2	3
38.062702	-120.180328	1904076	2	3
38.055077	-120.192383	1904100	2	3
38.059517	-120.178619	1911872	2b	3
38.05801	-120.18013	1911876	2	3
38.059731	-120.177505	1911877	2	3
38.058605	-120.177345	1911883	2	3
38.072483	-120.179512	1911923	2b	3
38.070759	-120.183258	1911960	2b	3
38.0448	-120.22657	1804019	2	3
38.042736	-120.227646	1804035	2	3
38.040142	-120.229988	1804043	2	3
38.038181	-120.238661	1804300	3	3
38.038181	-120.238661	1804301	2	3
38.038907	-120.238018	1804314	2	3
38.041153	-120.237488	1804359	2	3
38.041353	-120.237304	1804367	2b	3
38.036087	-120.237984	1804582	2a	3
38.034176	-120.238182	1804669	2	3
38.034603	-120.238991	1804676	2	3
38.048161	-120.245827	1807143	2	3
38.045834	-120.247597	1807219	2	3

38.053036	-120.194366	1904101	2b	3
38.05603	-120.197762	1903930	2	3
38.056683	-120.198914	1903934	2b	3
38.075054	-120.15033	1903936	2	3
38.075338	-120.151607	1903938	2	3
38.037788	-120.25666	1911206	2	3
38.063744	-120.188744	1902647	2	3
38.063385	-120.188032	1902659	2	3
38.086575	-120.155762	1902697	2	3
38.064506	-120.188007	1902635	2	3
38.033081	-120.264229	1902804	2	3
38.034998	-120.236312	1804868	2	3
38.036095	-120.235741	1804975	2	3
38.036266	-120.235123	1805033	2	3
38.036915	-120.235023	1805048	2	3
38.031433	-120.241013	1805732	2	3
38.051983	-120.234718	1798189	2	3
38.044666	-120.251953	1807236	2	3
38.044201	-120.248009	1807282	2	3
38.057041	-120.199394	1903948	2	3
38.077075	-120.15256	1903952	2	3

38.056728	-120.195854	1903955	2b	3
38.08131	-120.152	1903956	2	3
38.079212	-120.152809	1903958	2	3
38.039204	-120.255287	1911215	2	3
38.066784	-120.271156	1911230	2	3
38.066505	-120.271645	1911234	2	3
38.064503	-120.269791	1911241	2	3
38.065647	-120.273178	1911243	2	3
38.064686	-120.27198	1911254	2	3
38.044943	-120.231024	1803125	2	3
38.051895	-120.235054	1798351	2	3
38.05155	-120.229323	1798389	2	3
38.031334	-120.260033	1807355	2	3
38.026779	-120.254768	1807375	2	3
38.024124	-120.253181	1807425	2	3
38.030556	-120.262787	1808491	2	3
38.080318	-120.153137	1903960	2	3
38.079807	-120.152153	1903962	2	3
38.085899	-120.156303	1903966	2	3
38.078224	-120.152794	1903972	2	3
38.073332	-120.166127	1903973	2	3
38.087017	-120.154724	1903974	2	3

38.038589	-120.255714	1911295	2	3
38.027527	-120.251915	1911297	2	3
38.028503	-120.251793	1911313	2	3
38.029884	-120.25219	1911338	2b	3
38.030716	-120.25338	1911340	2c	3
38.03566	-120.274803	1911360	2	3
38.08305	-120.202126	1911376	3	3
38.040629	-120.218133		1	
38.040554	-120.354362	17970310	2	3
38.023861	-120.356117	17970390	2	3
38.016655	-120.355942	17970440	2	3
38.026417	-120.353699	17970560	2	3
38.025718	-120.37908	17970070	2	3
38.021549	-120.379387	17970080	2	3
38.012089	-120.276473	17975020	2	3
38.012021	-120.276897	17975080	2	3
38.012048	-120.276116	17975110	2	3
38.014129	-120.272967	17975260	2	3
38.012095	-120.275625	17975290	2	3
38.013223	-120.394091	17975380	2	3
38.002784	-120.38442	17975410	2	3
38.010973	-120.311026	17977010	2	3

38.010991	-120.312034	17977050	2	3
37.992305	-120.386568	17993070	2b	2
37.970936	-120.290352	17993310	2	2
37.973557	-120.291405	17993320	2	2
37.993973	-120.388268	17993390	2b	2
37.980679	-120.287994	17977490	2	2
37.974155	-120.295914	17993950	2	2
37.972027	-120.292198	17994040	2	2
37.992417	-120.387405	17994090	2b	2
38.048538	-120.323547	18011510	2	3
37.978597	-120.380057	17978000	2	2
37.980248	-120.380822	17978050	2	2
37.981339	-120.273102	17978620	2c	2
38.049289	-120.322688	18013330	2	3
38.011352	-120.410272	18026500	2b	2
38.019402	-120.409405	18027030	2b	2
38.022638	-120.275195	17978790	2	3
37.960419	-120.323708	17980920	2	2
37.961353	-120.324692	17980930	2	2
37.961983	-120.325447	17980980	2	2
38.012561	-120.284746	17982780	2	3
37.955823	-120.308375	18080120	2	2

37.95985	-120.311099	18080140	3	2
38.009348	-120.274567	17983010	2	3
38.013514	-120.279729	17983100	2	3
38.006291	-120.273183	17983330	2	2
38.012471	-120.286951	17984830	2	3
38.010492	-120.274201	17984900	3	3
38.010492	-120.274201	17984910	3	3
38.022453	-120.279373	18002890	2	3
38.021069	-120.279001	18003140	2	3
37.990812	-120.378993	18003250	2	2
38.002228	-120.312744	18003310	2	2
37.988278	-120.380505	18003510	2	2
38.012438	-120.287836	18003600	3	3
38.012346	-120.286165	18003700	3	3
38.012346	-120.286165	18003710	3	3
38.017301	-120.283356	18003730	2	3
38.011305	-120.27832	17985590	2	3
38.016101	-120.275069	17985660	2	3
38.0068	-120.273099	17985830	3	3
38.010504	-120.277498	17983660	2	3
38.016735	-120.281441	18003790	2	3
38.000675	-120.308884	18003860	2	2

38.019643	-120.28043	18003980	2	3
38.008228	-120.268955	18004600	2	3
38.009737	-120.273	17984460	2	3
37.981392	-120.380791	17979350	2a	2
37.985512	-120.385967	18004880	2b	2
38.007046	-120.38299	18004960	2	3
37.980647	-120.392125	18005650	2	2
37.979729	-120.389946	18006300	2a	2
38.00837	-120.387691	17975440	2	3
38.007977	-120.387491	17975470	2	3
38.012694	-120.400265	17975480	2	2
38.002216	-120.384073	17975500	2	3
37.985277	-120.381838	17979500	2	2
37.986403	-120.382702	17979650	2	2
37.987752	-120.38412	17979860	2	2
38.02664	-120.270537	17979900	2	3
37.997574	-120.269356	17979950	2b	2
37.993007	-120.381052	18006340	2b	2
37.981273	-120.392303	18006960	2	2
38.045448	-120.351173	17975980	2	3
38.014468	-120.306338	17976010	2	3
38.013344	-120.307151	17976070	2	3

37.813427	-120.299049	17976180	2	2
38.013667	-120.307748	17976210	2	3
38.014218	-120.30132	17976230	2	3
38.014405	-120.300949	17976300	2	3
38.01953	-120.269438	17980330	2	3
38.019661	-120.268802	17980430	2	3
37.991645	-120.387663	17994260	2	2
37.999752	-120.268302	17994320	2	2
38.007272	-120.317045	18007950	2	2
37.98378	-120.304298	18008220	2	2
38.008026	-120.314571	18009170	2	2
38.027885	-120.308535	18009460	2	3
38.027885	-120.308535	18009470	2	3
38.053688	-120.356033	17976370	2	3
38.003527	-120.408455	17976410	2	2
38.004368	-120.406151	17976440	2	2
38.015727	-120.304209	17976590	2	3
37.811249	-120.301414	17976610	2	2
38.01687	-120.405298	17976860	2a	2
37.811012	-120.299644	17976920	2	2
38.002277	-120.265441	17994740	2	2
38.00409	-120.265422	17994870	2c	2

38.000213	-120.264913	17995060	3	2
38.006129	-120.260736	17995180	2	2
38.021485	-120.305446	18009820	2	3
37.985462	-120.284823	18009910	2	2
37.959672	-120.311471	18080160	3	2
37.959496	-120.31166	18080170	3	2
37.963152	-120.308797	18080180	3	2
37.958534	-120.311931	18080190	2	2
37.885869	-120.37667	18081640	2	2
38.003696	-120.352379	17970740	2	3
38.014657	-120.266205	17970980	2	3
38.015766	-120.265498	17971040	2	3
38.014942	-120.267087	17971190	2	3
38.014942	-120.267087	17971210	2	3
38.00654	-120.260405	17995280	2	2
38.006388	-120.26052	17995310	2	2
37.978925	-120.312032	17995810	2b	2
37.984737	-120.325035	17995990	2	2
37.886741	-120.373454	18081670	2	2
37.924665	-120.357218	18081950	2	2
37.961054	-120.313652	18082510	2	2
37.962323	-120.317979	18082570	3	2

37.963089	-120.287483	18090480	3	2
38.025387	-120.302027	17971390	2	3
38.026476	-120.300921	17971410	2	3
38.012264	-120.304732	17971440	2	3
38.025809	-120.301459	17971480	2	3
38.02399	-120.30298	17971510	3	3
38.008537	-120.413467	17971710	3	2
38.020715	-120.29828	17971740	2	3
37.984195	-120.431778	17971870	2	2
37.987217	-120.390303	18001380	2a	2
38.013357	-120.277603	18001590	2	3
37.986245	-120.390003	18001670	2	2
38.014984	-120.274569	18001690	2	3
38.016221	-120.272329	18001740	2b	3
37.959896	-120.288377	18090510	2	2
37.962394	-120.291039	18090620	3	2
37.960453	-120.294022	18090690	3	2
37.960453	-120.294022	18090700	2	2
37.962096	-120.291832	18090730	3	2
37.960913	-120.293454	18090750	2	2
37.962221	-120.291275	18090770	3	2
37.953376	-120.301701	18091000	3	2

38.007698	-120.411993	17971900	2	2
38.007698	-120.411993	17971910	3	2
38.00746	-120.409532	17972020	3	2
38.018268	-120.307942	17972060	2	3
37.998272	-120.457954	17972130	3	2
37.998272	-120.457954	17972140	2	2
38.015691	-120.304214	17972190	2	3
38.014276	-120.30499	17972240	2	3
38.015621	-120.306721	17972260	2	3
38.016088	-120.273068	18001950	3	3
38.015748	-120.281772	18002500	3	3
37.984147	-120.394242	17996270	2	2
38.010452	-120.305353	17996320	2	3
37.984306	-120.387589	17997390	2	2
38.011375	-120.40408	17997710	3	2
38.010265	-120.403623	17997720	2	2
37.998405	-120.272532	17998330	2	2
38.00661	-120.271131	17998680	2	3
37.955168	-120.304483	18091070	2	2
37.955168	-120.304483	18091080	2	2
37.95213	-120.298952	18091110	2	2
37.951694	-120.3017	18091160	2	2

38.015492	-120.305554	17972350	2	3
38.015542	-120.306085	17972360	2	3
37.974575	-120.324997	17972600	3	2
38.014992	-120.269384	17972800	3	3
38.015118	-120.270228	17972840	3	3
38.01492	-120.271332	17973030	2	3
37.984722	-120.378723	17998800	2	2
37.985483	-120.378308	17998820	2	2
38.007788	-120.270651	17998830	2	3
37.976795	-120.381752	17999370	3	2
37.979923	-120.381057	17999980	3	2
38.010282	-120.270796	18000150	2	3
38.00983	-120.271109	18000250	2	3
38.014808	-120.272629	17973280	2a	3
37.978729	-120.331596	17973330	2	2
37.989185	-120.322662	17973600	2	2
37.989185	-120.322662	17973610	2a	2
37.989185	-120.322662	17973620	3	2
38.000336	-120.313171	18000450	3	2
38.013197	-120.272828	18000740	2	3
38.010019	-120.277436	17986120	2	3
38.015154	-120.286569	17986140	3	3

38.012893	-120.286915	17986210	2	3
38.012218	-120.283409	17986290	2	3
38.006838	-120.27256	17986410	2	3
38.012418	-120.26727	17974210	2	3
38.012349	-120.393151	17974890	3	3
38.010978	-120.279898	17974920	2	3
38.010765	-120.280037	17974960	2	3
38.013291	-120.287017	17986710	3	3
37.98254	-120.264816	17986810	2	2
38.015422	-120.278382	17986830	3	3
38.020024	-120.275155	17991130	2	3
37.983712	-120.384222	17991870	2	2
37.984205	-120.386588	17992010	3	2
38.004173	-120.284203	17992370	2c	2
37.963631	-120.384546		2b	
38.010002	-120.277382	2201606	2	3
38.155106	-120.053909	2202779	2	3
38.161922	-120.055634	2202506	2	3
38.146145	-120.073112	2202258	2	3
38.162422	-120.049957	2202071	2	3
38.157642	-120.054764	2202029	2	3
38.158154	-120.055992	2201924	2	3

38.161587	-120.050194	2201573	2	3
38.159878	-120.057014	2201544	2	3
38.080528	-120.153206	2201122	2	3
38.073443	-120.176895	2201119	2	3
38.092492	-120.133932	2201101	2	3
38.079038	-120.15201	2201099	2	3
38.09587	-120.115573	2201097	2	3
38.092257	-120.134745	2201096	2	3
38.087025	-120.154972	2201095	2	3
38.0719	-120.171617	2201089	2	3
38.081485	-120.147942	2201081	2	3
38.071411	-120.173698	2201080	2	3
38.07539	-120.151688	2201140	2	3
38.078289	-120.152794	2201139	2	3
38.075153	-120.150475	2201133	2	3
38.088276	-120.138199	2201130	2	3
37.985752	-120.263481	2202380	2	3
37.837048	-120.189018	2201963	2	3
37.836182	-120.185501	2201785	2	3
37.819523	-120.223518	2201598	2	3
37.837482	-120.179085	2201458	2	3
37.824642	-120.231865	2201432	2	3

37.835594	-120.193947	2202525	2	3
38.012398	-120.284683	2201637	2	3
37.987553	-120.375824	2201580	2	3
38.028503	-120.366676	2201478	2	3
38.002823	-120.38443	2201430	2	3
37.98711	-120.374679	2201316	2	3
38.026386	-120.368141	2201275	2	3
38.040962	-120.343277	2201233	2	3
38.007938	-120.387421	2202699	2	3
38.002277	-120.384102	2202437	2	3
38.016197	-120.306877	2202405	2	3
38.008366	-120.38768	2202366	2	3
38.013799	-120.276507	2202694	3	3
38.01567	-120.285961	2202621	3	3
38.012539	-120.292007	2202311	2b	3
38.092144	-120.135719	2201124	2b	3
37.98711	-120.374679	2201315	2a	3
38.007584	-120.305771	2202362	2b	3
38.196819	-120.013016	2201360	2b	3
38.029179	-120.288727	2201635	3	3
38.023952	-120.303047	2201474	3	3
38.01799	-120.304016	2201399	3	3

38.019207	-120.272583	2201248	3	3
38.015678	-120.265472	2201225	3	3
38.018604	-120.277298	2202768	3	3
38.014153	-120.275637	2202761	3	3
38.040943	-120.358704	2202740	3	3
38.026293	-120.276782	2202737	3	3
38.015182	-120.270035	2202682	3	3
38.023758	-120.269798	2202679	3	3
38.017342	-120.283447	2202662	3	3
38.010464	-120.274223	2202656	3	3
38.030811	-120.293163	2202618	3	3
38.028614	-120.365608	2202572	3	3
38.010078	-120.269791	2202520	3	3
38.014961	-120.269241	2202482	3	3
38.035774	-120.339462	2202479	3	3
37.995037	-120.252678	2202417	3	3
38.012558	-120.279724	2202346	3	3
37.997875	-120.255089	2202312	3	3
38.009022	-120.302162	2202296	3	3
38.008755	-120.267929	2202219	3	3
38.010895	-120.28006	2202194	3	3
38.01141	-120.306908	2202178	3	3

38.026264	-120.270653	2202150	3	3
38.011311	-120.279617	2202119	3	3
38.016815	-120.304878	2202108	3	3
38.015118	-120.270813	2202042	3	3
37.999992	-120.260162	2201940	3	3
37.996456	-120.252037	2201921	3	3
38.015143	-120.265678	2201890	3	3
38.011539	-120.289719	2201833	3	3
38.010353	-120.270714	2201829	3	3
37.825294	-120.188713	2201744	3	3
37.819523	-120.223518	2201596	3	3
37.813599	-120.131416	2201549	3	3
37.825687	-120.188148	2201468	3	3
37.825489	-120.19828	2201257	3	3
37.830124	-120.204681	2201238	3	3
37.841858	-120.169243	2202869	3	3
37.825607	-120.198517	2202305	3	3
37.820103	-120.226234	2202229	3	3
37.818905	-120.225731	2202186	3	3
37.824585	-120.19619	2202088	3	3
38.013721	-120.305855	2201796	3	3
38.012314	-120.268166	2201763	3	3

38.014725	-120.271706	2201760	3	3
37.998577	-120.261337	2201669	3	3
38.008572	-120.275246	2201659	3	3
38.010643	-120.274002	2201642	3	3
38.055557	-120.197985	2201450	2	3
38.057525	-120.256765	2202609	2b	3
38.058895	-120.175667	2201854	2	3
38.04454	-120.209366	2201914	2	3
38.026104	-120.252533	2201919	2	3
38.05608	-120.199791	2201933	2	3
38.065121	-120.185112	2201943	2	3
38.057125	-120.203033	2202635	2	3
38.051642	-120.202353	2202636	2	3
38.024242	-120.253273	2202643	2	3
38.103413	-120.123917	2201143	2	3
38.07332	-120.166108	2201148	2	3
38.091122	-120.138268	2201152	2	3
38.076587	-120.170638	2201154	2	3
38.077343	-120.152168	2201156	2	3
38.080438	-120.15152	2201160	2	3
38.056063	-120.197872	2201880	2	3

38.03809	-120.231712	2201903	2	3
38.059433	-120.214127	2201948	2	3
38.060951	-120.19223	2201950	2	3
38.050362	-120.226173	2201968	2	3
38.029976	-120.264076	2201973	2	3
38.029976	-120.264076	2201974	2b	3
38.066212	-120.269632	2202664	2	3
38.030254	-120.2369	2202669	3	3
38.077018	-120.169952	2201168	2	3
38.082214	-120.147308	2201174	2	3
38.078728	-120.146698	2201178	2	3
38.058449	-120.181717	2201610	2	3
38.057373	-120.19466	2201625	2	3
38.062054	-120.193619	2201631	2	3
38.06683	-120.280174	2201634	2	3
38.056947	-120.195543	2201990	2	3
38.032333	-120.267586	2202006	2	3
38.079159	-120.14595	2201193	2	3
38.074572	-120.172962	2201200	2	3
38.061107	-120.261898	2201650	2	3
38.030575	-120.22303	2201655	2	3
38.044239	-120.228844	2201674	2	3

38.0659	-120.26688	2202039	2	3
38.058332	-120.194797	2202040	2	3
38.032535	-120.204285	2202063	2	3
38.038433	-120.260887	2202067	3	3
38.05933	-120.270542	2202070	2	3
38.038757	-120.261101	2202458	3	3
38.060652	-120.179517	2202459	2	3
38.064083	-120.19165	2202478	2	3
38.062712	-120.194133	2202484	2	3
38.048244	-120.224762	2201237	2	3
38.05789	-120.195697	2202499	2	3
38.05917	-120.191188	2202519	2	3
38.067205	-120.182085	2201262	2	3
38.030899	-120.235695	2202537	2b	3
38.027618	-120.224403	2202241	2	3
38.056658	-120.193083	2202261	2	3
38.060089	-120.194717	2201291	2	3
38.066695	-120.271168	2201483	2	3
38.061692	-120.263267	2201679	2	3
38.030994	-120.253029	2201487	2	3
38.059137	-120.195133	2201493	2	3
38.032658	-120.269821	2201684	2	3

38.032658	-120.269821	2201685	2	3
38.062055	-120.193145	2202266	2	3
38.044144	-120.226807	2202294	2	3
38.062553	-120.194793	2201576	2	3
38.06181	-120.182426	2201584	2b	3
38.03231	-120.263008	2202300	2	3
38.023792	-120.252945	2202331	2b	3
38.054513	-120.21383	2202343	2	3
38.050567	-120.223545	2201593	2	3
38.064665	-120.27201	2201540	2	3
38.037842	-120.233414	2201757	2	3
38.054053	-120.1947	2201790	2	3
38.041245	-120.21788	2201801	2b	3
38.041245	-120.21788	2201802	2	3
38.054852	-120.234444	2201803	2	3
38.05118	-120.200028	2202365	2	3
38.037758	-120.261192	2202384	2	3
38.056413	-120.178353	2201545	2	3
38.069048	-120.181647	2201547	2	3
38.052038	-120.21383	2201297	2	3
38.050925	-120.220622	2201805	2	3
38.03006	-120.252045	2201811	2	3

38.03006	-120.252045	2201812	2b	3
38.052956	-120.234612	2202080	3	3
38.044018	-120.228996	2202401	2	3
38.06245	-120.182648	2201318	2	3
38.067368	-120.188612	2201327	2	3
38.05769	-120.198212	2202100	2	3
38.062965	-120.188072	2202118	2	3
38.059467	-120.188568	2202446	2	3
38.053422	-120.213888	2201342	2	3
38.061138	-120.17598	2201351	2	3
38.056999	-120.178864	2201352	2	3
38.056885	-120.19949	2201357	2	3
38.033051	-120.262184	2202130	2	3
38.058846	-120.19548	2202135	2	3
38.06044	-120.278213	2202144	2	3
38.02795	-120.258545	2202152	2	3
38.064461	-120.269974	2202153	2	3
38.064232	-120.276001	2202160	2	3
38.027359	-120.248581	2202199	2	3
38.056225	-120.184987	2202205	2	3
38.053474	-120.208153	2202450	2	3
38.050853	-120.217393	2202693	2	3

38.034142	-120.232063	2202704	2	3
38.039005	-120.261192	2202706	2	3
38.046407	-120.223455	2201389	2	3
38.05446	-120.194177	2202211	2	3
38.032013	-120.258583	2202218	2	3
38.028168	-120.224236	2202554	2	3
38.059838	-120.177518	2202561	2	3
38.057732	-120.186623	2202709	2	3
38.030453	-120.26638	2202712	2	3
38.050673	-120.22622	2202731	2	3
38.050537	-120.22549	2202749	2	3
38.056627	-120.185782	2202750	2	3
38.036106	-120.230782	2202766	2b	3
38.0238	-120.225632	2202788	2	3
37.100028	-120.929823		2	
37.7533	-120.129082	2202859	2	3
37.018202	-120.28972		2	
38.057907	-120.236266		1	
38.057693	-120.236485		2	
37.295142	-120.433797		1	
38.00007	-120.382133		1	
38.056907	-120.184315		1	

38.201134	-120.005736		1	2
37.908379	-120.510986	2854135	2b	2
37.718414	-119.669876	2857549	2b	2
37.959301	-120.372925	2858024	2b	2
37.988251	-120.283195	2858125	2b	2
38.062832	-120.184742		1	
38.060164	-120.2788		1	
38.057564	-120.178715		1	
37.124166	-120.267083		3	
37.123728	-120.267155		1	
37.958614	-120.288931		1	

POLE_TERM_MH_INFO	PLACEMENT
npt	Aerial
4090	Aerial
9301	Aerial
13616	Aerial
120014188	Aerial
9648	Aerial
NPT	Aerial
13600	Aerial
NPT	Aerial
12	Aerial
NPT	Aerial
3790	Aerial
120239658	Aerial
NPT	Aerial
9875	Aerial
NPT	Aerial
NPT	Aerial
120187266	Aerial
104085	Aerial
101265	Aerial
9108	Aerial

120779170	Aerial
9884	Aerial
10138	Aerial
103	Aerial
4090	Aerial
NPT	Aerial
9699	Aerial
2020	Aerial
2353	Aerial
NPT	Aerial
NPT	Aerial
120134333	Aerial
NPT	Aerial
NPT	Aerial
1918	Aerial
NPT	Aerial
505	Aerial
110472457	Aerial
107184	Aerial
NPT	Aerial
NPT	Aerial

NPT	Aerial
NPT	Aerial
NPT	Aerial
120239658	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
5754	Aerial
5940	Aerial
15088	Aerial
15088	Aerial
231	Aerial
NPT	Aerial
NPT	Aerial
15	Aerial
120779166	Aerial
11223	Aerial
9371	Aerial
2845	Aerial
NPT	Aerial

NPT	Aerial
120779167	Aerial
5695	Aerial
NPT	Aerial
NPT	Aerial
9520	Aerial
5371	Aerial
10353	Aerial
104092	Aerial
2783	Aerial
2041	Aerial
9466	Aerial
NPT	Aerial
10309	Aerial
104751	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
15129	Aerial
3309	Aerial
10369	Aerial

120766309	Aerial
120175823	Aerial
120238315	Aerial
3169	Aerial
953	Aerial
5874	Aerial
NPT	Aerial
2609	Aerial
390	Aerial
2931	Aerial
NPT	Aerial
110273021	Aerial
NPT	Aerial
25882	Aerial
NPT	Aerial
110304569	Aerial
9503	Aerial
110483349	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
128	Aerial

110150	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
18128	Aerial
9460	Aerial
17180	Aerial
9460	Aerial
126	Aerial
0122S	Aerial
16769	Aerial
NPT	Aerial
103622	Aerial
NPT	Aerial
NPT	Aerial
126	Aerial
NPT	Aerial
7	Aerial
NPT	Aerial
NPT	Aerial
120217167	Aerial
120152087	Aerial

6576	Aerial
220	Aerial
236	Aerial
120761317	Aerial
109725	Aerial
NPT	Aerial
1566	Aerial
NPT	Aerial
17180	Aerial
12	Aerial
6	Aerial
102951	Aerial
NPT	Aerial
NPT	Aerial
8	Aerial
NPT	Aerial
107904	Aerial
51	Aerial
NPT	Aerial
56	Aerial
NPT	Aerial
455	Aerial

NPT	Aerial
5	Aerial
10	Aerial
NPT	Aerial
18015	Aerial
126	Aerial
NPT	Aerial
110466345	Aerial
NPT	Aerial
249	Aerial
110090329	Aerial
1098345	Aerial
910P	Aerial
584	Aerial
NPT	Aerial
120105899	Aerial
11164	Aerial
120183829	Aerial
NPT	Aerial
B15AD	Aerial
110800	Aerial

NPT	Aerial
120241727	Aerial
110461038	Aerial
6	Aerial
NPT	Aerial
110461036	Aerial
11164	Aerial
19706	Aerial
NPT	Aerial
110392604	Aerial
18130	Aerial
96	Aerial
110483306	Aerial
110387724	Aerial
1098345	Aerial
NPT	Aerial
117065	Aerial
120005387	Aerial
NPT	Aerial
103210	Aerial
11164	Aerial
17995	Aerial

7	Aerial
110467445	Aerial
719785	Aerial
11164	Aerial
2545	Aerial
NPT	Aerial
63	Aerial
22770	Aerial
21892	Aerial
20635	Aerial
120057549	Aerial
2073	Aerial
22485	Aerial
469	Aerial
2	Aerial
15409	Aerial
B6	Aerial
21920	Aerial
20	Aerial
Npt	Aerial
23339	Aerial
34	Aerial

40	Aerial
37	Aerial
488	Aerial
NPT	Aerial
469	Aerial
NPT	Aerial
NPT	Aerial
110354060	Aerial
NPT	Aerial
29	Aerial
3	Aerial
NPT	Aerial
NPT	Aerial
npt	Aerial
21732	Aerial
Npt	Aerial
120124435	Aerial
Npt	Aerial
63	Aerial
34	Aerial
105124	Aerial
106250	Aerial

23025	Aerial
12025	Aerial
672	Aerial
22420	Aerial
33	Aerial
110096	Aerial
22016	Aerial
Npt	Aerial
npt	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
	Aerial
9309	Aerial
	Aerial
	Aerial
P1210	Aerial
	Aerial
	Aerial
	Aerial
120379810	Aerial

1098	Aerial
G102	Aerial
NPT	Aerial
NPT	Aerial
16	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial

128	Aerial
128	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
120254899	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial

NPT	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
3279	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
64	Aerial
NPT	Aerial
16	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial

NPT	Aerial
NPT	Aerial
NPT	Aerial
1100	Aerial
1048	Aerial
NPT	Aerial
G576	Aerial
C576	Aerial
C576	Aerial
1021	Aerial
NPT	Aerial
27	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial

1035	Aerial
NPT	Aerial
164151	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
994	Aerial
NPT	Aerial
576B	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
10A	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
120841802	Aerial

NPT	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
26307	Aerial
1102	Aerial
1102	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
11059	Aerial
SPAN	Aerial
18355	Aerial
NPT	Aerial
NPT	Aerial

SPAN	Aerial
NPT	Aerial
103393	Aerial
103395	Aerial
NPT	Aerial
103352	Aerial
10354060	Aerial
SPAN	Aerial
NPT	Aerial
NPT	Aerial
27	Aerial
SPAN	Aerial
12	Aerial
225	Aerial
SPAN	Aerial
2025	Aerial
2041	Aerial
103	Aerial
C672	Aerial
SPAN	Aerial
SPAN	Aerial
SPAN	Aerial

20586	Aerial
40	Aerial
SPAN	Aerial
NPT	Aerial
SPAN	Aerial
NPT	Aerial
SPAN	Aerial
111584	Aerial
SPAN	Aerial
16430	Aerial
15433	Aerial
NPT	Aerial
120112813	Aerial
120057606	Aerial
SPAN	Aerial
SPAN	Aerial
NPT	Aerial
2	Aerial
NPT	Aerial
1044P	Aerial
64	Aerial

109329	Aerial
NPT	Aerial
NPT	Aerial
9	Aerial
NPT	Aerial
15538	Aerial
NPT	Aerial
34	Aerial
15405	Aerial
NPT	Aerial
15417	Aerial
110410215	Aerial
9	Aerial
21730	Aerial
SPAN	Aerial
SPAN	Aerial
SPAN	Aerial
NPT	Aerial
SPAN	Aerial
SPAN	Aerial

23253	Aerial
567P	Aerial
120773943	Aerial
SPAN	Aerial
NPT	Aerial
NPT	Aerial
13	Aerial
NPT	Aerial
NPT	Aerial
A276	Aerial
120827163	Aerial
34	Aerial
NPT	Aerial
20689	Aerial
20872	Aerial
20649	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
120800088	Aerial

NPT	Aerial
120826918	Aerial
NPT	Aerial
NPT	Aerial
120869930	Aerial
NPT	Aerial
120800089	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
110466367	Aerial
NPT	Aerial
NPT	Aerial
120045447	Aerial
120804319	Aerial
120804318	Aerial
110418472	Aerial
NPT	Aerial
NPT	Aerial
120800100	Aerial
120800076	Aerial

NPT	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
120806412	Aerial
NPT	Aerial
120826979	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial

120823240	Aerial
120152196	Aerial
120769909	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
109262	Aerial
NPT	Aerial
120806409	Aerial
120153521	Aerial
12077575	Aerial
120774218	Aerial
NPT	Aerial
120775651	Aerial
NPT	Aerial
NPT	Aerial
120187268	Aerial
NPT	Aerial
NPT	Aerial

NPT	Aerial
107202	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
1109933	Aerial
NPT	Aerial
120827975	Aerial
120773929	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
120102873	Aerial
120826910	Aerial
120780353	Aerial
110422286	Aerial

120869926	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
120805925	Aerial
NPT	Aerial
NPT	Aerial
120153521	Aerial
NPT	Aerial
120867914	Aerial
NPT	Aerial
NPT	Aerial
120827085	Aerial
NPT	Aerial
120806412	Aerial
NPT	Aerial
NPT	Aerial
120789964	Aerial
120814174	Aerial
NPT	Aerial
NPT	Aerial

NPT	Aerial
NPT	Aerial
NPT	Aerial
	Aerial
2811	Aerial
	Aerial
	Aerial
	Aerial
23875	Aerial
	Aerial
1028	Aerial

5

NPT	Aerial
NPT	Aerial
181593	Aerial
107154	Aerial
107163	Aerial
NPT	Aerial
NPT	Aerial
109146	Aerial
120350038	Aerial
510P	Aerial
NPT	Aerial
NPT	Aerial
107036	Aerial
120774256	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
110363458	Aerial
121217649	Aerial
121217650	Aerial

110492683	Aerial
NPT	Aerial
NPT	Aerial
20281	Aerial
NPT	Aerial
121262268	Aerial
NPT	Aerial
120254875	Aerial
121219600	Aerial
NPT	Aerial
121229276	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
121219607	Aerial
121219550	Aerial
121217707	Aerial
121236193	Aerial
NPT	Aerial
103276	Aerial
103729	Aerial

NPT	Aerial
NPT	Aerial
120812335	Aerial
NPT	Aerial
121220567	Aerial
121220566	Aerial
NPT	Aerial
121220602	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
121236187	Aerial
121220135	Aerial
NPT	Aerial
121220498	Aerial
121220610	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial

120219138	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
103366	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
120773194	Aerial
121264513	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
121217667	Aerial
NPT	Aerial
121217656	Aerial
110461077	Aerial
121150164	Aerial
121217703	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial

NPT	Aerial
107047	Aerial
NPT	Aerial
107276	Aerial
NPT	Aerial
NPT	Aerial
121219525	Aerial
121219335	Aerial
121219494	Aerial
121262257	Aerial
121262216	Aerial
NPT	Aerial
121262225	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
109398	Aerial
109436	Aerial
NPT	Aerial
NPT	Aerial
121262223	Aerial
121219487	Aerial

121220501	Aerial
121220603	Aerial
120841801	Aerial
121262221	Aerial
121262212	Aerial
120761974	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
121220273	Aerial
121220361	Aerial
121220349	Aerial
NPT	Aerial
121220336	Aerial
121220525	Aerial
NPT	Aerial
121217638	Aerial
NPT	Aerial
117364	Aerial
NPT	Aerial
120792895	Aerial

NPT	Aerial
121219380	Aerial
120861178	Aerial
121219184	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
121219409	Aerial
121219185	Aerial
NPT	Aerial
121219194	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
110480815	Aerial
NPT	Aerial
110406177	Aerial
NPT	Aerial
104088	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial

NPT	Aerial
122460	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
120295166	Aerial
NPT	Aerial
NPT	Aerial
120501828	Aerial
120192273	Aerial
120789939	Aerial
NPT	Aerial
120192228	Aerial

NPT	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
121069892	Aerial
NPT	Aerial
NPT	Aerial
121027213	Aerial
120827038	Aerial
112234	Aerial
NPT	Aerial
NPT	Aerial

NPT	Aerial
NPT	Aerial
NPT	Aerial
184354	Aerial
184354	Aerial
NPT	Aerial
112136	Aerial
NPT	Aerial
120105719	Aerial
NPT	Aerial
NPT	Aerial
120014189	Aerial
104190	Aerial
NPT	Aerial
121151677	Aerial
NPT	Aerial
120136776	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
120154684	Aerial

121079233	Aerial
104457	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
120239700	Aerial
120844420	Aerial
NPT	Aerial
121029870	Aerial
121077373	Aerial
110462438	Aerial
NPT	Aerial
121069891	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
27J1F30E	Aerial

SM13491	Aerial
NPT	Aerial
NPT	Aerial
112935	Aerial
NPT	Aerial
120789516	Aerial
120789516	Aerial
NPT	Aerial
121202503	Aerial
172222	Aerial
157888	Aerial
NPT	Aerial
NPT	Aerial
121202560	Aerial
NPT	Aerial
NPT	Aerial
121069308	Aerial
NPT	Aerial
NPT	Aerial
121031937	Aerial
NPT	Aerial
NPT	Aerial

NPT	Aerial
NPT	Aerial
NPT	Aerial
120842761	Aerial
121202553	Aerial
NPT	Aerial
NPT	Aerial
112238	Aerial
112235	Aerial
120789420	Aerial
NPT	Aerial
12103456	Aerial
12059598	Aerial
NPT	Aerial
120576544	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
120379809	Aerial
120062570	Aerial

110248079	Aerial
3292	Aerial
12052863	Aerial
120575890	Aerial
120239659	Aerial
120575889	Aerial
120528633	Aerial
120576002	Aerial
120575887	Aerial
120379819	Aerial
120564857	Aerial
120576467	Aerial
120576402	Aerial
120576425	Aerial
120589078	Aerial
120575981	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
121217606	Aerial
NPT	Aerial

NPT	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
109531	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial

NPT	Aerial
110382208	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
120761298	Aerial
120122606	Aerial
110461038	Aerial
NPT	Aerial
110461036	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
120440607	Aerial

110387724	Aerial
NPT	Aerial
NPT	Aerial
102961	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
105855	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial

NPT	Aerial
NPT	Aerial
NPT	Aerial
121217614	Aerial
120861219	Aerial
NPT	Aerial
224698	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
231616	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
109868	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial

110428243	Aerial
120761317	Aerial
120021246	Aerial
NPT	Aerial
NPT	Aerial
121112790	Aerial
NPT	Aerial
NPT	Aerial
117081	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
105555	Aerial

NPT	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
121152472	Aerial
121217490	Aerial
105509	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial

NPT	Aerial
110202940	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
78453	Aerial
109696	Aerial
109696	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial

NPT	Aerial
NPT	Aerial
110486587	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
120509344	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
120509334	Aerial
120841802	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial

120930425	
	Aerial
121269319	Aerial
20872	Aerial
121269195	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
105005	Aerial
NPT	Aerial
110312253	Aerial
NPT	Aerial
120057548	Aerial
120057545	Aerial
NPT	Aerial
NPT	Aerial
120412312	Aerial
NPT	Aerial
120859330	Aerial

113246	Aerial
NPT	Aerial
23890	Aerial
18300	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
12745	Aerial
121028161	Aerial
121028161	Aerial
22730	Aerial
22733	Aerial
22838	Aerial
NPT	Aerial
117206	Aerial
NPT	Aerial
121264478	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial

NPT	Aerial
NPT	Aerial
121152207	Aerial
121071507	Aerial
17855	Aerial
12107867	Aerial
121217755	Aerial
121217755	Aerial
121217755	Aerial
121217755	Aerial
121217762	Aerial
NPT	Aerial
12127775	Aerial
NPT	Aerial
NPT	Aerial
120559402	Aerial
NPT	Aerial
NPT	Aerial
102097	Aerial
NPT	Aerial
NPT	Aerial

NPT	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
12041124	Aerial
NPT	Aerial
120312118	Aerial
NPT	Aerial
120412203	Aerial
121266202	Aerial
121267925	Aerial
120971212	Aerial
120413579	Aerial
120119415	Aerial
102004	Aerial
120151252	Aerial
10248	Aerial
NPT	Aerial

NPT	Aerial
110586	Aerial
NPT	Aerial
NPT	Aerial
110582	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
114297	Aerial
120412215	Aerial
120973012	Aerial
17975	Aerial
NPT	Aerial
120775776	Aerial
NPT	Aerial
121217575	Aerial
NPT	Aerial
NPT	Aerial
121237761	Aerial
20670	Aerial

121267921	Aerial
121267921	Aerial
121267914	Aerial
109161	Aerial
121225905	Aerial
NPT	Aerial
NPT	Aerial
102417	Aerial
NPT	Aerial
NPT	Aerial
120254876	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
121255594	Aerial
103133	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
102542	Aerial
121027866	Aerial

121217763	Aerial
17825	Aerial
121217769	Aerial
NPT	Aerial
120429818	Aerial
121225924	Aerial
103623	Aerial
121225771	Aerial
NPT	Aerial
NPT	Aerial
102423	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
120841740	Aerial
NPT	Aerial
NPT	Aerial
109725	Aerial
NPT	Aerial
121256597	Aerial
102536	Aerial

120483202	Aerial
NPT	Aerial
NPT	Aerial
120411938	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
18395	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
151262	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
120411911	Aerial
NPT	Aerial
NPT	Aerial
17806	Aerial

10279	Aerial
NPT	Aerial
120008863	Aerial
116253	Aerial
121217751	Aerial
120105673	Aerial
NPT	Aerial
120004542	Aerial
NPT	Aerial
NPT	Aerial
120411904	Aerial
110090263	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
120561010	Aerial
NPT	Aerial
NPT	Aerial

103168	Aerial
NPT	Aerial
20235	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
18251	Aerial
110613	Aerial
NPT	Aerial
12112793	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
121027725	Aerial
1115	Aerial
NPT	Aerial
110312255	Aerial
NPT	Aerial
NPT	Aerial
105018	Aerial

120057549	Aerial
120057608	Aerial
120057606	Aerial
NPT	Aerial
NPT	Aerial
120154759	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
120084423	Aerial
11240	Aerial
11164	Aerial
121217757	Aerial
NPT	Aerial
NPT	Aerial
1209982088	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
121255559	Aerial
121217754	Aerial

12127756	Aerial
NPT	Aerial
NPT	Aerial
105252	Aerial
NPT	Aerial
NPT	Aerial
105846	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
120809318	Aerial
NPT	Aerial
121221155	Aerial
NPT	Aerial
106766	Aerial
106824	Aerial
NPT	Aerial
103186	Aerial
NPT	Aerial
NPT	Aerial

121217569	Aerial
121217559	Aerial
NPT	Aerial
105760	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
110418188	Aerial
110418188	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
120021369	Aerial
110382213	Aerial
121266418	Aerial
NPT	Aerial
14800	Aerial
110523137	Aerial
NPT	Aerial
120057542	Aerial
120057542	Aerial
NPT	Aerial

NPT	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
121150284	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
120412130	Aerial
19026	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
11558	Aerial
110090283	Aerial
121225034	Aerial
121225052	Aerial
120867688	Aerial
121225036	Aerial
121239298	Aerial
1212569899	Aerial

NPT	Aerial
NPT	Aerial
121256749	Aerial
NPT	Aerial
110377570	Aerial
121262128	Aerial
121262134	Aerial
12073256	Aerial
121262131	Aerial
12125723	Aerial
120930720	Aerial
120864960	Aerial
121256827	Aerial
121256828	Aerial
121256831	Aerial
NPT	Aerial
121256653	Aerial
NPT	Aerial
NPT	Aerial
121225050	Aerial
120789964	Aerial

NPT	Aerial
Npt	Aerial
121225097	Aerial
121073956	Aerial
NPT	Aerial
NPT	Aerial
121299397	Aerial
120800095	Aerial
121299359	Aerial
120805925	Aerial
121074061	Aerial
121225065	Aerial
Npt	Aerial
Npt	Aerial
121239253	Aerial
121239218	Aerial
121239255	Aerial
121239260	Aerial
120852338	Aerial
121225107	Aerial
121225102	Aerial
121225103	Aerial

120852326	Aerial
12107846	Aerial
121268125	Aerial
121268102	Aerial
NPT	Aerial
121268110	Aerial
NPT	Aerial
121224962	Aerial
121262279	Aerial
121262308	Aerial
NPT	Aerial
NPT	Aerial
121069347	Aerial
NPT	Aerial
121259683	Aerial
121259693	Aerial
121268113	Aerial
121268059	Aerial
NPT	Aerial
512	Aerial
NPT	Aerial
NPT	Aerial

120806356	Aerial
121224940	Aerial
121224938	Aerial
NPT	Aerial
120789968	Aerial
NPT	Aerial
121259643	Aerial
107355	Aerial
1210002413	Aerial
120364194	Aerial
121268013	Aerial
100875	Aerial
121224643	Aerial
121224645	Aerial
121224642	Aerial
121074374	Aerial
121257033	Aerial
121257035	Aerial
121257034	Aerial
121262325	Aerial
120934232	Aerial
NPT	Aerial

121239218	Aerial
121224653	Aerial
NPT	Aerial
121259927	Aerial
121259965	Aerial
121259365	Aerial
120818713	Aerial
NPT	Aerial
121259597	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
121225041	Aerial
NPT	Aerial
121257047	Aerial
121259595	Aerial
121257122	Aerial
121257027	Aerial
121257005	Aerial

120859327	Aerial
121259632	Aerial
NPT	Aerial
121299363	Aerial
NPT	Aerial
121225074	Aerial
121225081	Aerial
121225087	Aerial
121014867	Aerial
121225092	Aerial
121262163	Aerial
121262128	Aerial
121225121	Aerial
121262126	Aerial
121262127	Aerial
121262130	Aerial
1220859334	Aerial
121269385	Aerial
NPT	Aerial
NPT	Aerial
120350144	Aerial
121262288	Aerial

NPT	Aerial
NPT	Aerial
NPT	Aerial
121256945	Aerial
121256943	Aerial
120792195	Aerial
120792183	Aerial
121269384	Aerial
121269375	Aerial
120997971	Aerial
121256930	Aerial
100511	Aerial
12082198	Aerial
121224735	Aerial
120775566	Aerial
121238081	Aerial
121256968	Aerial
121256846	Aerial
NPT	Aerial
NPT	Aerial
121264964	Aerial
NPT	Aerial

NPT	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
120516701	Aerial
NPT	Aerial
NPT	Aerial
121224755	Aerial
121262135	Aerial
1212257112	Aerial
121257110	Aerial
1212571111	Aerial
121262159	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
121152427	Aerial
121256925	Aerial
121256833	Aerial
121256835	Aerial
NPT	Aerial

120971263	Aerial
121262160	Aerial
121262148	Aerial
NPT	Aerial
121224955	Aerial
120218924	Aerial
121224935	Aerial
121224887	Aerial
NPT	Aerial
120864974	Aerial
120084281	Aerial
107237	Aerial
121226104	Aerial
121226104	Aerial
NPT	Aerial
111278	Aerial
NPT	Aerial
NPT	Aerial
121256658	Aerial
NPT	Aerial
121201724	Aerial
120930408	Aerial

121262175	Aerial
121026748	Aerial
121026730	Aerial
121224706	Aerial
121224716	Aerial
120775816	Aerial
121225054	Aerial
121225051	Aerial
121224694	Aerial
121225055	Aerial
120794984	Aerial
121256636	Aerial
121256639	Aerial
1104963	Aerial
NPT	Aerial
NPT	Aerial
110483495	Aerial
120930571	Aerial
120131098	Aerial
121026749	Aerial
120866602	Aerial

121026741	Aerial
NPT	Aerial
NPT	Aerial
120871355	Aerial
NPT	Aerial
NPT	Aerial
121027062	Aerial
121299393	Aerial
NPT	Aerial
NPT	Aerial
120963646	Aerial
NPT	Aerial
120451985	Aerial
120932966	Aerial
121256857	Aerial
121239230	Aerial
121224786	Aerial
121224775	Aerial
121224684	Aerial
121224794	Aerial
121224842	Aerial
110342273	Aerial

120823247	Aerial
121256905	Aerial
120238288	Aerial
121256812	Aerial
120777636	Aerial
121260857	Aerial
NPT	Aerial
	Aerial
NPT	Aerial
NPT	Aerial
121221154	Aerial
101234	Aerial
NPT	Aerial
NPT	Aerial
121266526	Aerial
121225675	Aerial
121266527	Aerial
121266534	Aerial
121266528	Aerial
NPT	Aerial
109343	Aerial
121225861	Aerial

121225862	Aerial
472	Aerial
14800	Aerial
1495	Aerial
NPT	Aerial
121234431	Aerial
117491	Aerial
15785	Aerial
NPT	Aerial
NPT	Aerial
139	Aerial
NPT	Aerial
121234249	Aerial
121152486	Aerial
110480761	Aerial
107939	Aerial
120789010	Aerial
NPT	Aerial
110354105	Aerial
NPT	Aerial
121266502	Aerial
NPT	Aerial

NPT	Aerial
121225639	Aerial
121266388	Aerial
121269237	Aerial
NPT	Aerial
1208272229	Aerial
1208272229	Aerial
121266481	Aerial
121266621	Aerial
120057611	Aerial
120799129	Aerial
110368284	Aerial
121266219	Aerial
NPT	Aerial
NPT	Aerial
11400124	Aerial
121225670	Aerial
120807284	Aerial
121269235	Aerial
121225668	Aerial
1201891	Aerial
102454	Aerial

121266555	Aerial
12002586	Aerial
12086330	Aerial
NPT	Aerial
120084413	Aerial
NPT	Aerial
NPT	Aerial
110505348	Aerial
NPT	Aerial
105124	Aerial
NPT	Aerial
NPT	Aerial
47	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
121237678	Aerial
12137	Aerial
NPT	Aerial
116254	Aerial
120925769	Aerial
121267942	Aerial

NPT	Aerial
121267944	Aerial
121226018	Aerial
121226017	Aerial
120035584	Aerial
121269189	Aerial
NPT	Aerial
121237920	Aerial
110467395	Aerial
NPT	Aerial
121225899	Aerial
121225947	Aerial
121225947	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
120998081	Aerial
94	Aerial
12007409	Aerial
41	Aerial
121237897	Aerial
121237888	Aerial

121237905	Aerial
120827252	Aerial
121225926	Aerial
121234387	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
109238	Aerial
121291691	Aerial
NPT	Aerial
121269209	Aerial
120810911	Aerial
120793088	Aerial
120793088	Aerial
120837614	Aerial
120780365	Aerial
121266160	Aerial
19966	Aerial
NPT	Aerial
NPT	Aerial
110329579	Aerial
NPT	Aerial

NPT	Aerial
121225773	Aerial
120761788	Aerial
120241725	Aerial
1212257741	Aerial
12076180	Aerial
120866563	Aerial
121225761	Aerial
120309892	Aerial
NPT	Aerial
12126634	Aerial
110291306	Aerial
11040166	Aerial
12126544	Aerial
NPT	Aerial
NPT	Aerial
120869992	Aerial
120869992	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
110466348	Aerial

NPT	Aerial
NPT	Aerial
121071414	Aerial
121225955	Aerial
120311201	Aerial
120311201	Aerial
120998081	Aerial
121267948	Aerial
121225987	Aerial
121266545	Aerial
120930711	Aerial
NPT	Aerial
120774353	Aerial
NPT	Aerial
NPT	Aerial
21370	Aerial
121237939	Aerial
NPT	Aerial
117383	Aerial
117383	Aerial
164123	Aerial
121264482	Aerial

121225986	Aerial
120451996	Aerial
110410004	Aerial
120773942	Aerial
120841784	Aerial
121269148	Aerial
27	Aerial
NPT	Aerial
121237831	Aerial
121070138	Aerial
NPT	Aerial
120788946	Aerial
121269140	Aerial
121269144	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
120175081	Aerial
121266538	Aerial
121225667	Aerial
120004878	Aerial

110342498	Aerial
121266398	Aerial
151269233	Aerial
121269159	Aerial
NPT	Aerial
121225654	Aerial
12125655	Aerial
110401137	Aerial
120775441	Aerial
121266377	Aerial
121266467	Aerial
455	Aerial
NPT	Aerial
121237872	Aerial
	Aerial
121225667	Aerial
2	Aerial
4	Aerial
121220132	Aerial
10	Aerial
121220429	Aerial
10	Aerial

121220481	Aerial
GB	Aerial
121224786	Aerial
NPT	Aerial
121224677	Aerial
110433218	Aerial
121268102	Aerial
512	Aerial
110342273	Aerial
121032138	Aerial
120364194	Aerial
120930720	Aerial
121224716	Aerial
121224794	Aerial
121224706	Aerial
121268013	Aerial
NPT	Aerial
NPT	Aerial
110363458	Aerial
2	Aerial
127	Aerial
A486	Aerial

120972108	Aerial
121266502	Aerial
121376035	Aerial
121355572	Aerial
24	Aerial
7	Aerial
121355554	Aerial
105250	Aerial
121299146	Aerial
C672	Aerial
121225989	Aerial
34	Aerial
121266328	Aerial
121266261	Aerial
17	Aerial
120173946	Aerial
7	Aerial
15385	Aerial
121217658	Aerial
121073946	Aerial
120761800	Aerial
120827170	Aerial

120765608	Aerial
120810911	Aerial
120829098	Aerial
121152581	Aerial
16	Aerial
121269342	Aerial
120841784	Aerial
121074230	Aerial
110400124	Aerial
120827229	Aerial
121032173	Aerial
121152496	Aerial
120773947	Aerial
120773942	Aerial
121074175	Aerial
120042672	Aerial
121190860	Aerial
12078903	Aerial
121070203	Aerial
120867499	Aerial
121225654	Aerial
121073065	Aerial

121069900	Aerial
120055253	Aerial
121070141	Aerial
120773940	Aerial
121032163	Aerial
121070150	Aerial
121070252	Aerial
120818724	Aerial
120788946	Aerial
NPT	Aerial
2	Aerial
NPT	Aerial
NPT	Aerial
NPT	Aerial
209	Aerial
NPT	Aerial
NPT	Aerial
18	Aerial
NPT	Aerial
NPT	Aerial
121079080	Aerial
120040445	Aerial

120773941	Aerial
120181656	Aerial
121152584	Aerial
120768169	Aerial
121026744	Aerial
120930425	Aerial
121224910	Aerial
28	Aerial
120812329	Aerial
121074374	Aerial
121262169	Aerial
120930723	Aerial
NPT	Aerial
121256856	Aerial
121268125	Aerial
121224842	Aerial
121268025	Aerial
NPT	Aerial
121224720	Aerial
121224765	Aerial
121026748	Aerial

NPT	Aerial
120834186	Aerial
16	Aerial
120790272	Aerial
121239205	Aerial
121239205	Aerial
121299332	Aerial
21	Aerial
NPT	Aerial
121224642	Aerial
121224735	Aerial
121262311	Aerial
121074205	Aerial
121257047	Aerial
6	Aerial
121026728	Aerial
121260723	Aerial
121224755	Aerial
120976939	Aerial
120775566	Aerial
110411002	Aerial
9	Aerial

120859327	Aerial
121257035	Aerial
121259569	Aerial
7	Aerial
121259365	Aerial
NPT	Aerial
121224965	Aerial
121262294	Aerial
120997963	Aerial
120045447	Aerial
121257033	Aerial
121225074	Aerial
B381	Aerial
506	Aerial
120187268	Aerial
120774275	Aerial
121257110	Aerial
121265779	Aerial
120774270	Aerial
121256816	Aerial
121074180	Aerial
121259343	Aerial

121259343	Aerial
121257046	Aerial
12	Aerial
121257004	Aerial
120084419	Aerial
17272	Aerial
NPT	Aerial
120972725	Aerial
120827091	Aerial
121265781	Aerial
3	Aerial
120773262	Aerial
NPT	Aerial
NPT	Aerial
120789964	Aerial
NPT	Aerial
6	Aerial
121224940	Aerial
5	Aerial
121259684	Aerial
120776867	Aerial
176	Aerial

176	Aerial
120806412	Aerial
8	Aerial
121262135	Aerial
121069347	Aerial
121074209	Aerial
121225052	Aerial
121225087	Aerial
121027065	Aerial
121224920	Aerial
121224938	Aerial
24034	Aerial
6	Aerial
120971265	Aerial
121265810	Aerial
17471	Aerial
121027062	Aerial
121299363	Aerial
121264962	Aerial
121262279	Aerial
NPT	Aerial
121259632	Aerial

24	Aerial
NPT	Aerial
120766366	Aerial
120930407	Aerial
121002413'	Aerial
121259853	Aerial
120218924	Aerial
120135482	Aerial
22446	Aerial
120827119	Aerial
120779342	Aerial
121216130	Aerial
28	Aerial
121259460	Aerial
	Aerial
10	Aerial
	Aerial
	Aerial
	Aerial
	Aerial
20795	Aerial
	Aerial

D20	
NPT	Aerial
NPT	Aerial
15	Aerial
9	Aerial
	Aerial
	Aerial
	Aerial
	Aerial
	Aerial
clearance	Aerial

TIX_CLOSEOUT_NARR
;md1646;PC-N;Sent out to clear a tree that was leaning on strand. When I arrived the strand was clear of anything. No tree left

;pe4219; PC-N; 10410 violeta way coulterville; TN: na

CH2861; RAISED DROP TO REQUIRED HEIGHT
EA2979; TREE BRANCHES HAVE BEEN CLEARED FROM CABLE AND NO SHRUBS TOUCHING CABLE, ALL CLEARED

;rr2576; PC-N; Safety hazards geo95 in Lagrange

dg3424; all pairs spliced

dg3424; Respliced 25 park cable and placed new case
jm687j; Tree was removed that was causing vegetation issues no tree or vegetation near pole at this time.
jm687j; Trimmed pine tree around our cable, no more tree pushing or rubbing against our line, took branches with me due to residential area
jm687j; Created DIG ticket for tree company to come cut large branch touching our strand. Branch is hanging over highway 120. Also no safe place to park to access branch, branch will fall onto highway.

em3528; Cbr yes,looks like trees have been trimmed

;ch8326; PC-N; Foliage removed; TN: 9999999

;rr2576; PC-N; bpc tickets in La grange

rn8732; cleared vegetation in designated area from cable.

;rr2576;PC-N;reattachment to higher cable and other various locations laGrange

;rr2576; PC-N; Geo 95 safety hazard in la grange

cf1419; removed bushes around pole needed help with bucket truck 10347 Narcisco Way,

dg3424; removed vegetation from drop wires, not service affe

;ch8326; PC-N; Removed foilage; TN: 9999999

ch8326; Vegetation removed

;ch8326; PC-N; Removed foliage; TN: 9999999

jb7519; vegetation removed from att equipment , job complete

bs2864; Job completed already

;rr2576; PC-N; safety hazard geo 95 in Lagrange

ds6453; no contractor needed for vegetation, lots of it was already trimmed away.

em3528; they have been trimmed already no major tree trouble at this location

cf1419; removed bushes and tree branches around pole 3152 Granite Springs Rd

da1367; cable ok, not sure if trees previously trimmed, but looks fine
jg9626; trimmed tree and cleared cable from tree multiple tree branches pushing down on cable all branches removed and cleared

em3528; Checked and tested,line is cleared,drivetime

;rr2576; PC-N; Geo 95 safety hazards in lagrange

em3528; Tested and checked cable,drivetime to lagrange

em3528; didnt see tree rubbing, drove around and checked

dg3424; removed trees from drop, their is other vegetation by cable but not interfering .

;sd9656; PC-Y; Cleaned up and condition ; TN: 2098675309

dg3175; removed tree limbs empeding on AT&T cables

dg3175; assist tree line issuses

ds6453; everything is already cleared away at location

lh5743; Notified manager MT8231. no vegetation on pole

em3528; checked around pole and all vegitation is cleared

ad2932; worked on clearing vegetation from AT&T facilities and placed new slick enclo

dg3424; removed vegetation from cable

jg9626; tree leaning on cable trimmed multiple branches cleared branches
jg9626; no Tree branches leaning on cable found drove up and down the near area and found nothing advised supervisor mt8321

dg3424; tree Trimming around cab

dg3424; trimmed vegetation around cable.

dg3424; Removed vegetation from cable.

dg3175; removed old splice at dead end

;al1824; PC-N; Removed dead drops raised low drops

;al1824; PC-N; Raised drops removed dead drops

;al1824; PC-N; Raised drops all work complete

;nk5685; PC-N; took down dead drops, pulled up low drops, assisted ml5474 with chronic ipdsl, tbhw

CH2861; TREES AND VEGETATION REMOVED.

;ch2861; PC-Y; Removed brush around cable and pole.

kw5925; All att work complete

kw5925; Vegetation removed..

;ch8326; PC-N; Removed dead aerial drop; TN: 999999

;dm9879;PC-N;Trees trimmed away from at&t lines, cleared off foliage.

jb8576; cmp, MarkIt was for a drop hanging down. Cleaned up low drop and now all is clear.

tj4856; cut trim limbs off plant

jx5547; Tree wasnt bad around lines. Job was takin care of

;ja2756; PC-Y; Tree limbs trimmed for clearance

;ja2756; PC-N; Tree removed/hazard no longer there
jb7519; Vexation issue resolved , found def att temp plastic Velcro cover and placed slick 5 on 600 & 50 prs cables . Job complete

;ja2756; PC-Y; No AT&T on pole/comcast only

cs1623; Overgrown vegetation has been removed from around our aerial facilities c8h

rs8367; drv jmstwn- Chinese camp,clrd trbl on ca span,complete.

jm687j; Trimmed trees and removed excess drop that was cut.

jm687j; Trees have been trimmed, from driveway.

cs1623; vegetation had been removed from cable facilities c8h

rs8367; Drv mdst-Sra, clrd trbl on spn,complete.

rb2924; Already taken care of,work completed

cr1893; All work complete.

dg3424; Removed a few branches by serving terminal, not service affecting.

dk332q; Cable appears to be cleared already. Nothing pulling or damaging cable.
jg9626; trimmed multiple branches to clear strand and cable that was been pushed down by branches home owner gave me permission to stack a pile of branches in from of property cleared cable

da1367; Tree trimming complete

cs1623; overgrown vegetation removed from cable facilities c8h

cs1623; cs1623; GO 95 tkt to remove vegetation from aerial cable facilities tree with branch over hang has already been taken down c8h

jg9626; Tree trimming to clear stress on strand and cable trimmed multiple branches cleared strand

rn8732; cleared multiple branched from tree to clear pathway for cable.

bs2864; job completed

cr1893; All work complete, drops removed turned in bpc for resplicing 100833582

jg9626; Trimmed multiple tree branches hanging on cable piled up branches on road side along other trees cleared any weight on cable

da1367; Drove to Sonora, Trimming complete

da1367; Drove to site,Trimming complete

bs2864; Cleared vegetation and all good now

uv639w; Bucket dose not reach branch that is on cable, would need a chainsaw to cut thick branch advised Eric cox

rx1696; Cleared hz debris,trimmed branches,not serv affctg

rx1696; Trimmed branches,cleared haz debris,not serv affctg

is3295; Trimmed branches line clear

;ns1598; PC-N; Removed downed drop
RS8367; INTIWN DRV 15 MIN,CLRD TRBL IN SPAN,FIBER BEING PLACED ACCROSS PARKING LOTS,COMPLETE.

;cs9743; PC-N; Drops removed

;rn8732; PC-Y; reattached drop to pole.; TN: 6318229

;ch8326; PC-N; Removed dead aerial drop lines; TN: 9999999

;ch8326; PC-N; Routine work complete; TN: 9999999

;cs9743; PC-N; Drop removed

mj1746; Inspected area and found no issues.

rb2924; line removed, all work co

WM9343; REMOVE OLD DROPS

;mt3262;PC-N;Input dIgit job for tree limb removal from Att cable causing impingement issues

;mt3262;PC-N;Input job for 46L to remove branches from Att cables to clear GO 95 violations

;mt3262;PC-N;Input tree removal / trim 46 L marked location to clear GO95 violations
;mg5372;PC-Y;Drove to and checked trees on line. Some trimming and dig it submitted
;TN:2097701148

;mt3262;PC-Y;Tree is marked for removal trimming will not be required

;mt3262;PC-N;Move ASW to proper GO95 clearances all ok now

jm687j; Tree limbs clear from our cable at this address now.

rn8732; Cleared all vegetation around low drop.
jx5547; Trimmed tree branches around pole and off drop put all clippings and tree branches in pile. Lady that lived there says they will use for fire wood

sm1615; Raised,drop,..

rn8732; All drop and wire work completed.

kb5463; All work complete. Close bpc.

kb5463; All rehab work complete

dg3424; removed brush from cable.

mj1746; Inspected area and found no immediate issues.

dk332q; Cut down branches over road that were rubbing on tree limbs. Area clear now.

ml5474; Removed asw and bridal wire, clean up terminal

uv639w; Vegetation cleared already

jm687j; Trimmed trees on fire road around cable no more vegetation, causing issues.

dp7958; Line has been cleared.
jx5547; Couple different trees putting pressure and stress on our lines. Trimmed all branches off and around lines. Put all trimmings in pile

jx5547; Poles and lines were good no stress or tension on drope

dp7958; Trimmed tree away from drop. Free and clear now

is3295; Abrasive branches on line cleared
dk332q; Branches no longer there. Will need a new mark it ticket because pole is broken. Branches are clear.

nk5685; Removed dead drops from midspan to poles, did not see any tree attachments, tbhw

dg3424; All vegetation work is completed. Not service affecting
cr1893; Need tree trimming 4 areas between 21732 El Puma Circle and 21756 El Puma Circle. Contractor 22238424.

da1367; Tree Trimming complete

rb2924; Drop no longer low,all work completed
;jq1534;PC-N;removed dead drop and also removed tree ,pole and tied cable and drops to tree to make safe for night at lakeview and hwy 108 twain harte

kw5925; rmvd hanging dead aerial drop

kw5925; removed hanging dead end drop.

kw5925; secured lashing and cable to strand.

ce2563; removed drop

hc3283; removed defective aerial drop from pole and terminal

rs8367; cleared all lines around prem,complete

ce2563; could not find any low hanging drop

;ml5474; PC-N; Rmv asw from pole

rb2924; line removed,work co

mj1746; inspected area and did not find any low or downed wires.

;ns1598; PC-N; Removed several drops and re attached others

rb2924; lines removed,work com
EM3528; CBR YES,TEST OK,DROP LOW,FIXED,CLEARED HAZARD,ALSO HELPED TECH PER MANAGER MT

SD9656; REHUNG DAMAGE DROP

JA2756; REMOVED OLD DROPS

;db4196; PC-Y; Hanging drop repaired. Seal leaking case MH112. ; TN: 2096314583

;jh4935; PC-N; low cable becaused delashed

broken pole at location

ch8326; Removed down aerial drop
jb7519; Did not have the proper hard ware to raise drop , spoke with tech that had said that some already removed drop and rerouted it , job complete
;jm6318; PC-N; Lifted all lines for customer

ml5474; No further tree work needed

;rc1373;PC-N;Trees trimmed clear GO95

;al1824;PC-N;Cleared limbs around cable

;rc1373;PC-N;Tree already trimmed

BB6851; TRIMMED SMALL BRANCHES OFF OF CABLE AND STRAND, C99

BB6851; TRIMMED SMALL BRANCHES OFF OF CABLE, C99

BB6851; TRIMMED SMALL BRANCHES OFF OF CABLE, C99

BB6851; TRIMMED SMALL BRANCHES AWAY FROM MULTIPLE CABLES, C99

BB6851; UNABLE TO FIND LOCATION BASED ON PICTURES AND MAPS, C99

BB6851; POLE CLEAR, HAS BEEN REPLACED, C99

JS3194; UNABLE TO LOCATE ISSUE BASED ON PICTURES.

SM1615; ALREADY DONE

SM1615; ALREADY DONE

SM1615; ALREADY DONE

SM1615; CLEARED,BRANCHES,FROM,POLE

SM1615; TRIMMED,BACK SOME BRANCHES

SM1615; ALREADY DONE,

SM1615; CLEARED,BRANCHES,OFF,POLE

SM1615; ALREADY DONE

SM1615; BRANCHES,CLEARED,OFF POLE,

DG9898; CHECKED POLE TOK NO TREE BRANCHES AROUND POLE

DG9898; BRANCHES REMOVED AND CLEARED TOK AROUND POLE

;dd378r;PC-Y;Trimmed trees off cable on bonds flat

DG9898; ; TOK ON POLE NO TREE BRANCHES AROUND POLE

DG9898; BRANCHES REMOVED AROUND CABLE ALL CLEAR

DG9898; REMOVED TREE BRANCHES AWAY FROM POLE TOK NOW

DG9898; TOK NOW BRANCHES REMOVED CLEAR

;cs9743; PC-N; @17600 highway 108 there is no G095 infraction.

DG9898; REMOVED TREE BRANCHES TOK AROUND OPLE

DG9898; TOK ON POLE NO TREE BRANCHES AROUND POLE

DG9898; CHECKED POLE TOK NO TREE BRANCHES AROUND POLE

DG9898; REMOVED BRANCHES AROUND POLE
BB6851; TRIMMED SMALL BRANCHES AWAY FROM POLE AND TERMINAL, ALSO EMAILED LINE CREW SUPP ABOUT LOW STRAND TOUCHING CUSTOMER ROOF, C99

BB6851; JOB HAS ALREADY BEEN COMPLETED, C99

BB6851; CUT SMALL BRANCHES AWAY FROM CABLE AND TERMINAL, C99

;cs9743; PC-N; Some foliage but nothing pulling down on the cable
BB6851; UNABLE TO LOCATE ISSUE, SPOKE WITH PROPERTY OWNER AT ADDRESS GIVEN AND ATT FACILITIES ARE UNDER GROUND, C99

BB6851; VERIFIED TREES IN PICTURES ARE NOT IMPINGING ON OR HARMING FACILITIES, C99

JS3194; TRIMMED SMALL BRANCHES

JS3194; UNABLE TO LOCATE BASED ON PICTURES

JS3194; TRIMMED SMALL BRANCHES.

JS3194; ISSUE ALREADY CLEARED

;cs9743; PC-N; Tree already removed

DG9898; REMOVED ALL BRANCHES HANGING OVER CABLE CLEAR AROUND POLE ALSO

DG9898; TOK NEW POLE PLACED OLD ONE WAS BROKEN ON TOP OF POLE

DG9898; REMOVED BRANCHES PLACED 3 SLIC TO PROTECT FROM RUBBING ON TREE TOK

;cs9743; PC-N; Nothing hanging off of our stran

BB6851; TRIMMED SMALL BRANCHES AWAY FROM CABLE, C99

BB6851; TREE CLEARED WHEN CLEARED FOR PGE LINES, C99

BB6851; TRIMMED SMALL BRANCHES AWAY FROM CABLES, C99

;al1824;PC-N;Trimmed branches around cable and pole

;al1824;PC-N;Trimmed branches around cable

;al1824;PC-N;Trimmed branches around cable and pole

;al1824;PC-N;Cleared tree limbs around cable

;al1824;PC-N;Cleared tree limbs around cable

;al1824;PC-N;Cleared tree limbs around cable

;al1824;PC-N;Trimmed branches around cable and pole

;al1824;PC-N;Cleared tree limbs around cable

WM9343; TRIM TREES AND WORK AT KENNEDYS

;cs9743; PC-N; Looks like the tree was already trimmed
;rc1373;PC-N;Branches are mid span unable to reach and not actually touching strand cleared GO95

;rc1373;PC-N;Trees trimmed GO95 cleared

;rc1373;PC-N;Trees already trimmed GO 95 cleared

;al1824;PC-N;Cleared tree limbs around cable

;al1824;PC-N;Trimmed branches around cable

;al1824;PC-N;Cleared tree limbs around cable

;al1824;PC-N;Cleared tree limbs around cable

;al1824;PC-N;Trimmed branches around cable and pole

DG9898; COMPLETE NO TREE LIMBS HANGING OVER CABLE TOK

DG9898; BRANCHES REMOVED TOK AROUND POLE

DG9898; COMPLETE TREE CUT ALREADY CLEAR AROUND POLE

;mh3568; PC-Y; Equipment and hardware removed at location; TN: 2099840012

;ce2563; PC-N; Removed unused drops

rx1696; remvd mult down drops in area,cleared hazardous area,not serv afftg

tj4856; abandoned drops on ground attached to pole on hill, wrecked out
rx1696; Removed multiple down drops,cleared terminal of branches on additional drops,not serv aff

;ce2563; PC-N; Removed unused drops

tj4856; Abandoned drops on two poles, wrecked out p, cleared

tj4856; drops down on hill and river side wrecked out

rt1486; removed extensive drops

DG9898; BRANCHES AND BUSHES REMOVED FROM POLE AND CABLE TOK

BB6851; TRIMMED SMALL BRANCHES AWAY FROM CABLE, C99

BB6851; TRIMMED SMALL BRANCHES AWAY FROM CABLE, C99

BB6851; TRIMMED SMALL BRANCHES AWAY FROM CABLE, C99

BB6851; TRIMMED SMALL BRANCHES AWAY FROM CABLE, C99
;bc8519;PC-N;Rehab,d terminal on mod ok dr and replaced SLC above bbox on lassen DT. No vegetation around assigned pole.

BB6851; TRIMMED SMALL BRANCHES AWAY FROM CABLE, C99

JS3194; TRIMMED SMALL BRANCHES

JS3194; CUT BACK SMALL BRANCHES, CABLE CLEARED

BC1852; BRANCHES CLEAR AROUND POLE , MARKED FOR TREE TRIMMING WITH LASAR

BC1852; TREE BRANCHES CLEAR FROM POLE ALREADY MARKED FOR TREE TRIMMING LASAR

JS3194; CUT BACK SMALL BRANCHES OFF CABLE

JS3194; CUT BACK SMALL BRANCHES OFF CABLE, CABLE IS CLEARED

;al1824; PC-N; Trimmed branches around cable along hwy 120

ml5474; No hzrd to remove, cables ok

nk5685; Tree branches have been trimmed away from facilities, tbhw

rb2924; Tree trimmed,work completed

ml5474; All tree hzrd ar3 clear

ml5474; Tree was removed off cables, no further work needed

nk5685; Tree branches have been trimmed and removed from lines, tbhw

nk5685; Removed dead drops, reterm drops and cable to pole with clamps, tbhw

ml5474; All tree branches have been removed

nk5685; Tree branches are trimmed off cable, tbhw
ml5474; Cut several branches to free cable and strand, put all branches in truck to dispose of at the yard

ml5474; No hzrd to cables, trimming not needed

rx1696; remvd mult drops on adjacent poles,cleared hazardous debris,not serv afftcg

cr1893; All work complete

cr1893; all work complete

rx1696; remvd mult down drops,cleared debris,not serv afftg
;jb7519;PC-Y;G095 violation , heavy foliage strain on pole , leaning , closed and placed new BPC ,;TN:2092015939

;al1824; PC-N; Tree limbs trimmed around cable

rb2924; Trees trimmed,work completed

rb2924; Removed drop,work completed

tj4856; Removed tree limbs on cable

ec2732; Removed branches from cable

ew042g; Veg is clear from tree company as large trees were also cleared.

ds6453; All wiring work completed. Trees have been tripped from cable along ct

is3295; Abrasive vegetation cleared up

kw5925; Gave cable protection.

gb3598; Trees are barely touching cable. Not service effecting at this time. Advised jc9747.

is3295; Abrasive vegetation removed from cable

ds6453; Tree trimming completed and is no longer all over the cable
GC408J; LOCATED TWO BIGGER BRANCHES LEANING OUT SERVICE STRANDS. REMOVED BRANCHES AND CLEARED STRAND.

GC408J; NO TREE LIMBS DAMAGING STRAND DETECTED. JOB CLOSED PER FLOW
GC408J; BRANCHES WILL BE REMOVED BY A MORE CAPABLE AND BETTER EQUIPPED LABOR WORKER.

dg3424; No trimming needed at location

GC408J; TREE BRANCHES CLEARED FROM LEANING ON A SPLICE CASE.

EW042G; AREA TRIMMED AWAY FROM CABLE TRUNKS. ALSO NOTICED HOMES WITH TREES PUSHING DOWN ON OUR DROPS. CUT THOSE DOWN. DROPS ARE NOW TENSION FREE.

ds6453; Trees trimmed but cables still going through the trees but not hanging on it.

GC408J; TREE BRANCHES LEANING ON OUR STRAND CUT.

mj1746; Task has been completed.

ec2732; Did tree trimming to clear cable

GC408J; ALL TREE REFUSE REMOVED
EW042G; TREES HAVE BEEN TRIMMED WHERE IT WAS A PROBLEM WITH THE CABLE TRUNKS. CHECKED UP AND DOWN THE AREA TO SEE IF MORE DEBRIS WAS A PROBLEM BUT ALL LOOKS GOOD. AREA CLEAR.

is3295; Abrasive vegetation cleared up

mj1746; Task has been completed

ec2732; Raised low hanging drop

ec2732; Removed low hanging unused drop

EW042G; CLEARED A LARGE AMOUNT OF VEGETATION. 2 DIFFERENT TREES. REMOVED LOTS OF TREE DEBRIS WRAPPED AROUND CABLE TRUNK AND DROP. ALL CLEARED NOW.

mj1746; Task has been completed.
ew042g; Area has been cleared of foliage. Some trees have been cut down as well. Cable trunk is clear of Vegetation.
ew042g; Cut very large branches causing excess weight on the cable trunks. Placed then on the side or the private road away from driveways and cars.

dg3424; Tree trimming completed

ew042g; Tree was cut at base and removed. All clear.

tj4856; Wrecked out abandoned drops
ew042g; The large tree branches have been cleared from the tension on the cable trunk. Area is clear. No other visual issues can be seen.

dg3424; Vegetation removed from wire
ew042g; Trees have been professionally removed and no longer an issue with cable damage. Veg clear.

ec2732; Removed tree branches off cable

kw5925; Tree trimming complete.

IS3295; ABRASIVE VEGETATION CLEARED OFF CABLE

dg3424; All vegetation removed

is3295; Abrasive vegetation cleared up

ds6453; Tree trimming completed. Cable is still going through trees but isnt being damaged

gb3598; Trees not in structure at this time but will need to be done in future. Advised Jc9747

ec2732; Cleared away branches from cable
EW042G; CLEARED WHAT COULD BE REACHED. THE CABLE VISUALLY DOESNT LOOK TO BE IN ANY KIND OF TROUBLE WITH THE LARGE TREE ITS MAKING CONTACT WITH. VERIFIED PICTURES WITH ERIC COX TO MAKE SURE ITS GOOD. NO REASON RIGHT NOW TO GET A 3RD PARTY COMPANY TO WORK ON THIS TREE. CABLE ALSO GOING THROUGH TREE AND NO DAMAGE NOR ANY MAJOR TENSION ON THE LINE

GC408J; ALL TREE FOLIAGE THAT IS POSSIBLY INTRUDING ON OUR EQUIPMENT HAS BEEN CLEARED.

tj4856; Wrecked out abandoned drops from a pole

IS3295; ABRASIVE VEGETATION CLEARED UP

is3295; Abrasive vegetation has been cleared

IS3295; ABRASIVE VEGETATION CLEARED
GC408J; UPON FURTHER INSPECTION TREE FOLIAGE DOES NOT SEEM TO BE HINDERING OR DAMAGING ATT PROPERTY CURRENTLY. RESIDENT WHERE THE TREE IS HAS SET UP YARD SALE TABLES SET WITH INVENTORY AND IS NOT HOME TO ASK IF THEY CAN MOVE TABLES FOR POSSIBLE TREE TRIMING. TICKET CLOSED DUE TO NON PROPERTY DAMAGING TREE BRANCHES ON STRAND.

GC408J; ALL TREE FOLIAGE CLEARED

dg3175; res,lves downed drops in area

dg3175; removed aireal drops in area

da1367; removed abandoned cut drop

;cl1646; PC-N; checking and repairing go95

em3528; drive time to and from Sonora,removed hazard wiredrops,cleaned up splice

da1367; trees cut back prior to Arival

rn8732; Removed multiple downed drops.

;ch8326; PC-N; Removed dead aerial drops; TN: 9999999

rn8732; cleared out multiple drops from multiple terminals. Cleared up a few hanging drops.

BC1852; CLEAR BRANCHES AROUND POLE

BC1852; CLEAR BRANCHES AROUND POLE

DG9898; REMOVED BRANCHES FROM POLE

;al1824; PC-Y; Trimmed branches around cable

DG9898; COMPLETE ALREADY

;al1824;PC-N;Cleared tree limbs around cable

;al1824;PC-N;Cleared tree limbs around cable

;al1824;PC-N;Cleared tree limbs around cable

;al1824;PC-N;Cleared tree limbs around cable

;al1824;PC-N;Cleared tree limbs around cable

;al1824;PC-N;Cleared tree limbs around cable

;al1824;PC-N;Cleared tree limbs around cable and relished cable

DG9898; BRANCHES REMOVED TOK AROUND POLE

DG9898; TREES CUT ALL CLEAR

DG9898; JOB IS COMPL

DG9898; REMOVED BRANCHES AND BUSHES FROM CABLE TOK

DG9898; BRANCHES REMOVED ALL CLEARED FROM POLE

DG9898; BRANCHES REMOVED   CLEARED AT POLE ALSO

DG9898; REMOVED BRANCHES HANGING ON CABLE CLEARED AROUND POLE

;dg9898;PC-N;Complete

BB6851; UNABLE TO LOCATE ISSUES MATCHING PICTURES TAKEN, C99

BB6851; UNABLE TO LOCATE ISSUE BASED ON PICTURES AND ADDRESS, C99

BB6851; TRIMMED SMALL BRANCHES AWAY FROM CABLE, C99

BB6851; TRIMMED SMALL BRANCHES AWAY FROM CABLE, C99

BB6851; TRIMMED SMALL BRANCHES AWAY FROM CABLES, C99

BB6851; TRIMMED SMALL BRANCHES AWAY FROM CABLE, C99

BB6851; ISSUE HAS ALREADY BEEN CLEARED, C99

BB6851; TRIMMED SMALL BRANCHES AWAY FROM CABLES, C99

JS3194; CUT BACK SMALL BRANCHES OFF CABLE, CABLE CLEARED

JS3194; CUT BACK SMALL BRANCHES OFF CABLE, CABLE CLEARED

JS3194; CUT BACK SMALL BRANCHES OF CABLE AND CLEARED CABLE

JS3194; TRIMMED BACK SMALL BRANCHES AND CLEARED CABLE PATH

;al1824;PC-Y;Trimmed branches around cable and pole

;al1824;PC-N;Tree crew already trimmed

DG9898; REMOVED BRANCHES AND BUSHES FROM POLE

JS3194; CABLE ALREADY CLEARED OF BRANCHES

;rc1373;PC-N;Trees already cut cleared GO95

;al1824;PC-N;Trimmed branches around cable and pole

;al1824;PC-N;Trimmed limbs around drop and cable

BB6851; TRIMMED SMALL BRANCHES AWAY FROM CABLE, C99

JS3194; TREES HAVE ALREADY BEEN CUT BACK OFF CABLE.

;rc1373;PC-N;Trees already trimmed

JS3194; CUT BACK SMALL BRANCHES OFF CABLE, CABLE IS CLEARED

;al1824;PC-N;Trimmed branches around cable and pole

BB6851; ISSUE ALREADY TAKEN CARE OF, C99

;al1824; PC-N; Tree limbs trimmed around cable

DG9898; TREES CLEARED REMOVED

DG9898; CLEARED BRANCHES AND BUSHES FROM POLE

DG9898; BUSHES AND BRANCHES REMOVED

CV3817; REMOVE BRANCHES LINES FREE NOW

CV3817; REMOVE BRANTCHES

CV3817; BRANCHES REMOVED

CV3817; BRANCHES REMOVED

CV3817; BRANCHES REMOVED

CV3817; BRANCHES REMOVED

CV3817; BRANCHES REMOVED

CV3817; BRANCHES REMOVED

CV3817; BRANCHES REMOVED

CV3817; MADE TREE TRIMMING TICKET FOR LASAR TOO MANY TREES DIGIT 13464249

CV3817; REMOVE BRANCHES

DG9898; BRANCHES REMOVED ALL CLEAR NOW

DG9898; REMOVED BRANCHES AND BUSHES

DG9898; BRANCHES AND BUSHES REMOVED

DG9898; BRANCHES CLEARED AND REMOVED

;al1824; PC-N; Trimmed limbs around cable

DG9898; ALREADY CLEARED TREES CUT

DG9898; TREES CLEARED BRANCHES REMOVED ALSO

;al1824; PC-N; Trimmed branches around cable

BC1852; REMOVE TREE BRANCHES AROUND POLE

;al1824; PC-N; Trimmed tree limbs around cable and pole

BC1852; REMOVE TREE BRANCHES AR

;al1824; PC-N; Trimmed branches around cable

;al1824; PC-N; Trimmed branches around cable

BC1852; REMOVE TREE BRANCHES AROUND POKE

BC1852; REMOVE TREE BRANCHES AROUND POLE

DG9898; BRANCHES REMOVED TOK AROUND POLE

DG9898; JOB IS DONE NEW POLE PLACED NO TREES OR BUSHES AROUND POLE

DG9898; BRANCHES NOT TOUCHING ANYMORE PULLING CABLE DROP CLEARED

DG9898; BRANCHES REMOVED TOK AROUND POLE

DG9898; REMOVED BRANCHES FROM LOCATION TOK NOWPIC

BB6851; TRIMMED SMALL BRANCHES AWAY FROM CABLE, C99

BB6851; UNABLE TO LOCATE ISSUE AS SHOWN ON PICTURES, C99

SM1615; ALREADY DONE

SM1615; ALREADY DONE

SM1615; BRANCHES,REMOVED

SM1615; REM,SMALL,BRANCHES

SM1615; SMALL BRANCHES,REMOVED

SM1615; REMOVED,SMALL,BRANCHES

;sg5282;PC-N;Trimming repairs adv cable

SM1615; ALREADY DONE

rb2924; wires removed,work c

rn8732; removed multiple drops from multiple poles.

rt1486; Removed drops and foliage

cs1623; G.O. 95 tkt to remove dead aerial drops from poles in mountainous area c8h

cs1623; G.O. 95 tkt to remove dead dangling drop wires c8h

rx1696; remvd branchez on drops,remvd down drops,cleared hazard , not serv affctg

jb8576; cmp, verified hazard was removed and checked surrounding poles for new issues.,

rn8732; removed multiple drops.
rx1696; remvd mult down drops in area at multiple neighboring poles,not serv afftcg,advsd cuatomer addtnl line down property of cablemprovider

cr1893; all work complete

rx1696; remvd mult down dead drops,not serv afftcg,removed hazard

rt1486; removed drops cleared pole
jb8576; cmp, removed drops from the pole that had been cut or taken down. Pictures really helped.

;bs2864; PC-N; Cleared already but I did check other area

;jm9856;PC-N;raised low cable santefe rd le grand.

rehab bpc work

AD2932; LTD GO95 VEGETATION ON POLE CLRD

;ch2861; PC-N; Not enough info on ticket, to work.

;ch2861; PC-N; Not enough info on ticket, to work.

CH2861; ALL VEGETATION AND DEBRIS REMOVED

;ch2861; PC-N; Not enough info on ticket, to work.

;ch2861; PC-N; Not enough info on ticket, to work.

;ch2861; PC-N; Not enough info on ticket, to work.
nk5685; Hammered in u nails to secure drops to pole to clear climbing path, removed dead drops, tbhw

ml5474; Rmv old asw from pole, asst from NK5685

ml5474; Rmv asw from term, asst from NK5635
nk5685; Removed dead drops, cleaned up other drops, assisted ml5474, on an still having issues, thhw
nk5685; Removed dead drops, zipped tied working drop cleaned up aerial term, assisted ml5474, tbhw
nk5685; Removed dead drops, and cleaned up working drops, also assisted ml5474 on tickets. Advised gp8678 of late dispatch on ticket, the

jx5547; Trimmed tree around pole and drop and branches that had tension on drop. Good to go

;ml5474; PC-N; Reattach bsw down pole, reattach asw to prem off same pole.

ml5474; Fiber cable back up in place, made normal

ml5474; Rmv all unused asw, clean up term

ml5474; Reconnect both asw and bsw, place new transition box

ml5474; Picked up all asw and hardware on the ground

ml5474; No unused asw at terminal, only 1 in use bypass that cant be removed.
nk5685; Removed dead drop, cut dead ends of old cable that was replaced, RBs trouble finding poles address was wrong on bp, tbhw

rs556s; Brush is clear around cable,

ml5474; Remove all unused asw from term

ec2732; Removed unused low drop

ec2732; Removed low hanging unused drop

ml5474; Rmv asw from term, fix others, asst from NK5685
ml5474; Asst NK5685 on Non Pariel Dr until 12:15 on f-2 on busy roadway, remove all unused asw at term

ml5474; Rmv all unused asw from term

nk5685; Reterm drop into six pair can, removed dead section of drop, tbhw

ec2732; Removed low hanging unused drop

ec2732; Removed low hanging unused drops

kb5463; BPC work complete. Rebuild

em3528; Drive was 145min,cleared hazard
nk5685; Rerouted and nailed down drops and cable to pole, zip tied bypass wires to cable, removed dead drop, tbhw

ml5474; Remove unused asw from term
nk5685; Removed dead drops, fixed bent 25 pr pole mount term, also assisted ml5474 on Dunn ct, techs on an would not start, tbhw

ml5474; Rmv all unused asw from term, riding with NK5685 today, ok per GP8678

ml5474; All unused asws removed

ml5474; Removed unused asw at terminal

em3528; Cleared brush hazard

dg3424; No drop to be removed at location

ds6453; All wire work completed

ml5474; Remove all unused asw from term, riding with NK5685 ok per GP8678

nk5685; Removed dead drops, rerouted working drops, placed drive rings zip cleaned up other utility lines, tbhw

nk5685; Removed dead drops, rerouted other drops, cleaned up spice cases, tbhw

ml5474; All unused asws removed

jm687j; No low hanging drop found trees have been cleared. No vegetation issue anymore.

rb2924; Drop removed,work completed

dg3424; Removed drops at location

rs8367; Drv jmstwn longbarn. Vacation home up steep driveway. Pge chngd poles and that shortened and lowered drop thru trees to front of prem. Relocated drop higher and plod connx box and extended drop to nid.

;ml5474; PC-N; Tried to remove tree but tree to big, not on our strand, close to cable tv strand but not touching, being held up by another tree.
;ml5474; PC-N; Tree not on strand, being held up by another tree, cable tv strand is closest to tree, go back to 19390 Ferretti Rd, new Voip install not working

zo2856; No ATT network found, line to dish TV needed removal, all ASW up to standards

ec2732; Removed low hanging unused drops

ec2732; Removed unused low hanging drops

ec2732; Removed unused low hanging drop

ec2732; Removed low hanging unused drop

fr2146; Removed old dead drop that was hanging from pole all work complete
jm687j; Investigated vegetation issues. new poles have been placed, no more vegetation issues or low clearance issues in this area.

uv639w; New poles installed and trees cut
jm687j; Investigated vegetation ticket found new poles were put in, no more low cable issues or vegetation issues at this area.

et975m; Go95 Cleared branch from cable

rs556s; Cable is clear of brush

jx5547; Checked p call and drop for any branches lines or against Paul. There was no tension lines whatsoever line and line Pole were good
nk5685; Removed dead drops from term, and assisted ml5474 with ticket on pine mountain dr, tbhw
nk5685; Removed dead drops, multiple dead drops on mueller due to multiple pole transfers. tbhw
nk5685; Removed multiple dead drops, rerouted other drop away from climbing pathed pulled up lower drops

is3295; Lines free if abrasive branches

uv639w; Cut down branches resting on line

is3295; Cut branches abrasive against cable
nk5685; Removed dead drops, drove in u nails to secure working drops to pole to clear climbing path, screwed down 6 pair splice can, tbhw

ml5474; Rmv all dead asw from term, asst from NK5685
ad2932; Worked on removing old drop and assist tech with chronic trbl then assist prem tech with mdu fiber repair

ad2932; Assist with replacing drop for new internet service and wire work adv jc9747

em3528; Drive time 2 hrs,cleared hazard,put in mark it

dg3424; Drop is present but it is used for seasonal service.

dg3424; No drop at location that needs to be removed

ds6453; All wiring work completed. Removed wiring that was hanging at pole

rt1486; All services up ty ok

ds6453; All wiring work completed. Placed guard at wires coming down the pole.

dg3424; Drop tail removed at location
jg9626; Removed dead drops from pole and house cleared terminal with dead short drops just hanging

nk5685; Removed multiple dead drops, no services on drop, assisted ml5474, tbhw

ml5474; Rmv mid span asw and all other non used asw

nk5685; Removed multiple dead drops, cleaned up debris around pole, tbhw

ml5474; Removed unused asw and clean up term

nk5685; Removed dead drops, cleaned up debris, tbhw
nk5685; Removed dead drops, from prem, also removed down drop 12749 cresthaven, no services on drops, tbhw

nk5685; Removed multiple dead drop, no services on drop, tbhw

ml5474; Removed unused asw and clean up term

rt1486; Removed dead drop all services ok

rt1486; Removed dead drop all ok

rt1486; Removed drop ok thank u

ds6453; Raised low hanging drop over driveway. Removed all excess drops

rt1486; Removed drop all good

kw5925; Aerial drop removed.

rt1486; Removed drop all good

nk5685; Removed multiple dead drops along green valley, no services on drops, tbhw

ml5474; All unused asws removed

ml5474; All unused asw removed from terminal

ml5474; Rmv all unused asw from term

ml5474; Rmv asw at term. Asst from NK5685

ml5474; Rmv old asw from pole, asst from NK5685

rt1486; All services up ty ok

ad2932; Removed geo95 not service affected

rt1486; All services up ty ok

zo2856; Raised existing ASW, coaxle left going to house, all ATT plant removed and raised

dg3424; All wire work completed

zo2856; Climbed pole to remove ASW, left fiber ASW , fiber ASW needs to be raised
ad2932; Drive time 1 1 2 hr both ways arrived to location removed low hanging drops due to trees that fell reattached lines and placed new j hooks and pties.

ml5474; Rmv asw from term, asst from NK5635

ml5474; All unused asw removed from terminal

ml5474; Removed all unused drops

rt1486; All services up tu ok

zo2856; Removed abandoned Comcast ASW , all ATT lines attached

ad2932; Worked on geo95 removed non service affected issues

kw5925; Aerial drop removed.

dg3175; Work completed . Will ret

kw5925; Aerial drop removed.

ad2932; Drive up from Modesto Removed geo95 issues not service affected

ad2932; Removed geo95 hazard not service affecting dwn dw removed

em3528; Cleared hazard,made clear

jb1568; bpc complete. Prev tech provided hardware.

ml5474; All unused asw removed

ds6453; Wiring work completed. Removed loose wiring

fr2146; Removed old dead drop all work completed

ds6453; Drop removed. Wire work completed

dg3424; Drop removed at location

fr2146; Removed old dead drop that was hanging from pole all work complete

fr2146; Removed old dead hanging drop all work complete

fr2146; Drove to pinecrest, removed old dead hanging drop all work complete

ec2732; Removed low hanging unused drops

ec2732; Removed low hanging unused drops
nk5685; Cleared cable trouble and assisted tech with dro replacement. Customer back in service, tbhw

dg3424; Respliced cable 25 pair.

kw5925; Unable to located any down low drops

dg3424; put case on terminal , cable was exposed.

dg3424; Unable to finish splice,no overtime

em3528; Drop down,hazard, replaced j hook and clamps

bs2864; job completed

bs2864; removed drop

kw5925; All wire work complete.

mj1746; All work has been completed.

bs2864; job is completed already

mj1746; All work resolved on job

JA2756; REPLACED DROP ALL HAZARDS REMOVED

ch8326; Removed dead aerial drops

ch8326; Removed dead aerial drops

dg3424; All wire work completed

jb7519; Removed one low hanging drop & one drop hanging off pole

ch8326; All wire work completed

dg3424; no vegetation work required , terminal is reachable with bucket truck.

dg3424; no vegetation work needed, terminals are reachable

dg3424; All wire work complete

da1367; All work complete, no further work needed

dg3424; removed drops, not service affect

;dg3424; PC-N; Moved drop to higher pole per clearance

dg3424; removed old drop at address, not service affecting.

;ch2861; PC-N; No aerial plant in area of claimed address. No work needed

;ch2861; PC-Y; Removed abandoned service wire.

ch8326; Reattached hardware to new pole

cs1623; BPC tkt to work on aerial bad plant c8h

DG3424; PLACED SPLICE CASE ON 25 PAIR CABLE.

JA2756; REMOVED DROPS ALL HAZARDS CLEARED

rb2924; Drops were already removed

ds6453; All wiring work complete

dg3424; Respliced cable on Zarzamora st.

pole trnasfer & down uy re-tension loc la grange

DG3424; CLEARED PAIRS IN CABLE, HELPED LOCATE FREQUENCY ISSUE IN CABLE.

dg3424; All wire work completed

;am4268; PC-N; fixing g095 violations 2911 zarzamora in la grange

;am4268; PC-N; fixing g095 violations

dg3424; Splicing completed on 50 pair count.

;jh4935; PC-N; cable hardware problem

bs2864; No issues found verifed

mj1746; Verified issue resolved.

lh5743; Notified manager MT8231. Tree limbs are cleared

;ct4872; PC-N; 3819 Bonds flat rd La Grange Mark It ID 100468860

CH2861; REPRD LOW DROPS,

da1367; cut down and removed abandoned drop

cs1623; GO95 tkt for down low hanging drop wires wires raised c8h
jg9626; Removed riser hardware and fixed before placing back up on pole cable was clear renailed riser

dg3175; assisted situation with CIMI ticket

re sagged over head guy

mj1746; No issues found in area

tj4856; Repaired section at violet and gravel

;jh4935; PC-N; removed pole

em3528; Drop low.fixed,,,,,,,,,drop

;ct4872; PC-N; cleared go95 at 9618 Gaza Way

bs2864; No drops on ground all good

;ct4872; PC-N; Cleared GO95 9989 Alamo Dr La Grange

fr2146; Drop removed all down line removed old drops not in use

dg3424; removed aerial drops , not service affect

;jm9856; PC-N; replaced loose dwn guy

Set 3 anchors on 3 diff loc along Mountain House Rd

ml5474; Removed all unused asw from old tree,

ml5474; Remove old asw from term pole,

nk5685; Removed all dead drops, cleaned up term, and base of pole of drops, tbhw
ml5474; Remove 2 old drops from pole, left Coulterville approx 2pm to help Modesto tech (Daniel) on N Airport Rd in Columbia, ok per GP8678

rs8367; Intown 10 min,trbl clrd,complete.

nk5685; Removed dead drops, packed in could not drive to pole, RBs travel time, tbhw
EA2979; REMOVED DROP FROM POLE AND CLEANED UP AREA AROUND POLE, WORK COMPLETED
EA2979; REMOVED DROPS DOWN FROM SERVICE POLES, CLEARING EXCESS WIRING, CLEARED ISSUE

nk5685; Removed all dead drops from term, also assisted tech on peppermint, placed approximately 7 spans of 6pair messenger bypass for chronic ip circuit, tbhw

nk5685; Removed dead drop, tried to pull up 25 pair cable, but too heavy will advise construction that cable needs to wrecked out, new cable has been spliced in, tbhw

nk5685; had to wait for windshield replacement to bedone at yard, did ple courses while waiting, prior to arriving to bpc to remove dead drops in coulterville, no serviced on line, tbhw
EA2979; FOUND LOCATION AND POLE HAS BEEN REPLACED BY PGE AND ALL HARDWARE HAS BEEN REPLACED, WORK COMPLETE

nk5685; Secured buried drop to new pole, removed dead drops from term, tbhw

ml5474; Reattached asw to pole

rs8367; Drv mdst-cltrvl rplcd case and attchd term to new pole,complete.
nk5685; Nailed down loose u guard, and secured loose drops to pole, rbs assisted ml5474 on pen on blanco, befor arriving to job site, travel time, tbhw
nk5685; Nailed in u guards, term loose drops, assisted tech on n airport way with pr recovery, advised gp8678 of Ot, tbhw

dg3424; Placed riser over drop on pole

;nk5685; PC-N; tree branches were cleared for fiber placement, assisted ml5474 with en tkt in coulterville ok per jm5912, tbhw

dg3175; sist prem tech with phi bee drop

NS1598; GEO95 CONDITION CLEARED UP

NS1598; GEO95 ISSUES RESO

dg3424; All wire work complete

bs2864; Checked and verified no issues
JB8576; CMP, I VERIFIED THAT TREES WERE NOT INTERFERING WITH CABLE BASED ON PHOTOS IN THE PACKAGE. NO MORE WORK NEEDED.
JB8576; , CMP, TICKET WAS TO REMOVE BRANCH PRESSING DOWN ON CABLE. I REMOVED MANY SMALLER BRANCHES TO REMOVE WEIGHT FROM THE LARGER BRANCH. I ALSO CUT A BRANCH ON ANOTHER TREE NEXT TO IT THAT WAS PUSHING UP. THERE IS SOME PRESSURE ON THE CABLE BUT HAS REMOVED A LOT OF TENSION. LARGE BRANCH WAS TO LARGE FOR ME TO CUT.

mj1746; Spoke with property owner upon arrival. Inspected and found no issues to resolve.
mj1746; Spoke with property owner and confirmed no issues to resolve with low or downed lines. Suspect issue resolved previously

jb7519; Drop down , no drop found anywhere address or in area , job complete .

RS8367; DRV MDST-JMSTWN,TRBL CLRD ONLINE. DELAY ON DISPATCH DUE TO NETWORK ISSUES TO RESET PASSWORDS,CY922P ADVSD.

kw5925; All att work complete.

RN8732; CLEARED TREE LIMB CAUSING STRESS ON CABLE.

bs2864; Removed drop and now all good

sv8697; third brush off cable.
;nk5685; PC-N; went out and prefielded cable run, and input dig tkt for contractors to remove tree branches off cable, tbhw

NS1598; SECTION THROW, NEW TERMINAL, 5 DROPS, SECOND SITE TREE TRIM

NS1598; GOE95 VEGETATION ISSUES RESOLVED

mj1746; Resolved issue at pole.

RN8732; CLEAR VEGETATION FROM CABLE AND POLE.

pr2872; contractor dig request for tree clearing off cable,dig 15394112

bs2864; Job completed already
jb8576; removed two large branches that had been rubbing against the cable. Had to meet up with another tech to borrow pole saw. Then returned the saw to the moccasin central office. Tree branches had been rubbing for a while.

kw5925; All att wire removal complete.

kw5925; All wire removal complete.

kw5925; Only visible remaining line down is owned by cable company.

kw5925; All wire removal complete.

;sl9636; PC-N; rmvd tree branches from facilities

kw5925; trimmed mult trees to clr from cable.
;rx1696; PC-Y; Trbl to heavy foliage section, trimmed affected area, no haz/no trbl to cable; TN: 2096318327

;nk5685; PC-N; inspected cable run and input dig for contractors to remove trees from multiple spans, tbhw
;nk5685; PC-N; inspected go95 violation, input tkt for tree trimming to get trees off of the cable soans, tbhw
HC3283; RPRD F2 CABLE 0704X162, ASSISTED TECH WITH POTS REPAIR 20073 FOREST VISTA DR, TWAIN HART, ASSISTED TECH WITH UVERSE INSTALL 22878 VIRGINIA, TWAIN HART, OKD PER SUP MT8231

ds6453; Cut drops removed from pole, lines cleared up

jb8576; cmp, checked at address listed but the pic did not match, found trouble on the other side of address on lulu mine. I removed small branches so that the cable could slide clear of the branch it was resting on. Cable is off of branch and moving freely.
jb8576; cmp, removed large branches from around the cable. Cable is free and clear of branches.

cr1893; found location and trimmed tree had to get bucket on slope

dg3424; All wire work completed
cr1893; long stretch with thick branches needed road work signs out trimmed back numerous treeG

;rx1696; PC-Y; Tok ,non serv affctg,trimmed branches,cleared haz; TN: 2096318327

tj4856; job from Cody

BC8519; TRIMMED AROUND TERMINALS. ADVISED SUB TO TRIM HIS TREES ON HIS PROPERTY NOT IN EASEMENT.

ds6453; Removed drops that were cut and hanging down at pole

;sl9636; PC-N; Input dig# 014490267 for tree trimming around cables

BC8519; TRIMMED TREE. ADVISED PGE OF LEANING POLE.
;rx1696; PC-Y; Light tree trimming, any additional requests for big branches need to be addressed by professional tree cutters,; TN: 2096318327
;cs1623; PC-N; Rehab tkt to clear vegetation surrounding phone cable facilities/vegetation had already been cleared/c8h

cs1623; rehab tkt to clear out vegetation away from cable facilities c8h

ce2563; tree has a.ready been trimmed

ce2563; removed vegetation around terminal

rx1696; cleared brush overgrown branches on cable , hazard cleared , not serv affctg
rn8732; Adjusted guard to cover drops. Gave mug to neighbor for waiting so long for us to fix that eye sore.

ce2563; removed brush from around term

bs2864; Job completed now thanks

rn8732; All work completed. Verified all looks good.

bs2864; Removed old drop from pole

bs2864; Drop has been removed now

sd9656; trimmings up and cleaned awa

dg3424; All wire work completed.

bs2864; Job completed now thanks

dg3424; All wire work completes

bs2864; Job completed now thanks

mj1746; Inspected area and verified issue resolved

da1367; trimmed & or removed branches touching cable

mj1746; Inspected area and cleared issue

bs2864; Job completed and good to go

cs1623; Drop wire already removed c8h

DG9898; JOB IS COMPLETE NOW

BC8519; TRIMMED TREES ON LINE.

DG9898; COMPLETE BRANCHES REMVED

ch8326; Dead drop removed , all wire work completed

rn8732; accidentally didnt dispatch after lunch. Cleared some foliage.

rn8732; cleared some foliage but put in dig 20369764 for the rest.

rn8732; med what I could and put in dig to trim the rest involving closing a lane. Dig 20369764.

bs2864; Job completed now thanks

mj1746; Inspected area and verified issue resolved.

rx1696; removed down drops,trimmed accessible branches, some contact with trees out of reach over property fence lines,not serv affc

;ml5474; PC-N; Put in dig for tree trimming

fr2146; opened dig ticket for trees to be trimmed

BC8519; TRIMMED TREE AND REHABD 1 TERMINAL.

mj1746; Inspected work area and no issue detected

bs2864; Job completed already

hc3283; cable rehab ticket cleared, inspected job site, verified all tree trimming completed, visually verified all tree branches cleared from cable, completed PLE courses for this month.
hc3283; verified tree trimming was completed, all tree branches removed from cable and pole, visually inspected area for compl

rt1486; Removed foliage

jb7519; Removed 1 def 2 pr drop & attachments , job complete

DG9898; BRANCHES REMOVED

bs2864; Job completed now thanks

RS8367; TOWN 15 MIN,BRANCHES CLRD ON CABLE PATH,COMPLETE.

RS8367; INTOWN,VEGETATION CLRD FROM CABLE PATH.

tj4856; cut off branch leaning on cable

hc3283; cleared bad plant condition, at 18394 Hwy 108, safety meeting in the morning, 2nd meeting with 2nd line, sk25

da1367; tree trimming complete.

jb8576; cmp, tree branches have been cleared.

;ml5474; PC-N; Input dig for tree removal on all spans

jb7519; removed 2 pr drop off of pole in front of customer Prem , job complete .

;ch8326; PC-N; Cleared foliage from cable; TN: 9999999

;ch8326; PC-N; Removed foliage near cable; TN: 9999999

dg3424; cleared go 95 , respliced 25 pair cable.

da1367; trees already trimmed by power company.

dg3424; go95 corrected, respliced 25 pair cable

bs2864; Job completed already

tj4856; no work needed cleared

jb8576; cmp, vegetation is cleared from cable.

jb8576; cmp, verified vegetation was cleared away.

cs1623; tree trimming around pole completed c8h

cs1623; tree trimming and vegetation removal com0leted c8h

jb8576; cmp, created a dig ticket to have the trees trimmed.

rx1696; trimmed back branches,cleared debris hazard,not serv affctg

cf1419; removed foliage impeding cable

bs2864; Job completed thanks

cf1419; trimmed trees around cable

;ml5474; PC-N; Put in dig for Nate???s tree to remove all trees off strand
;gb3598; PC-N; Need 2 trees cut back away from cable at 18189 Seco. Dig tkt# 20367446 to lazar.k; TN: 0000000000
;nk5685; PC-N; cut away tree branches from cable in kultiple spans, removed tree branches, will return to remove remain branches, tbhw

bs2864; Reattached drop and now good to go
;nk5685; PC-N; pictured cable span has been cleared of tree branches, other spans need to be writen up and cleared, tbhw

NS1598; GEO95 ISSUE RESOLVED

hc3283; inspectioned cable, verified all branches were trimmed, sk25
;ml5474; PC-N; Asst NK5685 on f-2 in Groveland till 1:00pm, asst Wade on EN ticket to French Flat till 3:15pm. Only asw so no trimming needed

fr2146; drove to Jamestown removed numerous branches that had grown over drops will need to return with trailer to remove branches that were removed from att cable

mj1746; Inspected area and verified issue resolved

;bc8519; PC-N; Removed branches from cable. Assisted job with install.

rx1696; removed several small branches relieved line of stress, any additional contact with tree would require professional tree cutters, tree advsd:located on private property

cs1623; GO 95 tkt to remove dead aerial drops c8h

;nk5685; PC-N; removed multiple tree branches from cable spans, behind bbox,

lh5743; 85 minute drive to rural plant job in the hills to address 10678 Wigwam Rd, leaning pole was reported late last year 2022. All poles are joint utility with the power company, suspect pole has been replaced by local phone company, No CBR or other details on G95 ticket.

rt1486; cleaned foliage

rx1696; trimmed branches,relieved weight upon cable, not serv affctg

cs1623; GO95 tkt for removal of aerial drops c8h

mj1746; Verified address and issue has been resolved already.
;ml5474; PC-N; Never made it to the prem, in Groveland working on multiple cable failures with multiple trees down on cable

mj1746; Verified area and that issue is resolved.
;sl9636; PC-Y; Walked lines, input dig# 14490267 to get trees removed from cables in multiple spans

mj1746; Inspected area and issue appears to have been already resolved.

ch8326; Removed aerial drops, non service affecting

BC8519; TRIMMED VEGETATION.

ch8326; Removed dead drops not service affecting

tj4856; wrecked out drops

tj4856; d out abandoned drops

rt1486; removed foliage

mj1746; Verified address and that low drop issue has already been resolved

rn8732; moved several branches relieving tension on cable.

GC408J; TREE BRANCHES REMOVED FROM LEANING ON STRAND.

jx5547; Everything was clear and good to go. Walked the line and seen everything was ok

rs8367; Intown 10 min,all trbl cleared,complete.

kb5463; Remove downed old broken serv drop
jb1568; No 21803 on Russian River. Cinched up low hanging cable at 21871 and 21857 Russian River and remove drop at 21843 Russian River Dr.

mm5268; Remove drops locations

ec2732; Removed unused low hanging drop

ec2732; Removed low unused drop

ec2732; Replaced riser cover, assist with 400ft drop in Jamestown

mm5268; Check riser guard for replacement
gb3598; trees already removed after heavy storms. No poles leaning & no cable down. Talked with cx at 22466 Church to verify..

mm5268; Removed def drops. In multiple areas

jm687j; Cut trees around Pole.

mm5268; Reattached drops at pole

dp7958; Trimmmed trees back as needed.

jb8576; Cmp, all clear no low drops.

dg3424; Completed drop removal

ec2732; Removed unused low hanging drop

kb5463; Strapped down riser guard

jb1568; Rprs complete. Need to make bpc for another close by.

ec2732; Removed unused low hanging drop

ec2732; Check all poles in area and no riser cable found uncovered

ec2732; Wrong size riser on truck will return and place correct size

kb5463; Inspect and complete work.

ec2732; Wrong size riser on truck will return with correct size

EW042G; DROP REMOVED FROM PROPERTY AND STREET LOCATIONS. ALL CLEAR

cf1419; Place riser guard on pole all done

em3528; Found loose drop,not hazardous,trimmed it shorter

dg3424; Riser placed on pole
ec2732; This address completed already check area and removed some unused low hanging drops

ec2732; Place new riser and cover cable

dg3424; Removed partial drop

bs2864; Job now completed thanks

TB3178; PLACED RISER U GUARD OVER BSW ON POLE IN WORK AREA

ch8326; Removed dead aerial plant

bs2864; Good to go now thanks
EW042G; ATT NETWORK IS GOOD. CABLE COMPANY LINES ARE ON THE BARB WIRE. NOT OUR LINES. CLOSING OUT TICKET.

ce2563; Drop going into conduit is cable company

rt1486; All complete thank u

ce2563; Down drop is cable company, did not remove

dg3424; No hardware needed at location

ch8326; BSW placed too far from pole to add hardware

ch8326; Unable to attach hardware due t location of facilities
ag636b; Work located at street poles. Cleared tree limbs on and around cable. Bucket assist with the higher portion.

ch8326; Unable to place hardware due to the locations of facilities

dg3424; Removed one drop, one drop still there that may be in service

dg3424; New pole, conduit coming up on cable , very rural

dg3424; No hardware needed to replace

ag636b; Work performed at street poles. Cleared tree limbs surrounding cable. Pics taken.

dg3424; Placed riser cover over drops

ch8326; Unable to attach hardware due to conduit locations

kw5925; All att work complete.

ch8326; Hardware placed at pole

ch8326; Placed riser guard at trouble address
jb8576; cmp, repaired second drop and had to zip tie the black optical drop to the existing conduit. No more space.
EW042G; CUT HANGING DROP WRAPPED AROUND POLE ON THE CORNER. PICTURES DIDNT MATCH THE POLE LOCATION. NEW POLE MAY HAVE BEEN ADDED AND ONE PICTURED REMOVED. WAS STILL A DROP HANGING, REMOVED.

kw5925; All att work complete.

mj1746; Task has been completed.

kb5463; Remove broken service drop. Condition clear

kw5925; Att drop removal complete.

ec2732; Removed unused low hanging drops

kw5925; Aerial drop removed.

rt1486; All complete ty ok ok

bs2864; Job is completed now

bs2864; Job is completed now

ce2563; Pole on private land, no access to pole, trailer parked next to pole

ce2563; Subs iw coming out of conduit. Sub told me to not touch his wire

jb8576; Removed old drops that were hanging down. Most of it had been removed already

jb8576; Cmp, verified drops were no longer hanging down. Pole is all clear.

tj4856; Gaurd loose and rebooted

jb8576; Cmp, hanging wire was already removed

;al1824; PC-N; Trimmed branches around cable strand

em3528; Wrong address,drove around looking for hazard
dg3424; Riser placed, could not put top bolts on riser because vehicle is parked in front of pole and cant reach top , need to use bucket truck.

sd9656; Cleared defects on job

cf1419; Removed 2 dead drops street really narrowlook at the street name

bs2864; Job is now completed

rn8732; Cleaned up drops going up the pole.

mj1746; Task has been completed

dg3424; Replaced riser cover over drops on pole.

rn8732; reattached riser to pole with both drops.

rn8732; All wire work done. Reattached conduit to pole. Attached drops to pole as well.

em3528; Removed hazard,test ok

em3528; Removed hazard,test good

em3528; Cleared hazard.

em3528; Removed drop, made safe, drivetime

rn8732; Removed all cut drops and fixed term. All wire work done.

dg3424; Drop raised at location

ch8326; Hardware placed assigned address

gb3598; Replace riser, job task completed

dg3424; Placed riser on pole

em3528; Cleared hazard,drive time

gb3598; Place new slick 25pr term.

rn8732; Took down 4 drops. Fixed term

dg3424; Removed drop, placed riser

rn8732; Pictures dont match location. Did remove a drop hanging in the trees all coiled up.

gs3625; Removed multiple dead drops from pole and out of tree no service

rb2924; Removed dead drops from pole,work completed

sd9656; Fixed defect in the pole

rb2924; Repaired loose drops and u guard, work completed

sd9656; Placed slick and fixed defects

rs8367; Drv to site,clrd all trbld hardware. Complete.

rn8732; Fixed all hardware, reattached drops to pole.

mj1746; Task has been completed.

rn8732; All work done. Reattached drops to pole.

ds6453; All wire work complete. Placed riser over cable going up the pole.

bs2864; Job completed now thanks

ds6453; Job completed. Riser placed at pole over cable

dg3424; Placed riser cover over drops
rs8367; Drv jmstwn-sra, found 7 drops,guards off,replaced guards and tacked drops all the way to term,complete.

rs8367; 2 drops found,both covered to term,complete

mj1746; Task has been completed.
rs8367; Intown 5 min,found low drop pole to pole-rehung self support drop,drop tied down grnd to term,complete.

jb8576; Cmp, all clear. There is a coax line hanging down.

jb8576; Cmp, verified it was all clear. No hanging drops.
jb8576; Cmp, verified all wire was covered by guard, there is one not covered but that is comcast not att.

gb3598; Rolled up to Sonora and added hardware to riser. Task completed

em3528; No trouble found,possible wrong address,or pole was replaced
gb3598; Replace damaged lunchbox term with new slick and cut in pairs and drops. Task completed

kw5925; All att work complete.
jm687j; Could not locate issue with address given. Shows ticket is from 2022 for low cable, no low cable found.

dg3424; All wire work completed

em3528; Placed guard on pole

dg3424; Riser placed at location

em3528; Placed u guard over drops

da1367; Pole has been replaced, no hardware needed

mj1746; Task has been completed

bs2864; Job is now completed

ad2932; Raised dw and put in for bpc for term replacement

dg3424; Replaced case at terminal

ad2932; Drive from Stockton to Sonora go to yard to get riser cover arrived to location placed riser protection and cleaned up area placed bpc for term replacement

ds6453; Wiring work completed. Removed drop at pole.

gb3598; No drop found low that I could find. Task completed

da1367; No hardware to be removed

da1367; O hardware to remove

ds6453; Found low hanging unused drop and removed. All wiring work complete

dg3424; All wire work completed

kw5925; All att work complete.

tj4856; Drop pull up to clear distance to road

tj4856; Wrecked out abandoned drop
gs3625; Removed multiple drops from midspan over roadway were wrapped around pole no service

kw5925; All Att work complete.

IS3295; REMOVED DOWN DROP AREA CLEAR

ch8326; Unable to place hardware due to cable locations

tj4856; Abandoned drop wrecked out

tj4856; Wrecked out a banded drops two drops

IS3295; REMOVED DOWNED DROP AND CLEARED

rb2924; secured drops to pole,submitted mark its for splices,all work complete

dg3424; Their is a riser on cable going up pole at this address

ch8326; Unable to place hardware, tree trimming blocking path

rs8367; Drv mdst-sra,at location found leaning pole,advsd local construction boss,complete.
rs8367; Intown,clrd immediate issues with pole hardware,pole needs additional down guy and advsd construction sup on email.

dg3424; Removed one drop ,not in service

rs8367; Intown 5 min,placed guard to protect bur drops,recent pole replacement by pge.

dg3424; Hardware replaced on pole

ch8326; Raised aerial drops,

kw5925; All att work complete.

ch8326; Road inaccessible due to tree trimming

dg3424; No riser needed at location

dg3424; No drop to be removed

ch8326; Unable to access road due to tree service

rt1486; All complete thank u

NS1598; ALL BPC AT THIS LOCATION TAKEN CARE OF

em3528; Did not see trouble at that address, possible wrong address

ch8326; Rep,aced hardware on pole

hc3283; Repair def hardware, repaired and replaced down riser covers on pole

dg3424; No riser needed at location

hc3283; Replaced hardware on pole, riser wire cover damaged, replaced metal wire cover

;nk5685; PC-N; inspected trees on line, incorrect address, please verify with gps location numbers, will input tkt for contractor to trim branches, will require lane closure,ntbhw

dg3424; No hardware needed at location

ch8326; Unable to attach hardware due to location of cable

ch8326; Unable to attach hardware due to location of facilities

ch8326; Placed hardware on pole

ch8326; Unable to place hardware due to location of dwid

cf1419; Place riser guard on pole got couple more

tj4856; Abandoned drop at pole, wrecked out into terminal

dg3424; Nowhere safe to park without blocking traffic on busy road.

mm5268; Raised 3 drops low in road 2 locations

em3528; Drive time,placed u guard over drops,hazard removed

dg3424; All wire work complete

mj1746; Task has been completed.

mj1746; Task has been completed

bs2864; Job is now completed

rs8367; Intown 5 min,got access to private road,trbl clrd,complete.

rs8367; Intown 5 min,all trbl cleared. Had to wait for access to private road.
gb3598; Existing riser on ground put riser in place and ground strapped top as thats all I had.
Task completed

mm5268; Replaced slic and cleaned up drops

ch8326; Removed dead aerial drop

dg3424; Riser in place, not service affecting

dg3424; Placed riser , not service affecting

mm5268; Replace gardnon pole

tj4856; Wrecked out multiple abandoned drops on two serving poles

gb3598; Remove old Ariel drop after locating Prem way back in the woods. Task completed

dg3424; Raised drop at address, no other hazards in area.

dg3424; Removed old drop, not service affecting

bs2864; Good to go now thanks

jb7519; Moved Riser guard down and replaced c bracket on guard , job complete

bs2864; Job is now completed

bs2864; Job is now completed

em3528; Drove to address on ticket, no hazard,drive time 1 hr

dg3424; Drop removed at location

gs3625; Removed dead drop from midspan attachment and out of terminal no service

jg9626; Removed old low hanging drops that have no service

is3295; Abrasive branches removed

dg3424; Drop removed from pole

bs2864; Job is now completed

ch8326; Not possible to place riser guard, drop conduit is 3 ft from pole

ch8326; Added riser guard, all work complete

bs2864; Job is now completed

bs2864; Job is now completed

ch8326; BSW conduit stubbed up too far from pole to place riser guard

bs2864; Job is now completed

jb8576; Cmp, placed new guard for drop and reattached at the top by the terminal. Tied down old conduit as well.

rs8367; Prev jmstwn-sra,clrd hardware issue,complete.

ch8326; DWID too far from pole to place hardware

bs2864; Job is now completed

ch8326; Replaced riser guard,

bs2864; Job is now completed

bs2864; Job completed now thank

rb2924; Drops removed, work completed

ch8326; Moved riser guard to enclose cable

ch8326; Did too far from pole to place riser guard

bs2864; Good to go now thank you

mj1746; Task has been completed

mj1746; Task has been completed
mj1746; Address on ticket appears to be incorrect. Nothing found matching picture at address give.

ce2563; Respliced cable, terminated drops, placed cad6

mj1746; Task has been completed

rt1486; Job complete thank u k

mj1746; Task has been completed. Pole transfer pending.

mj1746; Task has been completed

ce2563; Placed drop guard over bdw

cf1419; Hardware was already done

ds6453; All wiring work complete. Removed drops

dg3424; Riser was not attached on pole , was able to salvage riser and reattach, no hazards.

dg3424; Raised two drops up and tightened j hook

dg3424; Already riser at location

ch8326; Placed riser guard over BSW dwid

rn8732; removed dead drops and cleared terminal.

rn8732; removed what I could. Difficult location to reach when abundant absticles in the way.

rn8732; leared downed drops and cleaned terminal.

rn8732; reattached drop to the pole and removed an old drop.

rn8732; cleared all dead and downed drops and cleaned up terminal on my hooks. Couldnt use the bucket.
cf1419; Had trouble with atlas couldnt get on to server .. hardware put on Att equipment other is cable

rn8732; attached lines to pole.

tj4856; Restablished hardware and checked security

mj1746; Task has been completed

ch8326; Placed hardware on pole

dg3424; Drop removed at location

tj4856; Fixed loos hardware remained abonded drop

ch8326; No leaning pole 13290 terrace

bs2864; Job is now completed

rn8732; took down several downed drops and cleaned up terminal.

rn8732; cleaned up some low and downed drops.

rn8732; remove several down drops and cleaned terminal full of acorns.

rn8732; Cleared area of broken drops.

mj1746; Task has been completed

da1367; Removed 3 drops from pole

tj4856; Raised low drop to standard clearance

dg3424; Removed unused drop wire

jb8576; Cmp, errors went away. Not sure why. Kept testing

dg3424; New pole placed at address no hardware needed

MG5372; ASW WORK. GOT CALLED TO A FIBER OUTAGE IN ARNOLD AT NOON

dg3424; Drop removed at location

da1367; All work is complete, no further work reqd.

rt1486; Placed pole guard all services up

rb2924; Drop removed, work completed

EW042G; FALLEN AND CUT DROPS REMOVED. AREA IS SAFE. CLEAR OF ANY TRIP HAZARDS.

kw5925; Aerial drop removed.

bs2864; Job is now completed

tj4856; Rearacthed guard wrecked out abandoned drop

tj4856; Repaired guard, wrecked our abandoned drops
;nk5685; PC-N; trimmed multiple tree branches of cable span, pick up and dumped branches at you, tbhw

zo2856; Work previously completed
;nk5685; PC-N; removed multiple tree branches from cable span, and removed branches from cudtomers property, lines are clear, tbhw

fr2146; Drove to site removed old dead drops

rs8367; Trbl on service drop has been cleared,complete.

rs8367; Onsight, cleared trbl,complete
rs8367; Intown 5 min. No place to turn around,pge blocking path. Parked far away and walk to remove line.

;nk5685; PC-N; located trbl address, address on tkt was wrong, search by gps coordinates, created dig tkt to remove trees from midspan, assisted ml5474 on cable writeup, tbhw

da1367; Drop wire has been removed

lh5743; Notified manager MT8231, aerial copper tree is cleared in residential aerea in hills

rs8367; Intown 5 min clrd our drop,cable drop still low,complete.

ad2932; Worked on wire work and placement of riser guard

EW042G; DROPS CLEARED FROM POLE AND GROUND. ALL CLEAR

EW042G; DROP WIRES CLEARED.

rt1486; All services ok thank u

sd9656; Splice completed and vcosed with

RB2924; ALL WORK COM

NS1598; TRIMMED TREE BRANCHES AND MOUNTED SIDNEY APP CASE TO POLE
cr1893; tree still has green leaves and poses no immediate danger property owner in process of removing
cr1893; tree is not near main cable and poses no risk to main cable or strand has active power attachment and cable tv we only have single drop attachment

;ja2756; PC-Y; Trimmed tree/all work complete

rn8732; All drops removed and cleared.

cf1419; Removed dead drop from pole

cr1893; All work complete..

cr1893; All work complete

da1367; Removed drops coming down oole

rt1486; Repaired issue all service up

rt1486; Removed dead wire all services up

rb2924; Drop removed, work completed

ec2732; Reconnect riser to pole

ec2732; Replaced missing riser guard

ad2932; Arrived to prem removed dwn dw due to weather geo95 cleared

tj4856; Repaired guide with n

cf1419; Removed dead drop from pole

cf1419; Remove dead airel drops

ad2932; Drive from Modesto to mi-Wak arrived to prem located geo95 Removed dwn dw not service affected

;rb2924; PC-N; All work complete

rb2924; Drop removed, work completed

rs8367; Drv to longbrn,rmvd drop,complete.
BC8519; REMOVED BRUSH AND LIMBS CLOSE TO CABLE AND STRAND. RESPLICED 25 PAIR TERMINAL.

rt1486; All work complete thank u

cf1419; Removed dead drop from pole
ad2932; Worked on geo95 removal of dw due to weather from previous storm cleared not service affected

cf1419; Remove dead airel drop

ch8326; Removed aerial drop line

sd9656; emoved tree branches causing issues with cable

ad2932; Worked on wire work and placed temp service and assist on cable work on hwy 120

JB6185; LOCATED AND REMVD 2 SEC OF AERIAL DROP HANGING LOW,WORK COMPLETED

dg3424; Drop removed at location

bs2864; Job is now completed

bs2864; Job is now completed

rt1486; All services up ty ok

zo2856; Climbed pole to remove abandoned ASW

em3528; Removed drop hazard,put in mark it

em3528; Removed loose drops,cleared hazard

dg3424; No drop to be removed at said address

jg9626; Reattached drops back to standard hight clearing proper hight

cf1419; Removed dead drop on pole

cf1419; Removed dead airel drop wire

cf1419; Removed dead airel drops

ds6453; All wire work complete. Removed cut hanging drop

rt1486; Removed loose drop cleaned up off pole
ds6453; Poles replaced by power company. Hanging drops have been removed. All wire work complete

rs8367; Drv Intown,clrd trbl at prem,complete.

rb2924; Drop removed, work completed

kw5925; Aerial drop removed.

dg3424; No drop needed to remove

zo2856; Removed abandoned ASW

dg3175; Advised sup having to go back on job from Friday in Sonora on alder ln

rx1696; Remvd drop,not serv affctg

rs8367; All trouble cleared. Parked truck and walked to site. Complete.

rs8367; Intown 5 min. Clrd hardware trbl. Complete.

hc3283; Removed downed drop, cleared hazardous condition

jb7519; Removed drop from location , job complete

kw5925; Aerial drop removed.

rn8732; Fixed all drops and near by terminal

rs8367; Intown 15 min,removed defective drop from pole,complete.

ad2932; Removed down dw not service affected and worked on wire work

kw5925; Aerial drop removed. Travel back to Modesto.

cf1419; Removed 2 dead drops
rs8367; Low drop was tv cable. Hanging pole mt term. Placed new bk plate nd routed all drop. Complete.
cr1893; All work complete. Removed drop. Listed as sequoia ln, incorrect, was sequoia dr. Both are streets.

ch8326; Removed dead drop wire

jg9626; Removed old dead drops cleaned up terminal
dp7958; Tree Trimming was taken care of. Droppings left at the house. Customer said he would use them as firewood.

jg9626; Removed dead drop that were hanging from the pole none had service

ds6453; All wire work completed. Wires that were hanging are now attached at new pole

rt1486; All services up thank u

WM9343; REMOVE OLD DROPS

cf1419; Replace riser guards on poles

cf1419; Removed dead airel drop

dg3424; Placed riser at location

da1367; All wire work completed

dg3424; New pole was placed, drop was removed

ad2932; Worked on geo95 removal of dw not service affected
DS6453; POLES LOOKED LIKE THEYVE ALREADY BEEN REPLACED, CHECKED SURROUNDING ND ALL THE POLES LOOK NEW

dg3175; removed tree limbs away from cable in area of address given

dg3175; removed tree top in area

ch8326; Removed dead drop wire

rs8367; Intown 5 min,drop removed and pulled from under tree trunks,complete.

fr2146; Removed old dead drops verified no other ones down in area

cf1419; Removed dead drop from pole

bs2864; Job is now completed

ad2932; Worked on geo95 issues and put in MarkIt for term replacement

ds6453; All wire work completed. Removed hanging drop from pole

rs8367; Intown 5 min,clrd our trbl on hardware,left issues is on pge ground

ds6453; Removed cut drops hanging at pole and midspan. All wire work complete
rs8367; Drv mdst-mwkvlg,at site found loose cover and missing hardware,rplcd,other wires hanging down were tv cable drop.

RB2924; ALL ISSUES RES
rx1696; cleared branches on cable,removed debris, any work beyond would require professional tree trimmers for entire tree removal

ch8326; Removed aerial drop wire

rb2924; Drop removed,work completed

WM9343; TRIMMED TRESS

rx1696; trimmed branches surrounding laying upon cable,relieved stress,cleared debris

cf1419; Removed dead airel drop

hc3283; Removed hanging drop from pole, cleared safety harzard

hc3283; Removed drop, cleared safety harzard

cs1623; Tkt to remove dead low hanging wires c8h

rb2924; Trimmed tree,removed drops,work completed

GC408J; ESSENTIAL WORK COMPLETED.

GC408J; REMOVED DOWNED DROP FROM SERVING TERMINAL

GC408J; DUPLICATE TICKET, JOB PREVIOUSLY COMPLETED AND ALL WORK COMPLETE

rs8367; Intown 10 min,clrd hardware issue at pole. Complete.

dg3424; No hardware needed at location

ch8326; Removed down aerial drop

ch8326; Removed aerial drops

ch8326; Removed non hazardous aerial drop

ch8326; Removed aerial drop line

jg9626; Raised drop back to standard hight 2 low hanging low drops

cf1419; Removed dead airel drop

rx1696; cleared vegetation branches from cable,removed dead down drops

tj4856; Wrecked our abandoned drop

tj4856; Wrecked out abandoned drops two poles

GC408J; NO DOWNED ATT PROPERTY LOCATED. JOB CLOSED OUT

GC408J; ALL LINES REMOVED AND CLEARED

rs8367; 3 min Drv,clrd line trbl,complete

;mt3262; PC-N; Remove GO95 hazards from pole

rb2924; Drop removed, work completed

cr1893; All work complete. Removed drop.

tj4856; Wrecked out abandoned drops

ch8326; Removed aerial drop line

tj4856; Wrecked out abandoned drops

ch8326; Removed hazardous drop

ch8326; Removed aerial drop wire

ch8326; Removed aerial drop wire

hc3283; Cleared GO95, removed low drop, cleared area, sk25

zo2856; Duplicate ticket previously in the AM

ch8326; Replaced hardware on pole

ds6453; Removed drop lines hanging at pole. All wiring work completed

rs8367; drv mdst-twnhrt,clrd trbl over 2 spans,complete
rx1696; removed multiple dead drops hanging from neighboring poles,trimmed back branch growth from cable,cleared debr

rb2924; Drop removed, work completed

dg3424; Cloth drop removed from pole to house

cr1893; All work complete. Removed drops.

cf1419; Removed airel dead drop

cf1419; Remove dead airel drop

cf1419; Removed dead airel drop had to close out down hill iPad wasnt working

cf1419; Removed dead airel drops

da1367; All wire work compleye

rs8367; Intown 5 min,rmvd drop,complete.

bs2864; Job is now completed

ch8326; Removed aerial drop wire

rb2924; Drop removed, work completed

kw5925; Aerial drop removed.
rx1696; Remvd weight bearing branches that could be safely removed,any ,addtnl work require professional tree trimm
jb7519; Raised drop up per request , also took down hanging strand & removed 6 pr drop that was hanging off pole , job complete .

rs8367; Intown, removed drop,complete.

JB6185; LOCATED PREM AND FOUND NO AERIAL DROP HANGING LOW,WORK COMPLETED

rx1696; remvd branches on cable,cleared debris,not serv affctg
cs1623; CIMI rehab tkt to remove dead tree limbs that could possibly damage our cable trimming was already completed c8h

rt1486; All services up ,also pulled off to Modesto to do a pit on Brixton per Eric
lh5743; Notified manager MT8231, aerial drop for this address already cleared, will check other aerial drops different addresses on same street.

rb2924; Drop removed, work completed

bs2864; Removed drop and all good now

cf1419; Removed dead airal drop

cf1419; Removed dead Airel drop

rx1696; removed weight bearing branches,cleared debris,not serv aff
;nk5685; PC-N; inspector pleaee make a tkt for pg&e to come out and reattatch secondary power drop to assigned house, tbhw

dg3424; Drop was previously removed

zo2856; Removed abandoned ASW from pole

zo2856; All work previously completed

zo2856; All ASW removed previously

zo2856; Removed ASW from ground, removed zip tie holding up ASW crossing street placed mid span attachment, attached free floating clam shell to pole, dressed all ASW going into terminal.

rs8367; All trbl clrd,waited for access to community gate,complete.

kw5925; Aerial drop removed.

hc3283; Low drop, needs to be raised, raised, service drop, sk25,

zo2856; Removed abandoned ASW from strand and pole
cf1419; Replaced guard hardware around pole still have couple more poles no cell covrage up here
zo2856; Removed ASW and dressed non abandoned ASW into term, placed MarkIt to replace terminal

cf1419; Added hardware around pole no service in the area all work done

tj4856; Wrecked out abandoned drop

lh5743; Notified manager MT8231, aerial drop is clear in mountains residential area..

da1367; All wire work comolete

fr2146; Drove to Twain hart old dead drop removed
lh5743; Notified manager MT8231, arial drop is cleared in mountains residential aerea, will check other aerial drop ps in same street for G095 issues.

da1367; Hanging drop temoved

EW042G; DROP REMOVED FROM POLE. AREA NOW SAFE AND CLEAR.

IS3295; ABRASIVE VEGETATION CLEARED

dk332q; Branches already cut down. Area looks clear

kw5925; Aerial drop removed.

zo2856; Climbed clearance pole to remove abandoned ASW then removed from terminal pole.

rb2924; Drop removed, work completed

dg3424; Removed unused drop at location

cf1419; Had to raise drop that was hanging low. Narrow roads getting to job

zo2856; Removed ASW from pole, removed clam shell box

zo2856; ASW removed before my arrival, Comcast line coiled at base of pole

ch8326; Raised aerial service drop

rb2924; Drops removed,work completed

rb2924; Drops removed, work completed

rb2924; Drop removed,work completed
EW042G; DROP CUT AND REMOVED FROM AREA. MADE SURE NO OTHER HARDWARE WAS ON THE GROUND. ALL CLEAR

da1367; No issue found, suspect previously cleared

MG5372; REMVD ASW FROM POLE AND DIRT

kw5925; Aerial drop removed.

rs8367; drv tenhrt-sra-twnHrt to assist to clr trbl,ok per mt8231,complete.

MG5372; REMVD ASW FROM POLE AND TREE

dg3424; Drop removed from location

zo2856; Placed bug nuts to secure lashing, tied up middle section to strand

ch8326; Removed aerial drop wire

dg3424; Removed unused drop wire
rs8367; Drv mdst-twnhrt,removed drop at 2 locs at opposite end of property line,Drv bk up the hill to get signal to close,complete.

kw5925; Aerial drop removed.

bs2864; Removed old drops from pole

kb5463; Remove broken hanging 6pr service drop.

ch8326; Removed aerial drop line

MT3262; ALL ITEMS REMOVED FROM POLES TREES ARE CLEARED NOW

ch8326; Removed dead aerial drop

dg3175; asised tree lim

dg3424; Drop is raised at location

zo2856; Placed ground wire under guard, replaced guard with existing hardwear

mm5268; Couldnt locate addres may be wrong
TB3178; UPON ARRIVAL LOCATED UNCOVERED SERVICE LINES RUNNING UP POLE, PLACED RISER GUARD AND REROUTE SOME BSW INTO EXISTING RISER GAURD

kb5463; Remove broken disco serv drop from midspan.

ec2732; Removed unused low hanging drops
gs3625; Removed two down drops to home no service attached two buried drop up pole to terminal and secured u guard

gs3625; Removed multiple dead drops from pole and out of bushes no service

bs2864; All good to go now thanks

bs2864; Now good to go thanks

bs2864; Job completed now thanks

ec2732; Raised low hanging drops

ec2732; Removed unused low drops

ec2732; Replaced riser guard on pole

ec2732; Replaced missing riser guard

jb8576; Cmp, repaired the loose drop on pole, unable to install a guard but was able to secure the drop to the pole.

jb8576; Cmp, replaced the old guard as it was bent. Placed new guard

;ch8326; PC-N; Cleared foilage from cable; TN: 9999999
zo2856; Dug out both cables and placed on other side of pole, backfilled , attached cables up pole, placed riser guard

kw5925; Installed u-guard, submitted additional markits.

;ch8326; PC-N; Cleared foilage from cable; TN: 9999999

em3528; Re attached drops to pole with clamps,cleared hazard

gs3625; Raised and reattached 6 pair drop to chiropractic business hanging low in bushes

rs8367; All trb clrd,complete

em3528; Drive time to job,placed guard and removed hazard

gs3625; Removed dead drop and secured other drops at top of pole before terminal no service on drop removed

mj1746; Task has been completed.

kb5463; Routine rehab work completed.

mj1746; Task has been completed.

gs3625; Removed multiple dead drop from midspan attachment no service

mj1746; Task has been completed.

MG5372; ASW REMVD AND HAD TO HELP TECH ON CHRONIC U. ERASE

fr2146; Old drops removed all looks good

dg3424; Riser placed over drops on pole

kw5925; All att work complete.

da1367; IU-guard placed over drops

IS3295; REMOVED DOWNED DROP AND CLEARED

rb2924; Re attached hardware,all work completed

bs2864; Job completed now thank you

zo2856; Riser placed on pole previously , street smart training completed.

bs2864; Job is now completed

IS3295; DOWNED DROP CLEARED UP

ch8326; Placed hardware on designated pole

dg3424; Drop removed from pole

zo2856; Placed riser guard over BSW removed abandoned ASW

dg3424; 2 cases needed and cable piece, closing but making new mark it.

RN8732; CLEARED VEGETATION FROM CABLE TO EASE THE WEIGHT.

zo2856; Placed riser guard up pole covering BSW , all ASW previously removed

ec2732; Removed low hanging unused drops

tj4856; Wrecked out drops abandoned

tj4856; Wrecked out abandoned drops

ch8326; Removed dead aerial drop

ch8326; Removed dead aerial drop

dg3424; All wire work completed

dg3424; All wire work completed

gs3625; Removed dead drops from pole and terminal no service

kw5925; Att att work complete.

zo2856; Construction placed new pole and cleaned area

zo2856; Removed abandoned ASW from pole

zo2856; Placed riser guard , attached BSW to pole, removed climbing hazard by extending BSW

zo2856; Placed clamps around existing U guard

dg3424; No drop removal needed

zo2856; Placed riser guard over BSW

zo2856; Placed guard over BSW and removed nails causing potential injury.

zo2856; Attached ASW to pole, unable to place guard so BSW tied to other BSW

tj4856; Connected loose hardware and guides

zo2856; Removed ASW from pole

zo2856; Removed ASW and placed MarkIt for terminal replacement.

rs8367; Drv to location, all trbl clrd, complete.
zo2856; Dug up BSW to have them buried to the pole, ran all BSW up pole and placed riser guard

zo2856; Placed riser guard up pole, attached six pair can to pole, removed all climbing hazards

gs3625; Removed dead drop hanging from midspan attachment no service on drop

dg3175; Respliced f2 pairs to closed BPC

cf1419; No service on I pad removed drop that was hanging and raised other drops

cr1893; All work complete and done

zo2856; Returned to pick up traffic hazard, placed guard raised splice box on pole

dg3424; No drop to be removed

gs3625; Removed dead drop from pole coiled up enough slack at j hook in case its ever needed to provide service again

gs3625; Removed dead drop from pole and terminal no service on it

ec2732; Re-connect loose hanging riser guard

zo2856; Previously completed before my arrival

MG5372; REMVD ASW FROM POLE AND DIRT

ec2732; Removed unused low hanging drops

rb2924; Repaired drop,advised customer

mj1746; Task has need completed.

bs2864; Job has been completed

bs2864; Job completed now thank you

bs2864; Job completed now thanks

ec2732; Placed riser guard on new pole

zo2856; Placed riser guard, raised splice box, zip tied all drops removing hazards

zo2856; All work done at time of pole replacement.

cs1623; All hardware issues resolved c8h

zo2856; Placed riser guard at geo location, address not found

zo2856; Placed guard over exposed BSW

mj1746; Inspected area. Existing pole transfer request still pending.

mj1746; Inspected area and verified issue resolved.

mj1746; Cleared issue with downed drop

mj1746; Inspected area and verified no issues other than pending pole transfer

zo2856; Placed riser guard over BSW and removed nails causing possible injury

dg3424; All drop work completed

ec2732; Removed low hanging unused drop

zo2856; Removed abandoned ASW from pole

ec2732; Removed low hanging unused drop

zo2856; Placed MarkIt 100895815 for pole to be replaced so that ASW can be raised.

tj4856; Wrecked out four abandoned drops three spans

tj4856; Wrecked out abandoned drops

cr1893; All work complete. All done.

zo2856; All work previously completed

zo2856; Placed guard on BSW at pole

zo2856; Placed two extra bolts from previous days

em3528; Placed guard on buried wire

zo2856; Guard placed before my arrival

zo2856; Removed ASW, no faults of ATT

gs3625; Removed dead drop from pole and wrote up mark it for terminal replacement wrapped in plastic

zo2856; Removed abandoned ASW from pole

rg6161; Remove both drops from around pole & guy wires. Also secured terminal took pics.
gs3625; Removed dead drop from pole and terminal pulled down drop out of my multiple trees no service

bs2864; Job completed now thanks

bs2864; Job is now completed

zo2856; Placed riser guard over BSW at GEO location not address. GEO location matched pic

zo2856; Placed riser over ground wire bonding cable

bs2864; Job is completed now

bs2864; Job completed now thanks

dg3424; All wire work completed

MG5372; ASW REMVD AND CLEARED. WENT TO YARD TO GET FIBER EQUIPMENT

gs3625; Removed dead drops from terminal and pole no service

kw5925; Wire removal complete. Travel back to Modesto.

kw5925; Wire removal complete.

dg3424; Small riser on pole ,

rb2924; Drop removed, work completed

rb2924; Drop removed, work completed

kw5925; rmvd aerial drop caught up within tree, all work complete.

kw5925; att work complete.

cr1893; all work complete

kw5925; rmvd dead midspan drop

kw5925; rmvd mult dead aerial drops,rprd open SMT, wrk complete.

kw5925; all drop work complete.

kw5925; rmvd all drops, all work complete.

uv639w; Tree already trimmed

bs2864; Job is now completed

MG5372; REMVD ASWFROM POLE AND DIRT

MG5372; REMVD ASW AFTER FINDING POLE. POLE TO TREES

MG5372; REMVD MULTIPLE ASW WIRES FROM POLE

MG5372; REMVD ASWFROM POLE AND TREES
MG5372; ALL WORK AT THIS ADDRESS IS COMCAST. INSPECTOR NEEDS TO KNOW THE DIFFERENCE

;mh3568; PC-Y; Hardware removal complete; TN: 2095860010

dg3424; All wire work completed
;mh3568; PC-Y; Air device installation at specified address of MH4 and MH7 for construction work; TN: 2095860010

rt1486; Removed drop all services up
rs8367; Intown 5 min. Found cable company drop wrapped in same area as our cable. No work done.complete.

em3528; Removed hazard,placed mark it

zo2856; Removed abandoned ASW from Comcast No ATT lines low

em3528; Removed drop hazard,made markmits

rs8367; Drv mdst-long barn,removed 5 drops with ladder.

kw5925; Removed aerial drop.

dg3424; New pole was placed at location and drop was removed

ch8326; Removed aerial drop line
dg3424; No drops at location need to removed, new pole was placed recently and drops were removed then.

kw5925; Aerial drop removed.

rt1486; All services up removed drop

kw5925; Aerial drop removed.

em3528; Cleared hazard,plus drive time

rt1486; Removed dead drop ok ty

ml5474; Remove unused asw mid-span

ml5474; All unused asws removed

nk5685; Removed all dead drops from term and around pole, tbhw
nk5685; Removed dead drops, secured working drops going up pole with u nails, cleaned up drops in term, tbhw

ml5474; Remove asw from property

nk5685; Removed dead drops retermed loose working drops, tbhw

rs8367; Drv grvlnd-sra,rmvd trbl drop,left cable drop,complete.

dg3424; All wire work completed

dg3424; All wire work completed

dg3424; All wire work completed at 11928 highway 49

rt1486; Removed drop cleaned up term

dg3424; All cable work completed

rt1486; Complete thank you ok

bs2864; Job is nw completed thanks

dg3424; 2 pair drop removed at address

dg3424; All wire work completed

bs2864; Job completed now thanks

cr1893; cut many branches some pretty large freed cable from enveloped branch

kb5463; remobed large tree limb hanging and tangled in service drops. Condition clear.

kw5925; Aerial drop removed, trvl back to Modesto.
jb8576; cmp, removed large branch hanging from the cable.. pic showed a larger part of the tree but it had been just partly removed.

zo2856; Removed abandoned ASW

et975m; GO95 cleared branches off line

rb2924; Drop removed, work completed

jb7519; Area closed off, no sign of downed drop , job complete

rs8367; Drv Sri-twnhrt waited for access to pole,rmvd drop,complete.

cf1419; Removed dead airel drops

bs2864; Job is now completed

hc3283; Removed bad drop , not in use, cleared old drop

rb2924; Drop removed, work completed
rs8367; Intown 5 min,removed drop from pole adjacent to property line,Drv uphill to get signal to close tkt. Complete
rs8367; Intown 5 min,clrd droploc,cst cld on uverse trbl,modem trbl,cld sup-ok to stay on tkt and go to Sonora on go on the way back to yard-cst at 70 oak st,modem chngd,all in service,complete.

dg3424; No drop that needs removal at address

zo2856; ASW removed before my arrival.

rb2924; Drop removed, work completed

kw5925; Aerial drop removed.

tj4856; Wrecked out abandoned drops

dg3424; New pole at location,no drops present

kw5925; Aerial drop removed.

cr1893; All work complete. Removed drops.

kb5463; Repair rebuild load point splice.
jb8576; trees have been trimmed and cleared at the address given and at the poles before and after are clear

SL5436; ALL GO95 CLEARED NO HAZARD

mj1746; Task has been completed.

rs8367; All trouble cleared. Parked on side of road nd walked to site. Complete.

tj4856; Wrecked out abandoned drops

zo2856; Removed abandoned ASW

SL5436; ALL GO95 CLEARED NO HAZARD

dg3424; Removed partial drop that was hanging on pole

cf1419; Removed dead drop from pole

MG5372; REMVD MULTIPLE ASW FROM POLE AND TREES

ch8326; Removed dead aerial drop wire

zo2856; Removed abandoned ASW from pole

mj1746; Task has been completed.

tj4856; Wrecked out abandoned drops

zo2856; Abandoned ASW removed

MG5372; REMVD ASW FROM POLE AND DIRT

ch8326; Removed dead aerial drops
jb8576; Cmp, verified the hangin drop was removed. Address did not match had to use the geo to find the pole.

zo2856; Removed abandoned ASW

dg3424; Rehab completed,not service affecting

zo2856; ASW previously removed. No hazards found

MG5372; DROVE TO ADDRESS PROVIDED AND REMVD ASW FROM POLE AND DIRT

zo2856; Removed abandoned ASW

MG5372; DROVE TO ADDRESS PROVIDED AND ASW WAS REMVD FROM POLE

rb2924; Drop removed, work completed

zo2856; ASW previously removed before my arrival

rb2924; Drop removed, work completed

pr2872; tree no longer there,cut out but other entity

JB6185; LOCATED AND REMVD LOW SEC OF AERIAL DROP,WORK COMPLETED

tj4856; Wrecked out abandoned drops

ds6453; All wire work completed. Removed hanging wires

zo2856; Removed three BSW from pole

tj4856; Wrecked out abandoned drops

tj4856; Wrecked out abandoned drops

MG5372; REMVD MULTIPLE ASW FROM POLE AND DIRT

ch8326; Removed dead aerial drop

ch8326; Removed down aerial drops

zo2856; ASW was removed when new pole placed. No ASW found

MG5372; REMVD ASWFROM POLE AND TREE

zo2856; Removed ASW from pole, Terri Prem very appreciative.

zo2856; Removed abandoned ASW
cs1623; G.O. 95 tkt vegetation growing around aerial cable needs removal removed branches and limbs hindering direction of cable c8h

rb2924; Drops removed, work completed

cr1893; All work complete. Removed drops.

dg3424; Removed low drop, not service affecting

rs8367; Drv mdst-twnhrt,raised 5 drops low across entry roadway to homes,complete.

rn8732; All drop work fixed and done.

pr2872; assist line crew with cable replacement and splice cable together

rb2924; Drops removed, work completed

MG5372; ASW REMVD FROM POLE AND TREE

dg3424; Removed drop, not service affecting

zo2856; Removed abandoned ASW

gs3625; Removed dead drops from pole and terminal no service

bs2864; Job is now completed

tj4856; Wrecked out abandoned drops

rg6161; Removed drop. Took pics drove back to VLY flr, clsd in yard ,no wap

SL5436; ALL GO95 CLEARED NO HAZARDS

rb2924; Drop raised,work completed

gs3625; Removed dead drop hanging from pole and terminal no service

bs2864; Job is completed now

rg6161; Removed drop,no wap,closed bk near yard on way down from hills,overrun,ah2142

zo2856; Removed abandoned ASW from pole

gs3625; Removed down drop from terminal and pole no service

zo2856; Work previously done with pole transfer

gs3625; Removed downed dead drop from pole and terminal no service

gs3625; Removed dead drops from pole and out of terminal no service

zo2856; All work previously completed.

zo2856; All work previously completed

rg6161; Removed drop,took pics.
rg6161; Poles replaced. Landscape Chang. Took pics of all 3 poles from geo & physical address. Drop already gone on floor.remvd one on 3 rd pole

bs2864; Job is now completed

dg3424; Removed low drop, not service affecting

rg6161; Drive up to hills, removed drop.took pics

bs2864; Job is now completed

rg6161; Removed drop,took pic
rg6161; Removed broken drop, secured drop up pole & added hardware. Travel up from for to hills. Took pics

bs2864; Job is now completed

bs2864; Job is now completed

bs2864; Job is now completed
cf1419; Removed drop also road was closed due to repaving advise customer if anything he needs call me

tj4856; Wreck out abandoned drop
ml5474; Removed old asw from pole, asst Daniel from Modesto on N Airport Rd in Columbia on ticket from yesterday.

bs2864; Job is now completed thank you

ml5474; Asst KB5463 on chronic hi-cap to heli-pad, 10 miles to prem from T.H.

bs2864; Job is now completed

dg3424; Not att dropits cable tv

bs2864; Job is now completed

bs2864; Removed 2 drops and all good now

bs2864; Job is now completed

ec2732; Removed unused low hanging drop

;rd2824; PC-N; RE-LASHED LOOSE & LOW HANGING CABL LOC @ HENRY MILER VOLTA

bs2864; Removed drop and now good to go

je7418; Raised 500ft of drops back and hooks on pole all work completed

jb8576; cmp, found low hanging drop and repositioned the anchor at the strand. Drop is much higher

mj1746; No att facilities found at address on ticket. Suspect wrong address inputted.

CH2861; AREA CLEARED OF DEBRIS!

rb2924; No cable in vicinity of address given

kw5925; All att work complete.

rb2924; Drop removed,work completed

ao8154; Removed old drop and clean terminal splice

bb6851; Job complete, tree trimmed, c99

COMP_NOTE

All Wire/Work Jobs have Completed, Package now in Complete status.

User gh304f added to Notifications for this package.

Aerial cable has been raised per JA5893

New lashing wire has been installed per JA5897

Aerial cable has been raised per JA5893

Aerial cable has been raised per JA5893

Aerial cable has been raised per JA5893

Package Manually Completed by fh1421.

Aerial cable has been raised per JA5893

Aerial cable has been raised per JA5893

Package Manually Completed by rr2576.

Package Manually Completed by rr2576.

Package Manually Completed by rr2576.

All Wire/Work Jobs have Completed, Package now in Complete status.

Package Manually Completed by gh304f.

Hazard cleared by pe4219. Pole replaced.

Package Manually Completed by te7361.

Design Record Updated by fh1421.

Sent to construction on package id 1018279
This package completed and new package created for 3rd party notification, Pole Damage Needs Replace New RWM # 710079
This package completed and new package created for 3rd party notification, Pole Damage Needs Replace New RWM # 710075

Package Manually Completed by fh1421.
This package completed and new package created for 3rd party notification, Pole Damage Needs Replace New RWM # 710077
This package completed and new package created for 3rd party notification, Pole Damage Needs Replace New RWM # 710074
This package completed and new package created for 3rd party notification, Pole Damage Needs Replace New RWM # 710076
This package completed and new package created for 3rd party notification, Pole Damage New RWM # 709728
This package completed and new package created for 3rd party notification, Pole Damage Needs Replace New RWM # 710078
This package completed and new package created for 3rd party notification, Pole Damage Needs Replace New RWM # 710080
This package completed and new package created for 3rd party notification, Pole Damage New RWM # 709730
This package completed and new package created for 3rd party notification, Pole Damage New RWM # 709729

Updating Actual Minutes on CIMI_RWM_00517414_01

Updating Actual Minutes on CIMI_RWM_00517418_01

Package Manually Completed by rr2576.

All Wire/Work Jobs have Completed, Package now in Complete status.

Updating Actual Minutes on CIMI_RWM_00517502_01

Package Manually Completed by rr2576.

Updating Actual Minutes on CIMI_RWM_00517504_01

Updating Actual Minutes on CIMI_RWM_00517505_01

Updating Actual Minutes on CIMI_RWM_00517507_01

Updating Actual Minutes on CIMI_RWM_00517510_01

Package Manually Completed by rr2576.

Updating Actual Minutes on CIMI_RWM_00517589_01

Hazard cleared by rr2576 on 7/30/21. Placed new downguy and guard

Package Manually Completed by rr2576.

Hazard cleared by rr2576. Raised cable

Hazard cleared by rr2576. Transfer complete

Updating Actual Minutes on CIMI_RWM_00517594_01

All Wire/Work Jobs have Completed, Package now in Complete status.

Updating Actual Minutes on CIMI_RWM_00517596_01

Hazard cleared by rr2576. Replaced hardware.

Hazard cleared by rr2576. Replaced guy guard 7/30/21

All Wire/Work Jobs have Completed, Package now in Complete status.

Package Manually Completed by cc3591.
HAZARD CLEARED BY RR2576,WS4698. NEW HARDWARE PLACED TO RAISE LOW DROPS

Package Manually Completed by rr2576.

Package Manually Completed by rr2576.

HAZARD CLEARED BY RR2576,WS4698. PLACED NEW DOWNGUY GUARD

HAZARD CLEARED BY RR2576,WS4698. PLACED NEW DOWNGUY GUARD

Package Manually Completed by cc3591.

Package Manually Completed by rr2576.

Package Manually Completed by cc3591.

hazard cleared by rr2576. Placed new down guy and guard 7/30/21

safety hazard cleared by ws4698. Placed 2 guy guards

hazrad cleared by ws4698. Retension 2 down guys

Package Manually Completed by rr2576.

Updating Actual Minutes on CIMI_CRR25760805C01

Package Manually Completed by rr2576.

Package Manually Completed by rr2576.

Updating Actual Minutes on CIMI_RWM_00517631_01

Updating Actual Minutes on CIMI_RWM_00517633_01

Updating Actual Minutes on CIMI_RWM_00517634_01

Updating Actual Minutes on CIMI_RWM_00517635_01

Package Manually Completed by rr2576.

Updating Actual Minutes on CIMI_RWM_00517646_01

Package Manually Completed by rr2576.

Updating Actual Minutes on CIMI_RWM_00517650_01

Updating Actual Minutes on CIMI_RWM_00517651_01

All Wire/Work Jobs have Completed, Package now in Complete status.

Package Manually Completed by rr2576.

Updating Actual Minutes on CIMI_RWM_00517655_01

Updating Actual Minutes on CIMI_RWM_00517660_01

Updating Actual Minutes on CIMI_RWM_00517663_01

Updating Actual Minutes on CIMI_RWM_00517666_01

Updating Actual Minutes on CIMI_RWM_00517668_01

Updating Actual Minutes on CIMI_RWM_00517670_01

All Wire/Work Jobs have Completed, Package now in Complete status.

Package Manually Completed by rr2576.

Updating Actual Minutes on CIMI_RWM_00517710_01

Package Manually Completed by rr2576.

Updating Actual Minutes on CIMI_RWM_00517732_01

Updating Actual Minutes on CIMI_RWM_00517758_01

Updating Actual Minutes on CIMI_RWM_00517760_01

Updating Actual Minutes on CIMI_RWM_00517765_01

Updating Actual Minutes on CIMI_RWM_00517768_01

Updating Actual Minutes on CIMI_RWM_00517770_01

Updating Actual Minutes on CIMI_RWM_00517776_01

Updating Actual Minutes on CIMI_RWM_00517778_01

Updating Actual Minutes on CIMI_RWM_00517781_01

Updating Actual Minutes on CIMI_RWM_00517815_01

Updating Actual Minutes on CIMI_RWM_00517823_01

Updating Actual Minutes on CIMI_RWM_00517828_01

Updating Actual Minutes on CIMI_RWM_00517829_01

Updating Actual Minutes on CIMI_RWM_00517830_01

Updating Actual Minutes on CIMI_RWM_00517833_01

Updating Actual Minutes on CIMI_RWM_00517836_01

All Wire/Work Jobs have Completed, Package now in Complete status.

All Wire/Work Jobs have Completed, Package now in Complete status.

All Wire/Work Jobs have Completed, Package now in Complete status.

All Wire/Work Jobs have Completed, Package now in Complete status.

Updating Actual Minutes on CIMI_RWM_00518440_01

All Wire/Work Jobs have Completed, Package now in Complete status.

Package Manually Completed by gh304f.

New pole placed 12/9 per JA5893.

Updating Actual Minutes on CIMI_RWM_00523784_01

Updating Actual Minutes on CIMI_RWM_00523786_01

Updating Actual Minutes on CIMI_RWM_00524093_01

Package Manually Completed by fh1421.

User gh304f added to Notifications for this package.

All Wire/Work Jobs have Completed, Package now in Complete status.

New lashing wire has been installed per JA5897

Package Manually Completed by fh1421.

Closed and package id 798175 created for Engineering new pole(s)

New pole placed 12/8/20 per mg2419

This Package was completed from OSPCM/JAM! Moving to Complete.

New pole placed 12/1/2020 per RL2671 job A01ZEJD

New pole placed job A01ZDB4 11/25/20 per TS1793

Job A01ZEJD New pole placed on 1-11-2021 per SE1672.

Inspected GO95 infraction, no trouble found at this location.

Updating Actual Minutes on CIMI_RWM_00526117_01

Package Manually Completed by ts9129.

Package Manually Completed by jq1534.
Inspected GO95 infraction, no trouble found at this location. 44 work is already completed.

GO95 issue has been resolved. Placed a new Downguy guard.

Updating Actual Minutes on CIMI_RWM_00526144_01

Updating Actual Minutes on CIMI_RWM_00526161_01

Updating Actual Minutes on CIMI_RWM_00526172_01

Inspected GO95 infraction, no trouble found at this location.

44l awc

Updating Actual Minutes on CIMI_RWM_00526192_01

Updating Actual Minutes on CIMI_RWM_00526193_01

Updating Actual Minutes on CIMI_RWM_00526194_01

GO95 issue has been resolved. Placed a new Downguy guard.

GO95 issue has been resolved. Placed a new Downguy guard.

GO95 issue has been resolved. Placed a new Downguy guard.

Updating Actual Minutes on CIMI_RWM_00526217_01

Package Manually Completed by ts9129.

Updating Actual Minutes on CIMI_RWM_00526234_01

Updating Actual Minutes on CIMI_RWM_00526248_01

Address is invalid, need more information in order to go to the correct location.

Updating Actual Minutes on CIMI_RWM_00526279_01

GO95 issue has been resolved. Placed a new Downguy guard.

Updating Actual Minutes on CIMI_RWM_00526298_01

Updating Actual Minutes on CIMI_RWM_00526313_01

43 went out and did repair

Package Manually Completed by ts9129.
Inspected GO95 infraction, no trouble found at this location. 44 work is already completed.

Updating Actual Minutes on CIMI_RWM_00526358_01

Updating Actual Minutes on CIMI_RWM_00526359_01

Updating Actual Minutes on CIMI_RWM_00526370_01

Package Manually Completed by ts9129.

Updating Actual Minutes on CIMI_RWM_00526393_01

Updating Actual Minutes on CIMI_RWM_00526400_01

Updating Actual Minutes on CIMI_RWM_00526401_01

Package Manually Completed by ts9129.

Updating Actual Minutes on CIMI_RWM_00526409_01

Package Manually Completed by ts9129.

Updating Actual Minutes on CIMI_RWM_00526441_01

Package Manually Completed by ts9129.

Updating Actual Minutes on CIMI_RWM_00526452_01

Updating Actual Minutes on CIMI_RWM_00526456_01

Updating Actual Minutes on CIMI_RWM_00526464_01

Inspected GO95 infraction, no trouble found at this location.

Updating Actual Minutes on CIMI_RWM_00526479_01

Updating Actual Minutes on CIMI_RWM_00526484_01

Inspected GO95 infraction, no trouble found at this location.

Updating Actual Minutes on CIMI_RWM_00526513_01

Updating Actual Minutes on CIMI_RWM_00526541_01

Updating Actual Minutes on CIMI_RWM_00526563_01

Package Manually Completed by ts9129.

Updating Actual Minutes on CIMI_RWM_00526572_01

Updating Actual Minutes on CIMI_RWM_00526579_01

Package Manually Completed by ts9129.
Inspected GO95 infraction, no trouble found at this location. 44 work is already completed.

Updating Actual Minutes on CIMI_RWM_00526608_01

GO95 issue has been resolved. Placed a new Downguy guard.

Updating Actual Minutes on CIMI_RWM_00526614_01

Inspected GO95 infraction, no trouble found at this location.

Package Manually Completed by ts9129.

Package Manually Completed by ts9129.

All Wire/Work Jobs have Completed, Package now in Complete status.

All Wire/Work Jobs have Completed, Package now in Complete status.

All Wire/Work Jobs have Completed, Package now in Complete status.

All Wire/Work Jobs have Completed, Package now in Complete status.

Updating Actual Minutes on CIMI_RWM_00526681_01

All Wire/Work Jobs have Completed, Package now in Complete status.

All Wire/Work Jobs have Completed, Package now in Complete status.

Updating Actual Minutes on CIMI_RWM_00526716_01

Updating Actual Minutes on CIMI_RWM_00526717_01

All Wire/Work Jobs have Completed, Package now in Complete status.

Package Manually Completed by gh304f.

Package Manually Completed by gh304f.

Package Manually Completed by fh1421.

All Wire/Work Jobs have Completed, Package now in Complete status.

All Wire/Work Jobs have Completed, Package now in Complete status.

All Wire/Work Jobs have Completed, Package now in Complete status.

All Wire/Work Jobs have Completed, Package now in Complete status.

Replaced broken lashing per JA5893

All Wire/Work Jobs have Completed, Package now in Complete status.

pole has no hazard per KA712W.

All Wire/Work Jobs have Completed, Package now in Complete status.

Updating Actual Minutes on CIMI_RWM_00527520_01

Updating Actual Minutes on CIMI_RWM_00527572_01

Updating Actual Minutes on CIMI_RWM_00527573_01

Updating Actual Minutes on CIMI_RWM_00527574_01

Updating Actual Minutes on CIMI_RWM_00527575_01

Updating Actual Minutes on CIMI_RWM_00527621_01

Updating Actual Minutes on CIMI_RWM_00527623_01

Updating Actual Minutes on CIMI_RWM_00527624_01

Updating Actual Minutes on CIMI_RWM_00527625_01

Updating Actual Minutes on CIMI_RWM_00527734_01

Updating Actual Minutes on CIMI_RWM_00527735_01

Updating Actual Minutes on CIMI_RWM_00527736_01

Updating Actual Minutes on CIMI_RWM_00527739_01

Updating Actual Minutes on CIMI_RWM_00527740_01

Updating Actual Minutes on CIMI_RWM_00527742_01

Updating Actual Minutes on CIMI_RWM_00527746_01

Updating Actual Minutes on CIMI_RWM_00527747_01

Updating Actual Minutes on CIMI_RWM_00527798_01

Updating Actual Minutes on CIMI_RWM_00527803_01

Updating Actual Minutes on CIMI_RWM_00527805_01

Updating Actual Minutes on CIMI_RWM_00527864_01

Updating Actual Minutes on CIMI_RWM_00527865_01

Updating Actual Minutes on CIMI_RWM_00527912_01

Updating Actual Minutes on CIMI_RWM_00528103_01

All Wire/Work Jobs have Completed, Package now in Complete status.

Package Manually Completed by bo128w.

Updating Actual Minutes on CIMI_RWM_00528302_01

Updating Actual Minutes on CIMI_RWM_00528303_01

Updating Actual Minutes on CIMI_RWM_00528309_01

Updating Actual Minutes on CIMI_RWM_00528310_01

Updating Actual Minutes on CIMI_RWM_00528316_01

Updating Actual Minutes on CIMI_RWM_00528317_01

Updating Actual Minutes on CIMI_RWM_00528323_01

All Wire/Work Jobs have Completed, Package now in Complete status.

All Wire/Work Jobs have Completed, Package now in Complete status.

Updating Actual Minutes on CIMI_RWM_00528342_01

All Wire/Work Jobs have Completed, Package now in Complete status.

All Wire/Work Jobs have Completed, Package now in Complete status.

All Wire/Work Jobs have Completed, Package now in Complete status.

All Wire/Work Jobs have Completed, Package now in Complete status.

All Wire/Work Jobs have Completed, Package now in Complete status.

All Wire/Work Jobs have Completed, Package now in Complete status.

job was initally sent out last year in JUly 2020. Completed work

All Wire/Work Jobs have Completed, Package now in Complete status.

All Wire/Work Jobs have Completed, Package now in Complete status.

site inspection 1/12/2021, New pole in place.

Aerial cable has been raised per JA5893

Updating Actual Minutes on CIMI_RWM_00706555_01

Updating Actual Minutes on CIMI_RWM_00706556_01
All Wire/Work Jobs have Completed, Package now in Complete status.

Updating Actual Minutes on CIMI_RWM_00755678_01

All Wire/Work Jobs have Completed, Package now in Complete status.

All Wire/Work Jobs have Completed, Package now in Complete status.

All Wire/Work Jobs have Completed, Package now in Complete status.

All Wire/Work Jobs have Completed, Package now in Complete status.

All Wire/Work Jobs have Completed, Package now in Complete status.

All Wire/Work Jobs have Completed, Package now in Complete status.

All Wire/Work Jobs have Completed, Package now in Complete status.

new aerial line placed 7-12-21 per JA5893

All Wire/Work Jobs have Completed, Package now in Complete status.

All Wire/Work Jobs have Completed, Package now in Complete status.

All Wire/Work Jobs have Completed, Package now in Complete status.

All Wire/Work Jobs have Completed, Package now in Complete status.

All Wire/Work Jobs have Completed, Package now in Complete status.

All Wire/Work Jobs have Completed, Package now in Complete status.

All Wire/Work Jobs have Completed, Package now in Complete status.

All Wire/Work Jobs have Completed, Package now in Complete status.

All Wire/Work Jobs have Completed, Package now in Complete status.

All Wire/Work Jobs have Completed, Package now in Complete status.

All Wire/Work Jobs have Completed, Package now in Complete status.

All Wire/Work Jobs have Completed, Package now in Complete status.

All Wire/Work Jobs have Completed, Package now in Complete status.

All Wire/Work Jobs have Completed, Package now in Complete status.

All Wire/Work Jobs have Completed, Package now in Complete status.

All Wire/Work Jobs have Completed, Package now in Complete status.

new down guy and lean corrected 7-12-21 per JA5893

All Wire/Work Jobs have Completed, Package now in Complete status.

All Wire/Work Jobs have Completed, Package now in Complete status.

All Wire/Work Jobs have Completed, Package now in Complete status.

All Wire/Work Jobs have Completed, Package now in Complete status.

All Wire/Work Jobs have Completed, Package now in Complete status.

All Wire/Work Jobs have Completed, Package now in Complete status.

All Wire/Work Jobs have Completed, Package now in Complete status.

All Wire/Work Jobs have Completed, Package now in Complete status.

All Wire/Work Jobs have Completed, Package now in Complete status.

All Wire/Work Jobs have Completed, Package now in Complete status.

All Wire/Work Jobs have Completed, Package now in Complete status.

All Wire/Work Jobs have Completed, Package now in Complete status.

All Wire/Work Jobs have Completed, Package now in Complete status.

All Wire/Work Jobs have Completed, Package now in Complete status.

All Wire/Work Jobs have Completed, Package now in Complete status.

All Wire/Work Jobs have Completed, Package now in Complete status.

All Wire/Work Jobs have Completed, Package now in Complete status.

All Wire/Work Jobs have Completed, Package now in Complete status.

All Wire/Work Jobs have Completed, Package now in Complete status.

All Wire/Work Jobs have Completed, Package now in Complete status.

All Wire/Work Jobs have Completed, Package now in Complete status.

All Wire/Work Jobs have Completed, Package now in Complete status.

All Wire/Work Jobs have Completed, Package now in Complete status.

All Wire/Work Jobs have Completed, Package now in Complete status.

All Wire/Work Jobs have Completed, Package now in Complete status.

All Wire/Work Jobs have Completed, Package now in Complete status.

All Wire/Work Jobs have Completed, Package now in Complete status.

All Wire/Work Jobs have Completed, Package now in Complete status.

All Wire/Work Jobs have Completed, Package now in Complete status.

All Wire/Work Jobs have Completed, Package now in Complete status.

All Wire/Work Jobs have Completed, Package now in Complete status.

All Wire/Work Jobs have Completed, Package now in Complete status.

All Wire/Work Jobs have Completed, Package now in Complete status.

All Wire/Work Jobs have Completed, Package now in Complete status.

All Wire/Work Jobs have Completed, Package now in Complete status.

All Wire/Work Jobs have Completed, Package now in Complete status.

All Wire/Work Jobs have Completed, Package now in Complete status.

All Wire/Work Jobs have Completed, Package now in Complete status.

All Wire/Work Jobs have Completed, Package now in Complete status.

All Wire/Work Jobs have Completed, Package now in Complete status.

All Wire/Work Jobs have Completed, Package now in Complete status.

All Wire/Work Jobs have Completed, Package now in Complete status.

All Wire/Work Jobs have Completed, Package now in Complete status.

All Wire/Work Jobs have Completed, Package now in Complete status.

All Wire/Work Jobs have Completed, Package now in Complete status.

All Wire/Work Jobs have Completed, Package now in Complete status.

All Wire/Work Jobs have Completed, Package now in Complete status.

All Wire/Work Jobs have Completed, Package now in Complete status.

All Wire/Work Jobs have Completed, Package now in Complete status.

All Wire/Work Jobs have Completed, Package now in Complete status.

Package Manually Completed by ts9129.

GO95 issue has been resolved. Placed a new Downguy guard.

Package Manually Completed by ts9129.

Package Manually Completed by jq1534.
Inspected GO95 infraction, no trouble found at this location. 44 work is already completed.

not a hazard

not a hazard

Package Manually Completed by jq1534.

Package Manually Completed by mg2419.

Package Manually Completed by jq1534.

Package Manually Completed by jq1534.

Package Manually Completed by jq1534.

lashing wire not broken

lashing wire not broken

Package Manually Completed by jq1534.

Package Manually Completed by jq1534.

lashing wire not broken

no broken lashing wire burnt self support innerduct

place guy guard

lashing wire not broken

Package Manually Completed by mg2419.

NOT GO95 OR HAZ

Package Manually Completed by jq1534.

Package Manually Completed by jq1534.

Package Manually Completed by jq1534.

I&M bag on strand not a hazard or violation

lashing wire not broken

Updating Actual Minutes on CIMI_RWM_00756471_01

Package Manually Completed by mg2419.

Package Manually Completed by jq1534.

lashing wire not broken

lashing wire not broken

I&M bag on cable

Updating Actual Minutes on CIMI_RWM_00756510_01

Updating Actual Minutes on CIMI_RWM_00756511_01

Updating Actual Minutes on CIMI_RWM_00756520_01

Updating Actual Minutes on CIMI_RWM_00756521_01

Updating Actual Minutes on CIMI_RWM_00756522_01

Updating Actual Minutes on CIMI_RWM_00756523_01

Updating Actual Minutes on CIMI_RWM_00756524_01

Updating Actual Minutes on CIMI_RWM_00756525_01

All Wire/Work Jobs have Completed, Package now in Complete status.

All Wire/Work Jobs have Completed, Package now in Complete status.

All Wire/Work Jobs have Completed, Package now in Complete status.

All Wire/Work Jobs have Completed, Package now in Complete status.

New lashing wire placed 3-9-21 per JA5893

All Wire/Work Jobs have Completed, Package now in Complete status.

All Wire/Work Jobs have Completed, Package now in Complete status.

All Wire/Work Jobs have Completed, Package now in Complete status.

New lashing wire placed 3-8-21 per JA5893

All Wire/Work Jobs have Completed, Package now in Complete status.

All Wire/Work Jobs have Completed, Package now in Complete status.

All Wire/Work Jobs have Completed, Package now in Complete status.

All Wire/Work Jobs have Completed, Package now in Complete status.

All Wire/Work Jobs have Completed, Package now in Complete status.

All Wire/Work Jobs have Completed, Package now in Complete status.

All Wire/Work Jobs have Completed, Package now in Complete status.

Updating Actual Minutes on CIMI_RWM_00757097_01

Updating Actual Minutes on CIMI_RWM_00757098_01

Updating Actual Minutes on CIMI_RWM_00757104_01

Updating Actual Minutes on CIMI_RWM_00757125_01

Updating Actual Minutes on CIMI_RWM_00757127_01

Updating Actual Minutes on CIMI_RWM_00757129_01

Updating Actual Minutes on CIMI_RWM_00757286_01

Updating Actual Minutes on CIMI_RWM_00757314_01

Updating Actual Minutes on CIMI_RWM_00757435_01

Updating Actual Minutes on CIMI_RWM_00757438_01

Updating Actual Minutes on CIMI_RWM_00757440_01

Updating Actual Minutes on CIMI_RWM_00757443_01

Updating Actual Minutes on CIMI_RWM_00757448_01

Updating Actual Minutes on CIMI_RWM_00757449_01

Updating Actual Minutes on CIMI_RWM_00757496_01

Updating Actual Minutes on CIMI_RWM_00757500_01

All Wire/Work Jobs have Completed, Package now in Complete status.

All Wire/Work Jobs have Completed, Package now in Complete status.

Package Manually Completed by fh1421.

New lashing wire installed 3/11/2021 per JA5893.

Updating Actual Minutes on CIMI_RWM_00758103_01

Updating Actual Minutes on CIMI_RWM_00758105_01

Updating Actual Minutes on CIMI_RWM_00758106_01

Updating Actual Minutes on CIMI_RWM_00758108_01

Updating Actual Minutes on CIMI_RWM_00758114_01

Updating Actual Minutes on CIMI_RWM_00758136_01

Updating Actual Minutes on CIMI_RWM_00758137_01

Updating Actual Minutes on CIMI_RWM_00758143_01

Updating Actual Minutes on CIMI_RWM_00758145_01

Updating Actual Minutes on CIMI_RWM_00758166_01

Updating Actual Minutes on CIMI_RWM_00758169_01

Updating Actual Minutes on CIMI_RWM_00758171_01

Updating Actual Minutes on CIMI_RWM_00758172_01

Updating Actual Minutes on CIMI_RWM_00758173_01

Updating Actual Minutes on CIMI_RWM_00758174_01

Updating Actual Minutes on CIMI_RWM_00758177_01

Updating Actual Minutes on CIMI_RWM_00758182_01

Updating Actual Minutes on CIMI_RWM_00758183_01

Updating Actual Minutes on CIMI_RWM_00758198_01

Updating Actual Minutes on CIMI_RWM_00758218_01

Updating Actual Minutes on CIMI_RWM_00758219_01

Updating Actual Minutes on CIMI_RWM_00758220_01

Updating Actual Minutes on CIMI_RWM_00758221_01

Updating Actual Minutes on CIMI_RWM_00758222_01

Updating Actual Minutes on CIMI_RWM_00758318_01

Updating Actual Minutes on CIMI_RWM_00758346_01

Updating Actual Minutes on CIMI_RWM_00758378_01

Updating Actual Minutes on CIMI_RWM_00758381_01

Updating Actual Minutes on CIMI_RWM_00758501_01

Updating Actual Minutes on CIMI_RWM_00758511_01

Updating Actual Minutes on CIMI_RWM_00758512_01

Updating Actual Minutes on CIMI_RWM_00758513_01

Updating Actual Minutes on CIMI_RWM_00758515_01

Updating Actual Minutes on CIMI_RWM_00758545_01

Updating Actual Minutes on CIMI_RWM_00758547_01

Updating Actual Minutes on CIMI_RWM_00758549_01

Updating Actual Minutes on CIMI_RWM_00758550_01

Updating Actual Minutes on CIMI_RWM_00758553_01

Updating Actual Minutes on CIMI_RWM_00758554_01

Updating Actual Minutes on CIMI_RWM_00758556_01

Updating Actual Minutes on CIMI_RWM_00758569_01

Updating Actual Minutes on CIMI_RWM_00758574_01

Updating Actual Minutes on CIMI_RWM_00758575_01

Updating Actual Minutes on CIMI_RWM_00758577_01

Updating Actual Minutes on CIMI_RWM_00758579_01

Updating Actual Minutes on CIMI_RWM_00758582_01

Updating Actual Minutes on CIMI_RWM_00758584_01

Updating Actual Minutes on CIMI_RWM_00758597_01

Updating Actual Minutes on CIMI_RWM_00758598_01

Updating Actual Minutes on CIMI_RWM_00758603_01

Updating Actual Minutes on CIMI_RWM_00758606_01

Updating Actual Minutes on CIMI_RWM_00758611_01

Updating Actual Minutes on CIMI_RWM_00758612_01

Updating Actual Minutes on CIMI_RWM_00758642_01

Updating Actual Minutes on CIMI_RWM_00758651_01

Updating Actual Minutes on CIMI_RWM_00758674_01

All Wire/Work Jobs have Completed, Package now in Complete status.

Updating Actual Minutes on CIMI_RWM_00758679_01

Updating Actual Minutes on CIMI_RWM_00758680_01

Updating Actual Minutes on CIMI_RWM_00758706_01

Updating Actual Minutes on CIMI_RWM_00758728_01

Updating Actual Minutes on CIMI_RWM_00758754_01

All Wire/Work Jobs have Completed, Package now in Complete status.

All Wire/Work Jobs have Completed, Package now in Complete status.

All Wire/Work Jobs have Completed, Package now in Complete status.

All Wire/Work Jobs have Completed, Package now in Complete status.

All Wire/Work Jobs have Completed, Package now in Complete status.

All Wire/Work Jobs have Completed, Package now in Complete status.

All Wire/Work Jobs have Completed, Package now in Complete status.

All Wire/Work Jobs have Completed, Package now in Complete status.

All Wire/Work Jobs have Completed, Package now in Complete status.

All Wire/Work Jobs have Completed, Package now in Complete status.

All Wire/Work Jobs have Completed, Package now in Complete status.

All Wire/Work Jobs have Completed, Package now in Complete status.

All Wire/Work Jobs have Completed, Package now in Complete status.

All Wire/Work Jobs have Completed, Package now in Complete status.

All Wire/Work Jobs have Completed, Package now in Complete status.

All Wire/Work Jobs have Completed, Package now in Complete status.

All Wire/Work Jobs have Completed, Package now in Complete status.

All Wire/Work Jobs have Completed, Package now in Complete status.

All Wire/Work Jobs have Completed, Package now in Complete status.

All Wire/Work Jobs have Completed, Package now in Complete status.

All Wire/Work Jobs have Completed, Package now in Complete status.

All Wire/Work Jobs have Completed, Package now in Complete status.

All Wire/Work Jobs have Completed, Package now in Complete status.

All Wire/Work Jobs have Completed, Package now in Complete status.

All Wire/Work Jobs have Completed, Package now in Complete status.

All Wire/Work Jobs have Completed, Package now in Complete status.

All Wire/Work Jobs have Completed, Package now in Complete status.

All Wire/Work Jobs have Completed, Package now in Complete status.

All Wire/Work Jobs have Completed, Package now in Complete status.

All Wire/Work Jobs have Completed, Package now in Complete status.

All Wire/Work Jobs have Completed, Package now in Complete status.

All Wire/Work Jobs have Completed, Package now in Complete status.

All Wire/Work Jobs have Completed, Package now in Complete status.

All Wire/Work Jobs have Completed, Package now in Complete status.

All Wire/Work Jobs have Completed, Package now in Complete status.

All Wire/Work Jobs have Completed, Package now in Complete status.

All Wire/Work Jobs have Completed, Package now in Complete status.

All Wire/Work Jobs have Completed, Package now in Complete status.

All Wire/Work Jobs have Completed, Package now in Complete status.

All Wire/Work Jobs have Completed, Package now in Complete status.

All Wire/Work Jobs have Completed, Package now in Complete status.

All Wire/Work Jobs have Completed, Package now in Complete status.

cables have been raised

All Wire/Work Jobs have Completed, Package now in Complete status.

All Wire/Work Jobs have Completed, Package now in Complete status.

All Wire/Work Jobs have Completed, Package now in Complete status.

All Wire/Work Jobs have Completed, Package now in Complete status.

All Wire/Work Jobs have Completed, Package now in Complete status.

All Wire/Work Jobs have Completed, Package now in Complete status.

All Wire/Work Jobs have Completed, Package now in Complete status.

All Wire/Work Jobs have Completed, Package now in Complete status.

All Wire/Work Jobs have Completed, Package now in Complete status.

All Wire/Work Jobs have Completed, Package now in Complete status.

All Wire/Work Jobs have Completed, Package now in Complete status.

All Wire/Work Jobs have Completed, Package now in Complete status.

All Wire/Work Jobs have Completed, Package now in Complete status.

All Wire/Work Jobs have Completed, Package now in Complete status.

All Wire/Work Jobs have Completed, Package now in Complete status.

All Wire/Work Jobs have Completed, Package now in Complete status.

All Wire/Work Jobs have Completed, Package now in Complete status.

All Wire/Work Jobs have Completed, Package now in Complete status.

All Wire/Work Jobs have Completed, Package now in Complete status.

All Wire/Work Jobs have Completed, Package now in Complete status.

All Wire/Work Jobs have Completed, Package now in Complete status.

All Wire/Work Jobs have Completed, Package now in Complete status.

All Wire/Work Jobs have Completed, Package now in Complete status.

All Wire/Work Jobs have Completed, Package now in Complete status.

All Wire/Work Jobs have Completed, Package now in Complete status.

All Wire/Work Jobs have Completed, Package now in Complete status.

All Wire/Work Jobs have Completed, Package now in Complete status.

All Wire/Work Jobs have Completed, Package now in Complete status.

All Wire/Work Jobs have Completed, Package now in Complete status.

All Wire/Work Jobs have Completed, Package now in Complete status.

All Wire/Work Jobs have Completed, Package now in Complete status.

All Wire/Work Jobs have Completed, Package now in Complete status.

All Wire/Work Jobs have Completed, Package now in Complete status.

All Wire/Work Jobs have Completed, Package now in Complete status.

All Wire/Work Jobs have Completed, Package now in Complete status.

All Wire/Work Jobs have Completed, Package now in Complete status.

All Wire/Work Jobs have Completed, Package now in Complete status.

All Wire/Work Jobs have Completed, Package now in Complete status.

All Wire/Work Jobs have Completed, Package now in Complete status.

All Wire/Work Jobs have Completed, Package now in Complete status.

All Wire/Work Jobs have Completed, Package now in Complete status.

All Wire/Work Jobs have Completed, Package now in Complete status.

All Wire/Work Jobs have Completed, Package now in Complete status.

All Wire/Work Jobs have Completed, Package now in Complete status.

All Wire/Work Jobs have Completed, Package now in Complete status.

All Wire/Work Jobs have Completed, Package now in Complete status.

All Wire/Work Jobs have Completed, Package now in Complete status.

All Wire/Work Jobs have Completed, Package now in Complete status.

All Wire/Work Jobs have Completed, Package now in Complete status.

All Wire/Work Jobs have Completed, Package now in Complete status.

Package Manually Completed by bo128w.

Package Manually Completed by bo128w.

Fixed broken lashing wire.

Package Manually Completed by bo128w.

Package Manually Completed by mg2419.

Package Manually Completed by mg2419.

Package Manually Completed by jq1534.

Package Manually Completed by jq1534.

Package Manually Completed by jq1534.

job to be completed with pole transfer 120804312

new guy guard placed with pole transfer

Package Manually Completed by jq1534.

Package Manually Completed by mg2419.

Updating Actual Minutes on CIMI_RWM_00761961_01

Updating Actual Minutes on CIMI_RWM_00761962_01

Updating Actual Minutes on CIMI_RWM_00761964_01

Updating Actual Minutes on CIMI_RWM_00761965_01

Updating Actual Minutes on CIMI_RWM_00761972_01

Updating Actual Minutes on CIMI_RWM_00761974_01

Updating Actual Minutes on CIMI_RWM_00761976_01

Updating Actual Minutes on CIMI_RWM_00761977_01

Updating Actual Minutes on CIMI_RWM_00761978_01

Updating Actual Minutes on CIMI_RWM_00761979_01

Updating Actual Minutes on CIMI_RWM_00761981_01

Updating Actual Minutes on CIMI_RWM_00761982_01

Updating Actual Minutes on CIMI_RWM_00761984_01

Updating Actual Minutes on CIMI_RWM_00777324_01

Complete per JA5893

New pole placed by TS1793 4/14/21

HAZARD CLEARED BY JA2891,JM9856 ON 5/25. STRAND RETIGHTENED

6-18-21 Re-sagged cable to eliminate hazard per TS1793.

Updating Actual Minutes on CIMI_CJA28911027C01

AWC PER TFS TECH
TFS is installing a new splice case per JG2182 SPOC for TFS.

new pole placed 9-14-21 per EB7424

GO95 Cable -> Clearance to ground per JA5893 01/31/22

Package Manually Completed by te7361.

All Wire/Work Jobs have Completed, Package now in Complete status.
959940 PKG ID for Engineer to determine if 3rd pole south of intersection Hwy 108/Hwy 120 on West side of the road has 30' of cut/abandoned strand/cable and case

Package Manually Completed by dg2874.

Updating Actual Minutes on CIMI_RWM_00972269_01

Updating Actual Minutes on CIMI_RWM_00972270_01

Updating Actual Minutes on CIMI_RWM_00972274_01

Updating Actual Minutes on CIMI_RWM_00972276_01

Updating Actual Minutes on CIMI_RWM_00972277_01

Package Manually Completed by jm8245.

Updating Actual Minutes on CIMI_RWM_00972280_01

Updating Actual Minutes on CIMI_RWM_01011675_01

Updating Actual Minutes on CIMI_RWM_01011687_01

Updating Actual Minutes on CIMI_RWM_01011690_01

Updating Actual Minutes on CIMI_RWM_01011691_01

Updating Actual Minutes on CIMI_RWM_01011692_01

Updating Actual Minutes on CIMI_RWM_01011715_01

Updating Actual Minutes on CIMI_RWM_01011717_01

All Wire/Work Jobs have Completed, Package now in Complete status.

Package Manually Completed by jq1534.

Updating Actual Minutes on CIMI_RWM_01011726_01

Updating Actual Minutes on CIMI_RWM_01011727_01

Updating Actual Minutes on CIMI_RWM_01011728_01

Updating Actual Minutes on CIMI_RWM_01011748_01

Package Manually Completed by eb1236.

Updating Actual Minutes on CIMI_RWM_01011787_01

Updating Actual Minutes on CIMI_RWM_01011813_01

Updating Actual Minutes on CIMI_RWM_01011815_01

Updating Actual Minutes on CIMI_RWM_01011818_01

Updating Actual Minutes on CIMI_RWM_01011848_01

Updating Actual Minutes on CIMI_RWM_01011849_01

Updating Actual Minutes on CIMI_RWM_01011857_01

Updating Actual Minutes on CIMI_RWM_01011860_01

inspected all work complete

Updating Actual Minutes on CIMI_RWM_01011868_01

Updating Actual Minutes on CIMI_RWM_01011879_01

Updating Actual Minutes on CIMI_RWM_01011892_01

Updating Actual Minutes on CIMI_RWM_01011898_01

Updating Actual Minutes on CIMI_RWM_01011903_01

Updating Actual Minutes on CIMI_RWM_01011905_01

Updating Actual Minutes on CIMI_RWM_01011911_01

Updating Actual Minutes on CIMI_RWM_01011917_01

Updating Actual Minutes on CIMI_RWM_01011919_01

Updating Actual Minutes on CIMI_RWM_01011924_01

Updating Actual Minutes on CIMI_RWM_01011931_01

Updating Actual Minutes on CIMI_RWM_01011935_01

44L AWC gps grid pack-in location/ broken guy/ r&r 6m ins down guy, guy guard

Updating Actual Minutes on CIMI_RWM_01011953_01

Updating Actual Minutes on CIMI_RWM_01011954_01

Updating Actual Minutes on CIMI_RWM_01011958_01

Updating Actual Minutes on CIMI_RWM_01011967_01

inspected all work complete

Updating Actual Minutes on CIMI_RWM_01011973_01

Updating Actual Minutes on CIMI_RWM_01011974_01

Updating Actual Minutes on CIMI_RWM_01011982_01

Updating Actual Minutes on CIMI_RWM_01011987_01

Updating Actual Minutes on CIMI_RWM_01011989_01

Updating Actual Minutes on CIMI_RWM_01012000_01

Package Manually Completed by te7361.

Updating Actual Minutes on CIMI_RWM_01012015_01

06/21/22 Hazard cleared per ja5893

All Wire/Work Jobs have Completed, Package now in Complete status.

All Wire/Work Jobs have Completed, Package now in Complete status.

Updating Actual Minutes on CIMI_RWM_01012054_01

Updating Actual Minutes on CIMI_RWM_01012057_01

Updating Actual Minutes on CIMI_RWM_01012058_01

Updating Actual Minutes on CIMI_RWM_01012059_01

Updating Actual Minutes on CIMI_RWM_01012063_01

Updating Actual Minutes on CIMI_RWM_01012066_01

Updating Actual Minutes on CIMI_RWM_01012078_01

Updating Actual Minutes on CIMI_RWM_01012079_01

Updating Actual Minutes on CIMI_RWM_01012080_01

Updating Actual Minutes on CIMI_RWM_01012081_01

Updating Actual Minutes on CIMI_RWM_01012083_01

Updating Actual Minutes on CIMI_RWM_01012101_01

Updating Actual Minutes on CIMI_RWM_01012132_01

Updating Actual Minutes on CIMI_RWM_01012135_01

Updating Actual Minutes on CIMI_RWM_01012137_01

Updating Actual Minutes on CIMI_RWM_01012142_01

Updating Actual Minutes on CIMI_RWM_01012144_01

Updating Actual Minutes on CIMI_RWM_01012147_01

Updating Actual Minutes on CIMI_RWM_01012174_01

placed u guard

Updating Actual Minutes on CIMI_RWM_01012178_01

Updating Actual Minutes on CIMI_RWM_01012211_01

Updating Actual Minutes on CIMI_RWM_01012213_01

Updating Actual Minutes on CIMI_RWM_01012214_01

Updating Actual Minutes on CIMI_RWM_01012217_01

Updating Actual Minutes on CIMI_RWM_01012219_01

Updating Actual Minutes on CIMI_RWM_01012220_01

Updating Actual Minutes on CIMI_RWM_01012221_01

Updating Actual Minutes on CIMI_RWM_01012223_01

Updating Actual Minutes on CIMI_RWM_01012224_01

Updating Actual Minutes on CIMI_RWM_01012227_01

Updating Actual Minutes on CIMI_RWM_01012229_01

Updating Actual Minutes on CIMI_RWM_01012232_01

Updating Actual Minutes on CIMI_RWM_01012234_01

Updating Actual Minutes on CIMI_RWM_01012237_01

Updating Actual Minutes on CIMI_RWM_01012238_01

Updating Actual Minutes on CIMI_RWM_01012239_01

Updating Actual Minutes on CIMI_RWM_01012240_01

Updating Actual Minutes on CIMI_RWM_01012242_01

Updating Actual Minutes on CIMI_RWM_01012265_01

Updating Actual Minutes on CIMI_RWM_01012267_01

Updating Actual Minutes on CIMI_RWM_01012268_01

Updating Actual Minutes on CIMI_RWM_01012270_01

Updating Actual Minutes on CIMI_RWM_01012271_01

Updating Actual Minutes on CIMI_RWM_01012276_01

Updating Actual Minutes on CIMI_RWM_01012278_01

Updating Actual Minutes on CIMI_RWM_01012286_01

Package Manually Completed by jq1534.

Updating Actual Minutes on CIMI_RWM_01012291_01

Updating Actual Minutes on CIMI_RWM_01012296_01

Updating Actual Minutes on CIMI_RWM_01012297_01

Updating Actual Minutes on CIMI_RWM_01012299_01

Updating Actual Minutes on CIMI_RWM_01012300_01

Updating Actual Minutes on CIMI_RWM_01012318_01

Updating Actual Minutes on CIMI_RWM_01012320_01

Updating Actual Minutes on CIMI_RWM_01012324_01

Updating Actual Minutes on CIMI_RWM_01012328_01

Updating Actual Minutes on CIMI_RWM_01012329_01

Updating Actual Minutes on CIMI_RWM_01012330_01

Updating Actual Minutes on CIMI_RWM_01012332_01

inspected all work complete

Updating Actual Minutes on CIMI_RWM_01012340_01

Updating Actual Minutes on CIMI_RWM_01012349_01

Updating Actual Minutes on CIMI_RWM_01012350_01

Package Manually Completed by jq1534.

Updating Actual Minutes on CIMI_RWM_01012371_01

Updating Actual Minutes on CIMI_RWM_01012375_01

Updating Actual Minutes on CIMI_RWM_01012378_01

Updating Actual Minutes on CIMI_RWM_01012380_01

Updating Actual Minutes on CIMI_RWM_01012382_01

Updating Actual Minutes on CIMI_RWM_01012383_01

Updating Actual Minutes on CIMI_RWM_01012384_01

Updating Actual Minutes on CIMI_RWM_01012385_01

Updating Actual Minutes on CIMI_RWM_01012386_01

Updating Actual Minutes on CIMI_RWM_01012391_01

Updating Actual Minutes on CIMI_RWM_01012393_01

inspected all work complete

Package Manually Completed by jq1534.

Updating Actual Minutes on CIMI_RWM_01012425_01

Updating Actual Minutes on CIMI_RWM_01012426_01

Updating Actual Minutes on CIMI_RWM_01012427_01

Updating Actual Minutes on CIMI_RWM_01012430_01

Updating Actual Minutes on CIMI_RWM_01012431_01

Updating Actual Minutes on CIMI_RWM_01012432_01

Updating Actual Minutes on CIMI_RWM_01012433_01

Updating Actual Minutes on CIMI_RWM_01012434_01

Updating Actual Minutes on CIMI_RWM_01012435_01

Updating Actual Minutes on CIMI_RWM_01012438_01

Updating Actual Minutes on CIMI_RWM_01018129_01

Updating Actual Minutes on CIMI_RWM_01018164_01

Updating Actual Minutes on CIMI_RWM_01018165_01

Updating Actual Minutes on CIMI_RWM_01018180_01

Updating Actual Minutes on CIMI_RWM_01018200_01

Updating Actual Minutes on CIMI_RWM_01018203_01

Updating Actual Minutes on CIMI_RWM_01018205_01

Updating Actual Minutes on CIMI_RWM_01018206_01

Updating Actual Minutes on CIMI_RWM_01018210_01

Updating Actual Minutes on CIMI_RWM_01018268_01

Updating Actual Minutes on CIMI_RWM_01018275_01

All Wire/Work Jobs have Completed, Package now in Complete status.

Updating Actual Minutes on CIMI_RWM_01018309_01

Updating Actual Minutes on CIMI_RWM_01018312_01

44 AWC

44 AWC

Updating Actual Minutes on CIMI_RWM_01018342_01

Updating Actual Minutes on CIMI_RWM_01018352_01

44 AWC

44 AWC

44 AWC

Updating Actual Minutes on CIMI_RWM_01018384_01

Updating Actual Minutes on CIMI_RWM_01018385_01

Package Manually Completed by jm8245.

Package Manually Completed by jm8245.

Updating Actual Minutes on CIMI_RWM_01018393_01

Package Manually Completed by jm8245.

Updating Actual Minutes on CIMI_RWM_01018395_01

Package Manually Completed by jm8245.

Package Manually Completed by jm8245.

Updating Actual Minutes on CIMI_RWM_01018405_01

44 AWC

Package Manually Completed by jm8245.

Updating Actual Minutes on CIMI_RWM_01018424_01

Updating Actual Minutes on CIMI_RWM_01018428_01

All Wire/Work Jobs have Completed, Package now in Complete status.

Updating Actual Minutes on CIMI_RWM_01018430_01

Package Manually Completed by jm8245.

Updating Actual Minutes on CIMI_RWM_01018440_01

Updating Actual Minutes on CIMI_RWM_01018449_01

44 AWC

Updating Actual Minutes on CIMI_RWM_01018456_01

Package Manually Completed by jm8245.

44 AWC

Package Manually Completed by jm8245.

44 AWC

44 AWC

44 AWC

Package Manually Completed by jm8245.

44 AWC

Package Manually Completed by jm8245.

Package Manually Completed by jm8245.

Updating Actual Minutes on CIMI_RWM_01018488_01

44 AWC

44 AWC

44 AWC

44 AWC

All Wire/Work Jobs have Completed, Package now in Complete status.

All Wire/Work Jobs have Completed, Package now in Complete status.

44 AWC

44 AWC

Updating Actual Minutes on CIMI_RWM_01018517_01

Updating Actual Minutes on CIMI_RWM_01018518_01

Package Manually Completed by jm8245.

44 AWC

Package Manually Completed by jm8245.

Updating Actual Minutes on CIMI_RWM_01018522_01

Updating Actual Minutes on CIMI_CRD28240412C01

All Wire/Work Jobs have Completed, Package now in Complete status.

Package Manually Completed by jm8245.

Updating Actual Minutes on CIMI_RWM_01018540_01

44 AWC

Package Manually Completed by jm8245.

Package Manually Completed by jm8245.

44 AWC

44 AWC

Package Manually Completed by jm8245.

Package Manually Completed by jm8245.

44 WAC

Updating Actual Minutes on CIMI_CJH49351216C01

AWC

Updating Actual Minutes on CIMI_CAM42681213C01

Updating Actual Minutes on CIMI_RWM_01018557_01

44 AWC

Updating Actual Minutes on CIMI_CJH49351213C01

44 AWC

Package Manually Completed by jm8245.

Updating Actual Minutes on CIMI_RWM_01018564_01

44 AWC

Package Manually Completed by jm8245.

Updating Actual Minutes on CIMI_RWM_01018568_01

Updating Actual Minutes on CIMI_RWM_01018570_01

Updating Actual Minutes on CIMI_CCT48721213C01

44 AWC

Package Manually Completed by jm8245.

44 AWC

Package Manually Completed by jm8245.

Updating Actual Minutes on CIMI_RWM_01018582_01

44 AWC

Updating Actual Minutes on CIMI_RWM_01018595_01

Updating Actual Minutes on CIMI_RWM_01018596_01

Updating Actual Minutes on CIMI_RWM_01018597_01

44 AWC

Updating Actual Minutes on CIMI_RWM_01018599_01

Package Manually Completed by jm8245.

Package Manually Completed by jm8245.

Updating Actual Minutes on CIMI_CJM98561031C01

44 AWC

Package Manually Completed by jm8245.

Updating Actual Minutes on CIMI_RWM_01018605_01

Package Manually Completed by jm8245.

Updating Actual Minutes on CIMI_RWM_01018607_01

Package Manually Completed by jm8245.

Package Manually Completed by jm8245.

Package Manually Completed by jm8245.

all work complete

Package Manually Completed by jm8245.

Package Manually Completed by jm8245.

Updating Actual Minutes on CIMI_CJH49351028C01

Updating Actual Minutes on CIMI_RWM_01018616_01

Updating Actual Minutes on CIMI_CCT48721027C01

Package Manually Completed by jm8245.

Updating Actual Minutes on CIMI_RWM_01018619_01

Updating Actual Minutes on CIMI_CCT48721028C01

Package Manually Completed by jm8245.

Package Manually Completed by jm8245.

Updating Actual Minutes on CIMI_RWM_01018623_01

Updating Actual Minutes on CIMI_RWM_01018624_01

Updating Actual Minutes on CIMI_CJM98561027C01

Package Manually Completed by jm8245.

Updating Actual Minutes on CIMI_CRD28241027C01

Updating Actual Minutes on CIMI_RWM_01019940_01

Updating Actual Minutes on CIMI_RWM_01019941_01

Updating Actual Minutes on CIMI_RWM_01019942_01

Updating Actual Minutes on CIMI_RWM_01019943_01

Updating Actual Minutes on CIMI_RWM_01019944_01

Updating Actual Minutes on CIMI_RWM_01019945_01

Updating Actual Minutes on CIMI_RWM_01019949_01

Updating Actual Minutes on CIMI_RWM_01019951_01

Updating Actual Minutes on CIMI_RWM_01019952_01

Updating Actual Minutes on CIMI_RWM_01019953_01

Updating Actual Minutes on CIMI_RWM_01019954_01

Updating Actual Minutes on CIMI_RWM_01019968_01

Package Manually Completed by jq1534.

Package Manually Completed by jq1534.

joint pole transfer job will clear infraction intent #120239659

Package Manually Completed by jq1534.

placed guy guard

Package Manually Completed by jq1534.

inspected all work complete

Updating Actual Minutes on CIMI_RWM_01019995_01

Updating Actual Minutes on CIMI_RWM_01019996_01

Updating Actual Minutes on CIMI_RWM_01019997_01

Updating Actual Minutes on CIMI_RWM_01019998_01

Updating Actual Minutes on CIMI_RWM_01019999_01

Updating Actual Minutes on CIMI_RWM_01020000_01

inspected all work complete

All Wire/Work Jobs have Completed, Package now in Complete status.

place guy guard

self support cable that is burnt not broken lashing wire

Updating Actual Minutes on CIMI_RWM_01020668_01

Package Manually Completed by mg2419.

All Wire/Work Jobs have Completed, Package now in Complete status.

All Wire/Work Jobs have Completed, Package now in Complete status.

Updating Actual Minutes on CIMI_RWM_01020677_01

Updating Actual Minutes on CIMI_RWM_01020678_01

All Wire/Work Jobs have Completed, Package now in Complete status.

All Wire/Work Jobs have Completed, Package now in Complete status.

Updating Actual Minutes on CIMI_RWM_01020689_01

Updating Actual Minutes on CIMI_RWM_01020690_01

PG&E down guy and cable TV strand.

Updating Actual Minutes on CIMI_RWM_01020693_01

Package Manually Completed by mg2419.

All Wire/Work Jobs have Completed, Package now in Complete status.

Updating Actual Minutes on CIMI_RWM_01020702_01

All Wire/Work Jobs have Completed, Package now in Complete status.

Updating Actual Minutes on CIMI_RWM_01020708_01

Updating Actual Minutes on CIMI_RWM_01020747_01

All Wire/Work Jobs have Completed, Package now in Complete status.

All Wire/Work Jobs have Completed, Package now in Complete status.

All Wire/Work Jobs have Completed, Package now in Complete status.

Updating Actual Minutes on CIMI_RWM_01020763_01

All Wire/Work Jobs have Completed, Package now in Complete status.

Updating Actual Minutes on CIMI_RWM_01020772_01

Updating Actual Minutes on CIMI_RWM_01020773_01

Updating Actual Minutes on CIMI_RWM_01020774_01

Phone lines are lower than 72 inches from secondary power.

Package Manually Completed by mg2419.

RIP CABLE NO FACTOR

Updating Actual Minutes on CIMI_RWM_01020782_01

Updating Actual Minutes on CIMI_RWM_01020783_01

Updating Actual Minutes on CIMI_RWM_01020787_01

Updating Actual Minutes on CIMI_RWM_01020832_01

All Wire/Work Jobs have Completed, Package now in Complete status.

Updating Actual Minutes on CIMI_RWM_01020835_01

Updating Actual Minutes on CIMI_RWM_01020836_01

Package Manually Completed by jq1534.

not a hazard anchor rod not pulling out of ground

Place down guy marker.

All Wire/Work Jobs have Completed, Package now in Complete status.

All Wire/Work Jobs have Completed, Package now in Complete status.

All Wire/Work Jobs have Completed, Package now in Complete status.

Updating Actual Minutes on CIMI_RWM_01020850_01

Updating Actual Minutes on CIMI_RWM_01020854_01

Updating Actual Minutes on CIMI_RWM_01020855_01

Updating Actual Minutes on CIMI_RWM_01020856_01

Updating Actual Minutes on CIMI_RWM_01020858_01

Updating Actual Minutes on CIMI_RWM_01020859_01

Updating Actual Minutes on CIMI_RWM_01020860_01

Updating Actual Minutes on CIMI_RWM_01020862_01

Package Manually Completed by jq1534.

I&M splice bag/case on strand not a hazard or violation

All Wire/Work Jobs have Completed, Package now in Complete status.

Updating Actual Minutes on CIMI_RWM_01020914_01

All Wire/Work Jobs have Completed, Package now in Complete status.

All Wire/Work Jobs have Completed, Package now in Complete status.

Updating Actual Minutes on CIMI_RWM_01020923_01

Updating Actual Minutes on CIMI_RWM_01020925_01

Updating Actual Minutes on CIMI_RWM_01020926_01

Updating Actual Minutes on CIMI_RWM_01020927_01

Updating Actual Minutes on CIMI_RWM_01020928_01

Updating Actual Minutes on CIMI_RWM_01020929_01

Updating Actual Minutes on CIMI_RWM_01020930_01

Updating Actual Minutes on CIMI_RWM_01020931_01

Updating Actual Minutes on CIMI_RWM_01020942_01

Updating Actual Minutes on CIMI_RWM_01020992_01

Updating Actual Minutes on CIMI_RWM_01020994_01

Updating Actual Minutes on CIMI_RWM_01020995_01

Updating Actual Minutes on CIMI_RWM_01020996_01

I&M bag on cable

Updating Actual Minutes on CIMI_RWM_01021001_01

Updating Actual Minutes on CIMI_RWM_01021002_01

Updating Actual Minutes on CIMI_RWM_01021003_01

Updating Actual Minutes on CIMI_RWM_01021007_01

44L AWC NO FACTOR

Updating Actual Minutes on CIMI_RWM_01021011_01

Updating Actual Minutes on CIMI_RWM_01021012_01

Updating Actual Minutes on CIMI_RWM_01021014_01

Place new down guy

Updating Actual Minutes on CIMI_RWM_01021034_01

Package Manually Completed by mg2419.

Updating Actual Minutes on CIMI_RWM_01021042_01

All Wire/Work Jobs have Completed, Package now in Complete status.

All Wire/Work Jobs have Completed, Package now in Complete status.

All Wire/Work Jobs have Completed, Package now in Complete status.

Updating Actual Minutes on CIMI_RWM_01021050_01

Updating Actual Minutes on CIMI_RWM_01021051_01

Updating Actual Minutes on CIMI_RWM_01021052_01

Updating Actual Minutes on CIMI_RWM_01021054_01

Updating Actual Minutes on CIMI_RWM_01021055_01

Updating Actual Minutes on CIMI_RWM_01021056_01

Power replaced pole and raised power

Updating Actual Minutes on CIMI_RWM_01021059_01

All Wire/Work Jobs have Completed, Package now in Complete status.

Updating Actual Minutes on CIMI_RWM_01021061_01

All Wire/Work Jobs have Completed, Package now in Complete status.

Updating Actual Minutes on CIMI_RWM_01021074_01

Updating Actual Minutes on CIMI_RWM_01021075_01

Updating Actual Minutes on CIMI_RWM_01021077_01

Updating Actual Minutes on CIMI_RWM_01021078_01

Updating Actual Minutes on CIMI_RWM_01021079_01

Updating Actual Minutes on CIMI_RWM_01021080_01

All Wire/Work Jobs have Completed, Package now in Complete status.

Updating Actual Minutes on CIMI_RWM_01021101_01

All Wire/Work Jobs have Completed, Package now in Complete status.

All Wire/Work Jobs have Completed, Package now in Complete status.

Updating Actual Minutes on CIMI_RWM_01021121_01

Updating Actual Minutes on CIMI_RWM_01021125_01

Updating Actual Minutes on CIMI_RWM_01021130_01

Updating Actual Minutes on CIMI_RWM_01021131_01

All Wire/Work Jobs have Completed, Package now in Complete status.

Updating Actual Minutes on CIMI_RWM_01021135_01

Updating Actual Minutes on CIMI_RWM_01021136_01

Updating Actual Minutes on CIMI_RWM_01021137_01

Updating Actual Minutes on CIMI_RWM_01021141_01

Updating Actual Minutes on CIMI_RWM_01021142_01

Updating Actual Minutes on CIMI_RWM_01021143_01

Updating Actual Minutes on CIMI_RWM_01021145_01

Updating Actual Minutes on CIMI_RWM_01021182_01

Package Manually Completed by mg2419.

Updating Actual Minutes on CIMI_RWM_01021184_01

Updating Actual Minutes on CIMI_RWM_01021186_01

Updating Actual Minutes on CIMI_RWM_01021187_01

Updating Actual Minutes on CIMI_RWM_01021188_01

Updating Actual Minutes on CIMI_RWM_01021189_01

Updating Actual Minutes on CIMI_RWM_01021191_01

Updating Actual Minutes on CIMI_RWM_01021192_01

Updating Actual Minutes on CIMI_RWM_01021193_01

Updating Actual Minutes on CIMI_RWM_01021194_01

All Wire/Work Jobs have Completed, Package now in Complete status.

Updating Actual Minutes on CIMI_RWM_01021197_01

All Wire/Work Jobs have Completed, Package now in Complete status.

Updating Actual Minutes on CIMI_RWM_01021210_01

All Wire/Work Jobs have Completed, Package now in Complete status.

All Wire/Work Jobs have Completed, Package now in Complete status.

Updating Actual Minutes on CIMI_RWM_01021213_01

All Wire/Work Jobs have Completed, Package now in Complete status.

Updating Actual Minutes on CIMI_RWM_01021215_01

Package Manually Completed by jq1534.

Package Manually Completed by jq1534.

Package Manually Completed by jq1534.

Package Manually Completed by jq1534.

Package Manually Completed by jq1534.

Package Manually Completed by jq1534.

place gravel in pole hole

place gravel in pole hole

Updating Actual Minutes on CIMI_RWM_01021247_01

Package Manually Completed by jq1534.

All Wire/Work Jobs have Completed, Package now in Complete status.

Updating Actual Minutes on CIMI_RWM_01021251_01

Updating Actual Minutes on CIMI_RWM_01021253_01

All Wire/Work Jobs have Completed, Package now in Complete status.

Updating Actual Minutes on CIMI_RWM_01021255_01

Updating Actual Minutes on CIMI_RWM_01021256_01

Updating Actual Minutes on CIMI_RWM_01021257_01

Updating Actual Minutes on CIMI_RWM_01021258_01

Updating Actual Minutes on CIMI_RWM_01021259_01

All Wire/Work Jobs have Completed, Package now in Complete status.

Package Manually Completed by mg2419.

Updating Actual Minutes on CIMI_RWM_01021265_01

All Wire/Work Jobs have Completed, Package now in Complete status.

Updating Actual Minutes on CIMI_RWM_01021268_01

Updating Actual Minutes on CIMI_RWM_01021271_01

All Wire/Work Jobs have Completed, Package now in Complete status.

Place new down guy

Updating Actual Minutes on CIMI_RWM_01021274_01

Updating Actual Minutes on CIMI_RWM_01021276_01

Updating Actual Minutes on CIMI_RWM_01021277_01

Updating Actual Minutes on CIMI_RWM_01021280_01

Updating Actual Minutes on CIMI_RWM_01021281_01

Updating Actual Minutes on CIMI_RWM_01021282_01

Updating Actual Minutes on CIMI_RWM_01023858_01

awc 44 labor

Updating Actual Minutes on CIMI_RWM_01031638_01

Updating Actual Minutes on CIMI_RWM_01050498_01

Updating Actual Minutes on CIMI_RWM_01050500_01

Updating Actual Minutes on CIMI_RWM_01050501_01

Updating Actual Minutes on CIMI_RWM_01050505_01

Updating Actual Minutes on CIMI_RWM_01050506_01

Updating Actual Minutes on CIMI_RWM_01050507_01

Updating Actual Minutes on CIMI_RWM_01050508_01

Updating Actual Minutes on CIMI_RWM_01050509_01

Updating Actual Minutes on CIMI_RWM_01050510_01

Updating Actual Minutes on CIMI_RWM_01050511_01

Updating Actual Minutes on CIMI_RWM_01050514_01

Updating Actual Minutes on CIMI_RWM_01050515_01

Updating Actual Minutes on CIMI_RWM_01050520_01

Updating Actual Minutes on CIMI_RWM_01050523_01

Updating Actual Minutes on CIMI_RWM_01050525_01

Updating Actual Minutes on CIMI_RWM_01050538_01

Package Manually Completed by mg2419.

Updating Actual Minutes on CIMI_RWM_01050542_01

Updating Actual Minutes on CIMI_RWM_01050547_01

Updating Actual Minutes on CIMI_RWM_01050549_01

Job has been completd

Updating Actual Minutes on CIMI_RWM_01050560_01

Updating Actual Minutes on CIMI_RWM_01050561_01

Updating Actual Minutes on CIMI_RWM_01050562_01

Updating Actual Minutes on CIMI_RWM_01050563_01

Updating Actual Minutes on CIMI_RWM_01050567_01

Updating Actual Minutes on CIMI_RWM_01050570_01

Updating Actual Minutes on CIMI_RWM_01050574_01

Updating Actual Minutes on CIMI_RWM_01050575_01

Updating Actual Minutes on CIMI_RWM_01050577_01

Updating Actual Minutes on CIMI_RWM_01050578_01

Updating Actual Minutes on CIMI_RWM_01050579_01

Updating Actual Minutes on CIMI_RWM_01050581_01

Updating Actual Minutes on CIMI_RWM_01050582_01

Updating Actual Minutes on CIMI_RWM_01050583_01

Updating Actual Minutes on CIMI_RWM_01050584_01

Updating Actual Minutes on CIMI_RWM_01050586_01

Updating Actual Minutes on CIMI_RWM_01050587_01

44L AWC

Updating Actual Minutes on CIMI_RWM_01050595_01

Updating Actual Minutes on CIMI_RWM_01050596_01

Address is incorrect. Pole pictured has minimal lean

Updating Actual Minutes on CIMI_RWM_01050619_01

Updating Actual Minutes on CIMI_RWM_01050627_01

Updating Actual Minutes on CIMI_RWM_01050628_01

Updating Actual Minutes on CIMI_RWM_01050630_01

Updating Actual Minutes on CIMI_RWM_01050632_01

Updating Actual Minutes on CIMI_RWM_01050633_01

Updating Actual Minutes on CIMI_RWM_01050634_01

Updating Actual Minutes on CIMI_RWM_01050635_01

Updating Actual Minutes on CIMI_RWM_01050636_01

Updating Actual Minutes on CIMI_RWM_01050638_01

Updating Actual Minutes on CIMI_RWM_01050639_01

Updating Actual Minutes on CIMI_RWM_01050640_01

Updating Actual Minutes on CIMI_RWM_01050642_01

Updating Actual Minutes on CIMI_RWM_01050643_01

Updating Actual Minutes on CIMI_RWM_01050646_01

Updating Actual Minutes on CIMI_RWM_01050650_01

Updating Actual Minutes on CIMI_RWM_01050653_01

Updating Actual Minutes on CIMI_RWM_01050654_01

Updating Actual Minutes on CIMI_RWM_01050657_01

Updating Actual Minutes on CIMI_RWM_01050658_01

pge span guy

Updating Actual Minutes on CIMI_RWM_01050662_01

Updating Actual Minutes on CIMI_RWM_01050666_01

Updating Actual Minutes on CIMI_RWM_01050669_01

Updating Actual Minutes on CIMI_RWM_01050670_01

Updating Actual Minutes on CIMI_RWM_01050673_01

Updating Actual Minutes on CIMI_RWM_01050675_01

Updating Actual Minutes on CIMI_RWM_01050679_01

Updating Actual Minutes on CIMI_RWM_01050686_01

Updating Actual Minutes on CIMI_RWM_01050687_01

Updating Actual Minutes on CIMI_RWM_01050690_01

Updating Actual Minutes on CIMI_RWM_01050692_01

Updating Actual Minutes on CIMI_RWM_01050713_01

Updating Actual Minutes on CIMI_RWM_01050722_01

Updating Actual Minutes on CIMI_RWM_01050726_01

Updating Actual Minutes on CIMI_RWM_01050728_01

Updating Actual Minutes on CIMI_RWM_01050732_01

Updating Actual Minutes on CIMI_RWM_01050737_01

Updating Actual Minutes on CIMI_RWM_01050739_01

Updating Actual Minutes on CIMI_RWM_01050740_01

Updating Actual Minutes on CIMI_RWM_01050741_01

Package Manually Completed by jq1534.

Updating Actual Minutes on CIMI_RWM_01050746_01

Updating Actual Minutes on CIMI_RWM_01050750_01

job will be completed with pole transfer job

Updating Actual Minutes on CIMI_RWM_01050760_01

Updating Actual Minutes on CIMI_RWM_01050761_01

Updating Actual Minutes on CIMI_RWM_01050762_01

Updating Actual Minutes on CIMI_RWM_01050763_01

Updating Actual Minutes on CIMI_RWM_01050764_01

Package Manually Completed by bo128w.

Package Manually Completed by bo128w.

Updating Actual Minutes on CIMI_RWM_01050775_01

Updating Actual Minutes on CIMI_RWM_01050779_01

Updating Actual Minutes on CIMI_RWM_01050781_01

Updating Actual Minutes on CIMI_RWM_01050783_01

Updating Actual Minutes on CIMI_RWM_01050786_01

Updating Actual Minutes on CIMI_RWM_01050787_01

Package Manually Completed by bo128w.

Updating Actual Minutes on CIMI_RWM_01050791_01

Updating Actual Minutes on CIMI_RWM_01050792_01

Updating Actual Minutes on CIMI_RWM_01050793_01

Updating Actual Minutes on CIMI_RWM_01050797_01

Package Manually Completed by bo128w.

Updating Actual Minutes on CIMI_RWM_01050800_01

Updating Actual Minutes on CIMI_RWM_01050801_01

Updating Actual Minutes on CIMI_RWM_01050803_01

Updating Actual Minutes on CIMI_RWM_01050804_01

Updating Actual Minutes on CIMI_RWM_01050808_01

Updating Actual Minutes on CIMI_RWM_01050811_01

Updating Actual Minutes on CIMI_RWM_01050815_01

Updating Actual Minutes on CIMI_RWM_01050816_01

Updating Actual Minutes on CIMI_RWM_01050817_01

Updating Actual Minutes on CIMI_RWM_01050819_01

Updating Actual Minutes on CIMI_RWM_01050826_01

Updating Actual Minutes on CIMI_RWM_01050827_01

Updating Actual Minutes on CIMI_RWM_01050834_01

Updating Actual Minutes on CIMI_RWM_01050836_01

Updating Actual Minutes on CIMI_RWM_01050839_01

Updating Actual Minutes on CIMI_RWM_01050842_01

Package Manually Completed by bo128w.

Updating Actual Minutes on CIMI_RWM_01050850_01

Updating Actual Minutes on CIMI_RWM_01050853_01

Updating Actual Minutes on CIMI_RWM_01050854_01

pge span guy

Updating Actual Minutes on CIMI_RWM_01050866_01

Updating Actual Minutes on CIMI_RWM_01050867_01

Updating Actual Minutes on CIMI_RWM_01050869_01

Updating Actual Minutes on CIMI_RWM_01050873_01

Updating Actual Minutes on CIMI_RWM_01050879_01

Updating Actual Minutes on CIMI_RWM_01050880_01

Updating Actual Minutes on CIMI_RWM_01050885_01

Updating Actual Minutes on CIMI_RWM_01050894_01

Updating Actual Minutes on CIMI_RWM_01050896_01

Package Manually Completed by te7361.

Updating Actual Minutes on CIMI_RWM_01050898_01

Updating Actual Minutes on CIMI_RWM_01050902_01

Package Manually Completed by bo128w.

Updating Actual Minutes on CIMI_RWM_01050904_01

Updating Actual Minutes on CIMI_RWM_01050907_01

Updating Actual Minutes on CIMI_RWM_01050910_01

Updating Actual Minutes on CIMI_RWM_01050912_01

Updating Actual Minutes on CIMI_RWM_01050920_01

Updating Actual Minutes on CIMI_RWM_01050921_01

Updating Actual Minutes on CIMI_RWM_01050923_01

Updating Actual Minutes on CIMI_RWM_01050925_01

Updating Actual Minutes on CIMI_RWM_01050932_01

Updating Actual Minutes on CIMI_RWM_01050939_01

Updating Actual Minutes on CIMI_RWM_01050945_01

Updating Actual Minutes on CIMI_RWM_01050946_01

Updating Actual Minutes on CIMI_RWM_01050949_01

Updating Actual Minutes on CIMI_RWM_01050953_01

Updating Actual Minutes on CIMI_RWM_01050954_01

Updating Actual Minutes on CIMI_RWM_01050955_01

Updating Actual Minutes on CIMI_RWM_01050959_01

Updating Actual Minutes on CIMI_RWM_01050961_01

Updating Actual Minutes on CIMI_RWM_01050966_01

Updating Actual Minutes on CIMI_RWM_01050967_01

44L AWC

Updating Actual Minutes on CIMI_RWM_01050971_01

Updating Actual Minutes on CIMI_RWM_01050973_01

Updating Actual Minutes on CIMI_RWM_01050984_01

Updating Actual Minutes on CIMI_RWM_01050985_01

Updating Actual Minutes on CIMI_RWM_01050986_01

Needs pole transfer.

pge pole and guy

Updating Actual Minutes on CIMI_RWM_01050994_01

Pole has secondary power on it, PGE responsibility

Updating Actual Minutes on CIMI_RWM_01051005_01

Updating Actual Minutes on CIMI_RWM_01051006_01

Updating Actual Minutes on CIMI_RWM_01051008_01

Updating Actual Minutes on CIMI_RWM_01051010_01

Updating Actual Minutes on CIMI_RWM_01051018_01

Package Manually Completed by bo128w.

Updating Actual Minutes on CIMI_RWM_01051023_01

Updating Actual Minutes on CIMI_RWM_01051026_01

Updating Actual Minutes on CIMI_RWM_01051044_01

Updating Actual Minutes on CIMI_RWM_01051045_01

inspected all work complete

All Wire/Work Jobs have Completed, Package now in Complete status.

Updating Actual Minutes on CIMI_RWM_01051059_01

Updating Actual Minutes on CIMI_RWM_01051060_01

Updating Actual Minutes on CIMI_RWM_01051066_01

Updating Actual Minutes on CIMI_RWM_01051067_01

Updating Actual Minutes on CIMI_RWM_01051069_01

All Wire/Work Jobs have Completed, Package now in Complete status.

Package Manually Completed by mg2419.

Updating Actual Minutes on CIMI_RWM_01051076_01

Package Manually Completed by bo128w.

Updating Actual Minutes on CIMI_RWM_01051079_01

Updating Actual Minutes on CIMI_RWM_01051080_01

Updating Actual Minutes on CIMI_RWM_01051085_01

Updating Actual Minutes on CIMI_RWM_01051086_01

Updating Actual Minutes on CIMI_RWM_01051087_01

Updating Actual Minutes on CIMI_RWM_01051093_01

Updating Actual Minutes on CIMI_RWM_01051095_01

Updating Actual Minutes on CIMI_RWM_01051102_01

Updating Actual Minutes on CIMI_RWM_01051105_01

Updating Actual Minutes on CIMI_RWM_01051106_01

Updating Actual Minutes on CIMI_RWM_01051109_01

Updating Actual Minutes on CIMI_RWM_01051110_01

Updating Actual Minutes on CIMI_RWM_01051111_01

Updating Actual Minutes on CIMI_RWM_01051118_01

Updating Actual Minutes on CIMI_RWM_01051120_01

Updating Actual Minutes on CIMI_RWM_01051123_01

Updating Actual Minutes on CIMI_RWM_01051125_01

Updating Actual Minutes on CIMI_RWM_01051130_01

Updating Actual Minutes on CIMI_RWM_01051141_01

Updating Actual Minutes on CIMI_RWM_01051143_01

Updating Actual Minutes on CIMI_RWM_01051151_01

Updating Actual Minutes on CIMI_RWM_01051152_01

Updating Actual Minutes on CIMI_RWM_01051153_01

pg&e pole

Updating Actual Minutes on CIMI_RWM_01051169_01

Updating Actual Minutes on CIMI_RWM_01051170_01

Updating Actual Minutes on CIMI_RWM_01051172_01

Updating Actual Minutes on CIMI_RWM_01051174_01

Updating Actual Minutes on CIMI_RWM_01051175_01

Updating Actual Minutes on CIMI_RWM_01051177_01

Updating Actual Minutes on CIMI_RWM_01051179_01

Package Manually Completed by jq1534.

Updating Actual Minutes on CIMI_RWM_01051183_01

Updating Actual Minutes on CIMI_RWM_01051188_01

Updating Actual Minutes on CIMI_RWM_01051191_01

Updating Actual Minutes on CIMI_RWM_01051192_01

Updating Actual Minutes on CIMI_RWM_01051193_01

Updating Actual Minutes on CIMI_RWM_01051196_01

Updating Actual Minutes on CIMI_RWM_01051199_01

Updating Actual Minutes on CIMI_RWM_01051200_01

Updating Actual Minutes on CIMI_RWM_01051201_01

Updating Actual Minutes on CIMI_RWM_01051203_01

Updating Actual Minutes on CIMI_RWM_01051210_01

Updating Actual Minutes on CIMI_RWM_01051211_01

Updating Actual Minutes on CIMI_RWM_01051213_01

Updating Actual Minutes on CIMI_RWM_01051219_01

Updating Actual Minutes on CIMI_RWM_01051231_01

Updating Actual Minutes on CIMI_RWM_01051233_01

Updating Actual Minutes on CIMI_RWM_01051234_01

Updating Actual Minutes on CIMI_RWM_01051236_01

Updating Actual Minutes on CIMI_RWM_01051237_01

Updating Actual Minutes on CIMI_RWM_01051238_01

Updating Actual Minutes on CIMI_RWM_01051240_01

Updating Actual Minutes on CIMI_RWM_01051242_01

Updating Actual Minutes on CIMI_RWM_01051245_01

Updating Actual Minutes on CIMI_RWM_01051246_01

Updating Actual Minutes on CIMI_RWM_01051247_01

Updating Actual Minutes on CIMI_RWM_01051249_01

Updating Actual Minutes on CIMI_RWM_01051251_01

Updating Actual Minutes on CIMI_RWM_01051252_01

Updating Actual Minutes on CIMI_RWM_01051254_01

Updating Actual Minutes on CIMI_RWM_01051255_01

Updating Actual Minutes on CIMI_RWM_01051257_01

Updating Actual Minutes on CIMI_RWM_01051258_01

Updating Actual Minutes on CIMI_RWM_01051260_01

Package Manually Completed by bo128w.

Updating Actual Minutes on CIMI_RWM_01051265_01

Updating Actual Minutes on CIMI_RWM_01051267_01

Updating Actual Minutes on CIMI_RWM_01051269_01

Updating Actual Minutes on CIMI_RWM_01051275_01

Updating Actual Minutes on CIMI_RWM_01051284_01

Updating Actual Minutes on CIMI_RWM_01051287_01

Updating Actual Minutes on CIMI_RWM_01051288_01

Updating Actual Minutes on CIMI_RWM_01051289_01

Updating Actual Minutes on CIMI_RWM_01051293_01

Package Manually Completed by jq1534.

Updating Actual Minutes on CIMI_RWM_01051296_01

Updating Actual Minutes on CIMI_RWM_01051297_01

Updating Actual Minutes on CIMI_RWM_01051301_01

Updating Actual Minutes on CIMI_RWM_01051310_01

Updating Actual Minutes on CIMI_RWM_01051312_01

06/21/22 Hazard cleared per ja5893

Updating Actual Minutes on CIMI_RWM_01051320_01

Updating Actual Minutes on CIMI_RWM_01051323_01

Updating Actual Minutes on CIMI_RWM_01051326_01

Updating Actual Minutes on CIMI_RWM_01051330_01

Package Manually Completed by jq1534.

Updating Actual Minutes on CIMI_RWM_01051333_01

Updating Actual Minutes on CIMI_RWM_01051334_01

Updating Actual Minutes on CIMI_RWM_01051341_01

Updating Actual Minutes on CIMI_RWM_01051342_01

Updating Actual Minutes on CIMI_RWM_01051344_01

Updating Actual Minutes on CIMI_RWM_01051349_01

Package Manually Completed by bo128w.

having job drawn to replace pole

Package Manually Completed by bo128w.

Updating Actual Minutes on CIMI_RWM_01051359_01

Updating Actual Minutes on CIMI_RWM_01051360_01

expose anchor, place guy guard

Place new hardware

44l unable to locate violation

Updating Actual Minutes on CIMI_RWM_01051368_01

Fixed cut cut loose cable, fixed loose hardware, placed new guy guard.

44l awc

Package Manually Completed by jc268g.

Updating Actual Minutes on CIMI_RWM_01054272_01

Updating Actual Minutes on CIMI_RWM_01054273_01

Updating Actual Minutes on CIMI_RWM_01054275_01

Updating Actual Minutes on CIMI_RWM_01054279_01

Updating Actual Minutes on CIMI_RWM_01054285_01

Updating Actual Minutes on CIMI_RWM_01054286_01

Updating Actual Minutes on CIMI_RWM_01054288_01

Updating Actual Minutes on CIMI_RWM_01054295_01

Updating Actual Minutes on CIMI_RWM_01054299_01

Updating Actual Minutes on CIMI_RWM_01054308_01

Package Manually Completed by bo128w.

Updating Actual Minutes on CIMI_RWM_01054316_01

Updating Actual Minutes on CIMI_RWM_01054317_01

All Wire/Work Jobs have Completed, Package now in Complete status.

Updating Actual Minutes on CIMI_RWM_01054320_01

All Wire/Work Jobs have Completed, Package now in Complete status.

Updating Actual Minutes on CIMI_RWM_01054344_01

Updating Actual Minutes on CIMI_RWM_01054348_01

Updating Actual Minutes on CIMI_RWM_01054349_01

Updating Actual Minutes on CIMI_RWM_01054350_01

Package Manually Completed by bo128w.

All Wire/Work Jobs have Completed, Package now in Complete status.

Updating Actual Minutes on CIMI_RWM_01054353_01

Updating Actual Minutes on CIMI_RWM_01054355_01

Updating Actual Minutes on CIMI_RWM_01054356_01

Updating Actual Minutes on CIMI_RWM_01054361_01

Updating Actual Minutes on CIMI_RWM_01054369_01

Updating Actual Minutes on CIMI_RWM_01054377_01

Updating Actual Minutes on CIMI_RWM_01054378_01

Updating Actual Minutes on CIMI_RWM_01054389_01

All Wire/Work Jobs have Completed, Package now in Complete status.

All Wire/Work Jobs have Completed, Package now in Complete status.

Updating Actual Minutes on CIMI_RWM_01054396_01

Updating Actual Minutes on CIMI_RWM_01054401_01

All Wire/Work Jobs have Completed, Package now in Complete status.

Updating Actual Minutes on CIMI_RWM_01054404_01

Updating Actual Minutes on CIMI_RWM_01054407_01

Updating Actual Minutes on CIMI_RWM_01054421_01

Updating Actual Minutes on CIMI_RWM_01054429_01

Updating Actual Minutes on CIMI_RWM_01054444_01

Updating Actual Minutes on CIMI_RWM_01054445_01

Updating Actual Minutes on CIMI_RWM_01054448_01

Updating Actual Minutes on CIMI_RWM_01054451_01

Updating Actual Minutes on CIMI_RWM_01054453_01

Updating Actual Minutes on CIMI_RWM_01054454_01

Updating Actual Minutes on CIMI_RWM_01054459_01

Updating Actual Minutes on CIMI_RWM_01054460_01

Updating Actual Minutes on CIMI_RWM_01054462_01

Updating Actual Minutes on CIMI_RWM_01054464_01

Updating Actual Minutes on CIMI_RWM_01054465_01

All Wire/Work Jobs have Completed, Package now in Complete status.

Updating Actual Minutes on CIMI_RWM_01054469_01

Updating Actual Minutes on CIMI_RWM_01054470_01

All Wire/Work Jobs have Completed, Package now in Complete status.

Updating Actual Minutes on CIMI_RWM_01054475_01

Updating Actual Minutes on CIMI_RWM_01054476_01

Updating Actual Minutes on CIMI_RWM_01054494_01

Updating Actual Minutes on CIMI_RWM_01054495_01

Updating Actual Minutes on CIMI_RWM_01054497_01

Updating Actual Minutes on CIMI_RWM_01054505_01

Updating Actual Minutes on CIMI_RWM_01054506_01

Updating Actual Minutes on CIMI_RWM_01054508_01

Updating Actual Minutes on CIMI_RWM_01054512_01

Updating Actual Minutes on CIMI_RWM_01054523_01

Updating Actual Minutes on CIMI_RWM_01054524_01

Updating Actual Minutes on CIMI_RWM_01054542_01

Updating Actual Minutes on CIMI_RWM_01054545_01

Updating Actual Minutes on CIMI_RWM_01054552_01

Updating Actual Minutes on CIMI_RWM_01054555_01

Updating Actual Minutes on CIMI_RWM_01054557_01

Updating Actual Minutes on CIMI_RWM_01054559_01

Updating Actual Minutes on CIMI_RWM_01054570_01

Updating Actual Minutes on CIMI_RWM_01054580_01

Updating Actual Minutes on CIMI_RWM_01054581_01

Updating Actual Minutes on CIMI_RWM_01054591_01

Updating Actual Minutes on CIMI_RWM_01054595_01

Updating Actual Minutes on CIMI_RWM_01054597_01

Updating Actual Minutes on CIMI_RWM_01054599_01

Updating Actual Minutes on CIMI_RWM_01054603_01

Updating Actual Minutes on CIMI_RWM_01054615_01

Updating Actual Minutes on CIMI_RWM_01054620_01

Updating Actual Minutes on CIMI_RWM_01054626_01

Updating Actual Minutes on CIMI_RWM_01054627_01

Updating Actual Minutes on CIMI_RWM_01054630_01

Updating Actual Minutes on CIMI_RWM_01054631_01

Updating Actual Minutes on CIMI_RWM_01054633_01

Updating Actual Minutes on CIMI_RWM_01054635_01

Updating Actual Minutes on CIMI_RWM_01054636_01

Updating Actual Minutes on CIMI_RWM_01054637_01

Updating Actual Minutes on CIMI_RWM_01054639_01

Complete per JA5893

Place guy guard

Updating Actual Minutes on CIMI_RWM_01054660_01

Updating Actual Minutes on CIMI_RWM_01054667_01

Updating Actual Minutes on CIMI_RWM_01054683_01

Updating Actual Minutes on CIMI_RWM_01054695_01

Updating Actual Minutes on CIMI_RWM_01054699_01

Updating Actual Minutes on CIMI_RWM_01054700_01

Updating Actual Minutes on CIMI_RWM_01054701_01

Package Manually Completed by jq1534.

Updating Actual Minutes on CIMI_RWM_01054710_01

Updating Actual Minutes on CIMI_RWM_01054712_01

Updating Actual Minutes on CIMI_RWM_01054713_01

Updating Actual Minutes on CIMI_RWM_01054724_01

Updating Actual Minutes on CIMI_RWM_01054727_01

All Wire/Work Jobs have Completed, Package now in Complete status.

Updating Actual Minutes on CIMI_RWM_01054740_01

Updating Actual Minutes on CIMI_RWM_01054743_01

Updating Actual Minutes on CIMI_RWM_01054748_01

Updating Actual Minutes on CIMI_RWM_01054762_01

Updating Actual Minutes on CIMI_RWM_01054764_01

Updating Actual Minutes on CIMI_RWM_01054768_01

Updating Actual Minutes on CIMI_RWM_01054769_01

Updating Actual Minutes on CIMI_RWM_01054770_01

Updating Actual Minutes on CIMI_RWM_01054771_01

Updating Actual Minutes on CIMI_RWM_01054776_01

Updating Actual Minutes on CIMI_RWM_01054780_01

Updating Actual Minutes on CIMI_RWM_01054784_01

Updating Actual Minutes on CIMI_RWM_01054787_01

Updating Actual Minutes on CIMI_RWM_01054791_01

Updating Actual Minutes on CIMI_RWM_01054794_01

Updating Actual Minutes on CIMI_RWM_01054796_01

Updating Actual Minutes on CIMI_RWM_01054801_01

Updating Actual Minutes on CIMI_RWM_01054803_01

Updating Actual Minutes on CIMI_RWM_01054804_01

All Wire/Work Jobs have Completed, Package now in Complete status.

Updating Actual Minutes on CIMI_RWM_01054812_01

Updating Actual Minutes on CIMI_RWM_01054816_01

Updating Actual Minutes on CIMI_RWM_01054817_01

All Wire/Work Jobs have Completed, Package now in Complete status.

Updating Actual Minutes on CIMI_RWM_01054821_01

Package Manually Completed by te7361.

Updating Actual Minutes on CIMI_RWM_01054827_01

Updating Actual Minutes on CIMI_RWM_01054831_01

Updating Actual Minutes on CIMI_RWM_01054834_01

Updating Actual Minutes on CIMI_RWM_01054844_01

Updating Actual Minutes on CIMI_RWM_01054851_01

Updating Actual Minutes on CIMI_RWM_01054868_01

Updating Actual Minutes on CIMI_RWM_01054870_01

Updating Actual Minutes on CIMI_RWM_01054873_01

Updating Actual Minutes on CIMI_RWM_01054875_01

Updating Actual Minutes on CIMI_RWM_01054876_01

Updating Actual Minutes on CIMI_RWM_01054883_01

Updating Actual Minutes on CIMI_RWM_01054884_01

Updating Actual Minutes on CIMI_RWM_01054893_01

Updating Actual Minutes on CIMI_RWM_01054894_01

Updating Actual Minutes on CIMI_RWM_01054899_01

AWC 46L

Updating Actual Minutes on CIMI_RWM_01054928_01

Updating Actual Minutes on CIMI_RWM_01054939_01

Updating Actual Minutes on CIMI_RWM_01054944_01

Updating Actual Minutes on CIMI_RWM_01054948_01

Updating Actual Minutes on CIMI_RWM_01054965_01

Updating Actual Minutes on CIMI_RWM_01054969_01

Package Manually Completed by te7361.

Updating Actual Minutes on CIMI_RWM_01054979_01

All Wire/Work Jobs have Completed, Package now in Complete status.

Updating Actual Minutes on CIMI_RWM_01054982_01

Updating Actual Minutes on CIMI_RWM_01054983_01

Updating Actual Minutes on CIMI_RWM_01054984_01

Updating Actual Minutes on CIMI_RWM_01054986_01

Updating Actual Minutes on CIMI_RWM_01054987_01

Updating Actual Minutes on CIMI_RWM_01054988_01

Updating Actual Minutes on CIMI_RWM_01054989_01

Updating Actual Minutes on CIMI_RWM_01054990_01

Updating Actual Minutes on CIMI_RWM_01054991_01

Updating Actual Minutes on CIMI_RWM_01054996_01

Updating Actual Minutes on CIMI_RWM_01055003_01

Updating Actual Minutes on CIMI_RWM_01055004_01

Updating Actual Minutes on CIMI_RWM_01055007_01

Updating Actual Minutes on CIMI_RWM_01055008_01

Updating Actual Minutes on CIMI_RWM_01055010_01

Updating Actual Minutes on CIMI_RWM_01055039_01

Updating Actual Minutes on CIMI_RWM_01055041_01

Updating Actual Minutes on CIMI_RWM_01055044_01

Updating Actual Minutes on CIMI_RWM_01055045_01

Updating Actual Minutes on CIMI_RWM_01055046_01

Updating Actual Minutes on CIMI_RWM_01055048_01

Updating Actual Minutes on CIMI_RWM_01055049_01

Updating Actual Minutes on CIMI_RWM_01055050_01

Updating Actual Minutes on CIMI_RWM_01055052_01

Updating Actual Minutes on CIMI_RWM_01055054_01

Updating Actual Minutes on CIMI_RWM_01055068_01

Updating Actual Minutes on CIMI_RWM_01055078_01

Updating Actual Minutes on CIMI_RWM_01055081_01

Updating Actual Minutes on CIMI_RWM_01055082_01

Updating Actual Minutes on CIMI_RWM_01055083_01

Updating Actual Minutes on CIMI_RWM_01055085_01

Updating Actual Minutes on CIMI_RWM_01055089_01

Updating Actual Minutes on CIMI_RWM_01055095_01

Updating Actual Minutes on CIMI_RWM_01055096_01

Updating Actual Minutes on CIMI_RWM_01055098_01

Updating Actual Minutes on CIMI_RWM_01055099_01

Package Manually Completed by bo128w.

Updating Actual Minutes on CIMI_RWM_01055102_01

Updating Actual Minutes on CIMI_RWM_01055103_01

Updating Actual Minutes on CIMI_RWM_01055105_01

Updating Actual Minutes on CIMI_RWM_01055106_01

All Wire/Work Jobs have Completed, Package now in Complete status.

Updating Actual Minutes on CIMI_RWM_01055112_01

Updating Actual Minutes on CIMI_RWM_01055114_01

Updating Actual Minutes on CIMI_RWM_01055123_01

Updating Actual Minutes on CIMI_RWM_01055130_01

Package Manually Completed by te7361.

Updating Actual Minutes on CIMI_RWM_01055136_01

Lash cable, completed

Updating Actual Minutes on CIMI_RWM_01055142_01

Updating Actual Minutes on CIMI_RWM_01055144_01

Updating Actual Minutes on CIMI_RWM_01055162_01

Updating Actual Minutes on CIMI_RWM_01055165_01

Updating Actual Minutes on CIMI_RWM_01055167_01

Updating Actual Minutes on CIMI_RWM_01055171_01

Updating Actual Minutes on CIMI_RWM_01055172_01

Updating Actual Minutes on CIMI_RWM_01055177_01

Updating Actual Minutes on CIMI_RWM_01055180_01

Updating Actual Minutes on CIMI_RWM_01055186_01

Updating Actual Minutes on CIMI_RWM_01055187_01

Updating Actual Minutes on CIMI_RWM_01055188_01

Updating Actual Minutes on CIMI_RWM_01055191_01

Updating Actual Minutes on CIMI_RWM_01055193_01

Updating Actual Minutes on CIMI_RWM_01055200_01

Updating Actual Minutes on CIMI_RWM_01055208_01

Updating Actual Minutes on CIMI_RWM_01055218_01

Updating Actual Minutes on CIMI_RWM_01055222_01

cable TV lashing wire

Updating Actual Minutes on CIMI_RWM_01055226_01

Updating Actual Minutes on CIMI_RWM_01055228_01

Updating Actual Minutes on CIMI_RWM_01055233_01

Updating Actual Minutes on CIMI_RWM_01055238_01

Updating Actual Minutes on CIMI_RWM_01055239_01

Updating Actual Minutes on CIMI_RWM_01055241_01

Updating Actual Minutes on CIMI_RWM_01055243_01

Updating Actual Minutes on CIMI_RWM_01055245_01

Updating Actual Minutes on CIMI_RWM_01055254_01

Updating Actual Minutes on CIMI_RWM_01055271_01

Updating Actual Minutes on CIMI_RWM_01055277_01

Updating Actual Minutes on CIMI_RWM_01055280_01

Updating Actual Minutes on CIMI_RWM_01055282_01

Updating Actual Minutes on CIMI_RWM_01055285_01

Updating Actual Minutes on CIMI_RWM_01055294_01

Updating Actual Minutes on CIMI_RWM_01055297_01

Updating Actual Minutes on CIMI_RWM_01055299_01

Updating Actual Minutes on CIMI_RWM_01055303_01

Updating Actual Minutes on CIMI_RWM_01055309_01

Updating Actual Minutes on CIMI_RWM_01055310_01

Updating Actual Minutes on CIMI_RWM_01055311_01

Updating Actual Minutes on CIMI_RWM_01055316_01

Updating Actual Minutes on CIMI_RWM_01055317_01

Updating Actual Minutes on CIMI_RWM_01055318_01

All Wire/Work Jobs have Completed, Package now in Complete status.

Package Manually Completed by bo128w.

Updating Actual Minutes on CIMI_RWM_01055326_01

Place guy guard, expose 6 in of anchor

Updating Actual Minutes on CIMI_RWM_01095568_01

Updating Actual Minutes on CIMI_RWM_01101693_01

Updating Actual Minutes on CIMI_RWM_01101695_01

Updating Actual Minutes on CIMI_RWM_01101698_01

Updating Actual Minutes on CIMI_RWM_01101702_01

Updating Actual Minutes on CIMI_RWM_01101712_01

Updating Actual Minutes on CIMI_RWM_01101713_01

Updating Actual Minutes on CIMI_RWM_01101720_01

Updating Actual Minutes on CIMI_RWM_01101721_01

Updating Actual Minutes on CIMI_RWM_01101723_01

Updating Actual Minutes on CIMI_RWM_01101724_01

Updating Actual Minutes on CIMI_RWM_01101725_01

Updating Actual Minutes on CIMI_RWM_01101726_01

Updating Actual Minutes on CIMI_RWM_01101728_01

Updating Actual Minutes on CIMI_RWM_01101734_01

Updating Actual Minutes on CIMI_RWM_01101735_01

Package Manually Completed by jq1534.

Updating Actual Minutes on CIMI_RWM_01101747_01

Updating Actual Minutes on CIMI_RWM_01101748_01

Updating Actual Minutes on CIMI_RWM_01101749_01

Updating Actual Minutes on CIMI_RWM_01101764_01

Updating Actual Minutes on CIMI_RWM_01101775_01

Updating Actual Minutes on CIMI_RWM_01101777_01

Updating Actual Minutes on CIMI_RWM_01101778_01

Updating Actual Minutes on CIMI_RWM_01101786_01

Updating Actual Minutes on CIMI_RWM_01101791_01

Updating Actual Minutes on CIMI_RWM_01101795_01

Package Manually Completed by jq1534.

Updating Actual Minutes on CIMI_RWM_01101813_01

Package Manually Completed by bo128w.

Package Manually Completed by jq1534.

Updating Actual Minutes on CIMI_RWM_01101822_01

Updating Actual Minutes on CIMI_RWM_01101829_01

Updating Actual Minutes on CIMI_RWM_01101830_01

Updating Actual Minutes on CIMI_RWM_01101833_01

Updating Actual Minutes on CIMI_RWM_01101838_01

Updating Actual Minutes on CIMI_RWM_01101852_01

anchor is not pulling

Updating Actual Minutes on CIMI_RWM_01101859_01

Updating Actual Minutes on CIMI_RWM_01101860_01

Updating Actual Minutes on CIMI_RWM_01101863_01

Place riser cover guard.

Place guy guard.

Package Manually Completed by bo128w.

Updating Actual Minutes on CIMI_RWM_01101871_01

Updating Actual Minutes on CIMI_RWM_01101876_01

Package Manually Completed by bo128w.

Updating Actual Minutes on CIMI_RWM_01101879_01

steps removed

Package Manually Completed by bo128w.

Package Manually Completed by bo128w.

Package Manually Completed by bo128w.

Updating Actual Minutes on CIMI_RWM_01101888_01

Updating Actual Minutes on CIMI_RWM_01101893_01

Updating Actual Minutes on CIMI_RWM_01101894_01

Package Manually Completed by bo128w.

Updating Actual Minutes on CIMI_RWM_01101899_01

Updating Actual Minutes on CIMI_RWM_01101908_01

Updating Actual Minutes on CIMI_RWM_01101911_01

Updating Actual Minutes on CIMI_RWM_01101915_01

Updating Actual Minutes on CIMI_RWM_01101920_01

Updating Actual Minutes on CIMI_RWM_01101926_01

AWC

Updating Actual Minutes on CIMI_RWM_01101940_01

Updating Actual Minutes on CIMI_RWM_01101946_01

Updating Actual Minutes on CIMI_RWM_01101949_01

CTV infraction

Updating Actual Minutes on CIMI_RWM_01101957_01

Updating Actual Minutes on CIMI_RWM_01101958_01

Updating Actual Minutes on CIMI_RWM_01101959_01

Updating Actual Minutes on CIMI_RWM_01101961_01

Updating Actual Minutes on CIMI_RWM_01101965_01

Updating Actual Minutes on CIMI_RWM_01101970_01

Updating Actual Minutes on CIMI_RWM_01101976_01

Updating Actual Minutes on CIMI_RWM_01101978_01

Package Manually Completed by jq1534.

PGE down guy span

Updating Actual Minutes on CIMI_RWM_01101989_01

Updating Actual Minutes on CIMI_RWM_01102000_01

Updating Actual Minutes on CIMI_RWM_01102002_01

Updating Actual Minutes on CIMI_RWM_01102004_01

Updating Actual Minutes on CIMI_RWM_01102008_01

Updating Actual Minutes on CIMI_RWM_01102009_01

Updating Actual Minutes on CIMI_RWM_01102010_01

Updating Actual Minutes on CIMI_RWM_01102014_01

Updating Actual Minutes on CIMI_RWM_01102021_01

Updating Actual Minutes on CIMI_RWM_01102023_01

Updating Actual Minutes on CIMI_RWM_01102031_01

Updating Actual Minutes on CIMI_RWM_01102032_01

Updating Actual Minutes on CIMI_RWM_01102036_01

Remove steps below 8 ft.

Updating Actual Minutes on CIMI_RWM_01102046_01

Updating Actual Minutes on CIMI_RWM_01102048_01

Tighten lashing, bug off and secure lashing to strand.

Updating Actual Minutes on CIMI_RWM_01102053_01

Updating Actual Minutes on CIMI_RWM_01102054_01

Updating Actual Minutes on CIMI_RWM_01102055_01

Updating Actual Minutes on CIMI_RWM_01102060_01

Updating Actual Minutes on CIMI_RWM_01102062_01

Package Manually Completed by mg2419.

Updating Actual Minutes on CIMI_RWM_01102067_01

Updating Actual Minutes on CIMI_RWM_01102075_01

All lines are mre than 24 inches from power

Place guy guard

Updating Actual Minutes on CIMI_RWM_01102083_01

Updating Actual Minutes on CIMI_RWM_01102087_01

Updating Actual Minutes on CIMI_RWM_01102091_01

Package Manually Completed by jq1534.

placed guy guard

anchor not pulling

Package Manually Completed by jq1534.

Updating Actual Minutes on CIMI_RWM_01102102_01

Updating Actual Minutes on CIMI_RWM_01102105_01

Updating Actual Minutes on CIMI_RWM_01102107_01

Updating Actual Minutes on CIMI_RWM_01102110_01

Updating Actual Minutes on CIMI_RWM_01102115_01

Updating Actual Minutes on CIMI_RWM_01102117_01

Updating Actual Minutes on CIMI_RWM_01102122_01

Updating Actual Minutes on CIMI_RWM_01102123_01

44L AWC removed/repaired lashing wire

Updating Actual Minutes on CIMI_RWM_01102132_01

Updating Actual Minutes on CIMI_RWM_01102137_01

Updating Actual Minutes on CIMI_RWM_01102140_01

Updating Actual Minutes on CIMI_RWM_01102143_01

placed new guy guard

Package Manually Completed by bo128w.

Updating Actual Minutes on CIMI_RWM_01102152_01

Updating Actual Minutes on CIMI_RWM_01102153_01

Updating Actual Minutes on CIMI_RWM_01102156_01

Updating Actual Minutes on CIMI_RWM_01102158_01

Needs pole transfer

Package Manually Completed by bo128w.

Updating Actual Minutes on CIMI_RWM_01102165_01

Updating Actual Minutes on CIMI_RWM_01102167_01

Package Manually Completed by jq1534.

Updating Actual Minutes on CIMI_RWM_01102176_01

Updating Actual Minutes on CIMI_RWM_01102178_01

Updating Actual Minutes on CIMI_RWM_01102180_01

Package Manually Completed by jq1534.

Updating Actual Minutes on CIMI_RWM_01102185_01

All 44 labor complete

Needs pole transfer

Updating Actual Minutes on CIMI_RWM_01102192_01

Package Manually Completed by bo128w.

Updating Actual Minutes on CIMI_RWM_01102195_01

Anchor and down guy in good working condition.

Package Manually Completed by mb553n.

Updating Actual Minutes on CIMI_RWM_01102203_01

Needs pole transfer

Package Manually Completed by bo128w.

Updating Actual Minutes on CIMI_RWM_01102211_01

All 44 labor complete

Updating Actual Minutes on CIMI_RWM_01102213_01

Updating Actual Minutes on CIMI_RWM_01102215_01

Updating Actual Minutes on CIMI_RWM_01102216_01

Updating Actual Minutes on CIMI_RWM_01102217_01

Package Manually Completed by mb553n.

Needs pole transfer

Updating Actual Minutes on CIMI_RWM_01102222_01

All 44 labor complete

Updating Actual Minutes on CIMI_RWM_01102225_01

All 44 labor complete

Updating Actual Minutes on CIMI_RWM_01102228_01

Updating Actual Minutes on CIMI_RWM_01102230_01

Updating Actual Minutes on CIMI_RWM_01102234_01

Updating Actual Minutes on CIMI_RWM_01102238_01

Updating Actual Minutes on CIMI_RWM_01102239_01

Updating Actual Minutes on CIMI_RWM_01102240_01

Updating Actual Minutes on CIMI_RWM_01102242_01

Updating Actual Minutes on CIMI_RWM_01102244_01

Updating Actual Minutes on CIMI_RWM_01102245_01

Needs pole transfer

Needs pole transfer

Package Manually Completed by bo128w.

Updating Actual Minutes on CIMI_RWM_01102255_01

Updating Actual Minutes on CIMI_RWM_01102260_01

Not Att equipement.

Updating Actual Minutes on CIMI_RWM_01102262_01

Package Manually Completed by bo128w.

Attach U guard to pole.

Updating Actual Minutes on CIMI_RWM_01102271_01

Updating Actual Minutes on CIMI_RWM_01102274_01

placed guard arm

remove step.

Updating Actual Minutes on CIMI_RWM_01102288_01

pge pole

Couldn't find pole, wrong address

Package Manually Completed by bo128w.

Updating Actual Minutes on CIMI_RWM_01102297_01

Updating Actual Minutes on CIMI_RWM_01102301_01

Package Manually Completed by bo128w.

Updating Actual Minutes on CIMI_RWM_01102304_01

Replace defective riser cover.

Updating Actual Minutes on CIMI_RWM_01102308_01

Updating Actual Minutes on CIMI_RWM_01102314_01

Package Manually Completed by bo128w.

Updating Actual Minutes on CIMI_RWM_01102321_01

Updating Actual Minutes on CIMI_RWM_01102324_01

Lashing was fixed on arrival.

Updating Actual Minutes on CIMI_RWM_01102328_01

Package Manually Completed by bo128w.

Updating Actual Minutes on CIMI_RWM_01102334_01

Strap down riser cover guards.

Package Manually Completed by bo128w.

Package Manually Completed by mg2419.

Updating Actual Minutes on CIMI_RWM_01126198_01

Updating Actual Minutes on CIMI_RWM_01135915_01

Updating Actual Minutes on CIMI_RWM_01135916_01

Updating Actual Minutes on CIMI_RWM_01135917_01

Updating Actual Minutes on CIMI_RWM_01135918_01

Updating Actual Minutes on CIMI_RWM_01135919_01

Updating Actual Minutes on CIMI_RWM_01135920_01

Updating Actual Minutes on CIMI_RWM_01135921_01

Updating Actual Minutes on CIMI_RWM_01135922_01

Updating Actual Minutes on CIMI_RWM_01135923_01

Updating Actual Minutes on CIMI_RWM_01135924_01

Updating Actual Minutes on CIMI_RWM_01135925_01

Updating Actual Minutes on CIMI_RWM_01135926_01

Updating Actual Minutes on CIMI_RWM_01135927_01

Updating Actual Minutes on CIMI_RWM_01135928_01

Updating Actual Minutes on CIMI_RWM_01135929_01

Updating Actual Minutes on CIMI_RWM_01135930_01

Updating Actual Minutes on CIMI_RWM_01135931_01

Updating Actual Minutes on CIMI_RWM_01135932_01

Updating Actual Minutes on CIMI_RWM_01135933_01

Updating Actual Minutes on CIMI_RWM_01135934_01

Updating Actual Minutes on CIMI_RWM_01135935_01

Updating Actual Minutes on CIMI_RWM_01135936_01

Updating Actual Minutes on CIMI_RWM_01135937_01

Updating Actual Minutes on CIMI_RWM_01135938_01

Updating Actual Minutes on CIMI_RWM_01135939_01

Updating Actual Minutes on CIMI_RWM_01135940_01

Updating Actual Minutes on CIMI_RWM_01135941_01

Updating Actual Minutes on CIMI_RWM_01135942_01

Updating Actual Minutes on CIMI_RWM_01135943_01

Updating Actual Minutes on CIMI_RWM_01135944_01

Updating Actual Minutes on CIMI_RWM_01135949_01

Updating Actual Minutes on CIMI_RWM_01135950_01

Updating Actual Minutes on CIMI_RWM_01135951_01

Updating Actual Minutes on CIMI_RWM_01135952_01

Updating Actual Minutes on CIMI_RWM_01135953_01

Updating Actual Minutes on CIMI_RWM_01135954_01

Updating Actual Minutes on CIMI_RWM_01135955_01

Updating Actual Minutes on CIMI_RWM_01135956_01

Updating Actual Minutes on CIMI_RWM_01135957_01

Updating Actual Minutes on CIMI_RWM_01135958_01

Updating Actual Minutes on CIMI_RWM_01135959_01

Package Manually Completed by bo128w.

Package Manually Completed by bo128w.

Package Manually Completed by bo128w.

needs pole transfer.

Joint pole. PGE owns pole and needs to replace or strighten pole.

Updating Actual Minutes on CIMI_RWM_01136009_01

Updating Actual Minutes on CIMI_RWM_01136010_01

Needs pole transfer.

Needs pole transfer.

Package Manually Completed by bo128w.

Needs pole transfer.

Needs pole transfer.

Package Manually Completed by bo128w.

Needs pole transfer.

Package Manually Completed by bo128w.

Needs pole transfer.

Needs pole transfer.

Needs pole transfer.

Package Manually Completed by bo128w.

Package Manually Completed by bo128w.

Needs pole transfer.

Package Manually Completed by bo128w.

Needs pole transfer.

Package Manually Completed by bo128w.

Needs pole transfer.

Needs pole transfer

Package Manually Completed by bo128w.

Needs pole transfer

Needs pole transfer

Needs pole transfer

Needs pole transfer

Package Manually Completed by bo128w.

Package Manually Completed by bo128w.

Needs pole transfer

Package Manually Completed by bo128w.

Needs pole transfer

Package Manually Completed by bo128w.

Needs pole transfer

Needs pole transfer

Needs pole transfer

Package Manually Completed by bo128w.

Needs pole Transfer.

Package Manually Completed by bo128w.

Needs pole Transfer.

Needs pole Transfer.

Package Manually Completed by bo128w.

Needs pole Transfer.

Package Manually Completed by bo128w.

Package Manually Completed by bo128w.

Package Manually Completed by bo128w.

Package Manually Completed by bo128w.

Package Manually Completed by bo128w.

Needs pole transfer

Needs pole transfer

Package Manually Completed by bo128w.

Needs pole transfer

Package Manually Completed by bo128w.

Package Manually Completed by bo128w.

Updating Actual Minutes on CIMI_RWM_01136170_01

Updating Actual Minutes on CIMI_RWM_01136197_01

Updating Actual Minutes on CIMI_RWM_01136216_01

Updating Actual Minutes on CIMI_RWM_01136224_01

Updating Actual Minutes on CIMI_RWM_01136228_01

Updating Actual Minutes on CIMI_RWM_01136232_01

Updating Actual Minutes on CIMI_RWM_01136236_01

Updating Actual Minutes on CIMI_RWM_01136243_01

Updating Actual Minutes on CIMI_RWM_01136244_01

Updating Actual Minutes on CIMI_RWM_01136248_01

Updating Actual Minutes on CIMI_RWM_01136256_01

Updating Actual Minutes on CIMI_RWM_01136259_01

Updating Actual Minutes on CIMI_RWM_01136260_01

Updating Actual Minutes on CIMI_RWM_01136262_01

Updating Actual Minutes on CIMI_RWM_01136264_01

Updating Actual Minutes on CIMI_RWM_01136267_01

Updating Actual Minutes on CIMI_RWM_01136274_01

Updating Actual Minutes on CIMI_RWM_01136285_01

Updating Actual Minutes on CIMI_RWM_01136287_01

Updating Actual Minutes on CIMI_RWM_01136289_01

Updating Actual Minutes on CIMI_RWM_01136293_01

Updating Actual Minutes on CIMI_RWM_01136296_01

Updating Actual Minutes on CIMI_RWM_01136297_01

Updating Actual Minutes on CIMI_RWM_01136303_01

secure lashing to cable

Updating Actual Minutes on CIMI_RWM_01136321_01

Updating Actual Minutes on CIMI_RWM_01136325_01

Updating Actual Minutes on CIMI_RWM_01136329_01

Updating Actual Minutes on CIMI_RWM_01136337_01

Updating Actual Minutes on CIMI_RWM_01136342_01

Updating Actual Minutes on CIMI_RWM_01136346_01

Updating Actual Minutes on CIMI_RWM_01136348_01

Updating Actual Minutes on CIMI_RWM_01136351_01

Updating Actual Minutes on CIMI_RWM_01136358_01

Updating Actual Minutes on CIMI_RWM_01136373_01

Updating Actual Minutes on CIMI_RWM_01136377_01

Updating Actual Minutes on CIMI_RWM_01136386_01

Updating Actual Minutes on CIMI_RWM_01136389_01

Updating Actual Minutes on CIMI_RWM_01136394_01

Updating Actual Minutes on CIMI_RWM_01136399_01

Updating Actual Minutes on CIMI_RWM_01136400_01

Updating Actual Minutes on CIMI_RWM_01136408_01

Package Manually Completed by bo128w.

Updating Actual Minutes on CIMI_RWM_01136414_01

Place guy guard

Updating Actual Minutes on CIMI_RWM_01136419_01

Updating Actual Minutes on CIMI_RWM_01136423_01

Updating Actual Minutes on CIMI_RWM_01136425_01

Updating Actual Minutes on CIMI_RWM_01136441_01

Updating Actual Minutes on CIMI_RWM_01136447_01

Updating Actual Minutes on CIMI_RWM_01136454_01

Updating Actual Minutes on CIMI_RWM_01136462_01

Updating Actual Minutes on CIMI_RWM_01136479_01

Updating Actual Minutes on CIMI_RWM_01136482_01

Updating Actual Minutes on CIMI_RWM_01136487_01

Updating Actual Minutes on CIMI_RWM_01136493_01

Updating Actual Minutes on CIMI_RWM_01136504_01

Updating Actual Minutes on CIMI_RWM_01136505_01

Updating Actual Minutes on CIMI_RWM_01136509_01

Updating Actual Minutes on CIMI_RWM_01136512_01

Updating Actual Minutes on CIMI_RWM_01136525_01

Updating Actual Minutes on CIMI_RWM_01136526_01

Updating Actual Minutes on CIMI_RWM_01136538_01

Updating Actual Minutes on CIMI_RWM_01136546_01

Updating Actual Minutes on CIMI_RWM_01136556_01

Package Manually Completed by bo128w.

Updating Actual Minutes on CIMI_RWM_01136580_01

Updating Actual Minutes on CIMI_RWM_01136585_01

Updating Actual Minutes on CIMI_RWM_01136591_01

Updating Actual Minutes on CIMI_RWM_01136597_01

Updating Actual Minutes on CIMI_RWM_01136605_01

Updating Actual Minutes on CIMI_RWM_01136610_01

Updating Actual Minutes on CIMI_RWM_01136619_01

Updating Actual Minutes on CIMI_RWM_01136621_01

Updating Actual Minutes on CIMI_RWM_01136622_01

Updating Actual Minutes on CIMI_RWM_01136623_01

Updating Actual Minutes on CIMI_RWM_01136630_01

Updating Actual Minutes on CIMI_RWM_01136639_01

Updating Actual Minutes on CIMI_RWM_01136641_01

Updating Actual Minutes on CIMI_RWM_01136642_01

Updating Actual Minutes on CIMI_RWM_01136652_01

Updating Actual Minutes on CIMI_RWM_01136657_01

Updating Actual Minutes on CIMI_RWM_01136659_01

no issues, its cable tv lashing thats hanging.

Package Manually Completed by bo128w.

Updating Actual Minutes on CIMI_RWM_01136679_01

Updating Actual Minutes on CIMI_RWM_01136692_01

Updating Actual Minutes on CIMI_RWM_01136696_01

Updating Actual Minutes on CIMI_RWM_01136705_01

Updating Actual Minutes on CIMI_RWM_01136709_01

Updating Actual Minutes on CIMI_RWM_01136731_01

Updating Actual Minutes on CIMI_RWM_01136735_01

Updating Actual Minutes on CIMI_RWM_01136740_01

Updating Actual Minutes on CIMI_RWM_01136741_01

Updating Actual Minutes on CIMI_RWM_01136744_01

Updating Actual Minutes on CIMI_RWM_01136748_01

Updating Actual Minutes on CIMI_RWM_01136751_01

Updating Actual Minutes on CIMI_RWM_01136754_01

Updating Actual Minutes on CIMI_RWM_01136756_01

Updating Actual Minutes on CIMI_RWM_01136757_01

Updating Actual Minutes on CIMI_RWM_01136759_01

Updating Actual Minutes on CIMI_RWM_01136760_01

Updating Actual Minutes on CIMI_RWM_01136763_01

Updating Actual Minutes on CIMI_RWM_01136765_01

Updating Actual Minutes on CIMI_RWM_01136768_01

Updating Actual Minutes on CIMI_RWM_01136771_01

Updating Actual Minutes on CIMI_RWM_01136773_01

Updating Actual Minutes on CIMI_RWM_01136790_01

Updating Actual Minutes on CIMI_RWM_01136797_01

Updating Actual Minutes on CIMI_RWM_01136802_01

Updating Actual Minutes on CIMI_RWM_01136813_01

Updating Actual Minutes on CIMI_RWM_01136815_01

Updating Actual Minutes on CIMI_RWM_01136831_01

Updating Actual Minutes on CIMI_RWM_01136834_01

Updating Actual Minutes on CIMI_RWM_01136839_01

Updating Actual Minutes on CIMI_RWM_01136847_01

Updating Actual Minutes on CIMI_RWM_01136848_01

Needs ole transfer

Updating Actual Minutes on CIMI_RWM_01136861_01

Updating Actual Minutes on CIMI_CRD28241028C01

Updating Actual Minutes on CIMI_RWM_01138257_01

Updating Actual Minutes on CIMI_RWM_01160962_01

awc 44 labor

awc 44 labor

44 AWC

HAZARD RESOLVED BY 46L ON EWO A02PV65. THANK YOU

Updating Actual Minutes on CIMI_RWM_01380274_01

Package Manually Completed by ds5682.

Updating Actual Minutes on CIMI_RWM_01397466_01

Updating Actual Minutes on CIMI_RWM_01403017_01

Updating Actual Minutes on CIMI_RWM_01405654_01

Updating Actual Minutes on CIMI_RWM_01405661_01

Package Manually Completed by ds5682.

Updating Actual Minutes on CIMI_RWM_01474766_01
PER CM DG2874, THIS HAZARD HAS BEEN RESOLVED BY LINE CREW. THANK YOU

Updating Actual Minutes on CIMI_RWM_01480453_01

Updating Actual Minutes on CIMI_RWM_01480454_01

Package Manually Completed by ds5682.