## The Following information regarding this incident has been reported:

**Reporting Date:** 1/9/2025 6:09:45 PM **Incident Date:** 1/7/2025 @ 6:15 p.m.

**Reported By:** Paul C. Pimentel, Principal Manager **Utility Name:** Southern California Edison Company

**Phone Number:** (626)302-5830

Email Address: <a href="mailto:paul.pimentel@sce.com">paul.pimentel@sce.com</a>

Incident Location: Near Eaton Canyon Altadena, Los Angeles County

# **Reasons For Reporting:**

- Fatalities? No (Utility: , Others: )
- Names of Fatalities:
- Injuries? (Utility: , Others: )
- Names of Injured:
- Damage? Yes (Utility: , Others: )
- Interruption? (Total Customers: , Total Hours: )
- Operator Judgement? No
- Media Coverage? Yes

Cause of Incident: Unknown (Other Cause: )

# **Agencies on Scene:**

### **Facilities Affected:**

- Utilities Facilities:
- Voltage (KV):
- Customer's Facilities:

### **DigIn Information:**

- Excavator Name:
- Contact:
- Phone: (\_\_\_)\_\_-\_

## **Incident Recovery:**

- On Scene Date & Time: @ 00:00 a.m.
- Service Restored: @ 00:00 a.m.

**Summary:** SCE submits this report out of an abundance of caution because the incident may meet the technical reporting criteria. The Eaton Fire has received significant media attention and has caused property damage exceeding \$200,000. SCE received evidence preservation notices from counsel representing insurance companies in connection with the fire, and there are online publications that seemingly suggest SCE equipment may be

associated with its cause. Therefore, the incident is arguably ?allegedly attributable to utility facilities,? which technically triggers this report. To date, no fire agency has suggested that SCE?s electric facilities were involved in the ignition or requested the removal and retention of any SCE equipment. Additionally, preliminary analysis by SCE of electrical circuit information for the energized transmission lines going through the area for 12 hours prior to the reported start time of the fire shows no interruptions or electrical or operational anomalies until more than one hour after the reported start time of the fire. Aside from the preservation notices suggesting SCE?s potential involvement and significant media attention surrounding the fire, we do not believe this incident meets the reporting requirements.