

From: webmaster@cpuc.ca.gov
To: [USRB](#)
Cc: ElectricDataRequests@pge.com
Subject: Electric Safety Incident Reported- PG&E Incident No: 260713-17860
Date: Monday, July 13, 2026 5:21:31 PM

The Following information regarding this incident has been reported:

Reporting Date: 7/13/2026 5:15:29 PM
Incident Date: 7/11/2026 @ 11:50 a.m.
Reported By: Sean Mackay, Director Investigations
Utility Name: PG&E
Phone Number: (415)205-9698
Email Address: ElectricDataRequests@pge.com

Incident Location: Feather River Highway 70 and Twain Store Road Twain, Plumas

Reasons For Reporting:

- Fatalities? No (Utility: , Others:)
- Names of Fatalities:
- Injuries? (Utility: , Others:)
- Names of Injured:
- Damage? No (Utility: , Others:)
- Interruption? (Total Customers: , Total Hours:)
- Operator Judgement? No
- Media Coverage? No

Cause of Incident: Fire (Other Cause:)

Agencies on Scene: Police, Fire,

Facilities Affected:

- Utilities Facilities: Caribou #2
- Voltage (KV): 60
- Customer's Facilities:

DigIn Information:

- Excavator Name:
- Contact:
- Phone: () -

Incident Recovery:

- On Scene Date & Time: @ 00:00 a.m.
- Service Restored: @ 00:00 a.m.

Summary: CPUC Electric Incident ? EI260711A ? On July 11, 2026, at 1148 hours, a second-party contractor was performing work on behalf of PG&E on a steel pole on the Caribou #2 60kV transmission line. This steel pole is located in the area of Feather River Highway 70 and Twain Store Road, in Twain of Plumas County, a tier-2 HFTD. A short time later, the Twain Fire was reported in the same area. As of July 13, 2026, the Twain Fire was recorded at 275 acres and 10% containment. PG&E is aware that the U.S. Forest Service is currently

investigating the incident. PG&E is reporting this incident under the government entity investigation criterion. PG&E is also investigating this incident. This information is preliminary.