							Closure/
							Notification
Loc#	RWM Pkg#	Pole	Issue Description (PUC Eng)	Address	City	Completed	Date
			a communications conductor was entangled in a third-party service	HWY 127 P/P 250' W/O C/L			
23	1299643	4874373E	·	553' N/O C/L HWY 91	Baker	Х	7/25/2023
8	1299644	329060	the down guy wire was loose.	BAKER BL 107' 1400 E/O DE/	Baker	Х	7/25/2023
				8390200-TECOPA & MINE			
?	1299645	750422H	the down guy wire was loose.	AREA LEAD INYO	Tecopa	Х	7/25/2023
30	1299646	230668S	a communications conductor was not properly secured on the pole.	72263 Hillview Dr	Baker	Х	7/25/2023
?	1299647	30495	the down guy wire was Broken	72100 Hillview Dr	Baker	Х	7/25/2023
			there was a damaged lashing wire; additionally, the location where				
19	1299648	4792298E	the down guy wire was attached to the down guy anchor was buried	56410 Death Valley Rd In tra	Baker	х	7/25/2023
			there was a damaged lashing wire; additionally, the location where				
19	1299649	4792298E	the down guy wire was attached to the down guy anchor was buried	56410 Death Valley Rd In tra	Baker	х	7/25/2023
18	1299649	750712H	there was a damaged lashing wire.	56410 Death Valley Rd	Baker	Х	7/25/2023
			the location where the down guy wire was attached to the down guy				
10	1299650	4659676E	anchor was buried.	72363 Baker Blvd	Baker	х	7/25/2023
52	1296521	4169410E	permanently abandoned service drop that were not removed:	99 Silver Ln	Baker	х	7/28/2023
				72698 I 15 Business (Baker			
9	1296520	329061	permanently abandoned service drop that were not removed:	Blvd)	Baker	х	7/28/2023
32	1296519	230667	permanently abandoned service drop that were not removed:	72210 Hillview Dr	Baker	х	7/28/2023
18	1296514	750712H	Strained by Vegetation	56410 Death Valley Rd	Baker	х	7/28/2023
93	1296518	20	a service drop was not properly secured and was tangling.		Mountain Pass	х	6/16/2023
			An AT&T communications service drop attached to Pole number				
55	1300633	4661015E	4661015E was touching a third party down guy wire	56766 Van Ella Rd	Baker	х	8/4/2023
59	Unable to locate	5377	the down guy wire was loose.		Arrowhead		
17	Unable to locate	2444	permanently abandoned service drop that were not removed:		Baker		