

Loc	RWM Pkg#	Pole	Issue Description (PUC Eng)	Address	City	Lat	long	Completed	Closure/ Notification Date
40	1292183	1334983E	Damaged pole riser	1521 Kensing Ln	Tustin	33.75951246	-117.7892582		ETR by 8/31/2023
26	1292184	1420207E	Damaged pole riser	12022 Red Hill Ave	Tustin	33.75539976	-117.7933148		ETR by 8/31/2023
33	1292185	82551419	Damaged pole riser	btwn 1521 Kensling In & 11687 Red Hill Ave	Tustin	33.75834662	-117.7906968		ETR by 8/31/2023
26	1292187	1420207E	The ground moulding attached to Pole number 1420207E was damaged.	12022 Red Hill Ave	Tustin	33.75539976	-117.7933148		ETR by 8/31/2023
17	1292188	1176769E	The AT&T down guy wire attached to Pole number 1176769E was not taut.	12222 Red Hill Ave	Tustin	33.75328004	-117.7956212		ETR by 8/31/2023
40	1295050	1334983E	the AT&T service drop was damaged	1521 Kensing Ln	Tustin	33.75951246	-117.7892582		ETR by 8/31/2023
29	1295051	1379496E	The AT&T communications conductor on Pole number 1379496E was strained by vegetation.	11882 Red Hill Ave	Tustin	33.75665444	-117.7920277		ETR by 8/31/2023
89	1295442	Pedestal	Vegetation was obstructing the AT&T pedestal at the following locations	28586 Sea Bay Avenue	Laguna Niguel	33.54809919	-117.718622		ETR by 8/31/2023
93	1295441	Pedestal	Vegetation was obstructing the AT&T pedestal at the following locations	28792 Drakes Bay Drive	Laguna Niguel	33.54576516	-117.718389		ETR by 8/31/2023
87	1295440	Pedestal	Vegetation was obstructing the AT&T pedestal at the following locations	28642 Sea Bay Avenue	Laguna Niguel	33.54689043	-117.7185912		ETR by 8/31/2023
41	1295088	Pedestal	The pedestal is damaged	20 Nutcracker Lane	Aliso Viejo	33.60652579	-117.7380416		ETR by 8/31/2023
74	1295089	Pedestal	The pedestal is damaged	12 Meadowpoint	Aliso Viejo	33.59165383	-117.7419431		ETR by 8/31/2023
66	1295090	Pedestal	The pedestal is damaged	5 Cardinal Avenue	Aliso Viejo	33.60728669	-117.7367529		ETR by 8/31/2023

Loc	RWM Pkg#	Pole	Issue Description (PUC Eng)	Address	City	Completed	Closure/ Notification Date
40	1292183	1334983E	Damaged pole riser	1521 Kensing Ln	Tustin	x	8/7/2023
26	1292184	1420207E	Damaged pole riser	12022 Red Hill Ave	Tustin	x	8/7/2023
33	1292185	82551419	Damaged pole riser	btwn 1521 Kensing Ln & 11687 Red Hill Ave	Tustin	x	8/7/2023
17	1292188	1176769E	The AT&T down guy wire attached to Pole number 1176769E was not taut.	12222 Red Hill Ave	Tustin	x	8/7/2023
40	1295050	1334983E	the AT&T service drop was damaged	1521 Kensing Ln	Tustin	x	6/16/2023
29	1295051	1379496E	The AT&T communications conductor on Pole number 1379496E was strained by vegetation.	11882 Red Hill Ave	Tustin	x	6/16/2023
89	1295442	Pedestal	Vegetation was obstructing the AT&T pedestal at the following locations	28586 Sea Bay Avenue	Laguna Niguel	x	7/12/2023
93	1295441	Pedestal	Vegetation was obstructing the AT&T pedestal at the following locations	28792 Drakes Bay Drive	Laguna Niguel	x	7/11/2023
87	1295440	Pedestal	Vegetation was obstructing the AT&T pedestal at the following locations	28642 Sea Bay Avenue	Laguna Niguel	x	7/13/2023
41	1295088	Pedestal	The pedestal is damaged	20 Nutcracker Lane	Aliso Viejo	x	7/11/2023
74	1295089	Pedestal	The pedestal is damaged	12 Meadowpoint	Aliso Viejo	x	7/11/2023
66	1295090	Pedestal	The pedestal is damaged	5 Cardinal Avenue	Aliso Viejo	x	7/11/2023
26	1292187	1420207E	The ground moulding attached to Pole number 1420207E was damaged.	12022 Red Hill Ave	Tustin	x	8/8/2023