# ANZA ELECTRIC COOPERATIVE, Inc.



P O Box 391909 (58470 Highway 371) Anza, CA 92539

Phone: (951) 763-4333

Fax: (951) 763-5297

Dear Mr. Daye,

This remediation plan outlines corrective measures to address the violations identified during the California Public Utilities Commission (CPUC) audit conducted from October 7-11, 2024. Anza Electric Cooperative, Inc. (AEC) is committed to rectifying these issues and implementing preventative measures to ensure ongoing compliance with General Orders (GOs) 95, 128, and 165.

## 1. Corrective Actions

### 1.1 Records Review Violations

**Issue:** AEC completed 5,825 patrol or detailed inspections and 1,028 underground inspections past the scheduled due dates, violating GO 165 and GO 128.

### **Corrective Action:**

- **Inspection Schedule Enhancement:** AEC has reviewed and comprehensively updated its inspection schedule to ensure timely compliance.
- Automated Alerts System: AEC has implemented an automated tracking and notification system to flag upcoming due dates.
- Alternative Workforce Allocation: AEC has leveraged alternative resources to help manage and implement the updated inspection strategy.
- **Progress Reporting:** AEC will review progress quarterly to analyze complete and pending inspections until full compliance is achieved.

## 1.2 Field Inspection Violations

#### 1.2.1 Maintenance Issues on Poles

**Issue:** Poles requiring maintenance, including missing or illegible identification tags, exposed ground wires, damaged high voltage signs, and inadequate climbing space due to vegetation.

### **Corrective Action:**

- **Pole Tag Replacement:** Tags on Poles 8561 and 7589 have been replaced or repositioned for visibility.
- **Ground Wire and Rod Protection:** Exposed ground wires and rods on Pole 7589 have been rectified with the installation of appropriate moulding.

## ANZA ELECTRIC COOPERATIVE, Inc.



P O Box 391909 (58470 Highway 371) Anza, CA 92539

Fax: (951) 763-5297

Phone: (951) 763-4333

- **High Voltage Sign Replacement:** New weather-resistant high voltage signs have been installed on affected poles (012317, 012319, 012323, 1792, 408, 7030, 1791, 1792, 408, 1793, 429, 5589, 1791, 453, 433).
- **Vegetation Management:** The vegetation obstructing climbing space on Pole 410 has been removed. Future obstructions will be identified and addressed through periodic inspections.

#### 1.2.2 Clearance Violations

**Issue:** Insufficient clearance between electrical and communication conductors and between guy wires and span wires.

## **Corrective Action:**

- **Guy Wire Adjustments:** Guy wire on Pole 11283 has been repositioned to maintain the required 3-inch clearance.
- **Service Drop Clearance:** The service drop on Pole 429 has been adjusted to maintain the minimum 12-inch clearance.

## 1.2.3 Guy Wire and Ground Wire Deficiencies

**Issue:** Loose guy wires and damaged ground moulding on multiple poles.

#### **Corrective Action:**

- **Tightening of Down Guys:** Tension adjustments have been made to the guy wires supporting Poles 11677, 1778, and 408.
- **Ground Moulding Replacement:** New protective coverings have been installed on Poles 8559, 7590, 8558, 2890, 7584, 411, 7588, 433, and 7589.
- **Preventative Maintenance:** Routine inspections will continue to monitor guy wire tension and ground moulding integrity.

# 2. Preventative Measures and Compliance Monitoring

To prevent future violations, AEC will implement the following measures:

- Enhanced Training Programs: Field personnel will undergo regular training sessions on compliance with GOs 95, 128, and 165.
- **Audit Preparation Protocols:** Internal audits will be conducted semi-annually to ensure compliance readiness and format adequacy.

# ANZA ELECTRIC COOPERATIVE, Inc.

A Touchstone Energy® Cooperative

P O Box 391909 (58470 Highway 371) Anza, CA 92539

Phone: (951) 763-4333 Fax: (951) 763-5297

- Improved Recordkeeping System: A new digital platform has been implemented and will streamline inspection logging and corrective action tracking while ensuring data will be presented in the required format.
- **Stakeholder Communication:** AEC will engage with the CPUC for ongoing guidance and compliance verification when issues arise.

# 3. Conclusion

AEC acknowledges the importance of compliance with CPUC regulations and is fully committed to ensuring the reliability and safety of its electric distribution system.