



July 22<sup>nd</sup>, 2024

VIA E-MAIL

Mr. Fadi Daye, P.E.  
Program and Project Supervisor  
Electric Safety and Reliability Branch  
Safety and Enforcement Division  
California Public Utilities Commission  
505 Van Ness Avenue  
San Francisco, CA 94102-3298

**Subject: 2024 SDG&E Response to CPUC Eastern Region Transmission Audit**

Dear Mr. Daye:

An electric transmission audit of San Diego Gas & Electric's (SDG&E) Eastern Region was conducted by the Electric Safety and Reliability Branch of the California Public Utilities Commission (CPUC) staff James Miller and Norvik Ohanian on April 15-19 2024. The table below identifies priority level 3 findings your staff captured during their field inspection, and the corrective measures SDG&E will take to remedy these findings.

CPUC Comment	SDGE Comment
Unauthorized signs were attached to the following poles: <ul style="list-style-type: none"><li>• Pole No. Z71402 supported an unauthorized sign advertising local "handyman services".</li><li>• Pole No. Z371391 supported an unauthorized sign for an automobile dealer</li></ul>	Patroller was directed to remove unauthorized signs on Z71420 and Z371391.
The high-voltage warning band on Pole No. Z30333 was damaged.	Correction of damaged high voltage warning band on Z30333 will be completed the next time crews are working on the tie line, not to exceed 60 months date due from April 17, 2024.

Items listed in your letter dated May 24<sup>th</sup>, 2024, have been addressed or are in the process of being addressed by SDG&E.

If you have questions regarding these comments, please do not hesitate to contact myself at (619)-751-5256 or at [saguila2@sdge.com](mailto:saguila2@sdge.com) or Monica Curry at (619) 694-9323 or at [mcurry@sdge.com](mailto:mcurry@sdge.com)

Sincerely,  
Sandra Aguilar  
Team Lead - Substation & Transmission Compliance  
cc. Monica Curry SDG&E, Christian Henderson SDG&E